Available from

GPO Sales Program

Division of Technical Information and Document Control

U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Printed copy price: \$8.50

and

National Technical Information Service Springfield, Virginia 22161

Title List of Documents Made Publicly Available

June 1-30, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	3
Domestic Licensing of Production and Utilization Facilities - Docket 50	9
Domestic Licensing of Special Nuclear Material - Docket 70	266
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	279
Nondocketed Items	289
10CFR — Commission Meeting Records	289
ACRS — Advisory Committee on Reactor Safeguards	291
COMMISSION — NRC Commissioners	294
CONTRACT — NRC Contracts and Modifications	296
FOIA — Freedom of Information Act Requests and Releases	300
GEN TECH IS — Generic Technical Issues	305
I&E — Inspection and Enforcement	305
MISC — Public Document Room Miscellaneous	306
NUREG — NUREG Reports and Related Correspondence	306
ORG — Correspondence with Other Organizations	311
PR — Proposed Rule	311
PRM — Petition for Rulemaking	316
PROJ — Projects - Predocket Licensing	317
PT21 — Noncompliance Reports and Related Correspondence	317
QA999 — Quality Assurance Inspections	318
REGGD — Regulatory Guides	321
RES — Research and Technical Assistance Reports	321
REVIEW GRP — NRC Research Review Groups	324
SECY — Position Papers Before the Commission	324
STATE PROG — State Programs	325
TOPREP — Vendor Reports and Related Correspondence	328
WASTE MGT — Nuclear Waste Management	329
XPORTLIC — Export and Import Licenses	330
Personal Author Index	339
Corporate Source Index	369
Report Number Index	399
Cross Reference of Enclosures to Principal Documents	401
Appendix A - Definitions of Docket 50 Categories	417
Annendix R. Definitions of Nondocketed Categories	425

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- Il General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are.


(1)

P. Operating license stage documents & correspondence



7904170015 Forwards into on TMI JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations.



- 1. NRC/PDR Document category (see Appendix A)
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author An asterisk in this position indicates that there is no personal author
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale, "Available at NTIS"; or "Available at GPO"

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records

ACRS — Advisory Committee on Reactor Safeguards

COMMISSION — NRC Commissioners

CONTRACT — NRC Contracts and Modifications

FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 Quality Assurance Inspections

REGGD - Regulatory Guides

RES - Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM Rulemakings

SECY - Position Papers Before the Commission

STATE PROG - State Programs

TOPREP - Vendor Reports and Related Correspondence

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

NUREG NUREG Reports and Related Correspondence

2

3

7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory. FIN A-2093. 178/11/30. 26pp. Available at NTIS.

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on the next page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8348	In Situ Uranium Leaching Project	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1	40-8355	AMAX Environmental Services, Inc.	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40-8380	Rocky Mountain Energy Co	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8434	Home State Mining Co., LA	6
40-0299	Union Carbide Corp.	3	40-8452	Bear Creek Uranium Co.	6
40-0665	Anaconda Co. South Texas Uranium Projects	3	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
40-0672	Nuclear Metals, Inc.	3	40-8576	Edlow International Co.	7
40-1162	Western Nuclear, Inc.	3	40-8584	Union 76 Minerals Exploration Co.	7
40-1341	Edgemont Uranium Mine, TVA, and Mines	4	40-8681	Energy Fuels Nuclear, Inc.	7
40-1341	Development, Inc.	•	40-8684	J & P Corp.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.	4	40-8693	Ogle Petroleum, Inc.	8
40-2259	Pathfinder Mines Corp.	4	40-8697	Rocky Mountain Energy Co.	8
40-3392	Allied Chemical Corp.	4	40-8698	Plateau Resources, Ltd.	8
40-3453	Atlas Minerals	4	40-8714	Cleveland Cliffs Iron Co.	8
40-4337	Marquette Univ.	5	40-8720	Standard Oil Co. of Indiana	8
40-4492	Federal American Partners (Mining)	5	40-8721	Rocky Mountain Energy Co.	8
40-5001	AMAX Environmental Services, Inc.	5	40-8722	Brush-Wellman, Inc.	8
40-6622	Pathfinder Mines Corp.	5	40-8727	Kerr-McGee Nuclear Corp	8
40-6659	Petrotomics Co., Getty Oil	5	40-8728	Teton Exploration Drilling Co., Inc.	8
40-7869	Plateau Resources, Ltd.	5	40-8745	Ogle Petroleum, Inc.	8
40-8027	Kerr-McGee Corp.	5	40-8752	Pinal Minerals & Mining, Ltd.	8
40-8052	Mitsui & Co. (USA), Inc.	5	40-8768	Kerr-McGee Nuclear Corp.	8
40-8064	Exxon Minerals Co. USA, Exxon Corp.	5	50-2	Univ. of Michigan Research Reactor	9
40-8084	Lisbon Mine, Rio Algom Corp.	5	50-3	Indian Point Station, Unit 1	9
40-8102	Exxon Minerals Co. USA, Exxon Corp.	5	50-5	Pennsylvania State Univ. Research Reactor	9
40-8304	Wyoming Mining Corp.	6	50-10	Dresden Nuclear Power Station, Unit 1	9
			50-18	Vallecitos Boiling Water Reactor	11

Docket	Name	Page	Docket	Name	Page
50-20	Massachusetts Institute of Technology	11	50-213	Haddam Neck Plant	21
eo 27	Research Reactor	12	50-219	Oyster Creek Nuclear Power Plant	22
50-27	Washington State Univ. Research Reactor	-	50-220	Nine Mile Point Nuclear Station, Unit 1	24
50-29	Yankee-Rowe Nuclear Power Station	13	50-223	Univ. of Lowell Research Reactor	25
50-30	Plum Brook Research Reactor Facility	13	50-224	Univ. of California Research Reactor	25
50-54	Union Carbide Research Reactor	13	50-225	RPI Critical Experiment	26
50-70	General Electric Test Reactor	13	50-228	Aerotest Radiography & Research Reactor	26
50-73	General Electric Nuclear Test Reactor	13	50-237	Dresden Nuclear Power Station, Unit 2	26
50-83	Univ. of Florida Training Reactor	14	50-243	Oregon State Univ. Research Reactor	27
50-111	North Carolina State Univ. Research Reactor	14	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28
50-116	Iowa State Univ. Research Reactor	14	50-245	Millstone Nuclear Power Station, Unit 1	29
50-128	Texas A&M Univ. Research Reactor	14	50-247	Indian Point Station, Unit 2	31
50-129	West Virginia Univ. Research Reactor	14	50-249	Dresden Nuclear Power Station, Unit 3	33
50-133	Humboldt Bay Power Plant, Unit 3	14	50-250	Turkey Point Plant, Unit 3	35
50-141	Stanford Univ. Research Reactor	15	50-251	Turkey Point Plant, Unit 4	37
50-142	UCLA Training Reactor	15	50-254	Quad-Cities Station, Unit 1	39
50-147	Rockwell International Corp. Critical Facility	15	50-255	Palisades Nuclear Plant	41
50-150	Ohio State Univ. Research Reactor	15	50-259	Browns Ferry Nuclear Power Station, Unit 1	43
50-155	Big Rock Point Nuclear Plant	15	50-260	Browns Ferry Nuclear Power Station,	45
50-157	Cornell Univ. Research Reactor	17	50.741	Unit 2	47
50-160	Georgia Institute of Technology Research Reactor	17	50-261 50-263	H. B. Robinson Plant, Unit 2 Monticello Nuclear Generating Plant	47 48
50-166	Univ. of Maryland Research Reactor	17	50-264	Dow Chemical Co.	49
50-170	National Naval Medical Center	17	50-265	Quad-Cities Station, Unit 2	49
50-171	Peach Bottom Atomic Power Station, Unit 1	17	50-266	Point Beach Nuclear Plant, Unit 1	51
50-184	National Bureau of Standards Reactor	18	50-267	Fort St. Vrain Nuclear Generating Station	52
50-185	Plum Brook Reactor — Mock-up	18	50-269	Oconee Nuclear Station, Unit 1	54
50-186	Univ. of Missouri Research Reactor	18	50-270	Oconee Nuclear Station, Unit 2	56
50-192	Univ. of Texas Research Reactor		50-271	Vermont Yankee Nuclear Power Station	58
50-201	West Valley Reprocessing Plant	18	50-272	Salem Nuclear Generating Station, Unit 1	59
50-206	San Onofre Nuclear Station, Unit 1	18	50-275	Diablo Canyon Nuclear Power Plant,	62
50-208	Columbia Univ. Research Reactor	19		Unit 1	
	Seamon Chir, Restarch Reactor	21			

Docket	Name	Page	Docket	Name	Page
50-277	Peach Bottom Atomic Power Station, Unit 2	64	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	113
50-278	Peach Bottom Atomic Power Station, Unit 3	66	50-320	Three Mile Island Nuclear Station, Unit 2	115
50-280	Surry Power Station, Unit 1	68	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	122
50-281	Surry Power Station, Unit 2	71	50-322	Shoreham Nuclear Power Station	125
50-281	Prairie Island Nuclear Station, Unit 1	73	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	126
50-285	Fort Calhoun Station, Unit 1	75	50-324	Brunswick Steam Electric Plant, Unit 2	129
50-286	Indian Point Station, Unit 3	76	50-325	Brunswick Steam Electric Plant, Unit 1	131
50-287	Oconee Nuclear Station, Unit 3	78	50-327	Sequoyah Nuclear Plant, Unit 1	133
50-288	Reed College Research Reactor	80	50-328	Sequoyah Nuclear Plant, Unit 2	137
50-289	Three Mile Island Nuclear Station, Unit 1	80	50-329	Midland Plant, Unit 1	140
50-293	Pilgrim Nuclear Power Station, Unit 1	86	50-330	Midland Plant, Unit 2	141
50-294	Michigan State Univ. Research Reactor	88	50-331	Duane Arnold Energy Center	143
50-295	Zion Nuclear Power Station, Unit 1	88	50-333	James A, Fitzpatrick Nuclear Power Plant	145
50-296	Browns Ferry Nuclear Power Station,	90	50-334	Beaver Valley Power Station, Unit 1	147
	Unit 3		50-335	St. Lucie Plant, Unit 1	149
50-297	North Carolina State Univ. PULSTAR Reactor	92	50-336	Millstone Nuclear Power Station, Unit 2	151
50-298	Cooper Nuclear Station	92	50-338	North Anna Power Station, Unit 1	153
50-301	Point Beach Nuclear Plant, Unit 2	93	50-339	North Anna Power Station, Unit 2	155
50-302	Crystal River Nuclear Plant, Unit 3	94	50-341	Enrico Fermi Atomic Power Plant, Unit 2	158
50-304	Zion Nuclear Power Station, Unit 2	97	50-344	Trojan Nuclear Plant	159
50-305	Kewaunee Nuclear Power Plant	99	50-346	Davis-Besse Nuclear Power Station, Unit 1	164
50-306	Prairie Island Nuclear Station, Unit 2	100	50-348	Joseph M. Farley Nuclear Plant, Unit 1	165
50-309	Maine Yankee Atomic Power Plant	101	50-352	Limerick Generating Station, Unit 1	166
50-311	Salem Nuclear Generating Station, Unit 2	103	50-353	Limerick Generating Station, Unit 2	167
50-312	Rancho Seco Nuclear Generating Station	105	50-354	Hope Creek Nuclear Station, Unit 1	168
50-313	Arkansas Nuclear One, Unit 1	107	50-355	Hope Creek Nuclear Station, Unit 2	168
50-315	Donald C. Cook Nuclear Power Plant,	109	50-357	Univ. of California	169
	Unit 1		50-358	William H. Zimmer Nuclear Station, Unit 1	169
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	110	50-361	San Onofre Nuclear Station, Unit 2	171
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	112	50-362	San Onofre Nuclear Station, Unit 3	173

Docket	Name	Page	Docket	Name	Page
50-363	Forked River Nuclear Station, Unit 1	174	50-414	Catawba Nuclear Station, Unit 2	205
50-364	Joseph M. Farley Nuclear Plant, Unit 2	175	50-416	Grand Gulf Nuclear Station, Unit 1	206
50-366	Edwin 1. Hatch Nuclear Plant, Unit 2	176	50-417	Grand Gulf Nuclear Station, Unit 2	208
50-367	Bailly Generating Station	179	50-423	Millstone Nuclear Power Station, Unit 3	210
50-368	Arkansas Nuclear One, Unit 2	180	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	211
50-369	William B. McGuire Nuclear Station, Unit 1	181	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	211
50-370	William B. McGuire Nuclear Station, Unit 2	183	50-433	Univ. of California at Santa Barbara Research Reactor	212
50-373	LaSalle County Station, Unit 1	184	STN-50-437	Floating Nuclear Plant	212
50-374	LaSalle County Station, Unit 2	186	50-438	Bellefonte Nuclear Plant, Unit !	213
50-376	North Coast Nuclear Plant, Puerto Rico	187	50-439	Bellefonte Nuclear Plant, Unit 2	214
50-382	Waterford Generating Station, Unit 3	187	50-440	Perry Nuclear Power Plant, Unit 1	215
50-387	Susquehanna Steam Electric Station, Unit 1	188	50-441	Perry Nuclear Power Plant, Unit 2	216
50-388	Susquehanna Steam Electric Station, Unit 2	190	50-443	Seabrook Nuclear Station, Unit 1	216
50-389	St. Lucie Plant, Unit 2	192	50-444	Seabrook Nuclear Station, Unit 2	217
50-390	Watts Bar Nuclear Plant, Unit 1	193	50-445	Comanche Peak Steam Electric Station, Unit 1	218
50-391	Watts Bar Nuclear Plant, Unit 2	195	50-446	Comanche Peak Steam Electric Station, Unit 2	221
50-392	Chin-Shan Power Reactor, Unit 1, Taiwan	196	50-448	Douglas Point Nuclear Station, Unit 1	224
50-395	Virgil C. Summer Nuclear Station, Unit 1	196	50-449	Douglas Point Nuclear Station, Unit 2	224
50-397	WPPSS Nuclear Project, Unit 2	197	50-452	Greenwood Energy Center, Unit 2	224
50-400	Shearon Harris Nuclear Power Plant, Unit 1	199	50-453	Greenwood Energy Center, Unit 3	
50-401	Shearon Harris Nuclear Power Plant.	199	50-454	- "	224
50.401	Unit 2	197	50-455	Byron Station, Unit 1	224
50-402	Shearon Harris Nuclear Power Plant, Unit 3	200	50-456	Byron Station, Unit 2	225
50-403	Shearon Harris Nuclear Power Plant,	200	50-457	Braidwood Station, Unit 1	226
30-403	Unit 4	200		Braidwood Station, Unit 2	227
50-404	North Anna Power Station, Unit 3	201	50-458	River Bend Station, Unit 1	228
50-405	North Anna Power Station, Unit 4	201	50-459	River Bend Station, Unit 2	228
50-409	La Crosse Boiling Water Reactor	202	50-460	WPPSS Nuclear Project, Unit 1	229
50-410	Nine Mile Point Nuclear Station, Unit 2	203	50-461	Clinton Power Station, Unit 1	229
50-412	Beaver Valley Power Station, Unit 2	204	50-462	Clinton Power Station, Unit 2	230
50-413	Catawba Nuclear Station, Unit I	204	50-466	Allens Creek Nuclear Station, Unit 1	230

Docket	Name	Page	Docket	Name	Page
50-467	Allens Creek Nuclear Station, Unit 2	232	STN-50-528	Palo Verde Nuclear Station, Unit 1	253
50-471	Pilgrim Nuclear Power Station, Unit 2	232	STN-50-529	Palo Verde Nuclear Station, Unit 2	254
STN-50-482	Wolf Creek Generating Station	233	STN-50-530	Palo Verde Nuclear Station, Unit 3	255
STN-50-483	Calloway Plant, Unit 1	234	50-537	Clinch River Breeder Reactor	257
STN-50-485	Sterling Power Project Nuclear, Unit 1	235	50-538	Memphis State Univ. Research Reactor	257
STN-50-486	Calloway Plant, Unit 2	235	STN-50-546	Marble Hill Nuclear Station, Unit 1	257
STN-50-488	Perkins Nuclear Station, Unit 1	236	STN-50-547	Marble Hill Nuclear Station, Unit 2	259
STN-50-489	Perkins Nuclear Station, Unit 2	237	50-548	Fort Calhoun Station, Unit 2	261
STN-50-490	Perkins Nuclear Station, Unit 3	238	\$0-549	Greene County Nuclear Power Plant	261
STN-50-491	Cherokee Nuclear Station, Unit 1	239	STN-\$0-553	Phipps Bend Nuclear Plant, Unit 1	261
STN-50-492	Cherokee Nuclear Station, Unit 2	239	STN-30-554	Phipps Bend Nuclear Plant, Unit 2	262
STN-50-493	Cherokee Nuclear Station, Unit 3	240	STN-50-556	Black Fox Station, Unit 1	263
50-496	Montague Nuclear Power Station, Unit 1	240	STN-50-557	Black Fox Station, Unit 2	263
50-497	Montague Nuclear Power Station, Unit 2	240	STN-50-561	B-SAR-205	263
STN-50-498	South Texas Project, Unit 1	240	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	263
STN-50-499	South Texas Project, Unit 2	243	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	264
50-500	Davis-Besse Nuclear Power Station, Unit 2	246	STN-50-573	Ko-Ri, Unit 2, Korea	265
50-501	Davis-Besse Nuclear Power Station, Unit 3	246	STN-50-574	Bagnac Nuclear Power Project, Philippines	265
STN-50-502	Haven Nuclear Plant, Unit 1	246	STN-50-591	ESSAR	265
STN-50-508	WPPSS Nuclear Project, Unit 3	247	STN-50-592	Palo Verde Nuclear Station, Unit 4	265
STN-50-509	WPPSS Nuclear Project, Unit 5	247	STN-50-593	Palo Verde Nuclear Station, Unit 5	265
50-513	WPPSS Nuclear Project, Unit 4	247	STN-50-596	New Haven, Unit 1	266
50-514	Pebble Springs Nuclear Plant, Unit 1	248	STN-50-597	New Haven, Unit 2	266
50-515	Pebble Springs Nuclear Plant, Unit 2	248	50-599	Carroll Facility I	266
STN-50-516	Jamesport Nuclear Station, Unit 1	248	50-600	Carroll Facility II	266
STN-50-517	Jamesport Nuclear Station, Unit 2	248	70-0008	Battelle Columbus Laboratories	266
STN-50-518	Hartsville Nuclear Plant, Unit i	249	70-0025	Rockwell International Corp,	266
STN-50-519	Hartsville Nuclear Plant, Unit 2	250	70-0027	Babcock & Wilcox Co.	267
STN-50-520	Hartsville Nuclear Plant, Unit 3	251	70-0033	Texas Instruments, Inc.	267
STN-50-521	Hartsville Nuclear Plant, Unit 4	252	70-0036	Combustion Engineering, Inc.	268
STN-50-522	Skagit Nuclear Power Project, Unit 1	252	70-0089	Massachusetts Institute of Technology	268
STN-50-523	Skagit Nuclear Power Project, Unit 2	253	70-0095	Massachusetts Institute of Technology	268

Docket	Name	Page	Docket	Name	Page
70-0124	Teledyne Isotopes	268	70-1252	Edlow International Co.	275
70-0135	Babcock & Wilcox Co.	268	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	275
70-0143	Nuclear Fuel Services, Inc.	269	70-1308	Morris Operations, General Electric Co.	276
70-0194	Massachusetts Institute of Technology	270	70-1308	National Aeronautics & Space	277
70-0267	Nuclear Science & Technology Facility at State Univ. of New York	270	70-1314	Administration, Langley Research Center	211
70-0364	Parks Township Site, Babcock & Wilcox	270	70-1319	U.S. Nuclear, Inc.	277
70-0307	Co.	2.10	70-1359	IRT Corp.	277
70-0371	United Nuclear Corp.	270	70-1510	Nuclear Assurance Corp.	277
70-0398	Dept. of Commerce	270	70-1621	Conover & Associates, Inc.	277
70-0442	Dept. of HEW, Food and Drug Administration	271	70-1729	Fuel Recovery & Storage Station, Allied General Nuclear Services	277
70-0572	Monsanto Research Corp.	271	70-1812	General Atomic Co.	277
70-0623	Kenyon College	271	70-1966	Tennessee Valley Authority	277
70-0687	Union Carbide Corp.	271	70-1992	Mt. Auburn Hospital, Cambridge, MA	277
70-0698	Waltz Mill Site, Westinghouse Electric Corp.	271	70-2131	Edlow International Co.	277
70-0734	General Atomic Co.	271	70-2260	St. Joseph Hospital, Stamford, CT	277
70-0754	Vallecitos Nuclear Center, General Electric	271	70-2474	Holy Name Hospital, Teaneck, NJ	277
10 0/27	Co.		70-2485	Edlow International Co.	277
70-0778	General Electric Co., Nuclear Energy Products Division	272	70-2486	St. Elizabeth Hospital, Medical Center, Lafayette, IN	277
70-0785	State Univ. of New York at Buffalo	272	70-2523	General Atomic Co.	277
70-0820	United Nuclear Corp.	272	70-2542	Westinghouse Electric Co.	278
70-0824	Babcock & Wilcox Co.	272	70-2609	Commonwealth Edison Co.	278
70-0925	Cimmaron Facility, Kerr-McGee Corp.	273	70-2619	Bloomington Hospital, Bloomington, IN	278
70-0938	Massachusetts Institute of Technology	273	70-2623	McGuire Spent Fuel Pool, Duke Power Co.	278
70-0984	Pacific Northwest Laboratory	273	70-2805	Nissho-Iwai American Corp.	278
70-1007	General Electric Co.	273	70-2838	Cincinnati Gas & Electric Co.	278
70-1100	Combustion Engineering, Inc.	273	70-2885	Commonwealth Edison	278
70 1113	General Electric Co.	274	70-2909	Westinghouse Electric Corp. Power Systems	278
3	Westinghouse Electric Corp.	274	70-2910	Tennessee Valley Authority	279
	etric Corp.	274	70-2920	Alabama Power Co.	279
	rr-McGee Corp.	275	70-2928	Tennessee Valley Authority	279
	ty, Babcock &	275	71-0015	Chicago Bridge & Iron Co.	279

71-0102 Source Products & Equipment Co., Inc. 279 71-5975 Model: 5975, Sehlumberger Well Services 282	Docket	Name	Page	Docket	Name	Page
71-0135 Babcock & Wilcox Co. 279 71-6056 Model: B3-1, Nuclear Engineering Co. 282	71-0102	Source Products & Equipment Co., Inc.	279	71-5975	Model: 5975, Schlumberger Well Services	282
71-0164 Massachusetts Institute of Technology 279 71-6144 Model: 6144, Nuclear Engineering Co. 282	71-0108	Univ. of Missouri	279	71-5980	Model: GE-600, General Electric Co.	282
71-0165 Dept. of the Navy 280 71-6206 Model: B, Babcock & Wilcox Co. 282	71-0135	Babcock & Wilcox Co.	279	71-6058	Model: B3-1, Nuclear Engineering Co.	282
71-0173	71-0164	Massachusetts Institute of Technology	279	71-6144	Model: 6144, Nuclear Engineering Co.	282
T1-0185 FBF, Inc. 280 T1-6275 Model: L1-28-4, Chem-Nuclear Systems, Inc. 282 T1-0230 Babcock & Wilcox Co. 280 T1-6275 Model: L1-28-4, Chem-Nuclear Systems, Inc. 282 T1-0387 Massachusetts Materials Research, Inc. 280 T1-6375 Model: Chem-Nuclear Systems, Inc. 282 T1-0387 Massachusetts Materials Research, Inc. 280 T1-6387 Model: GE-T-00, Inc. 280 T1-6387 Model: Super Tiger, Westinghouse Electric 283 Corp. T1-0389 Univ. of Georgia 280 T1-6553 Model: Super Tiger, Westinghouse Electric Corp. T1-6553 Model: Super Tiger, Dept. of Energy 283 T1-0390 Dept. of Commerce, National Bureau of Standards T1-6581 Model: Super Tiger, Dept. of Energy 283 T1-6381 Model: Seminel-25A, B, C, C3, D, E, F, 280 T1-6581 Model: Seminel-25A, B, C, C3, D, E, F, 280 T1-6691 Model: L1-50-100, Chem-Nuclear Systems, Inc. T1-6691 Model: MH-1A, Dept. of the Army 283 Model: BC-48-220, Atcor, Inc. 281 T1-6699 Model: MH-1A, Dept. of the Army 283 Model: BC-48-220, Atcor, Inc. 281 T1-6697 Model: MH-1A, Dept. of the Army 283 Model: NPI-67-0442, Neutron Products, Inc. 281 T1-6698 Model: NPI-67-0442, Neutron Products, Inc. 281 T1-6698 Model: NPI-67-0442, Neutron Products, Inc. 281 T1-6719 Model: CB-T-2, General Electric Co. 281 T1-6719 Model: SDAP 21, Dept. of the Navy 281 T1-6719 Model: SDAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 284 T1-5800 Model: SNAP 21, Dept. of the Navy 281 T1-6719 Model: SNAP 21, Dept. of the Navy 284 T1-5800 Model: SNAP 21, Dept. of the Navy 284 T1-5900 Model: SNAP 21, Dept. of the Navy 284 T1-5900 Model: SNAP 21, Dept. of the Navy 284 T1-5904 Model: SNAP	71-0165	Dept. of the Navy	280	71-6206	Model: B, Babcock & Wilcox Co.	282
T1-0185 FFF, Inc. 280 T1-6275 Model: LL-28-4, Chem-Nuclear Systems, 282 T1-0230 Babcock & Wilcox Co. 280 T1-6375 Model: PB-1, Chem-Nuclear Systems, Inc. 282 T1-0387 Massachusetts Materials Research, Inc. 280 T1-6375 Model: GB-Battelle Memorial Institute 283 T1-0388 Dept. of the Navy, USS Canopus 280 T1-6387 Model: Super Tiger, Westinghouse Electric 283 Corp. T1-0389 Univ. of Georgia 280 T1-6533 Model: Super Tiger, Westinghouse Electric 283 T1-0390 Dept. of Commerce, National Bureau of Standards T1-6581 Model: Super Tiger, Dept. of Energy 283 T1-0391 Dept. of the Navy 280 T1-6581 Model: Sentinel-25A, B, C, C3, D, E, F, 280 T1-6490 Model: Sentinel-25A, B, C, C3, D, E, F, 280 T1-6490 Model: MR1-1A, Dept. of the Army 283 T1-9364 Model: BC-48-220, Atcor, Inc. 281 T1-6679 Model: MR1-1A, Dept. of the Army 283 T1-5364 Model: NP1-67-0442, Neutron Products, Inc. 281 T1-6698 Model: NP5-4, Duct. of the Navy 281 T1-6698 Model: NP5-4, Nuclear Fuel Services, Inc. 283 T1-5450 Model: RCC-1, -2, -3, Westinghouse 281 T1-6717 Model: NP5-4, Nuclear Engineering Co. 284 T1-5697 Model: SNAP 21, Dept. of the Navy 281 T1-6717 Model: NP5-4, Nuclear Engineering Co. 284 T1-5697 Model: SNAP 21, Dept. of the Navy 281 T1-6717 Model: NP5-4, Nuclear Engineering Co. 284 T1-5697 Model: SNAP 21, Dept. of the Navy 281 T1-6717 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 284 T1-5862 Model: Sentinel-100F, Teledyne Energy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 284 T1-5860 Model: SNAP 21, Dept. of the Navy 281 T1-6718 Model: SNAP 21, Dept. of the Navy 284 T1-5939 Model: SNAP 21, Dept. of the Navy 281	71-0173	Battelle-Pacific Northwest Laboratory	280	71-6272		282
T1-0230 Babcock & Wilcox Co. 280 Inc.	71-0185	FBF, Inc.	280	71 (275	·	202
71-0387 Massachusetts Materials Research, Inc. 280 71-6387 Model: 60, Battelle Memorial Institute 283	71-0230	Babcock & Wilcox Co.	280	/1-02/3	_ ·	202
71-0388 Dept. of the Navy, USS Canopus 280 71-6400 Model: Super Tiger, Westinghouse Electric 283	71-0384	New England Nuclear Corp.	280	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	282
T1-0389	71-0387	Massachusetts Materials Research, Inc.	280	71-6387	Model: 60, Battelle Memorial Institute	283
71-0389	71-0388	Dept. of the Navy, USS Canopus	280	71-6400		283
71-0390 Dept. of Commerce, National Bureau of Standards Standards 280 71-6581 Model: 51032-1 & IA, Exxon Nuclear Co., 283 280 71-0391 Dept. of the Navy 280 71-6691 Model: LL-50-100, Chem-Nuclear Systems, 283 Inc. 71-6639 Model: Model: A-2, Exxon Nuclear Co., Inc. 280 71-6639 Model: Model: A-2, Exxon Nuclear Co., Inc. 280 71-6639 Model: Model: MI-1A, Dept. of the Army 283 Model: BG-48-220, Atcor, Inc. 281 71-6639 Model: Model: MI-1A, Dept. of the Army 283 Model: BG-48-220, Atcor, Inc. 281 71-6679 Model: Model: MI-1A, Dept. of the Army 283 71-5071 Model: URIPS-P-1, Dept. of the Navy 281 71-6697 Model: 8500 PKG, General Electric Co. 283 71-5364 Model: NPI-67-0442, Neutron Products, Inc. 281 71-6698 Model: NFS-4, Nuclear Fuel Services, Inc. 283 71-5450 Model: RCC-1, -2, -3, Westinghouse 281 71-6717 Model: 6717 B 284 Electric Corp. 71-6744 Model: Poly Tiger, Nuclear Engineering 284 Co. 71-5796 Model: B1361, Picker Corp. 281 71-6771 Model: SN-1, Nuclear Engineering Co. 284 71-5830 Model: SnAP 21, Dept. of the Navy 281 71-6786 Model: URIPS-8B, Dept. of the Navy 284 71-5862 Model: Sentinel-100F, Teledyne Energy 281 71-9001 Model: FL 10-1, General Electric Co. 284 71-5930 Model: GE-1500, General Electric Co. 281 71-9000 Model: FL 10-1, General Electric Co. 284 71-5940 Model: EX-16-10, Battelle Columbus 282 71-9010 Model: NLI-1/2, NL Industries, Inc. 284 71-5940 Model: EX-16-10, Battelle Columbus 282 71-9010 Model: EX-16-10, Battelle Columbus 282 71-9010 Model: EX-16-10, Battelle Columbus 282 71-9010 Model: EX-16-10, Battelle Columbus 285 71-9010 Model: EX-16-10, Battelle Columbus	71-0389	Univ. of Georgia	280	71 (552		202
T1-0391 Dept. of the Navy 280 T1-6601 Model: LL-50-100, Chem-Nuclear Systems, 283 T1-4888 Model: Sentinel-25A, B, C, C3, D, E, F, 280 T1-6639 Model: MH-1A, Dept. of the Army 283 T1-4986 Model: RA-2, Exxon Nuclear Co., Inc. 280 T1-6679 Model: MH-1A, Dept. of the Army 283 T1-5026 Model: BC-48-220, Atcor, Inc. 281 T1-6679 Model: 1/2 Super Tiger, Nuclear Engineering Co. 283 T1-5071 Model: URIPS-P-1, Dept. of the Navy 281 T1-6697 Model: 8500 PKG, General Electric Co. 283 T1-5364 Model: NPI-67-0442, Neutron Products, Inc. 281 T1-6698 Model: NFS-4, Nuclear Fuel Services, Inc. 283 T1-5450 Model: RCC-1, -2, -3, Westinghouse 281 T1-6717 Model: 6717 B 284 Electric Corp. 281 T1-6714 Model: Poly Tiger, Nuclear Engineering 284 Co. T1-5796 Model: B1361, Picker Corp. 281 T1-6771 Model: SN-1, Nuclear Engineering 284 T1-5830 Model: SNAP 21, Dept. of the Navy 281 T1-6786 Model: URIPS-8B, Dept. of the Navy 284 T1-5862 Model: Sentinel-100F, Teledyne Energy 281 T1-6786 Model: B1361, Picker Co. 284 T1-5930 Model: Sentinel-100F, Teledyne Energy 281 T1-9001 Model: F1-300, General Electric Co. 284 T1-5930 Model: GE-1500, General Electric Co. 281 T1-9009 Model: FL 10-1, General Electric Co. 284 T1-5930 Model: EX-16-10, Battelle Columbus 282 T1-9010 Model: EM-1-7, Lindustries, Inc. 284 T1-5940 Model: EX-16-10, Battelle Columbus 282 T1-9010 Model: EM-1-00-00004, Dept. of Transportation Transpor	71-0390		280			
Ti-4888 Model: Sentinel-25A, B, C, C3, D, E, F, Z80 Inc. Teledyne Energy Systems Ti-6639 Model: MH-1A, Dept. of the Army 283 Ti-5940 Model: RA-2, Exxon Nuclear Co., Inc. 280 Ti-6679 Model: MH-1A, Dept. of the Army 283 Ti-5940 Model: BC-48-220, Atcor, Inc. 281 Ti-6679 Model: 1/2 Super Tiger, Nuclear 283 Engineering Co. 283 Ti-5071 Model: URIPS-P-1, Dept. of the Navy 281 Ti-6679 Model: 8500 PKG, General Electric Co. 283 Ti-5364 Model: NPI-67-0442, Neutron Products, Inc. 281 Ti-6698 Model: NFS-4, Nuclear Fuel Services, Inc. 283 Ti-5450 Model: RCC-1, -2, -3, Westinghouse 281 Ti-6717 Model: 6717 B 284 Electric Corp. Ti-6744 Model: Poly Tiger, Nuclear Engineering 284 Co. Co.	71-0391	Dept. of the Navy	280			
71-4986 Model: RA-2, Exxon Nuclear Co., Inc. 280 71-5026 Model: BC-48-220, Atcor, Inc. 281 71-5027 Model: BC-48-220, Atcor, Inc. 281 71-5036 Model: BC-48-220, Atcor, Inc. 281 71-5040 Model: URIPS-P-1, Dept. of the Navy 281 71-5364 Model: NPI-67-0442, Neutron Products, Inc. 281 71-5450 Model: RCC-1, -2, -3, Westinghouse 281 71-5450 Model: RCC-1, -2, -3, Westinghouse 281 71-5607 Model: GE T-2, General Electric Co. 281 71-5796 Model: 181361, Picker Corp. 281 71-5830 Model: SNAP 21, Dept. of the Navy 281 71-5840 Model: SNAP 21, Dept. of the Navy 281 71-5852 Model: Sentinel-100F, Teledyne Energy 281 71-5926 Model: GE-1500, General Electric Co. 281 71-5939 Model: GE-1500, General Electric Co. 281 71-5940 Model: GE-1500, General Electric Co. 281 71-5940 Model: GE-700, General Electric Co. 282 71-5942 Model: GE-700, General Electric Co. 282 71-5957 Model: BM1-1, Dept. of Energy 282 71-5957 Model: BM1-1, Dept. of Energy 282 71-5957 Model: BM1-1, Dept. of Energy 282	71-4888		280	71-6601		283
71-5026 Model: BC-48-220, Atcor, Inc. 281 71-6679 Model: I/2 Super Tiger, Nuclear Engineering Co. 283	71-4986		280	71-6639	Model: MH-1A, Dept. of the Army	283
71-5364 Model: NPI-67-0442, Neutron Products, Inc. 281 71-6698 Model: NFS-4, Nuclear Fuel Services, Inc. 283 71-5450 Model: RCC-1, -2, -3, Westinghouse Electric Corp. 281 71-6717 Model: 6717 B 284 71-5607 Model: GE T-2, General Electric Co. 281 71-6744 Model: Poly Tiger, Nuclear Engineering Co. 284 71-5796 Model: 181361, Picker Corp. 281 71-6771 Model: SN-1, Nuclear Engineering Co. 284 71-5830 Model: SNAP 21, Dept. of the Navy 281 71-6786 Model: URIPS-8B, Dept. of the Navy 284 71-5862 Model: Sentinel-100F, Teledyne Energy Systems 281 71-9001 Model: IF-300, General Electric Co. 284 71-5926 Model: 100, General Electric Co. 281 71-9009 Model: 520, Argonne National Laboratory 284 71-5939 Model: GE-1500, General Electric Co. 281 71-9010 Model: NLI-1/2, NL Industries, Inc. 284 71-5940 Model: EX-16-10, Battelle Columbus Laboratories 282 71-9011 Model: E-MEH-00-00004, Dept. of Transportation 285 71-5942 Model: GE-700, General Electric Co. 282 71-9015 Model: TN-8, Tran				71-6679		283
71-5450 Model: RCC-1, -2, -3, Westinghouse Electric Corp. 281 71-6717 Model: 6717 B 284 71-5607 Model: GE T-2, General Electric Co. 281 71-6744 Model: Poly Tiger, Nuclear Engineering Co. 284 71-5796 Model: 181361, Picker Corp. 281 71-6771 Model: SN-1, Nuclear Engineering Co. 284 71-5830 Model: SNAP 21, Dept. of the Navy 281 71-6786 Model: URIPS-8B, Dept. of the Navy 284 71-5862 Model: Sentinel-100F, Teledyne Energy Systems 281 71-9001 Model: IF-300, General Electric Co. 284 71-5926 Model: 100, General Electric Co. 281 71-9007 Model: 520, Argonne National Laboratory 284 71-5939 Model: GE-1500, General Electric Co. 281 71-9009 Model: FL 10-1, General Electric Co. 284 71-5940 Model: EX-16-10, Battelle Columbus Laboratories 282 71-9010 Model: NLI-1/2, NL Industries, Inc. 285 71-5942 Model: GE-700, General Electric Co. 282 71-9015 Model: TN-8, Transnuclear, Inc. 285 71-5957 Model: BMI-1, Dept. of Energy 282	71-5071	Model: URIPS-P-1, Dept. of the Navy	281	71- 6697	Model: 8500 PKG, General Electric Co.	283
Ti-5607 Model: GE T-2, General Electric Co. 281 Ti-6744 Model: Poly Tiger, Nuclear Engineering 284	71-5364	Model: NPI-67-0442, Neutron Products, Inc.	281	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	283
71-5607 Model: GE T-2, General Electric Co. 281 Co. 71-5796 Model: 181361, Picker Corp. 281 71-6771 Model: SN-1, Nuclear Engineering Co. 284 71-5830 Model: SNAP 21, Dept. of the Navy 281 71-6786 Model: URIPS-8B, Dept. of the Navy 284 71-5862 Model: Sentinel-100F, Teledyne Energy 281 71-9001 Model: IF-300, General Electric Co. 284 71-5926 Model: 100, General Electric Co. 281 71-5939 Model: GE-1500, General Electric Co. 281 71-5940 Model: EX-16-10, Battelle Columbus 282	71-5450		281	71-671 7	Model: 6717 B	284
71-5830 Model: SNAP 21, Dept. of the Navy 281 71-6786 Model: URIPS-8B, Dept. of the Navy 284 71-5862 Model: Sentinel-100F, Teledyne Energy 281 71-9001 Model: IF-300, General Electric Co. 284 71-5926 Model: 100, General Electric Co. 281 71-5939 Model: GE-1500, General Electric Co. 281 71-5940 Model: EX-16-10, Battelle Columbus 282 Laboratories 71-9010 Model: NLI-1/2, NL Industries, Inc. 284 71-5942 Model: GE-700, General Electric Co. 282 71-5957 Model: BMI-1, Dept. of Energy 282	71-5607	Model: GE T-2, General Electric Co.	281	71-6744		284
71-5862 Model: Sentinel-100F, Teledyne Energy Systems 281 71-9001 Model: IF-300, General Electric Co. 284 71-5926 Model: 100, General Electric Co. 281 71-9007 Model: 520, Argonne National Laboratory 284 71-5939 Model: GE-1500, General Electric Co. 281 71-9009 Model: FL 10-1, General Electric Co. 284 71-5940 Model: EX-16-10, Battelle Columbus Laboratories 282 71-9010 Model: NLI-1/2, NL Industries, Inc. 284 71-5942 Model: GE-700, General Electric Co. 282 71-9011 Model: E-MEH-00-00004, Dept. of Transportation 71-5957 Model: BMI-1, Dept. of Energy 282 71-9015 Model: TN-8, Transnuclear, Inc. 285	71-5796	Model: 181361, Picker Corp.	281	71- 6771	Model: SN-1, Nuclear Engineering Co.	284
T1-5926 Model: 100, General Electric Co. 281 T1-9007 Model: 520, Argonne National Laboratory 284	71-5830	Model: SNAP 21, Dept. of the Navy	281	71-6786	Model: URIPS-8B, Dept. of the Navy	284
71-5926 Model: 100, General Electric Co. 281 71-5939 Model: GE-1500, General Electric Co. 281 71-5940 Model: EX-16-10, Battelle Columbus 282	71-5862		281	71-9001	·	284
71-5939 Model: GE-1500, General Electric Co. 281 71-5940 Model: EX-16-10, Battelle Columbus 282 Laboratories 71-9011 Model: E-MEH-00-00004, Dept. of 285 71-5942 Model: GE-700, General Electric Co. 282 71-5957 Model: BMI-1, Dept. of Energy 282	71-5926	Model: 100, General Electric Co.	281		· •	284
71-5940 Model: EX-16-10, Battelle Columbus 282 Laboratories 71-9011 Model: E-MEH-00-00004, Dept. of 285 71-5942 Model: GE-700, General Electric Co. 282 71-5957 Model: BMI-1, Dept. of Energy 282	71-5939	Model: GE-1500, General Electric Co.	281			284
71-5942 Model: GE-700, General Electric Co. 282 71-5957 Model: BMI-1, Dept. of Energy 282 Transportation 71-9015 Model: TN-8, Transnuclear, Inc. 285	71-5940	Model: EX-16-10, Battelle Columbus	282		Model: NLI-1/2, NL Industries, Inc.	284
71-5957 Model: BMI-1, Dept. of Energy 282 71-5957 Model: TN-8, Transnuclear, Inc. 285				71-9011		285
		•		71-9015	Model: TN-8, Transnuclear, Inc.	285
	71-5957	Model: BMI-1, Dept. of Energy	282	71-9016	Model: TN-9, Transnuclear, Inc.	285

Docket	Name	Page	Docket	Name	Page
71-9018	Model BU-6, General Electric Co.	285	71- 9 089	Model: HN-100 S, Hittman Nuclear & Development Corp.	287
71-9019	Model: BU-7, General Electric Co.	285	71-9091	Model: 30 A; General Electric Co.	287
71-9023	Model NLI-10/24, NL Industries, Inc.	285		·	287
71-9032	Model: 650, Technical Operations, Inc.	285	71-9093	Model: HN-400, Hittman Nuclear & Development Corp.	207
71-9039	Model: 715, Technical Operations, Inc.	285	71-9094	Modei: CNS1-14-195-H, Chem-Nuclear Systems, Inc.	287
71-9044	Model: GE-1600, General Electric Co.	285	71-9096	Model: CNSI-21-300, Chem-Nuclear	287
71-9045	Model: GE-1000, General Electric Co.	286	71-9090	Systems, Inc.	207
71-9046	Model: GE-1100, General Electric Co.	286	71-9103	Model: NLI-6502	288
71-9050	Model: GE-900, General Electric Co.	286	71-9111	Model: CN6-80A, Chem-Nulcear Systems, Inc.	288
71-9051	Model: GE-1400, General Electric Co.	286	71-9113	Model: 7-100, Chem-Nuclear Systems, Inc.	288
71-9070	Model: N-55, Dept. of Energy	286		,	
71-9071	Model: AP-101, Chem-Nuclear Systems,	286	71-9132	Model: T-3, Nuclear Packaging, Inc.	288
	Inc.		71-9135	Model: Century, Gamma Industries	288
71-9073	Model: OH-142, Nuclear Packaging, Inc.	286	71-9138	Model: 78-D-1458, Dept. of the Navy	288
71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	286	71-9141	Model: 900 Type B, Technical Operations, Inc.	288
71-9081	Model: CNSI-1600, Chem-Nuclear Systems, Inc.	287	71-9853	Model: ORNL — BNL — NBS Unirradiated Full Container,	288
71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	287		Dept. of Energy	

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	26	Calloway Plant, Unit 2	STN-50-486	235
Allens Creek Nuclear Station, Unit 1	50-466	230	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	112
Allens Creek Nuclear Station, Unit 2	50-467	232	. Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	113
Arkansas Nuclear One, Unit 1	50-313	107	Carroll Facility [50-599	266
Arkansas Nuclear One, Unit 2	50-368	180	Carroll Facility II	50-600	266
Duane Arnold Energy Center	50-331	143	Catawba Nuclear Station, Unit 1	50-413	204
B-SAR-205	STN-50-561	263	Catawba Nuclear Station, Unit 2	50-414	205
Bagnac Nuclear Power Project, Philippines	STN-50-574	265	Cherokee Nuclear Station, Unit 1	STN-50-491	239
Bailly Generating Station	50-367	179	Cherokee Nuclear Station, Unit 2	STN-50-492	239
Beaver Valley Power Station, Unit 1	50-334	147	Cherokee Nuclear Station, Unit 3	STN-50-493	240
Beaver Vailey Power Station, Unit 2	50-412	204	Chin-Shan Power Reactor, Unit 1, Taiwan	50-392	196
Bellefonte Nuclear Plant, Unit 1	50-438	213	Clinch River Breeder Reactor	50-537	257
Bellefonte Nuclear Plant, Unit 2	50-439	214	Clinton Power Station, Unit 1	50-461	229
Big Rock Point Nuclear Power Plant	50-155	15	Clinton Power Station, Unit 2	50-462	230
Black Fox Station, Unit 1	STN-50-556	263	Columbia Univ. Research Reactor	50-208	21
Black Fox Station, Unit 2	STN-50-557	263	Comanche Peak Steam Electric Station,	50-445	218
Braidwood Station, Unit 1	50-456	226	Unit 1		
Braidwood Station, Unit 2	50-457	227	Comanche Peak Steam Electric Station, Unit 2	50-446	221
Browns Ferry Nuclear Power Station, Unit 1	50-259	43	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	109
Browns Ferry Nuclear Power Station, Unit 2	50-260	45	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	110
Browns Ferry Nuclear Power Station, Unit 3	50-296	90	Cooper Nuclear Station	50-298	92
Brunswick Steam Electric Plant, Unit 1	50-325	131	Cornell Univ. Research Reactor	50-157	17
Brunswick Steam Electric Plant, Unit 2	50-324	129	Crystal River Nuclear Plant, Unit 3	50-302	94
Byron Station, Unit 1	50-454	224	Davis-Besse Nuclear Power Station, Unit 1	50-346	164
Byron Station, Unit 2	50-455	225	Davis-Besse Nuclear Power Station, Unit 2	50-500	246
Calloway Plant, Unit 1	STN-50-483	234	Davis-Besse Nuclear Power Station, Unit 3	50-501	246

Name	Docket	Page	Name	Docket	Page
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	62	Shearon Harris Nuclear Power Plant, Unit 3	50-402	200
Diablo Canyon Nuclear Power Plant, Unit 2	50-32 3	126	Shearon Harris Nuclear Power Plant, Unit 4	50-403	200
Douglas Point Nuclear Station, Unit 1	50-448	224	Hartsville Nuclear Plant, Unit 1	STN-50-518	249
Douglas Point Nuclear Station, Unit 2	50-449	224	Hartsville Nuclear Plant, Unit 2	STN-50-519	250
Dow Chemical Co.	50-264	49	Hartsville Nuclear Plant, Unit 3	STN-50-520	251
Dresden Nuclear Power Station, Unit 1	50-10	9	Hartsville Nuclear Plant, Unit 4	STN-50-521	252
Dresden Nuclear Power Station, Unit 2	50-237	26	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	122
Dresden Nuclear Power Station, Unit 3	50-249	33	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
ESSAR	STN-50-591	265	Haven Nuclear Plant, Unit 1	STN-50-502	246
Joseph M. Farley Nuclear Plant, Unit 1	50-348	165	Hope Creek Nuclear Station, Unit 1	50-354	168
Joseph M. Farley Nuclear Plant, Unit 2	50-364	175	Hope Creek Nuclear Station, Unit 2	50-355	168
Enrico Fermi Atomic Power Plant, Unit 2	50-341	158	Humboldt Bay Power Plant, Unit 3	50-133	14
James A. Fitzpatrick Nuclear Power Plant	50-333	145	Indian Point Station, Unit 1	50-3	9
Floating Nuclear Plant	STN-50-437	212	Indian Point Station, Unit 2	50-247	31
Forked River Nuclear Station, Unit 1	50-363	174	Indian Point Station, Unit 3	50-286	76
Fort Calhoun Station, Unit 1	50-285	75	Iowa State Univ. Research Reactor	50-116	14
Fort Calhoun Station, Unit 2	50-548	261	Jamesport Nuclear Station, Unit 1	STN-50-516	248
Fort St Vrain Nuclear Generating Station	50-267	52	Jamesport Nuclear Station, Unit 2	STN-50-517	248
General Electric Test Reactor	50-70	13	Kewaunee Nuclear Power Plant	50-305	99
General Electric Nuclear Test Reactor	50-73	13	Ko-Ri, Unit 2, Korea	50-573	265
Georgia Institute of Technology Research	50-160	17	La Crosse Boiling Water Reactor	50-409	202
Robert Emmet Ginna Nuclear Plant, Unit I	50-244	28	LaSalle County Station, Unit 1	50-373	184
Grand Gulf Nuclear Station, Unit 1	50-416	206	LaSalle County Station, Unit 2	50-374	186
Grand Gulf Nuclear Station, Unit 2	50-417	208	Limerick Generating Station, Unit 1	50-352	166
Greene County Nuclear Power Plant	50-549	261	Limerick Generating Station, Unit 2	50-353	167
Greenwood Energy Center, Unit 2	50-452	224	Maine Yankee Atomic Power Plant	50-309	101
Greenwood Energy Center, Unit 3	50-453	224	Marble Hill Nuclear Station, Unit 1	STN-50-546	257
ek Plant	50-213	21	Marble Hill Nuclear Station, Unit 2	STN-50-547	259
ear Power Plant,	50-400	199	Massachusetts Institute of Technology Research Reactor	50-20	11
ower Plant,	50-401	199	William B. McGuire Nuclear Station, Unit 1	50-369	181

Name	Docket	Page	Name	Docket	Page
William B. McGuire Nuclear Station, Unit 2	50-370	183	Palo Verde Nuclear Station, Unit 1	STN-50-528	253
	50-538	257	Palo Verde Nuclear Station, Unit 2	STN-50-529	254
Memphis State Univ Research Reactor			Palo Verde Nuclear Station, Unit 3	STN-50-530	255
Michigan State Univ. Research Reactor	50-294	88	Palo Verde Nuclear Station, Unit 4	STN-50-592	265
Midland Plant, Unit 1	50-329	140	Palo Verde Nuclear Station, Unit 5	STN-50-593	265
Midland Plant, Unit 2	50-330	141	Peach Bottom Atomic Power Station,	50-171	17
Millstone Nuclear Power Station, Unit 1	50-245	29	Unit 1		
Millstone Nuclear Power Station, Unit 2	50-336	151	Peach Bottom Atomic Power Station, Unit 2	50-277	64
Millstone Nuclear Power Station, Unit 3	50-423	210	Peach Bottom Atomic Power Station,	50-278	66
Montague Nuclear Power Station, Unit 1	50-496	240	Unit 3	30-216	O.C
Montague Nuclear Power Station, Unit 2	50-497	240	Pebble Springs Nuclear Plant, Unit 1	50-514	248
Monticello Nuclear Generating Plant	50-263	48	Pebble Springs Nuclear Plant, Unit 2	50-515	248
National Bureau of Standards Reactor	50-184	18	Pennsylvania State Univ Research Reactor	50-5	9
National Naval Medical Center	50-170	17	Perkins Nuclear Station, Unit 1	STN-50-488	236
New Haven, Unit 1	STN-50-596	266	Perkins Nuclear Station, Unit 2	STN-50-489	
New Haven, Unit 2	STN-50-597	266	·		237
Nine Mile Point Nuclear Station, Unit 1	50-220	24	Perkins Nuclear Station, Unit 3	STN-50-490	238
Nine Mile Point Nuclear Station, Unit 2	50-410	203	Perry Nuclear Power Plant, Unit 1	50-440	215
North Anna Power Station, Unit 1	50-338	153	Perry Nuclear Power Plant, Unit 2	50-441	216
North Anna Power Station, Unit 2	50-339	155	Phipps Bend Nuclear Plant, Unit I	STN-50-553	261 262
North Anna Power Station, Unit 3	50-404	201	Phipps Bend Nuclear Plant, Unit 2	STN-50-554	86
North Anna Power Station, Unit 4	50-405	201	Pilgrim Nuclear Power Station, Unit 1	50-293	
North Carolina State Univ. PULSTAR Reactor	50-297	92	Pilgrim Nuclear Power Station, Unit 2 Plum Brook Reactor — Mock-up	50-47 1 50-185	232 18
North Carolina State Univ. Research	50-111	14	Plum Brook Research Reactor Facility	50-30	13
Reactor	30-111	14	Point Beach Nuclear Plant, Unit 1	50-266	51
North Coast Nuclear Plant, Puerto Rico	50-376	187	Point Beach Nuclear Plant, Unit 2		93
Oconee Nuclear Station, Unit I	50-269	54		50-301 50-282	73
Oconee Nuclear Station, Unit 2	50-270	56	Prairie Island Nuclear Station, Unit 1		
Oconee Nuclear Station, Unit 3	50-287	78	Prairie Island Nuclear Station, Unit 2	50-306	100
Ohio State Univ. Research Reactor	50-150	15	Quad-Cities Station, Unit 1	50-254	39
Oregon State Univ. Research Reactor	50-243	27	Quad-Cities Station, Unit 2	50-265	49
Oyster Creek Nuclear Power Plant	50-219	22	Rancho Seco Nuclear Generating Station	50-312	105
Palisades Nuclear Plant	50-255	41	Reed College Research Reactor	50-288	80

Name	Docket	Page	Name	Docket	Page
River Bend Station, Unit 1	50-458	228	Three Mile Island Nuclear Station, Unit 1	50-289	80
River Bend Station, Unit 2	50-459	228	Trojan Nuclear Plant	50-344	159
H. B. Robinson Plant, Unit 2	50-261	47	Turkey Point Plant, Unit 3	50-250	35
Rockwell International Corp. Critical Facility	50-147	15	Turkey Point Plant, Unit 4	50-251	37
RPI Critical Experiment	50-225	26	UCLA Training Reactor	50-142	15
Salem Nuclear Generating Station,	50-272	59	Union Carbide Research Reactor	50-54	13
Unit 1			Univ. of California	50-357	169
Salem Nuclear Generating Station, Unit 2	50-311	103	Univ. of California at Santa Barbara Research Reactor	50-433	212
San Onofre Nuclear Station, Unit 1	50-206	19	Univ. of California Research Reactor	50-224	25
San Onofre Nuclear Station, Unit 2	50-361	171	Univ of Florida Training Reactor	50-83	14
San Onofre Nuclear Station, Unit 3	50-362	173	Univ. of Lowell Research Reactor	50-223	25
Scabrook Nuclear Station, Unit 1	50-443	216	Univ. of Maryland Research Reactor	50-166	17
Scabrook Nuclear Station, Unit 2	50-444	217	Univ. of Michigan Research Reactor	50-2	9
Sequoyah Nuclear Plant, Unit 1	50-327	133	Univ. of Missouri Research Reactor	50-186	18
Sequoyah Nuclear Plant, Unit 2	50-328	137	University of Texas Research Reactor	50-192	18
Shoreham Nuclear Power Station	50-322	125	Vallecitos Boiling Water Reactor	50-18	11
Skagit Nuclear Power Project, Unit 1	STN-50-522	252	Vermont Yankee Nuclear Power Station	50-271	58
Skagit Nuclear Power Project, Unit 2	STN-50-523	253	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	211
South Texas Project, Unit 1	STN-50-498	240	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	211
South Texas Project, Unit 2	STN-50-499	243	Washington State Univ. Research Reactor	50-27	12
Stanford Univ. Research Reactor	50-141	15	Waterford Generating Station, Unit 3	50-382	187
Sterling Power Project, Nuclear, Unit 1	STN-50-485	235	Watts Bar Nuclear Plant, Unit 1	50-390	193
St. Lucie Plant, Unit 1	50-335	149	Watts Bar Nuclear Plant, Unit 2	50-391	195
St Lucie Plant, Unit 2	50-389	192	West Valley Reprocessing Plant	50-201	18
Virgil C. Summer Nuclear Station, Unit 1	50-395	196	West Virginia Univ. Research Reactor	50-129	14
Surry Power Station, Unit 1	50-280	68	Wolf Creek Generating Station	STN-50-482	233
Surry Power Station, Unit 2	50-281	71	WPPSS Nuclear Project, Unit 1	50-460	229
Susquehanna Steam Electric Station,	50-387	188	WPPSS Nuclear Project, Unit 2	50-397	197
Unit 1			WPPSS Nuclear Project, Unit 3	STN-50-508	247
Susquehanna Steam Electric Station, Unit 2	50-388	190	WPPSS Nuclear Project, Unit 4	50-513	247
Texas A&M Univ. Research Reactor	50-128	14	WPPSS Nuclear Project, Unit 5	STN-50-509	247

Name	Docket	Page	Name	Docket	Page
Yankee-Rowe Nuclear Power Station	50-29	13	William H. Zimmer Nuclear Station, Unit 1	50-358	169
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	263	Zion Nuclear Power Station, Unit 1	50-295	88
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	264	Zion Nuclear Power Station, Unit 2	50-304	97

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NY

- BOO6170395 Forwards Waste Packaging Insp Rept 80-20 on 80012B-0201 No noncompliance noted SMITH, 0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch BO/04/24 2pp
- ---8006170398 Waste Packaging Insp Rept 80-02 on 800128-0201 No noncompliance noted Major areas inspected waste shipments & packages.vehicle placarding, packaging conditions & labels BOOK.H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch THOMAS.R D Region 5. San Francisco, Office of the Director BROWNE.W G Advanced Fuel & Spent Fuel Licensing Branch 80/03/31 10pp
- 8006190243 Forwards Waste Packaging Insp Rept 80-09 on 800121-25 No noncompliance noted SMITH, Q H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006190249 Waste Packaging Insp Rept 80-09 on 800121-25
 No noncompliance noted Major areas inspected vehicle
 placarding, packaging conditions & packaging marking
 800K.H E Region 5, San Francisco, Fuel Facility & Materials
 8afety Branch FONO.F T , THOMAS,R D Region 5, San Francisco,
 Office of the Director 80/03/25 5pp

DOCKET 27-039 SHEFFIELD, IL , NUCLEAR ENGINEERING CO

- BOO6120070 Forwards combined IC Investigation Repts 50-054/80-01 27-0048/80-01:27-0039/80-01:30-05986/80-01 & 70-0687/80-01 NRC has proposed civil penalties to Union Carbide:Bmith Kline & French Labs Respective states & DOT notified ORIER.B H Region 1, Philadelphia, Office of the Director 80/04/18 2pp
- --8006120095 IE Combined Investigation Repts 50-054/80-01,27-0048/80-01, 27-0039/80-01,30-05986/80-01 & 70-0697/80-01 Union Carbide failed to mark bill of lading Smith Kline & French Labs failed to use proper packaging CRCCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch KINNEY.W W Region 1. Philadelphia, Office of the Director 80/03/05 44pp
- 8004200122 Exception to ASLB 790503 decision declared final per ASLB 800507 order Contrary to Atomic Energy Act & NEPA decision has compelled transportation of waste to other states w/o consideration of consequences Certificate pf Svc encl WANATA W., CANNON, J.M. American Nuclear Society 80/09/21 4pp
- 8006190335 Motion to strike ANS, Chitago Section, 800521 exception to ASLB 790503 decision Right to exceptions waived due to failure to file timely petition No discernible injury established Certificate of Svc encl
 SEKULER, 8 N Illinois, 8tate of 80/05/27 4pp
- 8006170146 Order instructing American Nuclear Soc, Chicago sections to include in brief intended to be filed in support of exception to ASLB 790303 order, response to State of IL 800527 motion to strike Parties may file similar briefs BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/05/30 2pp'
- BOO6GOO664 Advises NRC that board chairman, VP de Poix, is temporarily assuming positions of president & chief executive officer, effective immediately EABONG F Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) BO/06/03 ip

- BOO6260210 Brief on appeal in support of appellant ANS, Chicago Section, exception to ASLB 790503 order Urges that order be vacated & expansion issue be renanded to ASLB directing NRC to file EIS 3 to study site alternatives Certificate of Svc encl CANNON, J M , HANAT, S W American Nuclear Society CANNON, J W Hid-America Legal Foundation BO/06/20 16pp
- DOCKET 27-047 BARNWELL, SC . CHEM-NUCLEAR BYSTEMS
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted STCHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --8005230341 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DDT placarding requirement POTTER.J P Region 2, Atlanta, fuel Facility & Materials Bafety Branch 80/03/28 4pp
- 8006040077 Forwards Waste Packaging Insp Rept 80-05 on 800319 No noncompliance noted 8TOHR, J P Region P, Atlanta, Fuel Facility & Materials Safety Branch 80/04/14 2pp
- --B0060400B2 Waste Packaging Insp Rept 80-05 on 800319 No noncompliance noted Major areas inspected shipping paper requirements.DOT placarding requirements, radiation levels, removable contamination & prohibited articles of contents POTIER.J P. WOODRUFF, R. L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/04 6pp
- 8006170782 Forwards Waste Packaging Insp Rept 80-13 on 800313-14 No noncompliance noted SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006170788 Waste Packaging Insp Rept 80-13 on 800313-14 No noncompliance noted Major areas inspected compliance w/DOT & NRC regulations re shipping paper & placarding requirements POTTER.J P. BROWN,R A Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 App
- 8006170790 Forwards Waste Packaging Insp Rept 80-03 on 800227-27 No noncompliance noted SMITH, O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --H006170796 Waste Packaging Insp Rept 80-03 on 800227-29. No noncompliance noted Major areas inspected shipping paper requirements. DDT placarding requirements. radiation levels. removable contamination & prohibited articles or contents PEERY, W W, POTTER, J P. Region 2. Atlanto, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- B006170B22 Forwards waste packaging insp rept on B00313-14 No noncompliance noted, SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch B0/04/24 1p
- --B006170827 Waste packaging insp rept on B00313-14 No noncompliance noted Major areas inspected licenses-shipper vehicles, including shipping paper requirements, DDT placarding requirements, radiation ievels 8 marking & labeling BROWN, R.A. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch POTTER, J.P. Region 2, Atlanta, Office of the Director B0/03/28. 6pp
- 8006180092 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 ip

- --8006180093 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected licenses-shipper vehicle, including shipping paper requirements, BDT placarding requirements, radiation levels & marking & labeling PECRY, N.W. POTTER, J. P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 8006180607 Forwards waste packaging insp rept on 800313~14 No noncompliance noted SMITH.O H Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 80704/24 Zpp
- --8006180611 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles for compliance w/NRC & DOT regulations including shipping papers, placarding & radiation levels
 POTTER, J P. BROWN, R A. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 App
- 8006180617 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH, G H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/04/24 2pp
- ---8006180624 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected compliance of licensee-shipper vehicles w/NRC & DDT regulations including shipping paper & placarding requirements & radiation levels PDTTER.J P. PEERY.W W. Region 2. Attanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 8006190222 Forwards Waste Packaging Insp Rept 80-03 on 800313-14 No noncompliance noted SMITH.0 H Region I. Philadelphia. Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006190230 Waste Packaging Insp Rept 80-03 on 800313-14
 No noncompliance noted Major areas inspected compliance
 w/NRC & DOT regulations, including shipping paper, placarding
 & radiation levels
 POTTER, JP , BROWN, R A Region 2, Atlanta, Fuel Facility &
 Materials Safety Branch 80/03/28 &pp
- 8006190361 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006190371 Waste Packaging Insp Rept 80-03 on 800227-29
 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements and action levels, removable contamination & DOT marking & labeling POTTER, JP, PEERY, WW Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 8006200557 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 ip
- --8006200364 Waste Packaging Insp Rept 80-03 on 800227-29 No honcompliance noted Major areas inspected shipping paper requirements. DUT placarding requirements radiation levels & removable contamination PEERY. W W . POTTER. J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- GOOA18000B Forwards Waste Packaging Insp Rept 80-06 on 800414-15 No noncompliance noted STOHRJ P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 2pp
- --8006180012 Waste Packaging Insp Rept 80-06 on 800414-15 No noncompliance noted Major areas inspected shipping paper requirements, BDT placarding requirements, radiation jevels & removable contamination TRBUP.0 L. HGARTHUR.T C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 Spp
- 8005170270 Responds to 800129 request for technical assistance Technical assistance that NRC expects to provide involves preparation of independent site-specific environ assessment document SMITH, R D Low Level Waste Licensing Branch 80/05/15 1p
- 800619033B Requests 15 addit copies of site stabilization & closure plan & 60 copies of environ assessment to complete review distribution
 BRAGGNETTE, K.S. Low Level Waste Licensing Branch 80/05/29 ip

- 8006300462 Forwards "Preliminary Site Stabilization & Closure Plan for Barnwell Low Level Radwaste Disposal Facility," in response to NRC 800529 ltr WHITAKER.K Chem-Nuclear Systems. Inc 80/05/06 1p
- --8005300470 "Preliminary Site Stabilization & Closure Plan for Barnwell Low Level Radwaste Disposal Facility " # Chem-Nuclear Systems, Inc. 80/05/31 60pp
- DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO
- 8006120090 Forwards combined IE Investigation Repts 50-054/80-01 27-0048/80-01.27-0039/80-01.30-05986/80-01 & 70-0687/80-01 NRC has proposed civil penalties to Union Carbide Smith Kline & French Labs Respective states & DOT notified GRIER. B H Region i, Philadelphia, Office of the Director 80/04/18 2pp
- --8006120095 IE Combined Investigation Repts 50-054/80-01, 27-0048/80-01, 27-0037/80-01, 30-05986/80-01 t 70-0687/80-01 Union Carbide failed to mark bill of lading Smith Kline & French Labs failed to use proper packaging CRCCMER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch KINNEY, W W Region 1, Philadelphia, Office of the Director 80/03/05 44pp
- 8006180059 Forwards Waste Packaging Insp Rept 80-24 on 800204-15 No noncompliance noted SMITH.G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006180082 Waste Packaging Insp Rept 80-24 on 800204-15 No noncompliance noted Major areas inspected compliance of waste thipments w/NRC & DOT regulations, including vehicls placarding & package marking & labeling PECX.C C . BODK, M E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/04/02 iOpp
- 8006190159 Forwards Waste Packaging Insp Rept 80-04 on 800107-18
 No noncompliance noted
 SKITH, G H Region i, Philadelphia, Fuel Facility & Materials Safety
 Branch B0/04/24 2pp
- --800419016B Waste Packaging Insp Rept 80-04 on 800107-18
 No noncompliance noted Major areas inspected compliance of waste shipments w/NRC & DOT regulations including vehicle placarding, package conditions & marking & labeling FECK.C C Region 3, Chicago. Fuel Facility & Materials Bafety Branch THOMAG.R D. BOOK.H E Region 5, San Francisco. Fuel Facility & Materials Safety Branch B0/03/25 7pp
- 8006160245 Forwards Waste Packaging Insp Rept 80-08 on 800303 & notice of violation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/05/08 2pp
- --8006160248 Notice of violation on 800303 * Region 3. Chicago, Office of the Director 80/05/08 ip
- --B006160257 Waste Packaging Insp Rept 80-0B on 800303 Noncompliance noted failure to mark cask used to transport radwaste FISHER.W L. Region 3. Chicago, Fuel Facility & Materials Safety Branch PECK.C C Region 3. Chicago, Office of the Director 80/05/0B 2pp
- BO06050422 PNG-V-BO-036 on BO0516, NRC was notified that shipment of 74 55-gallon drums of low specific activity matl was received onsite 800515 w/one drum in damaged condition Btate of WA banned Atomic Disposal, Inc use of site THOMAS, R D Region 5, San Francisco, Office of the Director B0/03/16 1p
- 8006240289 PNO-V-80-043 on 800605.DL Ray plans to tour low level radwaste disposal site as part of day-long briefing & site tour Tour to include high level waste disposal research projects on Hanford reservation & FFTF 800%.H E Region 5, San Francisco, Office of the Director 80/06/03 1p
- 8006300664 Advises NRC that board chairman, VP de Poix, is temporarily assuming positions of president & chief executive officer, effective immediately EASUN.C F Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) 80/06/03 lp

- 8006170158 PND-V-8D-04\$ on 800603, shipment of ten drums of low level radwaste received Exam determined shipment not in compliance w/NRC regulations because of improper labels, seals, placards on trailer & improper shipping documents THOMAS, B Region 3, San Francisco, Office of the Director 80/06/04 1p
- 8006240294 PNO-V-80-044 on 800602, shipment of 132 drums of radwaste received, one w/leaking drum Leak caused contamination levels of 2,000 dpm on trailer bed \$ 1,000-1,200 on coveralls of employee Contamination cleaned up & trailer released THOMAS,R D Region 5, San Francisco, Office of the Director 80,004,014
- 8006240300 PNO-V-80-047 on 800605, shipment of 212 drums of low level radwaste received One drum had 2-inch gash in side & closure bolt on clamp ring had fallen out Second drum seeping liquid from bottom Burial permit cancelled THOMAS.R D Region 5, San Francisco, Office of the Director 80/04/05 in
- 8006240302 PND-V-80-046 on 800605, upon opening back door on trailer, 55-gailon drum of low level radwaste fell, almost striking employee Caused by improper bracing of shipment Leaking drum put into overpack & placed in disposal trench THDMAS, R D Region 5, San Francisco, Office of the Director 80/06/05 ip
- S006250189 PNO-V-80-050 on 800610.pf 128 drums of low level radwaste received, one had broken locking ring & four had loose locking rings No significant radioactive contamination WA cancelled burial permit & banned util from use of site THOMAS.R D Region 5, San Francisco, Office of the Director 80/06/10 1p

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

- 8006030027 Discusses Union Carbide Corp repts of four releases of tailings at project & remedial actions Recommends that corrective actions be incorporated into license Surface & core samples should be analyzed as shown in encl Table i WOOLBEY, R T Uranium Recovery Licensing Branch 80/05/08 5pp
- 8006070558 Advises that License 8UA-648 is amended to incorporate corrective actions noted in 790703 & 800116 repts rereleases of tailings slurry & liquid into unrestricted areas SCARANO, R A Uranium Recovery Licensing Branch 80/05/08 2pp
- 8006190037 Submits contract costs incurred & manhours used in reviewing Amend 12 to License BUA-648 submitted on 800329 KOTSCH, J Uranium Recovery Licensing Branch 80/05/13 2pp
- 800&06058& Advises of refund due re fee for manpower expenditures required for review of application for Amend 12 to License SUA-648
 MILLER, W D License Fee Management Branch 80/05/20 ip
- 8006250331 Informs that Amend 15 for License SUA--648 was issued 800608 NRC initiated amend requiring corrective actions to preclude release of tailings slurry & liquid into unrestricted areas. No fae required WOOLSEY, R. Uranium Recovery Licensing Branch 80/06/04 ip
- DUCKET 40-0645 ANACONDA CO SOUTH TEXAS URANIUM PROJECTS
- 8006300032 "App to Radon & Radon-Daughter Concentrations in Air in Vicinity of Anaconda U Mill " HOMENI, J B . DUNGEY, C E Argonne National Laboratory FIN A-2209 NUREG/CP-1133 APP 79/11/30 86pp Available at NTIS.

DOCKET 40-0672 NUCLEAR METALS, INC

- 8006200557 Forwards Waste Packaging Insp Rept 80-03 on 800227-29. No noncompliance noted. SMITH.0 H Region 1, Philadelphia. Fuel Facility & Materials Bafety Branch 80/04/24 ip
- ----9006200564 Waste Packaging Insp Rept 80-03 on 800227-27 No nuncompliance noted Major areas inspected shipping paper requirements, DDT placarding requirements, radiation levels & removable contamination PEERY, W. W. POTTER, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp

- DOCKET 40-1162 WESTERN NUCLEAR, INC.
- 8004040257 Forwards rept of 791101 observations re const of lift at site Photos for Peterson memo also encl FRANCIS,E Wyoming, State of 80/05/01 19pp
- BOO6170793 Submits evaluation of vendor permit request following BO0430 meeting Independent analyst reported that dam could fail or slough under worst case conditions Plan for monitoring plant seepage & sloughing will be required ACKERNAN.W C Wyoming. State of BO/05/07 9pp
- 8006030240 Forwards "Chronology of Events & Stability Assessments re Dump Area Split Rock Mill Tailings Retention Embankment " Rept details investigation & stability analysis of existing embankment, based on conditions at Section A-A BDGDEN: G Western Nuclear, Inc (subs of Phelps Dodge Corp) 80/05/08 tp
- ---8006030243 "Chronology of Events & Stability Assessments re Dump Area Split Rock Mill Tailings Retention Embankment " Two oversize drawings encl * D'Appolonia Consulting Engineers, Inc. 80/05/09 15pp
- 8006040096 Advises that application for permit is incomplete Specific items in adjudication file must be revised by statute Table, mapping, methods & referencing deficiencies represent urgent need for vendor to provide reclamation plan FRANCIS.E Wyoming, State of 80/05/08 10pp
- 8006120220 Responds to 800304 & 14 ltrs Authorization to charge production cost fees for public documents after extra copies have been sent encl Judicial review of final NRC actions vested in US Courts of Appeal Comments solicited SCARANO,R A Uranium Recovery Licensing Branch 80/05/09 16pp
- 800&03000t Submits trip rept re 80041& visit w/MY Dept of Environ Guality, D'Appolonia Consulting Engineers, Inc & owner to inspect excavation of test pits & visually estimate amount of debris in layer beneath tailings embankment GARCIA:PJ Uranium Recovery Licensing Branch 80/05/12 2pp
- 8006090079 Responds to 800318 itr re impact of contaminants from tailings pond Seepage has resulted in some degradation of onsite & adjacent offsite groundwater showing chemical concentrations that exceed drinking water sets

 LINEHAN, J J Uranium Recovery Licensing Branch 80/05/13 ig
- 8006090124 Responds to 800326 ltr re impact of contaminants from tailings pond Evaluation indicates seepage has resulted in degradation of onsite & offsite groundwater showing chemical concentrations that exceed drinfing water stds LINEHAN, J J Uranium Recovery Licensing Branch. 80/05/13 ip
- BOOA090139 Responds to 800324 ltr re contaminants from existing tailings pond moving underground to Bweetwater River Environ monitoring program will be conducted which includes analysis of groundwater wells

 LINEHAN, J J Uranium Recovery Licensing Branch 80/05/13 2pp
- 8006070556 Responds to 800401 ltr re mill site Forwards FES in ref to concern re surface & groundwater contamination Some onsite & offsite wells determined unsafe for drinking Licensee will be required to submit limiting plan H/o encl
 LINEHAN.J J Uranium Recovery Licensing Branch 80/05/13 2pp
- 8004240303 Forwards B Helm 800308 ltr assuring that boneyard area had been properly cleaned BOODEN,Q Hestern Nuclear, Inc (subs of Phelps Dodge Corp.) 80/05/13 lp
- --8006240306 Advises that old equipment boneyard area properly cleaned subsequent to 770412 tailing pand overtopping Nothing is ever left that could be buried in dike or could affect dike structure
 HELM.R W Western Nuclear, Inc. (subs of Phelps Dodge Corp.)
 80/05/08 2pp
- 8006240451 Forwards peptition to intervene in licensing proceeding KOZISEK, P. 8. Wyoming Outdoor Council 80/05/21 1p
- ---BO06240459 Petition to intervene in licensing proceeding alleging that groundwater adjacent to mill tailings is contaminated in excess of permitted limits Proposes hearing BOOKE.B L Hyoming Outdoor Council BOOKE.B L Booke.B.L 80/05/21 10pp

- 8006230146 Responds to 800327 ltr re FES for U mill Proposed reclamation plan provides for minimization of wind & water erosion & eliminates need for ongoing active care of tailings pile Long-term monitoring provided for in OEIS SCARANO.R A Uranium Recovery Licensing Branch 80/05/27 2pp
- 8006170806 Authorizes Williams-Robinstte & Associates to perform magnetometer survey of tailings dam Gurvey should be performed by 800607 LINSHANNJ J Uranium Recovery Licensing Branch 90/05/28 ip
- 8006250075 Responds to 800516 memo re stability of Split Rock retention dam NRC should perform magnetometer survey to define composition & extent of debris layer GARCIA.F J. Uranium Recovery Licensing Branch 80/06/04 ip
- 8006110089 Notice of appearance in proceeding Certificate of Svc encl WALPOLE, J R , KITE, M S , KIPPLN, T A Uestern Nuclear, Inc (subs of Phelps Dodge Corp) 80/06/05 3pp
- 8006300291 Forwards Figure 6 3 or FES showing suggested groundwater monitoring locations per 800318 meeting 1e NRC continuing evaluations of Split Rock mill tailings impoundment SCARANO.R A Uranium Recovery Licensing Branch 80/06/06 2pp
- 8006300660 Suggests two changes to proposed monitoring sys at site Primary purpose of monitoring program is effective containment of tailings seepage Seepage at site must be controlled not morely monitored ACKERMAN.W.C. GARLAND.B. Wyoming, State of 80/06/12 ip
- DOCKET 40-1341 EDGEMONT URANIUM HINE, TVA & MINES DEVELOPMENT, INC
- 8004120254 Forwards maps of alternative disposal Site 10 for facility decommissioning indicating geological & topographical features & subwatersheds which constitute drainage syswithin Site 10 area MiLLS:£ M Tennesses Valley Authority 80/03/25 4pp
- B006130004 Submits mods to engineering tests for determination of foundation matls at U mill disposal site Water pressure permeability test performed 40 ft below proposed bottom of impoundment rather than 40 ft from ground level MILLS.L M Tennessee Valley Authority 80/05/16 kp
- 8006190058 Summary of 800014 meeting w/util.EPA.HUD & State of SD in Denver.CO re agencies' problems in carrying out radiological monitoring program of potentially contaminated structures KILLER.H J Standardization & Special Projects Branch 80/05/22
- --800&1900&4 Forwards tentative agenda for 800512 meeting in Denver.CO Issues re environ stds.testing methodologies.protocol & monitoring priorities should be resolved RICHARDSON.J R South Dakota. State of 80/05/07 2pp
- 8006190365 Forwards minutes of 800514 meeting w/EPA.HUD.State of 80 & Edgement town officials in Denver re Edgement offsite contamination MILLER.H J Low Level Waste Licensing Branch 80/08/22 6pp
- --8006170369 Summary of 800514 meeting w/EPA.util.HUD & State of 8D in Denver re Edgemont offsite contamination MILLER.H J Low Level Waste Licensing Branch 80/05/22 ip
- --8006190375 Forwards proposed agenda for 800512 meeting in Denver re Edgement offsite contamination Emphasizes need to resolve environ stds.testing methodologies.protocol.monitoring priorities 1 data interpretation RICHARDSON.J R Bouth Dakota, State of 80/05/07 2pp
- 8006120184 Responds to FOIA request for TVA 760128 environ info rept. TVA responses to NRC comments on Edgement U Mill Jul 1976 environ info rept & analysis of decommissioning & long-term tailings stabilization Forwards documents W/o encls FELTON, J M Division of Rules and Records 80/06/03 ip
- 8006230097 Responds to FOIA request for Edgement U Mill decommissioning documents originating after Oct 1979 FOIA request Forwards listing of correspondence file for period requested Documents available in PDR M/o encl FELTON.J H Division of Rules and Records 80/06/16 1p

- DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-MCGEF CORP
- BOO6170255 Responds to 771228 ltr re facility decontamination Improved air sampling & radiation detection program established
 Region 3 periodically review air sampling data for offsite opposures
 DIRCKB, W.J. Office of Nuclear Material Safety & Safeguards
 80/03/05 3no
- 8006190121 Notification of 800520 meeting w/State of IL, Dept of Public Health, IL State Goological Survey, IL State (later Survey, City of West Chicago, ANL & EPA in Saint Charles, IL to disuces search for storage site as alternatives to present site DENNY, I L Korr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/05/09 4pp
- 8006090524 Forwards errata to B00501 comments on decommissioning plans & Dames & Moore 800501 rept Includes table of contents for decommissioning plan & App II of Dames & Moore rept BHELLEY, W.J. Kerr-Hegee Nuclear Corp. 80705/13 4pp
- 8006120236 Advises that 790725 application for renewal of License STA-583 meets timely renewal provisions of code License will remain in affect pending completion of NRC renewal review & action PAGE.R O Uranium Fuel Licensing Branch 80/05/16 1p
- DOCKET 40-2259 PATHFINDER MINES CORP
- 8006170254 Informs of calculated overexposure to soluble U Urinary analyses show TL Irvin.Gl Michaud & JC Nichols are no longer restricted to nonroutine work Supportive matl encl NUGENT.E L Pathfinder Mines Corp 80/05/15 lopp
- 8006030015 Submits contract costs & manhours used in reviewing Pathfinder Mines Corp 780526 application for Amends 3-5 & 7 to License SUA-648 re relocation of fence, mod of dam & revision to dust collection sys OILLEN.D M . LINEHAN.J J Uranium Recovery Licensing Branch 80/05/17 2pp
- 8006030038 Submits contract costs & manhours used in reviewing Pathfinder Mines Corp 790921 application for Amend 6 to License 5UA-648 re replacement of extraction circuit GILLEN, D M . LINEMAN, J J Uranium Recovery Licensing Branch 80/03/19 2pp
- 8006020509 Natifies vendor that NRC will refund portion of amend fee accompanying 790913 application for amend NRC manpower expenditures were less than originally anticipated MILLER.W G License Fee Management Branch 80/05/22 1p
- BOO6030010 Notifies vendor that NRC will refund portion of fee accompanying 780526 emend application NRC issued Amends 3,4,5 t 7 to License SUA-672 in response to application NRC manpower expenditures less than anticipated MILLER, W O License Fee Management Branch 80/05/22 ip
- 8006:80474 Advises of administrative changes, effective 8006:6 RW Payser, environ coordinator, will assume responsibilities of overseeing radiation function in mill dept NUGENT, E. Pathfinder Mines Corp 80/06/12 ip
- BOO6190595 Notifies NRC that foundation preparation for mod of Tailing Dam 4 will be completed during wk of 800707 Placement of downstream embankment fill will be concurrent w/foundation ercavation work

 NUGENT, E. L. Pathfinder Mines Corp. 80/06/13 1p
- DOCKET 40-3392 ALLIED CHEMICAL CORP
- 8006300970 Responds to NRC 800522 1tr by submitting results of exposure evaluation for employee Chest counts indicated lung burden within Reg Guides 8 ii & 8 22 limits Urinary U concentration chart encl CIPOLLA, A J Allied Chemical Corp 80/06/05 3pp
- BLANSHIM BALTA EREC-OF THAODO
- 8006120267 Forwards IE Insp Rept 40-3453/80-01 on 800403 No noncompliance noted BRQUMN.6 D Region 4. Dallas, Fuel Facility & Materials Safety Branch. 80/04/25 2pp

--8006120274 IE Insp Rept 40-3453/80-01 on 800403 No noncompliance noted Major armaes inspected const activities re raising Moab Mill tailings dam MALL:R E. Region 4. Dallas, Reactor Construction & Engineering

Mill tailings dam

HALL,R E Region 4. Dallas, Reactor Construction & Engineering

Support Branch BROWN,O D . TAPIA, J L Region 4. Dallas, Office
of the Director 80/04/25 3pp

8006200509 Responds to 800116 request for administrative amend authorizing 18-ft raise to tailings retention sys Request cannot be considered as administrative amend due to scope of review required Applicable NRC regulation encl SCARANUR A Uranium Recovery Licensing Branch 80/05/07 16pg

8006030574 Clarifies conversation w/J Deuel re ltr to Atlas Minerals concerning nest raise on tailings structure No plans exist for transporting tailing pile to some site yet to be salected
\$MANNY,0 T Atlas Minerals 80/05/08 10

DOCKET 40-4937 MARGUETTE UNIV

8006060088 Discusses IE insp of Licenses SUD-231,48-02931-06 & 48-02931-10 on 800423 & 0508 & forwards notice of violation MEPPLER.J G Region 3, Chicago, Office of the Director 80/05/21 20b

--8004060094 Notice of violation from insp on 800423 & 0508 Noncompliance noted mCi quantities of C-14 & I-131 used w/o performance of bioassays & radioactive mati user did not have proper training # Region 3, Chicago, Office of the Director 80/05/21 3pp

DUCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

8006040328 Submits add1 comments re DES for proposed facility Draft should assess cumulative effect from all sources at existing mill sites in addition to effect of proposed mill DANIELSON, L J , GUYERSON, M J National Wildlife Federation 80/04/16 Spp

8006120187 Advises that E Kemp will replace T Spisak as regulatory agency contact & coordinator WRIGHT.K H Affiliation Unknown 80/05/14 ip

8006160212 Summary of 800414 meeting w/Federal-American Partners in Bilver Spring.MD re environ rept suppl on surface tailings disposal alternatives GILLEN.D M Uranium Fuel Licensing Branch 80/05/22 2pp

8006230139 Forwards request for add1 info to be included in engineering design rept on tailings mgt alternatives Mar 1980 rept, "Suppl to Environ Rept -- Subsurface Tailings Disposal: " is inadequate Forthcoming rept must be submitted by 800616 LINEHAN, J J Uranium Recovery Licensing Branch 80/05/22 2pp

DOCKET 40-5001 AMAX ENVIRONMENTAL SERVICES, INC

8006270411 Forwards summary of 800520 meeting.re results of radiological surveys & hydrostratigraphic data conducted under License SIB-440 3 BMA-1219 O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/29

POCKET 40-6622 PATHFINDER MINES CORP

8006230163 Recommends approval of licensee 781120 request to amend License 8UA-442 eliminating Condition 28 re drain cover matt. Amend will not significantly affect environ or dam safety Graduation curves encl
PERSON: L 8 Uranium Recovery Licensing Branch 80/05/28 2pp

DOCKET 40-4459 PETROTOMICS CO . DETTY DIL

BOO6050534 Summary of BOO401 meeting w/licensee in Silver Spring,MD re license renewal application Radiological effluent & environ monitoring program entl KGTBCH.J L Uranium Recovery Licensing Branch 80/05/05 ápp DOCKET 40-7869 PLATEAU RESOURCES, LTD

8006290332 Requests approval to proceed w/covering residues from Hydro-Jet leaching facility w/mine waste HEAD.W J Plateau Rusources, Ltd 80/05/27 2pp

DOCKET 40-8027 KERR-MCGEE CORP

GOOSO90057 Forwards "Raftinate Program, 1979 Completion Rept." per License SUB-1010, Amend & Rept provides results & analyses of growing season & food Chain testing of treated raffinate produced forage during 1979 SHELLY

--8005070065 "Raffinate Fertiliter Program 1777 Completion Rept "
* Kerr-McGee Nuclear Corp 77/07/11 ip

8006090553 Application for amend of Liconse 808-1010 authorizing unlimited use of treated raffinate produced at Sequeyah facility as fertilizer Justification for propsed amend encl SHELLY:N J Kerr-McGee Nuclear Corp 80/05/16 8pp

8006090492 Requests payment of add1 ree re 800516 application for amend to License SUB-1010 Request classified as major safety & environ amend WEISS.J D License Fee Management Branch 80/05/27 ip

8006120534 Advises that major safety & environ amend fee is required for review of 800522 request to permit disposal of raffinate sludge in below grade pit
WEISS, J D Licensing Management Branch 80/06/02 1p

BOO6300026 Forwards OK State Univ 800529 itr explaining use of word "preliminary" in histopathology repts generated for vendor raffinate study Clarifies App C of 1979 raffinate fertilizer completion rept submitted to NRC on 800415
SHELLEY.W J Kerr-McGee Nuclear Corp BO/06/02 2pp

8006300645 Forwards "Benthic Macroinvertebrate Fauna of IL River Below Tenkiller Reservoir Adjacent to Effluent Outfall at Sequoyah FactilityiKerr-McGee Nuclear Corp, Gore, OK. Oct 1978-Dec 1979 " SHELLEY, W J Kerr-McGee Nuclear Corp 80/06/06 ip

---8006300649 "Benthic Macroinvertebrate Fauna of IL River Below Tenkiller Reservoir Adjacent to Effluent Dutfall of Sequoyah Facility, Kerr-McOee Corp.@ore.CK.Oct 1978-Dec 1979 " * Kerr-McOee Nuclear Corp 80/06/05 74pp

DOCKET 40-8052 MITSUI & CO (USA), INC

8006:20:79 Forwards plan to implement safeguard requirements for GNM of moderate & low strategic significance SAIKI.T Mitsui & Co . Ltd 80/05/13 9pp

DOCKET 40-8064 EXXON MINERALS CD USA, EXXON CORP

8006030124 Forwards summary of first quarter 1980 solution mine pilot operations Restoration operations provide primary source of fluids from solution mining activity to tailings pond TRUBSELL.H H Exxon Minerals Co . USA 80/04/24 13pp

DOCKET 40-8084 LISBON MINE, RIO ALGON CORP

8006040187 Application to amend License SUA-117 increasing capacity of tailings dam by reising height of existing lower pond Dames & Moore feasibility rept not enci LAWTON IN D Rio Algom. Ltd 80/03/28 2pp

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

8006230429 Notifies of exposure of individual during wk ending 800405.
airborne concentrations of soluble natural U in excess of IOCFR20 103 limits Mill dryer area washed down windication of substantial reduction in U concentration SHANNON, J B Exxon Minerals Co . USA 80/05/27 3pp

DOCKET 40-8304 MYDMING MINERAL CORP.

800606063 Summary of 800312-13 meeting w/licensee in Silver Spring, MD re status of ongoing liprovant excursion into shellow zone, increase in leachant flow 5 renewal of R&D license Licensee made commitments for add1 study & additions to amend LIREMAN, J J Uranium Recovery Licensing Branch 80/04/15 7pp

DOCKET 40-8348 IN SITU URANIUM LEACHING PROJECT

8008080006 Advises that 791026 itr requesting permission to commence surface reclamation at test site is being processed as amend to License 8UA-1223 Requests payment of Category 2B amend of her Matl license amend classification encl
WEISS.D License Fee Management Branch 80/01/3% 2pp

--B006060009 Forwards addendum to MC Goth 790124 rept "Synopsis of Research Insitu U Leaching Test Activities," providing addl data re groundwater monitoring Requests permission to commence surface reclamation CARLOS.P C Union Minerals 79/10/26 ip

--8006060012 Addendum to "Symposis of Research Insity U Leaching Project" entitled "Results of Aquifier Stabilization Observation & Other Surveys ' * Minerals Exploration Co (subs of Union Oil Co of California) 79/10/24 36pp

BOO6190051 Requests info to compliance w/new Chapter 14 regulations re in situ mining by BOO525 & advises that additestoration work on aquifer may be required if water sample analyses are not favorable are not favorable
ENGELMANN.R Wyoming State of 80/04/22 ip

DOCKET 40-8355 AMAX ENVIRONMENTAL SERVICES, INC.

8006270411 Forwards summary of 800520 meeting re results of radiological surveys & hydrostratigraphic data conducted under License 818-440 / 884-1219

O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29

DOCKET 40-9380 ROCKY MOUNTAIN FUERBY CO.

8006190344 Requests correction of 800331 amend request Line 4, Paragraph 1.Page 12 of request should read "sampling will be weekily," instead of "daily" Daily sampling of excursion well not nocessary

NEUMANN.M R Rocky Mountain Energy Co 80/05/06 2pp

BOO6170670 Forwards add1 sample results from BO0401-16 sampling of Pattern III monitor wells Well M-40 back within baseline range for parameters except U less than 1 2 mg/l Well M-43 still shows U & vanadium levels above baseline NEUMANN, M R Rocky Mountain Energy Co BO/05/14 App

8006240271 Forwards encl to in situ R&D license, per Chapter XIV mining requirements NEUHANN, M.R. Rocky Mountain Energy Co. 80/05/27 2pp

B006260079 Forwards executed application for in situ research testing license Form should be considered part of original license application submitted in accordance w/State of HY, Dept of Environ Quality regulations
IHANICKI.R E Rocky Mountain Energy Co B0/06/04 IP

DOCKET 40-8434 HOME STATE HINING CO LA

8005270286 Forwards overstied drawings for license renewal application for Source Matis License SUA-1247.per 800117 telcon RANSONE, J W Homestake Mining Co 80/01/17 2pp

---8005270296 "Flow Diagram Ion Exchange Circuit MANLEY.E Homestake Mining Co 79/12/31

--8005270304 "Proposed Project Site "
MANLEY/E A Homestake Mining Co 80/01/31 ip

--9005270310 Submits proposed program describing experimental ion exchange plant Plant will be located at LaSal mine site, area previously disturbed by mining activities & within permitted area of ACT/037/037 RANSOME. .. II Homestake Mining Co 80/01/14 4pp

DOCKET 40-8452 BEAR CREEK URANIUM CO

8006120101 Responds to NRC 800506 comments re tailings dam & tailings basin Incremental areas requiring compaction work will be staked & stripped of topsoil Sufficient clay matls will be added to compact areas to required permeabilities MEDLDCK.R L. Bear Creek Unanium Co. 80/05/19 2pp

8006230708 Requests technical assistance to review proposed dam raise 5 reclamation plan.per 790314 memo Safety evaluation summarizing hydrologic aspects of review should be completed by 800609 SCARAND, R. A. Uranium Recovery Licensing Branch 80/05/23 ip

DOCKET 40-8502 IRIGARAY MINE, WYDMING MINING CORP.

800606063 Summary of 800312-13 meeting w/licensee in Silver Spring, MD re status of ongoing lixiviant excursion into shallow zone, increase in leachant flow & renewal of R&D license Licensee made commitments for add study & additions to amend LINEMAN, J J Uranium Recovery Licensing Branch 80/04/15 7pp

8006050164 Forwards weekly water quality analysis results for shallow monitor & shallow research wells for 800325,0402 & 08 Pierometric contour maps, arsenic & selenium assay results & maps of new shallow iseaarch well locations WICHERS.D L. Wyoming Mineral Corp. 80/04/16 28pp

---800605016B "Production Units 1.2.3.4.5 % 6 Research Helk Locations.
Pleiometric Contours " Sheet 1 of 1
Wyoming Mineral Corp 80/04/16 1p

--- 8006050172 "Production Units 1,2,3,4,5 % 6 Research Well Locations "

Wyoming Mineral Corp 80/04/06 ip

800609000B Forwards alternate lixiviant restoration progress rept for Well Field E Field A restoration plan not yet approved by NRC erc WICHERS,D Wyoming Mineral Corp 80/04/24 15pp

8004030153 Expresses concern re recent NRC action concerning U mining site Economy of City of Buffalo, NY will suffer severe & immediate setbacks if work at mine is curtailed or HECHTLE O , KNEBELLJ A , MONEY, G F Buffalo, NY 80/04/25 ip

8006080535 Urges NRC to combat regulatory measures which resulted in closing of facility Many persons besides licensee employees will lose their jobs.causing tremendous economic dislocation in surrounding area OARLAND.R Amearth Excavators 80/04/25 1p

BOO4070028 Urges NRC to appose regulatory measures that led to closing of mining site Curtailment of operations will have tramendous adverse impact on local economy Many persons besides those on corp payroil will lose jobs RG8S.9 L Ross Construction Co 80/04/25 ip

B006020101 Opposes closing of mining operations Closing would be severe loss to Johnson County & Buffalo, WY COOK, J.H. Affiliation Unknown 80/04/26 ip

8006020567 Forwards info re composition of lixiviant at site in response to request re 800421 show cause order DIRCKS; M J Office of the Executive Director for Operations 80/04/28 2pp

8006020570 Notifies State of WY Dept of Environ Quality that closure of in-situ U mine will affect business operations resulting in lay-offs Emphasizes that in-situ operation minimizes effects of mining on environ
LARKIN,D H , LARKIN,J C Affiliation Unknown 80/04/28

8004120504 Responds to request to revise Permit 478 changing lixiviant to sodium bicarbonate Advises that proposed change in lixiviant is conditionally approved MORROW.D Wyoming, State of 80/05/09 2pp

8006060431 Forwards biweekly status rept of shallow monitor zone Info includes water quality analysis results, oversize piezometric & contour maps, arsenic & selenium assay results & monitoring data for Wells 8M-9 & 8M-17 WICHERS, D L. Wyoming Mineral Corp 80/05/12 10pp

- 8006120163 Forwards "Answer of WY Mining Corp to Order to Show Cause "Requests NRC take promp# action to lift show cause order TIEPEL,E W Wyoming Mineral Corp 80/05/12 ip
- ---8006120173 Answer to order to show cause Asserts that order was unwarranted No public health safety of other interest is jeopardized by continued operation Requests NRC take prompt action to lift order TIEPEL, E W Wyoming Mineral Corp 80/05/12 10pp
- BOO6050444 Forwards "Irigaray Shallow Zone Evaluation Rept " Presents data to fulfill requirements for lifting immediate effectiveness of 800421 show cause order TIEPEL,E W Wyoming Mineral Corp BO/05/16 2pp
- Wyoming Mineral Corp 80/05/16 54pp
- 8006240247 Forwards NRC 800421 order to show cause directing shutdown of facility in response to 800507 ltr No similar action contemplated for Rocky Mountain Energy Co or Nine Lake SCARAND, R A Uranium Recovery Licensing Branch 80/05/20 ip
- 8004180282 Ack receipt of 800509 ltr which approves use of sodium bicarbonate-based lixiviant at site Use of ammonia-based lixiviant in all production units will be discontinued & Permit 478 revised to incorporate change in lixiviant WICHERS.D L. Wyoming Mineral Corp. 60/05/22 ip
- 8006170127 Advises of approval of WY Minerals Curp application for Amend 2 to License SUA-1341 authorizing use of sodium bicarbonate in place of ammonium-bearing lixiviant KAUFMANN.R S Uranium Recovery Licensing Branch 80/05/23 2pp
- 8006200566 Confirms BD0523 teleon advising that order has been issued allowing commencement of injection of sodium carbonate/bicarbonate lixiviant into well field at Irigaray U Bolution Mining Project Amend 2 to Source Matl License SUA-1341 encl SCARAND.R A Uranium Recovery Licensing Branch 80/05/23 ip
- --8006200548 Order modifying license & terminating 800421 show cause MARTIN, J B Division of Waste Management 80/05/23 App
- ~-8006200570 Amends Source Matl License SUA-1341 by revising Conditions 10 & 33 Amend authorizes U recovery from max of 50 atres of well field by in situ solution extraction from U ore bodies SCARANO,R A Unanium Recovery Licensing Branch 80/05/23 ip
- 8006200640 Advises of 800523 discussions w/8tate of WY prior to issuance of 800523 order to licensee Resumption of operation is limited to Units 1-5 at present time Unit 4 will be LINEHAN, J.J. Uranium Recovery Licensing Branch 80/05/27 1p
- BOO6230jii Concurs w/mod of order to allow WY Minerals to resume operations Use of sodium bicarbonate rather than ammonium bicarbonate in units authorized Staff has not had chance to review water quality analysis

 ACKERMAN, W C Wyoming, State of BO/05/2B ip
- 8006290326 Summary of 800507 meeting w/WY Mining Corp in Rolla, MD re NRC evaluation of vendor analysis of available geologic & hydrogeologic data KAUPMANN, R S Uranium Recovery Licensing Branch 80/06/04 3pp
- 8006300118 Requests water quality analysis on newly drilled shallow monitor wells & shallow sand monitor wells MDRROW,D Wyoming, State of 80/06/12 ip

DOCKET 40-8576 EDLON INTERNATIONAL CO

- 8006200237 Ack receipt of 800430 ltr informing NRC of steps taken to correct violations noted in NRC 791204 ltr CROCKER,H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80705720 ip
- ---B00&20024B Responds to NRC 791204 ltr re violations noted during IE insp Corrective actions will provide procedures for instructions on basics of radiation, radiation protection & emergency response Matl storage area relocated HARMON, D W Edlow International Co B0/04/30 11pp

- DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO
- 800&040183 Forwards revised environ monitoring procedures & fee for administrative amend to License SUA-1350, per 800407 telcon ACOSTA, A P Union Minerals 80/04/11 3pp
- 8006020533 Advises NRC that fill placement has resumed on Cell C of subsurface tailings impoundment at U project Revised tentative date for commencement of tailings cell liner installation is 800616 ACOSTA, A P Union Minerals 80/05/08
- 800616020B Advises that mill startup date has been scheduled for 800815 per 790216 cover ltr for License SUA-1350 ACOSTA: A F Union Minerals 80/05/14 1p
- 8006270263 Forwards annual revision of reclamation bond including mill decommissioning mill site & tailings dam reclamation Summary breakdown of costs associated w/reclaiming mill & tallings area emct ACCSTA,A P Union 76 Minerals Exploration Co 80/06/19 7pp
- DUCKET 40-8681 ENERGY FUELS NUCLEAR, INC.
- 8006270093 DFS re operation of White Mesa V Project * Office of Nuclear Material Safety & Safeguards NUREG-0494 78/12/31 200pp
- 8006030088 Advises of 800404 training session ie radon & radom progeny sampling EADIE, G.G. Uranium Recovery Licensing Branch 80/04/01 1p
- 8006120459 Forwards administrative fee for amend to License SUA-1358 QLASSIER O C Energy Fuels Nuclear. Inc 80/05/08 2pp
- 8006180156 Responds to 800522 request to provide written info re proposal to expand White Mesa U mill Proposal will involve enlarging mill to 3.111-3.511 TPD capacity, w/associated enlargement of tailings disposal facility BAKER, C E Energy Fuels Nuclear. Inc 80/05/22 2pp
- B006240531 Confirms B00522 telcon stating wishes to revise position re archaeological data recovery program changes at White Mesa U project Seeks relief in form of license amend re testing of undetermined sites & 1982 completion date BAKER.C E Energy Fuels Nuclear, Inc 80/05/23 2pp
- 8006200589 Discusses problems re memorandum of agreement concerning U mill site Problems relate to Energy Fuels Nuclear interpretation of memorandum & Insuring that artifacts are not transported out of state Related matl encl BMITH.M T Utah. State of B0/05/28 26pp
- 8006300281 Forwards IE Insp Rept 40-8681/80-02 on 800805 No noncompliance noted BROWN-0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/05/28 2pp
- --8006300285 TE Insp Rept 40-8681/80-02 on 800505 No moncompliance noted Major areas inspected U mill preoperation including organization & administration WILBORN.L Region 4, Dallas, Office of the Director BR Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/05/27 4pp BROUN, D. D.
- 8006200634 Forwards State of UT 800521 Itr & Energy Fuels Nuclear, Inc 800516 & 07 itrs re White Mess aichaeological data recovery Expresses concern re removal of J Dykeman from project BAKER.C E Energy Fuels Nuclear. Inc 80/05/29 7pp
- 8006300461 Requests payment of fre associated w/800523 request for relief from License Conditions 41 & 47 of License 8UA-1358 Request requires major safety & environ fee HEISS.J D License Fee Management Branch 80/06/06 Ip

DOCKET 40-8664 J & P CORP

8006050510 Notifies NRC that no activities have been started under License SUA-1337 Licensee is acquiring baseline data & studying another potential R&D site NRC will be notified when test plans & schedules become definitive BELING.D G J&P Corp 80/05/05 ip

DOCKET 40-8693 OGLE PETROLEUM, INC.

8006020034 Forwards quarterly rept for License SUA-1373 Rept indicates no leach solution excursions b radiation levels within safe ranges b below working levels
HERLINY,D Teton Exploration Drilling Co , Inc. 80/04/09 ip

--8006020037 "Decrational Summary," quarterly sept

* Teton Exploration Drilling Co., inc. 80/04/09 155pp

8006090004 Forwards "Upper Control Limits for Excursion Indicators "HERLIHY.D Teton Exploration Drilling Co., Inc. 60/04/22 2pp

8006040063 Forwards additional content of final restoration rept for plint phase of project M/o rept CATCHPOLE.G J Ogle Petroleum Inc 80/05/09 ip

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

BOOAGAGOBP Forwards application to amend license BUA-133B to allow use of carbonate rather than acid lixiviant % to change procedures associated wives of carbonate lixiviant Fee enci NEUMANN: M R Rocky Mountain Energy Co 60/04/23 2pp

~~8004040093 Application for amend of License GUA~1338 authorizing use of carbonate rather than acid listviant & changing procedures associated w/use of carbonate listviant ** Rocky Mountain Energy Co. 80/04/30 A2pp

8006240268 Forwards addendum to 780718 application for mining.providing info required in Chapter XIV W/o encl INANICKI.R E Rocky Mountain Energy Co 80/05/27 ip

DOCKET 40-8698 PLATEAU RESOURCES. LTD

8006030032 Notifies that Amend 2 to License SUA-13/1 was initiated by NRC & is therefore fee exempt Amend requires advance notification of certain const milestones for imap purposes PERSON, L. , LINEHAM, J. Uranium Recovery Licensing Branch

PERSONAL A LINEHAN, J J 80/05/15 Lp

DOCKET 40-0714 CLEVELAND CLIFFS IRON CD

8006020458 Forwards add1 data & amplification of requested changes to License SWA-1352 in response to ARC request Changes detailed in 800321 submittal do not require license amend & do not increase radiological hazards LOUDERBACK.TF Cleveland-Cliffs Iron Co 80/05/07 (12pp

8006120253 Requests amend to Source Maths License BUA-1352 Amend would change Conditions 10 % 11 Condition 10 to include two addl info transmittals & Condition 11 to permit project site area of 42 172 acres Amend foe encl LQUDERBACK, T.E. Cleveland-Cliffs from Co. 80/05/13 Spp

DOCKET 40-9720 STANDARD DIL CO OF INDIANA

8006050520 Notifies NRC that providuate restoration may begin within 30-60 days in Aquifer N at site Leach solution injection & mining activities will continue in Aquifer N while restoration takes place in Aquifer N HERLIHY.D Tetan Exploration Drilling Co. Inc. 80/04/30 1p

DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

8006130117 Summary of 800425 meeting w/vendor in Silver Spring. MD remeans of verifying whether hydraulic connection exists between Teapot Sandstone & Parkman Sandstone at site ROTHFLEISCHOJ Uranium Recovery Licensing Branch 80/05/02 4pp

DOCKET 40-8722 DRUSH-WELLMAN, INC.

8004040090 Informs that due to late delivery of components, etartup of U recovery plant will be delayed from 800519 to 0602 Supplements 80032! Itr re License 5UA-1354 activities POMERS.M B Srush-Mellman. Inc 80/05/13 ip

DOCKET 40-9727 KERR-MOREE NUCLEAR CORP.

8006060474 Forwards License SUA-1378, authorizing vendor to own, use & transfer source % byproduct/matl that results from minewater U extraction EIA & safety analysis also encl SCARANO, R A Uranium Recovery Licensing Branch 80/04/08 ip

--8006050496 License SUA-1378 authorizing vendor to own.use & transfer source t byproduct/mati that results from minewater U estraction SCARAND, R.A. Uranium Recovery Litensing Branch 80/04/08 7pp

--B006060479 Guidelines for decontamination of facility & equipment prior to release for uniestricted use or termination of licenses for byproduct, source of SNM # Uranium Recovery Licensing Branch 76/11/30 5pp

--8006060501 EIA supporting issuance of License SUA-1378 authorizing ion sichange plant for U recovery from minewater HU.O . MILLER, H J Uranium Recovery Licensing Branch 80/04/08

DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC

8006250130 Forwards data in response to R Scarano 800418 request re North 5 South Levenberger reservoir berms Moisture content meets design specs Review of enc! data needed to proceed w/ groundwater restoration HERLINFO United Nuclear Corp , UNG Recovery Systems Div 80/05/15 19pp

800611034B Forwards results of consolidated test requested by NRC Overall consolidation at 2.000 ksf under saturated conditions is 5% to 6.47 compared w/4.3% under ambient moisture conditions HERLIHY, D. Teton Exploration Diviling Co., Inc. 80/06/06. 4pp

BOObil0359 Requests use of freeboard analysis for North & South Lauenberger evapolation pands per BOO201 rept 'Embankment Info for North & South Leuenberger Reservoirs " Accumulated Ra-226 concentration data discussed HERLIHY, D Teton Exploration Drilling Co . Inc BO/06/06 3pp

DOCKET 40-8745 BOLE PETROLEUM

BCO6080155 Clarifies agreements on groundwater issues made w/State of MY.Dept of Environ Quality during 803416 meeting Criteria apply to mining Unit 1 Criteria for other units will be based on Unit 1 results 9 add1 baseline data FRANCIS.E . MANCINI, T Myoming. State of 80/05/01 4pp

BOO6120049 Forwards "Rison Basin Project Radiological Safety Program," in support of NRC source mati license application CATCHPCLE.0 J Ogle Petroloum. Inc. 80/05/19 ip

--800&(2005) "Bison Basin Project Radiological Safety Program " ◆ Ogle Petroleum, Inc. 80/05/18 22pp

DOCKET 40-8752 PINAL MINERALS & MINING, LTD

8006130190 Requests opportunity to meet w/NRC re facility license renewal following review of documents sent by AZ AEC NRC should advise of future plans for regulating U activities & legislation that would affect plant MCKLVEEN, J W Radiation & Environmental Monitoring, Inc. 80/05/05

DUCKET 40-8748 KERR-MCKEE NUCLEAR CORP

BODA300695 Notifies of completion of preliminary review of application for source math license Application acceptable for further processing Assigns docket number & requests addl copies of ROTHFLEISCH, J.E. Uranium Recovery Licensing Branch 80/06/11 1P

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN REBEARCH REACTOR

F Security, medical, emergency & fire protection plans

8006180256 Forwards emergency plan for facility KERR.W Michigan, Univ of 80/06/12 1p

--8006180264 Emergency plan for tacility * Michigan, Univ of 75/09/30 78pp

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D.G. Division of Licensing 80/05/22 73pp

O Adjudicatory correspondence

8006190547 Order granting extension until 800707 for Commission to elect whether to review ALAB-436 & portions of ALAB-561 CHILK, S.J. Office of the Secretary of the Commission 80/06/16

8006260186 Forwards UCS 800623 motion to disqualify Commissioner Hendrie WEISS,E R., JORDAN,W S. Sheldon, Harmon & Weiss 80/06/23 1p

--8006260192 Responds to 730717 ltr re util siting criteria Indian Point sites meet NRC regulations & criteria Considerable energy has been expended to assure public health & safety HENDRIE, J M Atomic Energy Commission. Directorate of Licensing 73/09/10 3pp

H General correspondence

8006020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas HAMM.K Affiliation Unknown 80/03/19 1p

BOO6020027 Responds to BOO319 ltr re location of nuclear power plants in areas of high population density Every effort is being made to protect public health & safety at all nuclear power plants DENION.H R Office of Nuclear Reactor Regulation, Director 80/04/21 2pp

P Operating license stage documents & correspondence

7911200331 Confirms requirements re condensation oscillation loads for Mark I containment long-term program developed at 790815 meeting w/Mark I owners group Confirmatory condensation test & plan schedule due by 791031 EISENHUT.D Q Division of Operating Reactors 79/10/02 47pp

791119014B Forwards "Discussion of TMI Lessons Learned Bhort-Term Requirements " Revisions to encl implementation schedule for NUREG-057B requirements should be submitted w/justification within 15 days.if schedule requirements cannot be met DENTON.H R Office of Nuclear Reactor Regulation, Director 79/10/30 2pp

--7911190247 "Discussion of TMI Lessons Learned Short-Term Requirements "

Office of Nuclear Reactor Regulation, Director 79/10/30
73pp

8006070165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days. EISENHUT, D O Division of Licensing 80/05/07 150pp

8006130122 Requests comments on NUREG-0377, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
EISENHUT,D O Division of Licensing 80/05/19 72pp.

- 8006120404 Forwards slides used by utils during 800Å03 meeting re technology exchange in area of mitigation feature for severe accidents at facilities GGESER.D. Westinghouse Electric Corp. 80/06/05 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8006200044 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BD/05/28 ip
- R Periodic operating reports & related correspondence
- 8006170431 Forwards data specified in Section 401 Certification for May 1980 to NY State Dept of Environ Conservation MONTI,W A Consolidated Edison Co of New York 80/06/10 ip
- --B006170434 Circulating water temp.gross electrical output & river water discharge info for May 1980

 Consolidated Edison Co of New York B0/04/10 14pp
- 8006180529 Forwards "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point.NY Consolidated Edison Project. Dec 1979-Feb 1980 " CAHILL.W J Consolidated Edison Co of New York 80/06/13 1p
- --8006180536 "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project, Dec 1979-Feb 1980 "
 - Woodward-Clyde Consultants. Inc 80/05/12 46pp
- 8006180426 Forwards daily fish counts from intake screens for May 1980 CAHILL W J Consplidated Edison Co of New York 80/06/15 ip
- ---8006180427 Daily fish counts from intake screens for May 1980 * Consolidated Edison Co of Neu York 80/06/15 App

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

BOO6130278 Informs NRC that new physical security plan for physical protection of SNM of low strategic significance will be submitted by BOO801 LEVINE.S H Pennsylvania State Univ BO/06/06 ip

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

D NRC Draft/Final Environmental Statements, suppls & correspondence

8006160188 Forwards facility DES re environ considerations under NEPA re primary cooling sys chemical decontamination, NUREG-0686. Enotice of issuance & availability EIS should be prepared CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/05/30 ip

--8006160174 Notice of issuance & availability of facility DES re primary cooling sys chemical decontamination, NURE9-0686 CRUTCHFIELD.D Operating Reactors Branch 8 80/05/30 2pp

--8006160198 DES re primary cooling sys chemical decontamination * Office of Nuclear Reactor Regulation, Director NUREO-0686 80/05/31 63pp

BOO6200055 Advises of issuance of DES re primary cooling sys chemical decontamination CRUTCHFIELD,D M Operating Reactors Branch 5 BO/05/30 2pp

8006200080 Forwards DES re primary cooling sys chemical decontamination DES has been sent to EPA & Ofc of FR for publication Requests comments within 45 days of FR publication CRUTCHFIELD, D.M. Operating Reactors Branch 5

8006230014 Forwards DES, NUREO-0686, for proposed primary cooling sys chamical decontamination FR notice of availability encl Ltr sent to addressees on attached list CRUTCHFIELD, D Operating Reactors Branch 5 80/05/30 8pp

8006230090 Forwards notice of availability which is being forwarded to Ofc of FR for publication of DES CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/05/30 3pp

- 8006170453 Ac) receipt of draft E}S re primary cooling sys chemical decontamination No comment at this time GOTNER,M.L. Agriculture,Dept of 80/06/10 ip
- 8006240332 Informs NRC that HUD Region 5 ofc has reviewed draft EIS re primary cooling sys chemical decontamination & has no comments BINFORD.E C Housing & Urban Development, Dept of 80/06/18 1p
- 8006300410 Advises that review or DES re primary cooling sys chemical decontamination failed to reveal effects on prime farmland FITZQERALD,W J Illinois, State of 80/06/24 ip
- F Security, medical, emergency & fire protection plans
- 7911060551 Notification of 791030-1101 meeting w/util in Zion.IL to review emergency plans
 BEVAN.R B Operating Reactors Granch 3 (Pre 791030) 79/10/23
- 8004020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline uill also be used KEPPLER. J G Region 3. Chicago, Office of the Director 80/04/18 Zon
- 8004040131 Forwards comments re 770818 submittal of training & qualification plan Response requested within 30 days Comments withheld (ref 10CFR2 770)
 CRUTCHFIELD, Operating Reactors Branch 5 80/05/07 2pp
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Bection 50 48 & App R to 100FR50 & is expected to be published in FR by end or May EtBENHUT, D O Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUF, D.O. Division of Licensing 80/05/22 73pp
- 8000200627 Requests revision of 800024 safeguards contingency plan in accordance w/comments described in encl to ltr Response requested within 30 days Encl withheld (ref 100FR2 790) CRUTCHFIELD.D M Operating Reactors Branch 5 80/05/27 2pp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEDPLES.D L. Commonwealth Edison Co 80/06/04 2pp
- ---8006180319 Oraft emergency plan annex * Commonwealth Edison Co 80/07/31 48pp
- --8006180324 Draft emergency plan annex * Commenwealth Edison Co 80/07/31 50pp
- --8004180331 Draft emergency plan annex * Commonwealth Edison Co 80/07/31 52pp
- ~-8005180340 Draft emergency plan annex * Commonwealth Edison Co 80/07/31 37pp
- --8006180347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co 80/07/31 139pp
- 8006180031 Provices info re access of NRC & NRC contractor personnel to facilities to conduct appraisal of health physics program Onsite phase is scheduled for approx 2 this beginning 800619 List of authorized NRC personnel encl KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/05 App
- 8006240316 Forwards. "Dresden Nuclear Power Station 800619 Emergency Response Plan Exercise," to verify Comm Ed emergency plan PEOPLES.D L Commonwealth Edison Co 80/06/18 2pp
- ---8006240318 "Dresden Nuclear Power Station 800619 Emergency Response Plan Exercise "
 * Commonwealth Edison Co 80/06/19 63pp
- 8006240490 Responds to NRC 800425,30,0501,09 & 20 ltrs requesting additing the regular training t qualification plans Requests that response submittal date be extended to 800804 PEOPLES:D L Commonwealth Edison Co 80/06/18 ip

- H General correspondence
- 8006170681 Forwards copies of advertisements based on info from public repts Hopes that advertisements will gain public support b have some impact on IL Commerce Commission in future rate cases LEE, B Commonwealth Edison Co BO/06/10 5pp
- 8006300685 Responds to 800409 request that EIS for chemical decontamination be piepared EIS will be prepared DENTON. H R Office of Nuclear Reactor Regulation, Director 80/06/23 1p
- ~-800A300AB7 Responds to 8003RB ltr re facility chemical decontamination Questions ie EIS purpose not required MCCULLDUGH.E R McCullough. E R 80/04/09 3pp
- P Operating license stage documents & correspondence
- 8006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/18
- BOD6090165 Forwards add1 TMI~2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams 8 licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D Q Division of Licensing 80/05/07 150pp
- BOO6250177 Forwards NUREG-0654.Vol I & II & NUREG-0626 W/o encl CRUTCHFIELD.D Operating Reactors Branch 9 80/05/16 2pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl ETSENHUT, D & Division of Licensing 80/05/19 72pp
- 8006120496 Forwards response to 800227 memo re facility decontamination "For Comment" issue of DES will be ready by end of May DENTON H R Office of Nuclear Reactor Regulation, Director PORTON 122 dem
- ---B006120499 Requests short paper on what is being done at facility, what type of approval NRC gave & whether negative declaration or environ assessment should be performed AMEARKE, JF Commission B0/02/27 ip
- B006030062 Application to amond Licenses DPR-2.DPR-19.DPR-25.DPR-29 & DPR-30.clarifying term "operable." submitted as Tech Spec change request, in response to NRC 800410 ltr NAUGHTON.W F Commonwealth Edison Co 80/05/30 2pp
- --8006030072 Tech Spec change request for Tech Specs Bections i 0-1 2.2 i & 2.3 0.5 0 & 6 0-6 & re definitions, administrative controls, safety limits, limiting safety sys setting & limiting conditions for operation * Commonwealth Edison Co 80/05/30 42pp
- 8006190305 Responds to M Fistcher questions re BEP. Topic IX-1.spent fuel storage Spent fuel storage pool designed to withstand anticipated earthquake loadings as Class I structure JANECEK,R F Commonwealth Edison Co 80/06/02 3pp
- 8006200551 Advises that reorganization of Dfc of Nuclear Reactor Regulation became effective on 800428 Project Hanager P O'Connor will coordinate licensing activities for facility Reorganization described in encl CRUTCHFIELD,D Operating Reactors Branch 5 80/06/02 35pp
- 8006300604 Ltr to all BHR licensees forwarding "For Comment" edition of NURE9-0619, "BHR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W
- B006190456 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 79080B request JANECEW.R F Commonwealth Edison Co 80/06/i1 3pp

DOCKETED ITEMS

- BOD6200386 Comments on NRC evaluation of SEP Topic XV-20, "Radiological Consequences of Fuel Damaging Accidents" Table XV-2 contained typographical error Yrs included on peaking factor data should be removed Data is unitless

 JANECEK.R F Commonwealth Edison Co 80/06/11 ip
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltr re add1 TMI-2 related requirements Dresden Unit 1 is currently undergoing extensive mod & decontamination, therefore no response is provided PEOPLES.D L Commonwealth Edison Co 80/06/12 10pp
- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations "Revised Revision ii includes basis on which equivalent education requirements will be established PEOPLES,D L Commonwealth Edison Co 80/06/23 1p
- G Inspection reports, IE Bulletins & correspondence
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted BTOHR.JP Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --B005230341 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/BOT & NRC regulations including shipping paper & BOT placarding requirement POTTER, J P. BROWN, R A Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 4pp
- 8006200110 Forwards IE Circular 80-08, "8WR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18
- B00617030B Forwards IE Insp Repts 50-010/80-07,50-237/80-07 & 50-249/80-10 on B00303-0404 & notice of violation HEISHMAN,R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --8006170312 Netice of violation from insp on 800303-0404 * Region 3, Chicago, Office of the Director 80/04/ B0/04/22 1p
- --8006170320 IE Insp Repts 50-010/80-07,50-237/80-07 & 50-249/80-10 on 800303-0404 Noncompliance noted failure to follow radiation protection procedures BARKER,J L. TONQUE.T M., SPESSARD,R L. Region 3, Chicago, Office of the Director 80/04/22 5pp
- 8006200119 Advises that IE Circular 80-08, "BWR Tech Bpec Inconsistency Reactor Protection Sys Response Time," was sent to listed utils on 800418 CARROLL,D E Ragion 3, Chicago, Office of the Director 80/04/25
- 8004230016 Forwards IE Insp Rept 50-010/80-08 on 800303-05,07.13-14, 0408 & 07 & notice of violation DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/05/16 2pp
- --8004230020 Notice of violation from insp on 800303-05.07.13-14.0408 &
 - 09 * Region 3, Chicago, Office of the Director 80/05/06
- --8006230024 IE Insp Rept 50-010/80-08 on 800303-08,07,13-14,0408 & 09, Noncompliance noted failure to make adequate evaluation to determine compliance w/100FR20 106 & concentrations in excess of Tech Spec I inits in discharge canal FISHER,W L. Region 3. Chicago, Fuel Facility & Materials Safety Branch PAUL,R A Region 3. Chicago, Office of the Director 80/05/06
- 8006130076 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J M Division of Rules and Records 80/05/23 Spp
- ---8006130099 Forwards response to updated memo received on 800313 re util interrogatories re proposed imposition of civil penalty Cover sheet of IE insp rept encl KEPPLER, J O Region 3. Chicago. Office of the Director 80/03/21
- -8006130138 RO on 740128, during primary containment leak rate test, excessive leakage was detected passing through 2-inch line in radwaste pipeway Caused by removal of two air operated valves Two-inch line was repaired WORDEN, W P Commonwealth Edison Co 74/02/22. 2pp

- ---B006130141 Excerpt of IE Insp Rept 50-010/74-01 conducted on 740128 & 30 Noncompliance noted open 2-inch line violated containment integrity for two fuel cycles & no rept was submitted recontainment testable penetrations Atomic Energy Commission 74/02/28 MANIRA, F . DANCE, H C
- --8006130142 Responds to AEC 740228 itr re leakage in 2-inch line penetrating primary containment Emergency procedures have been revised to require closing motor-operated isolation valves after feedwater injection is terminated LEE.B Commonwealth Edison Co 74/03/20 3pp
- 8004200057 Advises that IE Circular 80-13, "Orid Strap Damage in Wastinghouse Fuel Assemblies," was sent to listed utils on 800528 PAPPAS,H Region 3. Chicago, Office of the Director BO/05/30
- 8006300558 Forwards response to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Proposed mods identified only if present sys design may compromise protective action of equipment equipment
 PEOPLES,D L Commonwealth Edison Co 80/06/10 9pp
- R Periodic operating reports & related correspondence
- 8004110100 Forwards monthly operating repts for Apr 1780 STEPHENSON, 8 B Commonwealth Edison Co 80/05/12 1
- ---B006i10102 Monthly operating repts for Apr 1980 CIESZKIEWICZ,S Commonwealth Edison Co 80/0 BO/05/05 28ep
- 8006170448 Forwards monthly operating repts for May 1980 STEPHENBON, B B Commonwealth Edison Co 80/06/09 19
- --8006170452 Monthly operating rept for May 1980 CIESZKIEWICZ.S Commonwealth Edison Co 80/06/02 400
- --8006170457 Monthly operating rept for May 1980 CIESZXIEWICZ.S Commonwealth Edison Co 80 80/04/02 600
- --B006170461 Monthly operating rest for May 1980 CIESZKIEWICZ.S Commonwealth Edison Co 80 80/06/02 8pp
- DOCKET 50-18 VALLECITOS BOILING WATER REACTOR J Insurance & indemnity information
- 8006160109 Forwards Endorsement 118 to ANI Policy NF-1. CORREA M A Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div 80/06/10 2pp
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR F Security, medical, emergency & fire protection plans
- 8006300270 Forwards table listing all licenses authorizing SNM, form, location, type of matl.authorized amounts & 800331 inventory Table withheld (ref 10CFR2 790)
 CLARK.L Massachusetts Institute of Technology 80/06/23 ip
- P Operating license stage documents & correspondence
- 8006300270 Forwards table listing all licenses authorizing SNM, form, location, type of mat1, authorized amounts & 800331 inventory Table withheld (ref 10CFR2 790) Massachusetts Institute of Technology 80/06/23
- 8 Reportable occurrences. LERs & related correspondence
- 8004020405 RO 90-20/80-02 on 800519, intermittent binding of shim blade number i not in accordance w/Yech Specs Caused by foreign matl inpeding motion Electromagnet containing foreign matl replaced & other blades checked
 BERNARD, J. CLARK, L. Massachusetts Institute of Technology
 80/05/23 App.
- 8006050384 Forwards revised Page 2 of RO 50-20/80-2 dtd 800523. Revisior corrects second paragraph of Section 7 re frequency of blade thickness measurements & clarifies description of electromagnetic coupling of blade BERNARD, J. CLARK, L. Massachusetta Institute of Technology 80/05/27 200 BERNARD, J . CL. 80/05/27 20p

- 8006230051 Forwards revised Page 2 to RO 50-20/80-2 BERNARD, J. CLARK, L. Massachusetts Institute of Technology 80/05/27 ip
- ---8006230062 Revised Page 2 to RG 50-20/60-2 correcting second paragraph of Section 7 to read "routinely measured every 6 months " 4 Hassachusetts Institute of Technology 80/05/27 1p
- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8006060311 Requests to be informed when to expect action on pending litense renewal & security plan HILSON.W E | Pashington State Univ | B0/06/02 | 1p
- BOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- 8006070497 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & 1s expected to be published in FR by end of May EISENHUT.D G Division of Licensing 80/05/19 46pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR\$0 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC BO0517 ltr Page 14a not enc!
 EISENHUT,D 0 Division of Licensing BO/05/22 73pp
- 8006030028 Submits revised commitments & schedule for mad of fire suppression sys Addl engineering requirements & patential long delivery time for addl components necessitate change In situ combustable fire detectors to be implemented 801101 HODDY,D E Yankee Atomic Electric Co 80/05/27 4pp
- 8006230576 Forwards revised responsibility matrix for safeguard security plan Encl withheid (ref 10CFR2 770)
 MODDY,D E Yankee Atomic Electric Co 80/06/16 3pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. licensing erams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D.O Division of Licensing 80/05/07 150pp
- 6006250157 Forwards NUREO-0654, Vol I & II & NUREO-0611 W/o encl GRUTCHFIELD, D Operating Reactors Branch 5 80/05/16 2pp
- 8006130122 Requests comments on NUREQ-0577. "Potential for Low Fracture Toughness & Lampilar Tearing on PWR Steam Generator & Rauctor Collant Pump Supports " Proposed review grocedure & implementation schedule encl
 ELSENHUT.D © Division of Licensing 80/05/19 72pp
- 8008030367 Provides current status of program to evaluate LOCA loads Terminating efforts relative to installation of LOCA restraints due to issuance of Hestinghouse buners group, "Asymmetric LOCA Loads Evaluation Rept "
 KAY, J A Yankee Atomic Electric Co 80/05/28 2pp
- 8006190098 Advises that reorganization of Ofc of Nuclear Reactor Regulation became effective on 800428 Project manager A Burger will coordinate licensing activities for facility Reorganization described in encl CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 35pp
- BOO6070260 Submits evaluation of instrumentation for detection of inadequate core couling.in accordance w/TMI Category "A" Item 2 i 3 b Installation of further instrumentation not planned SMITH.R i. Yantee Atomic Electric Co BO/06/04 4pp

aster equipment list & "Yankee Rowe Containment team Line Repture Inside Containment" re on of electrical equipment Analyses for nt will be completed by Sept & Dec 1980 kee Atomic Electric Co 80/06/05 21pp

Rowe Containment Analysis for Main Steam line antainment " Electric Co 80/05/30 42pp.

- 8006170236 Forwards implementation schedulo & summary stating commitments in response to NRC 800307 ltr re add1 requirements from TMI Action Plan MODDY.D E Yankee Atomic Electric Co 80/06/12 6pp
- @ Inspection reports, IE Bulletins & correspondence
- 8006180054 Forwards IE Insp Rept 50-029/80-03 on 800215-19 No nancompliance noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/29 2pg
- ---9006180057 IE Insp Rept 50-029/80-03 on 800215-19 No noncompliance noted Major areas inspected circumstances surrounding failure of low pressure turbine
 HARTIN,T T Region i, Philadelphia, Reactor Operations Nuclear Support Branch FOLEY, T Region i, Philadelphia, Office of the Director 80/04/25 Spp
- BOO6030103 Forwards lE Mgt Meeting Rept 50-029/80-04 on 800227 BRUNNER: E J Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch BO/05/01 1p
- --B006030ii0 IE Mgt Meeting Rept 50-029/80-04. Areas discussed details re establishment of onsite ofc for purpose of placing full-time NRC inspector at facility FOLEY. T. MCOSCAR. J. Region 1. Philadelphia. Office of the Director MARTIN. T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch B0/04/27 3pp
- 8006250161 Forwards IE Insp Rept 50-029/80-07 on 800317-24 No noncompliance nuted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/06 2pp
- --8006250164 IE Insp Rept 50-029/80-07 on 800317-24 No noncompliance noted Hajor areas inspected emergency procedures for small break LOCA.LERs & monthly operating repts

 MARTIN.TT Region i. Philadelphia, Reactor Operations Nuclear Support Branch FOLEY.T, RAYMIND.W J. Region I. Philadelphia, Office of the Director 80/05/05 Spp
- 8006060503 Forwards "Main Steam Line Rupture Analyses for Yankee Rowe," in response to IE Bulletin 80-04 Overall conservatism of design to main steam line tuptures has not been lessened Second level review underway MOODY, D & Yankee Atomic Electric Co 80/05/08 2pp
- ---B006050506 "Main Steam Line Rupture Analyses for Yankee Rowe "
 * Yankee Atomic Electric Co NRC 80/05/31 29pp
- 8006240590 Submits add1 info re IE Bulletin 79-19, "Packaging Low Level Radwaste for Transport & Burial" Training program being revised to Insure that training, committed to in util 790920 Itr to NRC. will be provided MODDY.D E Yankee Atomic Electric Co 80/05/27 2pp
- 8006200035 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8006050283 Informs that util is in process of addressing IE Bullatin 79-03A Response has required diversion of engineering resources from identified safety issues HEIDERIL H Yankee Atomic Electric Co 80/05/29 2pp
- 8004060447 Discusses IE Bulletin 79-03A. "Longitudinal Held Defects in ASME SA-312. Type 304 Stainless Steel Pipe" Bulletin describes minor design deficiencies, rather than generic problems
 HEIDER, L. H. Yankeg Atomic Electric Co. 80/05/29 2pp
- R Periodic operating reports & related correspondence
- 8006170636 Forwards monthly operating rept for May 1980 MODDY, D.E. Yankee Atomic Electric Co. 80/06/12 1p
- --B006170638 Monthly operating rept for May 1980 BEERS, F.C. Yankee Atomic Electric Co. 80/06/12 5pp
- S Reportable occurrences. LERs & related correspondence
- 8006160006 Advises that LER 50-29/80-05 was not used for 1980 PERKINS.M A Region 1, Philadelphia, Office of the Director 80/06/10 ip

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

800A250353 Notification of 800617 meeting w/NASA Lewis Research Ctr in Bethesda.MD to discuss NASA application for authorization to dismantle Plum Brook test reactor % mockup reactor ERICKBON.P B Operating Reactors Branch 4 80/06/12 2pp

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

@ Inspection reports, IF Bulletins & correspondence

B006120090 Forwards combined IE Investigation Repts 50-054/80-01 27-0048/80-01,27-0039/80-01,30-05986/80-01 & 70-0687/80-01 NRC has proposed civil penalties to Union Carbide, Smith Kline & French Labs Respective states & DD1 notified GRIER, B H Region i, Philadelphia, Office of the Director Rline & F. GRIER, B H Re

--B006120095 IE Combined Investigation Repts 50-054/80-01,27-0048/80-01, 27-0039/80-01,30-05986/80-01 & 70-0687/80-01 Union Carbide failed to mark bill of lading Smith Kline & French Labs railed to mark bill or labing Smith Wille & France Caus failed to use proper packaging CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Gafety Granch KINNEY.W W Region 1, Philadelphia, Office of the Director 80/03/05 44pp

B006300597 Forwards IE Insp Rept 50-054/80-02 on B00414-17 No nancompliance noted MARTIN.N G Region 1. Philadelphia. Bafeguards Branch 80/05/16 200

--8006300602 IE Inap Rept 50-054/80-02 on 800414-17 No noncompliance noted Major areas inspected security plan, protection of SNN, security organization, access control, alarm sys, keys & locks Details withheld (ref 10CFR2 790)
DEVLIN.J W Region 1, Philadelphia, Safeguards Branch MCKEQWN, L. M Region 1, Philadelphia, Office of the Director 80/05/13 1p

S Reportable occurrences, LERs & related correspondence

8006200262 RO on 800503 rod was discovered separated from rod drive & remained fully in core Reactor was immediately shut down Routine insps of present rods will continue w/special attention to similar type of rod failures RIZICKA.N Q Union Carbide Corp 80/05/15 App

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Adjudicatory correspondence

8006230496 Forwards notice of appearance & Certificate of Svc re show cause order for GETR HALTERMAN, H L. House of Rep. 80/06/13 2pp

--8006230459 Notice of appearance re show cause order for GETR Certificate of Svc encl HALTERMAN.H L House of Rep 90/06/12 2pp

J Insurance & indemnity information

8006300434 Forwards Endorsement 24 to MAELU Policy MF-95 CORREA,M A Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/06/20 2pp

O Advisory Committee on Reactor Safeguards reports & correspondence

8004:300ii Summary of ACRS Subcommittee on OETR 77iii4 meeting in Burlingame.CA re geologic & seismologic aspects of GETR

ACRS - Advisory Committee on Reactor Safeguards 80/04/15 11pp

8006120302 Discusses recommendation for addl subsurface investigations at & beneath GETR Purpose was to establish feasibility of isolating GETR from foundation disturbance in event of earthquake PHILBRICK.88 Philibrick, 88 80/05/02 2pp

8006240519 Notice of ACRB Subcommittee on GETR 800616-17 meeting in Sunol.CA to review geologic.seismologic & structural engineering aspects of plant site HOYLE.J C Office of the Secretary of the Commission 80/05/29

P Operating license stage documents & correspondence

- 8006060449 Forwards NRC safety evaluation re proper geologic & seismic design bases for GETR EISENHUT, D.G. Division of Licensing 80/05/23 2pp
- -B006060452 Safety evaluation re geologic & seismic design bases for facility modifying NRC 790927 rept stating that surface offset of 25 meters could occur beneath GETR Burface uffset of one meter beneath facility is appropriate design basis # Office of Nuclear Reactor Pegulation, Director 80/05/23
- --B006060457 Furwards USOS 800508 ltr to NRC & USOS repts, "Faults of GETR Test Reactor Site, Vallecitos Nuclear Ctr.Pleasanton, CA", "Beismicity of Livermore Valley, CA Region, 1969-79" & "Surface Faulting Near Livermore, CA" MDRRIS,R H Interior, Dept of, Geological Survey 80/04/22 ip
- --8006060462 Advises that U808 has re-examined position re potential net slip along Verona Fault near OETR at Vallecitos, CA, set forth in 790905 review Analysis of data presented by applicant at ACRS 791114 meeting does not alter U808 position MORRIS,R H Interior, Dept of, Geological Survey 80/05/08 1p
- --8006060471 "Faults at GETR Test Reactor Site,Vallecitos Nuclear Ctr. Pleasanton,CA " HERD,D G , BRABB,E E Interior,Dept of, Geological Gurvey G0/04/30 SBpp
- --8006060473 "Seismicity of Livermore Valley,CA Region,1969-79 "
 ELLSWORTH,W L , MARKS,S M Interior,Dept of, Geological Survey
 80/05/23 43pp
- --8006060476 "Surface Faulting Near Livermore, CA Associated u/Jan 1980 Barthquakes "
 BQNILLA.M G , LIENKAEMPER.J , TINSLEY.J C Interior.Dept of,
 Omological Survey 80/05/23 36pp
- --BOO6060491 Responds to NRC request for assistance in review of GE probability studies for facility site Forwards Benjamin & Associates comments & LLL 800421 memo TERA Corp rept "Seismic Rupture Hazard at GETR Review & Analysia" encl BERRREUTER.D L , TOKARZ,F J Lawrence Livermore Laboratory FIN 80/05/08
- --8004040483 "Seismic Rupture Hazard at GETR Review & Analysis " * TERA Corp 80/05/01 93pp
- 8006120305 Forwards evaluation of applicant review of CETR foundation photographs per 800506 request MORRIS, R H Interior, Dept of, Geological Survey 80/06/06 3pp
- 8006250299 Requests add1 info justifying facility ability to meet laadings associated w/design bases specified in NRC 800523 evaluation Schedule for response should be submitted within days .R A Operating Reactors Branch 3 80/06/10 1p
- 8006240113 Discusses topics for upcoming ACRS Subcommittee on GETR 800616-17 meeting NELSON.C C Operating Reactors Branch 3 80/06/11 2pp

T Hearing transcripts on non-antitrust matters

- BOD6300619 Transcript of ACRS Nuclear Bafety Subcommittee 800616 meeting in Bunol.CA in matter of GETR show cause order Pp 1-226 # ACRS Advisory Committee on Reactor Safeguards 80/06/16 350pp
- 8006270374 Transcript of ACRS Subcommittee on GETR 800617 meeting in Sungl.CA Pp 227-507 Morning session # ACRS Advisory Committee on Reactor Safeguards BO/06/17 281 pp

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8006090508 Forwards IE imag Rept 50-073/80-01 on 800225,26,28 & 0303 No noncompliance noted BOOK,H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/05/05 2pp

--8006090513 IE Into Rept 50-073/80-01 on 800225.26.28 & 0303 No noncompliance noted Major areas inspected radigactive effluents emergency planning radiation safety procedures, personnel esposures instruments & tour of facility BOOK, H E. MENSLAWSKI, F.A., FISH, R. F. Region B. San Francisco. Office of the Director 80/05/02 Spp

DOCKET 50-80 UNIV OF FLORIDA TRAINING REACTOR

- a Inspection reports, tE Bullatins & correspondence
- 8005090479 Ack receipt of 800507 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-083/80-01 LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/21 1p
- --8004090485 Responds to NRC 800407 ltr re violations noted in IE Insp. Rept 50-083/80-01 Corrective actions Tech Specs changed, daily check changed to incorporate restricted testing of ulthdraul interlock BIAZ.N J Florida. Univ of, Gaingsville 80/05/07 2pp
- --8006090491 forwards lE lnsp Rept 50-083/80-01 on 800317-20 & notice of violation
 LEWIS, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/09 2PP
- --8006070496 Notice of violation from insp on 800317-20 * Region 2. Atlanta, Office of the Director 80/04/09 ip
- --B006090505 IE Insp Rept 50~083/80~01 on 800317~20 Noncompliance noted failure to perform required safety sys checkout prior to startup KELL000.P J Region 2. Atlanta, Reactor Decrations Nuclear Support Branch WAGNER, A O Region 2. Atlanta, Office of the Director 80/04/09 4pp
- 5 Reportable occurrences. LERs & related correspondence
- 8006020365 RO during wk of 800512 no surface contamination monitoring was performed Operator in charge was assigned to work at another faculity No procedures exist for assigning responsibility Procedures have been revised DIAZ.N J Florida, Univ of Gainesville 80/05/23 ip
- 8006240548 Forwards Univ of FL rept re failed temp control thermocouple on Varian electron capture unit Failure led to contamination of lab & exposure of personnel to tritium KERR-0 H Assistant Director for State Agreements Programs 80/04/03 3pp
- DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR
- 8006170478 Forwards dismantling plan for R-3.10 kW reactor in response to NRC request BAXE.R F., THOMAS.J L. North Carolina State Univ 80/06/05 2pp

DOCKET 50-116 TOWA STATE UNIV RESEARCH REACTOR

- O Inspection reports, IE Bulletins & correspondence
- 8006190389 Forwards IE Insp Rept 50-116/80-01 on 800515-16 No noncompliance noted DAVIS,A B Region 3, Chicago, Puel Facility & Materials Safety Branch 80/06/04 2pp
- --B006190398 IE Insp Rept 50-116/80-01 on 800515-16 No noncompliance noted Major areas inspected emergency planning implementation procedures, coordination w/support agencies, kits & nonitoring equipment EBSIO.T H. GREENR J. Region 3. Chicago. Office of the Director B0/06/02 3pp

DOCKET 50-128 TEXAS ASM UNIV RESEARCH REACTOR

- G Inspection reports, IE Builetins & correspondence
- 8006020527 Ack receipt of 800414 ltr in response to NRC 800401 ltr & notice of violation Requests addl info to properly evaluate adequacy of corrective action, including corrective steps taken, results & steps taken to avoid further violations MADSEN. O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/05/15 2pp
- ~-8006020534 Responds to item of noncompliance noted in IE Insp 50-128/80-01 Corrective actions SOP Book Surveillance Record has been placed at front of Vol 1 of each set of SOPs for documentation of SOP book surveillance Memo 59 encl BERG.R R Texas A & M Univ 80/04/14 App
- 8006230143 Ack receipt of 800414 & 0523 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-128/80-01 MADSEN,G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/05/30 ip
- --8004230132 Responds to NRC 800515 itr re violations nated in IE Insp Rept 50-128/80-01 Corrective actions redundant SOP book will not be returned to control room RANDALL, J D Teras A & M Univ 80/05/23 2pp
- S Reportable accurrences, LERs & related correspondence
- 8006230420 RD on B00513, secondary cooling tower fan discovered to have disintegrated causing damage to cooling tower & resulting in loss of secondary cooling capacity Caused by failure of fan transmission mounting Temporary fan assembly installed FELTZ.D & Yexas A & M Univ 80/05/23 2pp
- DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR
- BOOAD30341 Application to amend License R-58 Amend allows for A-month extension of license to permit transfer of fuel & components of reactor SLACK, S Y, KOPPELMAN, R West Virginia Univ 80/05/29 1p
- DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8006020175 Notifies that FEMA/NRG Steering Committee has reconsidered appropriate size of emergency planning zones for small water cooled power reactors Steering Committee has adopted encl position on planning basis for reactors IPPOLITU,T A Operating Reactors Branch 2 80/05/14 Spp
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D @ Division of Licensing 80/05/17 44pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101," transmitted by NRC 800519 itr Page 14a not enci EISENHUT, D & Division of Licensing 80/05/22 73pp
- 8006;70117 Requests participation in study of people-related problems in nuclear safeguards NRC representatives will visit facility & interview security mgt personnel IPPDLITO, T A Operating Reactors Branth 2 80/06/03 2pp
- G Adjudicatory correspondence
- 8006190497 Forwards intervenor proposed time schedule for further proceedings & historical summary leading to present status of plant
 BROWNL J Junes, Brown & Clifford 80/06/06 2pp
- --8006170437 Proposed time schedule for further proceedings 800601-0930 for consultant data re seismic & geologic studies, 801001 for NRC & intervenor statements & 801001 for PQ&E conclusions W/Certificate of Syc & historical summary BRDWN.L J. Jones, Brown & Clifford SHERWODD, M.R. Sierra Club 80/06/03 9pp

- 6006230372 Order re ABLB 800603 prehearing conference in Eureka, CA Licensee motion to hold OL amend proceeding in abeyance until 801001 granted Joint intervenors are directed to file contentions 43 days after receipt of consultant rept LAZO:R M Atomic Safety and Licensing Board Panel 80/06/17 4pp
- P Operating license stage documents & correspondence
- 8000090165 Forwards add1 THI~2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIBENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006190122 Requests comments on NUREQ-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D. G Division of Licensing 80/05/19 72pp
- 8006300604 Ltr to all BMR licensees forwarding "For Comment" edition of NUREO-0619, "INMR Feedwater Norrie & Control Rod Drive Return Line Norrie Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT,D O Division of Licensing 80/06/05 22pp
- G. Inspection reports. IE Bulletins & correspondence
- 8006200116 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency ~ Reactor Protection Sys Response Time " No written response required. ENDELKEN, R. H. Region 5, Gan Francisco: Office of the Director 80/04/18 io
- HOO6200052 Forwards IE Circular 80-13, "Grid Btrap Damage in Westinghouse Fuel Assemblies" No written response required ENGELKEN.R H Region 5, Ban Francisco. Office of the Director 80/05/28 ip.
- R Periodic operating reports & related correspondence
- 8006160022 Forwards monthly operating rept for May 1980 WEEKB, E.D. Pacific Qas & Electric Co. 80/06/04 ip
- --- BQOA160023 Monthly operating rept for May 1980
 BAUM.P W Pacific Oas & Electric Co 80/06/03. App
- T Hearing transcripts on non-antitrust matters
- 8006160211 Transcript of 800603 prehearing conference in Eureka.CA Pp 1~189 * Commission 80/06/03 190pp
- DOCKET 50-141 STANFORD UNIV RESEARCH REACTOR
- 8006110122 Bubmits info re univ application to terminate reactor facility License R-60 & release site for unrestricted use HOLMEB.J A , FINSTON.R.A Stanford Univ 80/06/03 4pp
- DUCKET 50-142 UCLA TRAINING REACTOR
- O Adjudicatory correspondence
- 8006120325 Notice of establishment of AGLB to preside in proceeding on petitions to intervene &/or requests for hearing & to preside over proceeding in event that hearing is ordered LAZOR M. Atomic Sefety and Licensing Board Panel 80/06/10 2pp.
- BOO6130252 Response to Campus Committee to Bridge the Oap BOO522 petition to intervene Petitioner satisfies interest & aspect requirements & should be admitted as party if contention requirement is satisfied W/Certificate of Byc. ORAY, J. R. Hearing Branch 1 80/06/11 14pp
- 8006160117 Application for extension until 800707 for Regents of Univ of CA to respond to Committee to Bridge the Cap 800606 patition to intervene. Petition was not received until 800610. Declaration of mail svc encl.
 HEL
- 8006180271 Forwards Regents of Univ of CA 800612 application for extension of time to answer patition to intervene States no objection to requested extension M/o ancl.

 ORAN, J. R. Hearing Branch 1, 80/06/16 1p.

- 8006240430 Order granting sitension until 800708 for licensee to respond to Campus Committee to Bridge the Dap petition to intervene re proposed renewal of license BOWERS.ES Atomic Safety and Licensing Board Panel 80/06/18 ip
- 8006240206 Forwards NRC 800611 response to Committee to Bridge the Gap patition to intervene in proposed renewal of license Svc list has been updated to include all ASLB members H/o encl GRAY, J. R. Hearing Branch 1 80/06/24 19
- Q Inspection reports, IE Bulletins & correspondence
- 80060&0559 Forwards IE Insp Rept 50-142/80-02 on S00104 & 0213-14 & notice of violation CREMS, J L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/03/07 2pp
- --8006060371 Notice of violation from insp on 800104 & 0213-14

 * Region 5, Ban Francisco, Office of the Director 80/03/06 ip
- --8006060578 IE Insp Rept 50-142/80-02 on 800104 & 0213-14 Noncompliance noted logkesping by operators & review by supervisory personnel needs improvement & neutron channel calibrator exceeded Tech Spec requirement STERNBERG,D M , MORN,A J , BACAGLIO,M J Region 5, San Francisco, Office of the Director 80/03/06 5pp
- DOCKET 50-147 ROCKHELL INTL CORP CRITICAL FACILITY
- G Inspection reports, IE Bulletins & correspondence
- 8006060013 Requests closeout insp for licenses 800430 request to terminate License GX-17 Insp necessary to confirm radiation survey results NOVAK.T M Assistant Director for Operating Reactors 80/05/13.
- DOCKET 50-150 DHIO STATE UNIV RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8006230102 Forwards IE Insp Rept 50-150/80-02 on 800416-17 No noncompliance noted HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Bupport Branch 80/05/08 2pp
- --8006230113 IE Insp Rept 50-150/80-02 on 800416-17 No noncompliance noted Major areas inspected logs & records reactor surveillance requalification training & reviews & audits RIDEMAY, K.R. BAKER, K.R. Region 3, Chicago, Office of the Director 80/05/07 5pp
- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8004040123 Forwards comments & discussion re 790823 submittal of guard training plan Response requested within 30 days. Comments & discussion withheld (ref 10CFR2 790) CRUTCHFIELD, D Operating Reactors Branch 5 80/05/15 2pp
- 8006090497 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end of May EIGENHUT, D. Q Division of Licensing 80/05/19 46pp.
- BOOA040016 Requests that revised pages for safeguards contingency plan. Revision 1, bearing appropriate revision number & date per encl comments; be submitted within 30 days of receipt of ltr. Encl withheld (ref 100FR2 790) CRUTCHFIELD, D Operating Reactors Branch 5 80/05/20 2pp
- 8006130063 Porwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not anci EISENHUT, D G. Division of Licensing 80/05/22, 73pp
- O Adjudicatory correspondence
- 8006120058 Responses to licenses first set of interrogatories. Identifies documents planned to be used in support of case Forwarding ltr encl. O'NEILLIJ, JOHNS.8 J Affiliation Unknown 80/03/28- 4pp

- 8006050366 Requests help in drafting testimony re Contention IIE-3 concerning criticality of spent fuel pool mods Util believes info provided constitutes thorough & adequate analysis of criticality considerations affecting proposed mods STEPTOE,P.P. Isham, Lincoln & Beale 80/05/08 2pp
- 8006i60137 Answers to intervenor Christa-Maria Interrogatories 9-1 through 9-15 & 9-31 Affidavits.prof qualifications. Certificate of Svc. supporting documentation & forwarding 1tr encl Related correspondence GALLO.J Isham. Lincoln & Beale 80/05/17 97pp
- BOO6240358 Request for immediate order requiring licensee to permit intervenor access to site on BOO624 to observe testing of emergency plan Adequacy of emergency plan is subj of intervenor contention Certificate of Svc encl JORDAN.W 8 Christa-Maria JORDAN.W 8 Sheldon, Harmon & Weiss 80/06/20 App
- B00624012B Response in opposition to intervenors Christa-Maria et al request for access to observe B00624 emergency plan exercise Access will have advance effect on exercise & proper conduct of discovery Certificate of Byc encl QALLO, J Consumers Power Co GALLO, J Isham, Lincoln & Beale B0/06/22 17pp
- 8006260259 Order permitting intervenor Christa-Haria entry onsite to observe emergency plan testing & permitting licenses to excercise rights of appeal Licenses request to refer ruling to ABLAB is denied due to absence of irreparable impact GROSEMAN.H Atomic Safety and Licensing Board Panel 80/06/23 500

- 8006170130 Requests shutdown of facility Examples of danger presented by plant include inadequate biological shield & increasing numbers of old fuel rods in spent fuel pool WALLACH.T Affitiation Unknown 80/05/23 ip.
- 8006270157 Responds to 800424 ltr re NC Gardner concerns about facility operation w/containment vented to atmosphere Containment bidg designed & constructed on basis that containment would be continuously ventilated NC Gardner 800410 ltr enci.

 DIRCKS.N J Office of the Executive Director for Operations 80706705 Spp
- 8006270181 Responds to 800429 request for info re M LeMiere inquiry about amount of nuclear wasts disposed in State of MI Spent fuel from four operating MI reactors stored onsite NRC evaluated status of waste mgt in 1977 W/related FR excerpts DIRCKS:N J Office of the Executive Director for Operations 80/06/09 10pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D O Division of Licensing 80/05/07 150pp
- 800A090151 Denies util 791027 request for exemption from fee requirements Fers collected to assure that nuclear plants constructed & operated w/reasonable essurance that public health & safety will not be endangered MILLER.W O License Fee Management Branch 80/05/15 ip
- 8006250141 Forwards NUREO-0654,Vols I & II & NUREO-0626 W/o enci CRUTCHFIELD.O Operating Reactors Branch 5 80/05/16 2pp
- 8006130122 Requests commants on NUREQ-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactur Coolant Pump Supports" Proposed review procedure & implementation schedule encl
 EISENHUT.D. G Division of Licensing 80/05/19, 72pp
- 8006250395 Advises that licensing activities will be coordinated by W Paulson, due to reorganization of Dfc of Nuclear Reactor Regulation, effective 800428 Reorganization chart encl characters D, D M Dperating Reactors Branch S. 80/06/02. 2pp
 - organization chart for Dfc of Nuclear Reactor Regulation. 00428 Distribution of functions and of Nuclear Reactor Regulation. Director. 80/04/02,

- 8006270235 Advises that reorganiztion of Ofc of Nuclear Reactor Regulation became effective on 800428 Project manager, W Paulson will coordinate licensing activities for facility Description of reorganization encl CRUTCHFIELD,D Operating Reactors Branch 5 80/06/02 34pp
- BOO6300604 Ltr to all BWR licensess forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzie & Control Rod Drive Return Line Nozzie Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT, D O Division of Licensing 80/06/05 22pp
- 8006260029 Forwards evaluation of SEP Topics II-1 A re exclusion area authority & control, II-18 re population distribution & II-1 G re potential hazards Evaluation will be basic input into integrated safety assessment unless mods required CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/06 20pp
- 8006170670 Notifies that util will comply w/addl TMI-2 atcident requirements outlined in NRC 800507 itr.w/exception of Item I A i 3. "Shift Manning " Util tabulation of requirements & interpretation of implementation schedule encl HOFFMAN.D P Consumers Power Co 80/06/12 App
- 8006250R4B Forwards info re boiling of spent fuel pool & effect on storage facility Licensee analysis submitted on 800201 concludes that under worst conditions, stress is within design limits Changes to Response 4 encl H
- Q Inspection reports, IE Bulletins & correspondence
- 8006200106 Forwards IE Circular 80-08. "BWR Tech Spec Inconsistency Reactor Protection Sys Response Time "No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/18 in
- BOO6120908 Forwards response to violations noted in IE Insp Rept 50-155/80-05 Details withheld (100FR2 790) HBFFHAN,DP Consumers Power Co 80/06/09 lp
- 8006200386 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Review demonstrated that neither Model AH-90 nor NH-90 installed in safety-related sys HOFFMAN,D P Consumers Power Co 80/06/17 ip
- 8 Periodic operating reports & related correspondence
- 8006110068 Forwards annual operating rept detailing facility changes, tests & experiments performed in 1979
 HOFFMAN, D.P. Consumers Power Co. 80/06/06 1p
- --8006110072 Annual operating rept detailing facility changes, tests & experiments performed in 1979
 * Consumers Power Go 80/06/06 19pp
- S Reportable occurrences, LERs & related correspondence
- 8006040300 Forwards LER 80-011/03L-0 HOFFMAN, D P Consumers Power Co 80/05/30 ip
- --800A040303 LER 80-011/03L-0 on 800501, during monthly gravity checks, cell 2 of battery for channel A of reactor depressurizing sys read below Tech Specs Cell did not respond adequately to equalizing charge Cause of failure unknown Cell replaced * Consumers Power Co. 80/05/30 ip
- 8006170515 Forwards LERs 80-014/03L-0,80-015/03L-0 & 80-016/03L-0. HUSTON,R W Consumers Power Co 80/06/11 ip
- --8006170527 LER 80-014/03L-0 on 800512 sensor channel D of reactor depressurizing sys was removed from svc to correct problem following intermittent automatic test circuit alarms Caused by setpoint drift Unit readjusted * Consumers Power Co. 80/06/11 ip
- --B006170529 LER B0-015/03L-0 on B00515, sensor channel D of reactor depressurizing sys was removed from svc to correct problem following intermittent automatic test circuit alarms Caused by setpoint drift Unit readjusted # Consumers Power Co 80/06/11 ip
- --8006170534 LER 80-016/03L-0 on 800527, sensor channel D of reactor depressurizing sys was removed from svc to correct problem following intermittent automatic test circuit alarms Caused by setpoint drfit Unit readjusted

 * Consumers Power Co 80/06/11, 1p

BOO6170706 Informs NRC of current plans re design deficiency concerning partial closure of ventilation isolation valves. Plans differ from those submitted as LER 79-28 & 80-19 on 791226 & 800523, respectively. HDFFMAN, D.P. Consumers Power Co. 80/06/13 2pp

8006270307 Informs NRC of mod to swing check valve operators to assure operability Precautions & procedures will be implemented to reduce possibility of vacuum within containment Public health & safety will not be jeopardized HQFFMAN.D P Consumers Power Co 80/06/13 2pp

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR P Operating license stage documents & correspondence

8006040167 Application to renew License R-80 for 20 yrs Current license expires 800629 Licenses will forward complete application demonstrating that facility, components & sys can be safely operated over renewal period GODK.W D Cornell Univ 80/05/27 ip 80/05/27 1s

DOCKET 50-140 GEORGIA INST. OF TECH. RESEARCH REACTOR F Security, medical, emergency & fire protection plans

8006020421 Requests extension until 800625 to complete necessary changes for submittal of amended security plan Implementation of plan would be accomplished within 30 days following NRC approval RUSSELLJ L. Georgia Institute of Technology 80/03/27 1p

8004250248 Forwards proposed physical security plan Plan withheld (ref 100FR2 790) KIRKLAND,R S Georgia Institute of Technology 80/04/23 lp

S Reportable occurrences, LERs & related correspondence

8006110118 Ro on 800410 heavy-water temp recorder TRA-D1 was not recalibr after replacement of worn sliding contacts on scanner select switch Cause not stated Importance of recalibr emphasized to personnel KIRKLAND, R S Georgia Institute of Technology 80/05/23 2pp

DOCKET 90-166 UNIV OF MARYLAND RESEARCH REACTOR C Utility Environmental Report (ER), amends & correspondence

8006110337 EIA supporting renewal of DL * Maryland, Univ of 80/06/30 14pp

F Security, medical, emergency & fire protection plans

8006110232 Emergency plan * Maryland, Univ of 80/06/30 60pp

K Utility Final Safety Analysis Report (FSAR) & amends

8006110169 FBAR for MD Univ Training Reactor * Maryland, Univ of 80/06/11 200pp

8006ii0174 Chapter 1 of MD Univ Training Reactor FBAR, "Introduction & General Description of Facility "

* Maryland, Univ of 80/06/ii 12pp

8006110180 Chapter 2 of MD Univ Training Reactor FBAR, "Site

Characteristics " # Maryland, Univ. of 80/06/11 14pp

8004110186 Chapter 3 of MD Univ Training Reactor FSAR, "Reactor

Maryland: Univ of 80/06/11 15pp

8006110170 Chapter 4 of MD Univ Training Reactor FSAR, "Reactor" * Maryland, Univ of, 80/06/11 40pp

8006110197 Chapter 5 of MD Univ Training Reactor FSAR, "Reactor Coolant & Purification Sys "

* Maryland, Univ of 80/06/11 10pp.

8006110201 Chapter 6 of MD Univ Training Reactor FSAR, "Experimental

Facilities " * Maryland, Univ. of 80/06/11 13pp

8006110207 Chapter 7 of MD Univ Training Reactor FBAR, "Instrumentation & Control "
* Maruland, Univ of 80/06/11 Sipp

8006110212 Chapter 8 of MD Univ Training Reactor FSAR, "Auxiliary Equipment " * Maryland, Univ of 80/06/11 11pp

8006110213 Chapter 9 of MD Univ Training Reactor FSAR: "Radwaste Mgt " * Maryland, Univ, of 80/06/11 4pp

8006110216 Chapter 10 of MD Univ Training Reactor FSAR, "Conduct of .peracton → Maruland, Univ of 80/06/11 19pp

8006110218 Chapter 11 of MD Univ Training Reactor FSAR, "Safety Analysis " * Maryland, Uni∨ of BO/O6/ii 14pp

P Operating license stage documents & correspondence

8006110159 Tech Specs for facility * Maryland. Univ of 80/06/30 54pp

V Operator Examinations

8006110195 "MD Univ Training Reactor Requalification Program " * Maryland, Univ of 80/06/30 13pp

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER P Operating license stage documents & correspondence

8006020032 Forwards comments & suggested changes to Tech Specs MILLER, J R Standardization & Special Projects Branch 80/05/12

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION: UNIT 1

H General correspondence

8006170802 Discusses 800430 ltr to NRC expressing concern re arrangements for recent meeting at plant Meetings between NRC & licensees are open to public in most cases Public announcement was issued on 800331.well before meeting date DENTON.H R Office of Nuclear Reactor Regulation, Director 140 p 80/05/30

---800617080B Provides statement for use of NRC review teams during public meetings while making site visits to assess emergency preparedness measures On 791207.President directed FEMA to take lead in offsite emergency planning b plan assessment GAMM.F A Federal Emergency Management Agency 80/05/07 ip

8004270134 Responds to 800501 \$ 08 ltrs re R Schleif & H Walters concerns about arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting M/public announcement & mailing list.

DIRCKS: M J Office of the Evecutive Director for Operations 80/06/02 19pp

8006270152 Responds to 800506 ltr re arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting Public announcement & mailing list encl DIRCKS, W.J. Office of the Executive Director for Operations 80/06/03 14pp

---8006270195 Requests info re constituent inquiry about NRC notification of 800424 public meeting MATHIAS,C M Benate 80/05/09. 1p

I Financial information

8005i9052i Forwards util "1979 Annual Financial Rept" & 1980 internal cash flow statements.as evidence of guarantee of payment of deferred premiums
BRADLEY,E J Philadelphia Electric Co. 80/05/15 7pp

U Congressional/Esecutive Correspondence

- 8006270141 Responds to 800424 ltr re arrangements made for recent meeting at facility Public announcement for meeting was issued 800331 Public announcement & mailing list for meeting encl
 DIRCKS.W J Office of the Executive Director for Operations 80/06/02 topp
- --8006270146 Expresses concern re arrangements for 800424 meeting at facility Adequate notice of meeting was not provided. SARBANES.P.S. Senate 80/04/24 1p
- 800.6270147 Responds to 800506 ltr re arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting Public announcement & mailing list encl DIRCKS W J Office of the Executive Director for Operations 80/06/02 17pp
- --8006270180 Comments on arrangements made for recent meeting at facility NRC should schedule another meeting to obtain further public comments & analyses on emergency response plan LONG.C D. House of Rep., Appropriations 80/05/06 3pp
- 8006020379 Forwards "Decomissioned Annual Rept. 1979 "
 ALDEN, W.B. Philadelphia Electric Co. 80/05/23 ip.
- --8004020385 "Decommissioned Annual Rept. 1979 "
 ULLRICH, R T Philadelphia Electric Co 80/05/23 is
- DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

 G Inspection regorts, IE Sulletins & correspondence
- BOOG) 70049 Forwards IE Insp Rept 50-184/80-02 on 800324-28 No nancompliance noted Cover sheet only encl Rept withheld (ref 10CFR2 790)
 MARTIN. W G Region 1. Philadelphia. Safeguards Branch 80/04/24 200
- ~-8006190075 lE lnsp Rept 50-184/80-02 on 800326-28 No noncompliance noted Major areas inspected security plan protection of SNM & security organization Cover wheet only Rept withheld (ref 100FR2 790)
 DEVLIN.J W Region I. Philadelphia. Safeguards Branch LADUN.R H Region I. Philadelphia. Office of the Director 80/04/14 Ip

DOCKET 50-185 PLUM BROOK REACTOR - MOCK-UP

- B006250333 Notification of B00617 meeting w/NASA Lawis Research Ctr in Bethesda,MD to discuss NASA application for authorization to disnantla Plum Brook test reactor & mockup reactor ERICKSOM,P 3 Operating Reactors Branch 4 80/06/12 2pp
- DOCKET 50-184 UNIV OF MISSOURI RESEARCH REACTOR

 F Security, medical, amergency & fire protection plans
- 800636026B Ack receipt of 800527 ltr informing NRC of steps taken to address concerns identified in NRC 800506 ltr Response is satisfactory Refresher training program will be examined in dapth during future insp. KEFPLER.J 0 Region 3. Chicago, Office of the Director 80/06/16
- ---B006300275 Responds to NRC B00506 ltr re insp on B00326-27.Reg Quide 2 6 has been reviewed & emergency plan will be written Facility emergency procedures have been issued w/1979 revisions included BRUGGER.R H Missouri. Univ of, Columbia B0/05/29 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8006160210 Forwards TE Insp Rept 50-186/80-02 on 800326-27 & 0421 Na noncompilance noted KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/06, 220
- ---8006160215 IE Insp Rept 50~186/80~02 on 800326~27 & 0421 No noncompliance noted Hajor areas inspected emergency planning discussion & exam of drills conducted 1979~80 QREER.R J . ESSIO.T H Region S. Chicago. Office of the Director 80/04/28 70.

- 8006300268 Ack receipt of 800527 ltr informing NRC of steps taken to address concerns identified in NRC 800506 ltr Response is satisfactory Refresher training program will be examined in depth during future insp KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/16 is
- --B006300275 Responds to NRC B00506 ltr re insp on 800326-27 Reg Guide 2 & has been reviewed & emergency plan will be written Facility emergency pracedures have been issued w/1979 revisions included BRUGGER.R M Missouri, Univ of, Columbia 80/09/29 2pp
- S Reportable occurrences. LERs & related correspondence
- 8006110137 RO on B00509, emergency generator failed to start when starting sequence was initiated by automatic weekly exerciser Caused by tripped starter motor Generator inspected & retested when starter motor MCKIBBEN.J C , BRUGGER, R M Missouri, Univ of, Columbia B0/06/02
- 8006110064 RO on B00516. W/reactor operating at full power in automatic mode, automatic regulating blade drive mochanism was discovered producing grinding noise Caused by worn spot on drive pear Regulating blade gear drive was replaced MCKIBREN. J C . BRUGGER.R M Missouri. Univ of. Rolla B0/06/04

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

- Q Inspection reports: IE Bulletins & carrespondence
- 800606011B Forwards IE Insp Rept 50~192/80~01 on 800416~18 No noncompliance noted MADBEN,G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

 F Security, medical, emergency & fire protection plans
- 8006230297 Forwards site security plan for low enriched matl No fees applicable Plan withheld (ref 10CFR2 790) MICHEL(C J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80703/18 1p.

- 8006200580 Forwards D Davis 800420 postcard expressing concern re state of repair of facility Requests NRC response DDC 800428 ltr to D Davis encl TVR.J A Energy, Dept of 80/04/28 4pp
- 8006240094 Responds to 800221 ltr to President Carter Decisive action needs to be taken to effectively use nuclear power to help give US added measure of energy independence & improve domestic economic situation
 HAMLQUIST.E J Energy, Dept of 80/05/07 4pp
- 8006260073 Responds to 800221 ltr to President Cartar opposing facility & nuclear power in general Opposition is not consistent w/administration policy President Carter reaffirmed commitment to nuclear power after Kemeny Rept WAHLQUIST.E J Energy, Dept of 80/05/07 App
- P Operating license stage documents & correspondence
- 8006200579 Responds to NRC 791210 request by providing confirmation that manipulator sleave parts & other similar openings were sealed on 800103 Action provides addl protection against potential turnados.

 CLARK.J.R. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80703/14 doc

- BOO6120257 Submits comments to aid in evaluation of environ impact of immobilizing high level wastes at facility Selection of final waste form prior to selection of repository site may not be consistent w/"sys approach" noted in IRO rept MALARO, J C High Level Waste Licensing Management Branch 80/04/29
- BOOA200059 Ack receipt of Mar 1980 rept re insp.& evaluation of NFB high level waste storage sys Expresses concern re manpower availability for milestones re completion of in-tank & annular space photographic theys HOUGHNY,C J Advanced Fuel & Spent Fuel Licensing Branch 80/05/13
- BOO6130110 Summary of BO0416 meeting w/vendor in Silver Spring.MD re results of NRC analyses of effect of tornado generated missiles at West Valley site HAUGNHEY.C J Advanced Fuel & Spent Fuel Licensing Branch BO/05/15 4pp
- BOD6130164 Summary of BOO416 meeting w/NFS & NY State Energy R&D Authority in Silver Spring, MD re results of NRC analyses of effect of missiles at West Valley site HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch
- 8006240597 Confirms 800606 telcon re BAR for proposed mod to plant SAR being forwarded under separate cover Requests return upon completion of research project HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80706/06 Ip

G Inspection reports, IE Bulletins & correspondence

- B006090078 Ack receipt of 800410 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-201/80-02 MARTIN, N J Region I, Philadelphia, Safeguards Branch 80/05/01 lb
- --8006090081 Forwards IE Insp Rept 50-201/80-02 on 800128-31 & notice of violation withheld (ref 100FR2 790)
 MARTIN,W G Region 1, Philadelphia, Bafeguards Branch 80/03/19
- --8006070086 IE Insp Rept 50-201/80-02 on 800128-31 Noncompliance noted failure to maintain physical barrier to vital area in effective condition Details withheld (ref 10ER2 770)
 DEVLIN.J W Region 1. Philadelphia, Safeguards Branch LADUN,R H
 Region 1. Philadelphia, Office of the Director 80/03/12 ip
- 8006190192 Ack receipt of 800919 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-201/80-03 SMITH, G H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/21 ip
- --B006190197 Rasponds to NRC B00423 itr re violation noted in IE Insp Rept 50-201/B0-03 Corrective actions employees cited have been scheduled for whole body counting BUCKHORTHJ JP Nuclear Fuel Services, Inc (subs of Getty Dil Co) B0/05/15 2pp
- --8006170201 Forwards IE Insp Rept 50-201/80-03 on 800326-28 & notice of violation BHTHA 0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/23 2pp
- --8006190205 Notice of violation from insp on 800326-28 * Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/04/18 ip
- ---8006190208 IE Insp Rept 50-201/80-03 on 800326-28 Noncompliance noted. failure to perform whole body count for all radiation workers on annual basis CLEMONS.P Region 1. Philadelphia, Office of the Director KNAPP.P Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 80/04/18 7pp

R Periodic operating reports & related correspondence

- B006200573 Forwards results & flow measurements for Mar 1980 in accordance w/provisions of NPDES Permit NY00004973, DUCKMORTH.J P Nuclear Fuel Services, Inc (subs of Getty Gil Co) B0/04/03 App
- 8006230141 Forwards corrected Table 5-6, "Deer Bample Data," of Environ Rapt 27 Contains results of reanalysis of deer harvested Nov 1979 & analytical results of second deer harvested Dec 1979

 DUCKWORTH, J P Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 80/04/21 | 1p.

- --8006230144 Corrected Table 5-6, "Deer Sample Data," to Environ Rept 27 * Nuclear Fuel Services, Inc. (subs. of Getty Oll Co.) 80/04/21 ip
- 8006230244 Forwards quarterly rept for Jan-Mar 1980 DUCKWORTH.J.P. Nuclear Fuel Services, Inc., West Valley Reprocessing Plant B0/04/2B 1p
- --8006230247 Quarterly rept for Jan-Mar 1980 \
 * Nuclear Fuel Services, Inc , West Valley Reprocessing Plant 80/04/28 12pp

DOCKET 50-206 SAN UNDFRE NUCLEAR STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D & Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101;" transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- B006020340 Advises that add1 90 days is required to respond to comments in NRC 800425 ltr re util 790923 guard training & qualification plan Add1 time required to establish physical exercise program Response will be submitted by 800901 BASKIN.K P Bouthern California Edison Co 80/05/23 ip
- BOOG160213 Ack receipt of 791212 change in security plan Change does not decrease plan effectiveness CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/02 2pp

O Adjudicatory correspondence

- 8006030461 Forwards mod of 800404 confirmatory order granting 800519 request for extension to complete requirements of order STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 2pp
- --800A050464 Mod of 800404 confirmatory order granting extension until one wi prior to return to svc for completion of items re IE Bulletin 79-27 in 800404 order STELLO.V Dfice of Inspection & Enforcement, Office of the Director 80/05/23 2pp
- 8004090442 Responds to 800519 request for extension of deadline date for completion of items in 800404 order Mod to order granting request encl STELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/23 3pp
- --8006090466 Order extending shutdown to 800522 to permit insp of outstanding emergency procedure items prior to return to sve STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 2pp

- 8006170197 Comments on decreased income from investment in util due to NRC attention to protesters rather than facts No lives have been lost resulting from nuclear power plant failures ELLIOTT.C P Affiliation Unknown 80/09/27 ip
- P Operating license stage documents & correspondence
- BOO6110007 Forwards "Responses to NRC Requirements Established to Date Following TMI Accident." in response to NRC 790913 request Includes commitments to actions set forth in NUREG-0578 DRAKE, J H Southern California Edison Co. 79/10/17 3pp
- ---8006110013 "Responses to NRC Requirements Established to Date Following TMI Accident " * Bouthern California Edison Co 79/10/31 &App
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors, Licensees requirements for TMI Action Plan include shift manning, licensing exams & licenses dissemination of operating experiences Response requested within 30 days EISENHUT, D Q Division of Licensing 80/05/07 150pp

- 1006060567 Forwards Amend 48 to License DPR-13 & notice of issuance & GRUTCHFIELD, D M. Operating Reactors Branch 5 80/05/16 3pp
- --8006060573 Amend 48 to License DPR-13 reducing data retrieval rate for temp recording sys.exempting continuous temp recording requirement & requiring 80% data retrieval rate for failure CRUTCHFIELD, D M Operating Reactors Branch 5 80/05/16 4pp
- --8004060576 Notice of issuance & availability of Amend 48 to License CRUTCHFIELD, D M Operating Reactors Branch 5 80/05/16 2pp
- B006250158 Forwards NUREG-0654, Vol I & II & NUREG-0611 W/o encl CRUTCHFIELD, D Operating Reactors Branch 5 80/05/16 2pp
- 8006130122 Requests comments on NUREG-0527, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Cociant Pump Supports " Proposed review procedure & implementation schedule entl EISENNUT, D. O. Division of Licensing 80/05/19 72pp
- 8006030295 Discusses open items re implementation of Category A Lessons Learned Task Force requirements per NRC 800502 request Open items involve instrumentation for inadequate core cooling, post-accident sampling ? reactor cooling sys venting BASKIN.K.P Southern California Edison Co 80/05/22 4pp
- 800è020547 Responds to 800i10 ltrs re environ rediclogical sampling program being conducted at facilities Disagrees w/Marine Review Committee allegations that program is inadequate Forwards detailed responses to Marine Review Committee rept DENTON-H R Office of Nuclear Reactor Regulation. Director 80/05/23 2pp
- --8006020554 "Detailed Responses to Marine Review Committee Rept "
 * Radiological Assessment Branch 80/05/23 13pp
- --8006020559 "Radiological Effluent Tech Specs for PWRs " * Commission NUREG-0472 80/02/01 80pp
- ---8006020566 Informs NRC that CA Coastal Commission found program for monitoring radiological discharges from facilities to be grossly inadequate Requests that NRC work w/Southern CA Edison to correct deficiencies in monitoring program FISCHER, M.L. California, State of 80/01/10 ip
- 8006030373 Forwards results of investigation of anchorage of safety-related electrical equipment BASKIN.X P Southern California Edison Co 80/05/23 App
- 800&030439 Responds to NRC 800417 ltr requesting add1 info re SEP Topic VI-4 Containment isolation sys is being modified during current refueling outage Enfo will be provided by 800&09 BASKIN-K P Southern California Edison Co 80705/23 ip
- BOO611043i Forwards requests for addition for review of FSAR Approval of CEMPD-17B re methods for determining fuel assembly loads has been suspended pending receipt of addition from C-E BCHMENCER, A Licensing Branch 3 BO
- BOO6170221 Notifies that Project Manager T Nambach is coordinating licensing activities as result of reorganizatin within Ofc of Nuclear Reactor Regulation Description of new organization encl CRUTCHFIELD, D. Operating Reactors Branch 5 80/06/02 32pp
- 8006300230 Forwards request for addl info re SEP Topic VI-4.containment purgs & venting Response requested within 30 days CRUTCHFIELD, D. Operating Reactors Branch 5 80/06/12 4pp
- 8006190584 Discusses completed review of NRC 800507 ltr forwarding five add1 items resulting from post-TMI reviews Forwards commitments to meet implementation requirements for Items RASKIN, K.P. Southern California Edison Co. 80/06/13 7pp
- 8006200464 Forwards info re environ qualification of safety-related electrical equipment per NRG 800306 & 28 requests Info identified not available for inclusion in submittal will be provided in appropriate revisions

 BABKIN, K P Southern California Edison Co. 80/06/18 54pp

- @ Inspection reports, IE Bulletins & correspondence
- 8006200056 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/05/28 ip
- 8006180295 Ack receipt of 800513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/80-09 CREMB, J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/02 ip
- ---8006180301 Responds to NRC 800421 ltr re violations noted in IE Insp Rept 50-206/80-09 Corrective actions emergency operating instruction 6-3-5 34 revised & training for operators PAPAY, LT Southern California Edison Co BO/05/13 Spp
- --8006180305 Forwards IE Insp Rept 50-206/80-09 on 800301-0404 & natice of violation CREMS.J L. Region 5. San Francisco: Reactor Operations Nuclear Support Branch 80/04/21 2pp
- --8006180310 Notice of violation from insp on 800301-0404 * Region 5, San Francisco. Office of the Director B0/04/16
- --8006180314 IE Insp Rept 50-206/80-09 on 800301-0404 Noncompliance noted failure to follow emergency procedure & operation outside limiting condition for operation FAULKENDERRY. B. Region S. San Francisco, Reactor Operations Nuclear Support Branch MILLERL, Region 5. San Francisco, Office of the Director 80/04/16 12pp
- B006190497 Submits results of Westinghouse ultrasonic insp of low pressure turbine discs during Spring 1980 refueling outage Disc 5 displayed tangential aim indication in bore area at balance hole 13 Turbines to be returned to normal operation BASKIN,K P Southern California Edison Co 80/06/05 1p
- 8006270174 Forwards results of steam generator insps BASKIN, K P Southern California Edison Co 80/06/24 App
- R Periodic operating reports & related correspondence
- 8006160011 Forwards menthly operating rept for May 1980 CURRAN, J M Southern California Edison Co 80/06/09
- --8004160013 Monthly operating rept for May 1980 JQY, J M Southern California Edison Co 80 80/06/09
- S Reportable occurrences. LERs & related correspondence
- 8004040297 Forwards LER 80-019/017-0 OTTQ80N.H L Southern California Edison Co 80/05/22 2pp
- --8004040307 LER 80-019/01T-0 on 800510 during inspire IE Bulletin 79-14.
 U-boit support missing on RHR cooling water return lins
 Subsequent analysis showed selsmic streases excessive w/o
 support lew support installed 800510
 CURRAN, J M Southern California Edison Co 80/05/22 ip
- 8006030430 Forwards LER 80-020/017-0 OTTOSON, H L Southern California Edison Co 80/05/28 2pp
- -8006030438 LER 80-020/01T-O on 800513.two failed hydraulic shock & swar suppressors found during functional testing performance Caused by operator error & excessive hydraulic fluid leakage; leading to abnormal wear CURRAN.J M Gouthern California Edison Co 80/05/28 ip
- 8004030420 Forwards LER 80-024/01T-0 OTTOSON:H L Southern California Edison Co 80/05/29 2pp
- --8006030434 LER 80-024/0:17-0 on 800516. while performing radiographic stams of selected main steam lines inside containment, four welds were found w/indications consisting of slag inclusions, porosity k/or lack of penetration GURRAN, J M Southern California Edison Co 80/05/29 ip CURRAN, J M
- 8004030513 Forwards LER 80-021/01T-0 OTTOSDN,H L Southern California Edison Co 80/05/29 2pp

- EUO05180099 Comments on AO rept to Congress for first quarter CYBO Buggosts change of wording re-saltwater cooling sys pumps HICHELSON, C Director's Office 80/05/04 1p
- B006120286 Forwards LER 80-025/99X-0 OTT080N.H L Southern California Edison Co B0/06/06 2pp
- --8006120290 LER 80-025/99X-0 on B00505, during dye penetrant insp of reactor coolant pump flywheel bores in refueling outage, linear indications found in welds Cause unstated Welds in bore of flywheels installed to prevent relative motion CURRAN. J M Bouthern California Edison Co 80/06/06 1p
- B006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch albows & 2-inch tees were mfg to
 A234WPB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY.J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006130210 Forwards LER 80-026/01T-0 % rept re automatic initiation of auxiliary feedwater sys.per 800513 meeting w/NRC
 BASKIN,K P Southern California Edison Co 80/06/10 3pp
- --8006130218 LER 80-026/01T-0 on 800609, preliminary results of mein steam line break accident scenarios to determine containment response required corrective actions to reduce calculated peak containment prossures Rept re 800513 meeting encl CURRAN, J M Southern California Edison Co 80/06/09 48pp
- 8006230313 Forwards LER 80-023/03L-0 OTT090N.H L Southern California Edison Co 80/06/18 2pp
- --800A230323 LER 80-023/03L-0 on 800523, during refueling outage, flaw detected extending below min wall thickness in heat exchanger E-20B Caused by improper clearance of previously repaired flaw Flaw repaired CURRAN, J M Southern California Edison Co 80/06/18 1p
- DOCKET 50-209 COLUMBIA UNIV RESEARCH REACTOR

 F Becurity, medical, emergency & fire protection plans
- 8004070352 Notifies that univ lacks security plans bringing physical protection to level consistent w/corrent rules & regulations Bince no BNM or 89NM is associated w/license, measures for physical protection were not initiated LORIO.P M Columbia Univ 80/05/30 1p

DOCKET 50-213 HADDAM NECK PLANT

- F Security, medical, emergency & fire protection plans
- 8006060426 Forwards request for add1 info ro facilities' #mergency plans Plans should be evaluated against NUREG-0654 & encl comments by 800630 CRUTCHFILED.D M Operating Reactors Branch 5 80/05/12 36pp
- 80040904B7 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50,48 & App R to 10GFR50 & is expected to be published in FR by end of May.

 EISENHUT, D Q Division of Licensing 80/05/19 46pp
- BOO6130063 Forwards revised Pages i-14 to new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800517 ltr Page 14a not encl EISENHUT, D 0 Division of Licensing 80/05/22 73pp
- BO06060367 Bubmits info to reaffirm adequacy of current fire protection plans to fulfill BER commitments. One oversize drawing encl COUNSIL. W. 9 Northwast Nuclear Energy Co (subs of Northwast Utilities) COUNSIL. W. 9 Connecticut Yankee Atomic Power Co B0/05/27 Bpp
- P Operating license stage documents & correspondence
- 8004200571 Requests and emargency change to route approved by NRC 800331 ltr Change necessary due to portion of route being closed for maint, Encl withheld (ref 10CFR2 790).

 GOUNGILIN 0 Gonnecticut Yankee Atomic Power Co 80/04/21. 1p.

- 8006080486 Advises that 800421 request for change in spent fuel route has been reviewed & approved Pages describing detour route for "Spent Fuel Route Survey" insertion withheld (ref 100FR2 790)
 MCCORKLE.G W Physical Security Licensing Branch 80/04/23 ip
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D Q Division of Licensing 80/05/07 150pp
- 8006250180 Forwards NUREG-0654.Vol I & II & NUREG-0611 H/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/05/16 2pp
- 8006130122 Requests comments on NUREC-0577, "Potential for Lou Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D G Division of Licensing 80/05/19 72pp
- 8006020203 Application to amend License DPR-65 by incorporating revisions to Tech Specs for Millstone 2 in response to NRC 800410 request Proposed changes are necessary for safe operation of Pacility Millstone 2 is only unit w/Tech Specs CDUNSIL.W 0 Connecticut Yankee Atomic Power Co CDUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/21 3pp
- --8006020211 Proposed revisions to Tech Specs for Millstone 2.
 incorporating requirements of NRC 800410 ltr to all power
 reactor licenses
 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/05/31 700
- 8006110237 Forwards "Environ Qualification of Electrical Equipment" in response to NRC requests Responds to five items identified in NRC 800306 itr containing environ qualification program schedule Component worksheets and COUNSIL.W G Connecticut Yankee Atomic Power Co 80/06/02 204pp
- B006190402 Notifies that licensing activities are being coordinated by R Caruso, due to reorganization of Oft of Nuclear Reactor Regulation Forwards description of reorganization CRUFCHFIELD.D Operating Reactors Branch 5 B0/06/02 35cp
- 8006130327 Reconfirms that all possible boron dilution paths evaluated in response to NRC 800423 ltr Worst case allows 31 5 minutes to recognize & terminate dilution flow COUNSIL.W 0 Connecticut Yankee Atomic Power Co 80/06/04 2pp
- 8006130316 Notifies that info re transient & accident analysis is provided by MCAP-9691 in response to NRC 791030 ltr NRC 800317 requests conflict w/verbal agreement re scope of NUREC-0578 Requirement 2 1 9(c) No further action planned COUNSIL.W O Connecticut Yankes Atomic Power Co 80/06/06 2pp
- BOO6190457 Forwards info ro five add1 TMI-2 related requirements applying to operating reactors per BOO507 request Integrated assessment of collective impact of all requirements should be conducted COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Power Co
- 8006200456 Responds to open items noted in NRC 800117 ltr re requirements for auxiliary feedwater sys Each feedwater train will have two operators verifying proper valve alignment New level instrumentation sys installed by 810101 COUNSIL.W G Connecticut Yankee Atomic Power Co 80/06/10 2pp
- 8006270198 Responds to 800418 questions re SEP Topic XV-16, radiological consequences of small lines carrying primary coolant outside containment No completely scaled areas exist where break might occur COUNBIL, N O Connecticut Yankee Atomic Power Co 80/06/20 4pp
- 8006300383 Responds to NRC 800214 ltr rs request for SEP references to docketed info Addresses topic number, title & listing of references identified to date List does not reflect exhaustive review of docketed correspondence COUNSIL, W O Connecticut Yankee Atomic Power Co COUNSIL, W. O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23 14pp

9 Inspection reports. IE Bulletins & correspondence

- 8006090191 Forwards IE Investigation Rept 50~293/80-12 on 800305-07 & 19-20 in response to allegations re illegal shipments of spent fuel MARTIN.H G Region 1, Philadelphia, Safeguards Branch 10/04/18
- --8006090194 lE Investigation Rept 50-293/80-12 on 800305-07 & 19-20 No noncompliance noted Major areas inspected examination of pertinent documents & records & physical inventory of all fuel assemblies
 KEHOELD., ROBERTS, K. Region 1, Philadelphia, Office of the Director JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch 80/04/16 12pp
- B006240017 Responds to IE Bulletin B0-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Review determined adequate vacuum protection exists on those sys for which tank demage could necur
- 8008240611 Atk receipt of 800508 ltr informing NRC of incorrect statements made in IE Insp Rept 50-293/80-12 Corrected pages enci W/o enci MARTIN.W O Region 1. Philadelphia, Safeguards Branch 80/05/22
- ---8006240617 Responds to NRC 600418 ltr Northeast Nuclear Energy Coincorrectly identified as util licensed to operate Haddam Nack Plant COUNSIL.H G . SMITZER.D C Northeast Nuclear Energy Co. (subs of Northeast Utilities) 80/05/08 2pp
- 8006090405 Forwards IE Circuler BO-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies " No written response required GRIER, D II Region 1, Philadelphia, Office of the Director 80/05/28 ip
- R Periodic operating reports & related correspondence
- BOOS170925 Forwards monthly operating rept for May 1980
 ORAVES, R H Connecticut Yantes Atomic Power Co 80/05/12 1p
- ---B006170928 Monthly operating rept for May 1980 * Connecticut Yankee Atomic Power Co B0/06/06 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006120270 RD while performing leak rate testing 6La acceptance criteria exceeded Cause not stated Followup rept will be provided within 14 days ORAVES R H Connecticut Yankee Atomic Power Co 80/05/17 1p
- 8006240297 Forwards ETS/NR/50-213/80-04 GRAVES/R H Connecticut Vankes Atomic Fower Co. 80/05/28 ip
- --8006240301 ETB/NR/50-213/80-04 during first quarter 1989, tritium activity level in water exceeded ETB limit Gaused by high release of radioactive liquid discharge prior to refueling shutdown Reporting requirements revised a Connecticut Yankse Atomic Power Co 60/05/28 2pp.
- 8006030510 Forwards LER 80-007/017-0

 ORAVES, R. H. Connecticut Yantes Atomic Power Co. 80/05/30. 1p
- ---8006030518 LER 80-009/01T-0 on 800516, while performing local leak rate testing leakage rate exceeded Tech Spec limits Caused by failure of component cooling water theck valve due to warped seating surface Surfaces reworked THOMAS, R H Connecticut Yankes Atomic Power Co 80/05/30. ip
- 8006130270 RB during eddy current testing of steam generators 1 & 2, two tubes in steam generator 2 exceeded plugging limit of 50% wall degradation Add1 insp performed & no further defects discovered gRAVES,R.N. Connecticut Yankee Atomic Power Co 80/06/05 ip
- 8006120375 RG 50-213/80-05 on 800628, while venting vol control tank to waste gas systemplanned release of Xe-133 occurred Caused by inadequate capacity in waste gas tenk to handle vol control tank yeart Study of vol control vent design initiated GRAVES, R. H. Connecticut Yankee Atomic Power Co. 80/06/06. 2pp

B006300420 RG B0~10/1P on 800621, while performing reviews of Category I, five seismic type supports found missing from two separate high pressure safety injection lines Three add supports found jeopardizing sys operability Supports to be replaced GRAVES, R H Connecticut Yankee Atomic Power Co 80/06/23 1p

DOCKET 50-219 OYSTER CREEK NUCLEAR POHER PLANT

- B006300441 Forwards Endorsements 54 & 55 to MAELU Policy MF-44
 GERETY, H F General Public Utilities GPU Service Corp 80/06/23
- F Security, medical, emergency & fire protection plans
- B006040128 Forwards comments re 800817 submittal of guard training & qualification plan Response requested within 30 days. Comments withheld (ref 10CFR2 790)
 CRUTCHFIELD.D Operating Reactors Branch 5 80/05/07 2pp
- 8006190073 Responds to 800514 telcon me NRC concerns for emergency readiness at facility Lists action to be undertaken & completed by end of current outage GRIER. 8 H Region 1. Philadelphia. Office of the Director 80/05/16
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CFR50 % is expected to be published in FR by end of May EISENHUT, D @ Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- B006090249 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFR2 790)
 FINFROK, I R Jersey Central Pawer & Light Co 80/06/03 1p
- BOO6300356 Notifies that revised security officer training & qualification plan will be submitted by BOO630 in response to NRC request received on BOO519 PINFRDCK. I R Jersey Contral Power & Light Co BO/06/23 ip

- 800612050B Forwards Qcean County NJ Freeholder, RA Gasser, 80050B mailgram expressing concerns re adequacy of repairs being made at facility NRC should directly contact county officials w/response HUGHES M. J House of Rep 80/05/14 2pp
- 8006300691 Responds to B0080B mailgram to Congressman Hughes re adequaty of spray sparger repairs Repairs evaluated in encl safety evaluation to Amend 47 to License DPR-16 M/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/23 4pp
- --8006300693 Forwards RA Gasser 800508 mailgram re adequacy of spray sparger repairs, for response HUGHES, W.J. House of Rep. 80/05/14 3pp
- J Insurance & indemnity information
- 8006240498 Forwards Endorsements 68.69 t. 70 to NELIA policy NF-164
 GERETY.H F General Public Utilities GPU Service Corp B0/06/19
- P Operating license stage documents & correspondence
- 8006020586 Advises that 791004 proposal for spent reactor fuel shipment route meets requirements of 10CFR73 37 w/exception of areas covered by enclosed replacements Encls withheld (ref 10CFR2 790)
 MCCORKLE.O W Physical Security Licensing Branch 80/04/16 2pp
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D C. Division of Licensing. 80/05/07 150pp

- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems 80/05/09 8pp
- 9006250037 Forwards NUREG-0654,Vol I & II & NUREG-0626 for info W/o encl CRUTCHFIELD,D Operating Reactors Branch 5 80/05/16 2pp
- B006130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D Q Division of Licensing 80/05/19 72pp
- 800603000P Forwards Tech Spec Change Request 86 for License DPR-16 Class II fee enci FINFRQCK.I R Jersey Central Power & Light Co 80/05/22 ip
- --8006030012 Application for Tech Spec Change Request 86 for License DPR~16 Certificate of Svc & util 800522 ltr to Lacey Tournehip encl FINFROCK, 1 R Jersey Control Power & Light Co 80/05/22 3pp
- --8006030014 Tech Spec Change Request 84 revising Section 1 1 definition of "operable" & adding Section 3 re general limiting conditions for operation # Jersey Central Power & Light Co 80/05/22 6pp
- 8004090395 Responds to NRC 800214 ltr requesting docketed info recentain BEP topics
 NA9ALY Jersey Central Power & Light Co 80/04/02 2pp
- 8006230263 Notifies that facility licensing activities are being coordinated by W Paulson, due to reorganization of Ofc of Nuclear Reactor Regulation Forwards description of reorganization CRUTCHFIELD, D Dereating Reactors Branch 5 80/06/02 35pp
- 8006190604 Forwards add1 info re SEP Topic III-6, "Beismic Design Consideration," in response to NRC request JA Blume & Associates, "Seismic Reanalysis of Buried Emergency Byc Haler Lines," encl
 NAGAI.Y Jersey Central Power & Light Co 80/06/03 7pp
- --8006190612 "Seismic Reanalysis of Buried Emergency Svc Water Lines "
 # John A Blume & Associates, Engineers (subs URB Corp)
 79/12/19 16pp
- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREQ-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC Prior to final implementation W/o encl EISENHUT, D & Division of Licensing 80/06/05 22pp
- 8006170496 Bubmits further info re implementation of NUREO-0578
 Description of upgrade of containment vent & nitrogen purge
 systresults of release pathways design review & info re
 plant shielding review encl
 FINFROCK, I R Jersey Central Power & Light Co 80/06/10 13pp
- 8006180423 Requests permission to complete mods during 1781 fall outage beginning no later than 811130 Encl list of mods completed Plant-unique test on safety relief valve discharge device & vacuum breakers performed Four-month extension justified. FINFROCK, I. R. Jersey Central Power & Light Co. 80/06/11 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006020176 Forwards IE Insp Rept 50-219/80-07 on 800311-14 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/07 2pp
- --9006020180 IE Insp Rept 50-219/80-09 on 800311-14. No noncompliance noted Major areas inspected inservice insp data review meeting, plant tour & foliowup on regional request. KEIMIO,R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. BRIGGS,L, MALTON,O Region 1, Philadelphia, Office of the Director 80/04/04 App
- 8006200090 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency Reactor Protection Sys Response Time." No written response required ORIER, B. H. Region 1, Philadelphia: Office of the Director 80/04/18 | 19

- 8006020467 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Review of valve list indicates that no AH-90 or NH-90 series hydramotor valve actuators are used in any safety/nonsafety-related sys at facility
 ROSB.D A Jersey Central Power & Light Co B0/05/09 ip
- 8006270403 Forwards IE Insp Rept 50-219/80-14 on 800418 No noncompliance noted SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/12 2pp
- ---8006270406 IE Insp Rept 50-219/80-14 on 800418 No noncompliance noted Major areas inspected status of radiation protection commitments KNAPP,P J , NIMITZ,R L. Region 1. Philadelphia, Office of the Director 80/05/09 34pp
- 8006190148 Forwards IE Mgt Meeting Rept 50-219/80-18 on 800429 ORIER,B H Region i, Philadelphia, Office of the Director 80/05/23 2pp
- --8006190153 IE Mgt Heeting Rept 50-219/80-18 Areas discussed licensee corrective actions arising from insp findings, radiation protection concerns resulting from recent insp & actions to improve overall mgt controls
 BRIOOS, L. E., XNAPP, P. J. Region I. Philadelphia, Office of the Director XEIMIGO, R. Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/20 8pp
- 8006250007 Ack receipt of 800505 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-217/80-12 Ltr withheld (ref 10CFR2 790)
 MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/05/27 ip
- --8006250013 Forwards IE Insp Rept 50-219/80-12 on 800325-28 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN W G Region 1, Philadelphia, Bafeguards Branch 80/04/16 2nn
- --8006250017 IE Insp Rept 50-219/80-12 on 800325-28 Noncompliance noted failure to foliom Procedure 1002 3,5NM inventory Details withheld (ref 10CFR2 790)
 JONNER, J H , SUMMERS, R Region 1, Philadelphia, Safaguards Branch 80/04/14 | 1p
- BOO6270084 Forwards IE Insp Rept 50-219/79-25
 GRIER, B H Region i, Philadelphia, Office of the Director 80/06/05 ip
- --B006270090 lE Insp Rept 50-219/79-25 re 800605 mgt meeting to discuss NRC concerns resulting from Radiation Protection Insp 50-219/79-07 Discussed licensee immediate corrective actions & long-term plans NIMITZ.R L. Region i, Philadelphia, Office of the Director BMITH.O H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch B0/05/27 22pp
- R Periodic operating reports & related correspondence
- 8006200455 Forwards monthly operating rept for May 1980 ROSS.D A Jersey Central Power & Light Co 80/06/13 ip
- --8006200458 Monthly operating rept for May 1980
 MCCLAIN, C M Jersey Central Power & Light Co 80/06/04 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006060156 Forwards RO 80-17-1P re possibility of removal of more than one control rod w/surrounding fuel CARROLL, J T Jersey Central Power & Light Co 80/05/16 ip
- --8006060163 RO 80-17-1P on 800516, during refueling shutdown, control rod interference checks revealed that rod block bypass jumpers were not removed during control blade replacement resulting in possible removal of control rods w/surrounding fuel PICKEISSEN, K O , MOLNAR, J Jersey Central Power & Light Co 80/05/16 2pp
- 800&040337 PNO-I-80-082, an 800521, one worker received 2-inch contaminated cut measured at 80 counts per minute Worker treated medically State of NJ notified No press releases planned NIMITZ.R., KNAPP.P., CAPHTON.D. Region 1, Philadelphia. Office of the Director 80/05/22 1p.
- 8004030444 Forwards LER 80-016/01T-0 ROSS,D A Jersey Central Power & Light Co 80/05/23 ip

- --9006030450 LER 80-016/017-0 on 800512.util recognized that 800420 discovery of defective pressure switch.PSL D.constituted immediate rept Caused by cocked teflon actuator Switch removed & will be replaced ROSS.D A Jersey Central Power & Light Co 80/05/23 3pp
- 8006060419 Forwards LER 80-017/017-0 ROSS.D A Jersey Central Power & Light Co - 80/05/30 ip
- --8004060424 LER 80-017/017-0 on 800516.while performing control rod interference checks, green-green rod position indication remained illuminated while uithdrawing rod 10-23 Caused by operator & procedure in bypass & component failure ROSS,D A Jersey Central Power & Light Co 80/05/30 3pp
- --800616002; LER 80-018/03L-0 on 800507, during monthly surveillance testing of reactor high pressure scram sensors, RE030 found to be less conservative than specified Gaused by sensor repeatability Sensor reset R098, D A Jersey Central Power & Light Co 80/06/05 3pp
- 8006160050 Forwards revised LER 80-001/01T-1 FINFRGCW,T R Jersey Central Power & Light Co 80/06/05 ip
- ---B006i60055 Revised LER 80-00!/0IT-1 on 800105. while performing electromatic relief valve operability test. valve failed to open Caused by improper staking of grub screw during assembly Retainer ring replaced ROSS.D A Jersey Central Power & Light Co 80/06/05 4pp
- ~~8006160096 Revised LER 80-002/03L-1 on 800116.during fuel bundle clip insp prior to fuel "sipping," fuel bundle UD3-023 was misoriented & not properly seated in one cell Gaussé by personnel error & inadequate procedures Procedures revised ROSS-D A Jersey Central Power & Light Co 80/06/05 4pp
- ~-8006120297 RO 50-219/80-20-iP on BOO605. Following insp of fire barrier, several penetrations found in degraded condition Caused by delay in performing further rise watches attributed to personnel error Fire watch being conducted GUINTENZ,T.E. Jersey Central Power & Light Co. 80/06/06. 2pp
- 8006190453 RO on 800502, during routine surveillance testing of isolation condenser initiation pressure switches, false high pressure signal caused reactor scram Caused by opening of gauge valve Mod performed on instrument line FENFROCK, I R Jersey Central Power & Light Co 80/06/16 2pp
- 8005240497 Forwards updated LER 80-013/017-1 RDSS.D A Carolina Power & Light Co 80/06/16 to
- --8005240502 Updated LER E0-013/017-1 on 800309.ftre suppression water sys removed from syc to replace diesel pump 1-1 discharge valve V-9-4 due to crack in valve body Caused by excessive stress between flange & valve due to increased vibration ROSS, D A Carolina Fouer & Light Co 80/06/16 2pp
- --8D06260187 LER 80-019743L-0 on 800517 during leak rate reduction program set pressures for two core spray sys relief valves were found to be incorrect Caused by component failure Satpoints for relief valves reset ROSS,D A Jersey Central Power & Light Co 80/06/17 3pp
- 8006260171 Forwards LER 80-020/017-0 8089:D A Jersey Central Power & Light Co 80/06/18 1p
- --8005260172 LER 80-020/01T-0 on 800505, following insp of fire barriers protecting safety-related areas, several penetrations found in degraded condition Caused by deficiencies in installation specs & personnel error re delay in establishing watches ROSS, D.A. Jersey Central Power & Light Co. 80/06/18 3pp
- 8006270299 Forwards revised LER 79-026/03L-1 RGSS,D A Jersey Contral Power & Light Co 80/06/20 ip

- --B004270303 Revised LER 79-024/03L-1 on 790807, while excavating to make repairs on equipment drain tank line, leak discovered in laundry tank discharge pipe Apparently caused by component failure Line repaired ROSE, D.A. Jersey Central Power & Light Co. B0/04/20. 3pp
- B006300474 Forwards LER 80-010/03L-1 RGSs,D A Jersey Central Power & Light Co 80/06/20 ip
- ---8006300477 LER 80-010/03L-1 on 790417, excavation was started to repair leak near inside penetration within pipe tunnel Activity was detected in soil near DEDT line DEDT line rerouted on 800316 Line will be repaired RDSS-D A Jersey Central Power & Light Co 80/06/20 3pp
- 8006300472 Forwards LER 80-023/03L-0 FINFROCK I R Jersey Central Power & Light Co 80/06/23. 1p
- --8006300482 LER 80-023/03L-0 on 800523, prior to inservice insp reactor vessel hydro, testing revealed that electromatic relief valve high pressure sensor IA83E exceeded Tech Spec setpoint On 800531, sensor IA83E found to exceed setpoint ROSS, D A Jersey Central Power & Light Co 80/06/23 3pp
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Security, medical, emergency 2 fire protection plans
- BOO6090497 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 100FR30 % is expected to be published in FR by end or May EISENHUT, D G Division of Licensing 80/05/19 46pp
- B006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101." transmitted by NRC B00319 1tr Page 14a not encl EISENHUT.D 0 Division of Licensing B0/05/22 73pp
- 8006190039 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licenses security forces b practices; including visit to facility to interview security mpt personnel IPPOLITO,T A Operating Reactors Branch 2 80/06/03 2pp
- B006190475 Forwards sys description & drowings for proposed sprinkler protection of cable trays in response to NRC 790726 ltr Concurrence requested by B00715 Drawings available in Central Files only DISE.D P Niagara Mohawk Power Corp B0/06/10 ip
- J Insurance & indemnity information
- BOO6110241 Forwards Endorsement 70 to NELIA Policy NF-161 RUSHMORE, J W Niagara Mohawk Power Corp 80/06/04 2pp
- BC05110253 Forwards Endorsement 59 to MAELU Policy MF-46 RUSHMORE, J W Niegara Mohawk Power Corp 80/05/04 2pp
- P Operating license stage documents & correspondence
- 8006Q30570 Responds to NRC request for info re plans to shut down margin testing & examinations of highly exposed control blades Shutdown test performed in Spring 1977 Similiar test to be performed during failure cycles LEMPOES.TE Niagara Mohawk Power Corp 80/05/02 2pp
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Liconsees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES.C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl, EISENHUT,D & Division of Licensing 80/05/19 72pp

- 8006030471 Forwards containment vent & purge sys info & drawings,in response to NRC 800428 itr Drawings available in Central Files only RHODE, & K. Niagara Mohawk Power Corp. 80/05/29 2pp
- 8006060394 Responds to 800215 % 0509 requests for review of plant geotechnical investigations Util should evaluate safety implications of crack in reactor bldg north wall WIŁKINSON.T A Army.Dept of. Corps of Engineers 80/05/30 2pp
- BOO6300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-0619. "BUR Feedwater Noirle & Control Rod Drive Return Line Noirle Cracking "Comments will be evaluated by NRC prior to final implementation W/o encl Division of Licensing 80/06/05 22pp
- 8006300305 Forwards response to NRC 800516 request for info re turbine discs Info demonstrates that continued operation does not present undue safety hazard to public DISE.D P Niagara Mohawk Power Corp 80/06/19 7pp
- 8006270289 Forwards final results of plant shielding design review required by NUREO--0578.Recommendation 2 1 6 b Includes plant radiation tone maps.components/sys subj to excessive radiation damage from TID sources & description of mods DISE.D P Niagara Mohawk Power Corp 80/06/20 13pp
- 8006300378 Forwards table outlining position re commitment to requirements & schedulos of five add1 TMI-related items.in response to NRC 800507 request Requests NRC acceptance criteria for responses to ensure timely implementation DISE.D P Niagara Mohawk Power Corp 80/06/20 12pp
- @ Inspection reports, IE Bulletins & correspondence
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/04/07 2pp
- --8005230341 Waste packaging inspirept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DDT placarding requirement POTTER, J.P., BROWN, R.A. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 60/03/28 4pp
- 8006020264 Forwards 1E Insp Rept 50-220/80-02 on 800303-07 No. noncompliance noted
 BRUNNER, F J Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch 80/04/11 2pp
- --8006020264 IE Insh Rent 50-220/80-02 on 800303-07 No honcompliance moted Major areas inspected small break LDCA procedures training verification of as-built piping sys t isolation candenser piping supports
 KISTER H B Region 1, Philadelphia, Reactor Operations Nuclear
 Support Branch BAUNACK, W. JURNSON, J Region 1, Philadelphia,
 Office of the Director 80/04/10 9pp
- 8006200089 Forwards If. Circular 80-08. "BuR Tech Spec Inconsistency Reactor Protection Sys Response Time " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/18 1p
- 8006190222 Forwards Waste Packeging Insp Rept 80~03 on 800313-14 No noncompliance noted SMITH, 0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 Zpp
- --8006190230 Waste Packaging Insp Rept 60-03 on 800313-14
 No noncompliance noted Major areas inspected compliance
 w/NRC & DOT regulations, including shipping paper, placarding
 & radiation levels
 POTTER.J F. BROWN R A Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch 80/03/28 App
- BOOA03005B Responds to IF Bulletin 79-14 re seismic analysis for safety-related piping Insp of all areas including inside drywell completed Evaluation & review resulted in 140 restraint mods LEMPGES, T E Niagara Mohawk Power Corp B0/04/30 3pp
- 8005020462 Forwards response to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " All safety-related equipment remains in emergency mode upon reset of engineered safety feature actuation signal LEMPOES.T E Niagara Mohawk Power Corp 80/05/12 3pp

- 8006120358 Informs of improvement in schedule of work being performed by GE re remaining requests contained in IE Bulletin 79-01B Plans to provide aforementioned response by 801231 instead A 910331 LEMPOES, T E Niagara Mohawk Power Corp 80/05/13 ip
- 8006200577 Discusses results of recent ultrasonic insps of GE low pressure turbines Some undications of cracks in keyway have been discovered at three plants Requests info re turbine discs to determine underlying reasons for cracking IPPOLITO,T A Operating Reactors Branch 2 80/05/14 3pp
- B006020046 Forwards "Evaluation of Licensee's Responses to IE Bulletin 79-08. Niagare Mohauk Power Corp. Nine Mile Point Nuclear Station. Unit 1 " Util has met requirements of bulletin IPPOLITO.T A Operating Reactors Branch 2 80/05/21 23pp
- 800630027i Supplements 800430 response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Two restraints in containment spray raw water sys were modified to be consistent w/original design LEMPGES, T. E. Niagara Mchawk Power Corp. 80/06/02 ip
- 8006300265 Responds to items of noncompliance noted in IE Insp Rept 30-220/80-04 Corrective actions Instruction Procedure 01-18 has been written APN-2 will be revised to describe current maint organization
 LEMPGES, T E Niscara Mohawk Power Corp. 80/06/23 is
- 8 Periodic operating reports & related correspondence
- 8006i10171 Forwards monthly operating rept for May 1980 LEMPGES.T C Niagara Mohaw? Power Corp 80/06/06
- --8006110176 Monthly operating tept for May 1980 * Niagara Nohawk Power Corp 80/06/03 4p
- S Reportable occurrences, LERs & related correspondence
- 8006070360 Forwards LFR 80-010/03L-0 LEMPGES: T E Niagara Mohawk Power Corp 80/06/03 lp
- --8006090362 LER 80-010/03L-0 on 800528, while performing valve chacks, operator discovered cardox tank pressure below Tech Spec limits Caused by delivery of too low temp carbon dioxide by supplier Low pressure alarm connected FALISE, M J Niagara Mohawk Power Corp 80/06/03 1p
- 8006090370 Forwards LER 80-009/03L-0
 LEMPGES, T E Niagara Mohawk Power Corp. 80/06/03 1p
- --8006090376 LER 80-009/03L-0 on 800521.during steady state operation, attempts to attoke 122 containment spray isolation valve failed Caused by isolation valve solenoids being dirty Ravising procedures to require periodic maint for valve FALISE, M J Niagara Mohawy Power Corp 80/06/03 1p
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR P Operating license stage documents & correspondence
- 8006200609 Requests addl info to support license amend request re increase in power lavel Requires resubmittal of SAR, submittal of revised Teck Specs & revised physical security MILLER. J R Standardization & Special Projects Branch 80/08/30 Эвр
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR
- G Adjudicatory correspondence
- 8006240614 Discusses 800414 decision to deny Friends of the Earth 791211 petition re facility Decision will constitute final action unless Commission institutes review within 20 days Forwards decision.FR notice & related safety evaluation DENTON.H R Office of Nuclear Reactor Regulation, Director
- 8006020301 Order granting extension until 800602 for Commission to elect whether to review Director's decision, DD-80-15, taken under 10CFR2 206 Office of the Secretary of the Commission 80/05/23

- 8006120314 Advises that decision of Ofc of Nuclear Reactor Regulation director to request to suspend activities, revoke OL, remove radioactive matts & hold public hearings is final NRC action CHILK,S J Office of the Secretary of the Commission 80/06/10
- 8 Reportable occurrences, LERs & related correspondence
- 8006050484 PMO-V-80-035 licensee irradiated U sample in reactor as part of class experiment Sample was returned via pneumatic sample transfer sys to receiving station within ventilation hood Sample holder had cracked No exposures involved VUHAS.G P Region S. San Francisco. Office of the Director 90/05/16 2pp
- DOCKET 50-225 RP1 CRITICAL EXPERIMENT Q Inspection reports. IE Builetins & correspondence
- 8006300606 Forwards IE Insp Rept 50-225/80-03 on 800429-0501 No noncompliance noted
 MARTIN.W G Region i, Philadelphia, Safeguards Branch 80/05/66
- --8006300610 IE Insp Rept 50-225/80-03.on 800429-0501 No montempliance noted Major areas inspected security plansprotection of SNM, security organization.access control.alarm sys.keys.locks & hardware Details wishhold (ref 10CFR2 790)

 BEVLIN.J W Region I. Philadelphia. Safeguards Branch
 HAMKINS,W C. LADUN.R M Region I. Philadelphia. Office of the Director 80/05/13 ip
- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- B00619029B Forwards description of improvements in facility security re-safeguards alarm sys Changes withheld (ref 10CFR2 790)
 NEWACHECK, 8 L. Aerotast Operations 80/06/13 ip
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- BOO6020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline uill also be used KEPPLER.J G Region 3. Chicago. Office of the Director BO/O B0/04/18
- 8006040131 Forwards comments re 790818 submittal of training & qualification plan Response requested within 30 days Comments withheld (ref 10CFR2 790) GRUTCHFIELD.D Operating Reactors Branch 5 80/08/09 2pp
- BOO6120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AMEARNELJ F Commission 80/05/13 2pp
- B006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D G Division of Lacensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 100FR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl
 EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8008200827 Requests revision of 800324 safeguards contingency plan in accordance w/comments described in encl to ltr Response requested within 30 days Encl withheld (ref 10CFR2 790) CRUTCHFIELD:DM Operating Reactors Branch 5 80/05/27 2pp
- 8008050276 Informs that licensee submitted add1 info on 800408 re fire protection review Evaluation enci re Item 3 i 5.water **tuppression** Brookhaven National Laboratory. 80/06/02 2pp
- 8005180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also enc! PEDFLES,D L. Commonwealth Edison Co 80/06/04 2pp

- --8006180331 Draft emergency plan anner
 # Commonwealth Edison Co 80/07/31
- ---8006180347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co 80/07/31 13900
- 8006180031 Provides into re access of NRC & NRC contractor personnel to facilities to conduct appreisal of health physics program Unsite phase is scheduled for approx 2 wks beginning 800617 List of authorized NRC personnel encl KEPPLER. J Q Region 3. Chicago. Office of the Director 80/06/05
- B006240316 Forwards, "Dresden Nuclear Power Station B00619 Emergency Response Plan Exercise." to verify Comm Ed emergency plan PEOPLES, D.L. Commonwealth Edison Co. 80/06/18 2pp
- --8004240318 "Dresden Nuclear Power Station 800419 Emergency Response Plan Evercisa Commonwealth Edison Co 80/06/19 63pp
- 8006240490 Responds to NRC 800429.30.0501.09 & 20 ltrs requesting add1 info re guard training & qualification plans Requests that response submittal date be extended to 800804 PEOPLES.D L Commonwealth Edison Co 80/06/18 ip
- P Operating license stage documents & correspondence
- 7703140172 Forwards GE rept NEDE-23B9B-P, "Analytical Model for Computing Water Rise in Safety Relief Valve Discharge Line Following Valve Closure "Rept provided as Task 7 1 2 2 of Mark I program Rept withheld (ref 10CFR2 790) JANECEK, R F Commonwealth Edison Co 79/03/12 ip
- 8006070165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include whift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT,D 0 Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose.CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006250177 Forwards NUREG-0654, Vol I & II & NUREG-0626 W/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/05/16 2pp
- 8006130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enc1 EISENHUT.D @ Division of Licensing 80/05/19 72pp
- 8006030478 Notifies of delay in evaluation of reactor-turbine bldg design parameters, due to difficulties in obtaining info on installed equipment weights & reviewing final as-built drawings info will be forwarded by 800715

 JANECEK, R F Gommonwealth Edison Co 80/05/21 1p
- 8006030062 Application to amend Licenses DPR-2, DPR-19, DPR-25, DPR-29 & DPR-30, clarifying term "operable," submitted as Tech Spec change request, in response to NRC 800410 ltr NAUGHTON.W F Commonwealth Edison Co 80/08/30 2pp
- ---B006030072 Tech Spec change request for Tech Specs Sections 1 0-1 2,2, & 2 2,3 0.5 0 & 6 0-6 6 re definitions.administrative controls.safety limits.limiting safety sys setting & limiting conditions for operation # Commonwealth Edison Co B0/05/30 42pp
- 800Ai90305 Responds to M Fletcher questions re SEP Topic IX-1, spent fuel storage Spent fuel storage pool designed to withstand anticipated earthquake loadings as Class 1 structure JANECEK, R F Commonwealth Edison Co 80/06/02 3pp
- 8006200551 Advises that reorganization of Dfc of Nuclear Reactor Regulation became effective on 800428 Project Manager P D'Connor will coordinate licensing activities for facility Reorganization described in encl CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 35pp.
- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT.D O Division of Licensing 80/06/05 22pp.

- 8006130260 Forwards "Environ Gualification of Electrical Equipment. Dresden Nuclear Power Station. Unit 2." Vols 1-3 PEOPLES D L Commonwealth Edison Co 80/06/10 2pp
- --8006130261 "Environ Qualification of Electrical Equipment, Drosdon Nuclear Power Station, Unit 2, " Vol 1 of 3 * Bochtel Power Corp (subs of Bachtel Corp) 80/06/02 64PP
- --8006130262 "Envisor Qualification of Electrical Equipment, Dresden Nuclear Power Station, Unit 2." Vol 2 of 3 * Bechtel Power Corp (subs of Bechtel Corp) 80/06/02 170pp
- --8006130263 "Environ Qualification of Electrical Equipment, Dresden Nuclear Power Station, Unit 2," Vol 3 of 3

 * Bechtel Power Corp (subs of Bechtel Corp) 80/06/02 200pp
- 8006190456 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 790808 request JANECEK.R F Commonwealth Edison Co 80/06/11 3pp
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltm re add1 TMI-2 related requirements Dresden Unit 1 is currently undergoing extensive mod & decontamination, therefore no response 1s provided PEOPLES,D L. Commonwealth Edison Co. 80/06/12 10pp
- 8004190419 Confirms availability of ECCS equipment following do power supply failure.per 800425 request Mods to ensure availability of HPCI following do power failure completed at Dresden & in progress at Guad Cities
 JANECEK.R F Commonwealth Edison Co 80/06/12 2pp
- BOO6250277 Forwards response to NRC 800516 ltr requesting info re turbine disc cracking Stress corrosion cracks not observed to date JANECEK, R. F. Commonwealth Edison Co. 80/06/23 16pp
- BOO6270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations "Revised Revision 11 includes basis on which equivalent education requirements will be established PEOPLES.D L Commonwealth Edison Co BO/06/23 1p
- G Inspection reports, IF Bulletins & correspondence
- 8006200110 Forwards IE Circular 80-08. "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 90/04/18 1p
- 8004170308 Forwards IE Insp Repts 50-010/80-07,50-237/80-07 & 50-249/80-10 on 800303-0404 & notice of violation HEIBHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --B006170312 Nutice of violation from insp on 800303-0404 * Region 3, Chicago, Office of the Director 80/04/22 ip
- ---B006170320 IE Insp Repts 50-010/80-07.50-237/80-07 & 50-249/80-10 on B00303-0404 Noncompliance noted failure to follow radiation protection procedures BARKER, J. L. TONGUE, I M. SPEBSARD, R. L. Region 3, Chicago, Office of the Director B0/04/22 5pp
- 800602000B Responds to IE Bulletin 79-26 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated B4C leaching Control blade exposures will be monitored during cycles to verify projected end-of-cycle exposure PEOPLES.D L. Commonwealth Edison Co. 80/05/19 2pp
- BOO6300558 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Proposed mods identified only if present sys design may compromise protective action of equipment PEOPLES D L. Commonwealth Edison Co 80/06/10 9pp
- R Periodic operating reports & related correspondence
- BOOG110100 Forwards monthly operating repts for Apr 1980 STEPHENSON, B B Commonwealth Edison Co 80/05/12 1
- --8006110102 Monthly operating repts for Apr 1980 C1682KIEW1CZ.B Commonwealth Edison Co 80/05/05 28pp

- 8006170448 Forwards monthly operating repts for May 1980 STEPHENBON, 8 B Commonwealth Edison Co 80/06/09 1p
- --8006170457 Monthly operating rept for May 1980 CIESZKIEWICZ,S Commonwealth Edison Co 80/06/02 App
- S Reportable occurrences. LEAs & related correspondence
- 8006030394 Forwards LER 80-016/01T-0 STEPHENSON, B B Commonwealth Edison Co 80/05/20 1p
- ~-8004030400 LER 80~016/01T-0 on 800515, while shut down & conducting 300 psi primary sys hydrostatic leak insp,water discovered dripping from LPCI check valve Caused unknown ZIRMAS. Commonwealth Edison Co. 80/05/21 2pp
- 8006030340 Forwards LER 80-015/03L-0 8TEPHENBON,B B Commonwealth Edison Co 80/05/27 ip
- --8004030349 LER 80-015/03L-0 on 800502, during routine operability surveillance, torus to drywell vacuum breaker was found inoperable Caused by swelling of teflon shaft bushings Bushings were machined to achieve required clearence DUNBAR, J Commonwealth Edison Co 60/05/28 1p
- 8006030364 Forwards LER 80-014/03L-0 8TEPHENSON, B B Commonwealth Edison Co 80/05/27 1p
- ---8006030379 LER 80-014/03L-0 on 800427, during normal operation, main steam line rad monitor 2C caused reactor protection sys channel A half-scram Caused by bad relay Defective component replaced BADRAN, B Communwealth Edison Co 80/05/27 1p
- 8006160097 Forwards LER 80-018/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/06/03 1p
- --8006160102 LER 80-018/03L-0 on 800512 during reactor startup. HPCI inboard steam isolation valve failed to close Caused by reactor heatup Steam caused valve packing to swell Packing adjusted & valve cycled eatisfactorily ZIRWAS,K R Commonwealth Edison Co 80/06/03 1p
- 8006170510 Forwards LER 80-017/03L-0 BTEPHENBON, B B Commonwealth Edison Co 80/06/05 ip
- --8006170519 LER 80-017/03L-0 on 800512, following unit scram, double valve indication observed on HPCI inboard isolation valve due to failed valve Caused by packing loak which allowed water to enter motor operator Motor dried out & valve repacked ZIRWAS.K Commonwealth Edison Co 80/06/05 ip
- DOCKET 50-249 GREGON STATE UNIV RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8006300286 Forwards 791018 Tech Spec amend request, proposed changes to Tech Specs, justification for changes to 791102 ltr redisclosure Mati withheld (ref 10CFR2 790) RINGLE, J C Oregon State Univ 80/06/18 ip •
- P Operating license stage documents & correspondence
- 8006240389 Responds to 800613 telcon re incident that happened at facility on 800520 Incident investigated & reactor operation procedures.(BSTROP 4.will be amended Amend calls for suspension of test reactor operation WANO, C H Oregon Btate Univ 80/06/18 3pp
- B Reportable occurrences. LERs & related correspondence
- 8006110183 RO on 800520, while performing routine pulses, one of five pulses produced peak power & measured fuel temp beyond expectation for 2 55 dollar reactivity insertion Apparently caused by 2 75 dollar reactivity insertation RINGLE, J. C. Oregon State Univ 80/06/03 4pp

- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plane
- 8006090497 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 100FR50 % is expected to be gubished in FR by end of May EISENHUT.D O Division of Licensing 80/05/19" 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule locFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr.Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- 8006020394 Bubmits response to Items 3 1 B.3 1 11,3 1 21,3 1 48 & 3 1 49 of mods to fire protection plan requested by NRC 790214 safety evaluation Completion schedule of mods will be delayed beyond June 1980 due to complexity of designs WHITE.L B Rochester Gas & Electric Corp 80/05/23 2pp
- 8006030338 Submits response to NRC 770214 fire protection safety evaluation re status of Items 3 i 34 (prefire strategies). 3 i 5 (fire doors). 3 i 24 (piping & duct penetrations) & 3 2 8 (exposed structural steel) WHITE.L D Rochester Gas & Electric Corp 80/05/29 2pp
- 8006ii0355 Responds to NRC 800425 itr transmitting fire protection safety evaluation suppl Info re design/clarification of previous submittals & verification of completed design encl Repts & drawings awailable in Central Files
 WHITE/L D Rochester Cas % Electric Corp 80/06/04 27gp
- 8006240542 Advises that NRC review of 800328 safeguards contingency plan revision is ongoing Requests response within 30 days to comments contained in encl Enci withheld (ref 10CFR2 790) GRUTCHFIELD.D Operating Reactors Branch 5 80706706 2pp

9 Adjudicatory correspondence

- 8006030196 Response to ASLB 800429 order requesting status repts Recommends deferral of adjudicatory proceedings' schedule consideration until 1981; to prepare for hearing after issuance of SER Supporting documentation encl KETCHEN,E G Hearing Branch 4 80/04/29 26pp
- 8006110225 Status rept by NY State Energy Dfc in reponse to ASLB 800429 order Recommends that.parties be permitted to identify addicententions & that prehearing conference be held to discuss issues Mynotice of appearance & Certificate of Syc enci
- 8006180006 Etatus rept in response to ASLB 800429 order Recommends schedule for findings, safety evaluation suppl.discovery & further prehearing conferences Recommends determination of SEP progress in one yr VDIGT.H H Rochester Gas & Electric Corp VOIGT.H H LeBoewf, Lamb. Leiby & MacRae 80/06/02 8pp
- --8095180010 Order denying applicant motion to dismiss MR Slade intervention Admits MR Slade contentions except C.G & H Centificate of Svc encl LUTON-E Atomic Safety and Licensing Board Panel 77/03/25 7pp
- 8006160104 Order dismissing intervenor Rochester Committee for Scientific Info per 740313 & 791210 stipulations terminating proceeding after applicant compliance w/requirements Requests for reconsideration may be filed within 14 days OROSEMAN.H Atomic Safety and Licensing Board Panel 80/06/12
- P Operating license stage documents & correspondence
- 8006090365 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D G Division of Licensing 80/05/07 150pp
- 800.6030094 Confirms 800515 mgt meeting in Ontario.NY arranged per 800429 telcon Agenda encl ORIER.8 H Region 1. Philadelphia. Office of the Director 80/05/09 2pp

- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT,D O Division of Licensing 80/05/19 72pp
- 8005250154 Forwards NUREQ-0454,Vol I & II & NUREQ-0611 W/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/05/21 2pp
- 8006030318 Forwards data & results of 48-h Standby Auxiliary Feedwater Pumps C & D endurance test WHITE,L D Rochester Gas & Electric Corp 80/05/28 37pp
- 8005030324 Forwards Procedure M-11 SB.Revision 9. "Major Mechanical Insp of Auriliary Feed Pumps." & Procedure PT-16, Revision 23. "Auriliary Feedwater Sys." in response to NRC 800418 request MHITE, L D Rochester Gas & Electric Corp 80/05/28 ip
- --8006030328 Procedure M-11 58, Revision 9, "Major Mechanical Insp of Auxiliary Feed Pumps" SCHULER: T. R. Rochester Gas & Electric Corp. 80/01/28 | 3bp
- --8006030347 Procedure PT-16.Revision 23, "Auxiliary Feedwater Bys " SCHULER: T R . MDDN, J Rochester Oas & Electric Corp 80/03/31 3Abn
- 8006030294 Responds to NRC 791023 request Forwards revised util 791214 commitments re containment purging WHITE.L D Rochester Gas & Electric Corp 80/09/29 2pp
- 8006040237 Act receipt of B00429 ltr re piping seismic analysis Design criteria will be submitted by B00715 & stress analysis repts for A-RHR & B main steam lines inside containment will be submitted by B00915 Mod Schedule will be based on analyses WHITE:L D Rochester Gas & Electric Corp 80/05/30 ip
- 8006040338 Forwards nonproprietary version of RELAP4-EM blowdown input for facility Proprietary info not enclosed reflects ENC proprietary analytical models & techniques or ENC fuel data Blowdown sys nodelization is in XN-NF-77-88 WHITE-L D Rochester Gas & Electric Corp 80/05/30 23pp
- 8006070326 Submits verification of compliance w/short-term Lessons Learned Task Force requirements re RCB venting Provisions made for venting reactor vessel head & pressurizer & for subsepting noncondensible gases from steam generator tubes WHITE.L D Rochester Gas & Electric Corp 80/06/02 4pp
- 8006190404 Notifies that licensing activities for plant are being coordinated by S Nowicki, due to reorganization of Ofc of Nuclear Reactor Regulation Forwards description of reorganization CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 35pp
- 8006090331 Forwards response to NRC 800226 ltr requesting addl info re SEP design basis events Topics cover steady state & instrument errors.single failure analysis.steam line break analyses & primary pump rotor seizure WHITE.L D Rochester Gas & Electric Corp 80/06/03 10pp
- BOO6160002 Forwards response to NRC 800306 request for info re "SEP Qualification Program Submittal Content " RUDMAN,R J Rochester Gas & Electric Corp 80/06/10 ip
- 8005180537 Comments on 800506 presentation to NRC Commissioners re status of SEP & description of difficulty as lack of aggression by licensees NRC has not provided guidelines Issues w/higher priorities have arisen WHITE, L D Rochester Gas & Electric Corp 80/06/12 3pp
- 8006180514 Forwards util response to 800507 ltr containing action items resulting from TMI Action Plan.including feedback procedures of operating experience to plant staff & worker radiation protection improvements

 WHITE
- B006250262 Forwards addl info rre SEP Topic XV-16. "Radiological Consequences of Small Lines Carrying Primary Cooling Outside Containment." per NRC 800311 request Drawings referenced in Table i submitted w/780912 ltr One oversize drawing encl WHITE, L D Rochester Gas & Electric Corp 80/06/18 7pp
- --8006250265 "Piping flow Diagram Heating, Ventilating & Air Conditioning " * Rochester Gas & Electric Corp. 75/09/30 ip

- 8006300433 Responds to 800425 ltr requesting review assessment & addl info on SEP Topic III-12 Util unable to respond within time frame requested Response expected 800801 WHITE L D Rochester Gas & Electric Corp 80/06/24 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8006050426 Ack receipt of 800501 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 50-244/80-04
 BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/14 lp
- --8004050429 Responds to NRC 800411 ltr re deviation noted in IE Insp Rept 50-244/80-04 Corrective actions new training effort to cover emergency procedure was undertaken WHITE/L D Rochester Gas & Electric Corp 80/05/01 2pp
- --8006050432 Forwards IE Insp Rept 50-244/80-04 on B00303-07 & notice of deviation BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 60/04/11 2pp
- --8006050440 IE Insp Rept 50-244/80-04 on 800303-07 Noncompliance noted failure to meet commitment re training of personnel on new procedure KISTER,H B. JOHNSON,D F., RAYMOND,W J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/10 9pp
- BOO6190103 Forwards evaluation of util responses to IE Bulletins 79-06A & 79-06A.Revision 1 Appropriate actions taken to meet bulletin requirements CRUTCHFIELD.D Operating Reactors Branch 5 80/05/28 20pp
- 8006200028 Forwards IE Circular 80-13, "Grid Strap Damage in Mestinghouse Fuel Assemblies" No written response required GRIER: BH Region I, Philadelphia, Office of the Director 80/05/28 ip
- 8006240605 Responds to IC Bulletin 80-02. "Exam of Containment Liner Penetration Welds " Containment penetrations described in bulletin do not resemble design employed at facility WHITELL D Rochester Gas & Clectric Corp 80/05/29 ip
- 8006300346 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol holdup tanks Licensee is evaluating addition of vacuum protection for holdup tanks which would satisfy criteria discussed in bulletin HHITE,L D Rochester Gas & Electric Corp 80/06/03 2pp
- 8006300494 Responds to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Circumstances & sequence of events of Davis-Besse 800419 event were reviewed Review included assignment to operational assessment group for on-shift discussions WHITE.L D Rochester Gas & Flectric Corp 80/04/03 3pp
- R Periodic operating reports & rolated correspondence
- 800&1&0037 Forwards monthly operating rept for May 1980 SNOW.B A Rochester Oas & Electric Corp 80/04/09 1p
- --BOO6160038 Monthly operating rept for May 1980 MCNAMARA:A E Rochester Gas & Electric Corp 80/06/09 5pp
- S Reportable occurrences, LERs & related correspondence
- 8004030587 RD 80-04 during performance of post-mod installation testing both power operated relief valves determined inoperable & RGS vent established Caused by two switches which supply do power in off position BNGW.8 A Rochester Gas & Electric Corp 80/05/07 ip
- BOO6050030 Forwards WCAP-9663. "Metallurgical Investigation of Cracks in Pressurizer Nozzle-to-Safe-End Weld of Robert Emmett Dinna Nuclear Power Generating Station " Rept is followup to LER 79-023 WHITE.L D Rochester Gas & Electric Corp BO/05/28 ip
- --B006050032 "Metallurgical Investigation of Cracks in Pressurizer Noizie-to-Bafe-End Weld of Robert Emmett Ginna Nuclear Power Generating Station " RAD,6 V , CAPLAN, J S Westinghouse Electric Corp , Nuclear Energy Bystems WCAP-9663 80/02/29 29pp

- 8006090317 RO 80-05 on 800603, during performance of procedure S-30 1, breaker for A-loop accumiator discharge valve. MDV-865, discovered in closed position Cause not stated Breaker immediately placed in proper position SNOW. B A Rochester Cas & Electric Corp 80/06/03 1p
- 8006230601 RO 80-05 on 800603 during performance of safety injection valve position verification procedure discovered breaker for A-loop accumulator discharge valve MDV-865 was in closed position Breaker placed in proper position.

 SNOW B A Rochester Qas & Electric Corp 80/06/03 1p
- 8006190473 Forwards LER 80-005/01T-0
 WHITE, L D Rochester Gas & Electric Corp. 80/06/16 in
- --B006190478 LER B0-005/01T-O on 800603 during performance of monthly verification procedure, loop A accumulator injection circuit breaker found in on position Cause not stated Breaker returned to off position
 PECK.C H Rochester Gas & Electric Corp 80/06/16 2PP

V Operator Examinations

- 8006110238 Forwards info re specific training of shift technical advisors & licensed operators, in response to NRC 800508 request Resumes of licensed operators enrolled in training encl
 WHITE.t. D Rochester Gas & Electric Corp 80/05/12 19pp
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8006060426 Forwards request for add1 info re facilities' emergency plans Plans should be evaluated against NUREQ-0654 & encl comments by 800630 CRUTCHFILED.D M Operating Reactors Branch 5 80/05/12 36pp
- BOO4090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds now Bection 50 48 & App R to 10CFR30 & is expected to be published in FR by end of May EISENHUT, D 0 Division of Licensing BO/03/17 App
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D Q Division of Licensing 80/05/22 73pp
- 8006060367 Submits info to reaffirm adequacy of current fire protection plans to fulfill BER commitments One oversize drawing encl COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Power Co 8D/05/29 Spp

- 8006170464 Advises of personnel change EJ Mroczka relieved JF Opeka as station superintendent on 800601 MROCZKA:E J Northeast Utilities 80/06/02 1p
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMT-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams 8 licensee dissemination of operating experiences Response requested within 30 days EIGENHUT.D.O Division of Licensing 80/05/07 150pp
- B006030514 Summary of B00422-23 meeting w/Mark I owners group in San Jose, CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES: CI. Assistant Director for Plant Systems B0/05/09 App
- B006130010 Discusses review of util B00124 submittal advising that blast wall between boiler room ½ diesel generator room, as required by Amend 53 to License DPR-21, is unnecessary Installation of blast wall still required CRUTCHFIELD,D Operating Reactors Branch 5 80/05/09 3pp
- 8006130122 Requests comments on NUREG-0977, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Collant Pump Bupports " Proposed review procedure & implementation schedule encl EISENHUT, D @ Division of Licensing 80/05/19 72pp

- 8006250039 Forwards NUREO-0654, Vol 1 & NU REG-0626 for info W/o enci CRUTCHFIELD, D Operating Reactors Branch 5 80/05/19 2pp
- 8004020203 Application to amend License DPR-65 by incorporating revisions to Tech Specs for Hillstone 2 in response to NRC 800410 request Proposed changes are necessary for safe operation of facility Hillstone 2 is only unit u/Tech Specs GOUNSIL.W G Connecticut Yanke Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/21 3pp
- 8006250005 Requests participation of util in interim reliability evaluation program Studies help identify accident sequences & vulnerabilities in procedures & basic design Util should appoint engineer to participate in initial 800604 maeting EISENHUT, D Q Division of Licensing 80/05/23 5pp
- 8006050367 Advises that do power supply sys has been reviewed to verify that impact of failure on ECCS performance is no more limiting than previously analyzed active failures COUNSIL-W C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/27 3pp
- BOOA090286 Responds to NRC BO0507 request for info re undervoltage protection First Level 2 undervoltage scheme electrically connected to 3451V side of preferred offsite supply Relays physically located in control room COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/05/30 2pp
- 5005110163 Forwards addl info on SEP Topic III-6, "Beismic Review," consisting of engineering data or drawings of feedwater line inside containment diesel oil 2 air lines, isolation condensor condensate line 8 shutdown cooling line COUNSIL.4 © Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/30 14pp
- SOOAllOOB: Forwards aperture cards of piging & instrumentation diagrams for cleam-up & sampling sys W/o encl COUNSIL.P O. FEL-W F Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/OS/O2 Ip
- 8006:10226 Forwards addl info re environ qualification of electrical equipment info does not fully respond to NRC request Analytical efforts are in progress at OE to substantiate adequacy of FEAR sec condition profiles in dryuell COUNSIL.W G Northeast Utilities 60/06/02 300pp
- 6006160045 Provides descriptive info & design assessment of proposed low level radwaste storage facility onsite No NRC review required Facility will be operational late 1980 COUNSILLY 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/02 9pp
- BOO6180557 Advises that reorganization of Qfc of Nuclear Reactor Regulation became effective on 800428 Project manager J Shea will coordinate licensing activities for facility Reorganization described in encl CRUTCHFIELD
- 8006240598 Forwards Amenda 68 & 59 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability CLARK,R A Decreting Reactors Branch 3 80/06/03 4pp
- ---8006240604 Amends 68 & 59 to Litenses DPR-2; & BPR-65, respectively, deleting Sections 4 1 & 4 2 from ETS CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D C Operating Reactors Branch 5 80/06/03 7pp
- --8005240607 Notice of issuance & availability of Amends 68 & 59 to Licenses DPR-21 & DPR-65, respectively CLARK, R A Operating Reactors Branch 3 80/06/03 2pp
- BOO6300604 Ltr to ail BWR licensees forwarding "For Comment" edition of NUREG-0619, "BWR Feedwater Notice & Control Rod Drive Return Line Rottle Cracking " Comments will be evaluated by NRC prior to final implementation 1/o encl EIGENHUT.D G Division of Licensing 80/06/05 22pp
- 8006240165 Notification of 800612 meeting u/utils in Bethesda.MD to discuss interim reliability evaluation program OLSHAN,L N Operating Reactors Branch 1 80/06/09 2pp
- 8006190457 Forwards info re five add1 TMI-2 related requirements applying to operating reactors per 800507 request Integrated assessment of collective impact of all requirements should be conducted CDUNSIL-U O. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL-W G Connecticut Yankee Atomic Power Co 80/06/10 30pp

- 8006300379 Discusses effect of dr power supply failure on ECCS performance Recent info indicates unique transfer switch controlling power supply to isolation condenser valve IC-3 Mods to transfer switch scheduled for Sept 1980 outage CDUNSIL, I/9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/19 2pp
- 8006270293 Submits responses to NRC questions re containment atmospheric control sys purge valves Sufficient engineering evaluations exist to justify continued purge & inerting operations as needed COUNSIL.H G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80706/20 3pp
- 8006300460 Updates schedule, previously submitted 770518, for implementing Mark I containment long-term program mods COUNSIL.N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80706/20 3pp
- 8006300383 Responds to NRC 800214 ltr re request for SEP references to docketed info Addresses topic number, title & listing of references identified to date List does not reflect eshaustive review of docketed correspondence COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80706/23 14pa
- 4 Inspection reports, IE Bulletins & correspondence
- 8006050519 Forwards IE Insp Repts 50-245/79-21 & 50-336/79-22 on 790804-0901 No noncompliance noted BRUNNER, E J Region J. Philadelphia, Reactor Operations Nuclear Support Branch 79/11/01 2pp
- --B006050524 IE Insp Repts 50-245/79-21 % 50-336/79-22 on 790804-0901 No noncompliance noted Major areas inspected plant tours, physical security, ecam of feedwater piping per IE Bulletin 79-13, fire protection & surveillance testing MCCABE.E C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch SHEDLOSKY.J T Region 1. Philadelphia. Office of the Director 79/10/30 Bpp
- 8004040055 Forwards IE Insp Repts 50-245/80-03 % 50-336/80-02 on 800201-29 No noncompliance nated BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/18 2pp
- ---8006040059 IE Insp Repts 50-245/80-03 ½ 50-336/80-02 on 800201-29 No noncompliance noted Major areas inspected control rooms ½ accessible portions of Unit 1 reactor, turbine, radwaste, gas turbine generator ½ intake bldgs
 EUFDLOSKY, J T, ZIMMERMAN, R P. Region 1, Philadelphia, Office of the Director KEIMIG, R R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/16 10pp
- B006090191 Forwards IE Investigation Rept 50-293/80-12 on 800305-07 & 19-20. In response to allegations re illegal shipments of spent fuel MARTIN.W 9 Region J. Philadelphia. Safeguards Branch 10/04/18 to
- 8006200085 Forwards 16 Circular 80-08. "BWR Tech Boec Inconsistency -Reactor Protection Sys Response Time " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/18 ip
- 8004030064 Responds to IE Bulletin 80-07 concerning BWR jet pump assemblies Visual insp of all jet pumps performed & no deficiencies or discrepencies discovered Individual jet pump differential pressure readings reviewed COUNSIL,N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/29 3pp
- 8006250152 Forwards IE Insp Repts 50-245/80-04 & 50-336/80-03 on 800301-29 No noncompliance noted BRUNNERE J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/62 2pp
- ----B006250157 IE Insp Repts 50-245/80-04 & 50-336/80-03 on 800301-29 No noncompliance noted Major areas inspected plant operations, logs & records, previous insp findings, radioactive matl shipments, maint & IE bulletins & circulars KEIMIO.R Region I, Philadelphia, Reactor Operations Nuclear Bupport Dranch BHEDLGRY, J T, ZIMMERMAN, R P Region 1, Philadelphia, Office of the Director B0/05/01 13pp
- BO06090011 Act receipt of B00501 ltr informing NRC of status of feeGwater sparger supplied to Millstone 1 & noted in QA Program Insp Rept 99700403/77-03
 SEYFRIT.K V Region 4. Dallas. Office of the Director 60/05/12

- --B006090016 Follows up 800128 itr.advising that util owners have requested vendor to upgrade feedwater sparger fabricated by Marvin Engineering for Hillstone New sparger cannot be fabricated in limited time before Fall 1980 commitment BARNARD. J General Electric Co 80/05/01 2pp
- 8006240611 Ack receipt of 800508 ltr informing NRC of incorrect statements made in IE insp Rept 50-293/80-12 Corrected pages encl W/o encl MARTIN.4 0 Region i, Philadelphia, Safeguards Branch 80/05/22
- --8006240617 Responds to NRC 800418 ltr Northeast Nuclear Energy Co incorrectly identified as util licensed to operate Haddam Neck Plant COUNSIL,W G , SWITZER,D C Northeast Nuclear Energy Co (subs of Mortheast Utilities) 80/05/08 2pp
- 8006300226 Forwards Mgt Meeting Rept 50-245/80-05 on 800313 CARLSON,R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/23 1p
- ---9006300236 Mgt Meeting Rept 50-245/80-05 on 800313 Major areas discussed findings of investigation of allegations re 791219 waterhammer event & licensee activites in sys mods & repeir GARLSON, R T , TRIPP.L E Region 1. Philadelphia, Reactor Construction & Engineering Support Branch CHAUDHARY, S K Region 1. Philadelphia, Office of the Director 80/05/22 3pp
- 8006200491 Updated rept re recirculation pump inservice insp Requests postponement of requirements of lable IMD-2500 because of time required for obtaining parts, tools & planning for refueling outage
 COUNSILM 0 . COUNSILM 0 . Northeast Utilities 80/06/10 2pp
- R Periodic operating reports & related correspondence
- 8006170438 Forwards monthly operating rept for May 1980 MRGCZKA,E J Northeast Utilities 80/06/09 1p
- --8006170440 Monthly operating rept for May 1980 HARRAN 9 Northeast Utilities 80/06/09 6pp
- S Reportable occurrences, LERs & related correspondence
- 8006180609 PNO-1-80-087 on 800530; two failed flexible couplings on turbine drain extraction steam line caused unscheduled extended outage Debris from bellows damaged at least three other lines & some internal baffles in condensor XELMIG,R, BRUNNER,E, J. Region 1, Philadelphia, Office of the Director 80/06/02 1p
- 8006240387 Forwards LER 80-007/03L-0 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/13 1p
- --8006240373 LER 80-007/03L-0 on 800516 discovered that semiannual functional test of cable vault smoke detection sys had been overlooked Caused by test not being listed on unit surveillance schedule Verification of schedules performed * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/13 3pp,

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- BOOGO704B7 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D Q Division of Licensing 80/05/19 46pp
- BO06130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC B00517 ltr.Page 14a not encl EISENHUT.D O Division of Licensing B0/05/22 73pp
- BOOGOGORO Advises NRC of recent developments re emergency preparedness at facilities Utils are revising emergency plans in accordance w/NUREO-0634, retaining EDS Nuclear, Inc to assist State of NY & Westchester County in revising plans CAHILL, H J Consolidated Edison Co of New York EARLY, P J. Power Authority of the State of New York 80/06/03 SPP

- 8006180526 Forwards design details for oil collection sys to be installed on reactor coolant pumps, per fire protection safety evaluation requirements CAHILL, W J Consolidated Edison Co of New York 80/06/06 6pp
- G Adjudicatory correspondence
- 8006060523 Order stating four-pronged approach to resolve UCB petition for Unit 1 decommissioning & Units 2-3 shutdown adjudication before ASLB, informal proceeding to determine issues, generic consideration & establishment of intra-agency task force CHILK, S. J. Office of the Secretary of the Commission 80/05/30 Bpp
- 8006190310 Responds to 800909 objection to scheduling meetings outside Washington, DC area Meetings are occasionally held outside of Washington, DC vicinity to allow persons living near plants opportunity to attend EIGENHUT, D G Division of Licensing 80/06/02 2pp
- 8006090297 Notice of withdrawal from proceeding, effective 800602 Certificate of Svc encl LEMIS, S H Hearing Blanch 2 80/06/06 4pp
- 8006190547 Dreer granting extension until 800707 for Commission to elect whether to review ALAB-436 & portions of ALAB-561 CHILK.S J Office of the Secretary of the Commission 80/06/16
- 8006240483 Comments on Commission 800530 order re-safe operation & criteria of operation CP & OL established criteria should apply & burden of proof must remain on licensee Specific design changes must be feasible WEISS, ER, JORDAN, WS Union of Concerned Scientists MEISS, ER Sheldon, Harmon & Weiss 80/06/20 9pp
- 800626021R Memorandum in response to Commission 800530 order initiating informal proceeding Urges development of industry-wide policy, guidance & stds prior to consideration of units separately in adjudicatory hearings
 BRANDENBURG.B Consolidated Edison Co of New York PRATT.C M
 Power Authority of the State of New York 80/06/20 23pp
- BO06260186 Forwards UCS BO0623 motion to disqualify Commissioner Hendrie HEIBS.E R , JORDAN.W S Sheldon, Harmon & Weiss BO/06/23 ip
- ---B00626018B Motion to disqualify Commissioner Hendrie from further participation in NRC deliberations re UCS petition for suspension of operations Request is based on Hendrie involvement w/facility as member of ACRS
 WEISS, E. R. JORDAN, W. S. Union of Concerned Scientists WEISS, E. R. Sheldon, Harmon & Weiss 80/06/23 10pp
- --8004240190 Notifies that during ACRS 125th meeting on 700917-19, review of util OL application was completed Upon satisfactory completion of const. facility can operate w/o undue risk to public JM Hendrie prof qualifications encl HEMDRIE, J H ACRS Advisory Committee on Reactor Safeguards 70/09/23 10pp
- --8006260192 Responds to 730717 ltr re util siting criteria Indian Point sites meet NRC regulations & criteria Considerable energy has been expended to assure public health & safety HENRIE.J M. Atomic Energy Commission. Directorate of Licensing 73/09/10 Jpp
- H General correspondence
- BOOA020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas MAMM.K. Affiliation Unknown BO/03/19 ip
- 8005020027 Responds to 800319 ltr re location of nuclear power plants in areas of high population density Every effort is being made to protect public health & safety at all nuclear power plants
 DENTON. H R Office of Nuclear Reactor Regulation, Director 80/04/21 2pp
- 8004190434 Comments on 800530 order re shutdown of plants pending adequate emergency plans No plant can operate unless acceptable emergency plans exist Emergy & economic factors should have minimal influence on decision to shut down. MOLF.B Affiliation Unknown 80/06/11 3pp

- P Operating license stage documents & correspondence
- 8006070165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI-Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D 0 Division of Licensing 80/05/07 150pp
- 8006040002 Notification of 800520 meeting u/utils, contractors & consultants in Bethesda. KD to exchange technology reactions to sequence & related phenomena per A Schwencer 800410 tr to L Peoples LQNG. J K Reactor Systems Branch 80/05/15 2pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT,D G Division of Licensing 80/05/19 72pp.
- 8006170836 Forwards request for add1 info required to complete review of non-Class I seismic equipment resulting in flooding of safety-related equipment Requests response within 45 days VARGA.S A Operating Reactors Branch 1 80/05/20 8pp
- 8006020172 Notification of 800530 meeting w/utils in Bethesda, MD reservers accident mitigation features for facilities OLSHAN, L. REEVES, E. Operating Reactors Branch 1 80/05/23 1p
- 8006130208 Forwards Amend 61 to License DFR-26, safety evaluation & notice of issuance & availability
 VAROA.S A Operating Reactors Branch 1 80/05/23 2pp
- --8006130214 Amend 61 to License DPR-26, increasing staffing of station nuclear safety committee & incorporating STB provisions allowing crew composition below min requirements for 2-h period VAROALS A Operating Reactors Branch 1 80/05/23 6pp
- --8006130220 Safety evaluation supporting Amend 61 to License DPR-26 * Office of Nuclear Reactor Regulation, Director 80/05/23 2pp
- ---8006130223 Notice of issuance & availability of Amend 61 to License DPR-26 VARQALS A Operating Reactors Branch 1 80/05/23 2pp
- 8006200174 Forwards request for add1 info concerning GA program which supplements 800408 ltr Response should be provided within 30 days of ltr VAROA.8 A Operating Reactors Branch 1 80/05/23 5pp
- 8006230029 Requests 800604 meeting w/util personnel to discuss Interim Reliability Evaluation Program (IREP) & potential impact on facility EISENHUT, D G Division of Licensing 80/05/23 Spp
- 8006090493 Notification of 800603 meeting w/vtil in Bethesda.MD to discuss filtered vented containment sys & core retention devices MEYER.J F Reactor Systems Branch 80/05/27 3pp
- B006110091 Forwards drawings & add1 info re electrical override/bypass aspects of containment purge sys.in response to NRC B00423 ltr Remainder of response will be provided by B00715 brawings available in Central Files only CAHILL.W J Consolidated Edison Co of New York B0/05/28 lipp
- 8006120404 Forwards slides used by utils during 800603 meeting retechnology exchange in area of mitigation feature for severe accidents at facilities COEBER.D Hestinghouse Electric Corp 80/06/05 ip
- 8006170451 Forwards "Mitigation of Severe Accident Study Rept" Rept includes presentations made to NRC & ACRS on 800220 & 0305, respectively & consists of state-of-the-art analyses conducted within 60-day period CAHILL-W J Consolidated Edison Co of New York EARLY.P J Power Authority of the State of New York 80/06/05 2pp
- --8006170454 Informs that Section 6 of rept submitted on 900605 was inadvertently stamped proprietary Class 2 Rept is nonproprietary.

 CAMILLY J Consolidated Edison Co of New York EARLY, P J Power Authority of the State of New York 80/06/06 1p
- --8006170459 Responds to 800528 ltr transmitting rept covering work performed by various consultants Entire Westinghouse rept nonproprietary.
 PEUPLES D L Commonwealth Edison Co 80/06/99 3pp

- --8006170466 "Mitigation of Severe Accident Study Rept," consisting of repts re evaluation of residual risk, steam explosions, containment response for Class 9 accidents & post-accident containment vent sys conceptual designs

 * Westinghouse Electric Corp 80/03/31 400pp
- 8006240165 Notification of 800612 meeting w/utils in Bethesda.MD to discuss interim reliability evaluation program DLSHAN.L N Operating Reactors Branch 1 80/06/09 2pp
- 8006130294 Forwards summary of actions taken to comply w/NRC 800211 Confirmatory Order re verification of sump recirculation be review of administrative check by verification procedures for single failure point valves
 O'TOOLE, J D Consolidated Edison Co of New York 80/06/10 Spp
- 800616010B Forwards Con Ed 800505 ½ Power Authority of State of NY B00507 ltrs to DOE re economic effects of extended shutdown for consideration by NRC task force CAHILLN J Comsolidated Edison Co of New York EARLY,P J Power Authority of the State of New York 80/06/10 15pp
- BOO6180434 Forwards response to five add1 TMI-2-related requirements per 800507 request Response re implementation of Item 1, shift manning, will be sent as expeditously as possible after receipt of NRC guidance CAHILL.W J Consolidated Edison Co of New York 80/06/12 Bpp
- 8006270047 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda.HD re accident mitigation features for facilities LONG.J K Reactor Systems Branch 80/06/12 27pp
- BOO6250280 Notification of SOO618 meeting w/utils.contractors & consultants in Bethesda.MD for presentation in area of core-melt accident sequences for racilities Agenda encl MEYER.J F Reactor Systems Branch BO/O6/16 2pp
- 8006200583 Notification of 800617 meeting w/utils & consultants in Bethesda.MD to discuss technology exchange re containment structural response failure pressures & failure modes MEYER,J F Reactor Systems Branch 80/06/17 2pp
- 8006240349 Forwards request for Amend 2 to application for amend to OL No add1 fee required CAHILL.W J Consolidated Edison Co of New York 80/06/23 2pp
- --B006240350 Request for Amené 2 to application for amend to OL, modifying previous applications to reflect addl support sys redesign CAHILL, N. J. Consolidated Edison Co. of New York 80/06/19 3pp
- --8006240352 Proposed revised Tech Spec pages for Table 3 12-1 re safetyrelated shock suppressors « Consolidated Edison Co of New York 80/06/23 App
- --B006240354 Bafety evaluation supporting Amend 2 to application for amend to GL * Consolidated Edison Co or New York 80/06/30 3pp
- BOO6240361 Forwards application for amend to License DPR-26.deleting certain fire protection safety evaluation requirements 5 modifying Tech Specs re limiting conditions for operation 5 surveillance CAMILL.W J Consolidated Edison Co of New York 60/06/23 2pp
- --8006240364 Application to amend License DPR-26 deleting certain fire protection safety evaluation requirements & modifying Tech Specs to incorporate limiting conditions for operation & surveillance requirements for addl fire detectors CAHILL, 4 J Consolidated Edison Co of New York 80/06/19 App
- --8006240367 Revised Tech Spacs incorporating limiting conditions for operation & surveillance requirements for add1 fire detectors hose stations & water supply capability Safety evaluation encl

 * Consolidated Edison Co of New York 80/06/30 18pp
- 8006250259 Affidavit certifying svc of application for amend of QL & Amend 2 to application for amend to QL on 800619
 LIBERATORILE F Consolidated Edison Co of New York 80/06/23 1
- Q Inspection reports, IE Bulletins & correspondence
- 8006170790 Forwards Haste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH-0 H Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp

- --8006170796 Waste Packaging Insp Rept 80-03 on 800227-29 No 106170796 Waste Mackaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements, DOT placarding requirements, radiation levels, removable contamination & prohibited articles or contents PEERRY.W M. POTTER.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 8006170387 Forwards IE Insp Rept 50-247/79-25 on 791209-800202 No honcompliance noted BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/20 2pp Support Branch
- --8006170391 IE Insp Rept 50-247/79-25 on 791209-800202 Noncompliance w/DDT regulations noted defective shipping container gasket resulted in leakage & contamination of exterior of shipping cask
 BAUNACK,W , SERABIAN,J Region i, Philadelphia, Office of the
 Director KISTER,H Region i, Philadelphia, Reactor Operations
 Nuclear Support Branch 80/04/24 10pp
- 8006060521 Forwards response to IE Builetin 80-04 Steamline break case w/failure of auxiliary feedwater runout protection sys would not result in containment overpressurization CAHILL,W J Consolidated Edison Co of New York 80/05/08 7pp
- 8006200044 Forwards IE Circulat 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p

R Periodic operating reports & related correspondence

- 8006170431 Forwards data specified in Bection 401 Certification for May 1980 to NY State Dept of Environ Conservation MONTI.W A Consolidated Edison Co of New York 80/06/10 ip
- --9006170434 Circulating water temp,gross electrical output & river water discharge info for May 1980 * Consolidated Edison Co of New York 80/06/10 16pg
- BOO6180529 Forwards "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point.NY Consolidated Edison Project. Dec 1979-Feb 1980 " CAHILL.N J Consolidated Edison Co of New York BO/06/13 ip
- --8006180536 "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project, Dec 1979-Feb 1980 "
 - Woodward-Clude Consultants, Inc. 80/05/12 46pp
- 8006180426 Forwards daily fish counts from intake screens for May 1980 CAHILL,W J Consolidated Edison Co of New York 80/06/15 Ig
- 8006190626 Forwards monthly operating rept for May 1980 CAHILL.W J Consolidated Edison Go of New York 80 80/06/15 1p
- ---8006190630 Monthly operating rept for May 1980 EICH.E Consolidated Edison Co of New York 80/06/06 2nn

8 Reportable occurrences, LERs & related correspondence

- EODÁO50474 PNS-1-80-011 on BOO519, four separate telcon bomb threats were received Two calls received by Peakskill Evening Btar & two by Supervisor's Ofc. Town of Peekskill, NY Bomb search procedures initiated at both plants
 DEVLIN, J. MARTIN.W Region 1. Philadelphia, Office of the Director BO/05/20 1p
- 8006240217 PNS-I-80-014 on 800603. Evening Star of Buchanon NY received phone call from unidentified male, stating that Status of Liberty bombed & facility would be next Search of facilities reported no evidence of bomb JONES, E W., MARTIN, W. Region 1. Philadelphia, Office of the Director 80/06/04 ip
- 8006240272 PNB-1-80-015 on 800604, Daily News, NY City newspaper, received phone call from unidentified male admitting membership in FALN who said factlity would be bombed next Bomb searches initiated w/negative results
 JUNES, E. W., MARTIN, W. Region 1, Philadelphia, Office of the Director 80/06/04 ip
- 9006160063 Forwards LFR 80-004/03L-0 Consolidated Edison Co of New York 80/06/11, 1p ZARAKAS, P

- --8004160068 LER 80-004/03L-0 on 800512 during normal operation. leak JUGICUOSE LER SU-004/0312-0 ON BUOGLE OUTING NORMAL OPERSION, IN discovered at socket weld connection on seal injection header.Line 402 downstream of filters Caused by leak in sucket weld associated w/2-inch, 90 degree elbaw MAKEPEACE.J M Consolidated Edison Co of New York 80/06/11
- 8006190535 Forwards LER 80-006/99T-0 CAMILL, W J Consolidated Edison Co of New York 80/06/17 1p
- --B006190541 LER 80-006/97T-0 on 800603 during normal plant operation all offsite electrical power was lost Caused by lightning strike Feeders cleared of faulted condition MAKEPEACE.JM Consolidated Edison Co of New York 80/06/17

T Hearing transcripts on non-antitrust matters

- 8006180125 Transcript of 800830 Affirmation Session 80-06 in Washington.DC Pp 1-2

 * Commission 80/05/30 3pp
- --8006180132 Recommends approval of encl revised draft order Encl PA Bradford separate statement to be appended to order BICKMIT.L. Office of the General Counsel SECY-80-182E 80/05/29 9pp
- --B0061B013B Responds to 800324 ltr to J Ahearne re problems of evacuating large populations in short period of time Program of upgrading emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant DENTON.H R DEfice of Nuclear Reactor Regulation. Director 80/04/29 2pp
- NO.180147 Bladorates on Concerns expressed in Subject for February Practical evacuation plans around nuclear power sites Problems of evacuating large populations in short time have been underestimated Requests open hearings on issues WDLF.B Affillation Unknown BO/O3/24 2pp
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 800&020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to lint all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J G Region 3, Chicago. Office of the Director BO/04/18
- 8004040131 Forwards comments re 790818 submittal of training & qualification plan Response requested within 30 days Comments withheld (ref 10CFR2 790)
 CRUTCHFIELD,D Operating Reactors Branch 5 80/05/09, 2pp
- 8006120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/05/13 2pp
- 8006070487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 % App R to 100FR50 % is expected to be published in FR by end of May EIBENHUT.D 0 Division of Licensing 80/05/19 44pp.
- 8004130043 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 itr Page 14a not encl EISENHUT, D & Division of Licensing 80/05/22 73pp
- B006200627 Requests revision of B00324 safeguards contingency plan in accordance w/comments described in encl to 1tr Response requested within 30 days Encl withheld (ref 10CFR2.790) CRUTCHFIELD.D M Operating Reactors Branch 5. 80/09/27 2pp
- 8006050276 Informs that licensee submitted add1 info on 800408 refire protection review Evaluation entire Item 3 1 5.water suppression, HALL, R E Brookhaven National Laboratory 80/04/02 2pp.
- 8006180793 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES, D.L. Commonwealth Edison Co. 80/04/04 2pp

- --8006180331 braft emergency plan annex * Commonwealth Edison Co 80/07/31 520s
- --\$006180347 Revision 1 to draft emergency plan * Commonwealth Edison Co 80/07/31 139pp
- 8006180031 Provides info re access of NRC & NRC contractor personnel to facilities to conduct appraisal of health physics program Onsite phase is scheduled for approx 2 wks teginning 800619 List of authorized NRC personnel encl KEPPLER. J G Region 3, Chicago. Office of the Director 80/06/05 4pp
- B006240316 Forwards. "Diesden Nuclear Power Station 800619 Emergency Response Plan Exercise," to verify Comm Ed emergency plan PEDPLES.D L. Commonwealth Edison Co. 80/06/18 2pp
- --8006240318 "Dresden Nuclear Power Station 800619 Emergency Response Plan Exercise " • Commonwealth Edison Co 80/06/19 63pp
- 8005240490 Responds to NRC 800425.30.0501.09 & 20 ltrs requesting add1 info re guard training & qualification plans Requests that response submittal date be extended to 800804 PEOPLES.B t. Commonwealth Edison Co 80/06/18 ip
- P Operating license stage documents & correspondence
- 800&090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D G Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES, C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006:30122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D O Division of Licensing 80/05/19 72pp
- 8006030062 Application to amend Licenses DPR-2,DPR-19.DPR-25,DPR-29 & DPR-30.clarifying term "operable." submitted as Tech Spec change request, in response to NRC 800410 ltr NAUGHTON,W F Commonwealth Edison Co 80/05/30 2pp
- ---8006030072 Tech Spec change request for Tech Specs Sections 1 0-1 2,2 1 & 2 2,3 0,5 0 & 6 0-6 å re definitions administrative controls, safety limits, limiting safety sys setting & limiting conditions for operation 9 Commonwealth Edison Co 80/05/30 42pp
- B006300604 Ltr to all BWR licenses forwarding "For Comment" edition of NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking ' Comments will be evaluated by NRC prior to final implementation W/o encl #EISENHUT.D G Division of Licensing #B0/06/05 22pp
- 8006190456 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 790808 request JANECEK.R F Commonwealth Edison Co 80/06/11 3pp
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltr re add1 TMI-2 related requirements Bresden Unit 1 is currently undergoing extensive mod & decontaction, therefore no response is provided PEOPLES.D L. Communuealth Edison Co 80/06/12 10pp
- 8006190419 Confirms availability of ECCS equipment following &c power supply failure, per 800425 request Mods to ensure availability of MPCI following &c power failure completed at Dresden & in progress at Quad Cities

 JANECEK.R F Commonwealth Edison Co 80/06/12 2pp
- B006230196 Forwards draft NEDC-24236; "Evaluation of Jet Pump Hold-Down Beam Fallure at Dresden Unit 3 " Rept withheld (ref 10CFR2 790) JANECEK.R F Commonwealth Edison Co 80/06/19 tp
- 8005250277 Forwards response to NRC 800516 ltr requesting info re turbine disc cracking Stress corrosion cracks not observed to data. JANECEK.R F Commonwealth Edison Co 80/06/23 16pp

- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1~7 of CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations" Revised Revision 11 includes basis on which equivalent education requirements will be established PEOPLES D L Commonwealth Edison Co 80/06/23 1p
- G Inspection reports. IE Bulletins & correspondence
- 8006200110 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/04/18
- 8006170308 Forwards IE Insp Repts 50-010/80-07.50-237/80-07 & 50-249/80-10 on 800303-0404 & notice of violation HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --8006170312 Notice of violation from insp on 800303-0404 * Region 3. Chicago, Office of the Director 80/04/22 ip
- --8004170320 IE Insp Repts 50-010/80-07.50-237/80-07 & 50-249/80-10 on 800303-0404 Noncompliance noted failure to follow radiation protection procedures BARKER. J. L. TONGUE, T. M. SPESSARD.R. L. Region 3, Chicago, Office of the Director 80/04/22 5pp
- 8006020070 Forwards IE Insp Rept 50-249/80-09 on 800410-11 No noncompliance noted FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006020077 IE Insp Rept 50-249/80-08 on 800410-11 No noncompliance noted Major areas inspected reactor water cleanup sys,pipe damage from water hammer & control rod drive sys seismic restraints

 DANIELSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branck YIM, I T Region 3, Chicago, Office of the Director 80/04/23 4pp
- 8006020008 Responds to 1E Builetin 79-26 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated B4C leaching Control blade exposures will be monitored during cycles to verify projected and-of-cycle exposure PEOPLES.D L Commonwealth Edison Co 80/05/19 2pp
- 8006300558 Forwards response to 1E Bulletin 80-06. "Engineered Bafety Feature (ESF) Reset Controls " Proposed mods (dentified only if present sys design may compromise protective action of equipment PEOPLES,D t. Commonwealth Edison Co 80/06/10 9pp
- R Periodic operating reports & related correspondence
- BOO6110100 Forwards monthly operating repts for Apr 1980 STEPHENSON, B B Commonwealth Edison Co 80/05/12 1p
- --8006110102 Monthly operating repts for Apr 1980 CIESZKIEWICZ.S Commonwealth Edison Co 80/05/05 28pp
- BOO6170448 Forwards monthly operating repts for May 1980 STEPHENSON, B B Commonwealth Edison Co 80/06/09 1p
- --8006170461 Monthly operating rept for May 1980 CIESZKIEHICZ.S Commonwealth Edison Co 80/06/02 8pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006040203 Forwards LER 80-022/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/05/27 1p
- --8004040208 LER 80-022/03L-0 on 800429 during normal shutdown conditions intermediate range monitor 12 downscale rod block was found to trip below Tech Specs Caused by electronic drift Trip point immediately readjusted HOLLAND, P Commonwealth Edison Co 80/05/28 ip
- 8006160121 Forwards updated LER 80-002/03X-1 STEPHENSON, B B Commonwealth Edison Co., 80/06/03 1p
- ---B006160125 Updated LER B0-002/03X-1 on 800122, during normal operation, while performing LPCI monthly surveillance, MO-3-1501-i1B valve would not close Caused by stripped screw on one of main line terminals Screw replaced & breaker overhauled ZIRWAS, K R Commonwealth Edison Co 80/06/03 ip

- 8006230381 Forwards LER 80-025/03L-0 STEPHENSON, R. B. Commonwealth Edison Co. 80/06/10 In
- --8006230387 LER 80-025/03L-O on 800521.during main steam line high flow isolation surveillance.flow switch DPIS 3-261-2A was out of Tech Spec limits No apparent cause Switch successfully retested Tests will continue on monthly basis SPEROFF.R Commonwealth Edison Co 80/06/11 1p
- 8006230559 Forwards LER 80-024/03L-0 STEPHENSON, B 0 Commonwealth Edison Co 80/06/13 1p
- --8006230565 LER 80-024/03L-0 on 800519, during normal operation w/reactor level instrument surveillance in progress, level switch LIS 3-263-988 tripped below Tech Spec limit Cause unknown Instrument immediately retested w/satisfactory results HOLLAND.P Commonwealth Edison Co 80/06/16 ip
- 8006230570 Forwards LER 80-023/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/04/13 10
- --8004230577 LER 80-023/03L-0 on 800519, during normal operation w/reactor lavel instrument surveillance in progress, level switch LIS 3-243-58A tripped below Tech Spec limit Caused by misaligned Yarway switch assembly, Model 4418C, Series 4418O HOLLAND.P Commonwealth Edison Co 80/06/12 lp
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D G Division of Licensing 80/05/19 46pp
- BOOG130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EIBENHUT, D O Division of Licensing 80/05/22 73pp
- BOO6110217 Notifies that revised emergency plan will be submitted by BOO615, in response to NRC BOO418 ltr
 UMRIGRE Florida Power & Light Co BO/06/06 lp
- BOOG130254 Forwards safe shutdown evaluations for auxiliary bldg hallway & cable spreading room in response to NRC 791029 request for fire protection info Reactivity control sys assures safe subcribical core conditions after reactor trip UHRIG.R E Florida Power & Light Co 80/06/07 Ripp
- 8006260056 Notification of 800619 meeting w/util in Bethesde,MD to discuss fire protection program & implementation of App R GROTENHUIS.M Operating Reactors Branch 1 80/06/09 2pp
- BOO6240192 Forwards proposed revision to emergency plan Apps to be submitted under separate cover Implementation to begin by BIO101.depending on resource availability & final resolution of open issues Plan withheld (ref Privacy Act) UHRIG:R E Florida Power & Light Co 80/06/19 lp
- GOO6240176 Advises that util has re-evaluated Section 3 1 12 of NRC 790321 fire protection SER, Sprinkler heads on outside wall of diesel generator bidg offer better means to reduce potential diesel generator sys demage UHRIO,R E Florida Power & Light Co 80/06/20 lp ,
- G Adjudicatory correspondence
- 8006260202 Requests that NRC advise Board members of projected dates for issuance of draft & final E[8, to enable parties to discuss scheduling of proceedings re issuance of OL amends Certificate of 8vc encl REIS.H F Lowerstein, Neuman, Reis, Axelrad & Toll 80/06/23 App
- H Ogneral correspondence
- 8004300696 Responds to 800410 ltr re facility EI8 EI8 prepared for all CP & OL applications EIS preparation process discussed OOLDBERG.B C Hearing Branch 2 80/05/08 2pp

- 800609006B Ack receipt of 800402 % 0229 ltrs Discusses criteria used in granting or denying amend requests NUREO-0651, "Evaluation of Steam Generator Tube Rupture Events," enci N/o encl VAROA.S A Operating Reactors Branch 1 80/05/20 2pp
- II Antitrust correspondence
- 8006240137 Notice by Orlando Utils Commission to withdraw intervention & request to institute proceeding re Commission 780727 order City of Orlando.petilsioner & util 800606 settlement resolved issues W/affidavit & Certificate of Svc WISE.W C Orlando.FL WISE.W C Wise, W C 80/06/20 4pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D G Division of Licensing 80/05/07 150pg
- 8006130122 Requests comments on NUREQ~0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Suppo.ts" Proposed review procedure & implementation schedule encl EISENHUT.D G Division of Licensing 80/05/19 72pp
- BOO6030053 Corrects & supplements 800318 ltr re steam generator repair Monitoring repts will be submitted annually by 800331 Improvements designed to enhance secondary water chemistry control being implemented UHRIG.R E Florida Power & Light Co 80/05/27 2pp
- BO06260076 Forwards evaluation of 791220 response to NRC 791016 requirements for auxiliary feedwater sys Requests response to comments on 65-4 & GL-3 & confirmation of conformance w/revision to Recommendation 2 within 45 days VAROA.S A Operating Reactors Branch 1 80/05/30 9pp
- 8006200047 "Proposed Amend to Facility OLs DPR-31 & DPR-41, Delta T vs Reactor Power Shift Check. Turkey Point Units 3 & 4." informal rept UDY: A C E086, Inc FIN A-6256 8006200047 80/05/31 7pp
- 8006060341 Forwards info supplementing response to NRC 770828 ltr re containment purge valves Provisions are adequate to preclude failure of valves to close due to entrained debris in fluid stream UHRIG-R E Fiorida Power & Light Co 80/06/03 App
- 8006060342 Advises of intention to begin repair of Unit 4 steam generators in Oct 1781 & Unit 3 in Oct 1782 Requests that NRC begin preparation of EIB so that ASLB proceedings re amend to OL can be completed UHRIO.R E Florida Power & Light Co 80/06/03 Ip
- BOOGOTO390 Application to amend App A of Licenses DPR-31 & DPR-41, changing Tech Specs, Pages 3 2-2 & 3 2-4, to reflect results of revised ECCS analysis of power distribution limits for 25% steam generator tube piugging Revised Tech Specs encl. UHRIG.R & Florida Power & Light Co BO/06/05 2pp
- --B006070393 Revised Tech Specs.Pages 3 2-3 & 3 2-4 for amend to App A of Licenses DPR-31 & DPR-41 Reflects results of revised EGGS analysis on power distribution limits for 25% steam generator tube plugging # Florida Power & Light Co 80/06/05 3pp
- ---8004070397 "ECCS Analysis, 25% Steam Generator Tube Plugging " SCHMIDT, A D Florida Power & Light Co 80/04/05. 31pp
- 8006110093 Forwards util 800527 ltr to NRC re proposed amends to OL permitting steam generator repairs, Corrects & supplements 800318 ltr to NRC COLL.N A 8teel, Hector & Davis 80/05/05 4pp
- --8006i10099 Corrects & supplements 8003i8 ltr to NRC re proposed amends to OL permitting steam generator repairs Util has approved various plant improvements, including installation of condensate polishing demineralizers

 UHRIG.R E Florida Power & Light Co 80/05/27 2pp
- 8006200479 Forwards info re add1 TMI-related requirements per 800507 ltr. Includes shift manning, revising scope & criteria of licensing exams, procedures for feedback of operating experience to plant staff & PMR vendor rept UHRIO.R.E Florida Power & Light Co 80/06/13 3pp

- 8004240261 Requests extension until 800801 to incorporate NRC proposed changes into Tech Specs as discussed in L-80-157 ltr Effect of shared sys will need to be investigated & specs will need to be reviewed to determine applicability of STS 3 0 3 & 5 UHRIG.R E Florida Power & Light Co 80/06/18 ip
- 8006300227 Requests that any info re plants or animals in site vicinity, listed or proposed to be listed as endangered species-be provided for preparation of EIS per amend review VAROA.5 A Operating Reactors Branch 1 80/06/19 2pp
- O Inspection reports. IE Bulletins & correspondence
- B006090470 Forwards IE Insp Repts 50-250/80-14 & 50-251/80-12 on 800410 & 11 Mo noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --B006090473 IE Insp Repts 50-250/80-14 & 50-251/80-12 on 800410 & 11 No noncompliance noted Major areas inspected const status & action on previous insp findings
 RAUSCH, J K Region 2, Atlanta, Reactor Construction & Engineering Support Branch WILCOX, J D , MCFARLAND, C R Region 2, Atlanta, Office of the Director 80/04/30 3pp
- 8008050569 Forwards IE Bulletin 80-11, "Masonry Hall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8006050286 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys
 Operability " Requires action & response within 30 days
 IE Info Notice 80-20. 'Loss of Decay Heat Removal Capability
 at Dayis-Besse Unit 1 While in Refueling Mode" encl
 D'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/09
- 8006300107 Forwards IE Circulat 80-ii. "Emergency Biesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 2pp
- 8006040013 Ack receipt of 800118,0321 & 0501 ltrs informing NRC of steps taken to correct violations nated in IE Insp Repts 50-250/79-35,50-251/79-35,50-355/79-33 & 50-389/79-22 MURPKY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Brench 80/05/19 lp
- --8006040021 Responds to NRC 791219 ltr re violations noted in IE Insp Repts S0-250/79-35.50-251/79-35.50-335/79-33 & 50-389/79-22 Corrective actions OA procedures will be revised w/full compliance achieved by 800/33 UHRIO.R E Florida Power & Light Co 80/05/01 ip
- --8006040025 Responds to NRC 791219 & 800220 ltrs re violations noted in IE Insp Repts 50-250/79-35.50-251/79-35, 50-335/79-33 & 50-389/79-22 Corrective actions OA procedures will be revised re implementation of 100FR2! UHRIO.R E Florida Power & Light Co 80/03/21 3pp
- 8005170165 Ack receipt of 800519 ltr informing NRC of steps taken to correct violations noted in RE Insp Repts 50-250/80-08 & 50-251/80-08 STOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/05/29 1p
- ~-8006170171 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-250/80-08 & 50-251/80-08 Corrective actions personnal counseled in correct procedural compliance Notation made on califor tickler card UHRIG.R E Florida Power & Light Co 80/05/19 2pp
- --8006170176 Forwards IE Insp Repts 50-250/80-08 & 50-251/80-08 on 800325-28 & notice of violation STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/24 3pp
- ~-8006170180 Notice of violation from into on 800325-28 * Region 2. Atlanta. Office of the Director 80/04/23 ip
- ~-8006170185 IE Insp Repts 50-250/80-08 & 50-251/80-08 on 800325-28 Noncompliance noted failure to have & follow written procedures for radiochemistry counting equipment MONTOMERY.D M Region 2: Atlanta, Office of the Director TROUP.O Region 2: Atlanta, Fuel Facility & Materials Safety Branch 80/04/23 9pp

- BOOA180017 Ack receipt of BOO507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-10 & 50-251/80-10 | FMIS. R. C. Repton 2. Atlanta, Reactor Construction & Engineering
 - Support Branch 80/05/30 ip
- --9006180021 Responds to NRC 800414 ltr re violations noted in IE Insp Repts 50-250/80-10 & 50-251/80-10 Corrective actions preventative maint to be performed on tritical portions of plant communications sys UHRIG.R E Florida Power & Light Co 80/05/09 4pp
- --8006180024 Confirms.per conversation w/R Vogt-Lowell, that response to IE Insp Repts 50-250/80-10 % 50-251/80-10 will be submitted by 800509
 UHR16.R E Florida Power & Light Co 80/05/07 ip
- --8006180028 Forwards 1E Insp Repts 50-280/80-10 & 50-251/80-10 on 800201-29 & notices of violation & deviation LEWIS.R C Region 2, Atlanta, Reactor Construction & Engineering Support Breach 80/04/14 ip
- --8006180032 Notice of violation from insp on 800201-29 * Region 2, Atlanta, Office of the Director 80/04/02 ip
- --8006180033 Notice of deviation from insp on 800201-29
 * Region 2, Atlanta, Office of the Director 80/04/02 1p
- --8006180036 IE Insp Repts 50-250/80-10 & S0-251/80-10 on 800201-29 Noncompliance noted failure to generate final approved maint procedures for auxiliary feedwater VOGT-LOWELL,R Region 2. Atlanta, Office of the Director MARTIN:R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 App
- 8006260127 Submits supplemental response to IE Bulletin 79-25, "failures of Westinghouse BFD Relays in Safety-Related Sys "Relays are tested monthly by licensed operations personnel Relay failures, maint & testing are documented UHRIG, R E Florida Power & Light Co 80/05/30 1p
- B006190646 Forwards response to IE Builetin 79-018. "Environ Qualification of Class IE Equipment " W/o encl UHRIG.R E Florida Power & Light Co B0/06/02 ip
- 8006200212 Ack receipt of 800521 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 50-250/80-15 & 50-251/80-13 LENIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/04 ip
- --8005200216 Responds to NRC 800425 ltr re deviation noted in IE Insp Repts 50~250/80-15 % 50~251/80-13 Corrective actions mod initiated to install audible & visual alarm for loss of voltage to fire pump UHRIO.R E Florida Power & Light Co 80/05/21 2pp
- --8006200219 Forwards IE Insp Repts 50-250/80-15 & 50-251/80-13 on 800301-31 & notice of deviation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- --8006200222 Notice of deviation from insp on 800301-31 * Region 2, Atlanta, Office of the Director 80/04/23 ip
- --B006200227 IE Insp Repts 50-250/80-15 t 50-251/80-13 on B00301-31 Noncompliance noted fire pumps inoperable for 17 days due to breaker left open following maint MARTIN:R D Region 1. Philadelphia. Reactor Operations Nuclear Support Branch V007-L0WELL:R J Region 2. Atlanta, Office of the Director B0/04/23 4pp
- B006300021 Forwards response to 1E Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Power restoration to vital ac or do buses is accomplished per established plant operating procedures UHRIG.R E Florida Power & Light Co 80/06/05 2pp
- BOO6230184 Forwards supplemental response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bue During Operation " Each alarm associated w/loss of power to buses is addressed in appropriate annunciator list UMRIG.R E Florida Power & Light Co 80/06/06 2pp
- 8006250304 Responds to IE Bulletin 80-12 Sufficient hardware, redundancy, diversity, reliability & control exist to handle loss of decay heat removel occurrence
 URRIG,RE Florida Power & Light Co 80/06/11 2pp

- 8006300579 Responds to IE Bulletin 80-05 Adequate measures to protect refueling water storage tank against vacuum conditions have been taken No mods required UHR10.R E Florida Power & Light Co 80/06/12 3pp
- R Periodic operating reports & related correspondence
- 8006170467 Forwards monthly operating repts for May 1980 SCHMIDT, A D Florida Power & Light Co 80/06/07 ip
- --8006170471 Monthly operating rept for May 1980 CHILSON, V Y Florida Power & Light Co BO/06/07 5pp
- --8006170474 Monthly operating rept for May 1980 CHILSON, V T Florida Power & Light Co 80/06/07 4pp
- --8006170479 Monthly operating rept for May 1980 CHILSON, V T Florida Power & Light Co 80/06/07 App
- S Reportable occurrences, LERs & related correspondence
- 8006050479 PNG-II-60-013 on 800518 bomb threat was received by Central Dispatch, Metropolitan Bade County Public Safety Dept Licensee conducted search no bomb was found HOMELL, J C. OILLESPIE.F. Region 2. Atlanta, Office of the Director NRC 80/05/19 1p
- 8006110025 Forwards LER 80-007/03L-0 8CHMIDT,A D Florida Power & Light Co 80/05/26 ip
- --8006110033 LER 80-007/03L-0 on 800424 during planning & implementation of surveillance per Tech Spec 4 15 4 a 1. six electrical penetration fire barriers found nonfunctional Caused by incomplete installation Barriers repaired SCHOPPMAN, M A Florida Power & Light Co 80/05/26 2pp
- BO06250028 PND-II-BO-076 on B00527.licensee was informed by Westinghouse that nonconservative error was found in computer inputs used Feb 1979 to calculate heat flux hot channel factor for fuel assemblies ELRDD.8 : QUICK,D Region 2. Atlanta, Office of the Director B0/05/28 ip
- \$006230555 Forwards LER 80-011/01T-0 SCHMIDT, A D Florida Power & Light Co 80/05/10 ip
- --8006230564 LER 80-011/017-0 on 800527.util was notified by NB89 vendor that nonconservative error had been discovered in computer inputs used in Feb 1979 10CFR50 46 App K LOCA analysis Gaused by personnel error SCHOPPMAN.M A Florida Power & Light Co 80/06/10 2pp
- 8006230581 Forwards LER 80-009/03L-0 SCHMIDT, A D Florida Power & Light Co 80/06/10 ip
- --8006230588 LER 80-009/03L-0 on 800911, while performing QP 14004 1, steam generator protection channels periodic test, trip satpoints of bistable B8-3-475 & 488A found nonconservative Caused by instrument drift Sistables reset SCHOPPMAN.M A Florida Power & Light Co 80/06/10 ip
- 8006230579 Forwards LER 80-010/03L-0 BCHMIDT, A D Florida Power & Light Co 80/06/13 ip
- ---8006230586 LER 80-010/03L-0 on 800514 during normal operation, process radiation monitors R-11 % R-12 were out of svc for approx 16-h Caused by failule of air sampling blower due to normal wear Blower replaced & monitor returned to svc BCHOPPMAN.M A Florida Power & Light Co. 80/06/13 1p.
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F Security, medical, emergency & fire protection plans
- 6006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end of May EISENHUT, D @ Division of Licensing 80/05/19, 44pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC BOO519 1tr Page 14s not encl EISENHUT, D & Division of Licensing 80/05/22 73pp

- 8006110217 Notifies that revised emergency plan will be submitted by 800615, in response to NRC 800418 ltr
 UHRIQ,R E Florida Power & Light Co 90/06/06 ip
- B006:30254 Forwards safe shutdown evaluations for auxiliary bldg hallway & cable spreading room in response to NRC 791029 request for fire protection info Reactivity control sys assures safe subcritical core conditions after reactor trip UHRIG.R E Florida Power & Light Co B0/06/09 21pp
- 8006260056 Notification of 800619 meeting w/util in Bethesda.MD to discuss fire protection program & implementation of App R GROTENHUSS.M Operating Reactors Branch 1 80/06/09 2pp
- 8006240192 Forwards proposed revision to emergency plan Apps to be submitted under separate cover implementation to begin by 810101.depending on resource availability & final resolution of open issues Plan withheld (ref Privacy Act) UHRIG.R E Florida Power & Light Co 80/06/19 ip
- BOO6240196 Advises that util has re-evaluated Section 3 1 12 of NRC 790321 fire protection SER Sprinkler heads on outside wall of diesel generator bldg offer better means to reduce potential diesel generator sys damage UHRIO.R E Florida Power & Light Co 80/06/RO 1p.
- Q Adjudicatory correspondence
- 8006260202 Requests that NRC advise Board members of projected dates for issuance of draft & final EIS, to enable parties to discuss scheduling of proceedings re issuance of OL amends Certificate of Suc encil REIS, HF Lowenstein, Newman, Reis, Axelrad & Toll 80/06/23 App
- H General correspondence
- 8006300696 Responds to 800410 ltr re facility E18 E18 prepared for all CP & OL applications E18 preparation process discussed GOLDBERG.8 C Hearing Branch 2 80/05/09 2pp
- 8006070068 Ack receipt of 800402 & 0227 itrs Discusses criteria used in granting or denying amend requests NUREO-0651.
 "Evaluation of Steam Generator Tube Rupture Events," encl W/D encl VAROA, S A Operating Reactors Branch 1 80/05/20 2pp
- M Antitrust correspondence
- BOO6240137 Notice by Orlanda Utils Commission to withdraw intervention by request to institute proceeding re Commission 780727 order City of Orlando.potitioner & util BOO606 settlement resolved issues Waffidavit & Certificate of Svc WISE.W C Orlando.FL WISE.W C Ulse. W C 80/06/20 4pp
- P Operating license stage documents & correspondence
- BOO6090165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIBENHUT, D O Division of Licensing 80/05/07 150pp
- 8006:30122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D Q Division of Licensing 80/05/19 72pp
- 8006030053 Corrects & supplements 800318 ltr re-steam generator repair Monitoring repts will be submitted annually by 80033! Improvements designed to enhance secondary water chamistry control being implemented UHRIO,R E Florida Power & Light Co 80/05/27. 2pp
- 8006260076 Forwards evaluation of 791220 response to NRC 791016 requirements for auxiliary feedwater sys Requests response to comments on 68-4 & GL-3 & confirmation of conformance w/ revision to Recommendation 2 within 45 days VARQA.8.A Operating Reactors Branch 1 80/05/30 9pp
- BOO6200047 "Proposed Amend to Facility OLs DPR-31 & DPR-41.Delts T vs Reactor Power Shift Check.Turkey Point Units 3 & 4," informal rept UDY.A C EGB., Inc FIN A-6206 8006200047 80/05/31 7pp

- B004060341 Forwards info supplementing response to NRC 770828 ltr re containment purge valves Provisions are adequate to preclude failure of valves to close due to entrained debris in fluid
 - UHRIO.R E Florida Power & Light Co 80/06/03 6pp
- 8006080342 Advises of intention to begin repair of Unit 4 steam generators in Oct 1981 % Unit 3 in Oct 1982 Requests that NRC begin preparation of EIS so that ASLS proceedings reamend to OL can be completed UHRIG.R E Florida Power & Light Co 80/06/03 lp
- 8006090370 Application to amend App A of Licenses DPR-Qi & DPR-41, changing Tech Specs,Pages 3 2-2 & 3 2-4, to reflect results of revised ECCS analysis of power distribution limits for 25% steam generator tube plugging Revised Tech Specs encl UHRIO,R E Florida Power & Light Co 80/06/05 2pp
- --B006090393 Revised Tech Specs,Pages 3 2-3 & 3 2-4 for amend to App A of Licenses BPR-31 & DPR-41 Reflects results of revised ECCS analysis on power distribution limits for 25% steam generator tube plugging 4 Florida Power & Light Co 80/06/05 3pp
- --8006070397 "ECCS Analysis,25% Steam Generator Tube Plugging " SCHMIDT,A D Florida Power & Light Co 80/06/05 3ipp
- 8005i10093 Forwards util 800527 ltr to NRC re proposed amends to OL permitting steam generator repairs Corrects & supplements 800318 ltr to IRC COLL.N A Steel, Hector & Davis 80/06/05 4pp
- --8006110079 Corrects & supplements 800318 ltr to NRC re proposed amends to DL permitting steam generator repairs Util has approved various plant improvements.including installation of condensate polishing demineralizars UMRIQ.R E Florida Power & Light Co 80/05/27 2pp
- 8006200479 Forwards info re add1 TM1-related requirements per 800307 ltr Includes shift manning revising scope & criteria of licensing exams procedures for feedback of operating experience to plant staff & PUR vendor rept UHRIG.R E Florida Power & Light Co 80/06/13 3pp
- 8006240261 Requests extension until 800801 to incorporate NRC proposed changes into Tech Specs as discussed in L-80-157 ltr Effect of shared sys will need to be investigated & specs will need to be reviewed to determine applicability of STB 3 0 3 % 5 UHRIGAR E Florida Power & Light Co 80/06/18 1p
- 8006300229 Requests that any info re plants or animals in site vicinity, listed or proposed to be listed as endangered species, be provided for preparation of EIS per amend review VARQA.S A Operating Reactors Branch 1 80/06/19 2pp
- O Inspection reports, IE Bulletins & correspondence
- 9006090470 Forwards IE Insp Repts 50-250/80-14 & 50-251/80-12 on BOO410 & It No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/05/01 2pp
- --- 9006090473 IE Insp Repts 50-230/80-14 & 50-251/80-12 on 800410 & 11 No Nonvolve it into Repts 50-230/80-14 & 50-231/80-12 on 800450 & 11 moncompliance noted Major areas inspected const status & action on previous inspectings
 RAUBCH-J K Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch WILCOX-J D MCFARLAND.C R Region 2. Atlanta,
 Office of the Director 60/04/30 3pp
- 8004040567 Forwards IE Bulletin 80-11, "Masonry Hall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 800A050286 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Requires action & response within 30 days IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Days-Besse Unit I While in Refueling Mode" enc! Office of the Director 80/05/07
- 8006300107 Forwards IE Circular 80-11. "Emergency Divsel Generator Lube Gil Cooler Failures " No written response required O'REILLY:J P Region 2. Atlanta, Office of the Director 80/05/13

- 8006040013 Ack receipt of 800118,0321 & 0501 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-35,50-251/79-35,50-335/79-33 & 50-387/79-22 MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 1p
- --8006040021 Responds to NRC 791219 itr re violations noted in IE Inap Repts 50-250/79-35,50-251/79-39,50-335/79-33 & 50-389/79-22 Corrective actions GA procedures will be revised w/full compliance achieved by 800731 UHRIG.R E Florida Power & Light Co 80/05/01 ip
- --8006040025 Responds to NRC 791219 & 800220 ltrs re violations noted in IE lnsp Repts 50-250/79-35.50-251/79-35.50-335/79-33 & 50-387/79-22 Corrective actions QA procedures will be revised re implementation of IOCFR21 UHRIG.R & Florida Power & Light Co 80/03/21 3pp 90/03/21 3pp
- 8006170165 Ack receipt of 800519 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-250/80-08 & 50-251/80-08 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety 80/05/29
- --B006170171 Responds to NRC B00424 itr re violations noted in IE Insp Repts 50-250/B0-08 & 50-251/B0-0B Corrective actions personnel counseled in correct procedural compliance Notation made on calibr tickler card UHRIG.R E Florida Power & Light Co 80/05/19 2pp
- --8006170174 Forwards IE Insp Repts 50-250/80-08 & 50-251/80-08 on B00325-28 & notice of violation STOHR,J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/04/24 Spp
- --8006170180 Notice of violation from insp on 800325-28 * Region 2, Atlanta, Office of the Director 80/0 80/04/23 1p
- --8006170188 IE Insp Repts 50-250/80-08 \$ 50-251/80-08 on 800325-28 Noncompliance noted failure to have 5 follow written procedures for radiochemistry counting equipment MONTOGMERY.D M Region 2, Atlanta, Office of the Director TROUP.O Region 2, Atlanta, Fuel Facility 5 Materials Safety Branch 80/04/23 9pp
- 8006180017 Ack receipt of 800807 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80-10 & 50-251/80-10 LENIS,R C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/30 1p
- ---8006180021 Responds to NRC 800414 ltr re violations noted in IE Insp Repts 50-250/80-10 & 50-251/80-10 Corrective actions preventative maint to be performed on critical portions of lant communications sys HR10:R E Florida Power & Light Co 80/05/09
- --8006180024 Confirms, per conversation w/R Vogt-Lowell, that response to IE Insp Repts 50-250/80-10 & 50-251/80-10 will be submitted by 800509 UHRIO, R E Florida Power & Light Co 80/05/07 ip
- --B006180028 Forwards IE Insp Repts 50-250/80-10 & 30-251/80-10 on 800201-29 & notices of violation & deviation LEWIS,R C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/04/14 ip
- --8006180032 Notice of violation from insp on 800201-29 * Region 2, Atlanta, Office of the Director 80/0 80/04/02 10
- --8004180033 Notice of deviation from insp on 800201-29 * Region 2. Atlanta. Office of the Director 80/0 80/04/02 ip
- --8006180036 IE Insp Repts 50-250/80-10 \$ 50-251/80-10 on 800201-29 oublibuods in Insp Repts 50-250/80-10 to 250/80-10 on 800201-29
 Noncompliance noted failure to generate final approved maint
 procedures for auxiliary feedwater
 VGGT-LGHELL, R Region 2. Atlanta, Office of the Director
 WARTIN, R D Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch 80/04/02 5pp
- 8006260127 Submits supplemental response to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Bafety-Related Sys "Relays are tested monthly by licensed operations personnel Relay failures, maint & testing are documented UHRIGAR E Florida Power & Light Co 80/05/30 ip
- B006170646 Forwards response to IC Duiletin 79-01B, "Environ Qualification of Class IE Equipment " W/o encl UHRIG:R E Florida Power & Light Co 80/06/02 1p

- 8006200212 Ack receipt of 800921 ltr informing NRC of steps taken to correct deviation noted in IF lnsp Repts 50-250/80-15 & 50-251/80-13 LEWIS.R C__Region 2: Atlanta Reactor Operations Nuclear Support
 - 80705704
- --8006200216 Responds to IRC 800425 ltr re deviation noted in IE Insp Repts 50-250/80-15 % 50-251/80-13 Corrective actions mod initiated to install audible % visual alarm for loss of to tire pump E Florida Power & Light Co 80/05/21 2pp
- --8006200219 Forwards IE Insp Repts 50-250/80-15 & 50-251/80-13 on 800301-31 % notice of deviation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- --8006200222 Notice of deviation from insp on 800301-31 * Region 2: Atlanta, Office of the Director 80/0 80/04/23 1p
- -- BOO6200227 IE Insp Repts 50-250/80-15 % 50-251/80-13 an BOO301-31 Nancompliance noted fire pumps inoperable for 17 days due to breaker left open following maint MARTIN.R D Region 1. Philadelphia, Reactor Operations Nuclear Support Branch VOGT-LOWELL.R J Region 2, Atlanta, Office of the Director 80/04/23 1pp
- B006090340 Forwards results of steam generator insps showing approx 22 4% lube plugging Requests permission to resume operation on 800612 UHRIG.R E Florida Power & Light Co 80/06/05 2pp
- --8006070342 Steam generator insp program conducted in May 1780 Summalizes insps.results of insps & preventice plugging programs accomplished during current outage 4 Florida Fower & Light Co 80/06/03 32pp
- BOO6300021 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation % Control Power Bys Bus During Operation " Power restoration to vital ac or dc buses is accomplished per established plant operating procedures UHRIG.R E Florida Power & Light Co 80/06/05 2pp
- 8006230184 Forwards supplemental response to IE Bulletip 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Each alarm associated w/loss of power to buses is addressed in appropriate annunciator list UHRIO.R E florida Power & Light Co 80/06/06 2pp
- 8004250304 Responds to IF Bulletin 80-12 Sufficient hardware, redundancy, diversity, reliability & control exist to handle loss of decay heat removal occurrence UHRIG.R E Florida Power & Light Co 80/06/11 2pp
- 800630057? Responds to IF Bulletin 80-05 Adequate measures to protect refueling water storage tank against vacuum conditions have been taken No mods required URRIG.R E Florida Power & Light Co BD/06/12 3pp
- R Periodic operating reports & related correspondence
- EOO.6170467 Forwards monthly operating repts for May 1980 SCHMIDT. A D Florida Power & Light Co 80/06/07 1p
- --8006170474 Monthly operating rept for May 1980 CHILBON, V T Florida Power & Light Co 80/ 80/06/07 4pp
- S Reportable occurrences, LERs & related correspondence
- 8006050479 PNS-II-80-013 on 800519, bomb threat was received by Central Dispatch, Metropolitan Dade County Public Bafety Dept Licensee conducted search no bomb was found HOWELL.J C., GILLESPIE.F. Region 2. Atlanta, Office of the Director NRC 80705/19 ip
- BOQ4030454 Forwards LFR 80-007/01T-Q BCHMIDT, A D Florida Power & Light Co 80/05/21 1p
- --8006630456 LER 80-007/01T-0 on 800507. While performing planned maint as result of problem on Unit 3 (LER 250-79-3i), disc stud nut was discovered missing from 4A main steam check valve Caused by failure of associated locking device SCHOPPMAN.M A Florida Power & Light Co 80/05/21 2pp

- 8006130376 PND-11-80-094 licensee identified 5-inch track in 40 steam generator feedwater nozzle-to-pipe reducer Licensee evaluating corrective action Unit shut down for turbine rotor replacement b steam generator insp ELROD.8. GUICK, D Region 2. Atlanta, Office of the Director GO/05/23 ip
- 8004250028 PNO-I!-80-096 on 800527, licensee was informed by AVACATION FAULTI-BU-076 on 800527, licensee was informed by Westinghouse that nonconservative error was found in computer inputs used Feb 1979 to calculate heat flur hot channel factor for fuel assemblies ELROD. 8. QUICK.D Region 2. Atlanta, Office of the Director 80/05/28 1p
- 8006190258 Forwards updated LER 80-003/03L-0 SCHMIDT, A D Florida Power & Light Co 80/05/30 ip
- --8006190285 Updated LER 80-003/03L-0 on 800215, while testing 4C steam generator feedwater control valve change in steam generator level lifted low setpoint valve Valve did not fully reseat Caused by binding between lifting gear & release nut SCHOPPMAN.M A Florida Power & Light Co 80/05/30 ip
- 8006230567 Forwards LER 80-008/01T-0 8CHMIDT.A D Florida Power & Light Co 80/06/09 ip
- -800&230571 LER 80-00B/01T-0 on 800523 review of radiographs per IE Bulletin 79-13 revealed indications of cracking in feedwater noisle to pipe weld on steam generator 4 C reducers Cause not stated Fitbings containing defects are being replaced BCHOPPMAN.M A Florida Power & Light Co 80/06/09 2pp
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1 F Becurity, medical, emergency & fire protection plans
- 8006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CFR30 & is expected to be published in FR by end of May EISENHUT.D G Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101;" transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- 8006090018 Forwards request for add1 info heeded for review of safeguards contingency plan Requests add1 info be submitted within 30 days of receipt of itr Enc1 withheld (ref 10CFR2 770) IPPOLITO T A Operating Reactors Branch 2 80/05/27 2pp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES D.L. Commonwealth Edison Co. 80/06/04 2pp
- --8006180317 Draft emergency plan annex s Commonwealth Edison Co B0/07/31 48pp
- ---BOO41BO347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co BO/07/31 139pp
- 8006170559 Forwards drawings & responses to questions re fire protection safe shutdown analysis, requested in NRC 791022 ltr JANECEK, R F Commonwealth Edison Co 80/06/06 5pp
- ---8006170564 "Single Line Diagram Emergency Power Sys "
 * Sargent & Lundy, Inc. 76/06/30 ip
- --8006170586 "Behematic Diagram Engine Control & Generator Excitation, Standby Diosel Generator i " * Sargent & Lundy, Inc. 76/06/30 1p
- -- 9006170571 "Schematic Control Diagram Engine Control & Generator Excitation Standby Diesel Generator 1 & 2 " # Bargent & Lundy, Inc 79/10/01 ip

- --8006170597 "Schematic Control Diagram Engine Control & Generator Excitation,Standby Diesel Generator 2 " Sargent & Lundy, Inc. 76/07/07 ip
- --8006170607 "Relaying & Matering Diagram Residual Auxiliary Transformer 12 & 4160 Volt Switchgears 13 & 14 " * Sargent & Lundy, Inc. 76/06/30 1p
- --8006170613 "Relaying & Metering Diagram 4160 Volt Switchgears Buses
 - Sargent & Lundy. Inc 76/06/30 ip
- --8006170616 "Schematic Control Diagram 4160 Volt Buses 13-1 & 14-1 Main
 - * Sargent & Lundy, Inc. 76/06/30 ip
- --8006170622 "Schematic Control Diagram 4160 Volt Bus 13-1 Standby Diesel 1/2 Feed Breakers "
 * Sargent & Lundy, Inc 79/10/01 1p
- --- 8006170628 "Schematic Control Diagram 4160 Volt Bus 14-1 Standby Diesel
 - 1 Feed & 24-1 Tie Greakor " * Sargent & Lundy, Inc. 79/10/01 1p
- --8006170632 "Schematic Control Diagram 480 Volt Transformer 18 & 19 & Buses 18 & 19 Main Breakers"

 * Sargent & Lundy, Inc. 76/06/30 ip
- 8006240490 Responds to NRC 800425.30,0501.09 & 20 ltrs requesting add1 info re guard training & qualification plans Requests that response submittal date be extended to 800804 PEOPLES.D L Commonwealth Edison Co 80/06/18 1p
- H General correspondence
- 800.6120082 Responds to 800415 itr requesting response to J Smith concerns re radiuste dumping at facility Radiuste produced as result of plant operation shipped offsite for burial at licensed burial site DIRCKS.N J Defice of the Executive Director for Operations 80/05/28 1p
- ---8006120086 Requests response to encl J Smith ltr re radwaste dumping at RAILSBACK, T House of Rep 80/04/15 2pp
- P Operating license stage documents & correspondence
- B006090165 Forwards add) TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing erams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing B0/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREG-0577, "Potential For Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enc! EIGENHUT, D G Division of Licensing 80/05/19 72pp
- 8006030062 Application to amend Licenses DPR-2, DPR-17, DPR-25, DPR-29 & BPR-30, clarifying term "operable," submitted as Tech Spec change request in response to NRC 800410 ltr NAUGHTON, W F Commonwealth Edison Co 80/05/30 2pp
- --8006030072 Tech Spec change request for Tech Specs Sections 1 0-1 2,2 1 & 2 2,3 0,5 0 & 6 0-6 6 re definitions, administrative controls, safety limits, limiting safety sys setting & limiting conditions for operation * Commonwealth Edison Co 80/05/30 42pp
- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREO-0619, "BWR Feedwater Notrie & Control Rod Drive Return Line Notale Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENMUT.D 0 Division of Licensing 90/06/05 22pp

- 800A090356 Forwards proposed amend to OL to extend end-of-cycle coastdown operation Class III fee encl
 JANECEK,R F Commonwealth Edison Co 80/06/06 4pp
- --8006090363 Proposed amend to CL extending licensed coastdown limit from 707 to 40% reactor power Forwards supporting documentation # Commonwealth Edison Co 80/06/Q6 18pp
- 8006190456 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 790808 request JANECEK, R F Commonwealth Edison Co 80/06/11 3pp
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltr re add1 TMI-2 related requirements Dresden Unit 1 is currently undergoing extensive mod & decontamination, therefore no response is provided PEOPLES.D L Commonwealth Edison Co 80/06/12 10pp
- 8006190419 Confirms availability of ECCS equipment following 6c power supply failure,per 800425 request Mods to ensure availability of HFCI following 6c power failure completed at Dresden & in progress at Quad Cities

 JANECEK. R F Fommonwealth Edison Co 80/06/12 2pp
- 8006250277 Forwards response to NRC 800516 Itr requesting info re turbine disc cracking Stress corresion cracks hot abserved to date JANECEK, R F Commonwealth Edison Co 80/06/23 16pp
- BOD6270306 Forwards revised Revisions it & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations " Revised Revision it includes basis on which equivalent education requirements will be established PEOPLES, D. L. Commonwealth Edison Co. 80/06/23 1p
- @ Inspection reports, IE Bulletins & correspondence
- B005230330 Forwards waste packaging insp rept on B00313-14 No noncompliance noted STOHR,JP Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --8005230341 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DDT placarding requirement PDTTER, J P Region 2. Atlanta, Fuel Facility & Materials Gafety Branch 80/03/28 4pp
- 8006200110 Forwards IF Circular 80-08. "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response regoired KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/04/18
- 8006020185 Forwards IE Insp Repts 50-254/80-07 % 50-265/80-10 on 800325-27 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/04/23 2pp
- --8004020192 IE Inso Repts 50-254/80-07 % 50-265/80-10 pn 800325-27 No UUGD20172 IE IMSP REPTS 50-254/80-07 3 50-265/80-10 on BUG325-27 Noncompliance noted Major areas inspected environ protection program, environ monitoring program 5 confirmatory measurements of radiological effluents ESSI0.7 H. GRANT, W.B. & LOVENDALE, P.C. Region 3. Chicago, Office of the Director BO/04/17 5pp
- 8006170268 Forwards IE Insp Repts 50-254/80-09 \$ 50-265/80-12 on 800401-02 No noncompliance noted HEISHKAN.R F Region 3: Chicago, Reactor Operations Nuclear Support Branch 80/05/01 2pp
- --8006170276 IE Insp Repts 50-254/80-07 & 50-265/80-12 on 800401-02 No noncompliance noted Major areas inspected initial training & retraining of licensed & nonlicensed personnel & licensed operator requalification training
 SMANSON.E R Region 3. Chicago, Office of the Director JACKIK, I N Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/04/29 Jpp
- 8006230075 Forwards IE Insp Repts 50-254/80-10 & 50-265/80-13 on 800327-0507 No noncompliance noted HEISHMAN,R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/05/16 2pp

ī

- --8006230078 IE Insp Repts 50-254/80-10 & 50-265/80-13 on 800327-0507 No noncompliance noted Major aleas inspected operational safety, long-term shutdown, maint & surveillance SPESSARD, R. L. CHRISSOTIMOS, N. Region 3, Chicago, Office of the Director 80/05/15 Bpp
- BOO602000B Responds to IE Bulletin 79-26 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated B4C leaching Control blade exposures will be monitored during cycles to verify projected end-of-cycle exposure PEOPLES, D L. Commonwealth Edison Co. 80/05/19 2pp
- BOO630055B Forwards response to IE Bulletin BO-06, "Engineered Safety Feature (ESF) Reset Controls " Proposed mads identified only if present sys design may compromise protective action of equipment PFOPIFS.D L. Commonwealth Edison Co. 80/06/10 900
- R Periodic operating reports 5 related correspondence
- 8006110078 Forwards monthly operating repts for May 1980 KALIVIANAK18,N Commonwealth Edison Co 80/05/30 ip
- ---8006110084 Monthly operating repts for May 1980 * Commonwealth Edison Co 80/05/30 25pp
- 8006110034 Forwards list of mods.tests & experiments completed during May 1980 & summary of safety evaluations KALIVIANAKIS.N Commonwealth Edison Co 80/06/02 2pp
- S Reportable occurrences. LERs 3 related correspondence
- BCO6050192 PNO-III-BO-098 on BCO519, approx 13 Ci noble gases were released from offgas charcoal adsorber sys directly to main chimney when operator accidentally opened bypass valve Matter being followed by resident inspector HUETCR.C. J. FISHER.W T. DAVIS.A B. Region 3. Chicago. Office of the Director 80/05/20 ip
- BOO6110141 Forwards LER 80-012/03L-0
 KALIVIANAKIS,N Commonwealth Edison Co BO/05/23 1p
- --8006110151 tER 80-012/03L-0 on 800429, reactor recirculation motor generator set 1A tripped due to low oil presure from lube oil pump 1A1 trip Possibly caused by contractor personnel dropping matl on generator set control cabinet BWALES.J Commonwealth Edison Co 80/05/23 2pp
- BCOG110304 Forwards LER 80-011/03L-0 KALIVIANAKIS, N Commonwealth Edison Co BO/05/27 1p
- --8006110312 LER 80-011/03L-0 on 800429 main feed breaker to MCC 19-1 tripped Caused by excessive current trip time which allowed phase-to-phase short internal to be carried back to MCC 19-1 Notor & circuit breaker replaced HCELLER.J Commonwealth Edison Co 80/05/27 2pp
- BG06230391 Forwards LER GO-015/03L-O KALIVIANAKIS,N Commonwealth Edison Co BO/06/09 lp
- --8004230392 LER 80-019/03L-0 on B00511, during manual operation of relief valves, valve 1-203-3B failed to open HPCI & other valves operable Caused by dirty contact on valve operator hold-in coil switch Bwitch replaced & valve returned to svc 800512 EAGLE. J Commonwealth Edison Co 80/06/09 2pp
- 8006300330 EN-80-25 notice of violation % notice of proposed imposition of civil penalty will be issued on or about 800620 Action based on noncompliance re external radiation levels on vehicle exceeding limits Will issue press release BROCKETT, T W , THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/06/18 ip
- DOCKET 50-255 PALISADES NUCLEAR PLANT

 F Security, medical, emergency & fire protection plans
- 8006020234 Notifies that new telephone sys called Health Physics Network (HPR) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER.J G Region 3, Chicago, Office of the Director 80/04/18 2pp

- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end or May EISENHUT, D G Division of Licensing 80/05/19 46pp
- 8006030580 Notifies that review of safeguards contingency plan & Revision 1 dated 790601 & 800219, respectively, complete Requests revised plan pages within 30 days w/appropriate revision number & date Encl withheld (ref 10CFR2 790) CRUTCHFIELD, D II Operating Reactors Branch 5 80/05/20 2pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D.G. Division of Licensing 80/05/22 73pp
- 8006240578 Requests response to encl comments for NRC review of 790823 guard training & qualification plan Encl withheld (ref 100FR2 790)
 CRUTCHFIELD, D. Operating Reactors Branch 5 80/06/06 2pp
- Q Adjudicatory correspondence
- 8004060465 Discovery rept per ASLB 800229 order Served interrogatories & request to produce documents on NRC Initiated 800319 F01A request Will file motion to compel NRC responses to certain interrogatories & documents Related correspondence MURPHY.P M Consumers Power Co MURPHY.P M Isham. Lincoln & Beale 80/04/25 3pp
- 8004120263 Motion to compel NRC to produce documents requested in util Interrogatories 2, 3, 4, 5, 12, 13, 14, 15 & 17 Util will review NRC objections re other matls Certificate of Svc encl Related correspondence MILLER.M I , MURPHY, P M, BIELAWSKI, A P Consumers Power Co 80/05/14 21pp
- 8006060579 Memorandum & order granting extension until 800613 for parties to file joint or individual statements re agreement & rulings areas Status rept due 800601 not required Certificate of Sec enc! SMITH,I W Atomic Safety and Licensing Board Panel 80/06/02 20
- 8006170232 Memorandum & order granting CPC & NRC 800530 telcon request to suspend discovery pending possible settlement or limitation of issues Parties must file joint statement reareas of agreement & areas heeding rulings by 800613 SMITH.I W Atomic Safety and Licensing Board Panel 80/06/02 ip
- BOO6160123 Forwards draft agreed order on discovery re licensee physical tests Requests that ABLB enter order approving schedule Related correspondence MURPHY,P H Isham, Lincoln & Beale BO/06/05 4pp
- BOO6120346 Order amending discovery schedule Licensee granted until BOO613 to file suppl to BOO514 motion to compel Licensee shall respond to discovery initiated by NRC on BOO623 SMITH, I W Atomic Safety and Licensing Board Panel BO/06/09 2p.
- 8006170524 Supplemental motion to compel NRC response to 800225 Interrogatories 2 through 5.13 through 15 & 17 Matl not privileged relevant or necessary to decision Certificate of Svc encl MILLER.M I MURPHY.P M , BIELAWSKI.A P Consumers Power Co 80/06/13 10pp
- 8006300513 Response to NRC 800418 interrogatories re civil penalty proceeding Includes info re Sept 1979 discovery of two locked-open manual containment soclation valves & associated radiation releases Certificate of Svc & documents encl MURPHY.P M , MILLER.M I Consumers Power Co MURPHY.P M Isham, Lincoln & Beale 80704/23 33pp
- --8006300517 "Inplace Hepa & Charcoal Filter Testing," health physics procedure SHCKKLEY, V E Carolina Power & Light Co LEWIB, J O Consumers Power Co 76/12/29 3pp
- --B006300530 "In Place Testing of Hega Filters & Iodina Adsorbers," effective 750321 * Consumers Power Co 75/03/11 1200

- 8006270181 Responds to 800429 request for info re M LeMiere inquiry about amount of nuclear waste disposed in State of HI Spent fuel from four operating Mi reactors stored onsite NRC evaluated status of waste mgt in 1977 Whrelated FR excerpts DIRCKS.N.J. Office of the Erecutive Director for Operations 80706709 10pp
- P Operating license stage documents & correspondence
- BOD6130016 Forwards corrected Pages 3-25a & 4-39 to Tech Specs issued w/Amend 51 to DPR-20 Spec 4 1 1 a 1 on Page 4-1 should not be misinterpreted to prohibit performance of channel functional tests which Include valve operation CRUICHFIELD.D Operating Reactors Sranch 5 B0/05/05 2pp
- --8006130019 Corrected Pages 3-25a & 4-39 to Tech Specs issued w/Amend 51 to DPR-20 * Operating Reactors Branch 5 79/09/10 2pp
- 8005090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. Licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISEMHUT.D G Division of Licensing 80/05/07 150pp
- 8006280002 Requests info re environ qualification of electrical equipment Response to fire categories of SEP qualification should be submitted within 60 days Quidance reflecting reviews performed at site encl
 CRUICHFIELD, D Operating Reactors Branch 5 80/05/16 10pp Operating Reactors Branch 5 80/05/16 10pp
- 8006250141 Forwards NUREG-0654.Vols 1 & II & NUREG-0626 W/o enc1 CRUTCHFIELD.0 Operating Reactors Branch 5 80/05/14 2pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness & Lamellar Yearing on FWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENNUT.D & Division of Licensing 80/05/19 72pp
- 80060903B3 Confirmt telcon between util & R Skelton concerning R Thomas 800827-30 visit to facility NRC personnel util require access to plant info & vital areas CRUTCHFIELD.D M Operating Reactors Branch 5 80/05/21 2pp
- \$006020272 Advises that mods will be made to separately annunciated control switch not in automatic overspeed overcrank & loss of &c control Annunciator window signs will clearly state that emergency diesel generator automatic start is blocked NGFFMAN.D P Consumers Power Co 80/05/28 2pp
- 8004040311 Forwards emergency implementation procedures EI8-3, EI8-4, EI8-5, EI8-6, EI8-7, EI8-8 & EI8-9 & Card B for plant health physicist HOFFMAN, D P Consumers Power Co 80/05/27 1p
- --8008040313 Emergency procedure.Card 8, for plant health physicist 4 Consumers Power Co 80/05/14 3pp
- ---8006040315 "Determination of Extent of Core Damage "
 * Consumers Power Co 80/04/29 8pp
- ---8004040316 "Emergency High Range Effluents Monitor "
 * Consumers Power Co 80/04/26 7pp
- --8006040318 "in-plant Aurborne lodine Monitoring & Thyroid Blocking Agent Administration Under Accident Conditions " & Consumers Power Co 80/04/29 Spp
- --8006040320 "Sampling & Analysis of High Activity Reactor Coolant "
 ∢ Consumers Power Co 80/04/24 3pp
- ---8006040323 "Sampling & Analysis of High Activity Containment
 - Atmosphere **

 * Consumers Power Co 80/04/30 7pp
- ---8004040325 "Offsite Accident TLD Procedure "
 * Consumers Power Co 80/04/21 5pp
- --8004040330 "Office Airborne lodine Monatoring Under Accident
 - Consumers Power Co 80/04/30 5pp

- 8006170049 Notifies that Project Manager T Wambach is coordinating licensing activities as result of reorganization within Ofc of Nuclear Reactor Regulation Description of new organization encl
 CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/02 32pp
- 8006070300 Responds to NRC 800410 request that term "operable" be appropriately applied to facility Plant review committee has approved Tech Spec changes to fulfill NRC request HOFFMAN, D.P. Consumers Power Co. 80/06/04 ip
- 8006110153 Furwards reactor internals noise monitoring test results Reactor core barrel tightly clamped w/no other anomalous vibrations during testing HOFFMAN.D P Consumers Power Co 80/06/04 1p
- --8006110157 "Reactor Internals Noise Monitoring Tests Nov 1978-Nov 1979 '
 * Consumers Power Co 79/11/30 34po
- 8005090271 Justifies use of Monte Carlo calculation (XMC) as ref calculational method XMC applicable to facility XMC local power distribution calculation due to similarity between util lattice & SMR assemblies measured HOFFMAN. D P Consumers Power Co 80/06/06 2pp
- 8006110165 Forwards summary of Cycle 4 DNB analysis per 800605 meeting w/H Balukjian & L Philips HOFFMAN.D P Consumers Power Co 80/06/06 5pp
- B0061203B4 Requests approval of min frequency response of d-c to 100 hert: plus or minus 5% for eddy current test equipment HUSTON.R W Consumers Power Co B0/06/09 1p
- 8006190783 Outlines Core Performance Branch responsibilities re util 800514 request for changes in nuclear peaking factor for Cycle 4 Branch should review radial vs axial peaking factor trade-off, Type H fuel parameters & rupture model SPEIS, T P Reactor Systems Branch 80/06/09 2pp
- B006i60051 Notifies that util will meet requirements & schedules specified in NRC 800507 ltr w/five exceptions Item re shift manning & overtime procedures involves union & licensed gersonnel problems
 HUSTON: R W Consumers Power Co 80/06/11 2pp
- 8006240283 Provides response to Woodward-Clyde Consultant questions re seismic adequacy of facility Diesel generator day tank drawing will be forthcoming Encl engineering specs, data & manual available in Contral Files only MARUSICH R M Consumers Power Co 80/06/20 2pp
- 8006300377 Forwards info supplementing previous responses to NUREQ-0578 re sys integrity review Info summarizes sys tests, initial test results, significant repairs made % post-repair test results HOFFMAN,DP Cansumers Power Co 80/04/25 2pp
- O Inspection reports: IE Bulletins & correspondence
- 8006040153 Refers to 800410 ltr to Region 3 describing actions taken in response to 791109 order modifying License DPR-20 Insp confirms accomplishments Restart is no longer delayed by oreer STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/25 ip Director
- 8006180041 Forwards IE lasp Rept 50-255/80-05 on B00303-07,10,12-14, 17-21 & 24-28 No noncompliance noted HE18HMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- --8006180046 IE Insp Rept 50-255/80-05 on 800303-07, 10, 12-14, 17-21 & JOSIBOURS IE Insp Rept 50-253-260-05 on BOO303-07, 10,12-14,17-21 & 24-28 No noncompliance noted Hajoi areas inspected resident Insp program activities, including operations, reportable events, IE bulletins & NUREG-0578 requirements BAKER, KR. , JORGENSCH, B.L., BOVD, D.C. Region 3, Chicago, Office of the Director 80/04/21 17pp
- 8006190673 Forwards IE Insp Rept 50-255/80-07 on 800423 No nancompliance noted
 FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/05/09 2pp
- --8006190675 IE Insp Rept 50-255/80-07 on 800423 No noncompliance noted Major areas inspected allegation re poor weld quality of rod hangers on containment spray ring DANIECSON,D H., WARD, K.D. Region 3. Chicago, Office of the Director 80/05/08 3pp

- BOO4050530 Ack receipt of 800508 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-255/79-20 HEISHMAN,R F Region 3, Chicago. Reactor Operations Nuclear Support Branch BO/05/14 ip
- --8005050533 Responds to NRC 800320 ltr re violations noted in IE Insp Rept 50-255/79-20 Corrective actions personnel will be instructed on recently developed administrative controls re Tech Specs surveillance test program HOFFMAN, D.P. Consumers Power Co. 80/05/08 2pp
- 8006130076 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON.J M Division of Rules and Records 80/05/23 3pp
- --8006130080 Discusses review of licensee 791129 response to IE 791109 notice of violation 5 notice of proposed imposition of civil penalties Forwards draft response 5 order supporting position taken in notice proposing civil penalty KFPPLER.J G Region 3, Chicago, Office of the Director 79/12/07
- --B0061300B2 Responds to N Moseley memo received B003i3 Lists noncompliances which appear to meet criteria identified in util Interrogatories 12,13 % i4 ENGELMEN,R H Region 5, San Fiancisco, Office of the Director 80/03/18 2pp
- --GOO41300B6 Responds to request for assistance in answering util interrogatories Forwards examples of previous noncompliances involving Item 12 in memo No examples re Items 13 & 14 were found D'REJLLY, J P. Region 2, Atlanta, Office of the Director BD/03/19 3on
- --8006130088 Forwards LERs in response to util Interrogatory 12 re violations of containment integrity 8 civil penalty No items of noncompliance found re util Interrogaturies 13 or 14 WESTERMAN, Y F Region 4. Dallas, Office of the Director 80/03/19 ip
- ---B006:30099 Forwards response to updated memo received on B003:3 re util interrogatorites re proposed imposition of civil penalty Cover sheet of IC insp rept encl
 KEPPLER.J G Region 3, Chicaga, Office of the Director 80/03/21
- --BOO6130124 Confirms 790913 verbal rept of RO re violation of containment integrity Tech Specs Requirements had not been met during Cycle 3

 DEWITTIR B Consumers Power Co 79/09/14 1p
- --8006130136 Draft preposed AO on 790914, util reported that containment integrity had been breached for indeterminate amount of time Caused by inadequate procedures Procedures have been updated

 ** Consumers Power Co 79/09/14 Hpp
- 8006180161 Ack receipt of 800516 ltr informing NRC of staps taken to correct violation noted in IC Insp Rept 50-255/80-04 HIND, J.A. Region 3. Chicago, Safeguards Branch 80/06/04 1p
- --R0061B0166 Responds to NRC 800428 ltr re violations noted in 1E lnsp Rept 50-255/E0-04 Corrective actions withheld (ref 10CFR2 790) HOFFMAN D P Consumers Power Co E0/05/16 1p
- 8006130285 Notifies that schedule for instruction of testing personnel tempervisors in revised Tech Specs surveillance program identified in IC Bulletin 79-20 no longer applicable due to delays in plant startup Revised completion dates 80613 & 30 HUBTON, R W Consumers Power Co 60/06/09 ip
- 8006130249 Forwards inservice insp program update following review in accordance w/code requirements & Tech Specs Applicable code has been changed to ASME Boiler & Pressure Code Section XI 1977 edition w/addenda through Bunmer 1978 HUSTON, R W Consumers Power Co 80/06/10 2pp
- 8004170593 Informs NRC that util response to 1E Bulletin 80-12, "Decay Heat Removal Sys Operability," will be provided by 800430 due to extensive nature of bulletin requests & late receipt of consultant rept HUSTON,R & Consumers Power Co 80/06/11 1p
- 9006200352 Responds to LE Bulletin 79-18 requiring survey to determine whether current alarms sys/evacuation announcement sys clearly audible throughout plant Project will be completed & results submitted to NRC by 800731
 HDFFMAN.D P Consumers Power Co 80/06/17 1p

- 8006200499 Responds to IF Bulletin BO-09, "Hydromotor Actuator Deficiencies" No subj actuators installed HOFFMAN.D P Consumers Power Co 89/06/17 1p
- 8006270209 Responds to LE Bulletin 80-04. "Engineered Safety Feature Reset Controls " W/list of sarety-related equipment not remaining in omergency mode upon engineered safety feature signals & list of equipment that returns to normal HOFFMAN.D P Consumers Power Co 80/06/23 20pp
- R Periodic operating reports & related correspondence
- 6006110133 Forwards monthly operating tept for May 1980 ADAMS, W.E. Carolina Power & Light Co. 80/06/03 1p
- --8006110136 Monthly operating rept for May 1980 BODTKE.P J Carolina Power ? Light Co 80/06/03 4pp
- S Reportable occurrences. LERs & related correspondence
- 8006110130 Forwards LER 80-013/017-0 HOFFMAN, D.P. Consumers Power Co. 80/06/04 1p
- --8006i10132 LER 80-013/01T-0 on B00521, HP81 flow indication for loop 2A was inoperable Caused by ruptured bellows Transmitter was replaced to restore operability a Consumers Power Co. 80/06/04 (p.
- 8006190414 Forwards LERs 80-014/03L-0,80-015/03L-0,80-016/03L-0 & 80-017/03L-0 HOFFMAN, D P Consumers Power Co 80/06/13 ip
- --8006190422 LER 80-014/C3L-0 on 800512, during routine testing of hydraulic snubbers, oil level in snubber 5 found to be less than zero Caused by rust combined w/vibrator, accelerating seal failure Rust found inside accumalator Consumers Power Co 80/06/13 1p
- --8006190426 LER 80-015/03L-0 on 800512, during routine testing of hydraulic snubber, oil level in snubber 9 found to be less than zero Cause of seal damage unknown; normal wear suspected Accumulator plunger seal found to be damaged * Consumers Power Co. 80/06/13 lp
- --8006190428 LER 80-016/03L-0 on 800515, during testing of hydraulic snubber of level in snubber 7 found to be less than zero Caused by seal degradation Snubber will be disassembled to confirm cause

 4 Consumers Power Co 80/06/13 1p
- ---8006190431 LCR 80-017/03L-0 on 800510, review of PS testing procedures revealed setpoint PS-1.801 through 1.804 to be lower than permitted Caused by procedure author not recognizing different setpoint requirements of Tech Specs 2 3 & 3 16 4 Consumers Power Co 80/06/13 ip
- 8006200445 Forwards NPDES noncompliance notification KOFFMAN, D.P. Consumers Power Co. 80/06/16 1p
- --8006200448 NPDES noncompliance notification on 800527.weekly grab sample for oil & greaso measured 84 0 mg/l Caused by excess oil entering turbine sump & possible plugging of filter in oil separator unit Filter & sqs will be inspected FORBES.R | Consumers Power Co 80/06/06 Spp
- 8006240508 Forwards LER 80-018/03L-0 HUSTON/R W Consumers Power Co 80/06/19 ip
- --8006240513 LER 80-018/03L-0 on 800522, during routine testing of hydraulic snubbers, oil level in snubber 2 was found to be loss than zero t was declared inoperable Apparently caused by seal degradation
 4 Consumers Power Co 80/06/19 ip
- DOCKET 50 259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8006040147 Requests 800820-21 meeting to visit technical support ctr, operational support ctr & emergency operations facility re compliance w/NUREO-0654 Public comments will be received at 800521 evening meeting Heeting notice & agenda encl 1PPOLITO,T A Operating Reactors Branch 2 80/05/14 2pp

- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 49 & App R to 10CFRSO & is expected to be published in FR by end or May EISENHUT, D G Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 Fire Protection Program for Nuclear Power Plants Operating Prior to 770101," transmitted by NRC 800519 ltm Page 14a not enci EISENHUT.D G Division of Licensing 80/05/22 73pp Division of Licensing 80/05/22 73pp
- 8005000322 Submits apposition to NAC clarification of emergency planning requirements Locating energency operations facility within emergency planning ione adds to number of people to be evacuated 5 creates weakness inside ione GODWINIA V Alabama. State of 80/05/29 2pp
- 8006050235 Forwards 800521 revisions to training & qualification plan & responses to IRC 800430 comments Encls withheld (ref 100FR2 790)
 HILLS,L H Tennessee Valley Authority 80/06/02 1p
- 800A0A0313 Forwards revisions to safeguards contingency plan Plan withheld (ref 10CFR2 770)
 MILLS.L M Tennessee Vailey Authority 80/06/02 1p
- 8006170803 Requests participation in URC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices.including visit to facility to interview security mgt personnel IPPOLITO.T A Operating Reactors Branch 2 80/06/03 2pp
- P Operating license stage documents & correspondence
- 8006070165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TM1 Action Plan include shift manning licensing erams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT. B G Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose,CA re-confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems 80/05/09 8pp
- 800A130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Rrisctor Coolant Pump Supports "Proposed review procedure & implementation schedule enci EISENHUT.D G Division of Licensing 80/05/19 72pp
- 8006070372 Forwards request for addl info re next round of study for JOHNTONIE RELIABLISTY Evaluation Program Requests 800604 meeting wintil in Betherda.MD to discuss program & potential impact on facility EISENMUT.D G Division of Licensing 80/05/23 5pp
- 8006050177 Notification of 800527 meeting w/util in Bethesda, MD for util presentation of proposed schedule for implementation of major mods required by NRC CLARK, RJ Operating Reactors Branch 2 80/05/27 ip
- B006030394 Notification of 800529 meeting w/util in Bethesda,MD to discuss util proposed design or post-accident sampling facilities CLARK,R J Operating Reactors Branch 2 80/05/27 1p
- 8006110286 Ack receipt of 800425 ltr to HG Parris re effect of dc power supply failure on ECCS performance Response will be provided before 800725 as given verbally to RJ Clart on 800530 MiLLS, L M Tennessee Valley Authority 80/06/03 ip
- 8006300604 Ltr to all SHR licensess forwarding "For Comment" edition of NUREC-0619, "BWR Feedwater Noirle & Control Rod Drive Return Line Noirle Cracking "Comments will be evaluated by NRC prior to final implementation N/O enc! EISENHUT, D.G. Division of Licensing 80/06/05 22pp
- 8006240165 Notification of 800612 meeting w/utils in Bethesda.MD to discuss interim reliability evaluation program OLSHAN.L N Operating Reactors Branch 1 80/06/09 2pp
- 8006230514 Forwards proposed changes to facility Tech Specs per DG Eisenhot 860410 ltm : 100FR50 59 provisions. MILLS,L M Tennessee Valley Authority 80/06/13 2pp

- ---8005230520 Proposed Tech Spec revisions for safety-related sys Change justifications enci * Tennessee Valley Authority 80/06/13 22pp
- 800623043B Forwards info concerning turbine discs per B00516 request Continued operation of facility is justified & OLs should not be modified, suspended or revoted, based on responses DURALL.JR Tennessee Valley Authority B0706/19 10pp
- 8006270269 Forwards response to NRC 800507 ltr re implementation of five addl TMI-2 Lessons Learned requirements concerning shirt manning, licensing eiams, licensee dissemination & small break LOCA general review matters MILLS, L M Tennessee Valley Authority 80/06/23 9pp
- O Inspection reports, IF Bulletins & correspondence
- 8006200098 Forwards IE Circular 80-08, 'BNR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required
 O'REILLY J P Region 2, Atlanta, Orfice of the Director 80/04/19 200
- 8006070058 Forwards IE Sulletin 80-11 "Masonry Wall Design " Requires action & unitten response IE Into Actice 79-28. "Overloading of Structural Elements Due to Pipe Support" encl O'RELLY, J.P. Region 2. Aflanty, Office of the Director 80/05/08 200
- B006040267 Forwards IE Sulletin B0-12, 'Decay Heat Removal Sys
 Operability 'No written response required IE Info Notice
 80-20. "Loss of Decay Heaf Memoval Capability at Davis-Besse
 Unit I While in Refueling Mode" encl
 0'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/09
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lubo Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/05/13
- 8006240160 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/80-19, 50-260/80-14 & 50-296/80-15 LENIS R C Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/06/02 1p
- --8006240164 Responds to NRC 800424 itr re violations nated in IE Insp Repts 50-259/80-19.50-260/80-14 * 50-296/80-15 Corrective actions personnel reminded that procedures must be followed when working on any critical piping sys or equipment MILLS.L M Tennessee Valley nuthority 80/05/20 3pp
- --8006240167 Forwards lE Insp Repts 50-257/80-17.50-260/80-14 5 50-276/80-15 on 800307 0404 'notice of violation LEWIS:R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/24 2pr
- --8006240167 Notice of violation from insp on 800307-0404

 * Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/04/24 ip
- --8006240174 IE Insp Repts 50-259/80-19,50-260/80-14 > 50-296/80-15 on 800307-0404 Noncompliance noted failure to follow procedures in heat-treatment of Unit I HPCI steam piping DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch SULIVAN.R F, CHASE, J U Region 2. Atlanta, Office of the Director 80/04/24 Spp
- 8006240251 Ack receipt or 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80~13, 50-260/80-11 & 50-296/80-12 LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 lp
- --8006240258 Responds to NRC 800423 ltr re violations noted in IE Imsp Regts 50-259/80-13,50-260/80-11 & 50-276/80-12 Corrective actions personnel instructed to keep shift engineer informed of work status & sys status procedure revised MILLB.L M Tennessee Valley Authority 80/05/20 3pp
- --8006240264 Forwards IE Insp Repts 50-259/80-13.50-260/80-11 & 50-296/80-12 on 800204-0307 / notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/23 2pp
- --8006240267 Notice of violation from INSP on 800204-0307 LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch SULLIVAN, J Region 2. Atlanta, Office of the Director. 80/04/29 1p

- --B006240273 IE insp Repts 50-259/80-13,50-260/80-11 % 50-296/80-12 on B00204-0307 Noncompliance noted failure to demonstrate HPCI operable when RCIL was inoperable for maint DARCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN.R Γ, CHASE, J W Region 2, Atlanta, Office of the Director B0/04/23 δρρ
- 8006250135 Ack receipt of 8005d1 ltr inturming NRC of steps taken to correct violations noted in IE lnsp Repts 50-259780-16, 50-260780-13 * 50-296780-14 STO4R.JP Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80706703 ip
- --8006250144 Responds to NPC 800425 iti re violations nated in IE Insp Repts 50-259/80-14,50 240/80-13 % 50-296/80-14 Corrective actions personnel trained on 800416 for emergency director duties % training records corrected MILLS.L M Tennessee Valley Authority 80/05/21 5pp
- --8006250150 Forwards IE Insp Pepts 50~259/80-16,50~260/80~13 & 50~296/80-14 on 800324-28 & 0331 0404 & notice of violation STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/25 2pp
- --8006250155 Notice of violation from this on 800324-28 \$ 0329-0404 # Region 2, Atlanta, Office of the Director 80/04/24 ip
- -8006250165 | E. Insp. Ropts 50-259/80-16, 50-260/80-13 & 50-296/80-14 on 800324-28 % 0329-0404 Moncompliance noted failure to train designated successors to emergency director % to keep training records in order % prepare training procedures JENKINS, G. R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch ANDREWS D. P. PERROTTI, D. J. Region 2. Atlanta, Office of the Director 80/04/24 13pp
- 8006300228 Forwards investigation results in response to IC Bulletin 80-04 Sys mods design changes to other possible actions will be provided in monthly progress repts beginning 800710 Review will be completed by 801101 CROSS.J L Tennessee Valley Authority 80/04/12 Spp
- R Periodic operating reports 8 related correspondence
- 8006170501 Forwards monthly operating repts for May 1980 ABERCROMBIE.H Tennessee Valley Authority 80/06/10 1;
- ---B006170507 Monthly operating repts for May 1980 * Tennessee Valley Authority 60/06/01 32pp
- 5 Reportable occurrences, LFRs / related correspondence
- BOOA030442 Forwards LER 80 0.39/03L-0 CALHOUN, J R Tennessee Valley Authority B0/05/29 ip
- --8006030452 LER 80-038/031-0 on 800430 during normal operation pen for halogen channel on RR-90-250 found downscale Caused by moisture collected in halogen detector Moisture drained Detector dried out No recurrence control planned a Tennessee Valley Authority 80/05/29 2pp
- 800611028/ Forwards LER 60-040/03L-0 CALHOUN, J. R. Tennessee Valley Authority 80/06/04 1p
- --8004110272 (ER 80 040/03L-0 on 800504 during routine startup, valve i-FCV-90-257-A would not fully open after closing Caused by short circuit due to failure of micro switches in valve actuator Switches failed due to condensation in actuator * Tennessee Valley Authority 80/06/04 2pp
- GOOG110269 Forwards LER 80-041/03L-0 CALHOUN, J.R. Tennessee Valley Authority GO/06/05 ip
- --BOO6110280 LER 80-041/031-0 on 800508, during normal operation, smoke detector in reactor bldg alarmed / would not clear Caused by increased detector sensitivity Detector replaced & fire watch established until repairs made / Tennessee Valley Authority 80/06/05 2pp
- 8008200024 Fina) Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities GEAY.J.L. Chemtron Corp., Tube Turns Div. 80/06/06. 3pp
- 8006170566 Forwards suppl to LFR B0~011/017-2 GALHOUN, J R Tennessee Valley Authority 80/06/09 ip

- --8006170575 Suppl to LER Bu-011/01T-2 on 800201, analysis of containment purge & vent sys indicated potential loss of secondary containment Caused by railure or initial plant design to consider LOCA during primary containment purge # Tennessee Valley Authority 80/06/07 2pp
- 8006170635 Forwards LER 80-015/017-1.supplementing 800219 ltr CAMHOUNUUR Tennessee Valley Authority 80/06/09 ip
- ~ 8006170639 LER 80 015/017-1 on 800206, during refueling found two spare unwelded 1-inch lines on penetration Y-49 w/only one manual isolation valve per line external to containment Caused by installation error X-19 line capped & similar lines welded ≠ Tennessee Valley Authority 80/06/09 2pp
- 8006170497 Forwalds LER 86-042/03t-0 CALHOUN, J.R. Tennessee Valley Authority 80/06/10 ip
- --8006170502 LER 80-042/031-0 on 800512. Junit at 96% power.core spray sys I room cooler failed Caused by apparent malfunction of check valves in header Check valves removed, inspected & reinstalled

 4 Tennessee Valley Authority 80/06/10 2pp
- BOO619046B Forwards LER 80-044/017-0 CALMOUN.J R lennessee Valley Authority BO/06/13 ip
- --B006190470 LER B0-044/01T-0 on B00602, while reviewing instrument buses pur IE Bulletin 79-2/, failure of 250 volt do battery board determined to cause feedwater flow to increase to full flow 2 disable feed pump this Caused by power nonseparation * Tennessee Valley Authority B0/06/13 2PP
- 8006300658 EN-80-062 on or about 800618, notice of violation & notice of proposed imposition of civil penalties to be issued to util Action based on alleged item of noncompliance reradiation in excess of limit on transport vehicle BROCKETT, T.W., THOPPSON, D. Office of Inspection & Enforcement, Office of the Director 80/06/16 lp
- DOCKET 50-260 DROWNS FERRY HUCLEAR POWER STATION. UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8006040147 Requests 800520-21 meeting to visit technical support ctr, operational support ctr, operational support ctr, reperational support ctr, recompliance w/NURC9-0654 Public comments will be received at 800521 evening meeting Recting notice & agenda oncl IPPGLITO.T A Operating Reactors Branch 2 80/05/14 2pp
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 100FRBO % is expected to be published in FR by end of May EISENHUT, D G Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 % new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 1tr Page 14a not encl EISENHUT, D © Division of Licensing 80/05/22 73pp
- BOD5050322 Submits opposition to NRC clarification of emergency planning requirements locating emergency operations facility within emergency planning zone adds to number of people to be evacuated & creates weakness inside Ione GODWIN.A V Alabama, State of BO/05/29 2pp
- 8006060235 Forwards 800521 revisions to training & qualification plan & responses to NRC 800430 comments Encls withhold (ref iOCFR2 790)
 MILLS.L M Tennessee Valicy Authority 80/06/02 ip
- 8006060313 Forwards revisions to safeguards contingency plan Plan withheld (ref 100742 790)
 MILLS.L fs. Tonnessee Valley Authority 80/06/02 ip
- 8006170803 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices, including visit to facility to interview security mpt personnel IPPOLITO,T A Operating Reactors Branch 2 80/06/03 2pp

- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI~2 related requirements to operating reactors Licenseas requirements for TMI Action Plan include shift manning, licensing erams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D O Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Merk I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISERMUT, D 0 Division of Licensing 80/05/19 72pp
- 8006050177 Notification of 800529 meeting w/util in Bethesda.MD for util presentation of proposed schedule for implementation of major mods required by NRC CLARK.R J Operating Reactors Branch 2 80/05/27 ip
- B006050394 Notification of 800529 meeting w/util in Bethesda.MD to discuss util proposed design of post-accident sampling facilities CLARKER J Operating Reactors Branch 2 80/05/27 ip
- 8005110286 Ack receipt of 800425 ltr to HQ Parris re affect of dc power supply failure on ECCS performance Response will be provided before 800725 as given verbally to RJ Clark on 800530 MILLS,L H Tennessee Valley Authority 80/06/03 lp
- 800.630.604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT, D G Division of Licensing 80/06/05 22pp
- 8006230514 Forwards proposed changes to facility Tech Specs per DB Elsenhut 800410 ltr & 100FR80 39 provisions MILLS, L M Tennessee Valley Authority 80706/13 2pp
- --8006230520 Proposed Tech Spec revisions for safety-related sys Change justifications encl * Tennessee Valley Authority 80/06/13 22pp
- 800623043B Forwards info concerning turbine discs per 800516 request Continued operation of facility is justified & Olis should not be modified, suspended or revoked based on responses DURALL, J. R. Tennessee Valley Authority 80/06/19 10pp
- 8006270269 Forwards response to NRC 800507 ltm re implementation of five add1 TMI-2 Lessons Learned requirements concerning shift manning licensing exams, licenses dissemination & small break LOCA general review matters MILLS.L M. Tennessee Valley Authority 80/06/23 9pp
- G Inspection reports, IE Bulletins & correspondence
- 8006200098 Forwards IE Circular 80-08, "BWR Tach Spec Inconsistency -Reactor Protection Sys Response Time " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/04/18
- 8006090058 Forwards IE Bulletin 80-11, "Masonry Mall Design " Requires action & unitten response IE Info Notice 79-28, "Overloading of Structural Elements Bue to Pipe Support" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 200
- 8006040267 Forwards IE Bulletin 80-12. Decay Heat Removal Sys
 Operability " No written response required IF Info Notice
 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse
 Unit 1 While in Refueling Mode" encl
 O'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/05/09
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Dil Cooler Failures" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13

- 8006240160 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-19, 50-260/80-14 & 50-296/80-15 LEHIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 tp
- --8006240164 Responds to HRC 800424 ltr re violations noted in IE Insp Repts 50-259/80-19,50-260/80-14; 50-296/80-15 Corrective actions personnel reminded that procedures must be followed When working on any critical piping sys or equipment MILLS.L M Tennessee Valley Authority 80/05/20 3pp
- --8006240167 Forwards lE Insp Repts 50-259/80-19.50-260/80-14 b 50-296/80-15 on 800307-0404 / notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/24 2pp
- ~-8006240169 Notice of violation from insp on 800307-0404 * Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/24 1p
- --8006240174 lE Insp Repts 50-259/80-19,50-260/80-14 \$ 50-296/80-15 on 800307-0404 Noncompliance noted railure to follow procedures in heat-treatment of Unit 1 HPCI steam piping DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN; R F , CHASE, J R Region 2, Atlanta, Office of the Director 80/04/24 5pp
- 8004240251 Ack recoupt o+ 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-13, 50-260/80-11 ½ 50-294/80-12 LEMIS R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 ip
- ---B006240258 Responds to NRC 800423 itr re violations noted in IE Inap Repts 50-259/80-13,50-260/80-11 & 50-294/80-12 Corrective actions personnel instructed to keep shift angineer informed of work status 5 sys status procedure revised MILLS/L M Tennessee Valley Authority 80/05/20 3pp
- --B006240264 Forwards IE Insp Repts 50-259/80-13,50-260/80-11 \$ \$0-296/80-12 on 800204-0307 \$ notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/04/23 2pp
- --8006240267 Notice of violation from insp on 800204-0307 LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch SULLIVAN.J Region 2. Atlanta. Office of the Director 80/04/23 ip
- --8006240273 IE insp Repts 50-257/80-13,50-260/80-11 t 50-296/80-12 en 800204-0307 Noncompliance noted failure to demonstrate HPC1 aperable when RCIC was inoperable for maint DANCE. H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULIVAN,R F, CHASE, J N Region 2, Atlanta, Office of the Director 80/04/23 App
- 8006290135 Ack receipt of 800521 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90~259/80-16, 50~260/80-13 & 50~296/80-14 & 50~260/80-13 & 50~296/80-14 STORR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/03 lp
- --8006250144 Responds to NRC 800425 ltr re violations noted in IE Insp Repts 50-259/80-16.50-260/80-13 & 50-296/80-14 Corrective actions personnel trained on 800416 for emergency director duties & training records corrected MILLS.L M Tennessee Valley Authority 80/05/21 Spp
- --8006250150 forwards IE Insp Repts 50-259/80-16.50-260/80-13 & 50-296/80-14 on 800374-28 % 0331-0404 % notice of violation STORR.J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/75 Rep
- --8004250155 Notice of violation from 1889 on 800324-28 & 0329-0404 * Region 2. Atlanta. Office of the Director 80/04/24 tp
- --8004650165 IE Insp Repts 50-259/80-14.50-260/80-13 & 50-296/80-14 on B00324-28 & 0329-0404 Noncompliance noted failure to train designated successors to energency director & to keep training records in order & prepare training procedures JENKINB, CR Region 2. Atlanta, Fuel Facility & Materials Bafety Branch ANDRENG, D L. PERPUTTI, D J Region 2. Atlanta, Office of the Director 80/04/24 13pp
- 8006300228 Forwards investigation results in response to IE Bulletin 80-05 Sys mods design changes? other possible actions will be provided in monthly progress repts beginning 800710 Review will be completed by 801101 CROES, J.L. Tennessee Valley Authority 60/06/12 Spp

- R Periodic operating reports 5 related correspondence
- 8006170501 Forwards monthly operating repts for May 1980 ABERCROMBIE.H Tennessee Valley Authority 80/06/10 B0/06/10 1n
- --8006170507 Monthly operating repts for May 1780 * Tennessee Valley Authority 80/06/01 32
- S. Reportable occurrences, LERs / related correspondence
- 8004110143 Forwards LER 80-021/031-0 Tennessee Valley Authoraty 80/06/04 ip
- ~-8006110156 LER 80-021/03L-0 on H00506, during routine shutdown, particulate channel 2-RR-90-249 was erratic 2 declared inoperable Caused by failure of iscoler amplifier Amplifier replaced Failure aftitiouted to normal aging * Tennessee Valley Authority 80/C6/04 2pp
- 8006206024 Final Part 21 rept is mixed heat or steel supplied by US Steel from which 4-inch elbows A 2-inch tres were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J L. Chemtion Corp. Tube Turns Div 80/06/06 3pp
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2 & Security, medical, emergency & fire protection plans
- SOO4090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 46 * App R to 10CFR50 * is expected to be published in FR by end of May EISENHUT.D O Division of Licensing 80/05/19 44pp
- 8004130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 1tr Page 14a not encl EISENHUT, D.G. Division of Licensing 80/05/22 73pp
- BOO6200507 Forwards request for add1 info re fire protection program Licensee has yet to meet all administrative control requirements outlined in NRC 800221 ltm Fire brigade drills must be performed in plant to promote teamwork VAROA.8 A Operating Reactors Branch 1 80/06/04 5pp
- BOO6180493 Forwards add1 info to util BOO318 ltr re facility fire protection Add1 info includes insulation of pipes, containment general area, leactor coolant pump bay area, electrical cable penetrations; fire water pipe rupture UTLEY, E.E. Carolina Power 5 light Co. BO/06/12 37pp
- 8006240312 Forwards descriptions of plant emergency ctrs to meet end-of-gr requirements & commitments Util not planning to construct new facilities Existing structures will serve functions UTLEY, E.F. Carolina Power & Light Co. 80/06/18 9pp
- Q Adjudicatory correspondence
- 8006110209 Notice of bithdrawal from proceeding effective 800602 Gertificate of Svc encl LENIS:S H Hearing Branch 2 80/05/10 2pp
- I Financial information
- 8006120011 Responds to 800508 request for comment on util 8-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial infofiled w/NRC CHRISTENBURY, E Hearings Division 80/05/29 ip
- P Operating license stage documents & correspondence
- 8004090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. Inccnsing erams & incensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Youghness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enct EISENHUT, D Q Division of Licensing 80/05/19 72pp

- 8006190126 Responds to 800318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concul w/util approach Procurement of spane or replacement parts subj to GA controls HAASS/N P Quality Assurance Branch 80/05/23 2pp
- 80062600B0 Recommends that util establish common baseline for future surveillance tests Util 770909 ltr 2 790814 suppl providing test results showed lack of continuity among individual tests Past concerns re structural integrity satisfied VAROA:8 A Operating Reactors Branch 1 80/05/30 2pp
- 8006090310 Forwards util responses to NRC 800207 questions re dedicated shutdown sys Graphs & fire protection drawings encl
 UTLEY/E E Carolina Power & Light Co 80/06/02 34pp
- BOO6200523 Forwards comments re proposed amend to Tech Specs re radiological effluent & environ monitoring sys Changes are to be incorporated into proposed Tech Specs Requests process control program for solidification of radioactive wastes VARGA:S A Operating Reactors Branch 1 80/06/02 86pp
- 8006230008 Discusses NRC generic review of secondary sys fluid flow instabilities at nuclear plants & associated util 750723, 780102 & 790918 ltrs Forwards safety evaluation re steam generator water hammer VAROA.S A Operating Reactors Branch & 80/06/02 2pp
- --8006230012 Safety evaluation re steam generator water hammer Potential for steam generator water hammer is sufficiently low to permit continued operation Auxiliary feedwater flow should be limited to 400 ppm * Dffice of Nuclear Reactor Regulation, Director 80/03/31 4pp
- 8006230017 Forwards request for addl info re adequacy of station electric distribution sys voltages based in NRC review of util 791003 \$ 05 ltrs Requests response within 45 days VARGA.B A Operating Reactors Branch 1 B0/06/02 5pp
- 8006160058 Responds to NRC 800506 ltr re loss of offsite power survey Sixty-day extension requested to review historic files associated w/transmission says Total response to survey should be completed by 800808 UTLEY
- BOD6180491 Responds to NRC BOD307 generic ltr re second set of TMI-related requirements for operating reactors Licensee can meet all requirements except Item I A 1 3, shift manning, for which 30-day extension is requested UTLEY.E E Carolina Power & Light Co 80/06/11 3pp.
- BOOÁ180361 Forwards evaluation of postulated tornado plus single active failure to capacity of auriliary feedwater sys Oversize drawing available in Central Files only UTLEY,E E Carolina Power & Light Co BO/06/12 App
- 8006230396 Application for amend to License DPR-23.revising containment purge & vent valve closing time Class III fee encl
 UTLEY.E E Carolina Power & Light Co 80/06/20 2pp
- --8004230398 Revised Tech Specs re containment purge & vent valve isolation time
 * Carolina Power & Light Co EO/06/20 900
- Q Inspection reports: IE Bulletins & correspondence
- 8006020002 Forwards licensee response to deviation noted in IE Insp Rept 50-261/79-29 Arrangement of control & sectional control valves does not meet applicable sections of NEPA Stds & Code MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/03/11 ip
- 8004130389 Forwards IE Insp Rept 50-241/80-07 on 800331-0403 No NOLISUARY Formands in 18th Rept Surgaryout, an Success of the noncompliance noted
 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch 80/04/29 2pp
- --8006130391 IE Insp Rept 50-261/80-07 on 800331-0403 No noncompliance noted Major areas inspected operations, LERs & IE Bulletin 79-018 KELLOBORP J Region 2. Atlanta, Reactor Operations Nuclear Support KELLDGO.P J Region 2. Atlanta, Reactor Operations Nuclear Support Brench BAUER.R C Region 2. Atlanta, Office of the Director 90/04/28 Spp

- 8006060583 Forwards IE Bulletin 80-11, 'Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY.J P Region 2. Atlanta. Orfice of the Director 80/05/08 2pp
- 800&050289 Forwards 1E Bullotin 80-12, "Decay Meat Removal Sys Operability " Requires action % response within 30 days 1E Info Notice 80-20, 'Loss of Decay Heat Removal Capability at Davis-Besse Unit ! While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 2pp
- 8006300128 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 Zon
- B006190672 Responds to IE Builetin B0-12, "Decay Heat Removal Sys Operability " Operator training util include review of loss of decay heat removal incident Hardware, administrative controls & safeguards are adequate FURR.B J Carolina Power & Light Co B0/06/03 2pp
- 8006250301 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Review & actions taken satisfy concerns of bulletin FURR.8 J Carolina Power & Light Co 80/06/10 2pp
- 8006240438 Notifies of new target dates for completion of Open Item 79-19-09 of IE Insp Rept 50-261/79-19 Revision to both calibr programs will be completed by 800730 Revisions to implementing procedures will be completed by 801231 STARKEY.R B Carolina Power & Light Co 80/06/24 ip
- R Periodic operating reports & related correspondence
- 8005160025 Forwards monthly operating rept for May 1780 STARKEY,R B Carolina Power シ Light Co 80/06/10 19
- --8004160026 Monthly operating rept for May 1980 WATFORD M Carolina Power & Light Co 80/06/03 4pp
- S Reportable occurrences, LERs & related correspondence
- 8006050374 RD on 800517, while operating at 407 reactor power level, power range high flux setpoint was not properly reset during quadrant power tilt greater than 2% Cause under investigation Setpoint reset & unit returned to operation STARKEY, R B Carolina Power & Light Co 80/05/19 ip
- 8004050328 Forwards LER 80-013/03L-0 8TARKEY: R B Carolina Power & Light Co 80/05/30 1p
- --8006050332 LER 80-013/03L-0 on 800517.while operating at 40% reactor power.radial tilt greater than Tech Spec limit was calculated w/o resetting power range high flux setpoint Caused by misinterpretation of Tech Specs Setpoints reset STARKEY, R B Carolina Power & Light Co 80/05/30 Jpp
- 8006050362 Forwards replacement to Attachment 3 to steam generator insp & safety evaluation rept submitted on 800427 Add1 tube added to 11st & three errors corrected UTLEY.E E Carolina Power & Light Co 80/06/02 12pp
- 8006110347 Forwards LER 80-012/03L-0 STARKEY,R B Carolina Power & Light Co 80/06/05 Ip
- ---8006110358 LER 80-012/03L-0 on 800506.while operating at 93% power, nuclear instrumentation runback occurred Control fuses blow on NIB power range detector N-42 Caused by faulty NIS circuit from detector N-42 Caused by Faulty NIS circuit from detector N-42 Failed detector replaced STARKEY.R B Carolina Power & Light Co 80/06/05 2pp
- 8006230572 Forwards updated LER 80-013/01T-1 STARKEY.R B Carolina Power % Light Co 80/06/18 1p
- ---8006230584 Updated LER 80-013/017-i on 800517.while operating at 40% power.radsal tilt calculated greater than Tech Spec limit Caused by personnel incorrectly interpreting requirements Personnel will be made aware of correct interpretation STARKEY, R B Carolina Power & Light Co 80/06/18 3pp

- DOCKET 50-243 MONTICELLO NUCLEAR GENERATING PLANT

 F Security, medical, emergency % fire protection plans
- 8006020231 Notifies that new telephone sys called Health Physics
 Network (HPN) has been installed at site Sys intended for
 use during emergencies to link all power plants & NRC
 Emergency Notification Sys hotline will also be used
 KEPPLER.J O Region 3. Chicago. Office of the Director 80/04/18
- 8004070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 'App R to 10CFR50 t is expected to be gublished in FR by end of May EISENHUT. D © Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 b new Page 14a for proposed rule 100FR50 "Fire Profection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISERNUT, D 6 Division of Licensing 80/05/22 73pp
- 8006020334 Requests add1 time for completion of fire protection mod Completion date of 800930 has been established for fire detector-related installation; testing MAYER L 0 Northern States Power Co 80/05/23 lp
- 8006190176 Provides info re access of MRC & MRC contractor personnel to facility for appraisal of health physics program Personnel list encl
 KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/27
- 8006120433 Forwards status summary of open issues from 790829 fire protection sarety evaluation Subject to implementation of encl requirements.util proposed resolutions are acceptable Suppl to safety evaluation will be issued IPFOLITO.T A Operating Reactors Branch 2 80/05/28 5pp
- 800619010B Forwards BNL evaluations of submittals re open issues associated w/fire protection SER IPPOLITO T A Gertating Reactors Branch 2 B0/06/04 3pp
- 8006230221 Forwards comments on safeguards contingency plan indicating need for revisions E addi into Response must be provided within 60 days Comments withheld (ref 10CFR2 790) IPPOLITO.T A Operating Feactors Branch 2 80/06/04 3pp
- 8005230374 Forwards draft input to facility fire protection safety evaluation re Items 3 1 10A3, control of combustibles & 3 1 2 (3), automatic water suppression sys Recommends accepting sys controls if control valves supervised HALL:R E Brookhaven National Laboratory 80/G6/13 3pp
- B006230337 Discusses submittal of final upgraded emergency plans Extension may be necessary, depending on content of pending NRC rules on emergency plans Schedule for emergency plan revisions targeted to meet 800801 submittal date MAYER.L. 0 Northern States Power Co 80/06/17 ip
- 8006240266 Advises of intention to leave hoses connected to hydrants in hose houses effective 800801 Proposed change will reduce time required to set up station in preparation for fire fighting

 MAYER.L D Northern States Power Co 80/06/18 1p
- G Adjudicatory correspondence
- 8006110023 Notice of withdrawal from proceeding effective B00602 Certificate of Svc encl LEWIS.5 H Hearing Branch 2 80/05/03 3pp
- P Operating license stage documents & correspondence
- 8006180101 Decommissioning study of Prairie Island Nuclear Generating Plant, Revision 1 JAMORSKY, M J Nuclear Energy Service, Inc 81A0623 R1 79/09/28 67pp
- --8094180108 Decommissioning study of Monticello Nuclear Generating Plant.Revision 1
 - * Nuclear Energy Service, Inc 81A0622 R1 79/09/28 48pp

1

- 8004090165 Forwards, add1 THT-2 related requirements to operating reactors Licensees requirements for TM1 Action Plan include shift manning, livensing evams 2 licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D.C. Division of licensing 80/05/07 150pp
- 8004030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-teim program GRIMES, C. I. Assistant Director for Plant Systems 80/05/09 Bpp
- BOO6130)2P Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamella: Tearing on FWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enc] EIBENHUT D G DIVISION of Licensing 80/05/19 72pp
- 8006020161 Summary of 800430 meeting w/util.GE ? NUTECH in Bethesda.MD re replacement of feedwater rozile safe ends NRC concluded that proposed mod w/other measures taken by licensee should prevent excessive clack instit
- 8006050247 Forwards evaluation of effects of dc power supply failure on ECCS in response to NRC 800425 request Evaluation is being expanded to consider loss of equipment due to water spillage ECCS equipment list will be submitted by 800830 MAYER.L O Northern States Power Co 80/05/30 2pp
- 8006190186 Responds to 800319 ltr requesting info re facility to update MN Pollution Control Agency files Lists licensee amend requests A disposition of each IPPOLITO.T A Operating Reactors Branch 2 80/06/03 2pp
- 8004090298 Forwards design info for high-range noble gas effluent & containment radiation monitors in response to NRC 791030 ltr 7MI Task force Short-Term Recommendation 2 | 8 b MAYER,L O Northern States Fower Co 80/06/05 7pp
- BOOAGOOAO4 Ltr to all BUR licensees forwarding "For Comment" edition of NURCG-0619, 'GUR feedwater Noizle & Control Rod Drive Return Line Noizle Clacking "Comments will be evaluated by NRC prior to final implementation M/o encl EISENHUT.D O Division of Licensing BO/06/05 22pp
- 8006170429 Forwards response to four of five new TMI-2 requirements identified in NRC 800507 ltr includes items re licensing erams, operating experience feedback. Bulletins & Ordons Task Force final recommendations & Control room habitability MAYER, L D Northern States Power Co 80/06/11 12pp
- 8006200373 Informs NRC that util intends to use REDY, transient licensing abalysis code, for Cycle 9 analyses Requests that util be notified by 800701 if course of action is incorrect MAYER.P C Northern States Power Co 80/06/16 1p
- 8006230437 Forwards response to NRC 800516 ltr requesting info re turbine disc cracking Response includes site-specific technical datarinsp inforwater chemistly results & generic info No stress correston cracking observed at site MAYER.L O Northern States Power Co 80/06/18 6pp
- Q Inspection reports, 1E Bulletins & correspondence
- 800620010B Forwards It Circular 80-0B, "BWR Tech Spec Inconsistency Reactor Protection Bys Response Time " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18 ip
- 8006180070 Forwards IE Insp Rept 50-269/80-04 on 800221-22 & 0327-28 No noncompliance noted DAVIS.A B. Region 3. Chicago, Fuel Facility & Materials Bafety Bran.h 80/04/29 2pp
- --B0061B0075 IE Insp Rept 50-263/80-04 on B00221-22 & 0327-28 No moncompliance noted Major areas inspected operational radiation protection program during refueling & maint, including organization & staffing & sposure control HUETER.L J Region 3, Chicago, Office of the Director FISHER.W L. Region 3, Chicago, Fuel Facility & Materials Bafety Branch B0/04/22 Bpp
- BOO6090453 Forwards IE Insp Rept 50-263/80-07 on 800319-21 & 0407-11 No honcompliance noted HEISHKAN:R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/05/05 2pp

- --B00609046: IE Insp Rept 50-263/80-07 on B00319-21 % 0407-11 No noncompliance noted Major areas inspected plant operations small break LOCA procedures, fire protection, IE Bulletins B0-03, 79-28, 78-10 f IE Circular 79-17 WARNICK, R F , BROUNC C, CHOULES, N Region 3, Chicago, Office of the Director B0/05/02 7pp
- 8006160245 Forwards Waste Packaging Insp Rept 60-08 on 800303 & notice of violation DAVIS,A B. Region 3. Chicago: Fuel Facility & Materials Safety Branch 80/05/08 2pp
- ~-8006160248 Notice of violation on 800303

 * Region 3, Chicago: Office of the Director 80/05/08 1p
- --8006160257 Waste Packaging Insp Rept 80-08 on 800303 Noncompliance noted failure to mark cask used to transport radwaste FISHER,N L Region 3, Chicago, Fuel Facility & Naterials Safety Branch PECK,C C Region 3, Chicago, Office of the Director 80/05/08 2pp
- R Periodic operating reports & related correspondence
- 8006060376 Forwards Revision 1 to monthly operating rept for Apr 1980 MAYER.L O Northern States Power Co 80/06/02 ip
- --8006060378 Monthly operating rept for Apr 1980.Revision 1 MYRABO, A L. Northern States Power Co. BO/05/27 1p
- 8006130265 Forwards monthly operating rept for May 1980 MAYER.L O Northern States Power Co 80/06/09 1p
- ~~8006130267 Monthly operating rept for May 1980 MYRABO.A L. Northern States Power Co. 80/06/03 4pp
- S Reportable occurrences, LERs & related correspondence
- 8006050375 Forwards updated LER 79-019/03L-1 MAYER: L O Northern States Power Co 80/06/02 1p
- --8006050378 Updated 79-015/03L-1 on 790712, during routine insp.steam leak from 13A intermediate pressure feedwater heater was detected Insulation removal revealed through-wall flaw in heater shell Caused by erosion-carrosion HAMMER.B J Northern States Power Co 80/06/02 ip
- 8006200466 Forwards LER 80-021/03L-0
 MAYER, L Q Northern States Fower Co 80/06/12 in
- ---8006200472 LER 80-021/03L-0 on 800515, during normal startup, reactor core isolation cooling control power fuse opened Caused by shorted relay coil in circuit due to ac relay inadvertently installed by maint personnel Relay replaced OVERLID.T W Northern States Power Co 80/06/12 ip
- DOCKET 50-264 DOW CHEMICAL CO
- Γ Security, medical. emergency & fire protection plans
- 8006190582 Responds to NRC 800507 ltr re Dow Chemical Co TRIDA reactor facility honpower reactor physical protection requirement Response not received re Dow TRIOA 781005 security plan Security plan meets 790724 & 800325 FR rules & regulations LANGNER, R R Dow Chemical Co , Dow Chemical U S A Div 80/06/09 ls
- P Operating license stage documents & correspondence
- 8006200539 Advises that DNS-RSS-001-P, "Topical Rept, Dow Sys for Solidification of Low Level Radwaste from Nuclear Power Plants," & Amend 1 to ropt have been determined proprietary & will be withheld from public disclosure MILLER, L R Standardization & Special Projects Branch 80/05/23 200
- DOCKET 50-265 BUAD-CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Bys intended for use during emergencies to link all power plants & NRC Emergency Notification Bys botline will also be used KEPPLER. J Q Region 3. Chicago, Office of the Director 80/04/18 2pp

- 8006090497 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 % App R to 10CFR50 % is expected to be published in FR by end of May EISENHUT, D O Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 1tr Page 14s not encl EISENHUT.D C Division of Licensing 80/05/22 73pp
- 8006090018 Forwards request for add1 info needed for review of safeguards contingency plan Requests add1 info be submitted within 30 days of receipt of itr Encl withheld (ref 10CFR2 790)

IDPOLITO, T A Operating Reactors Branch 2 80/05/27 20p

- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also entl PEOPLES.D L. Commonwealth Edison Co. 80/06/04 2pp
- --800ái80347 Revision i to draft emergency plan * Commonwealth Edison Co 80/07/31 139pp
- 8006170559 Forwards drawings & responses to questions re fi protection safe shutdown analysis, requested in NRC 791022 ltr
- TANECEK, R F Commonwealth Edison Co. 80/06/06 5pp
- --8006170564 "Single Line Diagram Emergency Power Sys "
 * Sargent & Lundy, Inc 76/06/30 to
- --8006170591 "Schematic Control Diagram Engine Control & Generator Excitation, Standby Diesel Generator 1 & 2 " * Sargent & Lundy, Inc. 79/10/01 ip
- -~8006170597 "Schematic Control Diagram Engine Control & Generator Excitation, Standby Diasel Generator 2 " * Sargent & Lundy, Inc 76/07/07 ip
- 800&240490 Responds to NRC 800425,30,0501.09 & 20 ltrs requesting additing one guard training & qualification plans Requests that response submittal date be extended to 800804 PEOPLES, D.L. Commonwealth Edison Co. 80/06/18 ip

- 800&1200B2 Responds to 800&15 ltr requesting response to J Smith concerns re raduaste dumping at facility Radwaste produced as result of plant operation shipped offsite for burial at licensed burial site
 DIRCKS,W J Office of the Executive Director for Operations 80/05/28 ip
- ---8004120084 Requests response to encl J Smith 1tr re radwaste dumping at facility
 RAILEBROK.T House of Rep. 80/04/15 2pp
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMI-2 related requirements to uperating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT,D 0 Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark 1 cuners group in San Jose CA re confirmatory analysis & tosting programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PUR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enc! EISENHUT.D 0 Division of Licensing 80/05/19 72pp
- BO06030062 Application to amend Licenses DPR-2.DPR-19, DPR-25, DPR-29 & DPR-30, clarifying term "operable." submitted as Tech Spec change request in response to ARC B00410 ltr NAU0HTUH. W F Commonwealth Edison Co 80/05/30 2pp

- --8006030072 Tech Spec change request for Tech Specs Sections 1 0-1 2.2 (\$2.3 0.5 0 \$6 0-6 6 re definitions, administrative controls, safety limits, limiting safety sys setting & limiting conditions for operation # Commonwealth Edison Co 80/03/30 42pp
- 8006200162 Forwards corrected Tech Spec pages inadvertently omitted from substitute pages sent IPPOLITO.T A Operating Reactors Branch 2 80/05/30 1p
- --8006200168 Tech Spec Pages 1 1/2 1-4,1 1/2 1-9,1 2/2 2-2 % 3 3/4 3-10 re safety limit basis, scram insertion & reactor low water level stram, inadvertently omitted from Amend 51 * Commonwealth Edison Co 80/05/30 4pp
- 8006300604 Ltr to all SWR licensees forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzle % Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation N/o encl EISENKUT.D © Division of Licensing 80/06/05 22pp
- 8006190456 Forwards verification of analysis program used for determining voltages for facility electric distribution sys per 79080B request JAMECEKAR F Commonwealth Edison Co 89/06/11 3pp
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltr re add1 TMI-2 related requirements Dresden Unit 1 is currently undergoing extensive mod & decontamination, therefore no response is provided PEOPLES.D & Commonwealth Edison Co 80/06/12 10pp
- 8006190419 Confirms availability of ECCS equipment following dc power supply failure.per 800425 request Mods to ensure availability of HPC1 following dc power failure completed at Dresden % in progress at Guad Cities

 JANECEK.R F Commonwealth Edison Co 80/06/12 2pp
- 8006270273 Forwards "Cycle 5 Startup Test Results " JANECEX.R F Commonwealth Edison Co B0/06/19 1p
- ~-8006270277 "Cycle 5 Startup Fest Results "
 # Commonwealth Edison Co 80/06/19 10pp
- 8006250277 Forwards responds to NRC 800516 ltr requesting info re turbine disc cracking Stress corrosion cracks not observed to date JANECEKIR F Commonwealth Edison Co 80/06/23 16pp
- 8006270306 Forwards revised Revisions il & 12 consisting of Page 1-7 of CE-i-A, "Comm Ed QA Program for Nuclear Generating Stations" Revised Revision II includes basis on which equivalent education requirements will be established PEQPLES;D L Commonwealth Edison Co 80/06/23 lp
- 9 Inspection reports, IE Bulletins & correspondence
- 8008200110 Forwards IE Circular 80-08, 'BWR Tech Spec Inconsistency ~ Reactor Protection Sys Response Time " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18 is
- 8006020185 Forwards IE Insp Repts 50-254/80-07 & 50-265/80-10 on 800325-27 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/04/23 2pp
- --8006020192 IE Insp Repts 50-254/80-07 % 50-245/80-10 on 800325-27 No noncompliance noted Major areas inspected environ protection program, environ monitoring program & confilmatory measurements of radiological effluents ESSIG, T H, GRANT, H B, LDVENDALE, P C Region 3, Chicago, Office of the Director 80/04/17 App
- 800&020082 Forwards IE Insp Rept 50-265/80-11 on 800312-13,26-28,0403-04 & 11 No moncompliance noted FIORELLI,G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- ---B006020087 IE Insp Rept 50-265/80-11 on 800312-13,26-28,0403-04 & 1;
 No noncompliance noted Major areas inspected core spray sys
 repair procedures, welding 2 personnel & mat1 certifications
 DANIFLSDN.D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch KEY, W J Region 3, Chicago, Office of
 the Director 80/04/22 App

- 8006170268 Forwards IE Insp Repts 50-254/80-09 & 50-265/80-12 on 800401-02 No noncompliance noted HEISHMAN R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/01 2pp
- --B006170276 IE Insp Repts 50-254/80-07 & 50-265/80-12 on 800401-02 No noncompliance noted Major areas inspected initial training & retraining of licensed & nonlicensed personnel & licensed operator requalification training SMANSON,F R Region 3. Chicago, Office of the Director JACKIN I N Region 3. Chicago Reactor Operations Nuclear Support Branch 80/04/29 3pp
- 8006230075 Forwards IF Insp Repts 50-254/80-10 & 50-265/80-13 on 800327-0507 No noncompliance noted HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/16 2pp
- --8006230078 IE Insp Repts 50-254/80-10 & 50-265/80-13 on 800327-0507 No noncompliance noted Major areas inspected operational safety, long-term shutdown, maint & surveillance SPESSARD, R. L. CHRISSOTIMOS, N. Region 3, Chicago, Office of the Director 80/05/15 Spp
- 8006020008 Responds to 1E Bulletin 79-26 Dresden Unit 2 is only facility requiring shutdown margin penalty for postulated B4C leaching Control blade exposures will be monitored during cycles to verify projected end-of-cycle exposure PEOPLES.D L Commonwealth Edison Co 80/05/19 2pp
- 8006300558 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls "Proposed mods identified only if present sys design may compromise protective action of equipment PEOPLES.D L. Commonwealth Edison Co. 80/06/10 7pp
- R Periodic operating reports & related correspondence
- 8006110078 Forwards monthly operating repts for May 1980 KALIVIANAKIS,N Commonwealth Edison Co 80/05/30 ip
- 8006110034 Forwards list of mods, tests & experiments completed during May 1980 & summary of safety evaluations KALIVJANAVIB.N Commonwealth Edison Co 80/06/02 2pp
- S Reportable occurrences, LERs & related correspondence
- BOOGLICERO Forwards LER 80-012/03L-0
 KALIVIANAKIS,N Commonwealth Edison Co BO/05/27 1pp
- ---9004110330 LER 80-012/03L-0 on 800428, reactor water conductivity exceeded 10 umhos/tm Tech Spec limit Caused by depleted demineralizers Unit shutdown initiated Demineralizers regenerated & low conductivity coolant added to reactor VAHRENWALD.J Commonwealth Edison Co. 80/05/27 2pp.
- 8006110363 Forwards LER 80-013/03L-0
 KALIVIANAKIS,N Commonwoalth Edison Co 80/05/27 1p
- --8006110367 LFR 80-013/03L-0 on 800428, while performing LPCI motor operated valve operability test & RHR to suppression chamber test, cooling valve MC 2-1001-36A failed to close Caused by binding of plunger arm on auxiliary interlock contacts MURRAY.R Commonwealth Edison Co 80/05/27 2pp
- BO06270266 Forwards LER 80-010/03L-0 KALIVIANAKIS.N Commonwealth Edison Co 80/06/10 ip
- --B006270272 LER B0-010/03I-0 on B00517.while performing quartierly MSIV closure timing surveillance procedure QOS 250-4.MSIV AD 2-203-1C closed in 2 5-s & MBIV AD 2-203-2D closed in 7 1-s Caused by equipment failure Speed control valves adjusted STEFFES.C Commonwealth Edison Co 80/06/10 2pp
- BOO6300330 EN-80-25 notice of violation & notice of proposed imposition of civil penalty will be issued on or about BOO620 Action based on noncompliance re external radiation levels on yehicle exceeding limits Will issue press release BROCKETT.T W., THOMPBON.D. Office of Inspection & Enforcement. Office of the Director 89/06/18 ip

- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- BOOGO30177 Natifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D G Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENMUT.D 0 Division of Licensing 80/05/22 73pp
- 8006300452 Forwards add1 info re design of fixed water suppression system fire hydrant insps & control room light fixtures for fire protection safety evaluation Notification requested by 8007181 if design mods are required FAY.C W Wisconsin Electric Power Co 80/06/23 iBpp
- Q Adjudicatory correspondence
- B004030289 Request for hearing on B00404 mod of 791130 order re resumption of operation despite continued existence of steam generator corrosion processes Asserts American Physical Bociety gosition re serious safety problem FALK.K M. Wisconsin's Environmental Decade 80/05/29 2pp
- 8006170399 Response in opposition to WI Environ Decade, Inc 800529 request for hearing re steam generator tube degradation Intervenar repeated claims before ASLB & failed to establish interest re mod to confirmatory order W/Certificate of Svc CHARNOFF, G, O'NEILL, J H Wisconsin Electric Power Co CHARNOFF, G Shaw, Pittman, Potts & Trowbridge 80/06/12 7pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D O Division of Licensing 80/05/07 150pp
- 8004040060 Notifies that facility will use Chem Nuclear, Inc Model CNB 6-80-2 radioactive shipping cask for delivery of matls to carrier FAY, C W Wisconsin Electric Power Co 80/05/14 ip
- 8006130122 Requests comments on NUREQ-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on FWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D @ Division of Licensing 80/05/19 72pp
- 8006170244 Forwards Amends 45 & 90 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 80/05/20 Spp
- ---8006170249 Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively, incorporating Tech Specs contained in Apps A & B in license Amends add limiting conditions for operation & surveillance requirements for low temp mitigating sys CLARK,R A Operating Reactors Branch 3 80/05/20 36pp
- --8006170253 Safety evaluation supporting Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively ** Office of Nuclear Reactor Regulation, Director 80/05/20, 12pp
- --8006170256 Notice of issuance & availability of Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively CLARK,R A Operating Reactors Branch 3 80/05/20, 2pp.
- BOO6130037 Forwards safety evaluation supporting design aspects of containment purge valve isolation override & other engineered safety feature actuation signals except radiation monitors which initiate containment purge isolation CLARK.R A Operating Reactors Branch 3 BO/05/22 2pp

- --B006130039 Safety evaluation supporting design aspects of containment purge valve isolation override 8 other engineered safety feature actuation signals except radiation monitors which initiate containment purge isolation # Operating Reactors Branch 3 B0/05/22 ip
- --8004130040 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override Containment Purge Valve Isolation & Other Engineered Safety Feature Signals for Point Beach Nuclear Power Station, Units 1 & 2 "
 HACKETT, D.B. EGVO, Inc. FIN A-0231 EG01183-4139 79/09/30 16pp
- 8006030344 Forwards description of proposed mode to instrument bus power supplies, in response to NRC 800421 ltr Mode will be completed by 810101 Diagram of proposed supply sys to white & yeslow instrument busses enci FAY.C W Wisconsin Electric Power Co 80/05/27 4pp
- 8006110279 Ack receipt of 800516 itr requesting that samples of steam generator tubes be provided to J Weeks at BNL Directed principle consultant. Westinghouse, to provide samples & deal w/J Weeks directly,
 FAY, C H Hisconsin Electric Power Co 80/06/02 ip
- BQ06110129 Advises that util is forwarding, under separate cover, set of piping b instrumentation diagrams for plant Listing of diagrams also forwarded u/package FAY.C W Wisconsin Electric Power Co 80/06/04 ip
- 8006120307 Discusses NUREG/CR-1280 re power plant staffing Util has neither unlimited funding nor unlimited supply of people to implement sys which Navy has developed Lists TMI-related aspects which have been overlooked

 SUTTNER, T A Affiliation Unknown 80/06/09 App
- 8006180555 Withdraws 800514 request for NRC contractor to visit factlity to perform interviews & other activities associated w/NRC contract Util 800527 ltr requested postponement or cancellation of visit due to high level of plant activities HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/05 ip
- --8005180558 Responds to 800514 request that NRC contractor be allowed to visit facility to meet w/training staff & test emergency procedures Requests postponement or cancellation of visit due to high level of activities at plant 8URSTEIN.S Wisconsin Electric Power Co 80/05/27 2pp
- 8006200460 Forwards response to NRC 800507 ltr re five add1 TMI-2 related requirements for operating reactors Assumes that implementation of add1 requirements was not meant to impede completion of previous commitments

 FAY.C W Wisconsin Electric Power Co 80/96/11 8pp
- G Inspection reports, IE Bulletins & correspondence
- B006180574 Forwards IE Insp Repts 50~266/80-07 & 50-301/80-06 on B00408-10 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/05/02 2pp
- --8004180581 IE Insp Repts 50-264/80-07 / 50-301/80-04 on 800408-10 No noncompliance noted Major areas inspected radiation protection program associated w/refueling outage,including radiation protection grocedures & training exposure control MILLER,D E., LOVENDALE.P.C. Region 3. Chicago, Office of the Director FISHER,W.L. Region 3. Chicago, Fuel Facility & Materials Safety Branch 89/04/28 7pp
- 8008200272 Forwards IE Insp Repts 50-266/80-09 % 90-301/80-08 on 800310-14 % 0408 % noncompliance noted HEISHMAN R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/14 2pp
- --8006200280 IE Insp Repts 50-266/80-09 & 50-301/80-08 on 800310-14 & 0408 No noncompliance noted Major areas inspected plant procedures & operator training On 800408 meeting was held to review plant performance WARNICK, R.F. SMITH, J.D., REIMANN, F.W. Region 3, Chicago, Office of the Director 80/05/16 5pp
- 8005090034 Forwards proprietary response to IE Insp Repts 50-264/80-06 & 50-301/80-05 Revision to modified amended security plan withheld (ref 10CFR2 790) BURSTEIN.S Wisconsin Clettric Power Co 80/05/29 2pp
- B006190550 Responds to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies" No safety-related sys os component uses AH-90 or NH-90 series hydramotor actuator FAY.C W Wisconsin Electric Power Co 80/05/29 Ip

- 8006300262 Responds to 1E 3011etin 80-12. "Decay Heat Removal Sys Operability " Plant design does not provide for automatic actuation of ECCS recirculation or automatic positioning of containment recirculation sump valves FAY.C W Wisconsin Electric Power Co 80/06/05 2pp
- 8006200541 Ack receipt of 800529 ltm informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-266/80-06 & 50-301/80-05 Hitle, J A Region 3, Chicago. Safeguards Branch 80/06/10 1p
- --8006200547 Responds to IRC 800502 ltr ia violations noted in IE Insp Repts 50-266/80-06 % 50-301/80-05 Corrective actions withheld (ref 102FP2 790) BURSTCIN.S Wisconsin Electric Power Co 80/05/29 ip
- 8006230038 Forwards IE Insp Repts 50-266/80-08 & 50-301/80-07 on 800519-23 No noncompliance noted HIMD, J.A. Region 3, Chicago, Safeguards Branch 80/06/10 2pp
- --8006230043 IE Insp Repts 50-265/80-08 & 50-301/80-07 on 800519-23 No noncompliance noted Major areas inspected mati control & accountability.organization.measurement & control storage & inventory Rept details withheld (lef 100FR2 790) HIMD-J A Region 3. Chicago, Safeguards Branch FINLEY, A G . PATIERSON, J P Region 3. Chicago Office of the Director 80/06/10 ip
- R Periodic operating reports > related correspondence
- 8006170473 Forwards monthly operating lepts for May 1980 FAY,C W Wisconsin Electric Power Co 80/06/10 1p
- --8006170477 Monthly operating repts for May 1980 FAV.C W - Wisconsin Electric Power Co - 80/06/05 - 9pp
- S Reportable occurrences. LERs & related correspondence
- 8006110149 Forwards LER 80-005/03L-0 FAY, C W Wisconsin Electric Power Co 80/06/02 1p
- ~-8006110161 LER 80-005/03L-0 on 800417 during normal operation, review of security logs revealed that designated fire brigade was below min supervision requirements on three occasions Caused by operations personnel designation error FAY.C W Wisconsin Flectric Power Co. 80/06/02 2pp
- V Operator Examinations
- 8005110271 Requests concurrence that operating training program is equivalent to extra man concept or background studies to justify arbitrary requirement Reply requested by 800701 FAY.C W Wisconsin Electric Power Co 80/06/04 2pp
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

 E NRC Safety Evaluation Report (SER), supply & correspondence
- 8006200626 Forwards safety evaluation of facility accident reanalyses in support of full power operation Reanalyses results are acceptable to justify full power operation provided that noted conditions are met DENISE.R P Assistant Director for Core 9 Containment Systems 80/04/20 ip
- --B006200627 Sarety evaluation of facility accident reanalyses in support of full power operation Reanalyses results are acceptable to justify full power operation provided that noted conditions are met * Assistant Director for Core & Containment Systems B0/04/30 19pp
- F Security, medical, emergency & fire protection plans
- 8008020541 Provides info re NRC contractor personnel who are likely to Visit facility w/NRC personnel to appraise health physics program Unsite phase is scheduled for approx 2 wks beginning 800816 List of contractor personnel encl W/o encl SEYPRIT, K V Region 4, Dailas, Office of the Director 80/05/19 in
- 800&030485 Forwards security plan mods re tables of changes & contents Plan withheld (ref 10CFR2 790) WAREMBDURG.D W Public Service Co of Colorado 80/09/19 3pp

- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 1006850 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, B G Division of Licensing 80/05/22 73pp
- P Operating license stage documents & correspondence
- 9006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams? licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D.G. Division of Licensing 80/05/07 190pp
- BOO6130122 Requests comments on NOREG-0577, "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Stram Generator & Reactor Coolant Pump Supports " Proposed review piocedure & implementation schedule encl EJSE(NUT.D & Division of Licensing 80/05/19 72pp
- 8004056301 Discusses status of fluctuation testing for rise-to-nower program Definite date for completion of tests below 70/power cannot be established at present Region constraint devices do not represent adverse conditions up to 70% power WARE(BOURG, D.W. Public Service Co. of Colorado. 90/05/27. 2pp
- 8006060266 Forwards addl info requested by NRC supporting change to Tech Spec DF 6 i se fissile fuel thorium/U ratio Demonstrates effects of kernel burnup on TRISO dicarbide fuel performance under simulated core heatup conditions SWART,FF Public Service Co of Colorado 80/05/28 5pp
- 80060602/3 Advises that licensee never received NRC 800507 ltr to all operating reactor licensees Licensee obtained copy from consultant but w(1) take no immediate action until ltr is formally transmitted from NRC SWART, f E Public Service Co of Colorado 80/05/30 ip
- 8006160034 Forwards Startup Rept 15. "Initial Approach to Power Tests (B-Series)." for 80023-0322 WAREKBOURG, D Public Service Co of Colorado 80/06/05 ip
- --8006160035 Startup Rept 15, "Initial Approach to Power Tests (B-Series)," for 800223-0522 * Public Service Co of Colorado 80/05/22 2pp
- 8006170692 Requests relief from Tech Boec LCO 4 2 9 requirements until mid 1781, due to excessive purified helium leakage in Loop 2 steam generator penetration sys Leakage paths represent penetration closure leakage different from LCO 4 2 9 WAREMBOURG, D.W. Public Service Co. of Colorado. 80/06/09. Spp.
- BOOA180034 Discusses licensee 7908P2 request for route approval to cover shipments of spent fuel from facility chemical gracessing plant Review of route approval request is subj to NRC fee schedule Requests payment of review fee MILLER, W.O. License Fee Management Branch 80/04/06 1p
- 8004240593 Advises that Ofc of Controller has been notified to issue invoice re 790822 request for route approval to cover shipments of spent fuel from facility to ID Chemical Processing Plant in Arco. ID
 MILLER, W. O. License Fee Management Blanch 80/06/06 1p
- 8006180419 Discusses previous commitment to conduct SR 5 3 7.secondary coolant activity, at 7P-h intervals Proposes beta/gamma scan at 72-h intervals & SR 5 3 7 at 1 wk intervals, due to 48-h duration of SR 5 3 7 WAREMSQUROLD Public Service Co of Colorado 80/06/10 ip
- 8006240400 Advises that licensee cannot respond to NRC 800507 ltr re addl TMI-2 requirements w/o referenced NRC ltrs on shift manning & licensing examinations Licensee will respond upon receipt of appropriate correspondence WAREMBOURGID W Public Service Co of Colorado 80/06/18 ip
- BOO6270199 Responds to question re effect of fissile fuel Thorium/U ratio reduction Total core ratio remains unchanged SNART.F.E. Public Service Co. of Colorado. 80/06/20. ip
- G Inspection reports. If Bulletins & correspondence
- BOOA030253 Comments on IF Info Notice 80-06 NRC should provide more guidence & specific examples for Bubparagraph & Requests that NRC install speaker phones that will permit communication between site & NRC operations ctr

- 8006040041 Responds to IF Bulletin 80-03, "Loss of Charcoal from 8td Type II, Tuo-Inch. Tray Adsorber Colls" Lists filter cells used in reactor plant exhaust sys Insps of inservice & stored cells found none of defects noted LEE.OR Public Service Co. of Colorado 80/03/22 ip
- 8005040043 Responds to IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Util interprets bulletin as applying only to PMRs 1 BMRs 1 not to HTGRs Ltt constitutes closing ref for 70-day reporting requirement WAREMBOURG.K Public Service Co or Colorado 80/03/27 1p
- 8006040040 Submits supplemental reply to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Sys " To date, 352 of 569 seismic Class I isometric packages have been audited 4 479 field audit craff actions completed SNAR1.F E Public Service Co of Colorado 80/04/23 4pp
- 8006240178 Forwards IF Insp Rept 50-267/80-09 on 800415-18 No noncompliance noted MADSEN.9 L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/01/30 2pp
- --8006240182 IE Irsp Rept 50-267/80-09 on 800415-18 No noncompliance noted Major areas inspected procedures, surveillance of pipe support & lestraint sys, maint piogram & plant tour WESTERMAN, T F , DEANLS Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/04/30 4pp
- 8006240050 Forwards IF Insp Rept 50-267/80-08 on 800401-30 & notice of violation MADSEN.G L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/05/06 2pp
- --8006240053 Notice of violation from insp on 800401-30 * Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/09/05 1p
- --8006240055 IE Insp Rept 50-267/80-08 on 800401-30 Noncompliance noted failure to meet Tech Spec for diosel generator day tank levels
 DICKERSON,M W., COLLINS,R E. Region 4. Dallas, Office of the Director MESTERMAN,T F. Region 4. Dallas, Reactor Operations Nuclear Support Bianch 80/05/05 6pp
- B006060593 Forwards IE Bulietin B0-ii, "Masonry Wall Design " Requires action & written responso IE Info Notice 79-20, "Overloading of Structural Elements Due to Pipe Support Loads" encl SEYFRIT, X V Region 4, Dallas, Office of the Director 80/05/08
- 8006040288 Forwards IE Bulletin 80-12. "Decay Heat Removal Bys Operability ' No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit I While in Refueling Mode" encl SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/09 in
- 8006060053 Ack receipt of 800506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/80-06 MADSEN.O L. Region 4. Dalias. Roactor Operations Nuclear Support Branch 80/05/22 ip
- --8004040097 Responds to NRC 800430 ltr re violations nated in IE Insp Rept 50-267/80-06 Corective actions calibr test of moisture std will be performed 3 request for change in Tech Spec wording will be submitted LEE.R E Public Service Co of Colorado 80/05/06 2pp
- 8006240005 Notifies that IC Insp Rept 50-267/79-22, forwarded by 800919 ltr.should be changed to 50-267/79-21 BROWN.0 D Region 4, Dallas. Fuel Facility & Materials Safety Bronch 80/05/23 ip
- --8006240007 Forwards IE Insp Rept 50-267/79-21 on 791206 No noncompliance noted BROHN: G D Region 4. Dallas, Fuel facility & Materials Safety Branch 80/05/19 2pp
- ---8004240008 IE Insp Rept 50-247/79-21 on 791204 No noncompliance noted Major areas inspected requirements of waste burial firms, audit program, regulations, instructions & operating procedures
 BROWN, © D Region 4, Dallas, Fuel Facility & Materials Safety
 Branch HARRISON, H C Region 4, Dallas, Office of the Director 80/05/15 3pp

- R Periodic operating reports & related correspondence
- 8006090375 Forwards monthly operating rept for Apr 1980 WAREMEQURG.D Public Service Co. of Colorado 80/05/29 1p
- ---8004090381 Monthly operating rept for Apr 1980
 Fublic Service Co of Colorado 80/05/29 9pp
- 8006160017 Forwards monthly operating rept for May 1980
 WAREMBOURG, D Public Service Co of Colorado 80/06/06 1p
- --8006160036 Monthly operating rept for May 1980 GAHM.J W Public Service Co of Colorado 80/06/02 Spp
- 8 Reportable occurrences, LERs & related correspondence
- BGC616003C Porwards LER 80-024/03L-0
 WAREMBGURG, D Public Service Co of Colorado 80/06/04 See
- --8006160031 LER 80-024/03L-0 on 800512, at 47% thermal power, 10 circulator seal differential pressure decreased significantly due to unknown causes Equalizing valve closed & CC circulator buffer helium pressure returned to normal & Public Service Co of Colorado 80/06/06 1p
- 8006160115 Ferwards LER 80-023/03L-0 WAREMBQURG.D Public Service Co of Colorado 80/06/06 App
- --B005160118 LER 80-023/03L-0 from 800507-17.plant was operated w/smergency feedwater header supply to helium circulator water turbine drives of one loop isolated on four separate occasions Caused by valve leatage & line leatage OAHM.J W Public Service Co of Colorado 80/06/06 1p
- 8006240335 RO on 800501 8 0617 minute releases of radioactivity occurred in reactor bldg Caused by malfunction in helium circulator sys No radiation was released into atmosphere Public & personnel health & safety were not jeopardized GASCHLER, J A Public Service Co of Colorado 80/06/18 ip
- DOCKET 50-267 OCCINEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- BOOLOGO487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENKUT.O.G Division of Licensing 80/05/19 46pp
- **BOOM STATEMENT OF THE PROPERTY OF THE PROPER
- 8006030108 Forwards revision to sefeguards contingency plan Plan withheld (ref 10CFR2 790) PARKER, 0 Duke Power Co 80/05/30 Ip
- 8006160074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 100FR2 770) PARKER, W.O. Duke Power Co. 80/06/09 ip
- 8006300004 Forwards comments & requests for additinfore guard training & qualification plan Encl withheld (ref 100FR2 770)
 REID.R W Operating Reactors Branch 4 80/06/12 2pp.
- 8006240209 Forwards cover ltr to 800409 revision to nuclear security training & qualification plan. Ltr withheld (ref 10LFR2 790) PARKER. W O Duke Power Co 80/06/19 ip
- G Adjudicatory correspondence
- 8006240894 Forwards Lincoln County, NC Board of County Commissioners 791001 & 800408 resolutions affirming position that agent nuclear fuel should be transported from Oconee to McQuire on interstate highways HOUSER, P II North Carolina, State of 80/04/17 3pp
- B005230577 Advises that util is to submit proposed findings of fact by B00519, non-NRC parties by B00529 & NRC by B00509 MCGARRY, J K Debevoise & Liberman B0/04/30 ig

- 8006060269 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision MCGARRY. J M Debevoise & Liberman 80/05/19 ip
- ---800&0&0281 Submittal of proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman BO/03/19 lp
- --8006060286 Proposed initial decision containing findings of fact & conclusions of law, approving amend to authorize storage of Oconee spent fuel at McGuire Environ radiological monitoring program shall be maintained W/Certificate of Svc MCGARRY, J II Duke Power Co MCGARRY, J M Debevoise & Liberman BO/05/19 88pp
- 8006180517 Response in opposition to Carolina Environ Study Group 800529 proposed elements of fact & conclusions of law toward initial decision No good reason presented for not approving application re spent feel shipment U/Certificate of Svc MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 80/06/13 21pp
- BOO6190593 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconne spent fuel transportation to & storage at McQuire
 KETCHEN.E O Hearing Branch 4 BO/06/17 1p
- ---8006190606 Proposed findings or fact 2 conclusions of law in form of initial decision approving license amend to authorize Decomes spent fuel transportation to 2 storage at McGuire Proposed transcript car rections 2 Certificate of Svc encl KETCHEN, E 0 , MGEFLING, R K Hearing Branch 4 80/06/17 159pp
- H General correspondence
- 8006270203 Forwards county board resolution requesting NRC to consider using ensite storage of radioactive matls rather than shipping through county Also forwards board resolution requesting public input re DOT regulations MARSHALL.H R Meckienburg County.NC 80/06/23 3pp
- P Operating license stage documents & correspondence
- 8006240237 Responds to technical assistance request for proposed Tech Spec changes for B&W operating plants Forwards requirements for add1 info ISRAEL.S L TMT-2 Bulletins & Orders 79/08/29 13pp
- 8006050537 Forwards schedules for util responses to NRC 791121 ltr re C Michaelson concerns on small break LOCAs CAPRA, R TMI-2 Bulletins & Orders 79/12/10° ip
- 8006060283 Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for B&H operating plants W/o encls
 CAPRAR A Light Water Reactors Branch 3 80/01/17 App
- 8006200562 Forwards rovision to 800317 route approval request for shipment of spent fuel.changing dates for shipment Revision withheld (ref 10CFR2 770) PARKER:W 0 Duke Power Co 83/04/17 ip
- 8006090165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams 8 licensee dissemination of operating experiences Response requested within 30 days EISERHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREO-0377. "Potential for Low Fractury
 Toughness & Lamellar Tearing on PWR Steam Generator &
 Reactor Coolant Pump Supports ' Proposed review procedure &
 implomentation schedule ont!
 EISENHUT, D G Division of Licensing 80/05/19 72pp
- 9006040217 Forwards NFS-1001, 'Reload Design Methodology,' Revision 1, replacing original entirely includes design of unrodded fuel cycles, clarification of certain areas & typographical error corrections Rept methods intended for use by Aug 1981 PARKER, N O Duke Power Co 80/05/20 ip

1

- --8006040221 "Reland Design Methodology," Revision 1 4 Duke Power Co NFS-1001 80/05/31 300pp
- 8006130022 Requests submittal of amend to license updating requirements of Reg Ouide 1 16. Revision 4 Response required within 60 days of receipt of Itr REID.R W. Operating Reactors Branch 4 80/05/29 2pp

- 8006300574 "Electrical lustrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys.' informal rept WEDER,D A EG&G, Inc FIN A-6296 8006300574 80/05/31 12pp
- 8006060364 Requests add1 info to respond to NRC 800507 ltr re TMI-2 Lessons Learned requirements Info needed includes areas re shift manning, safety & relief valves & outage of ECCS Response should be submitted by 800612 PARKER.N Q Duke Power Co 80/06/02 2pp
- 8006230134 Advises that R00328 request for Tech Spec change will be included in overall review of App I submittals Mark-up of B00323 ETS represents NRC review Radiological ETS should resubmitted based on mark-up.within 90 days REID.R W Operating Reactors Branch 4 80/06/02 2pp
- 8006110144 Forwards "Generic Startup Physics Test Program, May 1980," delineating tests to be included during startup following future refueling operations PARKER, M O Duke Power Co 80/06/04 Ip
- --8006i10158 "Generic Startup Physics Test Program, May 1980 " Modifies
 Unit i specific rept decreasing acceptance criteria for rod
 drop measurements substitution or RMS criteria for location
 of highest peak requirement in power distribution testing
 % Duke Power Co 80/05/31 12pp
- 8006110351 Forwards summary of events involving partial or total loss of offsite power to facilities & responses to NRC questions, per NRC 800505 lti
 PARKER.W O Duke Power Co 80/06/04 5pp
- 8006130322 Forwards results of analysis required by Items 6 & 9 of NRC 79080B ltr on degraded grid voltage Undervoltage trip setpoint will be changed for startup transformers & administrative controls will be established by 800701 PARKER, W O Duke Power Co 80/06/04 17pp
- 6006240163 Responds to NRC 800602 ltr requesting guidance re TMI-2 related requirements Automatic trip schedule of reactor coolant pumps during LGCA should be revised REID.R W Operating Reactors Branch 4 80/06/10 2pp
- 8006170229 Forwards corrected version of "Oconeo Nuclear Station Generic Startup Physics Test Program" PARKER,W O Duke Power Co 80/06/11 1p
- --8005170234 Corrected version of "Conee Nuclear Station Generic Startup Physics Test Program" + Duke Power Co 80/06/11 14pp
- BOD6170458 Advises that responses are being prepared re low pressure turbines per BOD513 request Work will be completed by BOD626

PARKER, W O Duke Power Co 80/06/11 1p

- 8006300351 Forwards draft NRC licensing position, "Safety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage critoria Requests reviews for onsite storage additions in monthly operating repts REID,R W Operating Reactors Branch 4 80/06/12 10pp
- 8006180478 Forwards response to NRC 800507 ltr re add1 requirements from TMI Action Plan Response contains implementation schedule & summary stating util commitments rerequirements PARKER, W O Dube Power Co 80/06/13 3pp
- 8006240465 Responds to NRC 800513 request for info concerning problem of low pressure turbine disc cracking Forwards detailed responses to site specific questions PARKER.W U Duke Power Co 80/06/16 8pp
- 8006260233 Requests that NRC complete review & approval of Category B Items 2 i 38.2 i 78 & 2 i 88 Review needed to facilitate installation of Category B mods prior to 810101 PARKER:W Q Duke Power Co 80/06/20 ip
- 8006300362 Forwards proposed Tech Spec revision in response to NRC 800410 ltr discussing term "operable" as applied to Tech Spec requirements No license fees provided since proposal submitted in response to NRC request PARKER.W D Duke Power Co 80/06/24 2pp
- --8006300364 Proposed Tech Spec interpreting term "operable" as applied to various Tech Spec requirements

 4 Duke Power Co 80/06/24 ip

- 8006300406 Advises that startup testing summary for Cycle 6 will be completed 5 transmitted by 800711 PARKER.W 0 Duke Power Co 80/06/24 Ip
- G Inspection reports, IE Bulletins & correspondence
- BO05230330 Forwards waste packaging insp rept on 800313-14
 No noncompliance noted
 STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety
 Branch 80/04/07 2pp
- --8005230341 Waste packaging insp rept on 800313-14 No noncomptiance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper > DDT placarding requirement POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 4pp
- BO06060146 Forwards IE Insp Repts S0-269/80-13,50-270/80-08 & 50-287/80-08 on 800303-31 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/23 2pp
- --8006060152 IE Insp Repts 30-269/80-13.50-270/80-08 & 50-287/80-08 on 800303-31 No noncompliance noted Major areas inspected plant operations, outage activities, followup on previous inspected plant findings & review of LERs
 MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch GRDERS,W T , JAPE,F Region 2, Atlanta, Office of the Director 80/04/23 5ρρ
- 8006060510 Forwards IE Bulletin BO-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pige Support Loads" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 200
- 8006050295 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Requires action & response within 30 days IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/07 2pp
- 8006170065 Forwards IE info Notice 79-37 w/errata sheet Requests addition of turbine discs Recommends that schedule be developed to perform full ultrasonic test of at least one low pressure turbine before next major outage REID.R W Operating Reactors Branch 4 80/05/13 3pp
- 8006300110 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/13 200
- B006180254 Ack receipt of IE Insp Repts 50-269/80-13,50-270/80-08 & 50-287/80-08 No proprietary info PARKER,N O Duke Power Co 80/05/20 1p
- 8005240109 Ack receipt of 800502 supplemental response informing NRC of re-evaluation of noncompliance & deviation noted in IE Insp Repts 50-269/79-37, 50-270/79-34 & 50-287/79-37 Stated position stands due to repetitive nature of incident D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/30
- ---8006240117 Supplements response to NRC 800407 ltr re noncompliance & deviation noted in IF Insp Repts 50-269/79-37, 50-270/79-34 & 50-287/79-37 Disagrees w/violation because event was not controllable by normal operating procedures PARKER, W Q Dute Power Co 80/05/02 2pp
- 8006240248 Forwards response to 1£ Bulletin 80-12 re decay heat removal sys reliability Control room has indication of each pump discharge pressure & each train flow Annunciators are initiated on low flow in either train or if pump is on PARKER.W D Dute Power Co 80/06/06 Spp
- 8006300190 Ack receipt of IF Insp Repts 50-269/80-16, 50-270/80-11 & 50-287/80-19 on 800422-25 No proprietary info PARKER, N O Duke Power Co 80/06/12 ip
- --8006300199 Forwards IE Insp Repts 50-269/80-16.50-270/80-11 & 50-287/80-10 on 800422-25 No noncompliance noted
 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch 80/05719 3pp

--8004300207 IE Insp Repts 50-249/80-14.50-270/80-11 & 50-287/80-10 on 800422-25 ho noncompliance noted Major areas inspected containment integrated lealage rate testing BRODAS.F H Region 2, Atlanta, Office of the Director UPRICHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/16 App

8006300213 Advises that response to IE Bulletin 80-06 will be provided by 800714 due to need for detailed review of engineered safeguards components PARKER.H O Buke Power Co 80/06/13 ip

S. Reportable Occurrences, LERs & related correspondence

8004050343 Forwards LER 80-010/03L-0 PARKER: W O Duke Power Co 80/05/12 2pp

--8006050344 LER 80-010/03L-0 on 800416, during entry of reactor bldg, personnel hatch inner door gasket was discovered leaking Caused by failure of gasket to seal properly Shim gaskets installed & Litching brackets adjusted LEWIS.S R Duke Power Co 80/05/12 ip

8006040298 Forwards LER 80-012/03L-0 PARKER:W D Duke Power Co 60/05/29 1p

--8004040302 LRR 80-012/0CL-0 on 800501, while at 75% full power, valve 1FDW-310 inadvertently closed isolating turbine driven EFW pump From ance-through steam generator IB Caused by not identifying unit number to be closed Personnel cautioned LEWIS.8 R Duke Fower Ca 80/05/29 3pp

8006110101 Forwards LER 80-013/03L-0 PARKER.W 0 Duke Power Co 80/06/05 3pp

---8006110105 LER 80-013/03L-0 on 800509 during performance testing, turbine driven emergency feedwater pump declared imperable Caused by failed integard bearing resulting from water-contaminated oil due to shaft packing leatage PHILPOTT.F T Duke Power Co 80/06/05 1p

8006130283 Forwards LER 50-015/01T-0 PARKER,W D Duke Power Co 80/06/06 3pp

~-8006130284 LER 80-015/01T-0 on 800523.util discovered four assemblies w/broken holddown springs Probably caused by high cycle fatigue 88W continuing efforts to resolve concern Adequate monitoring of loose parts monitoring sys verified WILSON.K R Duke Power Co 80/06/06 (p

8006170523 Forwards LER 80-016/01T-0 PARKER: W 0 Duke Power Co 80/06/12 3pp

---8006170530 LER 80-016/01T-0 on B00529, evaluation of steam generator tube failure in FSAR failed to consider release path for radioactive steam through main steam relief valves Offsite thyroid dose calculations performed per IOCFR100 LEHIS,R C Duke Power Co E0/06/12 ip

8008260174 Forwards LER 80-014/03L-0 PARKER,W 0 Duke Power Co 80/06/19 2pp

--8006260175 LER 80-014/03L-0 on 800521, unit started, but would not load above appro; 30 MWe Caused by loose wire in partial shutdown circuit Wire secured % unit verified operable Monthly maint procedure modified to include wire check PHILPOTI,FT Duke Power Co 80/06/19 lp

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans

8006090487 Forwards proposed rule antitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48? App R to 10CFR50 & is expected to be published in FR by end of Mag EISENHUT.D & Division of Licensing 80/05/19 46pp

d Pages i-14 & new Page 14s for proposed action Program for Nuclear Power . TOAEO1." transmitted by NRC 800519

ensing 80/05/22 73pp

safeguards contingency plan Plan

8006160074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 100FR2 790)
PARKER, W. G. Duke Powel Co. 80/06/09 ip

8006240209 Forwards cover ltr to 800609 revision to nuclear security training 3 qualification plan Ltr withheld (ref 100FR2 790) PARKER, N O Duke Pouel Co 80/06/19 ip

G Adjudicatory correspondence

B006240894 Forwards Lincoln County, NC Board of County Commissioners 791001 \$ 800408 resolutions afrirming position that spent nuclear fuel should be transported from Oconee to McGuire on interstate highways HOUSER, FM North Carolina, State or 80/04/17 3pp

8006060269 Forwards applicant proposed findings of fact & conclusions or law in form of initial decision MCGARRY, J. M. Debevoise & Liberman 80/05/19 ip

--8006060281 Submittel or proposed findings of fact & conclusions of law in form of initial decision MCOARRY.J M Duke Power Co in GARRY.J M Debevoise & Liberman 80/05/19 1p

--8006060286 Proposed initial decision containing findings of fact & conclusions of law approxing amend to authorize storage of Ocohee spent fuel at McGuire Environ radiological monitoring program shall be maintained M/Certiricate of Svc MCGARRY. J M Duke Power Co MCGARRY. J M Debovoise & Liberman 80/05/19 89pp

8006180517 Response in opposition to Carolina Environ Study Group 800527 proposed elements of ract & conclusions of law toward initial decision No good reason presented for not approving application is spent fuel shipment U/Certificate of Svc MCGARRY, J M Duke Power Co NCGARRY, J M Debevoise & Liberman 80/06/13 2159

8006190593 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to % storage at McGuire KETCHEN.E G Heiring Branch 4 80/06/17 1p

--8005190605 Proposed finding or Fact % conclusions of law in form of initial decision approving license amend to authorise Oconpe spent ruel transportation to % storage at McGuire Proposed transcript corrections & Centificate of Svc encl KETCHEN.E G . HOEFLING.R K Hearing Branch 4 80/06/17 155pp

H General correspondence

8006270203 Forwards county board resolution requesting NRC to consider using unsite storage of radioactive matls rather than shipping through county Also forwards board resolution requesting public input ie DOT regulations MARSHALL, H R Mectlenburg County, NC 80/06/23 3pp

P Operating license stage documents & correspondence

8006240P37 Responds to technical assistance request for proposed Tech Spec changes for BtW operating plants Forwards requirements for add info IGRAEL, S L TMI-2 Dulletins & Orders 79/08/29 13pp

8006050539 Forwards schedules for util responses to NRC 791121 ltr re C Michaelson concerns on small break LOCAs CAPRA:R TMI-2 Bulletins & Orders 79/12/10 ip

8006060283 Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for B&W operating plants (V/o encis CAPRAR A Light Water Reactors Sranch 3 80/01/17 3pp

BOOGROOSAY Forwards revision to 800317 route approval request for shipment of spent fuel, changing dates for shipment Revision withheld (ref IOCFR2 790] PARKER, W O Duke Power Co EO/04/17 ip

- 8006090165 Forwards add1 IMI-2 related requirements to operating reactors Licensees requirements to: TMI Action Plan Include shift manning, licensing erams / licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D.G. Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness 3 Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports Proposed review procedure & implementation schedule encl EISENHUT D G Division of Licensing 80/05/19 72op
- 800604021/ Forwards NES 1001, "Reload Design Methodology," Revision 1, replacing original entirely includes design of unrodded fuel cycles clarification of certiin areas & typographical error corrections Rept methods intended for use by Aug 1981 PARKER, Will Duke Power Co. 80/05/20 1p
- -8006040271 "Reload Design Methodology," Revision 1 4 Duke Power Co NFS-1001 80/05/31 300pp
- 8006050361 Natifies that mod approved by NRC on 771213 is complete & acceptable procedures incressary to terminate exemption to 10CFR50 46(n) have been implemented PARKER.N O Duke Power Co NRC 80/05/29 ip
- E006:30022 Requests submittil or imend to license updating requirements of Reg Guide 1 lanevision 4 Response required within 60 days of receipt or ltr REID.# W. Operating Reactors Branch 4 80/05/29 2pp
- GOO6060364 Requests add1 info to respond to NRC 800507 ltr re TMI-2 Lessons Leained requirements Into needed includes areas re shift manning safety 3 relier valves 5 outage of ECCS Response should be submitted by 800612 PARKER.W 0 Duke Power (v 80/04/07 2pp
- BOO4230144 Advises that BOO328 request for Tech Spec change will be included in overall review of App I submittals Mark-up of BOO523 ETS represents NRC review Radiological ETS should resubmitted based on mark-up within 90 days REII), R W Operating Reactors Branch 4 80/06/02 2pp
- 8006110144 Forwards "Generic Startup Physics Test Program, May 1980," delineating tests to be included during startup following future refueling operations
 PARKER, & D. Duke Power Co. 80/06/04 1p
- -- 8006110159 "Generic Startup Physics Test Program, May 1980 " Modifies
 Unit 1 specific rept.decreasing acceptance criteria for red
 drop measurements substitution of RMS criteria for location
 of highest peak requirement in power distribution testing
 + Duke Power Co 00/05/31 12pp
- 8006(1035) Forwards summing of events involving partial or total loss or offsite power to facilities / responses to NRC questions, per NRC 800505 ltr PARKER, N D Duke Power to 80/06/04 5pp
- 8006130322 Forwards results of analysis required by flems 6 & 9 of NRC 790808 ltr on degraded grid voltage Undervoltage trip setpoint will be changed for startup transformers & administrative controls will be established by 800701 PARKER.W O Duke Power Co 80/06/04 17pp
- 8006160032 Forwards addl pages to 800312 proposed changes to Tech Specs in support of Cycle 9 operation PARXER.N D Dute Power Co 60706709 ip
- ---BOO&160033 Add1 pages for proposed Tech Specs re Sections 3 5 2 6-3 5 2 6 concerning reactor coolant sys pressure, coolant outlet temp / reactor bldg pressure Dute Power Co 80/06/07 7pp
- 8006240163 Responds to NRC 800602 ltr requesting guidance re TMI-2 related requirements Automatic trip schedule of reactor coolant pumps during LOCA should be revised REID.R W. Operating Reactors Branch 4 80/06/10 2pp
- 8006170229 Forwards corrected version of "Oconee Nuclear Station Generic Startup Physics Test Program" PARKER.W D Duke Power Co 80/06/11 tp
- ---8006170234 Corrected version of "Oconee Nuclear Station Generic Startup Physics Test Program" + Duke Power Co 80/06/11 14pp

- 8006170458 Advises that responses are being prepared re low pressure turbines per 800513 request Nork will be completed by 800626 PARVER.N. O. Duke Power Co. 80/06/11 ip
- 8006300351 Forwards draft NRC licensing position, "Safety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating repts REID.R N Operating Reactors Branch 4 80/04/12 10pp
- 8006180478 Forwards response to NRC 800507 ltr re addl requirements from TH1 Action Plan Response contains implementation schedule 3 summary stating util commitments re requirements
 PARKER. W. O. Dube Power Co. 80/06/13 3pp
- 8006240465 Responds to NRC 800513 request for info concerning problem of low pressure turbine disc cracking Forwards detailed responses to site specific questions
 PARKER, W. O. Duke Power Co. 80/06/16. Opp
- 8006260233 Requests that NRC complete review & approval of Category B Items 2 1 38.7 1 74 2 1 60 Review needed to facilitate installation of Category B mods prior to 810101 PARKER.W O Duke Power Co 80/06/20 1p
- 8006300362 Forwards proposed Tech Spec revision in response to NRC 800410 ltr discussing term "operable" as applied to Tech Spec requirements No license fees provided since proposal submitted in response to NRC request PARKER.W O Duke Power Co 80/06/24 2pp
- --8006300364 Proposed Tech Spec interpreting term "operable" as applied to various Tech Spec requirements
 # Duka Power Co 80/06/24 ip
- 8006300574 "Clectrical Instrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys." informal rept WEBER, D A COSO, Inc FIN A-6256 G006300574 80/05/31 12pp
- Q Inspection reports, 18 Bulletins & correspondence
- 8004040146 Forwards IE Insp Regts 50-269/80-13.50-270/80-08 & 50-287/80-08 on 800303-31 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/04/23 2pp
- ---E006060152 IE Insp Repts 50-269/80-13.50-270/80-08 & 50-287/80-08 on 800203-31 No noncompliance noted Major areas inspected plant operations outage activities, followup on previous insp findings % review of LERs MARTIN,R D Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch ORDERS,W T. APPE.F. Region 2. Atlanta, Office of the Director 80/04/23 5pp
- 8006060510 Forwards IE Bulletin 80-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/08
- 8006050295 forwards if Bulletin BO-12, "Docay Heat Removal Sys Operability " Requires action / response within 30 days IE Info Notice 80-20, "loss of Docay Heat Removal Capability at Days-Besse Unit i While in Refucing Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 200
- 8006170065 Forwards IE Info Notice 79-37 w/errata sheet Requests add1 info re turbine discs Recommends that schedule be developed to perform full ultrasonic test of at least one low pressure turbine before next major outage REID,R W Operating Reactors Branch 4 80/05/13 3pp
- 8004300110 Forwards 1£ Circular 80-11, "Emergency Diesel Generator Lubø Dil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atjanta, Office of the Director 80/05/13
- 8006180254 Ack receipt of 1F Insp Repts 50-269/80-13,50-270/80-08 & 50-287/80-08 No proprietary into PARKER, W C Duke Power Co 80/05/20 1p

- 8006240109 Act receipt of 800502 supplemental response, informing NRC of re-evaluation of noncompilance b deviation nated in IE lasp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 Stated position stands due to repetitive nature of incident O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/30 in
- --8006249117 Supplements response to NRC 800407 ltr re noncompliance & deviation noted in [E Insp Repts 50-269/79-37,50-270/79-34 & 50-267/79-37 Disagrees w/violation because event was not controllable by normal operating procedures PARKER. W O Duke Power Co 80/05/02 2pp
- 800624024B Forwards response to IE Bulletin 80-12 re decay heat removal sys reliability Control room has indication of each pump discharge pressure & each train flow Annuniciators are initiated on low flow in either train or if pump is an PARKER, W O Duke Power Co 80/06/06 Spp
- 8006300190 Ack receipt of IE Insp Repts 50-269/80-16,50-270/80-11 & 50-287/80-10 on 800422-25 No proprietary info PARKER.W 0 Duke Power Co 80/05/12 1p
- --8006300197 Forwards IE Insp Repts 50-267/80-16,50-270/80-11 b 50-287/80-10 on 800422-25 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/19 3pp
- --8004300209 IE Insp Repts 50-269/80-16,50-2/0/80-11 & 50-287/80-10 on 800422-25 No noncompliance noted Major areas (nspected containment integrated leakage rate testing BROCKS,F H Region 2, Atlanta, Office of the Director UPRIOHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support Branth 60/05/16 4pp
- 6006300213 Advises that response to IE Bulletin 60-06 will be provided by 600714 due to need for detailed review of engineered safequent's components PARKER, W O Duke Power Co 60/06/13 ip
- 8 Reportable occurrences, LERs & related correspondence
- BOO6050241 Advises that submittal of RO 270/80-3 re inadvertent deboration during cold shutdown will be delayed Rept will be sent no later than 800605 PARKER, N G Duke Power Co 80/05/21 1p
- 8006110321 Forwards LFR 80-003/01T-0 PARKER,W O Duke Power Co 80/06/05 3pp
- --8006110326 LER 80-003/017-0 on 800507, deborating demineralizer was placed in svc while plant in cold shutdown & RCS drained down RCS boron concentration reduced from 1,895 ppm to 1,539 ppm Apparently caused by incorrect chemistry records LEWIS,8 R Duke Power Co 80/06/05 1p
- BOOG240506 Forwards LCR 80-004/01T-0 PARKER,W O Duke Power Co 80/06/17 3pp
- --B006240512 LER 80-004/01T-0 on B00603.w/unit in refueling outage, reactor protection sys channel C failed to trip on high RB pressure Probably caused by switch being damaged during outage Pressure switch replaced PHILPOTT.F T Duke Power Co B0/06/17 ip
- DOCKET 90-271 VERMONT YANKEE NUCLEAR POWER STATION

 F. Becurity, medical, emergency & fire protection plans
- GODAG90487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section SO 48 & App R to 1006R50 & is expected to be published in FR by end of May EISENHUT, D O Division of Licensing GD/05/17 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 100FR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 1tr Page 14a not encl EISENHUT, D O Division of Licensing 80/05/22 73pp
- B006200178 Notifies that revised safeguards contingency plan submitted B00318 found acceptable flam withheld (ref 10CFR2 790) IPPOLITO T A Operating Reactors Branch 2 80/05/30 2pp

- 11 General correspondence
- BOO6030184 Ack receipt of BOO428 ltr re opinions on facility operation Ltr is being forwarded to DFc of Nuclear Reactor Regulation ABRAHAM, K. Region i, Philadelphia, Office of the Director BO/05/12 ip
- --8006630185 Protests NRC warver under which Facility is operating Facility should be closed HEARD, C Affiliation Unknown 80/04/28 ip
- 800618017; Responds to 800414 ltr re reasons for decommissioning plant NRC will consider petitions & public views IPPOLITO,T A Operating Reactors Branch 2 80/05/30 1p
- ---BOOLBOI7B Requests that NRC decommission plant People in Vernon are upset & get no response to appeals Author is coming to Washington.DC on BOO426 GRANT.J Aftiliation Unknown BO/04/14 1p
- 8006300295 Responds to 800412 request to shut down facility Mods to increase safety implemented IPPDLITO, T A Operating Reactors Branch 2 80/06/13 1p
- --B006300260 Demands facility be shutdown because torus still not repaired MORROIL & S Affiliation Unknown 80/04/12 lp
- J Insurance & indemnity information
- BOO6200492 Forwards Endorsement 43 to MAELU Policy MF-56 & Endorsement 53 to NECIA Policy NF-189 CAREY.W W Vermont Yankee Nuclear Power Corp 80/06/16 3pp
- P Operating license stage documents & correspondence
- 8004090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREO-057/, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports ' Proposed review procedure & implementation schedule onci EISENHUT.D & Division of Licensing 80/05/19 72pp
- 8004070027 Approves util 800401 & 27 submittals re hydrogen monitoring equipment as meeting intent of short-term Lessons Learned Task Force requirements IPPOLITO.T A Licensing Branch 2 80/05/20 2pp
- BOO6020274 Forwards response to BOO312 request for add1 info re bypass & reset of engineered safety features Drawings will be forwarded under separate cover due to security concerns BMITH.R L. Vermont Yankee Nuclear Power Corp 80/05/28 12pp
- 8006030314 Forwards drawings in response to NRC 800312 request for add1 info for bypass & reset of engineered safety features for facility Drawings withheld (1ef 10CFR2 /70) SMITH.R L. Vermont Yaniee Nuclear Power Corp. 80/05/28 2pp
- 8006030468 Advises that GE study re effect of power supply failure on ECCS performance will be reviewed to determine whether conclusions apply to facility Results of review will be submitted by 80,001
 SMITH.R 1. Vermont Yankee Nuclear Power Corp 80/05/28 1p
- 8006110412 Rotification of 800624 moeting w/util in Bethesda.MD to discuss use of radwaste incinerator ROONEY.V L. Operating Reactors Branch 2 80/05/28 ip
- 8006300604 Ltr to all BMR licensees forwarding "For Comment" edition of NUREQ-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking 'Comments will be evaluated by NRC prior to final implementation H/O encl EISENHUT.D 0 Division of Licensing 80/06/05 22pp

- 8006170548 Forwards tabulation of TMI-2 related requirements & plans for addressing each May want to modify some requirements or schedules following comprohensive review Mods will offer equal or greater safety improvements HEIDER.L H Vermont Yankee Nuclear Power Corp 80/06/11 App
- 8006270192 Responds to 800516 request for info on turbine discs Ut,1 plans to perform ultrasonic testing of discs on one low pressure unit during next scheduled refueling outage No immediate actions required to minimize water grossion TRIBBLE, J E Vermont Yankee Nuclear Power Corp 80/06/19 5pp
- G. Inspection reports, IE Bulletins & carrespondence
- 8006200075 Forwards IE Circular 80-08. 'BWR Tech Spec Inconsistency Reactor Protection Sys Response Time " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/04/18 1p
- 8006190303 Forwards JE lnsp Rept 50-271/80-04 on 800313-14 & 17-19 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- --8006190308 IE Insp Rept 50-271/80-04 on 900313-14 & 17-19 No noncompliance noted Major areas inspected small break LOCA operator guidelines, including emergency procedure preparation 5 review for technical adequacy RAYMOND, N J . FOLLEY, T Region 1, Philadelphia, Office of the Director MARTIN, T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/24 8pp
- 8005060511 Responds to IE Bulletin 80-07 Hold-down beam assemblies & jet pump function can degrade during operation Surveillance program instituted to determine significant cracking of jet pump beam Procedures to determine jet pump failure revised HEIDER. L H Vermont Yankoe Nuclear Power Corp 80/05/08 2pp
- 8006070450 Responds to IE Bulletin 79-01B re evaluation of environ qualifications of Class IF electrical equipment Due to estensive in-house reviews required unable to complete responses on time Completion by 800530 GROCE, R H Yankee Atomic Electric Co 80/05/19 ip
- 8006090283 Informs that util is in process of addressing IE Bulletin 79-03A Response has required diversion of engineering resources from identified safety issues HEIDER: L. H. Vankee Atomic Electric Co. 80703/29 2pp
- 8006040469 Discusses IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312.Tupe 304 Stainless Steel Pipe " Bulletin describes minor design deficiencies, rather than generic problems HEIDER, L. H. Vankee Atomic Clectric Co. 80/05/29 2pp
- BO06260370 Responds to NRC 800403 ltr re violation noted in IE Insp Rept 50-271/79-14 Corrective actions job-specific reactor work permit issued & radiation surveys performed HEIDER: L. H. Vermont Yankes Nuclear Power Corp. 80/04/29 2pp
- 8006110018 Forwards YAEC-1216, "Environ Qualification of Safety-Related Electrical Equipment at VT Yankee Nuclear Power Station," in response to IC Bulletin 79-013 Periodic revisions forthcoming as consultants & manufacturers complete work HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 80/04/02 2pp
- --8006110027 "Environ Qualification of Safety-Related Electrical Equipment at VT Yankee Nuclear Power Station " URBANOWSKI,S F , TSGUDERGS, G , BAYTER,F D Yankee Atomic Electric Co YAEC-1216 80/06/02 184pp
- 800620050) Responds to IF Bulletin 79-018, "Environ Qualification of Class IE Equipment " Forwards YAEC-1216, "Environ Qualification of Safety-Related Electrical Equipment at Vermont Yankee Nuclear Power Station " W/o encl HEIDER, L H Vermont Yankee Nuclear Power Corp 80/06/02 3pp
- R Periodic operating reports & related correspondence
- 8006170645 Farwards monthly operating rept for May 1980 CENWAY.W F Vermont Yankee Nuclear Power Corp 80/06/12 1p
- --8006170649 Monthly operating rept for May 1980
 BEERS,F C Vermont Yantes Nuclear Power Corp 80/06/12 6pp

- S Reportable occurrences, LERs & related correspondence
- 8006030329 Forwards LER 80-019/017-0
 MURFHY, N P Vermont Yankee Nuclear Power Corp 80/05/30 ip
- --8006030333 LER 80-017/017-0 on 800516,AEOC rad monitors 17-150 A & B made inoperative under controlled conditions while evaluating augmented offgas sys (ADO) recombiner temps Caused by dihydrogen recombination before AOC recombiner MURPHY. W P Vermont Yankee Nuclear Power Corp 80/05/30 ip
- 8006170589 Forwards LER 80-018/01P-0 MURPHY.W P Vermont Yankee Nuclear Power Corp 80/06/12 1p
- --8006170595 LER 80-018/01P-0 on 800611.leakage developed in feedwater line Plant shutdown to colf condition initiated Caused by failure of feedwater check valve bonnet seal Seal will be repaired prior to resuming operation MURPHY.WP Vermont rankee Nuclear Power Corp 80/06/12 2pp
- U Congressional/Executive Correspondence
- B006120280 Requests that Commission meet w/VT Yankee Decommissioning Alliance due to widespread concern refacility KENNEDY/E M Sanate 80/04/28 ip
- V Operator Examinations
- 8006270421 Notifies that 800508 outline of proposed hot licensing training program acceptable per NUREG-0094. App F & HR Denton 800528 ltr requirements Formal approval may be granted after review of detailed description, due by 800801 COLLING. P F Operator Licensing Branch 80/06/17 2pp
- DOCKET 50-R72 SALEM NUCLEAR GENERATING STATION, UNIT 1

 F Becurity, medical, emergency & fire protection plans
- B006020163 Forwards facility security plan & payment of civil penalties resulting from B00320 notice of violation Plan withheld traf 10CFR2 790)

 80HNEIDER: W Public Service Electric & Oas Co of New Jersey.

 80/04/14 10
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to (DCRSO & is expected to be published in FR by end of May EISENHUT.D & Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl FISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006170647 Informs NRC of decision to delay activation of Quinton training facility as nearsite emergency operations facility until open issues have been addressed satisfactorily SCHMEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/06/13. 19
- G Adjudicatory correspondence
- 8004040339 Comments on & Webb hearing testimony re-roof of bldg housing spent fuel pool Webb.relied in part on erroneous info from W Russ.project engineer for facility Transcript does not include this info Intervenor 800505 ltr to util encl COLEMAN.A C , COLEMAN.E Q Affiliation Unknown 80/05/09 3pp
- 8006070067 Request for extension until 800528 to file transcript corrections States no objection to MRC motion for similar extension Transcript not yet received in licensee Newark, NJ ofc HETTERHAMN, M J Public Service Electric & Gas Co of New Jersey WETTERHAMN, M J Conner, Moore & Corber 80/05/13 2pp
- --8006070072 Proposed corrections to transcript of 800328-29 evidentiary hearings Certificate of Svc encl WETTERHANNM J Public Service Electric & Qas Co of New Jersey NETTERHANNM J Conner, Moore & Corber 80/05/13 19pp

- 8006230176 Forwards revised pages to Director's Decision DD 80-19
 Decision issued 800429 denied petition requesting certain
 actions re storage of spent ruel at site Corrections
 overlooked
 DENTON.H R Office of Nuclear Reactor Regulation, Director
- 80/05/23 lp
- ---8006230180 Advises that version of DD-80-19 signed is not version concurred on Forwards cover itr errata sheet listing changes & two revisions of Director's Decision Corrections should be issued by 800512

 MURRAY, J P Office of the Executive Legal Director 80/05/07
- BOOb180602 Notifies that Dfc of Nuclear Reactor Regulation Director's denial under IOCFR2 206 of request re spent fuel storage is final CHILK.S J. Office of the Sacretary of the Commission 80/05/29
- 8008200557 Responds to 800523 request for advance notice of activities refacility which involve NRC or State of MD Public Svc Commission NRC is not involved in proceeding Notification request should be directed to MD Public Svc Commission SHAPAR.H K Office of the Executive Legal Director 80/06/06 1p
- --8006200567 Requests advance notice of meetings, conferences, depositions, hearings or appearances re racility involving NRC or State of MO Public Svc Commission Also requests all relevant testimony 1 correspondence received by NRC HETTERHAHN, H. J. Conner, Moore 2 Corber 80/05/23 2pp
- 8006180509 Forwards licensee proposed findings of fact & conclusions of law in form of initial decision Licensee reserves right to file reply brief after svc of proposed findings & conclusions of law by other parties WETTERHAHN, M J Conner, Moore & Corber 80/06/13 1p
- --8006180513 Proposed findings of fact & conclusions of law in form of initial decision Board will not re-review decisions reached during Commission's OL review. From safety or environ standpoint Certificate of Svc encl HETTERHAHN. M J Public Service Electric & Gas Co of New Jersey RETTERHAHN. M J Conner, Moore & Curber 80/06/13 79pp
- 8006240505 Proposed findings of fact & conclusions of law in form of initial decision re amend to License DPR-70 No EIS required per NEPA Alternatives of storage at other sites need not be considered Amend should be issued as in encl draft order MODRE.JE Hearing Branch 3 PATON.W D Hearing Branch 4 80/06/23 65pp
- 8006270227 Forwards corrected Page 59 to NRC 800623 findings of fact & conclusions of law re OL amend proceeding MOORE.J E Hearing Branch 2 80/06/26 1p
- ---B006270233 Corrected Page 59 to NRC B00623 findings of fact & conclusions of law re OL amend proceeding MODRE.J E Hearing Branch 2 PATON.W D Hearing Branch 4 80/06/26 ip

- 8006120089 Responds to ltr to DOE re constituent inquiry about relationship of Merrill Croet Project to facilities NRC has no info re relationship Facilities use water from DE River Basin DIRKKS. U J Office of the Executive Director for Operations 807/05/30 6pp
- J Insurance & indemnity information
- 8006110097 Forwards Endorsements 31.4 & 1 to MAELU Policies MF-90.X8-60 & X8-72.respectively CORREA.M A Marsh & McLennan.inc , M & M Nuclear Consultants.inc Div 80/06/04 6pp
- 8005180507 Forwards executed Amend 8 to Indomnity Agreement B-74, deleting Item 3 & substituting license numbers GRIFFITHS,R Public Service Electric & Gas Co of New Jersey 80/06/12 2pp
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISEMHUT, D.C. Division of Licensing 80/05/07 150pp

- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports ' Proposed review procedure & implementation schedule encl EISENHUT.D C Division of Licensing 80/05/19 72pp
- 8004020051 Notifies of partial refund of Class III fee remitted w/800125 application for amend to Tech Specs re secondary water chemistry Class II fee was applicable MILLER.U O License Fee Management Branch 80/05/22 1p
- 8006170450 Commits to implement NUREG-0660 re add1 TMI-2 related requirements per 800507 ltr LIBRIZZI,FP Public Service Electric & Gas Co of New Jersey 80/06/07 lp
- 8006170651 Forwards auxiliary reedwater pump test results LIBRI271.F P Public Service Electric & Gas Co of New Jersey 80/06/10 1p
- 8006170620 Forwards response to NRC 790921 request for info re auxiliary feedwater flow requirements Decay heat resulting from reactor trip is dissipated by evaporating water in steam generators & venting generated steam LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/06/11 21pp
- Q Inspection reports. IE Bulletins & carrespondence
- 8006120369 Ack receipt of IF 800320 ltr forwarding notice of violation, notice of proposed imposition of civil penalties & order modifying license effective immediately Forwards penalty payment & response Encl withheld (ref 100FR2 790)
 SCHWEIDER: F W Public Service Electric & Gas Co of New Jorsey 80/04/14 ip
- 8006060105 Forwards IF Insp Rept 50-272/80-08 on 800311-14 No noncompliance noted BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/17 2pp
- ---B006000109 IE Insp Rept 50-272/B0-0B on B00311-14 No noncompliance noted Major areas inspected refusiing startup testing, control rod drive operation 3 position indication.core power distribution Σ in-core/excore detector callibr CAPHTON D. Region I. Philadelphia. Reactor Operations Nuclear Support Branch BETTENHOUSEN.L. Region I. Philadelphia, Office of the Director B0/04/15 7ρρ
- 8006180053 Forwards IE Insp Repts 50-272/80-07 % 50-311/80-03 on 800302-29 No noncompliance noted BRUNNER.C J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/29 2pp
- --8004:80054 IE Insp Repts 50-272/80-07 % 50-311/80-03 on 800302-29 No noncompliance noted Major areas inspected plant operations, logs & records.LERs.periodic repts.small break LOCA guidelines & previous insplitems KEIMIG.R R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch NORRHOLM.L J Region 1. Philadelphia, Office of the Director 80/04/23 18pp
- G004180121 Forwards IE Insp Repts 50-272/80-07 & 50-311/80-03 on B00332-27 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/27 2pp
- ---8006180126 IE Insp Repts 50-272/80-07 ½ 50-311/80-03 on 800302-29 No noncompliance noted Major areas inspected plant operations including facility tours, log & record reviews, licensee events review & review of periodic repts NORRHOLM, L J Region 1, Philadelphia, Office of the Director KEIMIO, R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/23 18pp
- 8004020535 Act receipt of 800408 ltr supplementing 770520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-272/77-13
 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/30 in
- 8006120181 Ack recoupt of 800410 ltr informing NRC of steps taken to correct violation noted in IF Insp Rept 50-272/80-05 BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/14 1p
- ---8006120190 Notice of violation from insp on 800203-0301 * Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/03/19 ip

- 8006200029 Forwards 1E Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8006110231 Responds to violations noted in IE Insp Repts 50-272/80-04 & 30-311/80-01 on 800128-31,0201,04-07 & 11-13 Corrective actions master equipment list will expand existing methods of compliance w/requirements of QA program sys & components SCHNEIDER,F W Public Service Electric & Gas Co of New Jersey 80/06/03 8pp
- 8006300233 Forwards partial response to IE Bulletin 79-010, "Environ Qualification of Class IE Equipment" Master list is approx 95% complete in identifying components Qualification data sheets approx 40% complete SCHNCIDER.F W Public Service Electric & Oas Co of New Jersey 80/06/04 26pp
- 8006300292 Responds to IF Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks"

 Facilities have had vacuum breakers installed on holdup tanks to prevent collapse in event vacuum is generated SCHNEIDER.F W Public Service Electric & Qas Co of New Jersey 80/06/06 ip
- 8006300490 Responds to IF Bulletin 80-19, "Decay Heat Removal Sys Operability " Sequence of events at Davis-Besse which resulted in automatic transfer of suction to empty containment sump will not occur at facilities SCHNEIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/09 App
- 8006240395 Submits supplemental rept revising 790919 response to IE Insp Rept 50-272/79-18 implementation of revisions to AP-13 t AP-9 has shown that revisions are sufficient to prevent recurrence of problem identified in insp SCINCIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/12 ip (
- 8006240371 Responds to NRC 800527 ltr re item of noncompliance noted in IE Insp Rept 50-272/80-10 Corrective actions responsibility for Type A.8 & C conteinment leak rate bests assigned to one group Review & approval procedure streamlined SCHNRIDER,F W Public Service Electric & Gas Cp of New Jersey 80/04/17 2pp
- R Periodic operating reports & related correspondence
- 8006160107 Forwards NPDES discharge monitoring repts for Apr 1980, aperating rept of industrial waste treatment plant & wastewater treatment rept W/o operating & wastewater treatment repts MIDURA: M Public Service Electric & Gas Co of New Jersey 80/06/03 2pp
- --8004160136 NPDES discharge monitoring rept for Apr 1980 SCHNEIDER: F.W. Public Gervice Electric & Gas Co. of New Jersey 80/06/03 12pp
- 8006160009 Forwards monthly operating rept for May 1980 MIDURA.H J Public Bervice Electric & Gas Co of New Jarsey BD/06/10 1p
- --8006160012 Monthly operating rept for May 1980 MILLER, L. K. Public Service Electric & Qas Co. of New Jersey 80/06/10 17pp
- S Reportable occurrences, LERs & related correspondence
- 8006230454 RO 79-50/01P on 790710.Westinghouse informed that reactor trip % auxiliary feedwater initiation could be delayed in event of main feedline rupture inside containment Caused by possible heatup of steam generator level ref leg MIDURA.H J Public Service Electric & Gas Co of New Jersey 79/07/10 ip
- 8006060212 Responds to NRC 800211 itr re violations resulting from LER 79-71 Corrective actions counselled individuals involved in incident & will revise AP-15 safety tagging rules to insure only shift supervisors authorized to approve tags 8CHNEIDER; FW Public Service Electric & Gas Co of New Jersey 80/03/06 3pp
- 8006160231 PND-I-80-083 on 800523, woman security guard passed out while resting in guard house during break Ambulance called immediately to transport patient to offsite hosp for observation BRUNNER, E. HILL, W. M., NDRRHDLH, L. J. Region i, Philadelphia, Office of the Director 80/05/23 ip

- 8006050344 Forwards supplemental LER 79-053/01X-2 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/05/30 1p
- --800&050371 Supplemental LER 79-053/01X-2 on 790810, during review of supports within sample stress calculations, unacceptable rejection rate found Caused by use of computer code which calculated pipting response w/algebraic summation method KAPPLE, A W Public Service Electric & Oas Co of New Jersey 80/05/30 3pp
- 8006170573 Forwards LER 80-026/03L-0 L1BAI771,F P Public Service Electric & Gas Co of New Jersey 80/06/12 1p
- --8006170578 LER 80-026/03L-0 on 800516.while performing routine surveillance, level transmitter for steam generator level channel IV for low level trip setpoint was found out of spec Caused by failed capacitors within circuitry MURPHY.M J Public Service Electric 3 Gas Co of New Jersey 80/06/12 2pp
- 8006170664 Forwards LER 60-025/03L-0 LIBRIZZI,F P Public Service Electric % Oas Co of New Jersey 80/06/12 3pp
- ---B006170671 LER B0-025/03L-0 on B00516 during containment entry steam noticed coming from area where reactor coolant sample lines pass through containment wall Caused by failure of sample line & seal weld on penetration Penetration weld repaired MCRPHY.N J Public Service Electric & Gas Co of New Jersey B0/06/12 1p
- 8006230527 Forwards LER 80-028/03L-0 LIBRIZZI,F P Public Service Ejectric & Qas Co of New Jørsey 80/05/17 2pp
- --8006230535 LER BO-028/03L-0 on BO0519 while reviewing records, discovered that surveillance requirement 4 3 3 6 2 was not completed during required interval Caused by lack of timely review Surveillance completed MARPHY. M J Public Service Electric & Gas Co of New Jersey BO/06/17 1p
- 8006240486 Forwards LER 80-027/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/06/18 Zpp
- --8006240492 LER 80-027/03L-0 on 800521, evaluation of need to perform insp of fire pump diesel engine was not made as required every 18 months by Tech Specs Caused by faulty tracking sys Sys corrected to ensure timely review HXPRYS J Public Service Electric & Oas Co of New Jersey 80/06/18 ip
- 8006300370 Forwards supplemental LER 79-049/01X-1 LIBRIZZ1,F P Public Service Electric & Gas Co of New Jersey 80/06/23 3pp
- --8006300373 Supplemental LER 79-049/01X-1 on 790710, during refueling outage, eram of concrete anchors for safety-related pipe supports revealed deficiencies Corrective action performed per Design Change Package IEC-593
 KAPPLE.A W Public Service Electric & Gas Co of New Jersey 80/06/23 tp
- B006300421 Forwards supplemental LER 79-013/04X-1 LIBRIZZI, P Public Service Electric & Gas Co of New Jersey 80/06/287 2pp
- --8006300424 Supplemental LER 79-013/04X-1 on 790102 during preparation of annual nonradioactive environ operating reptraverage 1978 suspended solids concentrate in discharge exceeded limit Caused by abnormally high demineralizer regenerations. KAPPLE:A W Public Service Electric & Qas Co of New Jersey 80/06/23 1p
- 8006300459 Forwards supplemental LER 78-070/01X-1 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/06/23 3pp
- --B006300465 Supplemental LER 78-070/01X-1 on 781021 during Mode 4 operation while heating up to enter Mode 3 high flow through RCP seals 5 other alarms indicating RCS leakage were observed Cause undetermined Instructions have been revised XAPPLE, A & Public Service Electric & Gas Co of New Jersey 80/06/23 1p

T. Hearing transcripts on non-antitrust matters

- 800606002B Corrections of transcript.ignoring phonetics.plurals & other minor errors.Pp 1585-1605 Certificate of Svc encl MACARTOR.J D Delaware. State of 80/05/02 3pp
- 8006130024 Proposed corrections for 800430 evidentiary hearing transcript Certificate of Svc encl METTERHAHN, M J Public Service Electric & Gas Co of New Jersey METTERHAHN, M J Conner, Moore & Corber 80/05/23 9pp
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8006030195 Forwards Hatls Engineering Branch input re water chemistry programs Wide encl RNIGHT.JP Assistant Director for Engineering 80/04/07 1p
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D 0 Division of Licensing 80/05/20 13pp
- BOOA020345 Advises that installation of insp ports & plugging of first row tubes are not prudent & should not be required Control rod guide tube support pin replacement has been completed for Unit 1 & will be done for Unit 2 CRANE,P A Pacific Gas & Electric Co 80/05/22 2pp
- 8006070150 Discusses underciad cracking in reactor vessel notitles
 Requests addl info re notitle base metal matt spec type &
 grade.clad process type.electrode size & number of clad
 layers & heat input for each clad
 SCHWENCER.A Licensing Branch 2 80/05/23 5pp
- BOOGO2016B Forwards "Description of Sys Interaction Program for Seismically-Induced Events," as suppl to 800507 rept CRANE,P A Pacific Oas & Electric Co 80/05/27 1p
- --B006020171 "Description of Sys Interaction Program for Seismically-Induced Events "
 # Pacific Gas & Electric Co 80/05/27 76pp
- BOOA03030 Requests meeting w/NRC to discuss BOO507 request for additing a retomatic switchover of ECCS Info not sufficient to conclude that switchover is either necessary or desirable CRANE.P A Pacific Qas & Electric Co BO/05/28 2pp
- 8006130119 Notification of 800604 meeting w/util in Bethesda.MD to discuss mgt organization shift staffing requirements & low power test program BUCKLEY.B C Licensing Branch 3 80/06/02 4pp
- 8006190403 Comments on facility licensing NRC should expedite licensing of nuclear power plants that meet NRC stds to meet future US energy needs HENDERSON.R Affiliation Unknown 80/06/02 1p
- BO06160040 Forwards Amend 83 to application for DL re Chapters 4A.5 & B of Hosgri rept Certificate of Svc encl CRANE.P A Pacific 9as & Electric Co 80/06/06 2pp
- --BOO6160044 Amend B3 to application for DL,re Chapters 4A.5 & B of Hosgri rept LANGLEY,E.B., CRANE,P A Pacific Gas & Electric Co BO/06/06 47na
- BOO6180627 Notification of BOO617-19 menting w/util in Ban Luis Obispo, CA to audit seismic sys interaction program BUCKLEY,B C Licensing Branch 2 80/06/06 4pp
- BO06240102 Forwards request for additional info re shielding design review.containment monitors & indine sampling & analysis sys Addl info required to continue review of response to NUREO-0578 SCHMENCER.A Licensing Branch 3 80/06/06 Gpp
- 8006190498 Advises that 12-inch containment pressure/vacuum relief valves will be limited, prior to fuel loading, to prohibit opening more than 50 degrees Limit effective until valve can be closed from more open position following postulated LOCA CRANE, P A Pacific Gas & Electric Co 80/06/13 ip

- BOO6300295 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt licensing matters w/respect to facilities have been assigned to 0 Buckiey Reorganization charts encl TEDESCOR L Assistant Director for Licensing 80/06/13 [2pp
- BOO6240416 Advises NRC that 800229 rept. "Response to NUREO-0578 Short-Term Lessons Learned Requirements." is util comprehensive response to TMI-2 incident & supersedes Jul 1979 voluntary rept CRANE, P A Pacific Oas & Electric Co 80/06/18 ip
- 8006250228 Responds to NRC 800123 ltr requesting consultation per Bection 7 of Endangered Species Act of 1973 re effects of facility aperation on five endangered species Operation not likely to jeopardize species Recommends monitoring MARTINSON.R K Interior.Dopt of, fish & Wildlife Service 80/06/19
- F Security, medical, emergency & fire protection plans
- BOOG120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, JF Commission 80/05/13 2pp
- BOO6250067 Advises that safeguards contingency plan submitted on EOO512 is acceptable & approved Plan withheld (ref 10CFR2 790) SCHMENCER: A Licensing Branch 3 80/06/06 4pp
- BOOA160039 Discusses location of principal nearsite emergency operations facility Distance factor is not critical parameter in selection of location Approval of location at San Luis Dispo County sheriff of requested CRANE,P A Pacific Gas & Electric Co BO/06/09 2pp
- Q Adjudicatory correspondence
- 800A04019A Motion for stay of proceedings pending review of affidavit of hundisclosure petitioned per present motion Affidavit implied per ASLAB 800411 second prohearing conference order is unconstitutional violating guarantees of free speech JONEB, Y I , BALDHIN, W A San Luis Obispo Mothers for Peace BALDHIN, W A 80/04/23 5pp
- --8006040196 Executed affidavit of mondisclosure re documents & info obtained from PO&E Certificate of Svc encl JONES,Y I San Luis Obispo Mothers for Peace 80/04/04 Spp
- BO06040199 Response in opposition to Hendric B00421 memorandum re participation in proceeding MRC regulations prevent participation of employee who had investigatory role on same or related case M/notice of appearance & Certificate of Evc FLEISCHAKER.D., JOHNSTON.M.P. San Luis Dispo Mothers for Peace JOHNSTON.M.P. Center for Law in the Public Interest 80/05/05
- 8004110417 Response in opposition to intervener San Luis (bispo Muthers for Peace motion to stay proceedings & polition for review of mondisclosure affidavit Petitioner failed to satisfy burden of proof Certificate of Svc enci NDRTON.8., OEHR.A G , FURBUSH.M H Pacific Gas & Electric Co 80/09/03 8pp
- B006020522 Advises that ASLAP no longer requires executed Baldwin affidavit since original notarized affidavit of nondisclosure has been received TOMPKINS, B.A. Atomic Safety and Licensing Appeal Panel 80/05/06 to
- 8006060031 Corrects MP Johnston 800505 notice of appearance.improperly listing Ctr for Law in Public Interest as client San Luis Obispo Mothers for Peace.Scenic Shoreline Preservation, Ecology Action Club et al are actual clients FLEISCHAKER.D Fleischaker.D B 80/05/21 1p
- 8006240313 Opposes on behalf of San Luis Obispo Mothers for Peace. 800517 notice of intent to permit Nordlinger participation in OL proceeding Potential conflict of interest may arise due to prior involvement w/ACRS consultant witnesses JONES, Y I Jones, Brown & Clifford 80/05/23 2pp
- BOO6110210 Motion to revise NRC 800905 response to joint intervanors' mottons to reopen 800328 record Presents RL Rothman & PT Kun 800519 joint affidavit as revision to 800505 joint affidavit Change involved does not invalidate design KETCHEN,E G Hearing Branch 4 80/06/06 3pp

- ---8006110228 Afridavit pointing out error in previous affidavit filed w/
 NRC response to intervenors' joint motion to reopen Imperial
 Valley earthquake data does not invalidate Nemark design
 response spectra for facility Certificate of Svc encl
 KUD,P T , ROTHMAN,R Office of Nuclear Reactor Regulation,
 Director 80/05/19 7pp
- 8006180519 Advises ASLAB that recent as-built audit demonstrates significant breakdown in util GA program Breakdown is magnified because pipe supports & anchors were supposedly 100% reinspected in response to NRC 1976 & 78 audits FLEISCHAKER.D Fleischaker. D S 80/06/10 3pp
- --8006180522 Responds to Items 2,3 & 4 of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Plant procedures for as-built documentation will assure strict conformitty between sys configuration & design documents LOCKE, R F Pacific Gas & Electric Co 80/04/17 3pp
- 8006120332 Notifies ASLAB that CA Governor EG Brown intends to participate in hearing re security plan issue Brown was admitted to proceeding as participant by ASLB 791116 order BROWN, H Hill Christopher & Phillips KLINE, J A , GEORGIOU, B S California, State of BO/06/11 3pp
- ---8006120334 Submits names of attys appearing on behalf of CA Governor EG Brown for security plan hearing Brown was admitted to proceeding as participant by ASLB 791116 order Certificate of Svc encl
 GROWN, H H Hill Christopher & Phillips 80/06/11 6pp
- 8006130271 Memorandum & order CLI-80-24 re intervenor San Luis Obispo Mothers for Peace access to util physical security plan Endorses ALAB-410 guidelines for making plans available. w/one exception Addl views of Commissioner Bradford encl CMILK-S J Office of the Secretary of the Commission 80/06/11 8pp
- 8006190609 Memorandum directed to parties, advising that author participation in proceeding does not violate Commission regulations or due process requirements Author will continue to take part in seismic issues HENDRIE, J M Commission 80/06/14 5pp
- 8006190559 Agrees to intervenor objection to M Nordlinger assignment as counsel re-security plan proceeding.per M Nordlinger commitment to intervenor BICKMIT.L Office of the General Counsel 80/06/17 ip
- 8006230474 Discusses forwarding of public commants re operation of facilities Messages tend to be repetitive Fails to see need to serve on all parties Ltrs not already in public record should be placed in PDR % local PDR in San Luis Obispo.CA BOWERS, E S Atomic Safety and Licensing Board Panel 80/06/17 ip
- BOO6230357 Memorandum advising parties that author did not participate in Commissioner Kennedy decision re recusancy & Commissioner Hendrie decision to take part in proceeding Author will take part in other license application matters BICKWIT, L Office of the General Counsel BO/06/18 Ip
- 8006240158 Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental environ statements on Class 9 accidents at Diablo Canyon.Rancho Seco & Palo Verde DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8006260199 Responds to 791024 petition requesting preparation of supplemental EIB re impact of Class 9 accidents at facilities No special circumstances exist which would warrant reopening proceedings Request denied DENTON-H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8006260161 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIB on Class 9 accidents No special circumstances exist which would warrant reopening environ proceedings DENTON, H R Gffice of Nuclear Reactor Regulation, Director 80/06/19 17pp
- ---8006260163 Notice of issuance of Director's decision per 2.206 denying Friends of the Earth 791024 petition to require preparation of supplemental E18 re Class 9 accidents DENTON, H R Office of Nuclear Reactor Regulation. Director 80/06/19 2pp

- B006260269 Decision ALAB-59B granting intervenors' motion to reopen record to admit Imperial Valley earthquake data Holds decision on remaining appeal in absyance until data is evaluated Now data may effect tey seismic findings BISHOP.C J Atomic Safety and Licensing Appeal Panel B0/06/24 29ap
- 8006270305 Response stating no objection to Governor EG Brown of State of CA participation in security plan hearing before ASLAB re GL proceeding Certificate of Svc encl
 TOURTELLOTTE. J Hearing Branch 4 80/06/25 4pp
- 8006300432 Order directing parties to inform ASLAB, by 800707, of option that should be selected from Commission 800611 ruling. CLI-80-24, remanding protected info issue to ASLAB Requests State of CA views, although not yet participant in OL issue BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/06/25

- 8004060504 Advises that 800512 ltr is being forwarded to Hashington, DC headquarters for inclusion in appropriate public docket file HANCHETT, J G Region 5. San Francisco. Office of the Director
 - HANCHETT, J G Region 5. San Francisco. Office of the Director 80/05/15 ip
- ---8006060507 Suggests that facility OL be granted as expeditiously as possible Further delay will cause rotating outages & inconveniences Unused facility burns abundant nuclear fuel & wastes precious oil BACCI,R R Affiliation Unknown 80/05/12 2pp
- ---B004060513 Suggests further seismic research before consideration of OL for facility Possibility exists for major earthquake in Ben Luis Chispo area Opposes opening of plant LING:D. Affiliation Unknown 80/05/09 1p
- --9006060516 Requests specific info on granting of OL for facility per W Schoenfelder inquiry Constituent bolieves unused plant wastes millions of barrels of oil every month & should be opened w/o further delay LAGOMARBING, R House of Rep 80/05/08 ip
- --8006060519 Forwards 800402 transcript of in camera hearing on security plan in San Luis Obispo.CA Applicant concerned that no special handling or identification made for security info Requests that NRC inform court reporters W/o encl NORTON.B Affiliation Unknown 80/04/28 ip
- ---8004040522 Requests that facility DL not be granted Too mang unanswered questions still remain No analysis of effects of Class 9 accident has been made # Affiliation Unknown 80/04/22 ip
- ---8006060528 Urges early licensing of facility to save rate paying citizens of GA added cost for imported oil & to save US undesirable consequences of importing approx 20 million barrels of oil per yr BASHFORD.A L Affiliation Unknown 80/04/29 ip
- --8006060530 Advises that 800402 ltr is being forwarded to Washington, DC headquarters for inclusion in appropriate public docket file HANCHETT, J G Region S, San Francisco. Office of the Director 80/04/28 to
- --8006060537 Requests that NRC consider feasibility of converting facility to natural or methane gas Inherent risk exists for nearby population if huclear accident triggers major earthquake or vice versa CLANGY,P Affiliation Unknown 80/04/02 1p
- 8006300663 FOIA request for documents re JM Hendrie participation in facility licensing proceeding. Hosgri fault or offshore faulting & UBOS studies
 JOHNSTON, M P Center for Law in the Public Interest, 80/05/15
 20p
- 8006190575 Opposes licensing of facility due to Hosgri fault & 800528 sarthquake proving that fault is active Facility licensing would be criminally irresponsible RAMLS.N Affiliation Unknown 80/05/29. 1p
- 8006190519 Opposes licensing of facility due to location near Hosgri fault Earthquake in CA is very real danger KLOPPINO, J Affiliation Unknown 80/06/02. 1p

- 8006190577 Requests that ARC reopen seismic hearings before granting facility OL due to recent Hosgri fault earthquake Plant was not designed to bear force of earthquake Fault might be capable
 ALLINA:A A Affiliation Unknown 80/06/02 1p
- 8006200540 Responds to encl 800418 ltr to President Carter expressing concern re licensing delays Delays caused by post-TMI afforts & subsequent application of "lessons learned" Facility is one of four high priority plants
 DENTON.HR Office of Auclear Reactor Regulation, Director 80/06/02 2pp
- BOO6190592 Requests that DL be denied due to earthquake along Hosgri fault BENNETTJ , DENNETT,H Affiliation Uninoum BO/06/03 ip
- 8006190597 Urges that CL be denied due to 800528 earthquake on Hosgri fault JOHNSON, L Affiliation Unknown 80/06/04 lp
- 8006300347 Forwards constituent Anson 800507 comments re wind speed assumptions used in development of nuclear emergency regulations NRC plans for public exacuation based on absolute fantasy CRANSTON. A Senate 80/06/04 App
- BOD6190460 Opposes issuance of OL due to prevalence of seismic activity in area SANDERON.J L. Affiliation Unknown BO/06/05 ip
- BOO5190465 Forwards RH Leddy BOO50B ltr expressing concern for plant safety due to proximity to earthquake fault Requests response to constituent LAGOMARSING, R J House of Rep BO/O6/O5 3pp
- 8006190450 Opposes issuance of OL due to proximity of active fault STEELE.F., STEELE.M. Affiliation Unknown 80/06/07 ip
- 8006180424 Forwards updated description of util corporate structure, reflecting establishment of nuclear power generation dept & of onsite safety review group & mgt oversight group for incorporation into FBAR CRANE.P A Pacific Gas & Electric Co 80/06/09 16pp
- 8006190514 Opposes licensing of facility due to location near Hosgri fault NRC critoria recommend that nuclear reactors should not be sited nearer than 12 1/2 miles to earthquake fault Facility is located practically on fault CATTOIR.h Affiliation Unknown 80/06/10 ig
- 8006230463 Responds to ltr re position on low power testing permit for facilities Proposed study to consider alternative approaches to energy problems will not result in delay in licensing.but will give better info on which to base decisions PANETTA.L E House of Rep 80/06/12 2pp
- 8006190441 Opposes granting of GL due to proximity to Hosgri fault Plant should be converted to non-nuclear fuel immediately MCRATEZ.P Affiliation Unknown 80/06/16 1p
- 8006300662 Responds to FQIA request for documents re JM Hendrie participation in facility licensing proceeding Hospri fault or offshore faulting & USOS studies Forwards documents listed in App A & NUREG-75/087 W/o encls
- G Inspection reports, IE Bulletins & correspondence
- 8006130057 Forwards IE Insp Rept 50-275/80-07 on 800415-17 No noncompilance noted CREMS J.L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/02 2pp
- ~-8006130067 IE insp Rept 50-275/80-09 on 800415-17 No noncompliance noted Major areas inspected preoperational test program & followup of outstanding items
 STERNBERG, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch BAGAGLIO, M J Region 5, San Francisco, Office of the Director 80/05/02 3pp
- 8006180297 Forwards response to IE Bulletins 79-06A & 79-06A; Revision i. "Review of Operational Errors & Sys Misalignments During TMI Incident " Operating procedures have been revised to incorporate Westinghouse owners group guidelines CRANE, P A Pacific Gas & Electric Co 80/05/02 App

- 8006060082 Forwards IE Insp Rept 50-275/80-11 on 800401-25 No noncompliance noted CREMS, J L Region 5, San Francisco. Reactor Operations Nuclear Support Branch 80/05/07 Spp
- --8004040084 IE Insp Rept 50-275/80-11 on 800401-25 No noncompliance noted Major areas inspected preoperational testing fire protection & operator training STERNBERG, D M · YOUNG, T Region 5, San Francisco, Office of the Director 80/05/02 3pp
- 8006250108 Forwards IE Insp Rept 50-275/80-04 on 800211-15 No noncompliance noted BOCK:HE Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/05/16 2pp
- --8006250112 IE Insp Rept 50-279/80-04 on 800211-15 No moncompliance noted Major areas inspected radiation protection & emergency response organization, staffing & training & radiation protection equipment BOOK, H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch NORTH. H S. WENSLANSKI, F Region 5. Ban Francisco, Office of the Director 80/05/16 7pp
- 8006180377 Forwards IE Insp Rept 50-275/80-12 on 800512-15 No noncompliance noted Encl withhold (ref 10CFR2 790) NORPERHAUG.L R Region 5. San Francisco. Safeguards Branch 80/06/04 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006250068 PNS-V-80-005 on 800602 contractor received bomb threat for facility from unknown caller Licenses advised & search conducted SCHUSTER.M D . NORDERHAUG.L R Region 5. San Francisco, Office of the Director 80/06/02 19
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- BOOA070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 30 48 & App R to 10EFR30 & is expected to be published in FR by end of May EISENHUT.D 9 Division of Licensing 60/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101." transmitted by NRC 800517 ltr Page 14a not encl EIGENHUT, D 9 Division of Licensing 80/05/22 /3pp
- 8006250191 Confirms 800603 corporate mgt meeting w/util in King of Prussia PA to discuss proposals for facility health physics staffing ORIER BH Region 1, Philadelphia, Office of the Director 80/05/29 ip
- 8006130324 Submits schedule for completion of mode to fire protection program.in response to NRC /90813 ltr All mode will be completed in accordance w/schedule specified in Table 3 l of 790323 fire protection SER DALTROFF.S L. Philadelphia Clectric Co 80/06/04 Rpp
- 8006110094 Forwards plant security personnel training & qualification plan SL Daltroff affidavit enc) Plan withheld (ref 100FR2 790)
 BRADLEY, E J Philadelphia Electric Co 80/06/09 Spp
- G Adjudicatory correspondence
- BOOACACT Request for extension until BOOALE for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy & intervenors have other commitments made prior to Feb 1980 Certificate of Svr encl XEPFORD, C Citizens for Safe Environment BO/05/20 App
- 8006060242 Correction to licensees' 800428 brinf on disposition of alleged Deficiency i Certificate of Svc encl BILDERO, J E Metropolitan Edison Co RADER, R M Philadelphia Electric Co RADER, R M Public Service Electric & O

- 8006170782 Forwards Waste Packaging Insp Rept 80-13 on 800313-14 No noncompliance noted SMITH.O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006170788 Waste Packaging Insp Rept 80-13 on 800313-14 No noncompliance noted Major areas inspected compliance w/DOT & NRC regulations re shipping paper & placarding requirements
 POTTER, J.P., BROWN, R.A. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 App
- 8006190243 Forwards Waste Packaging Insp Rept 80-09 on 800121-25 No noncompliance noted SMITHO H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006190249 Waste Packaging Insp Rept 80-09 on 800121-25

 No noncompliance noted Major areas inspected vehicle
 placarding.packaging conditions & packaging marking
 BOUK.H E Region 5. San Francisco, Fuel Facility & Materials
 Safety Branch FONO.F T. THOMAS.R D Region 5. San Francisco,
 Office of the Director 80/03/25 Spp
- 8006190361 Forwards Waste Pactaging Insp Rept 80-03 on 800227-29 No noncompliance noted SHITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --8006190371 Waste Packaging Insp Rept 60-03 on 800227-29
 No moncompliance noted Major areas inspected shipping paper requirements. BOT placarding requirements radiation levels. removable contamination & POT marking & labeling POTTER. J. P. PERRY. W. W. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/17 7pp
- 8006030121 Forwards response to portion of IE Bulletin 80-07 dealing w/ plants now in scheduled refueling outage Visual insp performed w/underwater TV camera Results of insp were acceptable & no reportable cracks were found DALTROFF.8 L Philadelphia Electric Co 80/05/02 3pp
- 8006020001 Responds to IE Bulletin 80-07. Item B irre BWR jet pump assembly failures Procedures for daily surveillance of jet pump parameters implemented Unit 3 jet pump beams to be inspected during next outage DALTROFF. S L Philadelphia Electric Co 80/05/07 3pp
- 8004060037 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/80-04 & 50-278/80-04 ORIER B H Region i, Philadelphia, Office of the Director 80/08/12 in
- --8006060039 Responds to NRC 800403 ltr re violations noted in IE Insp Repts 50-277/80-04 & 50-278/80-04 Corrective actions cautionary tags applied to valves & long-term mods to valves being developed DALTROFF:8 L Philadelphia Electric Co 80/04/28 App
- --8006060042 Forwards IE Insp Repts 50-277/80-04 & 50-278/80-04 on B00222-23 & 25-29 & notice of violation GRIER, B H Region 1, Philadelphia, Office of the Director B0/04/03. 2pp
- --8006040044 Notice of violation from insp on 800222-23 & 25-27
 * Region 1, Philadelphia, Office of the Director 80/03/27 2pp
- --8006060047 IE Insp Repts 90-277/80-04 & 50-278/80-04 on 800222-23 & 25-27 Noncompliance noted inadequate approved procedures for isolation valves & failure to follow procedures re mots & blocking & permit sus MCCARE, E. C. Region I, Philadelphia, Reactor Operations Nuclear Support Branch GREENMAN. E 9 , CONGILL, C J. Region I, Philadelphia, Office of the Director 80/03/27, 10pp

- R Periodic operating reports / related correspondence
- 6006170445 Forwards monthly operating repts for May 1980 CODNEY,M J. Philadelphia Electric Co. 80/06/10 1p
- --B006170446 Monthly operating tepts for May 1980 ALDEN,U M Philadelphia Electric Co 80/06/10 9pp
- 8006190339 Forwards "Annual Plant Mod Rept 1979 " ALDEN,W H Philadelphia Electric Co 80/06/13 1p
- --8006190345 "Annual Plant Mod Rept 1979 " ULLRICH,W T Philadelphia Electric Co 80/06/13 28pp
- S Reportable occurrences, LERs & related correspondence
- 8006110082 RD 2-80-10/1P on 800330-0407 & 17-22, radioactive water was released to circulating water sys Caused by flooding of normal condensor steam space permitting radioactive water to leak through defective condenser tube to water sys ULLRICH, N T Philadelphia Electric Co 80/06/04 2pp
- 8006300223 PNO-I-80-070 on 800610, licensee reported possible whole body radiation exposure of 3 118 rem of contractor employee during 2nd quarter of 1980 Dosimeter found offscale & worker actually received addl 1 574 rem on 800607 NEELY,D R, KNAPP,P J, SNITH,G H, Region 1. Philadelphia, Office of the Director 80/06/10 ip
- 8006250240 Forwards LER 80-010/01T-0 COONEY,M J Philadelphia Clectric Co 80/06/17 3pp
- --BOOA250241 LER 80-010/01T-O on BOOA03, w/unit at power, leak developed in A1 section of condenser Caused by lack of proper procedure during shutdown condition allowing hotwell level to rise Condenser tubes to be decontaminated COONEY, M J Philadelphia Electric Co 80/06/17 1P
- U Congressional/Executive Correspondence
- B005270141 Responds to B00424 ltr re arrangements made for recent meeting at facility Public announcement for meeting was issued B00301 Public announcement & mailing list for meeting encl DIRCKS.W J Office of the Executive Director for Operations B0706702 lopp
- --8006270146 Expresses concern re arrangements for 800424 meeting at facility Adequate notice of meeting was not provided SARBANES,P S Senate 80/04/24 1p
- 8006270147 Responds to 800806 it: re arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting Public announcement & mailing list encl DIRCKS, M J Office of the Executive Director for Operations 80/06/02 17pp
- ---8006270190 Comments on arrangements made for recent meeting at facility NRC should schedule another meeting to obtain further public comments & analyses on emergency response plan
 LONG.C D House of Rep., Appropriations 80/05/06 3pp
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F. Security, medical, omergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 90 48 % App R to 10CFR30 & is expected to be published in FR by end of May EISENHUT, 0 0 Division of Licensing 80/08/19 46pp
- 8006130063 Forwards revised Pages 1-14 & New Page 14a for proposed ruls 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800517 1tr Page 14a not encl EISENNUT.D 0 Division of Licensing 80/05/22 73pp
- BOO6280191 Confirms BOO603 corporate mgt meeting w/util in King of Prussia.PA to discuss proposals for facility health shysics staffing QRIER.B H Region 1. Philadelphia. Office of the Director BO/05/29 1p

- B006130324 Submits schedule for completion of mode to fire protection program, in response to NRC 790813 ltr All mode will be completed in accordance w/schedule specified in Table 3 1 of 790823 fire protection SER DALTROFF, B L Philadelphia Clectric Co 80/06/04 2pp
- BOO6110094 Forwards plant security personnel training & qualification plan SL Daltroff affidavit encl Plan withheld (ref 10CFR2 790)
 BRAOLEY, E. J. Philadelphia Electric Co. BO/O6/09 3pp
- 8006300002 Forwards comments & requests for addl info re safeguards contingency plan Encl withheld (ref 10CFR2 790) REID,R W. Operating Reactors Blanch 4 80/06/12 2pp

G Adjudicatory correspondence

- 8006060245 Request for extension until 800618 for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy & intervenors have other commitments made prior to Feb 1980 Cartificate of Svc ord!

 KEPFORD, C Citizens for Safe Environment 80/05/20 4pp
- 8006060262 Correction to licensees' 800428 brief on disposition of alleged Deficiency 1 Contificate of Svc encl SILBERG, J E Metropolitan Edison Co RADER, R M Philadelphia Electric Co RADER, R M Public Service Electric & Gas Co of New Jersey 80/05/20 5pp
- 8006060547 Response to intervenois.York Committee for Safe Environ & Citizens for Bafe Environ request for extension until 800618 to file proposed findings of fact in generic radon proceeding Many delays in proceeding are rause for concern CONNER.T B Philadelphia Electric Co CONNER.T B Conner, Moore & Corber TRAVIESO-DIA7 Netropolitan Edison Co 80/05/23 11pp
- 8006020550 Order granting extension until 800618 for York Committee for Bafe Environ & Citizens for Safe Environ to file proposed findings of fact % conclusions of law NRC findings due on 800703 % intervenors'? applicants' responses on 800718 818HOP, C. J. Atomic Safety and Licensing Appeal Panel 80/05/28 200
- 8006260207 Memorandum & order advising that Sterling issue is no longer germans to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 800702

 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/06/23

H General correspondence

- 8006170802 Discusses 800430 ltr to NRC expressing concern re arrangements for recent meeting at plant Meetings between NRC & licensees are open to public in most cases Public announcement was issued on 800331, well before meeting date DENION. HR Office of Nuclear Reactor Regulation. Director 80/05/30 lapp
- BD06270134 Responds to B00901 & OB ltrs re R Echleif & H Walters concerns about arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting M/public announcement & mailing list DIRCKS, N J Office of the Executive Director for Operations 80/06/02 19pp
- 8006270152 Responds to 800506 ltr re arrangements made for recent meeting at facility Public announcement was issued woll in advance of meeting Public announcement & mailing list entl DIRCKS.N J Office of the Executive Director for Operations 80/04/03 16pp
- --8006270155 Requests info re constituent inquiry about MRC notification of 800424 public meeting MATHIAS.C M Senate 80/05/09 ip

P. Operating license stage documents $\boldsymbol{\xi}$ correspondence

- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D © Division of Licensing 80/05/07 150pp
- 8005030514 Summary of 800422-29 meeting w/Mark I owners group in San Jose.CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES.C I Assistant Director for Plant Systems 80/05/09 8pp

- 8006130122 Requests comments on NURE9-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & Implementation schedule encl EISENHUT, D. G. Division of Licensing 80/05/19 72pp
- 8006050379 Forwards application for amend to Licenses DPR-44 & DPR-56 & related Tech Spec pages Application requests changes to Tech Specs re organization for plant operations & composition of plant operation review committee Fee encl
 BRADLEY,E J Philadelphia Electric Co 80/06/03 ip
- --80060503B3 Application for amend to Licenses DPR-44 & DPR-56, changing Tech Specs we organization for conduct of plant operations & composition of plant operation review committee Certificate of Svc enci
 BAUER, E.G., BRADLEY, E.J., BOYER, V.S. Philadelphia Electric Co. 80/96/03 App
- --8006050386 Revised Tech Spec Pages 245 % 246 re 800603 application for amend to Licenses DPR-44 % DPR-56 % Philadelphia Electric Co 80/06/03 2pp
- 800&130279 Advises that high range effluent noble gas monitor sys meets criteria of Lessons Learned Task Force short-term requirements w/exception of ANSI N32b-1979 which requires sys presently unavailable DALTROPE, S.L. Philadelphia Electric Cu BO/06/04 3pp
- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-0619, "BWR Feedwater Noirie & Control Rod Drive Return Line Noirie Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT, D O Division of Licensing 30/06/05 22pp
- 8006300526 Requests that rept detailing major additions/changes to onsite waste storage be included in monthly operating rept until applicable App I Tech Specs are incorporated into OLs Requests comments on encl draft licensing position REID.R W Operating Reactors Branch 4 80/06/12 11pp
- 8006200487 Responds to NRC 800513 ltr requesting info re low pressure turbine disc cracking Info includes background technical & historical data. insp on turbine rotors, steam chemistry & safety related impact No cracking revealed DALTROFF, B. L. Philadelphia Electric Co. 80/06/13 14pp
- 800.6260176 Forwards util positions re five add1 THI-2 related requirements discussed in NRC 800507 ltr Mod requirements will be reviewed by BMR owners group Util evaluation of GE 800221 response to Michelson concerns one!

 DALTROFF, B L Philadelphia Electric Co 80/06/20 8pp
- 8006260181 Forwards revised schedule for implementation of containment suppression chamber mods to conform w/Mark 1 long-term program acceptance criteria KEMPER.J B Philadelphia Electric Co 80/06/20 2pp
- @ Inspection reports. IE Bulletins & correspondence
- B006200079 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director B0/04/IB 1p
- 8006170395 Forwards Waste Packaging Insp Rept 80-20 on 800128-0201 No noncompliance noted BMITH: O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --B00617039B Waste Packaging Insp Rept 80-02 on 800128-0201 No noncompliance noted Major areas inspected waste shipments & packages, vehicle placarding, packaging conditions & labels B00K.H E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch THOMAS.R D Region 5. San Francisco. Office of the Director BROWNE.W & Advanced Fuel & Spent Fuel Licensing Branch 80/03/31 10pp
- 8006190243 Forwards Waste Packaging Insp Rept 80-09 on 800121-25 No nuncompliance noted SMITH, G H Region I. Philadelphia, Puel Facility & Materials Bafety Branch 80/04/24 2pp
- ---8006190249 Waste Packaging Insp Rept 80-09 on 800121-25
 No noncompliance noted Major areas inspected vehicle
 placarding, packaging conditions & packaging marking
 BOOK,HE Region 5, Ban Francisco, Fuel Facility & Materials
 Bafety Branch FONG.FT. THOMAS.R D Region 5, Ban Francisco,
 Office of the Director 80/03/25 5pp

- B006030121 Forwards response to portion of IE Bulletin 80-07 dealing w/plants now in scheduled refueling outage Visual inspiperformed w/underwater TV canera Results of inspipere acceptable 1 no reportable cracks were found DALTROFF/S L Philadelphia Electric Co 80/05/02 3pp
- BOO6020601 Responds to IE Bulletin BO-07. Item B 1.re BWA jet pump assembly failures Procedures for daily surveillance of jet pump parameters implemented Unit 3 jet pump beams to be inspected during nert outage DALTROFF. S.L. Philadelphia Electric CO BO/05/07 3pp
- B006060037 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-277/80-04 & 50-278/80-04 GRIER, B H. Region 1 Philadelphia Office of the Director B0/05/12 1p
- --800A060039 Responds to FRC 800403 ltr re violations noted in IE Insp Repts 50-277/80-04 & 50-278/80-04 Corrective actions cautionary tags applied to valves & long-term mods to valves being developed DALTROFF, S L Philadelphia Electric Co 80/04/28 App
- --800&060042 Forwards IE insp Repts 50-277/80-04 & 50-278/80-04 on 800222-23 & 25-27 & notice of violation GRIER.B H Region 1. Philadelphia, Office of the Director 80/04/03 Zpp
- ~-8004040044 Notice of violation from insp on 800222-23 & 25-29 • Region 1. Philadelphia Office of the Director 80/03/27 2pp
- --800A050047 IE Insp Repts 50-277/80-04 % 50-278/80-04 on 800222-23 % 20-29 Noncompliance noted inadequate approved procedures for isolation valves & failure to follow procedures re mods & blocking & perrit sys MCCABE.E C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch GREENMAN.E G. COMOILL.C J Region 1, Philadelphia, Office of the Director 60/03/27 10pp
- B006060557 Advises that response to IE Bulletin 79-01B will be submitted by 800617 Environ profiles for LCCA to high energy line break requires further refinement by Bechtol OALLAOMER. J W Philadelphia Electric Co 80/05/12 lp
- BOOM120423 Forwards request for add1 info re cracking in low pressure turbins discs Recommends development of ultrasonic insp for next fuel outage IE Info Notice 79-37 & summary of BOO109 meeting w/GE Encl REID,R U Operating Reactors Branch 4 80/05/13 3pp
- R Periodic operating reports & related correspondence
- 8006170445 Forwards monthly operating repts for May 1980 CDDNEY, M J Philadelphia Electric Co 80/06/10 ip
- --8006170446 Monthly operating repts for May 1980 ALDEN,W M Philadelphia Electric Co BD/06/10 9pp
- 8006190339 Forwards "Annual Plant Mod Rept 1979 " ALDEN, H M Philadelphia Electric Co 80/06/13 1p
- --B006190345 "Annual Plant Mod Rept 1979 "
 ULLRICH, N T Philadelphia Electric Co 80/06/13 28pp
- E Reportable occurrences. LERs & related correspondence
- 8006230566 RO 3-79-30/IP on 791002.smismic anchor insp program identified failure in support associated w/loop B core spray distharge line Caused by improper installation of anchor bolt Replacement of two failed bolts is in progress ULLRICH, W T Philadelphia Electric Co 79/IQ/03 2pp
- U Congressional/Executive Correspondence
- 8006270141 Responds to B00424 ltr re arrangements made for recent meeting at facility Public announcement for meeting was issued B00331 Public announcement & mailing list for meeting and DIRCKS.N J Office of the Elecutive Director for Operations 80/06/02 16pp
- --8006270146 Expresses concern re arrangements for 800424 meeting at facility Adequate notice of meeting was not provided SARBANES,P S Senate 80/04/24 1p

- 8006270147 Responds to 800506 Itr re arrangements made for recent meeting at facility Public announcement was issued well in advance of meeting Public announcement 5 mailing list encl DIRCKS W J Office of the Executive Director for Operations 80706/02 17pp
- --8006270150 Comments on arrangements made for recent meeting at facility NRC should schedule another meeting to obtain further public comments 2 analyses on emergency response plan LONG C D House of Rep . Appropriations 80/05/06 3pp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1

 F Security, medical, emergency 2 fire protection plans
- B006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 105FR50 % is expected to be published in FR by end of May EISENHUT.D G Division of Licensing 80/05/19 46pp
- B006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 8000317 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- 8006040174 Responds to NRC 800515 request for util review of guard training & qualification plan Anticipates forwarding response by 800714 SYLVIA:B R Virginia Electric & Power Co 80/05/29 Ip
- 8006260167 Forwards review of addl info provided in 790809.1113 to 800114 ltrs re fire protection program Status of review also and Util should attempt to improve schedule to complete mods by 801101 VAROA.S A Operating Reactors Branch 1 80/05/27 App
- 8006050323 Forwards amended security plan Plan withheld (ref 10CFR2 790) SYLVIA:B R Virginia Electric & Power Co 80/06/03 1p
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams 2 licensee dissemination of operating experiences Response requested within 30 days EISENHUT,D 9 Division of Licensing 80/09/07 150pp
- BOO6130297 Application to amend Licenses DPR-32 & DPR-37, clarifying term "operable." submitted as proposed Tech Spec Change 86, in response to NRC 600410 ltr Certificate of Svc encl FEROUSON, J H Virginia Electric & Power Co 60/05/16 3pp
- --8006130299 Fech Spec Change Request 86 for Toch Specs 1 0-2,3,0-1-3 0-4,3 7-2,3 9-1,3,9-2,3 10-3,3 10-4,3 11-3,3 11-5 3 18-1 & 3 21-1-3 21-5 revising term "operable" & clarifying applicability

 * Virginia Electric & Power Co 60/05/16 3pp
- BOO6130122 Requests comments on NUREC-0977, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D G Division of Licensing 80/05/17 72pp
- 8006020173 Advises that, contrary to date stated in 800428 ltr, temporary post-accident containment atmospheric sys will be installed by 800630, per NUREO-0578 Permanent sys will be installed by 810101 Sketches encl
 SYLVIA.B R Virginia Electric & Power Co 80/08/RB 4pp
- 8006200521 Forwards comments on proposed amend to Tech Spocs Util must forward response to comments on offsite dose calculation manual & process control program re-solidification of radwastes within 45 days

 VARGA, S.A. Operating Reactors Branch 1 80/06/04 45pp
- 8006110063 Provides commitment to meet addi TMI-2 related requirements, identified in NRC 800507 ltr.providing equipment procurement schedules da not impact implementation of hardware changes SYLVIA.B R Virginia Electric & Power Co 80/04/06 1p

- BOO6130334 Proposes multiphase plan to address NRC concerns re multistructure amplified response spectra being used to analyre piping sys in low head & high head safety injection lines List of multistructure problems & sample problem encl SYLVIA.B R Virginia Electric & Power Co 80/06/06 18pp
- B006170699 Discusses 800522 maeting w/NRC re test results of containment spray sys mods Data curves re post-LOCA sump pH vs time & proposed Tech Spec changes forwarded 800605, per NRC reducst final rept will be sent 800618

 SYLVIA, B R Virginia flectric & Power Co 80/06/11 2pp
- 8006190545 Forwards "Caustic Feed Design Analysis. Design Change 77-9 Containment Spray Sys Mod." 3 "Refueling Water Storage Tank - Chemical Addition Tank Drawdown Test. 800430 " Repts available in Central Files only SYLVIA-8 R Virginia Electric 7 Power Co 80/06/18 1p
- 8006190562 Forwards "Low Head Safety Injection Pump Performance Rept Mark Number 2-51-P-18." & "Vibration Test of Low Head Safety Injection Pump.Mark Number 2-51-P-18." available in Central Files only SYLVIA.B R Virginia Flectric & Power Co 80/06/18 1p
- 8006230507 Forwards "6-Inch Cavitating Venturi Performance Tests," Hydraulics Program Rept 24 Completes response to NRC 780101 request for addl info re NPSH mods SYLVIA:BR Virginia Electric & Power Co 80/06/19 2pp
- 8006300388 Confirms agreement re review criteria for control rod bank reactivity worth tests Modified Table A 2 of VEP-FRD-36, "Control Rod Reactivity Worth Determination by Rod Swap Technique" encl THOMAS, W N Virginia Electric & Power Co 60/06/26 App
- B006300456 Forwards history of experienced total & partial power outages at facilities, per NRC 800509 request SYLVIA, B R Virginia Flectric & Power Co 80/06/26 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --8005230341 Waste packaging inspirept on 800313-14 No noncompliance noted Major areas inspected licensed-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DUT placarding requirement POTTER, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/28 4pp
- B006160190 Forwards IE Insp Repts 50-280/80-09 & 50-281/80-10 on B00407-09 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/20 2pp
- --8006160196 IE Insp Repts 90-280/80-09 % 50-281/80-10 on 800407-09 No noncompliance noted Major areas inspected const status, action on previous insp findings & quality records RAUSCH, J K Region 2, Atlanta, Reactor Construction & Engineering Support Branch WILCOX, J D, MCFARLAND, C F Region 2, Atlanta, Office of the Director 80/04/29 3pp
- 8004040581 Forwards IE Insp Repts 50-280/80-15 & 50-281/80-16 on 800415-18 No noncompliance noted LEWIG.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/01 2pp
- --8006060585 IE Insp Repts 50-280/80-15 & 50-281/80-16 on 800415-18 No nancompliance noted Major areas inspected records mpt program & inservice pump & valve testing program & inservice pump & valve testing program UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch MESSITT.B R Region 2. Atlanta, Office of the Director 80/05/01 4pp
- 8006090066 Forwards IE Insp Repts 50-280/80-14 & 50-281/80-15 on 800416-18 No noncompliance noted MVRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/02 2pp
- --8006090074 IF Insp Repts 50-280/80-14 & 50-281/80-15 on 800416-18 No noncompliance noted Major areas inspected installed equipment review per IE Bulletin 79-018 response CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARDWICK.R J Region 2. Atlanta, Office of the Director 80/05/01 4pp

- 8006060515 Forwards IE Bulletin 80-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Luads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp
- 8006040248 Forwards IE Builetin 80-12, "Decay Heat Removal Sys Operability " Requires action & response within 30 days IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09 2pg
- 8006200514 Forwards IE Insp Repts 50-280/80-11 & 50-281/80-12 on 800415-17 No noncompliance noted STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/09 2pp
- --8006200516 IE Insp Repts 50-280/80-ii & 50-28i/80-i2 on 800415-i7 No noncompliance noted Major areas inspected steam generator shipment & action on previous insp findings GIRSON, A F Region 2, Atlanta, Fuel Facility & Materials Bafety Branch EMALD, & C Region 2, Atlanta, Office of the Director 80/05/09 Spp
- 8006300137 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/13 2np
- B006300237 Forwards IE Insp Repts 50-280/80-18 & 50-281/80-18 on B00427-0502 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/05/20 2pp
- ---8006300243 IE Insp Repts 50-280/80-18 % 50-281/80-18 on 800429-0502 No noncompliance noted Major areas inspected IE Bulletins 79-02 % 79-14 % licensee actions on previous insp items COMPTON R M Region P, Atlanta, Office of the Director HERDT A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 Spp
- 8006130195 Forwards nutice of violation & notice of proposed imposition of civil penalties re failure of surveys to detect package on 800414 exhibiting high radiation levels STELLOV Office of Inspection & Enforcement, Office of the Director 80/05/28 2pp
- ---8006130199 Notice of violation from insp on 800423-25 Noncompliance noted failure of surveys to detect package for transport on 800414 exhibiting high radiation levels * Office of Inspection & Enforcement, Office of the Director 80/05/28 1p
- --BOD6130204 Notice of proposed imposition of civil penalties in amount of \$8,000 re failure of surveys to detect package for transport on 800414 exhibiting high radiation levels # Office of Inspection & Enforcement, Office of the Director 80/05/28 ip
- 8006250292 Advises that responses to IE Bulletins 79-06 & 79-06A, Revision I,were found acceptable Branch evaluation encl VAROA.S A Operating Reactors Branch 1 80/05/28 16pp
- 8006240068 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/80-01 & 50-281/80-03 LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 ip
- 8006200604 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "No equipment on other instrument & control power busse is needed to maintain hot or cold shutdown condition

 BYLVIA, B R Virginia Electric & Power Co 80/05/30 54pp
- 8006090388 Responds to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Forwards WCAP-6938, "Metallurgical Investigation of Cracks in Steam Generator Feedwater Lines of Surry Station 1 " SYLVIA.B R Virginia Electric & Power Co 80/06/03 ip
- --8006090396 "Metallurgical Investigation of Cracks in Steam Generator Feedwater Lines of Surry Station i " ALBERTIN-L : RAO,0 V . ENRIETTO.J Westingbouse Electric Corp . Nuclear Energy Systems WCAP-9638 79/12/31 47pp

- 8006230098 Ack receipt of 800522 Itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-08 & 50-281/80-09 MURPHY C E Region 2. Atlanta Reactor Construction & Engineering
 - Support Branch 80706704
- --8006230114 Forwards 1E Insp Repts 50-280/80-08 & 50-281/80-09 on 800415-18 & notice of violation HURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --8006230118 Notice of violation from insp on 800415-18 * Region 2, Atlanta, Office of the Director 80/0 80/04/30 10
- ---8006230126 IE Insp Repts S0-280/80-08 & 50-281/80-09 on 800415-18
 Noncompliance noted nonfunctional fire door between
 emergency switchgear room & svc bldg cable vault & failure
 to implement fire protection procedures
 CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering
 Support Dranch 80/04/30 17pp
- 800A2301B3 Ack receipt of 800513 ltr informing NRC of steps taken to correct violation moted in IE lnsp Repts 50-280/80-04 & 50-281/80-04 STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/05 1p
- --8006230189 Responds to NRC 900418 ltr re violation noted in IE Insp Repts 50-280/80-04 & 50-281/80-06 Corrective actions designated emergency directors were retrained per emergency SYLVIA.B R Virginia Electric & Power Co 80/05/13 2pp
- --8006230179 Forwards IE Insp Repts 50-280/80-04 & 50-281/80-06 on 800310-14 & notice of violation STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/18 Zpp
- --8006230198 Notice of violation from insp on 800310-1/
 * Region 2, Atlanta, Office of the Director 80/6 80/04/11 in
- --B006230202 IE Insp Repts 50-280/80-04 & 50-281/80-06 on 800310-14
 Noncompliance noted failure to conduct retraining for
 designated emergency directors per emergency plans
 JENKINS. Q R Region 2, Atlanta, Fuol Facility & Materials Bafety
 Branch PERROTTI.D J , ANDREWS.D L Region 2, Atlanta, Office of
 the Director 80/04/11 12pp
- 8006250094 Ack receipt of 800522 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-280/80-13 & 50-281/80-14 LEHES, R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/06/06 ip
- --B006250079 Forwards response to NRC 800428 itr re violation noted in IE Insp Repts 50-280/80-13 & 50-281/80-14 Encl withheld (ref 10CFR2 790) SYLVIA.B R Virginia Electric & Power Co 80/05/22 ip.
- --8006250103 Forwards IE Insp Repts 50-280/80-13 & 50-281/80-14 on 800228-0304 & 0310-0403 & notice of deviation Notice of violation withheld (ref 10CFR2 790) LEMIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/28 2pp
- --8006250104 Notice of deviation from insp on 800225-0304 & 0310-0403 * Region 2, Atlanta, Office of the Director 80/04/23 ip
- --8006250107 IE Insp Repts 50-280/80-13 & 50-281/80-14 on 800225-0304 & 0310-0403 Noncompliance noted facility not built as described in FBAR & one apparent item of noncompliance in plant security Portions withheld (ref 100FR2 790) KELLOGO,P J Region 3. Chicago, Reactor Deprations Nuclear Support Branch SURKE,D J Region 3. Chicago, Office of the Director NRC 80/04/23 4pp
- 8006240238 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Two potential problem areas involving boron evaporator bottoms tank & boric acid storage tanks identified 8YLVIA:
- 8006300253 Forwards response to IE Bulletin 80-09 Hydramotor actuator Hodels AH-90 & NH-90 are not used at facility SYLVIA.BR Virginia Electric & Power Co BO/06/10 3pp

- 8006300235 Forwards response to IF Bulletin 80-12 re decay heat removal sus operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if subsystem is operable SYLVIA.BR Virginia Electric & Power Co 80/06/11 App
- BOO6300349 Responds to IC Bulletin 80-06 requesting review of drawings for all sys serving safety-related functions at schematic level, verification of controls & proposed design mods Actions & schedules delineated in Item 3
 SYLVIA.B R Virginia Fiectric & Power Co 90/06/12 10pp
- 8006240484 Resounds to NRC 800528 1tr re violations noted in IE Insp NO24444 Respins to NRC 8003-8 It For Politicions intelligible.

 Rept EA-80-28 Corrective actions radwaste section completely restaffed w/personnel having formal radwaste training SYLVIA, B R Virginia Electric & Power Co 80/06/20 5pp
- 8006300673 Forwards payment for civil penalty proposed in 800528 notice arising from IE Insp Repts 50-280/80-16 & 50-281/80-17 Response to repts will be forwarded separately SYLVIA.B R Virginia Electric & Power Co 80/06/20 3pp
- 8006240356 Responds to NRC 800527 ltr re violations noted in IE Insp Repts 50-280/80-19 % 50-281/80-19 on 800407-0502 Corrective actions increased emphasis will be applied to senior reactor operator & reactor operator retraining sessions SYLVIA:B R Virginia Electric & Power Co 80/06/23 4pp
- R Periodic operating reports & related correspondence
- 8006170513 Forwards monthly operating repts for May 1980 SYLVIA.B R Virginia Electric & Power Co 80/06/12
- --8006170517 Monthly operating repts for May 1980 BAUNDERS, R. COSTELLO, D. J. Virginia Electric & Power Co 80/06/05 49pp
- S Reportable occurrences. LERs & related correspondence
- 8004090545 EN-80-019 notice of violation & notice of proposed imposition of civil penalties will be issued on or about HO0528 Action based on two alleged items of noncompliance relating to improper radiation surveys of waste drums BROCKETIT.T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/05/23 ip
- 8004030334 Forwards LFRs 80-025/03L-0 & 80-030/01T-0 WILSON, J L Virginia Electric & Power Co 80/05/3
- --8006030348 LER BO-025/03L-0 on 800509, during performance of penetrant test 16 4 w/unit at cold shutdown, leakage determined to exceed allowable rate Caused by normal wear from operational use All valves w/leakage repaired or replaced HILSON, J L. Virginia Electric & Power Co. 80/05/30. 3pp
- ---8006030356 LER 80-030/01T-0 on 800520, during routine chemistry sampling of boric acid storage tank A & injection tank boric acid concentration found above limit Caused by addition of excessive amount of boric acid prior to sampling WILSON.J T Virginia Electric & Power Go 80/05/30 2pp
- 8006120319 Forwards LERs 80-027/03L-0 & 80-028/03L-0 WILSON, J L Virginia Electric & Power Co 80/06/0 80/06/05
- --8006120323 LER 80-028/03L-0 on 800516, while releasing waste gas decay tank 1-GW-TK-18, operator observed that tank was still lined up to receive gaseous waste Caused by inlet valve to tank inadvertently left opened Release terminated WILSON, J L Virginia Electric & Power Co 80/06/05 2pp
- --8006120328 LER 80-027/03L-0 on 800512, discharge valve for i-LW-P-8A was inadvertenly left open causing unsampled release from 1-LW-TK-11A thru gravity flow Caused by discharge valve 1-LW-247 inadvertently left openod Release terminated WILSON, J L Virginia Electric & Power Co 80/06/05 3pp
- BOO6110324 RO several lines in low head & high safety injection sys-were not analyzed for effects of fluid temp below 70 F Review of new norzle loads showed load on pump exceeded vendor allowable load Multiphase program proposed SYLVIA:B R Virginia Electric & Power Co 80/06/06 18pp
- 8006230497 Proposes multi-phase plan to address NRC concerns re amplified response spectra curves used as basis for analyses when plying sys is subjected to more than one spectra SYLVIA:8 R Virginia Electric & Power Co 80/06/06 iipp

- ~-8006170662 LER 80-031/03L-0 on 800528 during power operation low temp heat tracing alarm revealed railure of heat tracing circuit 2 on panel 8 Alarm caused by defective circuit breaker Breaker replaced & heat tracing operability verified WILSON.J L Virginia Electric & Power Co 80/06/12 2pp
- 8006180470 Fowards LER 80-033/01T-0 WILSON, J L Varginia Electric & Power Co 80/06/12 ip
- --800A180476 LER 80-033/01T-O on 800530 assumed value for spray notile thermal effectiveness for outside recirculation spray sys was less conservative than assumed in NPSH mod analysis Caused by error in NPSH calculations
 WILSON, U.L. Virginia Electric & Power Ca. 80/06/12 2pp
- 8006240427 Forwards LER 80-036/01T-0 WILBON.J L Virginia Electric & Power Co 80/06/20 in
- --B004240434 LER 80-036/01T-O on 800411.Westinghouse datermined that following secondary side high energy line rupture.potential exists for damaging of one or more charging pumps Damage could result if RCS pressure approaches 2.400 psig WILSUN.J i Virginia Electric & Power Co 80/06/20 3pp
- 8006270279 Forwards LERs 80-034/03L-0 & 80-035/03L-0 WILSON, J L Virginia Electric & Power Co 80/06/23 2pp
- --8006270287 LER 80-034/03L-0 on 800603.w/unit critical at 0% power,amp readings for circuit 24D.Panel 2 found below acceptance criteria Caused by excessive heat Initiated design mod to change manner by which borated lines are heat traced WILSON.J L Virginia Electric & Power Co 80/06/23 2pp
- ---8006270294 LER 80-035/03L-0 on 800603. w/unit critical at 0% power, amp readings for Circuit 22A,Panel 2 found below acceptance criteria Cause not stated Heat tracing tape completely replaced No addl action required WILSOM'U Virginia Electric & Power Co 80/06/23 ip
- DOCKET 50-281 SURRY POWER STATION, UNIT 2

 F Security, medical, emergency 3 fire protection plans
- B006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D G Division of Licensing 80/05/19 46pp.
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101;" transmitted by NRC 800517 ltr Page 14a not encl
 EISENHUT.D 9 Division of Licensing BD/05/22 73pp
- 8005040174 Responds to NRC 800515 request for util review of guard training & qualification plan Anticipates forwarding response by 800714 SYLVIA:8 R Virginia Electric & Power Co 80/05/27 ip
- 8006260167 Forwards review of addl info provided in 790809,1113 & 800114 ltrs re fire protection program Status of review also encl. Util should attempt to improve schedule to complete mods by 801101 VARGA, S A Operating Reactors Branch 1 80/05/29 6pp
- 8006050323 Forwards amended security plan Plan withheld (ref 10CFR2 790) SYLVIA.B R Virginia Electric & Power Co 80/06/03 1p
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. licensing exams 2 licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D G Division of Licensing 80/05/07 150pp
- B004020435 Forwards Amend 58 to License DPR-37, safety evaluation & notice of issuance & availability
 SCHWENCER, A Licensing Branch 1 80/05/14 2pp

- --8006020440 Amend 58 to License DPR-37.changing heat flux hot channel factor to 2 19 based on LOCA-ECCS analysis w/3% steam generator tube plugging limit SCHWERCER.A Licensing Branch 1 80/05/16 18pp
- --8006020443 Safety evaluation supporting Amend 58 to License DPR-37

 * Office of Nuclear Reactor Regulation, Director B0/05/16 Sp
- --8006020445 Notice of issuance & availability of Amend 58 to License DPR-97 SCHWENCER, A Licensing Branch 1 80/05/16 2pp
- 8006130297 Application to amend Licenses DPR-32 & DPR-37, clarifying term "operable." submitted as proposed Tech Spec Change 86, in response to NRC 800400 ltr Certificate of Svc encl FERGUSON, J H Virginia Electric & Power Co 80/05/16 3pp
- --8004130279 Tech Spec Change Request 86 for Tech Specs 1 0-2,3,0-1-3 0-4,3 7-2,3 9-1,3,9-2,3 10-3,3 10-4,3 11-3,3 11-5 3 18-1 & 3 21-1-3 21-5, revising term "operable" & clarifying applicability # Virginia Electric & Power Co 80/05/16 3pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamollar Tearing on PWR Steam Opnerator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D 0 Division of Licensing 80/05/19 72pp
- 8006020173 Advises that, contrary to date stated in 800428 ltr, temporary post-accident containment atmospheric sys will be installed by 800630.per NUREG-0578 Permanent sys will be installed by 810101 Sketches encl
 8YLVIA.B R Virginia Slectric & Power Co 80/05/28 4pp
- 8006200521 Forwards comments on proposed amend to Tech Specs Util must forward response to comments on offsite dose calculation manual 5 process control program re solidification of radwastes within 45 days

 VARGA.8 A Uperating Reactors Branch 1 80/06/04 45pp
- 8006110063 Provides commitment to meet add1 TMI-2 related requirements, identified in NRC 800507 ltr.providing equipment procurement schedules do not impact implementation of hardware changes SYLVIA.B R Virginia Electric & Power Co 80/06/06 ip
- 8006130334 Proposes multiphase plan to address NRC concerns re multistructure amplified response spectra being used to analyze piping sys in low head & high head safety injection lines List of multistructure problems & sample problem encl SYLVIA.B R Virginia Electric & Power Co 80/04/06 18pp
- 8004170697 Discusses 800922 meeting w/NRC re test results of containment spray sys mods Data curves re post-LOCA sump pH vs time & proposed Tech Spec changes forwarded 800605, per NRC request Final rept will be sent 800618

 SYLVIA.8 R Virginia Electric & Power Co 80/06/11 2pp
- GOO6180247 Resubmitts "Rept on Reanalysis of Safety-Related Sys, Burry Power Station, Unit 2," Revision 1 Original submittal contained errors NELGON, H W Ebasto Services, Inc (subs of Enserch Corp.) 80/06/12 3pp
- --BOOA180253 "Rept on Reanalysis of Safety-Related Bys.Surry Power Station. Unit 2." Revision I resubmitted due to errors in original submittal * Ebasco Services, Inc (subs of Enserch Corp) 80/04/11 100pp
- 8006190545 Forwards "Caustic Feed Design Analysis.Design Change 77-9 Containment Spray Sys Mod." & "Refueling Water Storage Tank - Chemical Addition Tank Drawdown Test.800430 " Repts available in Central Files only SYLVIA:B R Virginia Electric & Power Co 80/06/18 ip
- 8006190562 Forwards "Low Head Safety Injection Pump Performance Rept Mark Number 2-81-P-18." & "Vibration Test of Low Head Bafety Injection Pump Mark Number 2-81-P-18." available in Central Files only SYLVIA.B R Virginia Electric & Power Co 80/06/18 ip
- BOO4230507 Forwards "6-Inch Cavitating Venturi Performance Tests," Hydraulics Program Rept 24 Completes response to NRC 780101 request for adul info re NRSH mods SYLVIA,B R Virginia Electric & Power Co BO/06/19 2pp

- 800630038B Confirms agreement re review criteria for control rod bank reactivity worth tests Modified Table A 2 of VEP-FRD-36.
 "Control Rod Reactivity Worth Determination by Rod Swap Technique" encl
 THOMAS.W N Virginia Electric & Power Co 80/06/26 App
- B006300456 Forwards history of experienced total & partial power outages at facilities.per NRC B00509 request
 SYLVIA:B R Virginia Electric & Power Co B0/06/26 App
- @ Inspection reports, IE Bulletins & correspondence
- 8006160190 Forwards IE Insp Repts 50-280/80-09 & 50-281/80-10 on 800407-09 No noncompliance noted MURPHY: E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/30 2pp
- --B006160196 It Insp Repts 50-280/80-09 t 50-281/80-10 on B00407-09 No noncompliance noted Major areas inspected Const status, action on previous insp findings t quality records RAUSCH,J K. Region 2, Atlanta, Reactor Construction t Engineering Support Branch WILCOX.J D. MCFARLAND, C.F. Region 2, Atlanta, Office of the Director 80/04/29 3pp
- 8006060581 Forwards IE Insp Repts 50-280/80-15 & 50-281/80-16 on 800415-18 No noncompliance noted LEWIS.R C Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/05/01 2pp
- --800Å0Å0585 IE Insp Repts 50-280/80-15 % 50-281/80-16 on 800415-18 No noncompliance noted Major areas inspected records mgt program & inservice pump & valve testing program UPRIGHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch MESSITI.B R Region 2, Atlanta, Office of the Director 80/05/01 4pp
- 8006090066 Forwards IE Insp Ropts 50-280/80-14 & 50-281/80-15 un 800416-18 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/02 2pp
- --800&070074 IE Insp Repts 50-280/80-14 & 50-281/80-15 on 800416-18 No noncompliance noted Major areas inspected installed equipment review per IE Bulletin 77-018 response COMLON TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARDWICK, R J Region 2. Atlanta, Office of the Director 80/05/01 4pp
- 8006060515 Forwards IE Bulletin 80-11. "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" enc!

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 800604024B Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Requires action & response within 30 days IE Info Rotice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09 20n
- 8006200514 Forwards 1E Insp Repts 50-280/80-11 & 50-281/80-12 on 800418-17 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/09 2pp
- --B004200515 IE Insp Repts 50-280/80-11 & 50-281/80-12 on 800415-17 No noncompliance noted Major areas inspected steam generator shipment & action on previous Insp findings OIBBON A F Region 2. Atlanta. Fuel Facility & Materials Bafety Branch EMALD S C Region 2. Atlanta, Office of the Director 80/03/09 5pp
- 8006300137 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 200
- 8006300237 Forwards IE lnsp Repts 50-280/80-18 & 50-281/80-18 on 800427-0502 No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 2pp
- --8006300243 IE Insp Repts 50-280/80-18 % 50-281/80-18 on 800429-0502 No noncompliance noted flajor areas inspected IE Bulletins 79-02 % 79-14 % licensee actions on previous insp items COMPTON.R M. Region 2. Atlanta. Office of the Director HERDI, A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/20 5pp

- 8006130195 Forwards notice of violation % notice of proposed imposition of civil penalties re failure of surveys to detect package on 800614 exhibiting high radiation levels STELLO. V Office of Inspection & Enforcement, Office of the Director 80/05/28 2pp
- --8006130199 Notice of violation from insp on 800423-25 Nancompliance noted failure of surveys to detect package for transport on 800414 eximilating high radiation levels * Office of Inspection & Enforcement, Office of the Director 80/05/28 10
- --8006130204 Notice of proposed imposition of civil penalties in amount of \$B.000 re failure of surveys to detect package for transport on 800414 exhibiting high radiation levels

 * Office of Inspection & Enforcement, Office of the Director 80/05/23 1p
- 8006230292 Advises that responses to IE Bulletins 79-06 & 79-06A, Revision 1,were found acceptable Branch evaluation encl VAROA, S.A. Operating Reactors Branch 1 80/05/28 16pp
- B006240068 Ack receipt of B00509 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-280/80-01 & 50-281/80-03 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/05/29 1p
- 8006200604 Responds to IE Sulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "No equipment on other instrument 2 routrol power buses is needed to maintain hot or cold shouldown condition SYLVIA.B R Virginia Electric & Power Go 80/05/30 54pp
- 8006230098 Ack receipt of 800522 ltr informing NRC of steps taken to correct violation noted in IC Insp Repts 50-280/80-08 & 50-281/80-09 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/04 19
- --8006230114 Forwards IE Insp Repts 50-280/80-08 \$ 50-281/80-09 on 800415-18 & notice of violation HURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/05/01 2pp
- --8004230118 Notice of violation from insp on 800415-18 * Region 2, Atlanta, Office of the Director 80/04/30 ip
- --8006230126 IE Insp Repts 50-280/80-08 \$ 50-281/80-09 on 800415-18

 Nancompliance noted honfunctional fire doon between energency suitchgear room & svc bidg cable vault & failure to implement fire protection procedures
 CONLON.T C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 17pp
- 8006230183 Ack receipt of 800513 ltr informing NRC of steps taken to correct violation noted in IE lasp Repts 50-280/80-04 & 50-281/80-06 STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/06/05 ip
- --8004230187 Responds to NRC 800418 ltr re violation noted in IE Insp Repts 50-280/80-04 & 50-281/80-06 Corrective actions designated emergency directors were retrained per emergency plan BYLVIA,D R Virginia Ejectric & Power Co 80/05/13 2pp
- ~-8004230195 Forwards IE Insp Repts 50-280/80-04 & 50-281/80-04 on 800310-14 & notice of violation STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/04/18 2pp
- ~-B006230198 Notice of violation from insp on 800310-14
 * Region 2, Atlanta, Office of the Director 80/04/11 ip
- ~-800A230202 IE lnsp Repts 50-280/80-04 & 50-281/80-06 on 800310-14
 Noncompliance noted failure to conduct retraining for
 designated energency directors per emergency plans
 JENKINS.O R Region 2, Atlanta. Fuel Facility & Materials Safety
 Branch PERROTTI.D J. ANDREWS.D L. Region 2, Atlanta, Office of
 the Director 80/04/11 12pp
- 8008250094 Ack receipt of 800522 ltr informing NRC of steps taken to correct violation noted in If lasp Repts 50-280/80-13 & 50-281/80-14 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/06 10

1

- --8006250099 Forwards response to NRC 800428 ltr re violation noted in IE insp Repts 50-280780-13 / 50-281780-14 Encl withheld (ref 10CFR2 790) SYLVIA B R Virginia Electric & Power Co 80/05/22 ip
- --8006250103 Forwards IE Insp Repts 50-280/80-13 \$ 50-201/80-14 on 800225-0304 * 0310-0403 \$ notice or deviation Notice of violation withheld (ref 100FR2 790) LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/28 2pp
- --8006250104 Notice of deviation from insp on 800225-0304 & 0310-0403 * Region 2. Atlanta, Office of the Director 80/04/22 in
- --B005250107 IF Insp Repts 50-280/80-13 5 50-281/80-14 on 800225-0304 & 0310-0403 Noncompliance nated facility not built as described in FSAR 7 one apparent item of noncompliance in plant security Portions withheld (ref 100CR2 790) KELLOGG, P J Region 3, Chicago, Reactor Operations Nuclear Support Branch BURKE, D J Region 3, Chicago, Office of the Director NRC 80/04/23 4pp
- 800A240238 Forwards response to [E Bulletin 80-05 re vacuum conditions vasulting in damage to holdup tanks Two potential problem areas involving boron evaporator bottoms tank & boric acid storage tanks identified SYLVIA, B R Virginia Electric & Power Co 80/05/09 3pp
- 8006300253 Forwards response to 1F Bulletin 80-09 Hydramotol actuator Models AH-90 & NH-90 are not used at facility SYLVIA.B R Viginia Flectric & Power Co 60/06/10 3pp
- 8006300235 Forwards response to 1E Bulletin 80-12 re decay heat removal sys operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if subsystem is operable SYLVIA.B R Virginia Flectric & Power Co 80/06/11 4pp
- 8006300349 Responds to IE Bulletin BD-Uo requesting review of drawings for all sys serving safety-related functions at schematic level, verification of controls 2 pignosed design mods Actions & schedules delineated in Item 3 SYLVIA, B R Virginia Electric & Power Co 80/06/12 10pp
- 800£240484 Responds to NRC 800528 ltr re violations noted in IE Insp Rept EA-80-28 Corrective actions radwaste section completely restaffed w/personnel having formal radwaste training SYLVIA.8 R Virginia Electric & Power Co 80/06/20 5pp
- 8006300673 Forwards payment for civil penalty proposed in 800528 notice arising from IE Insp Repts 50-280/80-16 & 50-281/80-17 Response to repts will be forwarded separately SYLVIA.B R Virginia Electric & Power Co 80/06/20 3pp
- 8006240283 Responds to NRC 800930 itr re violations noted in IE Insp Rept 90-281/80-20 on 800509-08 Corrective actions operators & engineers involved have been reinstructed on importance of procedural & administrative compliance SYLVIA.NR Virginia Flectric & Power Co 80/06/23 4pp
- 8006240356 Responds to NRC 800527 ltr re violations noted in IE Insp Repts 50-280/80-19 & 50-281/80-19 on 800407-0502 Corrective actions increased emphasis will be applied to senior reactor operator & reactor operator retraining sessions SYLVIA, B R Virginia Flectric & Power Co 80/06/23 4pp
- R Periodic operating reports & related correspondence
- 8006170513 Forwards monthly operating repts for May 1780 SYLVIA.8 R Virginia Electric & Powe: Co 80/06/12
- --8006170517 Monthly operating repts for May 1980 SAUNDERB.R. COSTELLO.O J Virginza Electric & Power Co 80/06/05 49pp
- S Reportable occurrences. LERs & related correspondence
- 8004040351 PNO-II-80-087 on 800516, contractor employees were struck by door failing off trunnion while being removed Caused by loose set screw Injuries were treated Accident involved no radiation No press releases planned HARDIN.A K , KELLOOG, P J Region 2, Atlanta, Office of the Director NRC 80/05/14 ip

- 8006090545 EN-80-019 notice of violation & notice of proposed JUDIVIDES ENEO-019 notice of violation & notice of proposition of civil penalties will be issued on or about BOOS28 Action based on two alleged items of noncompliance relating to improper radiation surveys of waste drums BROCKETT. T. THOMPSON.D. Office of Inspection & Enforcement of the Director BO/OS/23 ip Office of Inspection & Enforcement, Office
- 8006110206 Forwards LER 80-004/01T-0 WILSON, J.L. Virginia Electric & Power Co. 80/06/04 1p
- --8004110245 LER 80-004/01T on 800521, during cold shutdown, pressure transmitter 458 inoperable due to wiring problem & isolation valve for pressure transmitter 403 found closed, negating varies for pressors transmitter 403 tubns (1986) negating overpressure mitigating bys Caused by cable problem WILSON, J. Virginia Electric & Power Co. 80/06/04. 2pp
- 8006110324 RO several lines in low head & high safety injection syswere not analyzed for effects of rluid temp below 70 F Review of new noizle loads showed load on pump exceeded vendor allowable load Multiphase program proposed SYLVIA, B R Virginia Electric & Power Co 80/06/06 19pp
- 8006120336 Forwards LERs 80-003/03L-0 & 80-005/01T-0 WILBON, J L Virginia Electric & Power Co 80/06/06 2pp
- --8006120339 LER 80-003/03L-0 on 800514. w/unit in cold shutdown. MGV-CW-2008 failed to close on safeguard signal Caused by electrical malfunction due to repairs in progress Redundant inlet valve shut Valve will be repaired & tested WILSGN, J L Virginia Electric & Power Co 80/06/06 2pp
- --8006120341 LER 80-005/01T-0 on 800306, during preparation for type A testing, leakage found through RSNX disphragm plate seal walds Caused by lack of fusion 2 slag inclusion Defects to be repaired 2 inspected by mondestructive test methods WILSON, J. L. Virginia Electric & Power Co. 80/08/06.
- 8006230499 Proposes multi-phase plan to address NRC concerns re amplified response Spectra Curves used as basis for analyses when piping sys is subjected to more than one spectra SYLVIA, B R Virginia Electric & Power Ca 80/06/06 lipp
- 8006270272 Forwards LER 80-006/03L-0 WILSON.J L Virginia Electric & Power Co 80/06/23 ip
- --8006270302 LER B0-006/03L-0 on 800527 contrary to Tech Spec 3 i 0 2 b
 (i) Containment 2 pressurizer lovel exceeded 33% w/o
 mitigation protection Caused by addition of water to primary
 sys to maintain level indication RCS drained
 WILSON, J L Virginia Electric & Power Co 80/06/23 2pp
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 800602023i Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Bys intended for use during emergencies to link all power plants & NRC Emergency Notification Bys hotline will also be used KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/04/18
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 % App R to 100FR30 & is expected to be gublished in FR by end or May EISENHUT. D C Division of Licensing 80/05/19 46pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC BO0519 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- BOOGOZO25B Forwards revised Page I unitted from 800510 Revision 1 to security force training & qualification plan Encl withheld (ref 100FR2 790) Northern States Power Co 80/05/27 1p MAYER, L. D
- BOO617009B Notifies of proposed IE contractor review of emergency operating procedures on 800609-13 Data will be used to provide composite picture of emergency procedures & will not result in items of noncompliance HEISHMAN, R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/03 2pp

- 8006230337 Discusses submittal of final upgraded emergency plans Extension may be necessary, depending on content of pending NRC rules on emergency plans Schedule for emergency plan revisions targeted to meet 800901 submittal data MAYER.L O Northern States Power Co 80/06/17 19
- G Adjudicatory correspondence
- 8006230266 Advises that State of MN 800424 contentions are being sent for docketing NRC will be prepared to discuss hearing schedule & state contentions during Jul 1979 prehearing conference in St Paul MN BARTH.C A Hearing Branch 3 80/06/19 1p
- 8006300419 Notice & order for 800806 proheering conference in US Courthouse.St Paul.KN re State of MN 800424 petiton to intervene in OL amend proceeding Licensee & NRC shall file responses to intervention petition by 800715 LAZO.8 M Atomic Safety and Licensing Board Panel 80/06/25 2pp
- P. Operating bicense stage documents \boldsymbol{b} correspondence
- 8006(8010) Decommissioning study of Prairie Island Nuclear Generating Plant,Revision (JAMDRSKY,M J Nuclear Energy Service, Inc. 81A0623 Rt 79/09/28
- ~-8006180108 Decommissioning study of Monticello Nuclear Generating Plant Revision 1 * Nuclear Energy Service, Inc. 81A0622 R1 79/09/28 48pp
- 8003280527 Submits update to 791213 ltr re status of investigations into Framotome reactor vassel nozzle cracking Results indicate reactor vassel nozzles are not susceptible to cracking ANDERSON. T M Westinghouse Electric Corp 80/01/31 2pp
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. Scensing exams 2 licensee dissemination of operating experiences Response requested within 30 days EIGENRUT.D C Division of Licensing 80/05/07 150pp
- 8006130122 Requests commonts on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Yearing on PWR Steam Generator & Reactor Coulant Pump Supports " Proposed review procedure & implementation schedule enci EISENHUT.D © Division of Licensing 80/08/19 729p
- 8006250044 Forwards safety evaluation re degraded grid voltage protection for Class IE ac power sys & LLL rept supporting mods Design mods & Tech Spec changes acceptable ROSA.F Power Systems Branch 80/05/22 ip
- ---B006250049 Bafety evaluation supporting proposed mods & Tech Spec changes re protection of Class IE equipment & sys from sustained degraded voltage * Power Systems Branch BD/05/22 2pp
- --B006250052 "Technical Evaluation of Proposed Design Mods & Tech Spec Changes on Orid Voltage Degradation for Prarie Island Nuclear Generating Plants Units 1 & 2 " WHITE: R L Lawrence (Ivermore Laboratory FIN A-0231 UCID-18654 80/03/31 15pp
- 8006090400 Forwards info re implementation of 10CFR50.App J.containment panetration testing requirements.per 800411 request MAYER.L O Northern States Power Co 80/05/30 8pp
- 8006170486 Forwards add1 info in support of 800131 license amend request in response to NRC questions Analyses cover makeup water sys, structure), chemistry/radiochemistry, radiological, matis/processes & rack disposal MAYER.L Q Northern States Power Co 80/06/10 20pp
- 8006230142 Responds to 800602 memo by submitting list of documentation & applicable comments on facilities purge & vent valves long-term mechanical operability Facilities meet interim position

 MARTIN.R Operating Reactors Branch 3 80/06/10 2pp
- 8006240059 Forwards listed drawings to enable continuation of review of generic issue, "Primary Coplant Sys Pressure Isolation Valves (Event 5) " W/o encis MARYIN.R E Operating Reactors Branch 3 80/06/10 3pp

- 8006170377 Forwards response to NRC 800507 ltr on addl TMI-2 requirements re shift manning licensing exams operating experience feedback. Dulletins ? Orders Task Force recommendations 3 control room habitability MAYER, L O Noithern States Power Co 80/06/11 14pp
- Q Inspection reports: IF Bulletins & correspondence
- 8006170316 Forwards IE Insp Repts 50-282/80-05 & 50-306/80-06 on 800301-31 No noncompliance noted HEISHIMALR F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --8006170321 IE Insp Rept* 50-282/80-05 % 50-306/80-06 on 800301-31 No noncompliance noted Major areas inspected plant operation, maint-followup of IERs, % review of licensee small break LUCA procedures
 FEIERABEND.C D , SWANSON.E P Region 3, Chicago, Office of the Director BOVD.D C Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/18 7pp
- BOOA030203 Responds to IE Sulistim 79-17. Revision in Item 4 Visual inspattisfactorily completed on Unit 1 in Apr 1980 No corrective actions necessary GLEBERTS. D.E. Northern States Power Co. 80/09/06 ip
- 8006110436 Forwards honoropiletary version of IE lnsp Repts 50-282/80-07 t 50-306/80-07 on 800428-0502 Notice of violation withheld (ref 100FR2 790) HIND.J A Region 3. Chicago, Safeguards Branch NRC 80/05/22 280
- --8006110444 Nonproprietary version of IE Insp Repts 90-282/80-07 & 50-306/80-07 on 800428-0502 Noncompliance noted some vital area physical barriers not maintained & alarm devices not tamper-indicating Datails withheld (ref 100FR2 770) HIND, J A Region 3, Chicago, Safeguards Branch CREED, J R, PIRTLE, O L. Region 3, Chicago, Office of the Director 80/05/21 2pp
- 8006130074 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J.M. Division of Rules and Records 80/05/23 3pp
- --8006130099 Forwards response to updated memo received on 800313 re uti interrogatories to proposed imposition of civil penalty Cover sheet of 1E insp rept encl KEPPLER.J Q Region 3. Chicago. Office of the Director 80/03/21
- --8006130120 Excerpt of IE Insp Repts 50-282/75-01 & 50-306/75-01 conducted on 750204-06 & 12-15 Noncompliance noted design change packages were not prepared b/or implemented in accordance w/licensee administrative control directives CHOULES:N C : HUNTER:D R Region 3: Chicago, Office of the Director woRDAN:E J Region 3: Chicago, Reactor Operations Nuclear Support Branch 75/03/25 5pp
- 8006230253 Revises response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Forwards sys component evaluation worksheet on Kerito Cable, Revision 2, replacing worksheet sent in 8005127 response GILBERTS, D.E. Nurthern States, Power Co. 80/05/23 3pp
- 8006249558 Responds to IE Sulletin 80-12, "Decay Heat Removal Sys Operablity" Operating procedure for reactor refueling (cavity flooded) will require one train of RHR available w/ accessible source of borated water to replenish any loss OILBERTS,D E Northein States Power Co 80/06/06 2pp
- R Periodic operating reports & related correspondence
- 8006180448 Forwards monthly operating repts for May 1980 & corrected page to Apr 1980 monthly operating repts
 MAYER.L O Northern States Power Co 80/06/13 ip
- --8005180451 Monthly operating repts for May 1980 HUNSTAD, A A Northern States Power Co 80/06/01, 8pp
- --8006190453 Monthly operating repts Apr 1980, corrected pages HUNSTAD, A A Northern States Power Co 80/06/13 19
- S Reportable occurrences. LCRs & related correspondence
- 8006030479 Environ Event Rept 80-01 on 800501.daily average discharge temp exceeded ambient river water temp by 5.7 F while two cooling towers were undergoing improteaning & repair One tower returned to svc & electrical load reduced MARD.E C Northern States Power Co 80/05/30 ip

- 8006070289 Environ Event Rept 80-02 on 800513-14, reclaiming ion exchanger out of svc when steam generator blowdown water discharged into river Sample of outfall revealed pH value greater than 8 5 Caused by seasonal change of river WARD.E C Northein States Power Co 80/06/04 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows ½ 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities
 SEAY, J L Chemtror Corp., Tube Turns Div 80/06/06 3pp
- 8004300493 Forwards updated LER 80-009/03L-1 MAYER, L O Northern States Power Co 80/06/27 2pp
- ---8006300499 Updated LER 80-009/03L-1 on B00310 during normal operation, nuclear power range channel 1N44 was inoperable for few minutes High voltage supply for detector latched up due to spike on yellow instrument bus HUNSTAD. A A Northern States Power Co 80/06/27 ip
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D 0 Division of Licensing 80/05/19 44pp
- B006040297 Forwards supporting info re fire protection sys,per NRC B00416 request Oversize drawings available in Central Files only JONES,W C Omaha Public Power District 80/05/20 42pp
- 8006130063 Forwards revised Pages inid & new Page 14a for proposed rule 10CFR90 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101;" transmitted by NRC 800519 ltr Page 14e not encl EISENHUT, D & Division of Licensing 80/05/22 73pp
- 8006270422 Forward request for addl info to complete review of 790619 revised safeguards contingency plan Response due within 30 days Encl withheld (ref 100FR2 790)
 CLARK.R A Operating Reactors Branch 3 80/06/10 2pp
- H General correspondence
- B006020095 Responds to B00313 ltrs re importance of public hearings for NRC licensing action NRC experience in Omaha B00116 public meeting supports more frequent meetings Automatic key to shut down reactor would bypass judgment of operator REID.R N Operating Reactors Branch 4 80/05/23 2pp.
- 8006110086 Requests that MA Tebor be substituted for MR Paradis on svc list In future, all info should be sent to MA Tebor TEBOR, M A LeBoeuf, Lamb, Leibų & MacRae 80/05/28 Ip
- J Insurance & indemnity information
- 8006230356 Forwards revised cash flow projection in response to NRC 800527 ltr pointing out deficit Fuel & production cost adjustment lags 6 months behind cash flow Costs for unanticipated extended fuel outage recoverable in late 1980 PETERSON.H E. Omaha Public Power District 80/06/18 4pp
- P Operating license stage documents & correspondence
- BOOLOGOILES Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. Licensing exams 3 licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07 150pp
- B006090493 Notification of B00603 meeting w/util in Bethesda.MD to discuss filtered vented containment sys & core retention devices MEYER.J F Reactor Systems Branch B0/05/27 3pp
- BOO6130122 Requests comments on NVREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coplant Pump Supports "Proposed review procedure & implementation schedule encl
 EISENHUT.D G Division of Licensing 80/05/19 72pp

- 8006120017 Forwards Amend 4B to License DPR~40, safety evaluation & notice of issuance & availability
 CLARK,R A Operating Reactors Branch 3 80/05/27 2pp
- ---B006120023 Amends 48 to License DPR-40, adding license condition re secondary water chemistry & changing Tech Specs to allow limited besting of shock suppressors during operation CLARK,R A Operating Reactors Branch 3 80/09/27 6pp
- --8006120026 Safety evaluation supporting Amend 48 to License DPR-40
 # Office of Nuclear Reactor Regulation, Director 80/05/27 3pp
- --8006120028 Notice of issuance & availability of Amend 48 to License DPR-40 CLARK,R A Operating Reactors Branch 3 80/05/27 2pp
- 8004090480 Notification of 800410 meeting w/util in Bethesda.MD to discuss crack propagation studies & asymmetric loads evaluation WAGNER.P C Operating Reactors Branch 3 80/04/02 ip
- 8006230422 Forwards response to NRC 800515 request for info re turbine disc integrity
 JONES.W C Omaha Public Power District 80/06/13 App
- 8006240324 Forwards implementation schedules for meeting addl TMI requirements submitted in NRC 800507 ltr
 JONES, W C Omaha Public Power District 80/06/17 3pp
- 8006300372 Forwards responses to NRC questions re rept, "Fort Calhoun Cycle 6 Emall Break ECCB Performance Evaluation at 1,500 MMt." submitted in support of 790717 application for amend of OL JONES, W C Omaha Public Power District 80/06/26 App
- G Inspection reports, IE Bullotins & correspondence
- BOO6040024 Forwards repts restatus of responses to IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Bys," % IE Bulletin 79-02. "Attempted Extortion - Low Enriched U" JONES, W C Omaha Public Power District 80/04/21 42pp
- 8004040125 Forwards IE Insp Rept 50-285/80-08 on 800414-17 No noncompliance noted MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- --8006060127 IE Insp Rept 50-285/80-08 on 800414-17 No noncompliance noted Major areas inspected implementation of NUREG-0576, fire protection commitments & progress on IE Bulletins 79-02 t 79-14 HESTERMAN, TF, KELLEY, DL, YANDELL, LA Region 4, Dallas, Office of the Director 80/04/24 4pp
- GOOLOGOSB7 Forwards IF Bulletin BD-11, "Masonry Wall Design " Requires action & written response IE info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl SEYFRIT, N. V. Region 4. Dallas, Office of the Director BO/05/08
- 8006050300 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys
 Operability " Requires action & response within 30 days
 IE Info Notice 80-20, "Loss of Decay Heat Removal Capability
 at Dayis-Besse Unit i While in Refueling Mode" enci
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09
 io
- 8006300543 Forwards response to IE Bulletin 80-04, "Analysis of PMR Main Steam Line Break w/Continued Fredwater Addition" Affected steam generator blows dry at 69 I seconds & thus terminates initial RGB cooldoom JUNES, N C Omena Public Power District 80/05/15 27pp
- G006230065 Forwards IE Insp Rept 50-285/79-18 on 791205 No noncompliance noted BROWN, G. D. Region 4. Dallas, Fuel Facility & Materials Safety Branch 60/09/19 2pp
- ~-8006230071 IE Insp Rept 50~285/79~18 on 791205 No nuncompliance noted Major areas inspected programs, procedures & activities astociated whandling of radwaste BROWN, 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch HARRISON, H C Region 4, Dallas, Office of the Director 80/05/15 3pp
- 8006130076 Add1 response to FQIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J M Division of Rules and Records, 80/05/23 3pp

- --8006130088 Forwards LERs in response to util Interrogatory 12 re violations of containment integrity & civil penalty No items of moncompliance found re util Interrogatories 13 or 14 MESTERMAN.T F Region 4. Dallas. Office of the Director 80/03/19 1p
- --8006130070 Forwards AD 50-285/74-14
 JONES.W C Omaha Public Power District 74/09/17 ip
- --8006130092 AO 50-285/74-14 on 740905 during routine insp.air was discovered issuing from vent side of containment pressure indicating manometer Caused by errors in preparation & review of procedure for establishing containment integrity & Omaha Public Power District 74/09/16 App
- 8006290078 Forwards corrected Page 8 to IE Investigation Rept 50-285/80-10 BROHN,0 D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/06/05 ip
- --800625009i Replacement Page 8 to IE Investigation Rept 50-285/80-10 BROWN, O D Region 4. Dallas, Fuel Facility & Materials Safety Branch HERR, R K Region 4. Dallas, Office of the Director KELLEY, D L Region 4. Dallas, Reactor Operations Nuclear Support Branch BO/05/22 ip
- --B006250082 Forwards IE Investigation Rept 50-285/80-10 on 800514-16 & notice of violation BROWN C D Region 4, Dallas. Fuel Facility & Materials Safety Branch 80/05/23 2pp
- --8006250084 Notice of violation from investigation on 800514-16
 * Region 4. Dallas, Office of the Director 80/05/22 ip
- --800A2900B5 IE Investigation Rept 50-285/80-10 on 800514-16
 Noncompliance noted failure to perform required radiation
 survey
 BRONN:0 D Region 4. Dallas, Fuel Facility & Materials Safety
 Branch HERR:R K Region 4. Dallas, Office of the Director
 KELLEY,D L Region 4. Dallas, Reactor Operations Nuclear Support
 Branch 80/05/22 10pp
- R Periodic operating reports & related correspondence
- 8006170442 Forwards monthly operating rept for May 1980 JONES, W.C. Omaha Public Power District 80/06/09 ip
- ---8006170443 Monthly operating rept for May 1980 HICKLE, 8 J Omaha Public Power District 80/06/09 19pp
- S Reportable occurrences. LERs & related correspondence
- BOO6230414 RD on BOO915, during primary sys leakage insp. leakage detected from reactor coolant pump RC-3C Caused by corrosion damage to closure studs Studs w/significant corrosion will be replaced & metallurgical exams performed STEVENS,S C Omaha Public Power District BO/05/22 3pp
- 8006110019 Forwards LER 80-008/03L-0 STEVENS,S C Omaha Public Power District 80/05/31 1p
- ---800&i100i5 LER 80-00B/O3L-0 on 8005i5.during check of power supply trip indicating lights.AB-1 matrix relay of reactor protective sys failed to trip clutch power supplies Gaused by failure of mercury wetted relay in matrix circuit CDRE.K., CONNOLLEY, J. Omaha Public Power District 80/05/19 450
- 8006110026 Forwards LER 80-009/99T-0 STEVENS.S C Omman Public Power District 80/06/05 ip
- ---8006110030 LER 80-009/99T-0 on 800522.during maint on stack iodine process monitor, new sensitivity calibr was required Caused by use of wrong calibr procedure Training will be conducted to ensure familiarity w/procedures
 MICHOLAS.J.B. FRANCO.F F Omaha Public Power District 80/05/29
 4pp
- 8006300468 Forwards LER 80-010/017-0 8TEVENS.8 C Omaha Public Power District 80/06/23 1a
- --ROO6300475 LER BO-010/01T-O: on BO0516, during cold pressure test, leakage discovered at gasket joint between pump casing & pump cover on reactor coolant pumps RC-3A, 3B & 3C Closure studs corroded by bovic acid Leaks caused by deteriorated gaskets FLEUHR, J. Omaha Public Power District BO/06/17 App

- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 S App R to 100FR50 & is expected to be published in FR by end of May EISENHUT.D & Division of Licensing 80/05/19 44pp
- BOO6040139 Forwards comments re 800430 submittal of revised safeguards contingency plan Response requested within 30 days Comments withheld (ref 100FR2 790) VARQA.S A Operating Reactors Branch 1 80/05/20 2pp
- BOO6130063 Forwards revised Pages 1-14 ½ new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D G Division of Licensing 80/05/22 73pp
- 80060&0280 Advises NRC of recent developments be emergency preparedness at facilities Utils are revising emergency plans in accordance w/NuREG-0654, retaining EDS Nuclear, Inc to assist State of NY & Westchester County in revising plans CAHILL, H J Consolidated Edison Co of New York EARLY, P J Power Authority of the State of New York BO/06/03 5PP
- G Adjudicatory correspondence
- 8006060923 Order stating four-grouped approach to resolve UCS petition for Unit 1 decommissioning & Units 2-3 shutdown adjudication before ASLB.informal proceeding to determine issues, generic consideration is establishment of intra-agency task force CHILK.S J Office of the Secretary of the Commission 80/05/30 80
- 8006190310 Responds to 800905 objection to scheduling meetings outside Washington,DC area Meetings are occasionally held outside of Washington,DC vicinity to allow persons living near plants opportunity to attend EISENHUT,D O Division of Licensing 80/06/02 2pp
- 8006110113 Notice of withdrawal from proceeding effective 800602 Notice of JE Moore appearance % Certificate of Svc encl LEWIS.S H Heering Branch 2 80/06/06 4pp
- 8005160003 Forwards response to NRC 800211 confirmatory order, 120-day action items

 EARLY, P J Power Authority of the State of New York 80/06/11
 15no
- 8006190547 Order granting extension until 800707 for Commission to elect whether to review ALAB-436 % portions of ALAB-861 CHILK/S J Office of the Secretary of the Commission 80/06/16
- 8006240483 Comments on Commission 800530 order re safe operation & criteria of operation CP & OL established criteria should apply & burden of proof must remain on licensee Specific design changes must be feasible WEISB.E R. JORDAN.W B Union of Concerned Scientists WEISB.E R Sheldon, Harmon & Weiss 80/06/20 9pp
- BOO6286212 Memorandum in response to Commission BOO530 order initiating informal proceeding Urges development of industry-wide policy guidance & side prior to consideration of units separately in adjudicatory hearings
 BRANDENBURG, B Consolidated Edison Co of New York PRATT, C M
 Power Authority of the State of New York BO/06/20 23pp
- BOO&2601B& Forwards UCB 800623 motion to disqualify Commissioner Hendrie WEISS E R , JORDAN W S Sheldon, Harmon & Weiss 80/06/23 ip
- --8006260188 Motion to disqualify Commissioner Hendrie from further participation in NRC deliberations re UCB petition for suspension of operations Request is based on Hendrie involvement w/facility as member of ACR5 MCI88.E R . JORDAN.W S Union of Concerned Belentists WCI88.E R Sheldon. Harmon & Weiss 80/06/23 10pp
- --8006260192 Responds to 730717 ltr re util siting criteria Indian Point sites meet NRC regulations & criteria Considerable energy has been expended to assure public health & safety HENDRIELJ M Atomic Energy Commission. Directorate of Licensing 73/09/10 3pp

- 8006020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas
 - HAMMIK Affiliation Unknown 80/03/19 1p
- 8006190436 Comments on 800530 order re shutdown of plants pending adequate emergency plans No plant can operate unless acceptable emergency plans exist Energy & eronomic factors should have minimal influence on decision to saut down HOLF. B Affiliation Unknown 80/06/ii 3pp
- 8006260178 Requests that following names be included on correspondence distribution list GT Berry, JP Bayne, GM Wilverding, CM Pratt & RJ Pasternak BAYNE, J P Power Authority of the State of New York 80/06/20

P Operating license stage documents & correspondence

- 8006090165 Forwards addl TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8004040002 Notification of 800520 meeting w/utils.contractors & consultants in Bethesda. MD to exchange technology reaccident sequence & related phenomena per A Schwencer 800410 itr to L Peoples LONG. J K Reactor Bystems Branch 80/05/15 2pp
- BOOG130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Stram Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EIGENHUT, D G Division of Licensing 80/05/19 72pp
- 8004020172 Notification of 800530 meeting w/utils in Bethesda.MD reserver accident mitigation features for facilities
 OLSHAN,L , REEVES,E Operating Reactors Branch 1 80/05/23 1p
- 8006190180 Forwards request for addl info re QA program Response should be submitted within 30 days VARQA.S A Operating Reactors Branch 1 80/05/23 Spp
- 8006030384 Responds to NRC 800425 ltr re confirmatory order requirement of attaining AFWS reliability improvements by 800811 Confirms schedule commitments Provides detailed description of proposed improvements Sys will be operative by 800811 EARLY, P. J. Power Authority of the State of New York 80/09/28
- 8006040274 Forwards responses to 800408 ltr re GA program review Responses do not constitute proper format for formal GA commitment BERRY,O T Power Authority of the State of New York 80/05/29
- BOO6030315 Forwards supplemental info re degraded grid voltage & adequacy of station electric distribution sys voltages EARLY, P J Power Authority of the State of New York 80/05/30 19pp
- 8004040373 Forwards additinfoite electrical override/bypass aspects of containment purge system 800411 request Oversize drawings available in Central Files only EARLY, P J Power Authority of the State of New York 80/06/02
- 8006120404 Forwards slides used by utils during 800603 meeting re technology exchange in area of mitigation feature for severe accidents at facilities ODEBER.D Westinghouse Electric Carp 80/06/05 ip
- BOOG170451 Forwards "Mitigation of Severe Accident Study Rept " Rept includes presentations made to NRC & ACRS on BOO220 & 0305; respectively & consists of state-of-the-art analyses conducted within 60-day period CAHILL.W J Consolidated Edison Co of New York EARLY,P J Power Authority of the State of New York 80/06/05. 2pp
- --8004170454 Informs that Section 6 of rept submitted on 800405 was inadvertently stamped proprietary Class 2 Rept is nonproprietary CAMILL, W J Consolidated Edison Co of New York, EARLY, P J Power Authority of the State of New York 80/04/04 ip

- ---8006170459 Responds to 800528 ltr transmitting rept covering work performed by various consultants Entire Westinghouse rept nonroprietary PEOFLES.D L Commonwealth Edison Co 80/06/09 3pp
- --B006170466 "Mitigation of Severe Accident Study Rept," consisting of repts re evaluation of residual risk, steam explosions, containment response for Class 9 accidents & post-accident containment vent sys conceptual designs

 * Westinghouse Electric Corp 80/03/31 400pp
- 8006160108 Forwards Con Ed 800505 & Power Authority of State of NY 800507 ltrs to BDE re economic effects of extended shutdown for consideration by NRC task force CAMILL.N J Consolidated Edison Co of New York EARLY, P J Power Authority of the State of New York 80/06/10 15pp
- 8006270047 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda.MD re accident nutiquation features for facilities LONG.J K Reactor Systems Branch 80/06/12 27pp
- BOO6230435 Forwards response to TMI-2 related requirements per BO0507 request
 BAYNE, J P Power Authority of the State of New York BO/06/16
- 8006250280 Notification of 800618 meeting w/utils, contractors & consultants in Bethesda, MD for presentation in area of core-melt accident sequences for facilities Agenda encl MEYER, J F Reactor Systems Branch 80/06/16 2pp
- BOO6200553 Notification of BOO617 meeting w/utils & consultants in Bethesda:MD to discuss technology exchange re containment structural response; failure pressures & failure modes MEYER, J F Reactor Systems Branch 80/06/17 2pp
- 8006250364 Notification of 800625 meeting w/util in Bethesda.MD to discuss re-evaluation of operational GA program BELKE.W L. Quality Assurance Branch 80/06/17 2pp
- BD0626016B Advises that 800611 responses to NRC 800211 confirmatory order contained typographical error in Items 7 & 8 Echadule date of 810101 is incorrect Items 7 & 8 feasibility study & schedule for installation to be completed by Dec 1981 BAYNE, J P Power Authority of the State of New York 80/06/20 200
- 8006270175 Forwards response to NRC 800523 request for info on facility GA program Responses not considered part of present NRC-approved GA program commitments
 BOSTON.J W Power Authority of the State of New York 80/04/23
- 0 Inspection reports, IE Bulletins & correspondence
- 800&060553 Forwards response to IE Bulletin 80-04 Analysis results show that steamline break w/failure of auxiliary feedwater runout protection sys would not result in containment overpressurization SCHMIEDER, J. R. Power Authority of the State of New York, 80/05/08 Snn
- 8006120119 Ack receipt of 800407 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/79-23 BRUNNER: E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/09 ip
- ~-8006120123 Responds to NRC 800314 ltr re violations noted in IE Insp Rept 80-286/79-23 Corrective actions licensed operations personnel have been instructed in procedures Combustibles have been removed from diesel generator room. BAYNE, J P Fower Authority of the State of New York 80/04/07
- ~-8006120132 Forwards IE Insp Rept 50~286/79~23 on 790930-1027 & notices of violation BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/14 2pp
- --800612013B Notice of violation, App A, from insp on 790930-1027 Portion withheld (ref lOCFR2 790)

 * Region 1, Philadelphia, Office of the Director 80/02/27 lp
- --B006120140 Notice of violation.App 11, from insp on 790930-1027 * Region I, Philadelphia, Office of the Director. B0/02/27. ip

- --8006120147 IE Insp Rept 50-286/79-23 on 790930-1027 Noncompliance moted failure to adhere to protedures & failure to remove identified combustibles Postions withheld (ref 100FR2 790) REBELOHBKI.J., JOHNSON.J. Region i, Philadelphia, Office of the Director KISTER.H. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/02/27 18pp
- 8006200045 Forwards IE Circular 80~13, "Orid Strap Damage in Hestinghouse Fuel Assemblies" No written response required GRIER, B H Region 1. Philadelphia, Dffice of the Director 80/05/28 1p
- 8006i10083 Forwards interim status rept he IE Bulletin 77-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Line walks of all 194 static span tables analyzed lines & 117 dynamically analyzed lines in accessible areas completed EARLY, P J Power Authority of the State of New York 80/06/04
- 6006300307 Responds to Item 7 of IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Procedures & equipment capabilities have been reviewed & analyzed & found adequate during various modes of operation

 ZULLA, S S Power Authority of the State of New York 80/06/09

 3pp
- R Periodic operating reports & related correspondence
- 8006170431 Forwards data specified in Section 401 Certification for May 1980 to NY State Dept of Environ Conservation MONTI, W A Consolidated Edison Co of New York 80/06/10 1p
- --800&i7043\$ Circulating water temp,gross electrical output & river water discharge info for May 1980 # Consolidated Edison Co of New York 80/06/10 14pp
- BOO6180529 Forwards "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project. Bec 1979-Feb 1980 "
 CAHILL. W J Consolidated Edison Co of New York 80/06/13 1p
- --8004180536 "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point, NY Consolidated Edison Project Dec 1979-Feb 1980 "
 - Woodward-Clyde Consultants, Inc. 80/08/12 46pp
- 800&190551 Forwards monthly operating rept for May 1980 & amended pages for operating repts for Mar & Apr 1980 ZULLA-S S Power Authority of the State of New York 80/06/13 1p
- --8006170561 Monthly operating rept for May 1980 CUNNELL.C Power Authority of the State of New York 80/06/02
- B0061B0426 Forwards daily fish counts from intake screens for May 1980 CAHILL. W J Consolidated Edison Co of New York B0/06/15 ip
- --B006160427 Daily fish counts from intake screens for May 1980
 * Consolidated Edison Co. of New York 80/06/15 4pp
- S Reportable occurrences. LERs & related correspondence
- 8004050474 PNS-I-80-011 on G00519, four separate telcon bomb threats were received fuo calls received by Peakskill Evening Star b two by Supervisor's Off. Town of Peakskill, NY Bomb search procedures initiated at both plants
 DEMLINJ . MARTIN, W Region 1. Philadelphia, Office of the Director 80/05/20 ip
- 8006240217 PNS-I-80-014 on 800603. Evening Star of Buchanon, NY received phone call from unidentified male stating that Status of Liberty bombed & facility would be next Search of facilities reported no evidence of bomb JONES, EV. MARTIN, W. Region 1, Philadelphia, Office of the Director 80/06/04 tp
- 8006240222 PNS-1-80-015 on 800604. Daily News, NY City newspaper, received phone call from unidentified male admitting membership in FALN who said facility would be bombed next Bomb searches initiated w/negative results
 JONES, E W MARTIN, W Region 1. Philadelphia, Office of the Director 80/06/04 ip
- 8004200380 RO on 800414, while sys was in incident mode, texting was performed in control room air filtration sys Test indicated total air filter flow was greater than extrapolate max flow rate allowed Upgrading control room air filtration chercoal ZULLA.5 5 Power Authority of the State of New York 80/06/16 80/06/16 1p

- 8006300464 Forwards LER 80-007/03L-0 7ULLA.S S Power Authority of the State of New York 80/06/26 ip
- -8006300467 LER 80-007/03L-0 on 800531, while operating at 70% power, performance of electrical tunnel water sprinkler sys test JPT-A13 indicated inoperability or south side deluge valve Caused by dirty contacts on associated relay GUKBLE, F P Power Authority of the State of New York 80/04/26
- T Hearing transcripts on non-antitrust matters
- 8006180125 Transcript of 800530 Affirmation Session 80-06 in Washington, DC Pp 1-2 * Commission, 80/05/30 3pp
- ---BOO6180132 Recommends approval of encl revised draft order Encl PA Bradford separate statement to be appended to order BICKWIT.1. Office of the General Counsel SECY-80-182E BO/09/29 9pp
- ---8006180138 Responds to 600324 ltr to J Ahearne re problems of evacuating large populations in short period of time Program of upgrading emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant DENTON-HR Office of Nuclear Reactor Regulation, Director 80/04/27 2pp
- --- 8006180147 Elaborates un concerns expressed in 800102 ltr re need for practical evacuation plans around nuclear power sites Problems of evacuating large populations in short time have been underestimated Requests open hearings on issues WDLF.B Affiliation Unknown 80/03/24 2pp
- DOCKET 50-287 GCONEE NUCLEAR STATION, UNIT 3
- F Security, medical, emorgency & fire protection plans
- 8006090487 Forwards proposed rule entitied, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds now Section 30 48 & App R to 10EFR50 & is expected to be gublished in FR by end of May EISENHUT, D & Division of Licensing 60/05/19 46pp
- B006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISEI&HUT.D Q
- BOO6050108 Forwards revision to safeguards contingency plan Plan withheld (ref 100FR2 790) PARKER, N O Duke Power Co 80/05/30 ip
- 8006160074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/06/09 1p
- B006300004 Forwards comments & requests for add1 info re guard training & qualification plan Encl withheld (ref 100FR2 790)
 REID:R W Operating Reactors Branch 4 80/06/12 2pp
- 8006240209 Forwards cover ltr to 800609 revision to nuclear security training & qualification plan Ltr withheld (ref 10CFR2 790) PARKER,W Q Duke Power Co 80/04/19 ip
- Q Adjudicatory correspondence
- 8006240594 Forwards Lincoln County.NC Board of County Commissioners 791001 & 800408 resolutions affirming position that spent nuclear first should be transported from Oconer to McGuire on interstate highways HOUBER.F M North Carolina. State of 80/04/17 3pp
- 8006060267 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J M Debeyosse & Liberman 80/05/19 ip
- --B008060281 Submittal of proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman B0/05/19 ip

- --8006060286 Proposed initial decision containing findings of fact & conclusions of law, approving amend to Authorize storage of Oconee spent fuel at McGuire Environ radialogical monitoring program shall be maintained W/Certificate of Svc MCGARRY. J M Duke Power Co MCGARRY. J M Debevoise & Liberman 80/05/19 88pp
- 8006180517 Response in apposition to Catolina Environ Btudy Group B00529 proposed elements of fact & cunclusions of law toward initial decision No good leason presented for not approving application re-spent fuel shipment W/Certificate of Svt MCGARRY, J M Duke Power Co MCGARRY, J M Debevoise & Liberman B0/06/13 21pp
- BOO6190593 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to & storage at McQuire KEYCHEN,C G Hearing Branch 4 80/06/17 ip
- --8006190606 Proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Ocones spent fuel transportation to & storage at McGuire Proposed tianscript corrections & Certificate of Syc encl KETCHEN.E G , HDEFLING.R K Hearing Branch 4 80/06/17 155pp

- 8006270203 Forwards county board resolution requesting NRC to consider using onsite storage of radioactive maths rather than shipping through county Also forwards board resolution requesting public input re DOT regulations MARSHALL.H R Mecklenburg County,NC 80/06/23 3pp
- P. Operating license stage documents \boldsymbol{b} correspondence
- 8006240237 Responds to technical assistance request for proposed Tech Spec changes for B&W operating plants Forwards requirements for add1 info ISRACL.S.L. THI 2 Bulletins & Orders 79/08/29 13pp
- 8006090539 Forwards schedules for util responses to NRC 791121 ltr re C Michaelson concerns on small break LOCAs CAPRA,R TMI-2 Bulletins & Orders 79/12/10 ip
- 8006060283 Forwards documents for Auxiliary Bys Branch review of auxiliary feedwater reliability analysis for B&W operating plants M/o encls
 CAPRA,R A Light Water Reactors Branch 3 80/01/17 3pp
- 8006200562 Forwards revision to 800317 route approval request for shipment of spent fuel.changing dates for shipment Revision withheld (ref 10cFR2 790) PARKER,W U Duke Power Co 80/04/17 ip
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D 0 DIVISION of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREG-0877, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D. G. Division of Licensing 80/05/19 72pp
- 8006040217 Forwards NFS-1001, 'Reload Design Methodology," Revision 1, replacing original ontirely includes design of unrodded fuel cycles.clarification of certain areas & typographical error corrections Rept methods intended for use by Aug 1781 PARKER,N O Duke Power Co 80/05/20 1p
- ~~B004040221 "Reload Design Methodology," Revision 1

 → Dute Power Co NFS-1001 B0/05/31 300pp
- 8006130022 Requests submittal of amend to license updating requirements of Reg Outde 1 16:Revision 4 Response required within 60 days of receipt of ltr REID:R W Operating Reactors Branch 4 80/05/29 2pp
- 8006300574 "Electrical Instrumentation & Control Aspects of Low Temp Overpressure Mitigating Sys.' informal rept WEBER, D. A. E086. Inc. FIN A-6256 8006300574 80/05/31 12pp

- B006060364 Requests add1 info to respond to NRC B00507 itr re TM1-2 Lessons Learned requirements info needed includes areas re shift manning safety & relief valves & outage of ECCS Response should be submitted by 800612 PARKER: N O Duke Power Co B0/06/02 2pp
- 8006230134 Advises that 800328 request for Tech Spec change will be included in overall review of App 1 submittals Mark-up of 800523 ETS represents NRC review Radiological ETS should resubmitted, based on mark-up, within 90 days REID.R W Operating Reactors Branch 4 80/06/02 2pp
- BOO6:10:144 Forwards "Generic Startup Physics Test Program, May 1980," delineating tests to be included during startup following future refueling operations PARKER. W 0 Duke Power Go BO/06/04 ip
- ---800411015B "Generic Startup Physics Test Program, May 1780 " Modifies Unit 1 specific rept, decreasing acceptance criteria for rod drop measurements substitution of RMS criteria for location of highest peak requirement in power distribution testing # Duke Power Co 80/05/31 12pp
- 8006i10391 Forwards summary of events involving partial or total loss of offsite power to facilities & responses to NRC questions, per NRC 800808 ltm.
 PARKER, W U Duke Power Co 80/06/04 5pp
- B006130322 Forwards results of analysis required by Items 6 & 9 of NRC 790B0B ltr on degraded grid voltage Undervoltage trip setpoint will be changed for startup transformers & administrative controls will be established by B00701 PARKER, N D Duke Power Co 80/06/04 17pp
- 8006240163 Responds to NRC 800602 ltr requesting guidance re TMI-2 related requirements Automatic trip schedule of reactor coolant pumps during LOCA should be revised REID.R W Operating Reactors Branch 4 80/06/10 2pp
- B006170229 Forwards corrected version of "Oconee Nuclear Station Ceneric Startup Physics Test Program" PARKER, W D Duke Power Co 80/06/11 1p
- --8006170234 Corrected version of "Oconee Nuclear Station Generic Startup Physics Test Program" * Duke Power Co 80/G6/11 14pp
- BOO6170498 Advises that responses are being prepared re low pressure turbines per 800513 request Work will be completed by 800626 PARKER W O Duke Power Co 80/06/11 ip
- 8006300351 Forwards draft NRC licensing position, "Bafety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating repts REID.R W Operating Reactors Branch 4 80/06/12. 10pp
- 8004180478 Forwards response to NRC 800507 1tr re add1 requirements from TMI Action Plan Response contains implementation schedule & summary stating util commitments re requirements
 PARKER.W D Duke Power Co 80/06/13 3pp
- 8006240465 Responds to NRC 800513 request for info concerning problem of low pressure turbine disc cracking Forwards detailed responses to site specific questions
 PARKER: W U Duts Power Co 80/06/16 8pp
- 8006260233 Requests that NRC complete review & approval of Category B Items 2 i 38,2 i 7A & 2 i BB Review needed to facilitate installation of Category B mods prior to 8i010i PARKER: W O Duke Fower Co 80/06/20 ip
- 8006300362 Forwards proposed Tech Spec revision in response to NRC 800410 ltr discussing term "operable" as applied to Tech Spec requirements No license fees provided since proposal submitted in response to NRC request PARKER. N O Duke Power Co 80/06/24 2pp
- --8006300364 Proposed Tech Spec interpreting term "operable" as applied to various Tech Spec requirements # Duke Power Co 80/06/24 ip

- Q Inspection reports, IE Buildtins & correspondence
- 8006060146 Forwards IE Insp Repts 50~267/80-13,50~270/80-08 & 50~287/80-08 on 800303-31 No noncompliance noted LEWIS.8 C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/23 2pp
- --8006060152 IE Insp Repts 50-269/80-13.50-270/80-08 & 50-287/80-08, on 800303-31 No noncompliance noted Major areas inspected plant operations, outage activities, followup on previous insp findings & review of LER MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch ORDERS H T . JAPE. F Region 2. Atlanta. Office of the Director 80/04/23 Spp
- 8006060510 Forwards IE Bulletin 80-ii. "Masonry Nall Design " Requires action & unitten response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- B006050295 Forwards IE Bulletin 80-12. "Decay Heat Removal Bys Operability " Requires action & response within 30 days IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" enc! O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/09
- 8006170065 Forwards IE Info Notice 79-37 w/errata sheet Requests add1 info re turbine discs Recommends that schedule be developed to perform full ultrasonic test of at least one low pressure turbine before next major outage

 REID.R W Operating Reactors Branch 4 80/05/13 3pp
- 8006300110 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13 2pp
- B006180254 Ack receipt of IE Insp Repts 50-249/80-13,50-270/80-08 & 50-287/80-08 No proprietary info PARKER.W 0 Dute Power Co 80/05/20 1p
- 8006240109 Ack receipt of 800502 supplemental response, informing NRC of re-evaluation of noncompliance & deviation noted in IE Insp Repts 50-289779-37, 50-270779-34 & 50-287779-37 Stated position stands due to repetitive nature of incident O'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/05/JO
- --B005240117 Supplements response to NRC 800407 ltr re noncompliance & deviation noted in IE Insp Repts 50-269/79-37.50-270/79-34 & 50-287/79-37 Disagrees w/violation because event was not controllable by normal operating procedures PARKER, W Q Dute Power Co 80/05/02 2pp
- 8006240248 Forwards response to IE Bulletin 80-12 re decay heat removal sys reliability Control room has indication of each pump discharge pressure & each train flow Annuniciators are initiated on low flow in either train or if pump is on PARKER.W G Dute Power Co 80/06/06 5pp
- 8006300190 Ack receipt of IE Insp Repts 50-269/80-16,50-270/80-11 & 50-287/80-10 on 800422-25 No proprietary info PARKER, W 0 Dute Power Co 60/06/12 1p
- --8006300199 Forwards IE Insp Repts 50-269/80-16,50-270/80-11 & 50-287/ 80-10 on 800422-25 No noncompliance noted LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/19 3pp
- --8006300209 IE Insp Repts 50-269/80-16.50-270/80-11 & 50-287/80-10 on 800422-25 No noncompliance noted Major areas inspected containment integrated leakage rate testing 8RBOMS.F H Region 2. Atlanta. Office of the Director UPRICHI.C M Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 80/05/16 4pp
- 8006300213 Advises that response to IE Bulletin 80-06 will be provided by 800714 due to need for detailed review of engineered safeguards components PARKER.H O Duke Power Co 80/06/13 ip
- S Reportable occurrences. LERs & related correspondence
- B004020341 Forwards LER 80~007/03L-0 PARKER, W O Duke Power Co 80/05/28 ip

- --8006020343 IER 80-007/03L-0 on 800428 vent gas particulate & iodine monitors considered inoperable due to failure to perform periodic surveillance on schedule Caused by personnel error Status board for periodic surveillance items will be kept LEHIS.S R Dute Power Co 80/05/28 3pp
- 8006110091 Forwards LER 80-008/03L-0 PARKER, W D Duke Power Co 80/06/06 3pp
- --8006110076 LER 80-008/03L-0 on 80050/, shutdown was initiated when reactor protective sys channel B was lost due to inverter failure Caused by blown fuses Power to ac vital instrumentation restored manually & fuses replaced LEWIS.S R Dute Power Co 80/06/05 ip
- B006250255 RD on 800614, once through steam generator tube leak indicated by increased count rate on RIA-40 & grab samples Caused by leak in steam generator A Gecondary sys contamination procedure initiated MATHEUS, T C Dute Power Co 80/06/17 1p
- BOO6260169 RO 287/BO-8 addl info has been reviewed which clarifies occurrence Channel B was not inoporable as indicated, since unit was still capable of performing function & requirements of Tech Specs Loss of power was not RO PARKER.W O Duke Power Co BO/06/20 2pp
- BOCKET 50-288 REED COLLEGE RESCARCH REACTOR

 F Becurity, medical, emergency & fire protection plans
- B006020216 Forwards draft security plan Plan withheld (ref 10CFR2 770) CHURCH.L B Read College B0/06/02 1p
- P Operating license stage documents & correspondence
- 8006020376 Tech Spec change request to License R-112 to change wording of Paragraph D 2 to "at least monthly" instead of "at least weekly when reactor is operational" re sampling of pool water for conductivity CHURCH-L B Reed College 80/05/13 200
- DOCKET 50-289 THRRE MILE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emorgency & fire protection plane
- BOO6030249 Discusses Emergency Preparedness Task Force review of proposed emergency plan Emergency plan should be reviewed against NUREG-0654 evaluation criteria Plan should be provided by BOO602
 REID.R W Operating Reactors Branch 4 BO/04/28 3pp
- 8006190624 Requests that response to NRC 791129 request for info re evacuation time estimates, be based on enc. guidence 4/a enc. REID, R W Operating Reactors Branch 4 80/09/10 Ip
- 8006120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/09/13 2pp
- BOOA02010A Requests that badges assigned by Unit I & II security be returned immediately to util Security Unit II. in Middletown. PArdue to employment termination MAUGHAN,F J Metropolitan Edison Co BO/05/15 1p
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 \$ App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D G Division of Licensing 80/05/19 4App
- 8006/30063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D 9 Division of Licensing 80/05/22 73pp
- 8004090263 Forwards add1 info re Amend 44 to License DPR-50, in response to NRC 800415 request Positions satisfy remaining open items of Amend 44 All mods will be completed prior to 801101. Alternate shutdown capability will be completed by 810531 HERBEIN, J G Metropolitan Edison Co 80/05/30 31pp

- 8006110071 Forwards util 800527 its to PA Dept of Environ Resources re request for open burning permit in order to conduct training for TMI fire bigade personnel Due to small amount of fuel involved.environ impact will be minimal HERBEIN.U G Metropolitan Edison Co 80/06/04 3pp
- 8006110182 Forwards util 800527 ltr sent to PA Dept of Environ Resources requesting permit to conduct fire fighting brigade training Expects minimal environ impact due to small amount of fuel, gasoline 5 lumber used HERBEIN, J G Hetropolitan Edison Co 80/06/04 App
- 8006120317 Forwards upgraded emergency plans in accordance w/guidance set forth in "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants, "NUREG-0454 HERBEIN, J G Metropolitan Edison Co 80/06/10 12pp
- --8004120318 GPU Nuclear Corp emergency plan for TMI nuclear station Unit 1.Revision 2 → Metropolitan Edison Co 80/06/30 200pp
- --8006120320 Commonwealth of PA diaster operations plan, Annex E, fixed nuclear facility incidents
 # Pennsylvania, State of 80/03/28 200pp
- --8006120321 Commonwealth of PA Dept of Health radiation emergency plan * Pennsylvania, State of 80/02/27 175pp
- --8006120322 Draft York County protective action plan for TMI nuclear
- ---8006120324 Cumberland County TMI emergoncy response plan
 # Cumberland County, PA 80/05/05 250pp
- ~~8006120326 Draft Lancaster County emergency evacuation plan for TMI 4 Lancaster County, PA 80/05/30 175pp
- ---8006120327 Lebanon County Emergency Mgt Agency emergency operations plan. "Radiation Incident TMI" * Pennsylvania: State of 80/02/15 100pp
- --BOO6120329 Dauphin County fixed nuclear facility incident response
- nii Dauphin County, PA 80/05/05 180pp

@ Adjudicatory correspondence

- 8006060250 Response to People Against Nuclear Energy 800331 interrogatories for which extension until 800505 had been agreed upon includes info re psychological distress issue W/prof qualifications, Certificate of 8vc & forwarding ltr ZAHLER, R E Metropulitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/05/05 40pp
- 8006120084 Response in opposition to Aamodt B00424 motion for reconsideration of ASLB 800409 order re intervenor motion to compel licenses answers to interrogatories Proposed procedure does not promote disclosure W/Certificate of Syc BLAKE,E L. Metropolitan Edison Co. BLAKE,E L. Bhaw, Pittman, Potts & Trowbridge 80/05/05 8pp
- 8006:803:5 Supplemental response to PA Public Util Commission Interrogatory 6 of first set of interrogatories Identifies addl cash flow forecasts placed in licensee discovery reading room Certificate of Svc & cover itr encl ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 80/05/05
- BO06040423 Status rept in response to ASLB BO0421 memorandum & order on Sholly motion to compel liconsee answers to Contention 16 interrogatories Submits areas of agreement between licensee & Sholly W/Certificate of Svc Related correspondence BLAKE,E L Metropolitan Edison Co BLAKE,E L, Shaw, Pittman, Potts & Troubridge B0/05/07 7pp
- 8006180190 Forwards box containing documents in response to 800324 requests % addit responses w/affidavit in answer to Anti-Nuclear Group Representing York interrogatories Related arrespondence CARTER K N Pennsylvania, State of 80/05/07 2pp
- --8006180194 Followup to responses to Anti-Nuclear Group representing York interrogatories Includes info re PEMA rept on mass core capacity Affidavit & Certificate of Svc encl Releted Correspondence
 DOUGHERTY, J L Pennsylvania, State of 80/05/07 5pp

- 8006060253 Add1 response to SC Sholly fourth set of interrogatories re Contention 15 Includes info re plant operators' roles as part of operating procedures & design of control room Cortificate of Svc & cover ltr encl Related correspondence ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw. Pittman, Potts & Trowbridge 80/03/09 12pp
- BOO6060475 Motion for sanctions against Environ Coalition on Nuclear Power Urges dismissal of intervener as party in proceeding for failure to comply wARLB BOO411 memorandum & order relicensee BOO118 interrugatories Certificate of Svc encl TROMBRIDGE.0 F , ZAMLER.R E Metropolitan Edison Co
- BOO6120036 Second motion to compel intervenor Chesapeake Energy
 Alliance response to BOO118 interrogatories Intervenor
 BO0426 response in compliance w/ASLB 800416 order failed to
 supply requested info Certificate of Svc encl
 TROMBRIDGE, G F Ketropolitan Edison Co TROMBRIDGE, G F Shaw,
 Pittman, Patts & Trowbridge 80/05/12 7pp
- 800&120040 Addi response to intervenor SC Shally 800225 fourth set of interrogatories re Contention 1& Includes info re security staffing, security audits & acts of sabotage Certificate of Svc & affidavit encl
 Stakk, E L Metropolitan Edison Co BLAKE, E L Shaw, Pittman, Potts & Trowbridge 80/05/12 10pp
- 8006i60151 Followup interrogatories directed to licensee Requests documentation & causes pipes cracking in borated water sys Certificate of Svc encl Related correspondence ADLER.T A Three Mile Island Alert ADLER.T A Widoff, Reager, Selkowit: & Adler 80/05/13 Spp
- BOOAOAO527 Notice of appearance in proceeding Certificate of Svc encl BERNSTEIN.D L Metropolitan Edison Co BERNSTEIN.D L Shaw, Pittman. Potts & Trowbridge 80/05/14 App
- 8006120020 Forwards JR Thorps 800509 affidavit in support 800505 licenses response to People Against Nuclear Energy interrogatories Svc list encl Related correspondence BERNSTEIN.D L Shaw, Pittman, Potts & Troubridgs 80/05/14 80/05/14 4pp
- BOO6120022 Advises that licensee exams used in operator accelerated retraining program have been place in licensee discovery reading room in response to Interrogatory 4 re Aamodt fourth set of interrogatories Related correspondence
 BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge 80/05/14 3pp
- 8006i80i5i Confirms 8003i3 telcon All documents re Contentions 2.16 & 17 will be made available for insp & copying on 800529.by Citizens Against Nuclear Dangers Related correspondence SNAPP.B A Pennsylvania Power & Light Co 80/05/14 ip
- 8005120414 Response in opposition to THE Alert 800513 followup interrogatories Intervenor did not comply w/discovery schedule & questions do not relate to Contention 5 re maint W/Certificate of Svc Related correspondense BLAKE,E L. Metropolitan Edison Co BLAKE,E L. Shaw, Pittman, Potts & Trowbridge 80/05/15 5pp
- HOO6:HO177 Response to Chesapeake Energy Alliance HO0426 supplemental interrogatories Includes info re EPICOR-II outage & other functional matters Certificate of Syc enci Related correspondence
 ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Shaw, Pittman,
 Potts & Trombridge 80/05/15 5pp
- 8004170105 Affidavit in support of licenses 800507 addl response to SGC Sholly fourth set of interrogatories re Interrogatories 15-006.18-010, 15-024, 15-026.15-033, 15-026.15-041.15-047, 15-061.15-070 & 15-075 Cartificate of Svc & cover ltr encl KEATEN, R W Metropolitan Edison CO BO/05/14 Spp
- BOO5060420 Recommendations on contentions' grouping Shally Contention 17.Antinuclear Oroup Representing York 5.UCS 13 & Environ Coalition on Nuclear Power 48 & C should be grouped under Class 9 accidents Certificate of Syc encl SHOLLY.S C Affiliation Unknown 80/05/19 7pp
- 8006180:54 Supplemental response to Asmodt interrogatories re Contention 2.per ASLB 800508 memorandum & order Includes info re personnel on duty during accident & shift data for Mar 1979 Certificate of Svc & cover ltr encl BLAKE.E L. Metropolitan Edison Co BLAKE.E L. Shaw, Pittman, Potts & Trowbridge 80/05/19 8pp

- 8008080388 Memorandum in support of TMI Alert responses to licensee interrogatories re Contention 5 Explains intervenor efforts in providing info in systematic fashion, despite delay in obtaining SER Certificate of Svc encl WIDDFF, M P Three Mile Island Alert WIDDFF, M P Widoff, Reager, Seltowitz & Adler 80/05/20 8pp
- 8006060400 Followup responses to State of PA second set of interrogatories includes info re name of hosp where cases of hypothyroidism were reported Related correspondence AAMODT Affiliation Unknown 80/03/20 13pp
- --800A0A0405 Response to Aamodt second set of interrogatories Includes info on state 1978 congenital hypothyroidism screening program & other related issues Related correspondence TOKUHATA.C K Pennsylvania, State of 80/05/20 2pp
- --8004050408 Response to Aamodt followup second set of interrogatories Includes info re thyroid relation w/background radiation Affidavit & Certificate of Svc encl CARTER.K H Pennsylvania. State of 80/05/20 App
- 8006120085 Supplemental response to licensee interrogatories re Contention 5 States criteria used to identify work orders included in Attachment A of TMI Alert 800506 response Certificate of Suc encl HIDDFF.N P Three Mile Island Alert WIDDFF.N P Widoff, Reager, Sellowitz & Adler 80/05/20 App
- 8006020S11 Memorandum & order substantiating 800S13 prehearing conference rulings & agreements Addresses schedule for prehearing events following safety evaluation: pleadings & discovery matters & amend of intervenous' contentions SMITH, I W. Atomic Safety and Licensing Board Panel 80/05/22 14pp
- BOOA170765 Motion for further spec of contentions due to liberal std applied by ASLB when ruling on admissibility Urges issuance of order regularing spec by 800630 from all intervenors Certificate of Svc enci
 TROMBRIDGE, G F Metropolitan Edison Co TROMBRIDGE, G F Shaw, Pittman, Potts & Trombridge 80/05/23 27pp
- 8005040213 Forwards PA Public Util Commission final order in consolidated Met Ed/PA Electric Co proceedings Also forwards concurring opinion by Chairwoman Shaneman OENTIEU, L.P. General Public Utilities — GPU Service Corp. 80/05/27 31pp
- 8006120335 Motion for order to compel licensee substantive responses to intervenor TMI Alect 800513 followup interregatories Licensee raised no objection to initial questions when propounded Certificate of Svc encl ADLER, T A Three Mile Island Alert. ADLER, T A Widoff, Reager, Sellowitz & Adler 80/05/29 4pp
- 8006060536 Hemorandum & order on hydrogen control contentions re Commission 800516 memorandum & order,CLI-80-16, deciding not to exclude issue from 770809 notice & order for hearing Parties may submit comments & pleadings within 10 days SMITH,I W Atomic Safety and Licensing Board Panel 80/05/30 Spp
- 8006180040 Forwards PA Consumer Advocate 800830 petition for reconsideration of Commission memorandum & order, CLI-80-19, which denied financial assistance to participating intervenors

 BLASK, J. K. Pennsylvania, State of 80/05/30 1p
- ---8006180043 Petition by PA Consumer Advocate for reconsideration of Commission memorandum & urder,CLI-80-19, which denied financial assistance to participating intervenors Petitioner is entrusted by statute to define consumers' interest BLASK,J K . COMEN,W W Pennsylvania, State of. 80/05/30 9pp
- 8008040122 Further response to ASLB 800331 memorandum & order re Class 9 accidents Encl "TMI-1 Potential Core Damage Accident Sequences & Preventive & Mitigative Measures," contains event trees & nerus to TMI-2 accident WiCertificate of Byc CUTCHIN, J M Hearing Branch 3 80/06/02, 4pp

nt Sequences & Preventive

ing conference

80/06/03

- B006110110 Expresses concern w/inadequaty of TMI Alert suppl response to licensee interrogatories \$ 800520 memo re TMI-1 restart Appropriate relief from ASLB.including possible move to dismiss contention 5, will be sought W/Certificate of Svc BLAKE.E L Shaw, Pittman, Potts & Trowbridge 80/06/04 2pp
- ~-8006110117 Opposes TMI Alert 800529 matter to compet follower discovery of licensee on grounds of untimeliness & irrelevancy of interrogatories Certificate of Svc encl BLAKE, E.L. Metrogolitan Edison Co. BLAKE, E.L. Shaw, Pittman, Potts & Troubridge 80/06/04 7pp
- 8006110370 Motion for reconsideration of Commission 800516 memorandum & order.CLI-80~16 Order resolved factual issues w/o benefit of record & w/o giving opportunity to parties to present cases WEISSER Union of Conterned Scientists WEISS, E.R. Sheldon, Harmon & Weiss 80/06/04 7pp
- --8006110380 Request for late filing of UCS motion for reconsideration of Commission 800516 memorandum & order, CLI-80-16 Intervenor was involved in other proceedings Cortificate of Svc encl WEISSER Vinion of Concerned Scientists WEISS, ER Sheldon, Harmon & Weiss 80/06/04 4pp
- BOO6110116 Forwards affidavit supporting licensee supplemental response to interrogatories on Contention 2 served on 800519
 Certificate of Byc enci
 BERNSTELLO, L. Shaw. Pittman, Potts & Trowbridge 80/06/05 5pp
- 8006120371 Opposition to licensee motion to require further specificity of contentions Licensee seeks to extend discovery w/o affording reciprocal opportunity & to compet testimony months before due date Certificate of Svc encl WEISS,E R Union of Concerned Scientists UEISS,E R Sheldon, Harmon & Weiss BO/06/05 App
- 8006110066 Forwards QPU 800514 cash & earnings forecast, reflecting recent NJ & PA rate order impact in response to Interrogatory 6 of PA Public Util Commission HERBEIN, 9 @ Metropolitan Edison Co 80/06/06 54pp
- 8006110155 Memorandum & order permitting TMI Alert to reply to licensee 800604 response raising issues re intervenor 800529 motion to compel discovery Response should address intervenor timeliness & be filed within 10 days 8MITH.I W Atomic Safety and Licensing Board Panel 80/06/06 ip
- 800&120330 Requests denial of license motion for further specificity of intervenor TMI Alert contentions & reaffirmation of ASLD B00505 order SER will contain info essential to development of contentions Certificate of Svc encl ADLER, T.A. Three Mile Island Alert ADLER, T.A. Widoff, Reager, Selkowitz & Adler B0/06/06 3pp
- 80061203BI Motion to defer ruling on hydrogen control contentions by suspending effectiveness of ASLB 800530 memorandum & order bending NRC review of UCS motion for reconsideration of CLI-80-16 Certificate of Svc encl WEISS, E R Union of Concerned Scientists WEISS, E R Sheldon, Harmon & Heiss 80/06/06 App
- 8006120380 Forwards PA Public Util Commission 800523 order re issue of financial competence BMITH, I W Atomic Safety and Licensing Board Panel 80/06/09 27pp
- B004i60004 Forwards under separate cover Revision 2 to licensee emergency plan.including current emergency plans of State of PA & Dauphin.York.Lancaster.Lebanon & Cumberland counties research hearing Certificate of Svc encl
 ZAHLER.RE Bhaw, Pittman, Potts & Trombridge 80/06/09 5pp
- 8006130239 Supplemental response to interrogatories Includes info re schematic diagram depicting TMI-2 vent header or gaseous radwaste disposal sys RW Keaton affidavit & Certificate of Svc encl TROUBRIDGE, 0 F Metropolitan Edison Co TROUBRIDGE, 0 F Shaw, Pittman, Potts & Troubridge 80/06/10 7pp
- 8006160043 Memorandum to svc list Notifies that licenses unable to perfect svc described in 800609 memorandum Amended Cartificate of 8vc encl ZAHLER,R E Shaw, Pittman, Potts & Troubridge NRC 80/06/10 ip

- 8006160052 Response stating no objection to UCS 800606 motion to defer ruling on hydrogen control contentions & suspend ASLB 800530 order Conditions position on granting 15 addl days for parties to comment on order W/Certificate of Svc TROMBRIDOE, OF Metropolitan Edison Co TROMBRIDGE, O F Shaw, Pittman, Potts & Trombridge 80/06/11 4pp
- 8006160042 Response to licensee 800523 motion for further spec of contentions Supports motion for Sholly Contention 14 & UCS Contention 13 Urges denial of remaining requests Certificate of Byc encl SNARTZ.L.L. Antitrust Division 80/06/12 8pp
- 8006160061 Memorandum & order declining to dismiss Environ Coalition on Nuclear Power as party in response to applicant 800509 motion Dismisses majority of intervenor contentions for failure to comply widiscovery requests JORDAN,W H . LITTLE,L W . SMITH.I W . Atomic Safety and Licensing Board Panel 80/06/12 24pp
- --8006160067 Response to ASLB 800513 prehearing conference questions re intervenor ability to answer interrogatories Opposes NRC & licensee pattern of procedural harassment Certificate of Svc KEPFORD, C Environmental Coalition on Nuclear Power 80/04/03
- BOD6250355 Notifies of BOD617 meeting w/Ofc of Executive Legal Director & Div of Licensing personnel in Bethesda.MD to discuss question & answer format for restart testimony Appropriate mpt personnel & designated witnesses from div should attend NOVAK.T Assistant Director for Operating Reactors 80/06/12 1p
- B006iB0402 Order granting UCS 800604 motion for late filing of petition for reconsideration of Commission B00416 decision, CLI-80-16 Parties are afforded until B00625 to respond to motion Decision shall be stayed until further orders re restart CHILK.S J Commission B0/06/13 Zpp
- 8006190628 First answers to licensee interrogatories includes info re priorities of corrective maint problems Supporting for the desired and supporting for the supporting for the
- 8006190435 Preliminary response to Sholly 800609 motion re ASLB 800530 order Requests 15-day extension to respond to substitution of Contention II Opposes extension of discovery on hydrogen control contention Certificate of Svc encl TROWNRIDGE, OF Metropolitan Edison Co TROWNRIDGE, OF Shaw, Pittman, Potts & Trowbridge 80/06/16 App
- BOO6190443 Response in opposition to Consumer Advocate of PA 800530 petition for reconsideration of Commission 800516 order denying financial assistance Commission authority properly exercised per applicable policy Certificate of Svc enci SWANSON, D T Hearing Branch 1 80/06/16 6pp
- BOO6200335 Certifies syc of BOO616 TMI-1 restart evaluation of licensee compliance w/short & long-term items of 790816 order, on BOO616 SWARTZ, L Antitrust Division BO/06/16 2pp
- 8006190533 Memorandum & order granting UCS 800606 motion seeking suspension of ASLB 800530 memorandum & order, re hydrogen control contentions, pending ruling on UCS motion for reconsideration of CLI-80-16 SMITH, I W Atomic Safety and Licensing Board Panel 80/06/17. Spp
- BO06300335 Forwards BO0616 "Further Commission Outdance for Power Reactor CLs, Statement of Policy," & Commission BO0607 statement of interim policy, "Nuclear Power Plant Accident Consideration under NEPA of 1969 " BWARTZ, L. Antitrust Division 80/06/17 3pp
- BOO6240447 Order suspending requirement for taking any steps predicated upon issue of amergency planning Extensive revision to gmargency plan BOO602 Class 9 sequence & BOO616 BER render BOO522 schedule too burdensome BMITH. I W Atomic Sefety and Licensing Board Panel BO/06/19 4pp
- 8006260171 Memorandum & order requiring further spec of Antinuclear Group Representing York, Newberry, Sholly, UCS & TMI Alert contentions, by 800731, following issuance of safety evaluation. SMITH.I.W Atomic Bafety and Licensing Board Panel 80/06/23

- 8006260194 Kemorandum on NRC rept. "TMI-1 Potential Cure Damage Accident Sequences & Preventive & Mitigative Measures " Accepts rept in lieu of response to ASLB 800331 order Specifies safety concerns to be subj of written testimnny SMITH.I U Atomic Safety and Licensing Board Panel 80/06/2 B0/04/23
- 8006260263 Memorandum & order setting schedule of events between 800616 safety evaluation & 800812 final prehearing conference re ASLB 800522 memorandum & order Motions for summary disposition may be filed by 800503 Certificate of Svc encl SMITH. I W Atomic Safety and Licensing Board Panel 80/06/23 Spp
- B006270237 Metion for further clarification of Environ Coalition on Nuclear Power Contentions 2-2 & 2-4 in manner consistent w/ASLB 800215 & 27 orders re emergency planning contentions in restart proceeding Certificate of Svc encl TROWBRIDGE, G F Houston Lighting & Power Co TROWBRIDGE, G F St Pittman. Potts & Trowbridge 80/06/23 7pp
- 8006260275 Response in support of UCS 800606 motion for reconsideration of Commission decision CLI-80-16 re hydrogen control criteria Urges waiver of hydrogen design basis assumptions if Commission adheres to decision Certificate of Svc encl TROUBERIDGE, OF Metropolitan Edison Co TROUBERIDGE, OF Shaw, Pittman, Potts & Troubridge 80/06/24 9pp
- 8006260213 Response to intervenor MI Lewis interrogatories per NRC commitments stated in NRC 800324 & 31 responses to MI Lewis motions to compel discovery includes corrected version of NRC previous Answer 20 W/affidavits & Certificate of Svc SWARTZ/L L Antitrust Division 80/06/25 12pp
- 8006270234 Response in apposition to UCS 800604 motion for reconsideration of CLI-80-16 Commission adequately & properly exercised authority re certified questions Haivar of regulation not warranted Certificate of 8vc encl
- 8006300408 Memorandum requesting licensee to notify ASLAB & parties whether App A of util June 1980 emergency plantes implementation, will be submitted in restart proceeding SHITM, I U Atomic Bafety and Licensing Board Panel 80/06/25
- 8006300427 Memorandum & order denying TMI Alert 800527 motion to compel licensee answers to followup interrogatories, due to untimeliness & irrelevancy, re restart proceeding BMITH, I W Atomic Safety and Licensing Board Panel 80/06/25 opp
- H General correspondence
- BOO6170150 Comments, submitted on behalf of Follett Corp, re restart of facility Return to syc will reduce cost of replacement power to util customers FDLK, J Affiliation Unknown BO/05/20 ip
- 8006170145 Urges licensing of nuclear power plants that meet new NRC stds DOEPKEN,H C Affiliation Unknown 80/05/26
- 8006170137 Comments on decreased income from investment in util due to NRC attention to protesters rather than facts No lives have been lost resulting from nuclear power plant failures ELLIOTT, C.P. Affiliation Unknown 80/05/27 ip
- 8006190446 Requests hearings re restart of facility be expedited Delay unreasonable & unfair to stockholders & users of util electricity JOYA.N Affiliation Unknown 80/06/04 ip
- BOO61903B1 Urges NRC to return TMI-1 to operation due to high energy costs & threat to industrial & commercial development ANDERSGN.B J Northampton County, PA 80/06/10 1p
- 8006240168 Ack receipt of itr expressing concern about delay in TMI-1 restart Commission ordered that TMI-1 remain in cold shutdown condition until further order by NRC & stated that public hearing be held prior to restart DENTON, HR Diffice of Nuclear Reactor Regulation, Director 8020640 2000 DENTON, H R D: 80/04/10 2pp
- BOO6270102 Provides status & history of actions re facility restart, in response to request for reply to H Obler ltr Preparations for restart hearing required more than guidelines in Commission 790807 order Hearing estimated to begin Oct 1980. DIRCKS.W.J. Office of the Executive Director for Operations. , Sbb
- --8006270106 Provides H Obler 800330 ltr re facility restart for response SARBANES, P.S. Sanate 80/04/15 1p

- 8006300300 Forwards NJ Utils Association resolution requesting that NRC expedite TMI-1 restart due to excellent svc provided by JCP&L LAWRING.OF New Jersey Utilities Association 80/06/19 4pp

I Financial information

- 8006110066 Forwards GPU 800514 cash & earnings forecast, reflecting racent NJ & PA rate order impact in response to Interrogatory 6 of PA Public Util Commission (HERBEIN, J G Metropolitan Edison Co 80/06/06 54pp
- 8006170711 Forwards 780927 operating agreement & 701102 Memorandum of Agreement re sharing of facility const costs, between Met Ed.JCPL & Penelec GENTIEU.L P General Public Utilities GPU Service Corp 80/06/11
- 8006200371 Forwards "General Public Utilities Cash & Earnings Forecast. June 1980-Dec 1981 " HERBEIN.J G Metropolitan Edison Co 80/06/16 19pp
- BOO6240303 Forwards "General Public Utils Sys Cash & Earnings Forecast" for Jun 1980-Dac 1981 per telcon between util & NRC HERBEIN, J G Hetropolitan Edison Co 80/06/16 2pp
- --B004240304 "General Public Utils Sys Cash & Earnings Forecast" for Jun 1980-Dec 1981 * Metropolitan Edison Co BD/06/05 18pp

J. Insurance & indemnity information

- 8006190033 Grants extension until 800601 for compliance w/Price-Anderson Act financial protection requirements DENION.H R Office of Nuclear Reactor Regulation, Director 80/04/0B 1p
- 8006030380 Confirms that effective 790501 supplemental limit of ANI Policy NF-220 was extended in accordance w/800529 ltr to Harsh & McLennan Confirms that effective 800601.limbility limit will be restored Ltr to Marsh & McLennan encl QUATTROCCHI.J American Nuclear Insurers 80/05/29 3pp
- 8006030411 Forwards Endorsement 36 to MAELU Policy MF-73 GERETY.H F General Public Utilities GPU Service Corp 80/09/30
- 8006050346 Responds to NRC 600408 ltr re financial protection Nuclear liability insurance pools will provide twenty million dollars primary insurance for TMT-2 as well as reinstating that amount expended for claims & expenses HERBEIN.J Q Metropolitan Edison Co 80/05/30 Jpp
- BOO6180408 Forwards BOO612 ltr to MAM w/endorsements that pools propose to use binder to implement coverage contained in 800520 ltr to C Bollman Endorsements sent to NRC for consideration of financial protection at plant GUATTROCCHI, J American Nuclear Insurers BO/06/12 Spp
- B006300676 Responds to 800530 ltr re compliance w/financial protection requirements for Unit 2 Since endorsement for add1 \$20 million not received.NRC unable to determine compliance Info re alternatives to insurance requested SALTZMAN. J Utility Finance Branch B0/06/13 2pp

P Operating license stage documents & correspondence

- BOO6090100 Responds to BO0321 ltr re util possible financial failure financial failure provides grounds for license revocation No contingency plans completed to cover possibility of financial failure

 AMEARNE.J F Commission 80/05/07 2pp Commission 80/05/07 2pp
- --8006090102 Inquires as to aftermath of util financial failure.

 EHANAMAN, S M Pennsulvania: State of 80/03/21 2pp

- 8006130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EIBENHUT,D G Division of Licensing 80/05/19 72pp
- B004020215 Informs that util presented info toward closing out facility restart open items at 900520 meeting 5 committed to confirm info & provide addl input in 800523 formal submittal Requests SER inputs by 800529 SILVER. H Operating Reactors Branch 4 80/05/22 1p
- 8006020195 Forwards Amend 18 to restart rept HERBEIN, J G Metropolitan Edison Co 80/05/23 1p
- -8006020201 Amend 18 to restart rept providing add1 info * Metropolitan Edison Co 80/05/23 24pp
- --8006020209 Radiation protection glan.App 7A.Revision 3 POTTS:W E . HERBEIN.J G Metropolitan Edison Co 98 80/05/20
- ---8006020210 Operational QA program, Revision 8 KAZANAS, N C , LONG, R L , HERBEIN, J G Metropolitan Edison Co 80/04/18 115pp
- 8006070425 Requests addi fee re 800411 Tech Spec Change Request 91 accompanied by Class II amend fee Proposed action involves Class III fee DIOOS:R M License Fee Management Dranch 80/05/27 ip
- 8006050280 Forwards schedules for future work to support TMI-1 restart safety evaluation HERDEIN, J G Metropolitan Edison Co 80/05/28 3pp
- 8006030302 Forwards answer to five informal questions re corrective actions for 800226 Crystal River accident Operators will be trained re integrated control sys/non-nuclear instrumentation power failures

 HERBEIN, J G Metropolitan Edison Co 80/05/29 3pp
- 8004030335 Forwards response to NRC 800305 ltr re loss of offsite power events. One partial loss of offsite power has occurred as described in LER 77-15 dtd 770828 No total loss of offsite power events experienced HERDEIN.J G Metropolitan Edison Co 80/05/30 2pp
- 8006030380 Responds to NRC 800410 ltr re use of term "operable" as applied to single failure criterion for safety sys in power reactors Requests extension until 800930 for TMI-1 Tech Spacs change No change required for TMI-2 HERBEIN, J G Metropolitan Edison Co 80 B0/05/30 1n
- 8006090364 Responds to 800410 ltr re use of term operable applying to single failure criterion for safety sys in power reactors Performing review of Unit 1 Tech Specs to determine need for mod Unit 2 operating under recovery Tech Specs HERBEIN.J 0 Metropolitan Edison Co 80/05/30 2pp
- 8006200631 Forwards NRC 800827 ltr.Amend 55 to License DPR-50.wafety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/04/03 4pp
- -8004200633 Advises that NRC has issued amend to License DPR-50. consisting of revisions to & additions of Tech Specs reventilation filter sys for control room, auxiliary & fuel handling bldgs & reactor bldg purge
 TOURTELLOTTE, J Hearing Branch 4 80/05/27 ip
- --8006200636 Amend 55 to License DPR-50, updating Tech Specs to include revised requirements for air treatment sys in emergency control room & reactor bldg REID,RW Operating Reactors Branch 4 80/06/03 17pp
- --8006200639 Safety evaluation supporting Amend 55 to License DPR-50 * Operating Reactors Branch 4 80/06/03 3pp
- --8006200643 Notice of issuance & availability of Amend 55 to License REID, R W Operating Reactors Branch 4 80/06/03 2PP,
- 8006130312 Forwards response to NRC 800517 telcon re util Tech Spec Change Request 77s which modified ring girder/tendon surveillance requirements HERBEIN.J G Metropolitan Edison Co 80/06/07 \$pp

- 8006170495 Forwards data re General Public Utils sys capabilities, peak load, reserve margins, net sys requirements & interchange RUNTE, W G General Public Utilities GPU Service Corp 80/06/11
- 8006260055 Forwards FR notice of availability of evaluation for TMI-1 restart & NURCO-0680 NUREG-0680 supersedes NRC 800111 status rept to evaluation of licensee compliance w/790809 order EISENHUT, D G Division of Licensing 80/06/16 4pp
- --8006260059 Notice of availability of evaluation for TMI-1 restart REID.R W Operating Reactors Branch 4 80/06/16 2pp
- --8006260060 "TMI-1 Restart Evaluation of Licensee Compliance w/Short & Long-Term Items of Section II of NRC Order dtd 790809 "
 * Commission NUREG-0680 80/06/30 200pp
- 800&300210 Requests meeting w/util within 30 days of receipt of ltr to resolve outstanding issues re review of NRC comments to draft radiological ETS Also requests final version of Figures 5-3 & 5-4 for review & acceptance REID,R W Operating Reactors Branch 4 80/06/17 4pp
- 8006270332 Forwards add1 fee for Tech Bpec Change Request 91 re mod of reactor vessel surveillance program
 HERBEIN.J G Metropolitan Edison Co 80/06/19 2pp
- 8006260004 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals, THI-1"

 UDY, A C EG&O, Inc FIN A-6256 8006260004 80/06/30 8pp
- O Inspection reports, IE Bulletins & correspondence
- BD06090195 Ack receipt of B00403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-320/77-25 & 50-209/77-19 GRIER.B H Region 1, Philadelphia, Office of the Director B0/04/29 2pp
- --B004090157 Responds to 800205 ltr re violations noted in IE Insp Repts 30-320/79-29 & 80-289/79-19 Requests submittal of corrective actions re Item 2 Util 800205 ltr will be withheld (ref 10CFR2 790) GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/18 2pp
- --8006090160 Forwards IE Insp Repts S0-320/79-25 & 50-289/79-19 on 790916-21, 24-28 & 1002-04 & notice of violation Notice of violation withheld (ref 100FRZ 790)
 MARTILLW G Region 1, Philadelphia, Safeguards Branch 80/01/14
- --8006090170 IE Insp Repts 30-320/79-25 & 50-289/77-19 on 790916-21,24-28 & 1002-04 Noncompliance noted licensee vehicle not escorted in protected area & safety equipment on vital area physical barrier not maintained Details withheld (ref 10CFR2 790) DEVLIN.J W. Region 1. Philadelphia, Bafeguards Branch LADUN,R H. SHEPHERD.R E. Region 1. Philadelphia, Office of the Director 80/01/09 2pp
- 8006060574 Bubmits response to IE Bulletin 80-04 Limited emergency feedwater addition to steam generator W/broken steam line would not significantly increase containment peak pressure following steam line break HCRBEIN.J O Metropolitan Edison Co 80/05/09 2pp
- B006250183 Forwards IE Insp Rept 50-289/80-04 on 800205-29 No noncompliance noted CARLSONR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/09 2pp
- --8006250186 IE Insp Rept 50-289/80-04 on 800205-27 No noncompliance noted Kajor areas inspected audit program for engineering design, fire protection & restart program EUNETER: S D Region t, Philadelphia, Reactor Construction & Engineering Support Branch GAGE, L, PAOLIND, R Region 1, Philadelphia, Office of the Director 80/05/07 7pp
- 8006250178 Forwards IE Insp Rept 50-289/80-06 on 800301-31 No noncompliance noted CARLSON.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/15 2pp

- --8006250182 IE Insp Rept 50-289/80-06 on 800301-31 No moncompliance noted Major areas inspected work activities & records associated w/restart program, GA audits, fire protection & inservice insp

 EDNETERS Region 1, Philadelphia, Reactor Construction & Engineering Support Branch GAGELL , PADLING, R Region 1, Philadelphia, Gffice of the Director 80/05/13 7pp
- 8006120491 Forwards request for addl info re cracking in low pressure turbine discs Recommends development of schedule for uitrasonic insp during next fuel outage IE Info Notica 79-37 townary of 800109 meeting W/GE encl
 REID:R W Operating Reactors Branch 4 80/09/19 5pp
- 8006070417 Amplifies response to IE Bulletin 80-04 contained in 800507 ltr. stating that TMI-1 containment design pressure was 60 psig Reiterates that containment design pressure is 55 psig Initial response accurate when assuming 55 psig pressure HERBEIN, J G Metropolitan Edison Co 80/05/20 lp
- 8006200040 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- BOO6040111 Forwards util 800519 ltr directed to IE re civil penalty imposed on licensee SWART7.L L Antitrust Division 80/06/02 3pp
- 8006090313 Clarifies 791017 response to IE Bulletin 79-13, Revision 2, re feedwater piping cracks Early responses addressed design, fabrication, preservice & inservice insp & operation history B&W owners group 790813 ltr is applicable HERBEIN, J Q Metropolitan Edison Co 80/06/02 2pp
- 800&070319 Requests extension until 800730 for submittal of final response to IE Bulletin 79-27 HERBEIN,J 0 Metropolitan Edison Co 80/06/02 1p
- 8006230366 Notifies that NIS-1 rept will not be issued until exams complete per util 800220 ltr & NRC Investigation Rept 50-289777-10
 HERBEIN.J @ Metropolitan Edison Co 80/06/17 ip
- BOO6300370 Responds to IE Bulletin 80-07 re hydramotor actuator deficiencies No purchase orders made w/ITT General Controls Vendors listed in bulletin not on supplier list N958 did not use hydramotor actuators at facility HERBEINJJ G Metropolitan Edison Co 80/06/25 ip
- BOO6300451 Responds to 1E Bulletin 80-12 Reviewing hardware capacity to prevent decay heat removal loss event Analyzing procedures for adequacy of safeguarding against loss of redundancy & diversity Will provide response by 800630 HERBEIN, J G Metropolitan Edison Co 80/06/25 ip
- R Periodic operating reports & related correspondence
- 8004020118 Forwards TMI Program Ofc status rept for wk of 800517-23 COLLINS, J T TMI Program Office 80/05/27 4pp
- 8006020295 Forwards liquid & gaseous effluent release repts for Mar 1980 & first quarter 1980 Tables 1-5 provide add1 data for liquid discharges to Susquehanna River for 1980 Explanation of monthly summary included PORTER.S W Porter-Gert: Consultants. Inc. 80/05/27 ip
- ---8006020303 Liquid & gaseous releases for Mar 1780 & first quarter 1780 Fables 1-5 provide add1 date for liquid discharges into Susquehanna River for 1780 Explanation of monthly tummary included * Porter-Gertz Consultants, Inc. 80/05/27 8pp
- 8006110103 EPA preliminary data rept on water sampling for 800522-30 COBTA, C F Environmental Protection Agency 80/06/03 1p
- BOO6190690 Forwards status rept for wk of BO0531-0606 COLLING.J T TM1 Program Office BO/06/09 6pp
- 8006200495 Forwards monthly operating rept for May 1980 HERBEIN.J.G Metropolitan Edison Co 80/06/14 1p
- --8006200496 Monthly operating rept for May 1980 MITCHELL, D G Metropolitan Edison Co 80/04/15 5pp

S Reportable occurrences. LERs 5 related correspondence

- 9006130226 PNO-TMI-80-032 on 800523 worker experiencing chest pains left site in ambulance Diagnosis was possible heart attack Unknown if individual was in radiological area CONTE.R J. SHANDAKY, M M. COLCINS, J F Region 1. Philadelphia. Office of the Director 80/05/23 1p
- B004040404 Forwards revised LER 80-001/01Y-1 MERBEIN, J G Metropolitan Edison Co 80/05/30 1p
- --800A0A0409 Revised LER 80-001/01X-1 on 800123, results of load study performed on ES busses determined overload could exist on 1P & 18 busses upon loss of ES channel & one of four situations Caused by inadequate design MITCHELL, D G Metropolitan Edison Cu 80/05/30 3pp
- 8006250026 PNO-TMI-80-033 on 800530. Catalytic electrician left site in ambulance after falling 15 ft from ladder in control room Individual was not in controlled area HAYERMAMP.D., SHANBAMY.M. Region 1. Philadelphia, Office of the Director COLLINS, J. T. TMI Program Office 80/05/30 1p
- 8006120400 RD-80-10/iP on 800603.864 ltr informed util of potential reportability of steam generator tube rupture safety analysis Caused by nonconservative error in FSAR Corrective action will be addressed in followup rept
- 8006250362 PNO-TMI-800-304 on 800606, while performing maint on river water chlorination sys, chlorinator bldg chlorine monitor alarmed Licensee technicians venting portion of chlorination sys piping actuated alarm & caused chlorine odor HAVERKEMP.D., FASANO.A., COLLINS.J T Region 1. Philadelphia, Office of the Director 80/06/06 1p
- 8006300471 Forwards LER 80-009/03L-0 MERBEIN, J G Metropolitan Edison Co 80/06/25 ip
- --8006300478 LER 80-009/03L-0 on 800607.reactor bldg tendon surveillance late date was excepted Caused by problems w/availability of contractor equipment Surveillance continuing MITCHELL.D O Metropolitan Edison Co 80/06/25 2pp
- DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT I
- 8006160001 "Alternate Safe Shutdown Capability in Event of Fire in Cable Spreading Room" * Boston Edison Co 80/01/31 92pp
- 80060904B7 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D & Division of Licensing 80/03/19 44pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp.
- 8004030036 Forwards three repts of "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Generating Station," prepared by Franklin Research Ctr ANDOGNINI. 6 G Boston Edison Co 80/05/29 1p
- --8004030040 "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Power Cenerating Station." for 790531 testing * Franklin Institute/Franklin Research Center F-C5159-1 80/01/31 80pp
- ---8004030043 "Test of Cable Penetration Fire Stops for Pilgrim 1 Nuclear Generating Station." final rept for 790929 testing * Franklin Institute/Franklin Research Center F-CD199-2 B0/03/31 SOpp
- --8006030047 "Test of Cable Penetration Fire Stops for Pilgrim i Nuclear Power Generating Station:" final rept for 790907 testing # Franklin Institute/Franklin Research Center F-C5199-3 80/04/30 SOpp
- 8006130303 Forwards revised cover sheet for Security Training & Gualification Plans 1-5 Cover sheets withheld (ref 10CFR2 790) ANDOGNINI. © C Boston Edison Co 80/06/04 1p

M Antitrust correspondence

- 8006240439 Order granting MA Municipals 791011 withdrawal of intervention Neither NRC nor DOJ objects No further antitrust proceedings required CMILK,S.J. Office of the Secretary of the Commission 80/06/19 200
- P Operating license stage documents & correspondence
- 8006070165 Forwards add) TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams 3 licensee dissemination of operating experiences Response requested within 30 days EISENHUY, D Q Division of Licensing 80/05/07 150pp
- BOO5030514 Summary of BO0422-23 meeting w/Mark I owners group in San Jose,CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems BO/05/09 Spp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Concrator & Reactur Coolant Pump Supports "Proposed review procedure & implementation schedule and EISENHUT.D & Division of Licensing 80/05/19 72pp
- 8006030345 Forwards supplemental response to NRC 771128 ltr re containment purge & vent sys Testing performed during refueling outage supported original conclusion that max leakage occurs at max differential pressure ANDO
- 800&03034& Requests delay until 800701 for submittal of proposed Tech Spec revision clarifying term "operable," requested by NRC 800410 ltr ANDOUNTRIGC Boston Edison Co 80/05/27 ip
- 8006030407 Discusses analysis of containment purge & vent valve operability Dynamic & pressure loads acting on discs & stem will not cause undue stress while valve is closing during design basis LOCA if valve opening maintained at 45 F ANDOGNINI.G C Boston Edison Co 80/05/27 2pp
- 800&030310 Informs that response to NRC 800214 ltr re proposed radiological effluent & environ monitoring Tech Specs will not be available until Jul 1980
 ANDOONINI.O C Boston Edison Co BO/05/29 ip
- 8006130280 Responds to NRC 800425 ltr re effect of dc power supply failure on ECCS performance Results of evaluation to be transmitted by 800801 ANDGONINI.6 C Boston Edison Co 80/06/02 ip
- 8006300604 Ltr to all BMR licensees forwarding "For Comment" edition of NUREO-0619. "BMR Feedwater Notice & Control Rod Drive Return Line Notice Cracking." Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT.D @ Division of Licensing 80/06/05 22pp
- 8006260179 Responds to NRC 800507 itr re five add1 TMI-2 related requirements for operating reactors Well-defined criteria is needed to ensure timely implementation of recommendations Implementation schedules may warrant flexibility ANDOGNINI.0 C Boston Fdison Co 80/06/18 1p
- O Inspection reports: IE Bulletins & correspondence
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted STGHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --8005230341 Waste packaging insp rept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DOT & NRC regulations including shipping paper & DOT placarding requirement POTTER, J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/03/28 4pp
- 800605006B Forwards IE Investigation Rept 50-293/80-12 on 800304-07 & 19-20 No noncompliance noted MARTIN.N G Region 1, Philadelphia, Safeguards Branch 80/04/18 20p

- ---8006050149 IE Investigation Rept 50-293/80-12 on 800304-07 & 19-20 No noncompliance noted Area investigated allegations that spent fuel rods had been illegally burjed at Barnwell, SC low level waste burjal ground JUYNER, J H Region I. Philadelphia. Safeguards Branch WOLTNER, E. SUMIMERS, R. Region 1, Philadelphia. Office of the Director 80/04/17 12pp
- 8006060097 Forwards If Insp Rept 50-293/80-10 on 800305-07 No noncompliance noted MARTIN,N G Region 1, Philadelphia, Safeguards Branch 80/04/18
- --8006060101 IE Insp Rept 50-293/80~10 on 800305-07 No noncompliance noted Major areas inspected full scope math control & accounting, including facility organization & operation Details withheld (ref 100FR2 790)
 JOYMER, J. H. Region 1. Philadelphia, Safeguards Branch NOLTHER, E. SUMMERS. R. Region 1. Philadelphia, Office of the Director 80/04/03 ip
- 8006070191 Forwards 1C Investigation Rept 50-293/80-12 on 800305-07 & 19-20, in response to allegations re illegal shipments of spent fuel MARTIN, W G Region 1. Philadelphia, Gafeguards Branch 10/04/18
- --B004690176 IE Investigation Rept 50-293/B0-12 on 900305-07 & 19-20 No noncompliance noted Hajor areas inspected examination of pertinent documents? records & physical inventory of all fuel assemblies

 KEHOL, D., ROBERTS, K. Region i, Philadelphia, Office of the Director JUYNER, J. H. Region 1, Philadelphia, Safeguards Branch B0/04/16 12pp
- 8006200082 Forwards IL Circular 80-08, "BWR Tech Spec Inconsistency Reactor Protection Sys Response Time " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/04/18 ip
- 8006170822 Forwards waste packaging insp rept on 800313-14 No noncompliance noted SMITH, 0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 ip
- --8006170829 Waste packaging inspirept on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles, including shipping paper requirements.DOT placarding requirements radiation levels & marking & labeling BROWN.R A Region 2. Atlants. Puel Facility & Materials Bafety Branch POTTER.J P Region 2. Atlants. Office of the Director 80/03/28 dept
- 8006180092 Forwards Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted SMITH, Q H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 ip
- --8006180093 Waste Packaging Insp Rept 80-03 on 800227-27 No noncompliance noted Major areas inspected licensee-shipper vehicle, including shipping paper requirements, DDT placarding requirements, radiation levels & marking & labeling PECRY, W W , POTTER, J P Region 2, Atlanta, Foel Facility & Materials Safety Branch 80/03/18 7pp
- 8006170804 Forwards IE Insp Rept 50~293/80-13 on 800331-0401 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/30 2pp
- --B006170805 IE Insp Rept 50-293/80-13 on 800331-0401 No noncompliance noted Major areas inspected refueling activities KEH0E.D V Region 1, Philadelphia, Office of the Director MARTIB.T T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/18 4pp
- 800b120342 Responds to IF Bulletin 80-08 Facility has fluid head penetration connections u/containment boundary butt welds between penetration sleeve & integral fluid head outer skirt Magnetic particle exams performed during const ANOGONIMI.G C Boston Edison Co 80/05/16 2pp
- 8006240611 Ack receipt of 800508 ltr informing NRC of incorrect statements made in IE Jusp Rept 50-273/80-12 Corrected pages encl W/o encl MARTIN.W G Region 1. Philadelphia, Safeguards Branch 80/05/22 to

- --8006240617 Responds to NRC 800418 ltr Northeast Nuclear Energy Co incorrectly identified as util licensed to operate Haddam Nack Plant CQUNSIL,W G , SWITZER.D C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/08 2pp
- 8006130076 Addl response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON.J M Division of Rules and Records 80/05/23 3pp
- 8006190332 Requests provision of personnel for field survey me plant breakwater review Low tide on 800610 will allow insp of toe of structure Site visit necessary to recommend final approval of design & placement BIVINS.W S Hydrologic & Geotechnical Engineering Branch 80/05/28
- 8006270175 Submits response to IE Bulletin 80-07. "BWR Jet Pump Assembly Failure " Visual television insp & ultrasonic testing revealed deficiencies on jet pumps 1.3 & 15 Jet pumps replaced in kind Data base broadened for surveillance ANDOONINI.0 C Boston Edison Co BO/06/19 2pp
- R Periodic operating reports & related correspondence
- 8006180444 Forwards monthly operating rept for May 1980 MCGUIRE, P J Boston Edison Co 80/06/01 1p
- --8006180446 Monthly operating rept for May 1980 WHITNEY.Q Q Boston Edison Co 80/06/01 6pp
- 9006190640 Forwards monthly operating rept for May 1980 MCGUIRE, P J Boston Edison Co BO/06/01 1p
- --8006190643 Monthly operating rept for May 1980
 WHITNEY, 0 0 Boston Edison Co 80/06/11 App
- S Reportable occurrences, LERs & related correspondence
- 8004050401 PND-I-80-078 on E00515,NRC was notified that Chem-Nuclear tractor trailer hauling low specific activity radwaste broke down Tractor engine determined irreparable No loss of contents or radiological problems identified CRUCKER.81. SMITH.0 H Region 1. Philadelphia. Office of the Director 80/05/15 ip
- 8006090385 Forwards LER 80-017/03L-0 MCGUIRE.P J Boston Edison Co 80/06/02 1p
- --8006090391 LER 80-017/03L-0 on 800505, during 24-h performance test of diesel generator per IE Bulletin 79-23, three attempts made before satisfactory coholusion on 800510 Caused by failure of potential transformer in high voltage chassis MCLGUORLIN, M T Bostan Edisan Ca 80/06/02 3pp
- 8006250242 Forwards LER 80-018/03L-0 MCGUIRE, P J Roston Edison Co 80/06/12 1p
- --9006250243 LER 80-018/03L-0 on 800523, while performing surveillance test 8 7 4 3. isolation valves, 5065-11, 13 % 23 declared inoperable Cause not stated Valve in each affected sample line closed & position recorded daily MCLOUGHLIN,M T Boston Edison Co 80/06/12 1p
- BO06250244 Forwards LER 80-019/09L-0 MCGUIRE.P J Boston Edison Co 80/06/16 1p
- --8006250246 LER 80-017/03L-0 on 800519 during startup of PNPS, HPC1 sys was declared inoperable Caused by wiring attendant to installation of alternate shutdown panel & seal exhaust leakage interference Wiring & leakage repaired MCLOUGHLIN, M T Boston Edison Co 80/06/13 2pp
- 8006240471 Forwards LER 80-020/03L-0 MCGUIRE,P J Boston Edison Co 80/06/18 1p
- --B006240479 LER B0-020/03i-0 on B00426, during refueling outage 4,14 primary containment isolation valves found to have seat leakage over requirements Caused by normal detenioration of disc to seat mating susface MCGUIRE,T J Boston Edison Co B0/06/18 2pp

- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

 Q Inspection reports, IE Bulletins & correspondence
- 8006250043 Forwards lE Insp Rept 50-294/60-02 on 600430-0501 No noncompliance noted DAVIS.A B Region 3, Chicago: Fuel Facility & Materials Safety Branch 80/05/14 2pp
- --8004250047 IE Insp Rept 50-294/80-02 on 800430-0501 No noncompliance noted Major areas inspected emergency glan & pracedures, coordination w/support agencies, survey instrumentation & environ monitoring program ESSIO.T H Region 3, Chicago, Office of the Director GREER, R J Region 2, Atlanta, Office of the Director 80/05/14 4pp
- 8004070307 Ack receipt of 800501 ltr informing NRC of steps taken to correct moncompliance noted in NRC 800424 ltr
 DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety
 Branch 80/05/22 ip
- ~-8006090515 Responds to stem of noncompliance noted in ARC 800426 its Corrective actions reactor safety committee meetings have been timely since 79(119 TERRY, 8 H. CARRICK, J. T. Michigan State Univ. 80/05/01 ip
- NGCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
 F. Security, medical, emorgency % fire protection plans
- 800612052B Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/05/13 2pp
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT. D G Division of Licensing 80/09/17 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 itr Page 14a not enci EISENHUT. D Q Division of Licensing 80/05/22 73pp
- B006120007 Advises that NRC review of B00324 safeguards contingency plan indicates need for addl revisions Specific comments withheld (ref 10CFR2 790) VARQA,8 A Operating Reactors Branch 1 80/05/27 2pp
- BOOA090274 Forwards addl fire protection info as suppl to util 800430 ltr re safe shutdown analysis which takes plant to hot shutdown Addl info provides for taking plant to cold shutdown PEOPLES, D.L. Commonwealth Edison Co. 80/05/28 lp
- 8006180293 Forwards Revision i to draft emergency plan Emergency plan station annexes also encl PEDPLES, D L. Commonwealth Edison Co. 80/06/04 2pp.
- ---8005180340 braft emergency plan annex * Commonwealth Edison Co 80/07/31 37pp
- --8006180347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co 80/07/31 139pp
- 8006240490 Responds to NRC 800425.30.0501.09 t²20 ltrs requesting addl info re guard training & qualification plans Requests that response submittal date be estended to 800804 PEOPLES.D L. Commonwealth Edison Co. 80/06/18 ip
- @ Adjudicatory correspondence
- 8005050236 Forwards util affidavits of TR Tramm & RE Ghannon describing planned minor changes in spent fuel rack replacement job procedures Changes relate to intervenor argument on appeal Related correspondence STEPTOE.P Isham, Lincoln & Beale 80/05/05 2pp
- ---8006060242 Affidavit recommending that genetrant test exams per uncl Procedure NDT-D, or equivalent, be substituted for ultrasonic test exam technique in spant fuel pit corrosion surveillance program BHANNQN, R E Commonwealth Edison Co 80/04/23 7pp

- --8006060243 "Liquid Penetrant Exam "
 * Commonwealth Edison Co 78/12/06 15co
- --8006060246 Affidavit describing decontamination techniques that will be employed in spent fuel replacement jobs to reduce total volof radwaste mat)
 TRAMM.TR Commonwealth Edison Co 80/05/05 2pp
- BOOA170218 Brief in support of ASLB BOO214 initial decision authorizing installation of new lacks.for which intervenor filed 15 exceptions Intervenor offers of support alloged error in decision

 STEPTOE.P P. MILLCR.M I Commonwealth Edison Co BTEPTOE.P P. Isham Lincoln & Beale BO/OS/OS 44pp
- 8006060357 Discusses C Guigg ltr to NRC requesting stay in proceeding re-proposed amend to increase spent fuel storage capacity Guigg assertions inaccurate AELB found that adequate design to safety features proclude loss-of-water accident STEPTOE.P P Isham, Lincoln & Beale 80/05/12 2pp
- B006020316 Order for 800701 oral argument in NRC Public Hearing Room. Bethesda:MD One hour of argument & rebuttal will be granted to each party D18HOP:C J Atomic Safety and Licensing Appeal Panel 80/05/23
- 8006190310 Responds to 800505 objection to scheduling meetings outside Hashington.DC area Meetings ate occasionally held outside of Washington.DC vicinity to allow persons living near plants opportunity to attend EISENHUT.D 0 Division of Litensing 80/06/02 2pp
- H General correspondence
- BOOBO20014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas HAMM,K Affiliation Unknown 80/03/19 ip
- P Operating license stage documents & correspondence
- BOO4010004 Forwards "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting From TMI-2 Lessons Learned "All Category A requirements satisfied SCHWENCER.A Operating Reactors Branch 1 (Pre BO
- ---8004010006 "Evaluation of Licensee Compliance w/Category A Items of NR Recommendations Resulting From TMI-2 Lessons Learned " * Division of Operating Reactors B0/02/28 lipp.
- 8006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline uill also be used KEPPLER, J. G. Region S. Chicago, Office of the Director 80/04/18 2pp
- BOO6090165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIGENHUT, D 0 Division of Licensing 80/05/07 150pp
- BOO6090493 Notification of 800603 meeting w/util in Bethesda,MD to discuss filtered vented containment sys & core retention devices
 MEYER.J F Reactor Systems Branch 80/05/27 3pp
- 8006040002 Notification of 800520 meeting w/utils.contractors & consultants in Dethesda,MD to exchange technology reaccident sequence & related phenomena per A Schwencer 800410 ltr to L Peoples LONO,J K Reactor 8ystems Branch 80/05/15 2pp
- 8006130122 Requests comments on NUREG-05/7, "Potential for Low Fracture Toughness 3 Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D & Division of Licensing 80/05/19 72pp
- 8006190171 Forwards request for add1 items required to complete upgrade review of GA program Response should be provided along w/response to 800408 request 4
 VARQA:5 A Operating Reactors Branch 1 80/05/20 4pp

- 8006020097 Notification of 800605 meeting w/util in Bethesda.MD to discuss upgraded OA program SPRAUL,J Quality Assurance Branch 80/05/21 2pp
- 8006020172 Notification of 800530 meeting w/utils in Bethesda, MD re severe accident mitigation features for facilities CL6HAN.L , REEVES.E Operating Reactors Branch 1 80/05/23 1p
- 8006240067 Advises that interim reliability evaluation program resulting from TMI action plan will be implemented Requests attendance at 800604 meeting in BethesdamD to discuss details
 EISENHUT, D 0 Division of Licensing 80/05/23 5pp
- 0006160057 Forwards revised Tech Spec Pages 94,328a,79,8 80 issued w/ Amends 54 & 51 to Licenses DPR-39 & DPR-48, respectively VAROA.S A Operating Reactors Branch 1 80/05/29 2pp
- BOO6020347 Update to BO0422 application to amend Licenses DPR-39 & DPR-48, incorporating administrative changes to App A. Tech Specs NAUGHTON, N F Commonwealth Edison Co BO/05/30 2pp
- ---8006020349 Revised Page 300 to App A.Toch Specs 6 0 for administrative controls Allows either rad-chem supervisor or lead health physicist to fulfill qualifications of radiation protection manager
 - * Commonwealth Edison Co 80/05/30 2pp
- 8006260009 "Loss of Offsito Power Scenarios for Hestinghouse Zion 1 PNR." preliminary assessment rept FLETCHER.C D., BRUSKE,S J., DELANEY.H M. EG&G. Inc. FIN A-6148C 8006260009 80/05/31 95pp
- 8006090296 Application for amend to Licenses DPR-39 & DPR-48, modifying allowed outage time per 800229 confirmatory order Combined Class I & III fee encl NAUGHTON, N F Commonwealth Edison Co 80/06/03 3pp
- 8006090305 Forwards response to NRC 800506 request for history of total & partial power outages & attendant degraded voltage No complete loss of offsite power has occurred, but one partial loss incident was reported to NRC NAUGHTON, W F Commonwealth Edison Co 80/06/05 2pp
- 8006120404 Forwards slides used by utils during 800603 meeting re technology exchange in area or mitigation feature for severe accidents at facilities ODEBER; D. Westinghouse Electric Corp. 80/06/05 1p
- BOOA170451 Forwards "Mitigation of Severe Accident Study Rept " Rept includes presentations made to NRC & ACRS on BOO220 & 0305, respectively & consists of state-of-the-art analyses conducted within AO-day period CAHILL, W J Consolidated Fdison Co of New York EARLY, F J Power Authority of the State of New York 80/06/05 2pp
- ---8006170459 Responds to 800528 ltr transmitting rept covering work performed by various consultants Entire Westinghouse rept nonproprietary PEOPLES,D L Commonwealth Edison Co 80/06/09 3pp
- --B006170466 "Mitigation of Severe Accident Study Rept," consisting of repts re evaluation of residual risk steam explosions, containment response for Class 9 accidents & post-accident containment vent sys conceptual designs # Westinghouse Electric Corp B0/03/31 400pp
- 8006130165 Forwards check inadvertently left off package submitted on BD0603 W/o encl PIENTA: R Commonwealth Edison Co 80/06/06 Ip
- HOO6140071 Forwards response to NRC Questions 2B 4B re facility QA program per HO0408 & 0520 requests
 PEOPLES, D L Commonwealth Edison Co HO/06/09 12pp.
- 8006240165 Notification of 800612 meeting w/utils in Bethesda.MD to discuss interim reliability evaluation program OLBHAN,L N, Operating Reactors Branch 1 80/06/09 2pp
- B006190307 Forwards commitments to comply w/requirements & schedules in NRC B00507 ltr re add1 TMI-2 related requirements Dresden Unit I is currently undergoing extensive mod & decontenmination, therefore no response is provided PEOPLES.D L Commonwealth Edison Co 80/06/12 10pp

- 8006270047 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda.MD re accident mitigation features for facilities LDNG, J. K. Reactor Systems Branch 80/06/12 27pp
- 8006250280 Notification of 800618 meeting w/utils.contractors & consultants in Bethesda.MD for presentation in area of core-melt accident sequences for facilities Agenda encl MEYER,JF Reactor Systems Branch 80/06/16 2pp
- B006200953 Notification of B00617 meeting w/utils & consultants in Bethesda.MD to discuss technology exchange re containment structural response failure pressures & failure modes MEYER.J F Reactor Systems Branch B0/06/17 2pp
- 8006300207 Requests re-evaluation of original proposal for submitting schedule for implementing ATHS instrumentation mods identified in NUREO-0460 Revised schedule & justification should be submitted in 30 days VAROA.S A Operating Reactors Branch 1 80/06/19 2pp
- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations" Revised Revision II includes basis on which equivalent education requirements will be established PEOPLES,D L Commonwealth Edison Co 80/06/23 1p
- 8006270329 Forwards response to NRC B00502 questions on adequacy of station electric distribution sys voltages Lowest bus voltage when starting largest non-Class IE load was calculated when all other loads were running Motor started NAUGHTON-W F Commonwealth Edison Co B0/06/23 9pp
- @ Inspection reports, IE Bulletins & correspondence
- 8006170727 Forwards IE Insp Repts 50-295/80-03 \$ 50-304/80-02 on 800207-0328 \$ notice of violation HEISHMAN.R F Region 3. Chicago: Reactor Operations Nuclear Support Branch 80/04/26 2pp
- --8006170730 Notice of violation from insp on 800207-0328 * Region 3, Chicago, Office of the Director 80/04/18 ip
- --8006170738 IE Insp Repts 50-295/80-03 & 50-304/80-02 on 800207-0328
 Noncompliance noted min shutdown margin requirements while
 in cold shutdown were below Tech Spec limits
 KOMLER, J E. LITTLE, W S Region 3, Chicago, Office of the
 Director 80/04/18 Spp
- 8006170291 Forwards IE Insp Repts 50-295/80-06 & 50-304/80-05 on 800310-11 & 0417-18 No noncompliance noted HEISHMAN,R F Region 3, Chicago: Reactor Operations Nuclear Support Branch 80/04/30 2pp
- --8006170295 IE Insp Repts 50-295/80-06 & 50-304/80-05 on B00310-i1 & O417-18 No noncompliance noted Major areas inspected small break LOCA procedure KOHLER, J. NELSON, R. Ragion 3, Chicago, Office of the Director LITTLE, N. B. Ragion 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/25 4pp
- 800619037B Forwards IE Insp Repts 50-275/80-04 & 50-304/80-03 on 80031B No noncompliance noted DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/05/07 2pp
- --8006190379 IE Insp Regts 50-295/80-04 & 50-304/80-03 on 800318 No noncompliance noted Major areas inspected confirmatory measurements from previous collection, effluent samples & submission of spiked samples EBBIG.T H. JANUSKA, A.O. Region 3, Chicago, Office of the Director 80/05/06 App
- 8006230070 Forwards IE Insp Repts 50~295/80~07 % 50~304/80~06 on 8004;4-30 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/13 2pp
- ---8006230077 IE Insp Repts 50-295/80-07 & 50-304/80-06 on 800414-30 No noncompliance noted Major areas inspected licenses actions to comply with 800227 confirmatory order LITTLE.H S · KOHLER.J E Region 3. Chicago, Office of the Director 80/05/12 9pp
- 8006130076 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON.J M Division of Rules and Records 80/05/23 3pp.

- --B00&130099 Forwards response to updated memo received on B00313 re util interrogatories re proposed imposition of civil penalty Cover sheet of IE insp. rept encl KEPPLER. J. G. Region 3. Chicago, Office of the Director 80/03/21 2pp
- --8006130102 Discusses three safety-related events occurring at facility Civil penalty for noncompliance items will be imposed Forwards notice of violation notice of proposed imposition of civil penalties & history of enforcement action VOLGENAU.E Office of Inspection & Enforcement, Office of the Director 77/09/30 2pp
- --8006130104 Natice of violation from insp on 770705-08.14.19 \$ 21 * Office of Inspection & Enforcement, Office of the Director 77/09/30 3pp
- --B004130108 Notice of proposed imposition of civil penalties in amount of \$21,000 re noncompliance discovered during insp on 770705-08,14,15 & 21 History of escalated enforcement action encl

 # Office of Inspection & Enforcement, Office of the Director
- 8006170326 Immediate action lit re JE physical security insp on 800512-15 & 19-20 Licensee is expected to undertake actions autilined in ent Encl withheld (ref 100FR2 790) KEFPLER. J G Region 3. Chicago. Office of the Director 80/05/23
- 8006250297 Advises that responses to IE Bulletin 79-06A, Revision 1, were found acceptable Evaluation encl VARQA, S. A. Operating Reactors Branch 1 80/05/28 17pp
- 8006300558 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Proposed mode identified only if present sys design may compromise protective action of equipment PEOPLES.D L. Commonwealth Edison Co 80/06/10 9pp
- S Reportable occurrences. LERs & related correspondence
- 8006180285 Forwards RD re diesel driven fire pump MANDKE,N & Commonwealth Edison Co 80/05/19 1p
- ---BOO61BOZB9 RO on BO0409, i6 & 23.0B dissel driven fire pump failed to auto start & tripped on overspeed after being started Caused by worn water pump drive belt & speed switch Engine cooling sys flushed & refilled w/antifreeze & demineralized water BCHNEIDER.H Commonwealth Edison Co BO/05/2B 2pp
- 8006030497 Forwards LER 80-021/03L-0 WANDKE,N E Commonwealth Edison Co 80/05/23 ie
- --B004030505 LER B0-021/03L-0 on B00423, while operating at 98% power, monthly surveillance requiring performance testing of safeguards logic & high pressure logic was performed it days late Caused by transcription error Testing was performed DEAN.W J Commonwealth Edison Co B0/05/23 ip.
- B006170470 Forwards LER 80-023/01T-0 WANDKE,N E Commonwealth Edison Co B0/06/06 Ip.
- ---8006170475 LER 80-023/01T-0 on 800523 charging pump 10CFR21 concern discovered through Westinghouse generic notification Caused by design flow insufficient at high pressure Standing order issued to open minificor valves when needed MADDEN. J Commonwealth Edison Co 80/06/06. 2pp
- 8006170498 Forwards LER 80-022/03L-0 WANDXE.N E Commonwealth Edison Co. 80/06/06 1p

- --8006270252 LER 80-025/03L-0 on 800510 while performing periodic tests, function generator INM-441B output was found out of tolerance Caused by instrument diffting Unit recallibrURNKINS.R V Commonwealth Edison Co 80/06/09 ip
- 8006270251 Forwards LER 80-027/01T-0 WANDKE.N E Commonwealth Edison Co 80/06/12 1p
- --8006270256 LER 80-027/017-0 on 800601. while in cold shutdown, bleedrates for steam generator snubbers under rated load found consistently below min limit Caused by weak bleed valve compensator springs Springs installed w/higher spring rates WENNERHOLM J Commonwealth Edison Co 80/06/12 2pp
- 8006270254 Forwards LER 80-024/03L-0 WANDKE,N E Commonwealth Edison Co 80/06/13 ip
- --8006270259 LER 80-024/03L-0 on 800515, while performing PT-10, safeguards actuation tests, IA svc pump failed to start from train A of safeguards Caused by contacts for safeguards actuation making intermittent contact Contacts adjusted CLARK,8 Commonwealth Edison Co 80/06/13 ip
- 8006300403 Forwards updated LER 80-024/99X-1 WANDXE,N E Commonwealth Edison Co 80/06/18 1p
- --8006300407 Forwards updated LER 80-024/79X-1 WANDKE:N E Commonwealth Edison Co 80/06/18 1
- --B006300412 Updated LER 80-024/99X-1 on B00515.while performing PT-10. safeguards actuation tests.1A svc water pump failed to start from train A Caused by type W-2 switch contacts making intermittent contact Permanent mod being ovaluated WANDXE.N E Communuealth Edison Co B0/06/18 3pp
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 8008040147 Requests 800520-21 meeting to visit technical support ctr, operational support ctr & emorgency operations facility re compliance w/NUREG-0654 Public comments will be recoived at 800521 evening meeting facting notice & agenda encl IPPOLITG.T A Operating Reactors Branch 2 80/05/14 2pp
- BOOGO90487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds now Bection 30 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D O Division of Licensing 80/09/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101." transmitted by NRC 800519 ltr Page 14a not encl EESENHUT.D 0 Division of Licensing, 80/05/22 73pp
- 8006050322 Submits opposition to NRC clarification of emergency planning requirements Locating emergency operations facility within emergency planning zone adds to number of people to be evacuated & creates weakness inside zone ODDMIN:A V Alabama. State of 80/05/29 2pp
- 8006060235 Forwards 800521 revisions to training & qualification plan & responses to NRC 800430 comments Encls withheld (ref 10CFR2 790)
 MILLS.L H Tennessee Valley Authority 80/06/02 1p
- 8006060313 Forwards revisions to safeguards contingency plan Plan withheld (ref 100FR2 790) MILLS:L M Tennessee Valley Authority 80/06/02 1p
- 8006170803 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces 8 practices, including visit to facility to interview security mpt personnel IPPOLITO.T A Operating Reactors Branch 2 80/06/03 2pp
- P Operating license stage documents & correspondence
- BOO6090169 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIGENHUT.D © Division of Licensing 80/05/07 150pp

- 8004030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA ie confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES.C I Assistant Director for Plant Systems 80/05/09 App
- 8006130122 Requests comments on NUREG-057/, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & Implementation schedule encl
 EISENHUT.D © Division of Licensing 80/05/19 72pp
- 8006050177 Notification of 800529 meeting w/util in Bethesda, MD for util presentation of proposed schedule for implementation of major mods required by NRC CLARK.R J Operating Reactors Branch 2 80/05/27 1p
- 8006050394 Notification of 800529 meeting w/util in Bethesda.MD to discuss util proposed design of post-accident sampling facilities Operating Reactors Branch 2 80/05/27 ip
- B006110286 Ack receipt of B00425 ltr to HG Parris re effect of dc power supply failure on ECCS performance Response will be provided before B00725 as given verbally to RJ Clark on B00930 MILLS.t. M Tennessee Valley Authority B0706703 1p
- BOO6300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation M/o encl EISENHUT.D G Division of Licensing 80/06/05 22pp
- 8006230514 Forwards proposed changes to facility Tech Specs per DG Eisenhut 800410 ltr & 100FR50 59 provisions MILLS-L M Tennessee Valley Authority 80/06/13 2pp
- --8006230520 Proposed Tech Spec revisions for safety-related sys Change justifications enci * Tennessee Valley Authority 80/06/13 22pp
- 800623043B Forwards info concerning turbine discs per 800516 request Continued operation of facility is justified & OLs should not be modified, suspended or revoked, based on responses DURALL, J.R. Tennessee Valley Authority 80/06/19 10pp
- 8006270269 Forwards response to NRC 800507 ltr re implementation of five add1 YMI-2 (essons Learned requirements concerning shift manning, licensing exams, licensee dissemination & small break LOCA general review matters

 MILLS, L M Tennessee Valley Authority 80/06/23 9pp
- G. Inspection reports, IE Bulletins & correspondence
- 800A200078 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/04/18
- BOOA090038 Forwards IE Bulletin 60-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8004040267 Forwards IE Bulietin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/09
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- 8006240160 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-259/80-19, 50-260/80-14 & 50-226/80-15 LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Br
- --8006240164 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-259/80-19.50-260/80-14 & 50-296/80-15 Corrective actions personnel reminded that procedures must be followed when working on any critical piping sys or equipment MILLS,L M Tennessee Valley Authority 80/05/20 Spp .

- ---8006240167 Forwards IE Insp Repts 50-259/80-19,50-260/80-14 & 50-296/80-15 on 800307-0404 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --8006240169 Notice of violation from insp on 800307-0404 # Region 2. Atlanta, Reactor Operations Nuclear Support Branch BB/04/24 1p
- --B006240174 IE Insp Repts 90-259/80-19.50-260/80-14 & 50-296/80-15 on 800307-0404 Noncompliance noted failure to follow procedures in heat-treatment of Unit 1 HPCI steam piping DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch SULLIVAN.R F. CHASE.J N Region 2. Atlanta. Office of the Director 80/04/24 Spp
- B006240251 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-13, 50-260/80-11 & 50-296/80-12 LEWISR C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/06/02 ip
- --8006240258 Responds to NRC 800423 ltr re violations noted in IE Insp Repts 50-257/80-13, 50-260/80-11 & 50-296/80-12 Corrective actions personnel instructed to keep shift engineer informed of work status & sys status procedure revised MILLS, L M Tennessee Valley Authority 80/05/20 3pp
- -8006240264 Forwards IE Insp Repts 50-259/80-13.50-260/80-11 & 50-296/80-12 on 800204-0307 b notice of violation LEWIS,R C Region 2. Atlanta, Reactor Sperations Nuclear Support Branch 80/04/23 2pp
- --8006240267 Notice of violation from insp on 800204-0307 LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN.J Region 2, Atlanta, Office of the Director 80/04/23 19
- --8004240273 IE Insp Repts 50-259/80-13.50-260/80-11 & 50-294/80-12 on 800204-0307 Noncompliance noted failure to demonstrate HPCl operable when RCIC was imperable for maint DANCE. H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch SULLIVAN, R F . CHASE. J W Region 2. Atlanta. Office of the Director 80/04/23 6pp
- GOO6250135 Ack receipt of 800521 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-16, 50-260/80-13 & 50-276/80-14
 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch GO/06/03 tp
- --8006250144 Responds to NRC 800425 ltr re violations noted in IE Insp Repts 50-259/80-16,50-260/80-13 & 50-296/80-14 Corrective actions personnel trained on 800416 for emergency director duties & training records corrected MILLB.L N Tennessee Valley Authority 80/05/21 5pp
- -8006250150 Forwards IE Insp Repts 50-259/80-16.50-260/80-13 & 50-294/80-14 on 800324-28 & 0331-0404 & notice of
- --8006250155 Notice of violation from insp on 800324-28 & 0327-0404 * Region 2. Atlanta, Office of the Director 80/04/24 1p
- --8006250165 IE insp Repts 50-257/80-16,50-260/80-13 & 50-276/80-14 on 800324-28 & 0329-0404 Noncompliance noted failure to train designated successors to amergency director & to keep training records in order & prepare training procedures JENKINS, O R Region 2, Atlanta, Fuel Facility & Materials Safety Branch ANDREMS, D L., PERROTTI, D J Region 2, Atlanta, Office of the Director 80/04/24 13pp
- 8006300228 Forwards investigation results in response to IE Bulletin BO-06 Sys mods.design changes & other possible actions will be provided in monthly progress repts beginning 800710 Review will be completed by 801f01 CROSS.J L. Tennessee Valley Authority 60/06/12 3pp
- R Periodic operating reports & related correspondence
- BOO6170501 Forwards monthly operating repts for May 1780 ABERCROMBIE.H Tennessee Valley Authority 80/06/10
- --8006170507 Monthly operating repts for May 1980 * Tennessee Valley Authority 80/06/01 32

- 8 Reportable occurrences: LERs & related correspondence
- BO06060309 Forwards LER 80-017/03L-0 CALHOUN, J R Tennessee Valley Authority B0/06/02 1p
- --8005050323 LER 80-017/03L-0 on 800404, after running 9I 4 ii c 3 & 4, last page of 9I was missing Last page had not been performed 3 of last 4 months, so one fire protection zone not tested monthly Caused by misplacement Page replaced * Tennessee Valley Authority 80/05/02 2pp
- B004i10104 Forwards LER 80-012/03L-0 CALHOUN, J R Fennessee Valley Authority 80/04/06 1p
- -8006110124 LER 80-012/03L-0 an 800509, while performing 81 4 2 A-3, LIS-3-56a switch 2 & LIS-3-56b switch 2 failed to operate Causad by stuck switch contacts Switch contacts cleaned & checked for proper setpoint

 * Tennessee Valley Authority 80/06/06 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J L Chemtron Corp., Tube Turns Div 80/06/06 3pp
- BOO6170581 Forwards LER 80-014/03L-0 CALHOUN.J R Tennessee Valley Authority 80/06/10 ip
- --9006170892 LER 80-014/03L-0 on 800512 during normal operation reactor core isolation cooling tripped on overspeed due to loss of speed control Caused by diode in EOM box failure due to end of life EOM box replaced & calibr # Tennessee Valley Authority 80/06/10 2pp
- 8006170506 Forwards LER 80-015/03L-0 CALHGUN,J R Tennessee Valley Authority 80/06/11 1p
- --8006170512 LER 80-015/03L-0 on 800512.3B RHR pump cooling water flow determined inadequate per T5 3 5 8 1(2) & 3 5 88 5 Caused by apparent restriction in cooling water piping Exchanger removed & flushed * Tennessee Valley Authority 80/06/10
- 8006170603 Forwards LER 80-016/03L-0 CALHOUN,J R Tennessee Valley Authority 80/06/11 1p
- ---8006170614 LER 80-016/03L-0 on B00513, following completion of flow test on diesel generator heat exchanger 3D, cooling water found inadequate per Tech Spec 3 5 9 2 Apparently caused by restriction in cooling water piping Mater lines flushed * Tennessee Valley Authority 80/06/11 2pp
- 8006180502 Forwards LER 80-013/03L-0 GALHGUN:J R Tennessee Valley Authority 80/06/12 1p
- --8006180520 LER 80-013/03L-0 on 800517,L18-3-568 switch 2 failed to operate Cause attributed to stuck switch contacts.Leaf switches inside level indicating switch replaced & checked for proper setpoint & repeatability

 * Tennessee Valley Authority 80/06/12 2PP
- 8006240499 Forwards LER 80-018/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/17 1g
- --8006240507 LER 80-018/03L-0 on 800519, reactor low pressure switch PS-3-74B SM 1, found out of tolerance Caused by instrument setpoint drift Barton 288 pressure switch inspected, recalibr & functionally tested for repeatablifty Tennessee Valley Authority 80/06/17 2pp
- DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR F Becurity, medical, emergency & fire protection plans
- 8006i19367 Ack receipt of NRC 8005i9 ltr re physical protection requirements Physical security plan submitted & implemented in 1974 achieves objectives of 10CFR73 67(a), (b), (c), (f) & (g), therefore new plan is not necessary
 BRAY, T C. North Carolina State Univ 80/06/04 ip

- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emorgency & fire protection plans
- 8006090407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR90 & 1s expected to be published in FR by end of May RISENHUT, D O Division of Licensing 80/05/19 46pp
- 8006:3006:3 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790:01." transmitted by NRC 8005:19 1tr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006070318 Forwards revised pages to safeguards contingency plan. Revision i Revision withheld (ref 10CFR2 770) PILANT.J M Nebraska Public Power District 80/05/30 ip
- 8006110251 Forwards addl info re guard training & qualification plan in response to NRC 800424 ltr Info withheld (ref 10CFR2 790) PILANT,J M Nebraska Public Power District 80/06/05 ip
- P Operating license stage documents & correspondence
- 8004090165 Forwards addl TMI-2 related requirements to operating reactors Licensees requirements for THI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days RISENHUT, D G Division of Licensing 80/05/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES C I Assistant Director for Plant Systems 80/05/09 Bpp
- 9006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Proposed review procedure & implementation schedule encl EISENHUT,D @ Division of Licensing 80/05/19 72pp
- B006030461 Responds to NRC B00410 itr requesting amend to radiological Tech Specs to clarify meaning of term operable Previous discussions w/IE inspector concluded spec contains adequate clarification & no addl revision is necessary PILANT. J M Nebreska Public Power District B0/05/30 ip
- 8006110075 Discusses effect of dc power supply failure on ECCS performance Forwards listing of ECCS sys available w/various single failures Loss of equipment due to water spillage has been satisfactorily addrossed PILANT.J M Nebraska Public Power District 80/06/03 3pp
- 8006300604 Ltr to all BMR licenses forwarding "For Comment" edition of NUREO-0619. "BMR Feedwater Nozzle 3 Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT.D O Division of Licensing 80/06/05 22pp
- HOO&24090D Advises that util intends to respond to HOO507 request re TMI-2 requirements within schedule Util presently evaluating alternatives within framework of QE BMR owners group PILANT.J M Nebraska Public Power District BO/06/18 2pp
- 8006230542 Requests expeditious deletion of Tech Spec 2 1 1/3 1 1 re max change of temp across condenser as indicated on encl revised pages Class 2 fee encl PILANT.J M Nebrasia Public Power District 80/06/20 3pp
- --B006230546 Deletes Tech Spec 2 1 1/3 1 1 re max change of temp across Nebraska Public Power District 80/06/20 2pp
- @ Inspection reports, IF Bulletins & correspondence
- 8006030519 Forwards IF Insp Rept 50-298/80-04 on 800311-13 & 24-27 No MADSEN, O L Region 4, Dallas, Reactor Operations Nuclear Support Branch BD/04/18 2pp
- --B006030334 IE Insp Rept 50-298/80-04 on 800311-13 & 24-27 No noncompliance noted Major areas inspected GA program. GE type 8BM control switch problem & refueling activities NESTERMAN. TF. CONSTRUELS, DEAN, S.R. Region 4, ballas, of the Director 80/04/17 5pp Region 4, ballas, Office

- 8006200115 Forwards IE Circular 80-08, "RWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/18
- 8006020130 Forwards IE lusp Rept 50-298/79-18 on 791203 No noncompliance noted BRGWN.0 D Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/04/30 2pp
- ---B004020135 IE Insp Rept 50-298/79-18 on 791203 No noncompliance noted Major areas inspected regulations, instructions & operating procedures, training & audit program BROWN. 9 D Region 4, Dallas, Eucl Facility & Materials Safety Branch HARRISON, H C Region 4, Dallas, Office of the Director B0/04/23 3pp
- 8006040046 Responds to IF Bulletin 80-07, "BWR Jet Pump Assembly Failure" Confirms 800505 telcon reporting completion of ultrasonic tests No crack indications were found PILANT, J M Nebraska Public Power District 80/05/05 1p
- 8006190284 Forwards IE Insp Rept 50-278/80-06 on 800408-11.21-23 & 29-30 No noncompliance noted MADSEN.6 L Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/05/07 2pp
- ---8006190289 IE Insp Rept 50-298/80-06 on 800408-11,21-23 & 29-30 No noncompliance noted Major areas inspected OA.calibr. inservice insp procedures & IE Bulletin 79-018 MESTERMAN, T F, SPANGLER, R G, CONSTABLE, G L Region 4, Dallas, Office of the Directon 80/05/06 8pp
- 8006060597 Forwards IE Bulletin 80-ii, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl SEYFRIT, K V Region 4. Dallas. Office of the Director 80/05/08
- 8006040287 Forwards IE Bullotin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit I While in Refueling Mode" encl SEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/09
- 8006140164 Discusses violation noted in IE Insp Repts 50-298/79-20 & 50-298/80-05 Package & vehicle not identical except in case of bulk shipments of low specific activity radioactive matls Citation appropriate Corrective actions requested SNIEZEK.J H Division of Fuel Facility & Naterials Safety 80/05/30 2pp
- R Periodic operating reports & related correspondence
- 8004070322 Forwards monthly operating root for May 1980 LESBOR.L C Nebraska Public Power District 80/06/02
- --8006070323 Monthly operating rept for May 1780
 #ALLINGER,P L Nebraska Public Power District 80/06/02
- S TINU THALL SOURCE THION TO THE STANDOR F Security, medical, emergency & fire protection plans
- 8006030177 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER.J G Region 3, Chicago, Office of the Director 80/0
- BOO60904B7 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Bection 50 48 % App R to 10CRRSO & is expected to be published in FR by end of May EISENHUY, D G Bivision of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101;" transmitted by NRC 800517 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp

- 8006300452 Forwards addl info re design of fixed water suppression sys, fire hydrant insps & control room light fixtures for fire protection safety evaluation Notification requested by 800718. If design mods are required FAY.C W Wisconsin Electric Power Co 80/06/23 18pp
- Operating license stage documents & correspondence
- 8006070165 Forwards addl TMI-2 related requirements to operating reactors Licenses requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8006040060 Notifies that facility will use Chem Nuclear Inc Model CN8 6-80-2 radioactive shipping cask for delivery of matls to carrier FAY.C W Wisconsin Electric Power Co 80/05/14 1p
- BOO6130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness > Lamellar Tearing on PWR Bteam Generator & Reactor Coolant Pump Bupports " Proposed review procedure & implementation schedule encl EISENHUT,D G Division of Licensing 80/05/19 72pp
- BOO6170244 Forwards Amends 49 % 50 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability CLARK, R A Operating Reactors Branch 3 BO/05/20 3pp
- --8006170247 Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively, incorporating Tech Specs contained in Apps A & B in license Amends add limiting conditions for operation & surveillance requirements for low temp mitigating sys CLARK, R A Operating Reactors Branch 3 80/05/20 36pp
- --8006170253 Safety evaluation supporting Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively # Office of Nuclear Reactor Regulation, Director 80/05/20
- -8006170236 Notice of issuance & availability of Amends 45 & 50 to Licenses DPR-24 & DPR-27, respectively CLARK,R A Operating Reactors Branch 3 80/03/20 2pp
- 8006130037 Forwards safety evaluation supporting design aspects of containment purge valve isolation override 5 other engineered safety feature actuation signals except radiation monitors which initiate containment purge isolation CLARK, R A Operating Reactors Branch 3 80/05/22 2pp
- --8006130039 Safety evaluation supporting design aspects of containment purge valve isolation override & other engineered safety feature actuation signals except radiation monitors which initiate containment purge isolation

 * Operating Reactors Branch 3 80/05/22 ip
- -8006136040 "Technical Evaluation of Electrical Instrumentation & Control Design Aspects of Override Containment Purge Valve
 Isolation & Other Engineered Bafety Feature Signals for
 Point Beach Nuclear Power Station. Vnits 1 & 2 "
 HACKETT, D B E080; Inc FIN A-0231 E00183-4139 79/09/30
- 8006030344 Forwards description of proposed mode to instrument bus power supplies, in response to NRC 800421 ltr Mode will be completed by 810101 Diagram of proposed supply sys to white & yellow instrument buses encl
 FAY, C W Wisconsin Electric Power Co 80/05/27 4pp
- BOO6110127 Advises that util is forwarding under separate cover.set of piping & instrumentation diagrams for plant Listing of diagrams also forwarded w/package FAY.C W Wisconsin Electric Power Co 80/06/04 ip
- 8006120307 Discusses NUREG/CR-1280 re power plant staffing Util has neither unlimited funding nor unlimited supply of people to implement sys which Navy has developed Lists TMI-related aspects which have been overlooked

 SUTTNER, T A Affiliation Unknown 80/06/05 App
- 8006180555 Withdraws 800514 request for NRC contractor to visit facility to perform interviews & other activities associated w/NRC contract Util 800527 ltr requested postponement or cancellation of visit due to high level of plant activities HEIBHMAN, F F Region 3, Chicago, Reactor Operations Nuclear Support Brench 80/06/05 ip

- --800618055B Responds to B00514 request that NRC contractor be allowed to visit facility to meet w/training staff & test emergency procedures Requests postponement or cancellation of visit due to high level of activities at plant BURSTEIR. S Wisconsin Electric Power Co B0/05/27 2pp
- B006200460 Forwards response to NRC 800507 ltr re five add1 TMI-2 related requirements for operating reactors Assumes that implementation of add1 requirements was not meant to impede completion of previous commitments
 FAY.C W Wisconsin Electric Power Co 80/06/11 8pp

G Inspection reports, IE Builtetins & correspondence

- B006180574 Forwards IE Insp Repts 50~266/80-07 & 50~301/80-06 on 800408-10 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/05/02 2pp
- ---GOO6180581 IE Insp Repts 50-266/80-07 & 50-301/80-06 on 800408-10 No noncompliance noted Major areas inspected radiation protection program associated wirefueling outage, including radiation protection procedures & training exposure control MILLER.D E , LOVENDALE.P C Region 3, Chicago. Office of the Director FISHER.W L Region 3, Chicago. Fuel Facility & Materials Safety Branch 80/04/28 7pp
- 8006200272 Forwards IE Insp Repts 50-266/80-09 % 50-301/80-08 on 800310-14 & 0408 No noncompliance noted HEIBHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/16 2pp
- --8006200280 IE Insp Repts 50-266/80-07 & 50-301/80-08 on 800310-14 & O408 No noncompliance noted Major areas inspected plant procedures & operator training On 800408 meeting was held to review plant performance WARNICK, R F, SMITH, J D, REIMANN, F W Region 3, Chicago, Office of the Director 80/05/16 Spp
- 8006050034 Forwards proprietary response to IE Insp Repts 50-266/80-06 & 50-301/80-05 Revision to modified amended security plan withheld (ref 10CFR2 790) BURBITEIN S Wisconsin Electric Power Co 80/05/29 2pp
- 8006190650 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" No safety-related sys or component uses AH-90 or NH-90 series hydramotor actuator FAY:C W Wisconsin Electric Power Co 80/05/29 ip
- 8006300262 Responds to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Plant design does not provide for automatic actuation of ECCS recirculation or automatic positioning of containment recirculation sump valves FAY.C W Wisconsin Electric Power Co 80/06/05, 2pp.
- 8006160092 Forwards response to NRC request for info re facility Mar 1980 eddy current insp Info provided re number of eddy current indications recorded in Steam Generator A & B hot legs & distribution by size & height above tubesheet FAY, C. W Wisconsin Electric Power Co 80/06/09 3pp
- 8006200541 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/80-06 & 50-301/80-05 HTMD-J A Region 3, Chicago, Safeguards Branch 80/06/10 1p
- --8006200547 Responds to NRC 800502 ltr re violations noted in IE Insp Repts 50-266/80-06 & 50-301/80-05 Corrective actions withheld (ref socre2 790) BURSTEIM:S Wisconsin Electric Power Co 80/05/29 1p
- 8006230038 Forwards IE Insp Repts 50-246/80-08 & 50-301/80-07 on 800819-23 No noncompitance noted HIND, J.A. Region 3, Chicago, Bafeguards Branch 80/06/10 2pp
- --B006230043 IE Insp Repts 50-266/80-08 & 50-301/80-07 on B00519-23 No noncompliance noted Major areas inspected mail control & accountability organization measurement & control storage & inventory Rept details withharld (ref 100FR2 790) HIND-J.A Region 3. Chicago. Safaguards Branch FINLEY,A 9 , PATIERSON.J P Region 3. Chicago. Office of the Director B0/06/10

R Periodic operating reports & related correspondence

BOOA170473 Forwards monthly operating repts for May 1980 FAY, C. W. Wisconsin Electric Power Co. 80/06/10 ip

- S Reportable occurrences. LERs & related correspondence
- 8006090832 Discusses review of 800228 steam generator leak occurrence & results of subsequent insp Concludes that generators adequately inspected & are safe for continued operation 882fety evaluation encl PAMLICKI,8 S Materials Engineering Branch 80/05/23 2pp

V Operator Examinations

8006i10271 Requests concurrence that operating training program is equivalent to eitra man concept or background studies to justify arbitrary requirement Reply requested by 800701 FAY.C W Wisconsin Electric Power Co 80706/04 2pp

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

- 8006070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end of May EISENHUT, D & Division of Licensing 80/05/19 44pp
- BOOA130063 Forwards revised Pages 1-14 & New Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 1tr Page 14a not encl EISENHUT.D G Division of Licensing 80/05/22 73pp
- 8006020159 Advises of extension until 800801 for deployment of emergency response TLDs.par 800307 draft emergency plan Sites are being surveyed for proper location of deployment BRIOHT.R M Florida Power Corp 80/09/28 2pp
- GOD6090326 Requests that response to NRC 600522 ltr re safeguards contingency plan-be provided by 800630 REID:R W Operating Reactors Brench 4 80/05/29 2pp
- 8006180531 Advises that fire protection program mods will not be completed by Oct 1980, due to NRC delay in responding to util 791206 & 800115 submittals on safety evaluation items BRIGHT,R 14 Florida Power Corp 80/06/11 3pp

H General correspondence

- 800627008B Responds to 800509 itr requesting response to F Robinson questions about impact of 800226 accident on environ Facility will not be authorized to restant until post-accident remedial actions are satisfactorily completed DIRCKB, U J Office of the Erecutive Director for Operations 80/06/10 ip
- --8006270075 Requests response to encl F Robinson inquiry re impact of 800226 accident on environ STONE,R Senate 80/05/07, App
- 8006270413 Add1 response to FOIA request for 22 categories of documents re facility NUREO-0525. "Safeguards Summary Event List. Revision 1." is available in PDR FELTON, U II Division of Rules and Records B0/06/20 ip

I Financial information

- 8006240495 Forwards internal cash flow projection for or ending 771231, to satisfy requirements of 100FR140 21 Confirmation requested LDADER, J G Florida Power Corp 80/06/20 2pp
- J. Insurance & indemnity information
- 8006160019 Forwards Endorsement 42 to ANI Policy NF-195 FIELDER.J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/06/09 Rpp

- K Utility Final Safety Analysis Report (FSAR) & amends
- BOO61BO511 Forwards proposed revised pages to FBAR re on-job training for licensed operators & backup licensees Changes to FBAR will be made by amend at later date BAYNARD.P Y Florida Power Corp BO/06/11 Spp
- P Operating license stage documents & correspondence
- 8006050539 Forwards utils schedules for response to NRC 791121 ltr re C Michaelson concerns on small break LDCAs CAPRA.R TMI-2 Bulletins & Orders 79/12/10 ip
- BOO6060283 Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for B&W operating plants N/o encis CAPRA,R A Light Water Reactors Branch 3 80/01/17 3pp
- 8006270283 Forwards Tech Spec Change Request 55.Revision 1.for License DPR-72 Proposed Tech Specs revise organization for mgt & technical support & corrects orfsite organization chart Certificate of Svc encl BRIGHT.R M Florida Power Corp 80/04/23 4pp
- -8006270347 Revised Tech Specs for administrative controls * Florida Power Corp 80/04/23 8pp
- --8006270353 Application for Tech Spec Change Request 55, Revision 1 for License DPR-72 re administrative controls + Florida Power Corp 80/04/23 2pp
- BOD6090165 Forwards addl TMI-2 related sequirements to operating reactors Licensees sequirements for TM1 Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIBENHUT, D. G. Division of Licensing 80/05/07 150pp
- BOO6130122 Requests comments on NUREG-057/, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D G Division of Licensing 80/05/19 72pp
- 8006030323 Forwards "Design Review of Plant Shielding & Environ Qualification of Equipment for Spaces/Sys Which May Be Used in Post-Accident Operations Outside Containment at Crystal River Unit 3 Nuclear Generating Station." Revision I BRIGHT.R N Florida Power Corp 80/06/01 2pp
- --8006030326 "Design Review of Plant Shielding & Environ Qualification of Equipment for Spaces/Sys Which May Be Used in Post-Accident Operations Dutside Containment at Crystal River Unit 3 Nuclear Generating Station: "Revision 1 # Gilbert/Commonwealth Cos @0/05/3i 33pp
- 8006060354 Forwards "Evaluation of Steam Line Break Consequences Associated w/Removal of Rupture Matrix Bignals from Emergency Feedwater Valves " Rept felfills commitment of Item 51 in Enci B of 800502 submittal BAYNARD, P Y Florida Power Corp 80/06/02 2pp
- --E006060355 "Evaluation of Steam Line Break Consequences Associated w/Removal of Rupture Matrix Signals from Emergency Faeduater Valves "

 4 Florida Power Corp 80/05/23 12pp
- BOO6110080 Forwards amend to BAW-1607, "Crystal River Unit 3 Cycle 3 Reload Rept," Revision i Certificate of Svc encl BAYNARD,P Y Florida Power Corp 80/06/06 4pp
- -8006il008\$ Amenú to "Crystal River Unit 3 Cycle 3 Reload Rept," Redision 1 BAKER,H A Babcock & Wilcox Co , Nuclear Material Div BAH-1067 80/05/30 lipp
- 8006170771 Partial response to FOIA request for 22 categories of documents re facility Forwards App A & B documents Portions of App A documents Partions of App A documents Partions of App A documents Partial Section withheld tref FOIA Exemptions 4 & 61 N/o encls, FELTON, J M . Division of Rules and Records 80/06/11, 5pp
- BOO6300444 Forwards draft NRC licensing position. "Bafety Considerations for Temporary Chaite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating repts REID.R W Operating Reactors Branch 4 BO/06/12 logp

- 8006170488 Forwards response to NRC questions on analysis in BAW-1607 & startup physics test program
 BRIGHTIR M Florida Power Corp. 80/06/13 6pp
- 8006300554 Advises that evaluation transmitted 800602 to Ofc of Nuclear Reactor Regulation requires Class III fee Necessary adjustments will be made after final review DI005.R M License Fee Management Branch 80/06/18 1p
- 8006230403 Requests extension until 800721 to commit to TMI-2 related requirements & schedule implementation per DO Eisenhut B00807 ltr BAYNARD, P Y Florida Power Corp 80/06/19 2pp
- 8006240326 Forwards response to Questions 1a, 1b, 1d & 1f of NRC 800229 NOW AUGUSED FORWARDS RESPONSE TO QUESTIONS 14:10:10 & 17 DE MI Itr requesting add info re containment purpe & vent sys Responses to Questions)c & le will be submitted by 800715 Certificate of Svc encl BAYNARD, P Y Florida Power Corp 80/06/20 4pp
- a Inspection reports. IE Bullatins & correspondence
- BOO6060561 Responds to NRC 800328 ltr re violations noted in IE Insp Rept 50-302/79-55 Corrective actions strengthening of Ocod Housekeeping Procedure AI-1000 through indoctrination & security training sessions HANCOCK, J A Florida Power Corp 80/04/17 2pp
- ---800&060564 Forwards IE Insp Rept 50-302/79-55 on 791210-14 and notice of violation LEMIS.R C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/28 2pp
- --8006060566 Notice of violation from insp on 791210-14
 * Region 2. Atlanta. Office of the Director 80/0 60/03/28. 1p
- --8006060568 IE Insp Rept 50-302/79-55 on 791210-14 Noncompliance noted improper housekeeping, cleanliness & radiation control practices QUICK,D R Hegion 2. Atlanta, Office of the Director MARTI Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/03/2B 400
- 8006170760 Responds to NRC 800328 ltr re violations noted in IE Insp Rept 30-302/80-14 Corrective actions emergency plan reviewed & emergency plan roster & notification procedure updated MODRE-0 C Florida Fower Corp 80/04/18 3pp
- --8006170762 Forwards IE Insp 50-302/80-14 on 800226-0307 & notice of violation O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/28 2pp
- --8006170765 Notice of viglation from insp on 800226-0307 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/27 ip
- --8006170769 IE Insp Rept 50-302/80-14 on 800226-0307 Noncompliance noted failure to notify state govt of Class B emergency via natl warning sys & failure to list telephone number of plant manager on emergency roster MARTINUR D Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/03/27 143pp
- 8004030078 Forwards IE Insp Rept 50-302/80-17 on 800319-21 & 25-28 No noncompliance noted MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/04/21 2pp.
- --8006030085 IE Insp Rept 50-302/80-17 on 800319-21 & 25-28 No noncompliance noted Major areas inspected inservice insp program.procedures.work & compliance w/IE Bulletin 79-17.
 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch. ECONDMOB.N. Region 2. Atlanta. Office of the Director 80/04/18 App
- 8006190262 Forwards IE Insp Rept 50-302/80-21 on 800423-25, No noncompliance noted MURPHY: E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/05 2pp
- --B006190268 IE Insp Rept 50-302/80-21 on B00423-25 No noncompliance noted Major areas inspected installed equipment per IE Bulletin 79-018 CONLONT E Region 2, Atlanta, Reactor Construction & Engineeri Bulleth 77-018
 CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch RUFF, A B Region 2, Atlanta, Office of the Director 80/05/05 3pp

- 8006200519 Forwards lE Insp Rept 50~302/80-18 on 800331-0411 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/07 2pp
- --8006200525 IE Insp Rept 50-302/80-18 on 800331-0411 No noncompliance noted Major areas inspected previous insp findings, fuel receipt, refueling activities, maint activities & IE Bulletin 77-018

 MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch. DONAT.T J Region 2. Atlanta, Office of the Director 80/05/07 6pp
- 8006060535 Forwards IE Bulletin 80-11, "Masonry Walk Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl C'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006050287 Forwards IE Builetin 80-12, "Decay Heat Removel Sys
 Operability " Requires action & response within 30 days
 IE Info Notice 80-20. "Loss of Decay Keat Removal Capability
 at Davis-Basse Unit 1 White in Refueling Mode" enc!
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/09
 200
- 8006300083 Forwards IE Circular 80-ii, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 200
- 8006260017 Forwards IE Insp Rept 50-302/80-20 on 800414-19 No noncompitance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/15 2pp
- --8006260023 IE Insp Rept 50-302/80-20 on 800414-19 No noncompliance noted Mayor areas inspected refueling & followup on licensee identified items
 GUICK,D., STETKA T. Region 2. Atlanta, Office of the Director MARTIN.R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/15 6pp
- 8004250073 Forwards IE Insp Rept 50-302/80-22 on 800428-0502 No noncompliance noted LEMIS:R C Region 2. Atlanta: Reactor Operations Nuclear Support Branch 80/05/16 2pp
- --8006250076 IE Insp Rept 50-302/80-22 on 800428-0502 No noncompliance noted Major areas inspected refueling, surveillance activities & IE Bulletin 79-2!
 UPRIGHT,C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch. BURNETT,P T Region 2, Atlanta. Office of the Director 80/05/16 4pp
- 8006020403 Forwards supplemental response to violation noted in IE insp Rept 50-302/80-13 Util 800508 memo distributed to all plant personnel re-emphasized intent of temporary procedure change & limits to change HANCOCK, J. A. Florida Power Corp. 80/05/27 3pp
- 8006190681 Ack receipt of 800506 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-15 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/05/29. 1p
- ---8006190683 Responds to NRC 800418 ltm re violations noted in IE Imsp Rept 50-302/80-15 Corrective actions personnel operating laundry reminded of importance of procedural adherence Laundry survey requirements posted in leundry area HANCOCK, J A Florida Power Corp 80/05/06. 2pp.
- --8006190687 Forwards IE Insp Rept 50-302/80-15 on 800318-21 & notice of violation STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/04/18 2pp
- --8004170671 Notice of violation from insp on 800318-21 * Region 2, Atlanta, Office of the Director 80/04/17, 1p
- --8006190692 IE Insp Rept 50-302/80-15 on 800318-21 Noncompliance noted. contamination of protective clothing, ready for userin excess of procedural limits EMALD.8 C Region 2. Atlanta, Office of the Director GIBSON, A.F., Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/04/17 9pp

- 8006110185 Forwards response to IE Bulletin 80-12. "Decay Heat Removal Bys Operability " Conduct of operations has been revised to establish administrative controls to be followed prior to voluntarily entering degraded mode of operation DRIGHT.R M Florida Power Corp 80/06/06 Spp
- B006110290 Forwards revised response to IE Bulletin 79-21, "Temp Effects on Level Measurements" Emergency procedures being revised to alert operators of possible erroneous level indication during post-accident conditions BRIOHT,R M Florida Power Corp B0/06/06 2pp
- 8006240566 Ack receipt of 800423 ltr re feedwater sys welds FW-1308, MK-124 to 125 & MK-132 to 133 Agrees w/proposal to monitor welds through normal inservice insp program provided welds are scheduled for insp during early insp period MURPHY.C E Region 2. Atlanta Reactor Constiuction & Engineering Support Branch 80706/09 ip
- --8004240573 Responds to NRC concerns re Insp followup Item 79-25-01
 Results of supplemental insp of 16 welds disclosed no
 evidence of svc-related indication Proposes insps of welds
 FM-1308 MK-124 to 125 % MK-132 to 133 during inservice insp
 HANCOCK, J A Florida Pawer Corp 80/04/23 2pp
- 8006170436 Advises extension until 800711 is needed to complete response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Centrol Sys Holdup Tanks " BRIGHT.R M Florida Power Corp 80/06/11 App
- BOO61704B4 Responds to items of noncompliance in IE Insp Rept 50-302/ BO-19 Corrective actions minutes of 11 nuclear general review committee meetings held during 1978 microfilmed & document control program altered HANCOCK, J. A. Florida Power Corp. 80/06/11 3pp
- 8006200387 Responds to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " No "flued head" designs or designs illustrated in ABME Boilor & Pressure Vessel 1974 Code, Winter 1975 addenda.Figure NE 1120-1 are used BAYMARD,P Y Florida Power Corp 80/06/12 1p
- 8006300580 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Surveillance Procedure SP-417 has been modified to Jemanstrate that all equipment remains in emergency mode upon removal of actuating signal BAYNARD,P Y Florida Power Corp 80/06/12 13pp
- 8006230485 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys Holdup Tanks" All sys reviewed to identify tanks which can receive primary water & to verify potential buckling problems BAYNARD, P Y Florida Power Corp 80/06/17 6pp
- 8006300376 Forwards response to 1E Bulletin 80-10, "Contamination of Ronradicactive 8ys % Resulting Potential for Unmonitored, Uncontrolled Release of Radicactivity to Environ " Secondary sys leakage during review caused some sys radicactivity BRICHT.R M Florida Power Corp 80/06/25 App
- R Periodic operating reports & related correspondence
- 8006170617 Forwards monthly operating rept for May 1980 BAYNARD, P Y Florida Power Corp. 80/06/10 1p
- --8006190621 Monthly operating rept for May 1980 CULVER,M W Florida Power Corp 80/06/02 3pp
- S Reportable occurrences. LERs & related correspondence
- 8006170878 Forwards draft for use in responding to request for info re Feb 1980 accident INORAMIF Office of Public Affairs 80/04/16 Spp.
- 8006040343 PNO-II-80-084 on 800515.potential leaks found on 24 control rod driveline motor tube to reactor vessal head flange connections Gaskets replaced Repair actions being evaluated Util will issue press release State of FL notified STETKA,T F., QUICK,D. Region 2, Atlanta, Office of the Director 80/05/16 1p
- BOO6040396 PND-II-80-088 on BOO518.contaminated yellow trash bag affired w/radioactive sticker was found in waste lumber load Survey revealed ten similar bags in dump Bags removed & dump burning performed Investigation underway GIBSON.0. JFNKINS.0 Region 2. Atlanta, Office of the Director BO/05/19 1p

- 8006050406 PND-II-80-089 on 800516, during exam of installed fuel halddown springs w/television camera, one cracked spring on fuel assembly identified Assemblies w/cracked fuel assembly halddown springs will be replaced ORAMAM, M. J. GUICK, D.R. Region 2, Atlanta, Office of the Director 80/05/19 1p
- 8004040346 PND-II-80-086A on 800520, stripped threads & galled threads were identified on nut rings Exam will determine galling extent Corrective actions will extend outage Util issued press release ORAHAM, M J. OUICK, D R. Region 2, Atlanta, Office of the Director 80/05/20 | 1p
- 8004030303 Forwards LER 80-019/01T-0 HANCOCK, J A Florida Power Corp 80/05/29 1P
- --8006030304 LER 80-019/01T-0 on 800517, crack indication discovered during insp of fuel assembly NJ018E upper end fitting holddown spring Investigation of cause underway When determined, rept w/corrective actions will be sent LANCASTER, K F Florida Power Corp 80/05/23 2pp
- 8006030499 Forwards LER 80-021/03L-0 HANCOCK, J A Florida Power Corp 80/05/29 1p
- --8006030500 LER 80-021/03L-0 on 800506, during insp of feedwater swingdisc check valve FHV-45, valve hinge pin was discovered missing Caused by deficiency during initial assembly of valve by manufacturer Valve is being repaired LANCASTER, K F Florida Power Corp 80/05/23 2pp
- 8006030505 Forwards LER 80-020/03L-0 HANCOCK, J A Florida Power Corp 80/05/29 ip
- ---8006030508 LER 80-020/03L-0 on 800501, during review of surveillance procedures, discovered that procedure for weekly battery check SP-510 was not performed for wk of 800406 Caused by damaged hydrometer used to perform surveillance LANCASTER, K. F. Florida Power Corp. 80/05/23 2pp
- 8004110123 Forwards deficiency rept re extensive cracking in valve disc guide on six valves HANCOCX.J A Florida Power Corp 80/05/30 ip
- --8006110134 Deficiency rept re extensive cracking in valve disc guide on six valves mfg by Dresser Industries Corrective action is being determined by manufacturer & will be accomplished prior to restart

 * Florida Power Corp. 80/05/30 1p
- 8006180099 Comments on AU rept to Congress for first quarter CY80 Suggests change of wording re saltwater cooling sys pumps MICHELSON, C Director's Office 80/06/04 1p
- B00620063B Part 21 rept revising 800530 rept re cracking of disc guides of six main steam safety valves mfg by Dresser Industries Correct valve type is 3707R Corrective action is being determined HANCOCK, J A Florida Power Corp 80/06/05 3pp
- 8006110128 Forwards LER 80~022/04L~0 HANCCICK, J.A. Florida Power Corp. 80/06/06 ip
- --8006110140 LER 80-022/04L-0 on 900528, samples not obtained for Apr from test wells 1 & 4 & pH results not reported for waste water ponds, test well 3 & discharge canal Caused by elimination of test well sites due to canal mod & loss of pH data LANCASTER, X F Florida Power Corp 80/05/30 2pp.
- 8006190596 Forwards LER 80-023/031-0 HANCGCK, J A Florida Power Corp 80/06/12 1p
- --8006190603 LER 80-023/03L-0 on 800517, radioactive matl in form of bagged contaminated waste 8 poly urapped scrap lumber was taken to site dump Caused by apparent communication problem between health physics personnel k bldg servicemen LANCASTER, K F Florida Power Corp 80/06/06 2pp
- 8006240419 Forwards LER 80-024/04L-0 HANCOCK, J A Florida Power Corp 80/06/19 1p.
- --8006240426 LER 80-024/04L-0 on 800523, discovered that I-131 charcoal cartridge for whe ending 800401 was inadvertently discarded Caused by personnel error Responsible pursonnel were instructed on proper procedures
 LANCASTER, K. F. Florida Power Corp. 80/06/19 2pp.

- 8006240446 Forwards LER 79-074/01T-1 HANCOCK, J.A. Florida Power Corp. 80/06/20 1p
- --8006240450 LER 79-074/01T-1 on 790817 & 22. reported that unplanned release of radioactive liquid was discharged to settling pond.contrary to ETS Caused by procedural deficiency Liquid was inadvertently released by sump pump automatic actuation LANCASTER.K F Florida Power Corp 80/06/18 2pp
- 8006300398 Forwards supplemental LER 79-086/03L-1 HANCOCK, J. A. Florida Power Corp. 80/06/24 1p
- --8006300401 Supplemental LER 79-086/03L-1 on 790916, channel D reactor bldg high pressure bistable tripped Caused by corrosion buildup on reactor bldg pressure switch Switch was cleaned & returned to svc LaNCASTER, K F Florida Power Corp 80/06/17 2pp
- DDCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8006:20528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/05/13 2pp
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 30 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D 0 Division of Licensing 80/05/19 46pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101," transmitted by NRC BO0519 ltr Page 14a not encl EISENHUT, D G Division of Licensing BO/05/R2 73pg
- BOO6120009 Advises that NRC review of BOO324 safeguards contingency plan indicates need for addl revisions Beecific comments withheld (ref iOCFR2 790) VARQA-B A Operating Reactors Branch 1 BO/05/27 2pp
- 8006090274 Forwards add1 fire protection info as suppl to util 800430 ltr re safe shutdown analysis which takes plant to hot shutdown Add1 info provides for taking plant to cold shutdown PEOPLES.D L Commonwealth Edison Co
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES.D L. Commonwealth Edison Co. 80/06/04 2pp
- --8006180340 Draft emergency plan annex * Commonwealth Edison Co 80/07/31 37pp
- ---8006180347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co 80/07/31 139sp
- BOO6240470 Responds to NRC 800425,30,0501,07 & 20 ltrs requesting addlentore guard training & qualification plans Requests that response submittal date be extended to BOO804 PEOPLEB, D L Commonwealth Edison Co BOO704/18 ip.
- O Adjudicatory correspondence
- 8004060236 Forwards util affidevits of TR Tramm & RE Shennon describing planned minor changes in spent fuel rack replacement jab procedures Changes relate to intervenor argument on appeal Related correspondence STEPTOE, P Isham, Lincoln & Beale 80/05/05 2pp
- --8006060242 Affidavit recommending that penetrant test exams per encl Procedure NDT-D.or squivalent, be substituted for ultrasonic test exam technique in spent fuel pit corrosion surveillance program BHANNGN.R E Commonwealth Edison Co 80/04/23 7pp
- --8006060243 "Liquid Penetrant Exam "
 * Commonwealth Edison Co 78/12/06, 15pp,
- --8006060246 Affidavit describing decontamination techniques that will be employed in spent fuel replacement jobs to reduce total vol of radwaste mati
 TRAMM.T R Commonwealth Edison Co 80/05/05 2pp.

- 8006170218 Brief in support of ASLB 800214 initial decision authorizing installation of new racks, for which intervenor filed 15 exceptions intervenor offered no reason to support alleged error in decision
 STEPTOE.P P. MILLER.M I Commonwealth Edison Co STEPTOE.P P. 196am. Lincoln & Beale 80/05/05 44pp
- 8006060357 Discusses C Guigg ltr to ARC requesting stay in proceeding re proposed amend to increase spent fuel storage capacity Guigg assertions inaccurate ASLS found that adequate design & safety features preclude loss-of-water accident STEPTOE,P P Isham. Lincoln & Seale 80/05/12 2pp
- 8004020314 Order for 800701 oral argument in NRC Public Hearing Room. Bethasda:MD One hour of argument & rebuttal will be granted to each party BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/05/23
- BOD6190310 Responds to 800805 objection to scheduling meetings outside Mashington.DC area Meetings are occasionally held outside of Mashington.DC vacanity to allow persons living near plants opportunity to attend EISENHUT.D C Division of Licensing 80/06/02. 2pp
- 8005260141 Ack receipt of 800417 petition requesting NRC to suspend license amend permitting reracking b compaction of facility fuel pool Petitioner has evidence from Salem Unit 2 proceeding for review FR notice encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/13 1p
- --8006260146 FR notice of request for action under 10CFR2 206 re Pollution & Environ Problems. Inc petition to suspend license amend for reracking & compaction of fuel pool Petitioner has add1 evidence for review DENTON.H R Office of Nuclear Reactor Regulation, Director 80706/I3 10

H General correspondence

- 8006020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas HAMM.K Affiliation Unknown 80/03/19 in
- P. Operating license stage documents & correspondence
- 8006020240 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J 9 Region 3, Chicago, Office of the Director. 80/04/18 2no.
- 8006090084 Comments on petition for rulemaking 51-6 Zion Unit 2 is poor place to experiment extractor fuel due to population density within 30-mile radius of emission stack DOHERTY.J F Affiliation Unknown 80/09/07 2pp
- BDDA090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days. EISENHUT.D G Division of Licensing 80/05/07 150pp
- BO06040002 Notification of B00520 meeting w/utils, contractors & consultants in Bethesda, MD to exchange technology reaccident sequence & related phenomena per A Schwencer B00410 itr to L Peoples
 LONGJ K Reactor Systems Branch B0/05/18 2pp
- 8006130122 Requests comments on NUREG-0877, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl , EISENHUT, D & Division of Licensing 80/05/19, 72pp.
- BOO5190171 Forwards request for add1 items required to complete upgrade review of GA program Rosponse should be provided along w/response to 80040B request. VARGA:S A Operating Reactors Branch 1 80/05/20 App
- 8006020097 Notification of 800605 meeting w/util in Bethesda, MD to discuss upgraded OA program 8PRAUL, J. Quality Assurance Branch 80/05/21 2pp
- 8006020172 Notification of 800830 meeting w/utils in Bethesda, MD re savere accident mitigation features for facilities QLSHAN, L. Operating Reactors Branch 1 80/05/23 lp

- 8006090493 Notification of 800603 meeting w/util in Bethesda.MD to discuss filtered vented containment sys & core retention devices
 MEYER.J F Reactor Systems Branch 80/05/27 3pp
- 8006160057 Forwards revised Tech Spec Pages 94,328a,79.% 80 issued w/ Amends 54 % 51 to Licenses DPR-37 & DPR-48, respectively VARGA:S A Operating Reactors Branch 1 80/05/29 2pp
- --8006160060 Corrected Pages 94,328a.79 \$ 80 to Amends 51 & 54 to Licenses DPR-48 & DPR-39,respectively * Operating Reactors Bianch 1 80/04/28 4pp
- 8006020347 Update to 800422 application to amend Licenses DPR-39 & DPR-48 incorporating administrative changes to App A.Tech Specs NAV9HTON.W F Commonwealth Edison Co 80/05/30 2pp
- --8006020349 Revised Page 300 to App A. Tech Specs 6 0 for administrative controls Allows either rad-chem supervisor or lead health physicist to fulfill qualifications of radiation protection
 - manager * Commonwealth Edison Co 80/05/30 2pp
- 8006090256 Application for amend to Licenses DPR-39 & DPR-48, modifying allowed outage time per 800227 confirmatory order Combined Class I & III fee encl NAUGHTON.N F Commonwealth Edison Co 80/06/03 3pp
- BOOA090305 Forwards response to NRC BOOS0A request for history of total & partial power outages & attendant degraded voltage No complete loss of offsite power has occurred, but one partial loss incident was reported to NRC NAUGHTON, W F Commonwealth Edison Co BO/OA/OS 2pp
- 8006120404 Forwards slides used by utils during 800603 meeting retechnology eichangs in area of mitigation feature for severa accidents at facilities
 GDESER, D. Westinghouse Electric Corp. 80/06/05 ip
- 8006170451 Forwards "Mitigation of Severe Accident Study Rept " Rept includes presentations made to NRC & ACRS on 800220 & 0305, respectively & consists of state-of-the-art analyses conducted within 60-day period CAHILL.W J Consolidated Edison Co of New York 80/06/05 2pp
- ---B006170459 Responds to B0092B ltr transmitting rept covering work performed by various consultants Entire Hestinghouse rept monproprietary PEOPLES, D.L. Commonwealth Edison Co. 80/06/09 Spp
- --B006170466 "Mitigation of Sovere Accident Study Rept," consisting of repts re evaluation of residual risk, steam explosions, containment response for Class 9 accidents 5 post-accident containment vent sys conceptual designs

 * Westinghouse Electric Corp 80/03/31 400pp
- 8006130165 Forwards check inadvertently left off package submitted on 800603 U/o encl PIENTA:R Commonwealth Edison Co 80/06/06 ip
- B006160071 Forwards response to NRC Questions 28 48 re facility QA program per B00408 & 0520 requests
 PEOPLES.D L Commonwealth Edison Co 80/06/09 12pp
- 8006190307 Forwards commitments to comply w/requirements & schedules in NRC 800507 ltr re add1 TMI-2 related requirements Dresden Unit 1 is currently undergoing extensive mod & decontamination, therefore no response is provided PEOPLES, D L Commonwoalth Edison Co 80/06/12 10pp
- 8006270047 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda,MD re accident mitigation features for facilities LONG,J K. Reactor Systems Branch. 80/06/12 27pp
- 8006250280 Notification of 800618 meeting w/utils, contractors & consultants in Bethesda. MD for presentation in area of core-melt accident sequences for facilities Agenda encl MEYER, J F Reactor Systems Branch 80/06/16 2pp
- 8006200553 Notification of 800617 meeting w/utils & consultants in Bethesda: MD to discuss technology exchange re containment structural response failure pressures & failure modes MEYER. J F Reactor Systems Branch 80/06/17 2pp

- BOD6300207 Requests re-evaluation of original proposal for submitting schedule for implementing ATMS instrumentation mods identified in NUREO-0460 Revised schedule & justification should be submitted in 30 days VARGALS A Operating Reactors Branch 1 BO/06/19 2pp
- 8006270306 Forwards revised Revisions II & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed 0A Program for Nuclear Generating Stations" Revised Revision II includes basis on which equivalent education requirements will be established PEOPLES.D L. Commonwealth Edison Co. 80/06/23 ip
- BOO6270329 Forwards response to NRC 800502 questions on adequacy of station electric distribution sys voltages Lowest bus voltage when starting largest non-Class IE load was calculated when all other loads were running Motor started NAUGHTON.W F Commonwealth Edison Co 80/06/23 7pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006170727 Forwards IE Insp Repts 50-295/80-03 & 90-304/80-02 on 800207-0328 & notice of violation HE18HMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/26 2pp
- --8004170730 Notice of violation from insp on 800207-0328 * Region 3, Chicago, Office of the Director 80/04/18 1
- ---8006170738 IE Insp Repts 50-295/80-03 \$ 50-304/80-02 on 800207-0328
 Noncompliance noted min shutdown margin requirements while
 in cold shutdown were below Tech Spec limits
 KCMLER.JC, LITTLE.W S Region 3, Chicago, Office of the
 Director 80/04/18 App
- 8006170271 Forwards IE Insp Repts 50-275/80-06 & 50-304/80-05 on 800310-11 & 0417-18 No noncompliance noted HEISHMANIR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/04/30 2pp
- ---8006170295 IE Insp Repts 50-295/80-06 & 50-304/80-05 on 800310-11 & 0417-18 No noncompliance noted Major areas inspected small break LOCA procedure KOHLER. J. NELSON.R. Region 3. Chicago. Office of the Director LITTLE. W S. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/04/25 App
- BOO6170378 Forwards IE Insp Repts 50-295/80-04 & 50-304/80-03 on BOO318 No noncompliance noted DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch BO/05/07 2pp
- --8006190379 IE Insp Repts 90-295/80-04 & 80-304/80-03 on 800318 No noncompliance noted Major areas inspected confirmatory measurements from previous collection effluent samples & submission of spiked samples E8810.T H . JANUSKA, A G Region 3, Chicago, Office of the Director 80/05/06 App
- 8006230070 Forwards IE Insp Repts 50-295/80-07 & 50-304/80-06 on BOO414-30 No noncompliance noted HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/13 2pp
- --8006230077 IE Insp Repts 50-295/80-07 & 50-304/80-06 on 800414-30 No noncompliance noted Major areas inspected licensee actions to comply with 800829 confirmatory order LITTLE,WS, KOHLER,JC, Region 3, Chicago, Office of the Director 80/05/12 9pp
- 8006130076 Add1 response to FOIA request for aix categories of documents re CPC Forwards documents listed in app FELTON.J M Division of Rules and Records 80/05/23 3pp.
- --B004i30077 Forwards response to updated memo received on B003i3 re util interrogatories re proposed imposition of civil penalty Cover sheet of IE insp rept encl KEPPLER.J & Region 3. Chicago. Office of the Director B0/03/21.
- --8006i30i02 Discusses three safety-related events occurring at facility
 Civil penalty for noncompliance items will be imposed
 Forwards notice of violation notice of proposed imposition
 of civil penalties & history of enforcement action
 VDLGENAU.E Office of Inspection & Enforcement, Office of the
 Director 77/09/30 2pp
- ----8006130104 Notice of violation from insp on 770705-08,14.15 & 21 * Office of Inspection & Enforcement, Office of the Director, 77/09/30 3pp

- --800613010B Notice of proposed imposition of civil penalties in amount of \$21,000 re noncompliance discovered during insp on 770705-08,14,15 & 21 History of escalated enforcement action encl

 4 Office of Inspection & Enforcement, Office of the Director 77/09/30 200
- 8006170326 Immediate action ltr re [E physical security insp on 800512-15 & 17-20 Licensee is expected to undertake actions outlined in enci Encl withheld (ref 100FR2 770)
 KEPPLER.J G Region G. Chicago. Office of the Director 80/05/23
- 8006250297 Advises that responses to IE Bulletin 79-06A.Revision i, were found acceptable Evaluation encl VARGA.S A Operating Reactors Branch 1 80/05/28 17pp
- B00630055B Forwards response to IE Bulletin B0-06, "Engineered Bafety Feature (ESF) Reset Controls " Proposed mods identified only if present sys design may compromise protective action of equipment PEOPLES.D L Commonwealth Edison Co 80/06/10 9pp
- S Reportable occurrences, LERs & related correspondence
- 8006050377 PND-III-80-094 on 800515, licensee reported that cracks had been found in A & C sections of low pressure turbing Section A will be replaced w/new spindle KDHLER.J F., LITTLE.W S. Region 3, Chicago, Office of the Diractor 80/05/14 1p
- 8006040333 PND-III-80-074A on 800516 crack was discovered in keyway of Disc i at generator end of C section low pressure turbine spindle Spindle will be replaced & B section will be examined wk of 800519
 KOHLER.J E . LITLE.W S Region 3. Chicago. Office of the Director 80/05/19 ip
- BD06110111 Forwards LER 80-019/03L-0
 WANDKE, N E Commonwealth Edison Co 80/05/27 1p
- --80061%0115 LER 80-019/03L-0 on 800429 during safeguards actuation test. 2A containment spray pump stop valve 2MOV-CB0002 failed to open Caused by maifunction of torque switch New torque switch installed GAJIC, Z Commonwealth Edison Co 80/05/27 1p
- BOO6110120 Forwards LER 80-020/03L-0
 WANDKE, N E Commonwealth Edison Co 80/06/03 is
- --8006110125 LER 80-020/03L-0 on 800507, maint personnel found steam generator 2A pressure channel 2P-516 low by 2 6%, exceeding channel accuracy Gaused by instrument drift of transmitter. Transmitter recalibr JENKINS.R V Commonwealth Edison Co 80/06/03 ip
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

 F Bectrity, modical, emergency & fire protection plans
- BOO6020257 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Bys intended for use during emergencies to link all power plants & NRC. Emergency Notification Bys hotlins will also be used KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18 Zpp
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50 48 & App R to 102FR50 & is expected to be published in FR by end of May EISENMUT,D Q Division of Licensing. 80/05/19. 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EIGENHUT,D 0 Division of Licensing. 80/05/22, 73pp
- P. Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07. 130pp

- 8006060588 Ack receipt of 800414 ltr Confirms util intent to proceed w/related reload for Cycle 6 & that "Reload Safety Evaluation, Kewanee Cycle 6, Mar 1980," has been filed VARGA.S A Operating Reactors Branch 1 80/05/09 ip
- 8006130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Cenerator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT,D Q Division of Licensing 80/05/19 72pp
- 8006120014 Summary of B00428 meeting w/util re planned addition of restraints to primary coolant sys to limit & support LOCA loads Restraints have been designed to carry max loads of 3000 ktps horizontally for cold leg LICCIARDO.R Operating Reactors Branch i 80/05/23 4pp
- 8006240638 Confirms distribution of info re FSAR & SER to assist in technical evaluation of electrical instrumentation & control design aspects of override containment purgo valve isolation & other engineered safety feature signals

 LICCIARDO,R B Operating Reactors Branch 1 80/06/05 1p
- 8006170426 Informs NRC of proposed mod to limit containment purge & vent valve opening to 65 degrees Util is proceeding u/mod w/understanding that NRC concurs unless informed to contrary by 800612 MATHEMS.E R Wisconsin Public Service Corp. 80/06/11 2pp
- 8006240493 Responds to concerns re satisfactory operation of containment purge 3 vent valves under LOCA conditions Blacking devices installed to limit opening of valves Discusses basis for mod MATHEMSLE R Wisconsin Public Service Cora 80/06/19 20p
- G Inspection reports, IE Bulletins & correspondence
- B006200088 Forwards IE Insp Rept 50-305/80-08 on B00421-24 No noncompliance noted HEISHMAN:R F Region 3. Chicago: Reactor Operations Nuclear Support Branch 80/05/12 2pp
- --8006200097 IE Insp Rept 50-305/80-08 on 800421-24 No noncompliance noted Major areas inspected plant operations IE bullatins & circular followsp. fire protection/prevention program & nonroutine events

 WARNICK.R F . HAGUE.R L . NELSON.R L Region 3, Chicago, Office of the Director 80/05/09 4pp
- 8006260066 Forwards IE Insp Rept 50-305/80-06 on 800324-28 & notice of deviation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/20 2pp
- ---8006260069 Notice of deviation from insp on 800324-28
 * Region 3. Chicago, Office of the Director 80/05/19 ip
- --8006260077 IE Insp Rept 50-305/80-06 on 800324-28 Noncompliance noted failure to implement approved Westinghouse guidelines HMITH.J. NELSON.R. HARNICK.R F Region 3. Chicago. Office of the Director 90/05/19 5pp
- 8006240279 Responds to IE Bulletin 80-06 Review of schematic & logic diagrams for all applicable components serving safety-related functions verifies that components will remain in emergency mode, following emergency safety feature reset MATHEWS, E. R. Wisconsin Public Service Corp 80/06/17 2pp
- 8006250185 Responds to IE Bulletin 80-12 re decay heat removal sys operability Une loss of decay heat removal incident occurred in Bept 1974 Operating procedures have been reviewed for safeguarding against loss of RRR capability MATHEWS,E R Wisconsin Public Service Corp 80/06/20 4pp
- R Periodic operating reports & related correspondence
- BOO6160075 Forwards monthly operating rept for May 1980 MATHENBLE R Wisconsin Public Service Corp BO/06/09. 19
- ~~BOOA160097 Monthly operating rept for May 1980
 RULTER, O H Wisconsin Public Service Corp 80/06/02 4pp
- 8 Reportable occurrences. LERs & related correspondence
- 8006200465 Forwards LERs 80-022/03L-0 & 80-023/03L-0 MATHEWS, E R Wisconsin Public Service Corp 80/06/16 1p

- --8006260469 LER 80-022/03L-0 on 800519 during refueling outage, pressuriter pressure transmitter found out of calibr Caused by instrument drift Transmitter recalibr NALEPHAD 5 Wisconsin Public Service Corp 80/06/18 ip
- POCKET 50-304 PRAIRIE ISLAND NUCLEAR STATION. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8006020231 Notifies that new telephone sys called Health Physics
 Network (HPN) has been installed at site Sys intended for
 use during emergencies to link all power plants & NRC
 Emergency Notification Gys hotline will also be used
 KEPPLER, J G Region 3, Chicago, Office of the Director 60/04/18
- BOOA090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101" Rule adds new Section 50 48 & App R to 10CFR30 & is expected to be published in FR by end of May EISENHUT.D Q Division of Licensing 80/05/19 44pp
- 8006i30063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 100FR90 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101." transmitted by NRC 800517 ltr Page 14a not encl E18ENHUT.D Q Di
- 8006020258 Forwards revised Page 1 omitted from 800510 Revision 1 to security force training & qualification plan Encl withheld (ref 100FR2 770) MAYER.L D Northern States Power Co 80/05/27 1p
- 8006176078 Notifies of proposed lE contractor review of emergency operating procedures on 800609-13 Data will be used to provide composite picture of emergency procedures & will not result in items of noncompliance HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/03 2pp
- 8006230337 Discusses submittal of final upgraded emergency plans Extension may be necessary, depending on content of pending NRC rules on emergency plans Schedule for emergency plan revisions tangeted to meet 800801 submittal date MAYER, L. O. Northern States Power Co. 80/06/17 1p
- 9 Adjudicatory correspondence
- 8006230266 Advises that State of MN 800424 contentions are being sent for docketing NRC will be prepared to discuss hearing schedule & state contentions during Jul 1979 prehearing conference in St Paul. MN BARTH.C A Hearing Branch 3 80/06/19 ip
- B006300419 Notice & order for B00806 prehearing conference in US Courthouse, St Paul, MN re State of MN 800424 petiton to intervene in GL amend proceeding Licensee & NRC shall file responses to intervention petition by 800715 LAZO,R M Atomic Bafety and Licensing Board Panel 80/06/25 2pp
- P Operating license stage documents & correspondence
- 8006180101 Decommissioning study of Prairie Island Nuclear Generating Plant.Revision 1 JAMORSKY,M J Nuclear Energy Service, Inc. 81A0623 R1 79/09/28 67pp
- BOO&090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days. EISENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT,D Q Division of Licensing 80/08/19 72pp
- 8006250044 Forwards safety evaluation re degraded grid voltage protection for Class IE ac power sys & LLL rept supporting mods Design mods 2 tech 8pec changes acceptable RDBA.F Power Systems Branch 80/03/22 ip

- --8006250048 Safety evaluation supporting proposed mods & Tech Spec changes re-protection of Class IE equipment & sys from sustained degraded voltage + Power Systems Branch 80/05/22 2pp
- --8006250052 "Technical Evaluation of Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Prarie Island Nuclear Generating Plants Units 1 & 2 " WHITE,R L Lawrence Livermore Laboratory FIN A-0231 UCID-18654 80/03/31 15pp
- B006090400 Forwards info re implementation of 10CFR50. App J. containment penetration testing requirements.per B00411 request MAYER.L Q Northern States Power Co 80/05/30 App
- 8006:70486 Forwards add1 info in support of 800131 license amend request in response to NRC questions Analyses cover makeup water sysistructural chemistry/radiochemistry, radiological, matis/processes & rack disposal MAYER, L O Northern States Power Co 80/06/10 20pp
- 8006230142 Responds to 800602 memo by submitting list of documentation & applicable comments on facilities purge & vent valves long-term mechanical operability Facilities meet interim position
 MARTIN.R Operating Reactors Branch 3 80/06/10 2pp
- 8006240059 Forwards listed drawings to enable continuation of review of generic issue. "Primary Coolant Sys Pressure Isolation Valves (Event 5) " W/o encls MARTIN.R E Operating Reactors Branch 3 80/06/10 3pp
- 8006170377 Forwards response to NRC 800507 ltr on add1 TMI-2 requirements re shift manning, licensing exams, operating experience feedback, Bulletins & Orders Yask Force recommendations & control room habitability 80/06/11 14pp Northern States Power Co
- G Inspection reports, IE Bulletins & correspondence
- 8006170316 Forwards IE Insp Repts 50-282/80-05 & 50-306/80-06 on NOS170316 Forwards IE Insp Repts 30-282/80-05 & 30-306/80-06 UII 800301-31 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/04/24 2pp
- --8006170321 IE Insp Repts 50-282/80-05 & 50-306/80-06 on 800301-31 No noncompliance noted Major areas inspected plant operation, maint followup of LERs. & review of licensee small break LOCA procedures FEIERABEND.C D , SWANSON.E R Region 3, Chicago, Dffice of the Director BDYD.D C Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/18 7pp
- 8006030203 Responds to IE Bulletin 79-17. Revision 1. Item 6 Visual insp satisfactorily completed on Unit 1 in Apr 1980 No corrective actions necessary GLEBERTS, D.E. Northern States Power Co. 80/05/06 ip
- 800&110436 Forwards nonproprietary version of IE Insp Repts 50-282/80-07 t 50-306/80-07 on 800428-0502 Notice of violation withheld (ref 10CFR2 790) HIND, J A Region J. Chicago, Safeguards Branch NRC 80/05/22
- -8006110444 Nonproprietary version of IE Insp Repts 50-282/80-07 & 50-306/80-07 on 800428-0502 Noncompliance noted some vital area physical barriers not maintained & alarm devices not tamper-indicating Details withheld (ref 10CFR2 790) HIND.J A Region 3. Chicago: Gafeguands Branch CREED.J R , PIRTLE.G L Region 3. Chicago: Office of the Director 80/05/2 80/05/21
- 8006130076 Addl response to FOIA request for six categories of documents re CPC forwards documents listed in app FELTON, J M Division of Rules and Records 80/05/23 3pp
- --B006130079 Forwards response to updated memo received on B00313 re util interrogatories re proposed imposition of civil penalty. Cover sheet of IE insp rept encl, XEPPLER.J G Region 3, Chicago, Office of the Director B0/03/21
- ---8006130120 Excerpt of IE Insp Repts 50-282/75-01 & 50-304/75-01 conducted on 750204-06 & 12-15 Noncompliance noted design change packages were not prepared &/or implemented in accordance w/licensee administrative control directives CHOULES.N C . HUNTER.D R Region 3, Chicago, Office of the Director JORAN.E J Region 3, Chicago, Reactor Operations Nuclear Support Branch 75/03/25 Spp

- 8006230253 Revises response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Forwards sys compan-evaluation worksheet on Kerite Cable Revision 2 replacing worksheet sent in 800512 response Northern States Power Co 80/05/23 3pp
- 8006240558 Responds to IE Bulletin 80-i2, "Decay Heat Removal Sys Operability " Operating procedure for reactor refueling (cavity flooded) will require one train of RHR available w/ accessible source of borated water to replemish any loss OILBERTS,D E Northern States Power Co 80/06/06 2pp
- R Periodic operating reports & related correspondence
- 8006180448 Forwards monthly operating repts for May 1780 & corrected page to Apr 1780 monthly operating repts
 MAYER.L Q Northern States Power Co 80/06/13 ip
- --8006180451 Monthly operating repts for May 1980 HUNSTAD, A A Northern States Power Co 80/06/01 8pp
- --B006180453 Monthly operating repts Apr 1780.corrected pages HUNSTAD.A A Northern States Power Co 80/06/13 ip
- S Reportable occurrences, LERs & related correspondence
- 8006040360 PNO-III-80-097 on 800519, facility was shut down due to leakage on reactor coolant seal 2 w/o radioactive release State informed No press releases planned BAKER, K R, HEISHMAN, R F Region 3, Chicago, Office of the Director BO/05/19 ip
- 8006030479 Environ Event Rept 80-01 on 800501, daily average discharge temp exceeded ambient river water temp by 5.7 F while two caoling towers were undergoing inspicieaning & repair One tower returned to svc & electrical load reduced WARD, E.C. Northern States Power Co. 80/08/30 ip
- 8004090289 Environ Event Rept 80-02 on 800513-14, reclaiming ion exchanger out of syc when steam generator blowdown water discharged into river Samplo of outfall revealed pH value greater than 8 5 Caused by seasonal change of river WARD.E C Northern States Power Co 80/06/04 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities SEAY, J L Chemtron Corp , Tube Turns Div 80/06/06 3pp
- DOCKET 90-309 MAINE YANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101 " Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end of May EISENHUT.D & Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 100FR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800517 ltr Page 14s not encl EISENHUT, D 0 Division of Licensing 80/05/22 73pp
- BODA030355 Recommends that FEMA receive notice of decisions made at forthcoming seminar re use of potassium todide for radiation emergencies Ideas will be incorporated into state contingency plan COTE, L.A. Maine, State of BD/05/23
- 8006170897 Advises that 791019 changes to approved security plan are consistent w/100FR90 54 provisions Plan withheld (ref 100FR2 790). CLARK,R A Operating Reactors Branch 3 80/05/29 2pp
- 8006230386 Informs that next revision to facility emergency plan will be submitted by 800801 GROCE.R H Maine Yankee Atomic Power Co 80/06/18. 1p

Q Adjudicatory correspondence

- 800&0&0447 Motion for extension until 800&11 to respond to Sensible ME Power 800428 specific contentions received on 800502 Licensee counsel presently involved in various cases Intervenor has no objection to motion M/Certificate of Svc DIGNAN,T Q, GAD,R K Maine Yankee Atomic Power Co
- 800Ai30251 Response to intervenor Sensible ME Power Contentions 1(a) through (d).(f) through (1) 5 (k),4(a).5.6.7.8.10.11 & 13 should be admitted Notice of appearance of EJ Reis on behalf of NAC & Cortificate of Syc enc]
 REIS.E J Hearing Branch 3 80/06/11 20pp
- BOO6180274 Response to Sensible ME Power specific contentions Objects to certain contentions on grounds that spent fuel pool expansion case is not forum for relitigating issues already resolved when OL issued W/Certificate of Svc DIGNAN.T G . QAD.R K Maine Yankee Atomic Power Co DIGNAN.T Q Ropes & Gray BO/O6/11 lipp
- BOOGIBO326 Motion to postpone first prehearing conference until 801001 Licensee is presently involved in considering alternate proposals & implementing NRC suggestion re TMI incident Certificato of Svc encl DIONAN,T G , GAO,R K Haine Yankee Atomic Power Co DIONAN,T G Ropes & Gray BO/OG/11 3pp

H General correspondence

- 8006130229 Responds to 800507 itr re changing situation for nuclear power plant emergency preparedness NRC is working closely w/FRM4 to develop coordinated federal guidelines Criteria for Interia use outlined in NUREG-0654/FEMA-REP-1 DIRCKB.W J Office of the Executive Director for Operations 80/Q5/27 2pp
- --8005130233 Urges that all federal guidelines re drafting peacetime nuclear contingency plans for fixed nuclear facilities be completed & promulgated quickly Final design requirements should ensure that all states can accomplish objectives BRENNAN, J E Maine, State of 80/05/07 ip
- 8006270351 Forwards util 800211 & 0523 responses re evacuation time astimates.in response to 791221 request QRIMES.B K Emergency Preparedness Program Office 80/06/09 ip

J Insurance & indomnity information

- BOO6120275 Advises of investigation into P Ripton claim re radiation contamination when air hose separated from face mask during employment w/fac11ity 780701-0813

 HARWARD J E American Nuclean Insurers B0/02/14 ip
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manufug.licensing exams & licensee dissemination of operating experiences Rosponse requested within 30 days EISENHUT, D Q Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREQ-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Colant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D @ Division of Licensing 80/05/19 72pp.
- 8006090271 Describes proposed hydrogen monitoring sys to be implemented, in response to NRC 791030 ltr re TMI short-term Lessons Learned requirements Evaluation of acceptability of proposed sys requested GROCE, R H Maine Yankee Atomic Power Co 80/06/04 2pp
- 8006090280 Responds to NRC 800508 itr re complete or partial loss of offsite power events Util 800304 itr responded to identical set of questions contained in NRC 791127 itr re offsite power loss & is resubmitted QRGCE,R H. Maine Yankee Atomic Power Co. 80/06/04 ip
- BOOA:3010A Notification of 800610 meeting w/util in Bethesda,MD to dicuss affects of fuel assembly buildup on reactor parameters & chemical treatments for removing crud NELBON.C C Operating Reactors Branch 3 80/06/04 App

- B006300418 Forwards "Fnd-of-Cycle 4 Fuel & CEA Eddy Current Insp Rept 1980 ME Yankee Refueling Qutage." & "ME Yankee End-of-Cycle 4 Summary of Fuel Insp Results." per NRC B00307 request Repts withheld (ref 10CFR2 790) VANDENBURGH. D Maine Yankee Atomic Power Co B0/06/04 9pp
- 8006170241 Forwards implementation schedule & summary stating commitments in response to NRC 800307 ltr re add1 requirements from TMI Action Pian MDODY. DE Maine Yankee Atomic Power Co 80/06/07 5pp
- 8006200424 Forwards "End of Cycle 4 Fuel & C&A Eddy Current Insp Rept 1980 Refueling Outage," & "End of Cycle 4 Summary of Fuel Insp Results," nonproprietary versions GROCE.R H Maine Yankee Atomic Power Co 80/06/11 1p
- --8006200426 "End of Cycle 4 Fuel & CEA Eddy Current Insp Rept 1980 Refueling Outage." nonproprietary version * Combustion Engineering. Inc GEN-129(M)-NP 80/03/24 12pp
- ---8004200428 "End of Cycle 4 Summary of Fuel Insp Results."
 nonproprietary version
 * Combustion Engineering, Inc. CEN-131(M)-NP 80/03/31 37pp
- 8006300398 Forwards proposed Tech Specs Change 66. Suppl 2 consisting of addl changes to App A of License DPR-36 re administrative controls Suppl delineates offsite & plant organizational structures & titles associated wyoostions
 THURLOW, E H Maine Yankee Atomic Power Co 80/06/20 3pp
- --B006300360 Proposed Tech Specs for administrative controls Changes more clearly delineate offiste & plant organizational structures & titles associated w/each position * Maine Yankee Atomic Power Co 80/06/20 28pp
- G Inspection reports, IE Bulletins & correspondence
- 800&030i06 Forwards IE Insp Rept 50-309/80-05 on B003i7-21 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch B0/04/22 2pp
- --8006030109 IE Insp Rept 50-309/80-05 on 800317-21 No moncompliance noted Major areas inspected licensee emergency procedures responding to small break LOCA, followup on LERs & review of monthly operating repts

 MARTIN, T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch LAZARUS, W Region 1, Philadelphia, Office of the Director 80/04/17 7pp
- 8006060027 Ack receipt of 800423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-04
 BRUNNER, E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/07 2pp
- --B006060030 Responds to NRC B00328 ltr re violations noted in IE Insp Rept 50-309/80-04 Corrective actions revised procedure to require evaluation of purchases equipment or svcs for future utilization requirements MODDy,D E Maine Yankee Atomic Power Co B0/04/23 1p
- --8006060032 Forwards IE Insp Rept 50-309/80-04 on 800218-22,27 & 0304-07 & notice of violation BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/28 2pp
- --8004060034 Notice of violation from insp on 800218-22,27 & 0304-07,
 * Region i, Philadelphia, Office of the Director 80/03/27 ip
- --8006060035 IE Insp Rept 50-309/80-04 on 800218-22,27 & 0304-07
 Noncompliance noted responsibilities & procedures not
 detailed & cleanup of RCS w/o procedure
 MARTIN.T T Region 1. Philadelphia, Reactor Operations Nuclear
 Support Branch LAZARUS.W J. SWETLAND.P D Region 1.
 Philadelphia, Office of the Director 80/03/27 7pp
- 8006090482 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Determination made that no safety-related sys or component uses AH-90 or NH-90 series hydramotor actuator mfg by ITT General Controls
 ORDCE,R H Maine Yankee Atomic Power Co 80/05/14 ip
- 8006090450 Responds to IE Sulletin 79~01B re evaluation of environ qualifications of Class IE alectrical equipment Due to extensive in-house reviews required, unable to complete responses on time Completion by 800530 OROCE, R H Yankee Atomic Electric Co 80/05/19 ip

- 8006170735 Ack receipt of 800307 ltr informing NRC of implementation of IE Bulletin 79-19 related training program SMITH,O H Region 1, Philadelphia, Fuel Facility & Materials SaPety Branch B0/09/21 ip
- ---8006170739 Responds to NRC 800213 ltm re questions on implementation re training requirements in LE Bulletin 79-19 & LE Insp Rept 50-309779-19 Corrective actions training program is underway & will be fully implemented by Jul 1980 MODDY.D E Maine Yankee Atomic Power Co 80/03/07 3pp
- --8006170744 Forwards IE Insp Rept 50-309/79-19 on 791129 & 30 No nancompliance noted GRIER, B H Region 1. Philadelphia, Office of the Director BO/02/13 2pp
- --8006170750 IE Insp Rept 50-309/79-19 on 791129 & 30 No noncompliance noted Major areas inspected licensee response to JE Bulletin 79-19 including review of DOT & NRC onsite regulations, procedures & personnel training PLUMILEE.K E Region 1. Philadelphia. Office of the Director CROCKER, H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/04 11pp
- BOO6130076 Addl response to FDIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J M Division of Rules and Records 80/05/23 3pp
- --8006130097 Notice of violation from insp on 780925-29 \$\fo1010-11 \tag{78712728} 2p
- 8006030178 Forwards inservice insp exam rept for 800112-0307 GROCE, R H Maine Yankee Atomic Power Co 80/05/28 ip
- ---8006030182 Inservice inspectam rept for 800112-0309 Describes exams
 performed during 1980 refueling outage

 < Maine Yankee Atomic Power Co 80/05/28 28pp
- 8004200043 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies 'No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8006230373 Ack receipt of 800423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-02 SMITH, G H Region 1, Philadelphia. Fuel Facility & Materials Safety Branch 80/05/28 ip
- --B006230377 Responds to NRC 800407 ltr re violations noted in IE Insp Rept 50-309/80-02 Corrective actions modified Procedure O-02-1: matl.equipment & svc purchase, requiring evaluation to datermine whether add procedures needed MODDY,D E Maine Yanise Atomic Power Co 80/04/23 1p
- --8006230382 Ack receipt of 800307 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/80-02 SMITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/07 lp
- --8006230440 Responds to NRC 800221 itr re violations noted in IE Insp Rept 50-309/80-02 Corrective actions incorporated procedure for operation of low level radwaste compactor into Health Physics Procedure 9 : 17 MODDY.D E Maine Yankee Atomic Power Co 80/03/07 2pp
- --8006230446 Forwards IE Insp Rept 50-309/80-02 on 800121-25 & notice of violation SMITH.K H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/02/21 2pp
- --8006230451 Notice of violation from insp on 800121-25 * Region I. Philadelphia, Office of the Director 80/02/14, ip
- --8006230452 IE Insp 80-309/80-02 on 800121-25 Noncompliance noted failure to establish, review & Implement procedure for bailing machine KNAPP.P J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch THONUS.L H Region 1, Philadelphia, Office of the Director 80/02/14 Spp
- 8006050283 Informs that util is in process of addressing IE Bulletin 79-03A Response has required diversion of engineering resources from identified safety issues HEIDER.L H Yenkes Atomic Electric Co 80/05/29 2pp

- 8006040469 Discusses IE Bulletin 79-03A, "Longitudinal Held Defects in ABME SA-312. Type 304 Stainless Steel Pipe" Bulletin describes minor design deficiencies, rather than generic problems
 HEIDER, L. H. Yankee Atomic Electric Co. 80/05/29 Zpp
- 800Aii0003 Forwards response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Periodic revisions will be forwarded VANDERBURGH, D E Maine Yankee Atomic Power Co 80/06/02 2pp
- --8006110008 "Environ Qualification of Safety-Related Electrical Equipment at Maine Yankee Atomic Power Co " URBANCUSKI.S F. TSQUDEROS.G. BAXTER.F D Maine Yankee Atomic Power Co YAEC-1217 80/06/02 150pp
- 8006160110 Responds to TE Bulletin 80-12 Procedure for plant cooldown contains provisions for blocking safety injection actuation systable automatically blocks containment spray, containment isolation 8 ECCS recirculation VANDENBURGH.D. Maine Yanker Atomic Power Co. 80/06/09 2pg
- R Periodic operating reports & related correspondence
- 8006020221 Forwards "Biological Monitoring Rept.1979 " GARRITY, J.H. Maine Yankee Atomic Power Co. 80/05/27 ip
- --8006020227 "Biological Monitoring Rept 1979 "

 * Naine Yankes Atomic Power Co 80/04/30 400pp
- BOGA030368 Forwards discharge monitoring rept for Apr 1980 GARRITY, J H Maine Yankee Atomic Power Co 80/03/28 2pp
- --800A0303A9 Discharge monitoring rept for Apr 1980
 FLANDERS.W Maine Yankee Atomic Power Co 80/05/19 5pp
- 8006170689 Forwards monthly operating rept for May 1980 MODDY, D E Maine Yankee Atomic Power Co 80/06/12 1p
- ---8006170696 Monthly operating rept for May 1980 BEERS, F C Maine Yantee Atomic Power Co 80/06/12 App
- S Reportable occurrences. LERs & related correspondence
- 8006090333 Forwards LER 80-012/03L-0 WDDD,E C Maine Yankee Atomic Power Co 80/06/03 1p
- --8006090357 LER 80-012/03L-0 on 800306, during monthly surveillance test procedure, low power safety injection loop 3 header stop valve failed to operate as required Caused by broken weld in coupling of operating extension shaft BRINKLER, J. E. Maine Yankee Atomic Power Co. 80/06/03 1p
- BOO6110189 Forwards LER 80-013/03L-0 WDDD, E C Maine Yankee Atomic Power Co BO/06/04 ip
- --8006110200 LER 80-013/03L-0 on 800807.during routine power operation.
 auxiliary operator noticed S-charging pump was not lined up
 w/required degree of separation Gaused by personnel error
 Surveillance test procedure revised
 BRINKLER.J E Maine Yankee Atomic Power Co 80/05/04 lp
- 8006110334 R0 80-014/01T-0 proliminary results from vessel wall irradiated surveillance capsule indicates higher shift than originally predicted Followup rept will be forwarded when all data is received & evaluation made HODDLE C Hains Yenkse Atomic Power Co 80/06/04 ip
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr. Add1 specific criteria for facilities under development EISENHUT.D Q Division of Operating Reactors 80/04/25 61pp
- BOO612052B Requests that FEMA review of state & local emergency plan be provided consistent w/enrl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission. BO/05/13 2pp

- 8006190649 Informs NRC of decision to delay activation of Guinton training facility as nearsite emergency operations facility until open issues have been addressed satisfactorily SCHMCIDER.F.W. Public Service Electric & Gas Co. of New Jersey
- G Adjudicatory correspondence
- 8006020323 Order granting extension until 800602 for Commission to elect whether to review Director's decision DD-80-17 taken under 100FR2 206 CHILK.S J Office of the Secretary of the Commission 80/05/23
- 8006230176 Forwards revised pages to Director's Decision DD 80-19
 Decision issued 800429 denied petition requesting certain
 actions re storage of spent fuel at site Corrections
 overlooked
 DENTON.H R Office of Nuclear Reactor Regulation, Director
 80/05/23 1p
- --8006230180 Advises that version of DD-80-19 signed is not version concurred on Forwards cover ltm.errata sheet listing changes & two revisions of Director's Decision Corrections should be issued by 800512

 MURRAY, J P Office of the Executive Legal Director 80/05/07 600
- 8005180602 Notifies that Ofc of Nuclear Reactor Regulation Director's denial under 100FR2 206 of request re spent fuel storage is final CHILK.S J Office of the Secretary of the Commission 80/05/29 ip
- 8006200559 Responds to 800523 request for advance notice of activities re-facility which involve NRC or State of MD Public 8vc Commission NRC is not involved in proceeding Notification request should be directed to MD Public 8vc Commission SHAPAR, MK Office of the Executive Legal Director 80/06/06 ip
- --8006200567 Requests advance notice of meetings, conferences, depositions, hearings or appearances re facility involving NRC or State of MD Public Svc Commission Also requests all relevant tastimony & correspondence receives by NRC HETTERHAHN, M J Conner, Moore & Corber 80/05/23 2pp
- H General correspondence
- 8006120089 Responds to ltr to DDE re constituent inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Pacilities use water from DE River Basin DIRCKS.N J Office of the Executive Director for Operations 80408470 App.
- 8006120242 Advises that NRC 800523 extension of time to consider Ofc of Nuclear Reactor Regulation denial of request for stay of OL issuance has elapsed Denial is final action CHILK 8 J Office of the Secretary of the Commission 80/06/10 in.
- J Insurance & indemnity information
- 8006110097 Forwards Endorsements 31.4 & 1 to MAELU Policies MF-90, XB-60 & XB-72-respectively CORREA, M A Mersh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 60/06/04 App
- 8006180507 Forwards executed Amend 8 to Indemnity Agreement 8-74, deleting Item 3 & substituting license numbers GRIFFITHS. R Public Service Electric & Gas Co of New Jerssy 80/06/12 2pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D & Division of Licensing 80/09/07 150pp
- BOOSIG0122 Requests comments on NUREO-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PAR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D O Division of Licensing 80/05/19, 72pp.

- 8006030360 Hithdraws 800514 request for amend to License DPR-75 re relief from Tech Spec shift manning requirements Requests return of fee SCHNEIDER, FW Public Service Electric & Gas Co of New Jersey 80/05/27 10
- 8006090366 Requests that audit of installed electric sys & equipment be performed per 791129 ltr Review sample may be limited to 5% of installed equipment & cables SCHWENCER.A Licensing Branch 2 80/05/29 2pp
- BO04090507 Natification of B00405 meeting w/util in Bethesda.MD to discuss licensed proposed engineered safety feature design for automatic switchover from injection mode to recirculation mode KERRIGAN, J Licensing Branch 2 80/05/30 2pp
- BO06120203 Forwards request for Class III amend to License DPR-75 consisting of Tech Spec changes re special test exception, position indication sys.shutdown section LIBRIZILF P Public Service Electric & Gas Co of New Jersey 80/06/06 lp
- --8004120210 Requests Class III amend to License DPR-75, allowing suspension of Tech Spec 3 1 3 2 2 (position indication sys-shutdown) during performance of rod drop time measurements 5 calibr when operable during rod withdrawal ECKERT.R M Public Service Electric & Gas Co of New Jersey 80/06/06 2pp
- ---8006120214 Revised Tech Specs for License DPR-75 ra position indication sys shutdown

 * Public Service Electric & Gas Co of New Jersey 80/06/06
- 8006170450 Commits to implement NUREC-0660 re add1 TMI-2 related requirements per 800507 ltr
 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/06/07 ip
- 8006250069 Notification of 800610 meeting w/util in Bethesda, MD to discuss licensee request for Toch Spec change on control rod position indication KERRIGAN, J. Licensing Branch 3 80/06/09 2pp
- BOO6300057 Notifies licensue that insp ports must be installed in steam generators & Row 1 tubes must be plugged prior to startup after first refueling No info presented that potential cracking near top of Row 1 U-bend can be avoided SCHWENGER.A Licensing Branch 2 80/06/09 2pp
- 8006240308 Forwards Amend 1 to License DPR-75, safety evaluation & notice of issuance t availability
 SCHWENCER, A Licensing Branch 2 80/06/11 2pp
- ---8006240310 Amend i to License DPR-75, suspending limitations of Tech Spec 3 1 3 2 2 during performance of individual full-length rod testing & rod position indication sys calibr. SCHMENCER.A Licensing Branch 2 80/06/11 5pp
- --8006240444 Safety evaluation supporting Amend 1 to License DPR-75
 * Office of Nuclear Reactor Regulation, Director 80/06/11 299
- ---8006240448 Notice of issuance & availability of Amend 1 to License DPR-73 SCHWENCER:A Licensing Branch 2 80/06/11 2pp
- 8006250098 Notification of 800618 meeting w/util in Bethesda.MD to discuss auxiliary feedwater sys MERRIOANU Licensing Branch 3 80/06/12 2pp
- 800625030B Notification of 800617 meeting w/utils in Bethesda.MD to discuss issuance of full power license for facilities DROMERICK.A W Licensing Branch 1 KERRIGAN.J D Licensing Branch 3 STANLE.C R Licensing Branch 2 80/06/16 4pp
- G Inspection reports, IE Bulletins & correspondence
- 8006030086 Forwards IE Insp Rept 50-311/80-06 on 800327-28 No noncompliance noted GARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/04/16 2pp

- --8006030090 IE Insp Rept 50-311/80-06 on 800327-28 No noncompliance noted Major areas inspected ultrasonic exam of reactor pressure vessel norrles, including observations & discussions w/licensee TRIPP.L E Region 1. Philadelphia, Reactor Construction & Engineering Support Branch MCSREARTY.R A Region 1. Philadelphia, Office of the Director 80/04/16 3pp
- B006180053 Forwards IE Insp Repts 50-272/80-07 \$ 50-311/80-03 on B00302-29 No noncompliance noted BRUNNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch B0/04/29 2pp
- --B006180056 IE Insp Repts 50-272/80-07 & 50-311/80-03 on 800302-29 No noncompliance noted Major areas inspected plant operations, logs & records, LERs, periodic repts, small break LOCA guidelines % previous insp items

 KEIMIG.R R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch NORRHOLM.L J Region 1, Philadelphia, Office of the Director 80/04/23 18pp
- 8006180121 Forwards IE Insp Repts 50~272/80-07 & 50-311/80-03 on B00302-29 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 60/04/29 2pp
- --8006:80:26 IE Insp Repts 50-272/80-07 & 50-31:/80-03 on 800302-29 No noncompliance noted Major areas inspected plant operations including facility tours, log & record reviews, licensee events review & review of periodic repts NORRHOLM, J. Region I. Philadelphia. Office of the Director KEIMIG.R R. Region i. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/23 18pp
- 8006200029 Forwards IE Circular 80-13, "Grid Strap Damage in Mostinghouse Fuel Assemblies " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/05/28 ip
- 800Ai1023i Responds to violations noted in IE Insp Repts 50-272/80-04 & 50-311/80-01 on 800128-31.0201.04-07 & 11-13 Corrective actions master equipment list will expand existing methods of compliance w/requirements of GA program sys & components SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey 80/06/03 Spp
- BOO6300282 Responds to 1E Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks "Facilities have had vacuum breaters installed on holdup tanks to prevent collapse in event vacuum is generated SCHNEIDER.F W Public Service Electric & Gas Co of New Jersey 80/06/06 ip
- 8006300490 Responds to IE Dulletin 80-12, "Decay Heat Removal Sys Operability " Sequence of events at Davis-Bease which resulted in automatic transfer of suction to empty containment sump will not occur at facilities SCHNEIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/09 4pp
- S Reportable occurrences, LERs & related correspondence
- 9006240443 Forwards LER 90-001/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 90/06/18 2pp
- ---8006240447 LER 80-001/03L-0 on 800522, when DL received, fire barriers were open due to recent removal of electrical cables, pipes & welding cables Cause not stated Barriers were verified sealed prior to core load MURPHY.M J Public Service Electric & Gas Co of New Jersey 80/06/18 | 1p
- B006300479 Forwards LER 80-002/03L-0 LIBRIZZI:F P Public Service Electric & Gas Co of New Jersey B0/06/25 3pp
- --B006300487 LER 80-002/03L-0 on 80052á, during routine surveillance, emergency diesel 2B could not be fully loaded Caused by three pins stuck in fuel injectors Pins were unstuck k diesel tested satisfactorily Insp arder has been initiated MURPHY, M J Public Service Electric & Oas Co of New Jersey 80/06/25

U Congressional/Executive Correspondence

- B006120074 Responds to 800409 ltr requesting info re new safety stds w/which facility must comply prior to OL issuance Facility response to post-TMI improved safety recommendations reviewed License to load fuel & test issued 800418 DIRCKS-W J Office of the Executive Director for Operations 80/05/22 2pp
- --8005120079 Requests info re new "strict safety stds" w/which facility must comply prior to OL issuance ROTH:N V Senate, Governmental Affairs 80/04/09 ip
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- BOOSO90487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Bection 50 48 & App R to 10CFRSO & is expected to be published in FR by end of May EISENHUT.D & Division of Licensing 90/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101," transmitted by NRC 800517 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp
- G Adjudicatory correspondence
- 8006060272 Discusses matl needed to respond to CA Energy Commission Interrogatory & Forwards complete list of B&W feedwater transients up to 791026 Requests that project managers complete summaries of transients by 791127 CAPRA:R A TMI-2 Bulletins & Orders 79/11/23 2pp
- 8006160049 Motion by CA Energy Commission for extension until 800801 to file proposed findings of fact & conclusions of law Suggests 800711 for licensee findings.800822 for NRC findings & 800705 for licensee reply W/proof of 8vc ELLISUN.C California. State of, 80/06/04 3pp
- 800626015B Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental snyiron statements on Class 9 accidents at Diablo Canyon, Rancho Seco & Palo Verde DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8006260157 Responds to /91024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at facilities No special circumstances exist which would warrant reopening proceedings Request denied DENTON.4 R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8006260163 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents DENYON-H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- I Financial information
- 8006030320 Annual Financial Rept 1979 * Sacramento Municipal Utility District 79/12/31 21pp
- 8006130337 Forwards Annual Financial Rept 1979
 MATTIMOE, J J Sacramento Municipal Utility District 80/06/09 1p
- P Operating license stage documents & correspondence
- BODADACEBS Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for B&W operating plants W/o encis CAPRAIR A Light Water Reactors Branch 3 BO/O1/17 Spp

- B0062006B Forwards 800314 memo re 780320 transient at facility known as "light bulb incident" Transient could have led to results as serious as TM1 Requests comments on memo w/amphasis on safety problems in Items 1-3
 EISENHUT.D Q Division of Operating Reactors 80/04/03 App
- ---BOO6200074 Advises of alternate sequence of events for 780320 incident at facility that could have resulted in outcome as serious as TMI Priority should be given to study of sequences in which successful core cooling may be in question BERNERO, R M. ROHSOME, P H. Probabilistic Analysis Staff BO/03/14 50s
- 800&0901&5 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Pian include shift manning licensing trans & licensee dissemination of operating experiences Response requested within 30 days RIBENHUT, D O Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREQ-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Bupports " Proposed review procedure & implementation schedule enc! EISENKUT.D G Division of Licensing 80/05/19 72pp
- 8006030342 Notifies of 800807 leak test of seal injection & makeup sys. letdown sys & HPIS while performing SP 207 04 at hot shutdown prior to returning to power No leakage found MATTIMOE, J J Sacramento Municipal Utility District 80/05/22 ip
- B006110069 Responds to 800501 ltr re facility compliance w/Category An NUREO-0578 items Bys will draw liquid samples from RCB cold leg & from containment sump via decay heat sys Analysis described in 800411 ltr MATTIMOE. J J Sacramento Municipal Utility District 80/05/30 300
- 8006110131 Forwards Revision 1 to "ASME Code Class Valve Testing Requirements" Pp 4-5 & 4-6 re program changes resulting from 790718 operational review for implementation of intervice testing program Requests add1 relief due to changes MATTIMOE. J J Sacramento Municipal Utility District 80/05/30 50e
- 8006240488 Forwards position on selected NURES-0660 action items as required by NRC 800507 ltr
 MATTIMOE, J. J. Sacramento Municipal Utility District 80/06/18
- θ Inspection reports. IE Bulletins & correspondence
- 8006060600 Ack receipt of 791212 memo forwarding revision to SMUD rept, "Analysis Summary in Support of Early Reactor Coolant Pump Trip "Informal copy of rept was incorporated into evaluation of 1E Bulletin 79-05C (NUREG-0623) CAPRA,R A TMI-2 Bulletins & Orders 79/12/13 ip
- --B006060603 Forwards 791024 revision to "Analysis Summary in Support of Early Reactor Coolant Pump Trip " Matl should be used to svaluate responses to IE Bulletin 79-05C UDRDAN.E L Division of Reactor Operations Inspections 79/12/12
- 8006090475 Forwards IE Insp Rept \$0-312/80-14 on 800325-27 No noncompliance noted SPENCER, 0.5 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --8006090503 IE Insp Rept 50-312/80-14 on 800325-27 No noncompliance moted. Major areas inspected activities performed in response to IE Hulletins 79-02 £ 79-13 & exam of weld cracking problem during valve installation DODDS:R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch NARBUIT.P P Region 5. San Francisco, Office of the Director 80/04/23 5pp
- BOC6180632 Responds to Item 6 of IE Bulletin 79-13.Revision 2,
 "Cracking in Feedwater Sys Piping " Visual insp of all main
 & auxiliary feedwater sys piping supports & snubbers
 gerformed during refueling outage to veriey operability
 MATTIMDE.J J Sacramento Municipal Utility District 80/04/28 ip
- B006230174 Forwards IE Imap Rept 50-312/80-12 on 800407-08 \$ 10 No noncompliance noted SPENCER, G B Region 5. San Francisco. Reactor Construction & Engineering Support Branch 60/05/12 2pp

- ~~8006250179 IE Insp Rept 50-312/80-12 on 800407-08 % 10 No noncompliance noted Major areas inspected environ qualification of Class
 IE equipment per IE Bulletin 79-018
 DODDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch ELIN.J Q Region 5, San Francisco, Office of the Director 80/05/09 4pp
- 8006250116 Forwards lE Insp Rept 50-312/80-09 on 800407-11 No ngncompliance noted CREWS, J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/19 2pp
- --8006250124 IE Insp Rept 50-312/80-09 on 800407-11 No noncompliance noted Major areas inspected fire protection mods, onsite organization & administration, receipt, storage & handling of equipment & followup on IE bulletins & circulars FAULKENBERRY. B Region 5, San Francisco, Reactor Operations Nuclear Support Branch ZWETZIG, G B Region 5, San Francisco, Office of the Director 80/05/19 9pp
- 8006250181 Forwards IE Insp Rept 50-312/80-16 on 800401-30 No noncompliance noted CREMS, J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/20 2pp
- --8006250184 IE Insp Rept 50-312/80-16 on 800401-30 No noncompliance noted Major areas inspected long-term shutdown activities & loss of hom-nuclear instrumentation power FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch CANTER, H. L. Q'BRIEN, J. P. Region 5, San Francisco, Qffice of the Director 80/05/20 7pp
- B006070512 Ack receipt of 800423 ltm responding to items of noncompliance in B00401 notice of violation & payment of civil penalties in amount of \$25,000 in response to 800401 notice of prapased imposition STELLO.V Office of Inspection > Enforcement, Office of the Director 80/05/27 lp
- 8006200053 Forwards IE Circular BO-13. "Grid Strop Damage in Westinghouse Fuel Assemblies " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/05/28 ip
- 8006130339 Forwards 800505 ltr to Region 5 re util responses to IE Bulletin 79-018, "Environ Qualification of IE Electrical Equipment" MATTIMOE.J.J. Sacramento Municipal Utility District 80/06/04 lp
- ~-8006130341 Forwards response to IE Bulletin 79~018, "Environ Qualification of IE Electrical Equipment " Responses, including equipment required to function under postulated accident conditions, available in Central Files only MATTIMOE, J J Sacramento Municipal Utility District 80/05/05
- 8006250051 Ack receipt of 800602 lir informing NRC of steps taken to correct violation noted in IE Insp Rept 50-312/80~10 CRENS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/12 ip
- --8006250054 Responds to NRC B00422 ltr re violation noted in IE Insp Rept 50-312/80-10 Corrective actions held training session w/crane operators & reviewed & updated maint procedures WALBRIDGE.W C Sacramento Municipal Utility District 80/06/02 20p
- --8006250057 Forwards IE Insp Rept 50-312/80-10 on 800303-31 & nutice of violation CREWS.J L Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/04/22 2pp
- --8006250060 Notice of violation from insp on 800303-31 # Region 5, Ban Francisco, Office of the Director 80/04/21 ip
- --B006250066 1E Insp Ropt 50-312/80-10 on 800303-31 Noncompliance noted movement of objects over fuel transfor canal w/o approved procedures
 FAULKENBERRY, B Region 5, San Francisco, Reactor Operations
 Nuclear Support Branch CANTEP, H L Region 5, San Francisco,
 Office of the Director 80/04/21 7pp
- R Periodic operating reports y related correspondence
- 8006190636 Forwards monthly operating rept for May 1980 RODRIQUES,R J Sacramento Municipal Utility District 80/06/05

- ---8006190641 Monthly operating rept for May 1980 COLCMBO.R C Sacramento Municipal Utility District 80/06/05
- S. Reportable occurrences, LERs A related correspondence
- B006030361 Forwards LER B0-025/03L-0
 MATTIMDE, J J Sacramento Municipal Utility District 80/05/20
- --8006030387 LER 80-025/03L-0 on G00502, review of applicabilty of IE Info Notice 80-13 revealed 27 GE type SBM switches in safety-related switcheer Fight cracked in cam followers Caused by exposure to hydrocarbons in mfg process COLUMBO, R W. Sacramento Municipal Utility District 60/05/20 in
- 8006160010 RD review of safety feature actuation sys indicates that when inverter A or B are removed from svc single failure of other inverter during accident will prevent sys operation Inverters will be treated as safety features equipment MCCOLLIGAN, J V Sacramento Municipal Utility District 80/06/09 1p
- B006250237 Forwards followup LER 79-021/03L-1 WALBRIDGE,W C Sacramento Municipal Utility District B0/06/16 3pp
- --8006250238 Followup LER 79-021/03L-1 on 791216, error in ref heat balance resulted in error for effective full power days calculation Caused by possible erosion wear on flow nozzle Nozzles will be replaced during next refueling outage COLOMBO, R W Sacramento Municipal Utility District 80/06/16 ip
- 8006300394 Forwards LER 80~02B/01T-0 MATTIMOE, J J Sacramento Municipal Utility District 80/06/19 Ip
- --B006300405 LER 80-028/017-0 on B00609, review of safety features actuation sys revealed that if one inverter was out of svc. failure of remaining inverter would disable sys Operational restrictions placed on inverter operability CULOMBO,R W Sacramento Municipal Utility District B0/06/19
- 8006300528 Forwards LER 80-029/04T-0 MATTIMOE, J J Sacramento Municipal Utility District 80/06/19 ip
- --8006300533 LER 80-027/04T-0 on 800519. May 1980 effluent monitoring charts indictaed effluent pH exceeded 8 5 Tech Spec limit Caused by pH fluctuations in dilution water.common phenomenon in summer months COLOMBO, R W Sacramenta Municipal Utility District 80/06/19 10
- T Hearing transcripts on non-antitrust matters
- 8006030188 Forwards NRC proposed transcript corrections per ASLB order re-post-hearing schedule in proceeding Certificate of Svc encl BLACK,R L Hearing Branch 1 80/05/30 3pp
- --8004030191 Proposed corrections to 800228,0303-06,0408-11,0414-15,0417 0506-10 & 0512-14 transcripts 4 Hearing Branch 1 80/05/30 29pp
- 8006f10336 Forwards stipulated mods to parties, proposed transcript corrections & stipulated addl proposed transcript corrections Parties suggest that ASLAB issue order adopting 800530 corrections as amended Certificate of Svc encl BAXTER, T.A. Shaw, Pittman, Potts & Trowbridge 80/06/09 App
- --8006110341 Stipulated mads to licensee,NRC & CA Energy Commission proposed transcript corrections
 * Shaw, Pittman, Potts & Troubridge 80/06/07 5pp.
- ---8006110350 Stipulated add1 proposed transcript corrections.

 * Shaw, Pittman, Potts & Trowbridge 80/06/07 1p
- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1
 F Security, medical, emergency 3 fire protection plans
- 8006090027 Forwards request for addl info re socurity personnel training & qualification plan Encl withheld (ref 10CFR2 790) REID.R W Operating Reactors Branch 4 80/05/19 2pp

- 8006070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101 " Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D O Division of Licensing 80/05/19 44pp
- B006i30063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC B00517 ltr Page 14a not encl EISENHUT.D G Division of Licensing 80/05/22 73pp
- 8006110242 Forwards revisions to proposed util safeguards contingency plan per RW Reid 900411 request Plan withheld (ref 10CFR2 790) TRIMBLE.D C Arkansas Power & Light Co 80/05/30 ip
- 8006180510 Ack receipt of NRC 800519 ltr requesting info on security personnel training b qualification plan Requests copy of dnaft NUREO-0674 dealing w/subject.prior to response to ltr TRIMBLE.D C Artansas Power b Light Co 80/06/13 ip

H General correspondence

- 8004270171 Responds to 800430 request to comment on R Lacewell concerns re spent fuel storage pool expansion Util indicated that no plans for expansion anticipated until 1982 or 1983 NRC approval & public consideration would pracede expansion DIRCKS-N J Office of the Executive Director for Operations 90/06/09 2pp
- P Operating license stage documents & correspondence
- 8006060278 Forwards util 791031 ltr re auxiliary emergency feedwater control sys Sys being developed by B&W appears to be fully responsive to NUREG-0578 concerns re separation from IGS & auto-start capability CAPRA,R A TMI-2 Bullotins & Orders 79/12/10 ip
- 8006060283 Forwards documents for Auxiliary Bys Branch review of auxiliary feedwater reliability analysis for B&W operating plants N/o encls CAPRA,R A Light Water Reactors Branch 3 80/01/17 3pp
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensee requirements for TMI Action Plan include shift manning, licensing exams 8 licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness & Lameller Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedulo encl EISENHUT,D G Division of Licensing 80/05/19 72pp
- 8004090032 Requests meeting w/util on 800604 in Bethesda MD to discuss interim reliability evaluation program Program is associated w/reliability engineering & rish assessment task included in NUREG-0660. "TMI Action Pian"

 EISENHUT.D G. Division of Licensing 80/05/23 5pp
- 8006130112 Summary of B00322 meeting w/util re 800510 reactor coolant pump seal leak event VISBING.G Operating Reactors Branch 4 80/06/02 6pp
- 8006240165 Notification of 800612 meeting w/utils in Bethesda.MD to discuss interim reliability evaluation program, QLSHAN.L N Operating Reactors Branch 1 80/06/09 2pp.
- 8006170700 Forwards response to NRC 800505 ltr re loss of offsite power events
 TRIMBLE,D C Arkansas Power & Light Co 80/06/11 3pp
- 8006180528 Responds to NRC 800505 ltr re loss of offsite power events Details of 750222,1205 & 800407 events indicate weather conditions were responsible on all occasions Only momentary losses of power were experienced TRIMBLE, D C Arkansas Power & Light Co 80/06/11 3pp
- 8006250288 Forwards Amend 45 to License DPR-51, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/06/12 2pp.
- --8006290290 Amend 45 to License DPR-51, modifying Tec Specs re surveillance requirements for hydraulic snubbers REID.R W Operating Reactors Branch 4 80/06/12 5pp

- ---8006250291 Safety evaluation supporting Amend 45 to License DPR-51 * Operating Reactors Branch 4 80/06/12 2pp
- -8006250296 Notice of issuance k availbility of Amend 45 to License REID.R W Operating Reactors Branch 4 80/06/12 2pp
- 8006300006 Discusses licensee plans to increase onsite waste storage Requests reviews of onsite storage additions in monthly operating rept following period in which evaluation was completed NRC onsite storage licensing position encl REID/R W Operating Reactors Branch 4 80/06/12 10pp
- 8006250380 Forwards safety evaluation supporting util justification of continued operation of facility w/reactor vessel is unveillance program conducted at Davis-Besse Unit i Related Tech Specs should be proposed REID:R W Operating Reactors Branch 4 80/06/16 2pp
- ---80022S03B2 Bafety evaluation supporting util justification of continued facility operation w/reactor vessel surveillance program conducted at Davis-Besse Unit i Related Tech Specs should be
 - Operating Reactors Branch 4 80/06/16 2pp
- B006230401 Submits response to B00507 request for commitment to TMI-2 related requirements Response to Items II K 3 25.27 & 44 will be delayed because util did not receive errata sheets until 800616 Arkansas Power & Light Co 80/06/18 3pp
- 8006300045 Discusses fees for review of APL-TDP-TA: " OA Manual-Operations " Requests payment upon receipt of invoice. MILLER:W Q License Fee Management Branch 80/06/23 1p
- @ Inspection reports. IE Bulletins & correspondence
- 8006060132 Notifies NRC that limited response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." will be submitted by 800426 Response will be limited to ac power supply to NNI buses TRIMBLE.D C Artansas Power & Light Co 80704/01 ip
- B006040051 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Review identified need to increase reliability of ac power supplied to non-nuclear instrumentation sys TRIMBLE,D C Arkansas Power & Light Co B0/04/23 5pp
- B006240036 Forwards IE insp Repts 50-313/80-06 & 50-369/80-06 on B00322-0421 & notice of violation MADSEN,O L Region 4. Dallas, Reactor Operations Nuclear Support Branch B0/03/03 2pp
- --8006240042 Notice of violation from insp on 800322-0421 # Region 4. Dallas, Reactor Operations Nuclear Support Branch 80705702 3pp
- ---B006240046 IE Insp Repts 30-313/80-06 & 50-368/80-06 on 800322-0421
 Noncompliance noted no control of combustibles & finding
 that waste control operator entered high radiation areas w/o
 using radiation survey instrument
 WESTERMAN.T F Region 4. Dallas, Reactor Operations Nuclear
 Support Branch 80/05/02 16pp
- 8006060597 Forwards IE Bulletin 80-11. "Masonry Wall Design " Requires action & written response IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" encl
 SEYFRIT.K V Region 4. Dallas. Office of the Director 80/05/08
- 8004050317 Forwards IE Bulletin 80-12, "Dreay Heat Removal Sys Operability " Requires actions % response within 30 days IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Dayis-Besse Unit i While in Refueling Mode" encl SEYFRIT.X V Region 4. Dallas, Office of the Director 80/05/09
- 8004050331 Responds to violations noted in IE lnsp Repts 50-313/80-06 & 50-368/80-06 Corrective actions doors to high radiation areas locked or repaired & locked Combustibles removed from prohibited areas & maint personnel notified TRIMBLE.D C Arkansas Power & Light Co 80/05/29 4pp
- 8006240184 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-05 % 50-348/80-05 MADERN, G.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/06/06 ip

- -8006240186 Responds to NRC ltr re violations noted in IE Insp Repts 50-313/80-05 & 50-368/80-05 Corrective actions revised Procedure 1304 23 & 2304 15 requiring specific sign-off for each leak rate test following containment entries TRIMBLE.D C Arkansas Power & Light Co 80/05/09 3pp
- 8006200489 Responds to IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Analyses of procedures for safeguarding against loss of sys capability should be completed by CAVANAUGH, W Arkansas Power & Light Co 80/06/12 3pp
- BOO6300319 Forwards evaluation of BOO411.16,0504 & 21 responses to IE Bulletins 79-05A & B Request; that util conform to provisions or provide sufficient justification for proposed deviations from guidance NGVAK.T M Reactor Systems Branch 80/06/13 22pp
- R Periodic operating reports & related correspondence
- BOOG110142 Forwards "Annual Environ Monitoring Rept"
 TRIMBLE,D C Artansas Power & Light Co BO/05/12 ip
- --8006110154 "Annual Environ Monitoring Rept " Oversize drawing encl * Arkansas Power & Light Co 80/05/12 400pp
- 8006110001 Forwards results of intake impingement monitoring during during month of Apr 1980
 TRIMBLE.D C Arkansas Power # Light Co 80/05/29 1p
- B006190686 Forwards monthly operating rept for May 1980 TRIMBLE,D C Artansas Power & Light Co 80/06/13
- S Reportable occurrences. LERs 3 related correspondence
- 8004050396 PND-IV-80-021C on 800515.following purge of reactor bldg, fans were left on to continue ventilation EPA officials indicated that no radiation levels were detected offsite Util samples indicated that 4 out of 8 had traces of Xe-133 HESTERMAN, T F. MADSEN, O L. Region 4. Dallas. Office of the Director 80/05/16 ip
- 8006230434 Forwards updated LER 79-017/03X-1 TRIMBLE.D C Artansas Power / Light Co 80/05/22 1p
- -8005230439 Updated LER 79-017/03Y-1 on 790911, during monthly test, diesel generator i tripped on low oil pressure after approx 3 minutes of operation Caused by inadequate corrosion inhibitor resulting in exfoliation type solder corrosion SHIVELY.C N Arkansas Power & Light Co 80/05/2P ip
- B006130264 Submits followup actions to RCP seal failure on B00510 in response to NRC request Following cooldown to cold shutdown, RCP Seal C cartridge was removed b transferred from containment bldg to hot instrument shop
 TRIMBLE.D C Artansas Power & Light Co B0/05/30 2pp
- 8006120277 Forwards LER 80-018/01T-0 TRIMBLE, D. C. Arkansas Power & Light Co 80/06/05 10
- --8006120283 LER 80-018/01T-0 on 800524, during investigation per IE Bulletin 80-08, discrepancy in records of weld insps found Caused by failure to properly review weld record documentation for particular weld during const BRAMLETT, L.S. Arkansas Power & Light Co. 80/06/05 ip
- 8006240096 Forwards request for additinfo re reactor coolant pump seal leak event on 800510 REID:R W Operating Reactors Branch 4 80/06/09 4pp
- 8006170623 Forwards LFR 80-01//031-0 TRIMBLE,D C Arkansas Power & Light Co 80/06/13 1p
- -8005170530 LFR 80-017/03L-O on 800517.while opening reactor bidg bypass dampers damper 7410 would not operate Caused by hoist still being connected to dampor Damper roset & hoist removed BRAKLETT.L S Ariansas Power & light CO 80/06/13 1p

- DOCKET 50-315 DOMALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8004090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D G Division of Licensing 80/05/19 46pp
- 800&030091 Notification of 800527 meeting w/util in Bethesdæ.MD to review design of proposed technical support ctr & emergency operations facility MINFR.S Operating Reactors Branch (80/05/2) 2pp
- BOO6130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Pragram for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not enc!

 EISENHUT, D. G. Division of Licensing 80/05/22 73pp
- H General correspondence
- 8006270181 Responds to 800429 request for info re M LeMiere inquiry about amount of nuclear waste disposed in State of MI Spant fuel from four operating MI seactors stored onsite NRC evaluated status of waste mgt in 1977 W/related FR excerpts DIRCKS,N J Office of the Executive Director for Operations 80/06/09 10pp
- J. Insurance & indemnity information
- 8008210255 Forwards payment for indemnity fee for 800926-810525 W/o enci DDLAN.J E Indiana & Michigan Clectric Co 80/05/16 ip
- P Operating license stage documents δ correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- BOO6130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D O Division of Licensing 80/05/19 72pp
- B006130192 Forwards Amends 37 & 20 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability
 VAR96.5 A Operating Reactors Branch 1 80/05/23 2pp
- --8006130196 Amends 37 & 20 to Licenses DPR-58 & DPR-74, respectively, providing one time only extension of time for testing Unit 2 ice condensor lower inlet doors & revising withdrawal schedule for reactor vessel surveillance capsules VARGA. S A Operating Reactors Branch 1 80/05/23 14pp
- --8004130201 Safety evaluation supporting Amends 37 & 20 to Licenses
 DPR-58 & DPR-74 respectively

 # Office of Nuclear Reactor Regulation, Director 80/05/23 3pp
- --8006130206 Notice of issuance & availability of Amends 37 & 20 to Licenses DPR-58 & DPR-74, respectively VARGA.8 A Decrating Reactors Branch 1 80/05/23 2pp
- 8006030284 Forwards remittance in response to 800409 itr requesting processing fee for NRC review of util 800324 submittal Requests that NRC review & reconsider whether fee is necessary
 HUNTER, R S Indiana & Michigan Electric Co 80/05/28 2pp
- 8004030300 Forwards addl info & Tech Bpecs re util 791217 response to NRC 79080B itr on adequacy of station elactrical distribution sys voltage DOLANA J E Indiana & Michigan Electric Co 80/05/28 11pp
- ~-8006030301 Tech Spec 3/4 8 3 re alternative ac power sources # Indiana & Michigan Electric Co 80/05/28 5pp

- 8006050037 Responds to NRC 800418 ltr re evaluation of ultimate strength of facility containment bldgs Requests updates of ongoing NRC work is hydrogen generation & containment capacity studies & opportunity to comment on results DOLAN. J E Indiana & Michigan Electric Co 80/05/30 2pp
- 8006170309 Reminds licensee that 800324 request to use divers to cut studs welded to buttom liner 5 supports in replacement of racks in spent fuel pool is subject to payment of fees Fees should be submitted within 15 days

 MILLER, W.O. License Fee Management Branch 80/06/02 1p
- 8006240087 Confirms 800762 meeting w/util in New York, NY to discuss proposed resolution of several operational & 6A problems Problems were previously discussed at 800415 mgt meeting KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10 to
- B006230407 Responds to A Schwencer B00429 info request re facility GE low pressure turbine Discusses site specific & generic questions re GE low pressure turbine, Berial 170X412 DDLAN-J E Indiana & Michigan Electric Co 80/06/16 Spp
- 8006230487 Forwards proposed Tech Spec 3 0 5 in response to NRC 800410 request DDLAN.J E Indiana & Michigan Electric Co 80/06/16 ip
- ~-800623049; Proposed Tech Spec 3 0 5 re criteria for operability Related Tech Specs encl # Indiana & Michigan Electric Co 80/06/16 7pp
- 8006æ40177 Withdraws 790319 & 8005æ2 Tech Spec change requests re rod position indication sys % steam generator water lavel low low reactor trip/engineered safety features actuation sustpoints Rod position indication sys change unnecessary DOLAN.J F Indiana & Michigan Electric Co 80/04/17 3pp
- B006240491 Notifies that fourth refueling outage initiated on B00530 Startup date for Cycle 3 operation scheduled for B00731 DDLAN.J E Indiana & Michigan Electric Co 80/06/1B 2pp
- 800A2404B2 Forwards response to NRC 800507 ltr re addl TMI-2 related requirements Procedures for feedback of operating experience to plant staff will be reviewed Licensee will provide info to Hestinghouse for generic rept HUNTER, R S Indiana & Michigan Electric Co 80/06/20 App
- G Inspection reports, IE Bulletins & correspondence
- B004170044 Forwards IE Insp Repts 50-315/80-07 & 50-316/80-06 of meeting on 800415 No noncompliance noted KEPPLER. J O Region 3, Chicago, Office of the Director 80/04/28 200
- --B006170052 IE Insp Repts 50-315/80-07 % 50-316/80-06 of meeting on 800415 No noncompliance noted Major areas inspected implementation of util 0A program & regulatory performance re personnel error & adherence to procedure BOYD, D C , MASSER E Region 3, Chicago, Office of the Director HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/04/24 2pp
- 8006170748 Discusses NRC 791228 issuance of Info Notice 79-37 re cracks in key way & bore sections of discs in Westinghouse low pressure turbines Addi info concerning info notice requested Response due within 30 days of receipt of ltr SCHWENGER.A Licensing Branch 2 80/04/29 3pp
- 8006130187 Forwards LE Insp Repts 50-315/80-04 & 50-316/80-03 on B00111-0331 & notice of violation HEISHMANR F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/02 2pp
- --8006130173 Natice of violation from insp on B00111-0331 * Region 3, Chicago. Office of the Director B0/04/30 1p
- --8006130198 IE Insp Repts 50-315/80-04 & 50-316/80-03 on 800111-0331 Noncompliance noted spent fuel pit concentration found to be below min level on 800317 MASSER E , DUBRY,N E , BOYD,D C Region 3, Chicago, Office of the Director 80/04/30 12pp
- 8006030281 Forwards remaining responses to 1E Bulletin 79-018 re environ qualification of Class IE equipment 1/0 enci HUNTER.R 8 Illinois Power Co 80/05/07 4pp

- 8006060019 Provides supplemental response to IE Bulletin 79-018.
 "Environ Qualification of Class IE Equipment" Forwards
 modified list of equipment to reflect refs to qualification
 charts List proves adverse environ qualification
 HUNTER.R 8 Indiana & Michigan Electric Co 80/05/07 1000pp 80705707 1000ap
- 8006200196 Forwards IE imag Repts 50-315/80-06 & 50-316/80-05 on 800421-25 No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/13
- ---B006200199 IE Insp Repts S0-315/B0-06 & S0-316/B0-05 on B00421-25 No noncompliance noted Major areas inspected radiological environ protection PSSIG.T H. GREER, R. J. MASSE, R. Region 3, Chicago, Office of the Director. B0/05/12 4pp
- 8006130076 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON.J M Division of Rules and Records 80/05/23 3pp
- --8004130099 Forwards response to updated memo received on 800313 re util interrogatories re proposed imposition of civil penalty Cover sheet of IE insp rept@nci KEPPLER.J Q Region 3. Chicago, Office of the Director 80/03/21
- --B006130111 IE Insp Rept 50-315/77-24 on 771206-07 Noncompliance noted both containment spray sys out of svc
 BAKER.K R , WARNICK.R F Indiana & Michigan Power Co 78/01/04
- --8006130113 RO on 771118 while performing routine surveillance test, heat exchanger inket valve was discovered closed Caused by personnel error Valves were opened upon discovery CHADMELL, H M Indiana & Michigan Power Co 77711/28 ip
- --8006130115 Confirms 771118 verbal rept re closed containment spray heat exchanger inlet valves Enjlowup rept will be provided by 771201 SHALLER, D V Indiana & Michigan Power Co 77/11/18 ip
- BOOA180594 Ack receipt of 800512 ltr informing NRC of steps taken to correct noncompliance noted in IE Inap Repts 50-315/80-05 & 50-316/80-04 Corrective action will be examined during HIND, J A Region 3, Chicago, Safeguards Branch 80/06/03
- --8006180600 Forwards response to NRC BD0417 ltr re noncompliance identified in IE Insp Repts 50-315/80-05 & 50-316/80-04 Response withheld (ref 10CFR2 790) Indiana & Michigan Power Co 80/05/12 ip
- 8006190383 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-315/80-01 & 50-316/80-01 HEISHWANR F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/05
- --B006190386 Responds to NRC B00505 ltr re violations noted in IE Insp Repts 80-315/80-0; & 50-316/80-0; Corrective actions Class i component list will be continually updated as addi components are identified DOLAN, J E Indiana & Nichigan Power Co 80/05/28 5pp
- BOO6240072 Responds to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment "Forwards corrected 3/or add1 pages to Attachments 5 & 6 to util BOO507 second set of responses HUNTER.R 8 Indiana & Michigan Electric Co 80/06/05 35pp
- R Pariodic operating reports ${\cal V}$ related correspondence
- 8006170521 Forwards monthly operating rept for May 1980 SHALLER, D. V Indiana & Michigan Electric Co B0/06/11 1p
- --8006170550 Monthly operating rept for May 1980 OILLETT.W T Indiana & Michigan Electric Co 8D/06/03 7ep

- 8006300502 Forwards LER 80-011/03L-0 SHALLER, D.V. Indiana & Michigan Electric Co. 80/06/25 ip
- --8006300508 LER 80-011/03L-0 on 800531. w/unit in shutdown mode. containment atmosphere air particulate & gaseous radiation monitoring sys pump tripped on low flow Caused by inaccurate flowmeter Flowmeter replaced DELONG, 8 D Indiana & Michigan Electric Co 80/06/25 2pp
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 1000R50 & 1s expected to be published in FR by end of May EISENHUT, D & Division of Licensing 80/05/19 46pp
- 8006030091 Notification of 800527 meeting w/util in Bethesda.MD to review design of proposed technical support ctr & emergency operations facility MINER.S Operating Reactors Branch 1 80/05/21 2pp
- B006130063 Forwards revised Pages 1-14 to new Page 14a for proposed rule iOCFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC B00919 ltr Page 14a not encl
 EISENHUT,D G Division of Licensing 80/05/22 73pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams % licensee dissemination of operating experiences Response requested within 30 days EISENMUT, D G Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Conlant Pump Supports "Proposed review procedure & implementation schedule encl EISENHUT,D G Division of Licensing 80/05/19 72pp
- BOO6130192 Forwards Amends 37 & 20 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability VARQA, S A Operating Reactors Branch 1 BO/05/23 2pp
- --8006130196 Amends 37 % 20 to Licenses DPR-58 % DPR-74 respectively, providing one time only extension of time for testing Unit 2 ice condenser lower inlet doors & revising withdrawal schedule for reactor vessel surveillance capsules VARGA, S A Operating Reactors Branch | 60/05/23 14pp
- --8006130201 Safety evaluation supporting Amends 37 & 20 to Licenses
 OPR-58 & DPR-74, respectively
 * Office of Nuclear Reactor Regulation, Director 80/05/23 3pp
- --8006130206 Notice of issuance & availability of Amends 37 & 20 to Licenses DPR-58 & DPR-74,respectively VARGA,8 A. Operating Reactors Branch t. 80/05/23 2pp
- BOOG120465 Advises that util 791218 application accepted as being supplementary to 780519 application based on addl info provided by Ofc of Nuclear Reactor Regulation No addl fees MILLER, W O License Fee Management Branch 80/05/27
- 8006030284 Forwards remittance in response to 800409 ltr requesting processing fee for NRC review of util 800324 submittal Requests that NRC review & reconsider whether fee is necessary HUNTER,R S Indiana & Michigan Electric Co 80/05/28 2pp
- 8006030300 Forwards add1 info 5 Tech Specs re util 791217 response to NRC 790808 ltr on adequacy of station electrical distribution sys voltage DDLAN. J E Indiana 5 Michigan Electric Co 80/05/28 iipp
- --9004030301 Tech Spec 3/4 8 3 re alternative ac power sources * Indiana & Michigan Electric Co 90/05/28 5pp
- 8006090037 Responds to NRC 800418 ltr re evaluation of ultimate strength of facility containment bldgs Requests updates of ongoing NRC work re hydrogen generation & containment capacity studies & oppositunity to comment on results DGLAN. J E Indiana & Michigan Electric Co 80/05/30 2pp

- 8006170309 Reminds licensee that 800324 request to use divers to cut studs welded to bottom liner & supports in replacement of racks in spent fuel pool is subject to payment of fees Fees should be submitted within 15 days
 MILLER.W O License Fee Management Branch 80/06/02 ip
- 8006240087 Confirms 800702 meeting w/util in New York,NY to discuss proposed resolution of several operational & GA problems Problems were previously discussed at 800415 mgt meeting KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10
- 6006230487 Forwards proposed Tech Spec 3 0 5 in response to NRC 800410 request DDLANJE Indiana & Michigan Electric Co 80/06/16 Ip
- ---B00623047(Proposed Tech Spec 3 0 5 re criteria for operability Related Tech Specs encl * Indiana & Michigan Electric Co 80/06/16 7pp
- 8006260177 Withdraws 790319 & 800522 Tech Spec change requests re rod position indication sys & steam generator water level low low reactor trip/engineered safety features actuation systemates actuation systemates actuation systemates with the systemate state of the processary DDLAN, J E Indiana & Michigan Electric Co 80/06/17 3pp
- 8004240482 Forwards response to NRC 800507 ltr re addl TMI-2 related requirements Procedures for feedback of operating experience to plant staff will be reviewed Licensee will provide info to Westinghouse for generic rept
 HUNTER.R 8 Indiana & Michigan Electric Co 80/06/20 App
- @ Inspection reports, IE Bulletins & correspondence
- 8004170044 Forwards IE Insp Repts 50-319/80-07 \$ 50-316/80-06 of meeting on 800415 No noncompliance noted KEPPLER.J C Region 3. Chicago, Office of the Director 80/04/28 200
- --BOO4170052 IE Insp. Repts 30-315/80-07 & 50-316/80-06 of meeting on BOO415 No noncompliance noted Major areas inspected implementation of util GA program & regulatory performance re personnel error & adherence to procedure BOYD.D C . MASSE.R E Region 3. Chicago, Office of the Director HEISHMAN, R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch BO/04/24 2pp
- 8006i30189 Forwards IE Insp Repts 50~315/80-04 & 50~316/80~03 on 800111-0331 & notice of violation HEISHMAN F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/02 2pp
- --8004130193 Notice of violation from insp on 800111-0331 * Region 3. Chicago. Office of the Director 80/04/30 1p
- --800Ai30i98 IE Insp Repts 50-3i5/80-04 & 50-3i6/80-03 on 800iii-033i Noncompliance noted spent fuel pit concentration found to be below min level on 8003i7 MASSE.R E . DUBRY.N E . 80YD.D C Region 3. Chicago, Office of the Director 80/04/30 i2pp
- 8006030281 Forwards remaining responses to IE Mulletin 79-018 re environ qualification of Class IE equipment W/o encl HUNTER.R S Illinois Power Co 80/05/07 4pp
- BOOA00019 Provides supplemental response to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment " Forwards modified list of equipment to reflect refs to qualification charts List proves adverse environ qualification HUNTER.R 8 Indiana & Michigan Electric Co 80/05/07 1000pp
- 8006200176 Forwards IE Insp Repts 50-315/80-06 & 50-316/80-05 on 800421-25 No noncompliance noted KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/13
- --B006200199 IE Insp Repts 50-315/B0-06 & 50-316/B0-05 on B00421-25 No noncompliance noted Major areas inspected radiological anylron protection ESSIO.T H. OREER R. J., MASSE.R. Region 3. Chicago, Office of the Director 80/05/12 App
- 8006180594 Ack receipt of 800512 ltr informing NRC of steps taken to correct moncompliance noted in IE Insp Repts 50-315/80-05 & 50-316/80-04 Corrective action will be examined during future insp
 HIND, J A Region 3, Chicago, Safeguards Branch 80/06/03 ip

- --8006180600 Forwards response to NRC 800417 ltr re noncompliance identified in IE Insp Repts 50-315/80-05 & 50-316/80-04 Response withheld (ref 10CFR2 790) DDLAN, J E Indiana & Michigan Power Co 80/05/12 lp
- BOO6190383 Ack receipt of BOO528 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/BO-01 & 50-315/BO-01 WEISHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch BO/06/05 ip
- --8006190386 Responds to NRC 800505 ltr re violations noted in IE Insp Repts 50-315/80-01 & 50-316/80-01 Corrective actions Class 1 components list will be continually updated as add1 components are identified DOLAN, J E Indiana & Michigan Power Co 80/05/28 5pp
- 8006240072 Responds to IE Bulketin 79-018, "Environ Qualification of Class IE Equipment " Forwards corrected &/or addl pages to Attachments 5 & 6 to util 800507 second set of responses HUNTER,R S Indiana & Michigan Electric Co 80/06/05 35pp
- R Pariodic operating reports & related correspondence
- 8006170698 Forwards monthly operating rept for May 1980 SHALLER, D.V. Indiana & Michigan Electric Co. 80/06/11 1p
- --8006170704 Monthly operating rept for May 1980 OILLETAN Y Indiana & Michigan Electric Co 80/06/03 7pg
- S Reportable occurrences. LERs & related correspondence
- 8006230412 RO 50-316/80-018 during investigation per IE Builetin 80-08, discovered reactor bldg flued head penetration weld FM-P-51-1 had not been repaired to correct fusion defect Weld defect will be repaired prior to power operation O'HANLON, J P Arkansas Power & Light Co 80/05/27 ip
- BOO6050306 Forwards LER 80-022/03L-0 & updated LER 79-041/03L-1 BHALLER,D V Indiana & Michigan Electric Co 80/06/02 1p
- --8006050312 LER 80-022/03L-0 on 800503.radiation monitor R-11 alarmed during normal operation Sample pump for R-11 & R-12 would not remain running Caused by wear of pump Pump replaced & air sampler tested Entire sys will be replaced WIZNER.D G Indiana & Michigan Electric Go 80/06/02 IP
- --8006050315 Updated LER 79-041/03L-1 on 79:101/hydrogen recombiner 1 failed to increase temp to 1,200 F within 5-h Caused by incorrect electrical connection of one heater element Wiring corrected & controller gain & bias adjusted WIZNER, D O Indiana & Michigan Electric Co 80/06/02 1P
- BOO6120300 Forwards updated LER 80-001/03X-1 SHALLER, D V Indiana & Michigan Electric Co 80/06/04 ip
- --8006120303 Updated LER 80-001/03X-1 on 800119, w/approx 10% power level, steam generators fed too much feedwater flow resulting in temp & pressure drop Caused by attempt to recover low steam generator level MURPHY.C.E Indiana & Michigan Electric Co 80/06/04 ip
- 8D06170669 Forwards LER 80-023/03L-0 8HALLER,D V Indiana & Michigan Electric Co 80/06/10 1p
- ---B006170677 LER 80-023/03L-O on 800516, during normal operation, low flow alarm for containment APD R-11 & R-12 was received Sample pump would not restart & R-11 & R-12 were declared inoperable Caused by inaccurate flow moter, Meter replaced RISCHLING.J L Indiana & Michigan Electric Co B0/06/10 2pp
- 8006240462 Forwards LER 80-024/03L-0 8HALLER.D V Indiana & Michigan Electric Co 80/06/19 1p
- --8006240476 LER 80-024/03L-0 on 800520, w/turbine drive auxiliary feedwater pump in nonrunning standby position, alarm received that pump tripped Probably caused by control linkage disconnecting from throttle valve LEASE R.S. Indiana & Michigan Electric Co. 80/06/19 1p

- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
 F. Security, medical, emergency & fire protection plans
- BOO6040192 Forwards request for additinfo re incomplete fire protection items per review required by 791113 SER Response should include commitments necessary to respive all items by BOI001 & be submitted within 30 days CLARK.R A Operating Reactors Branch 3 80/05/19 23pp
- 8006070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 30 48 & App R to 100FR50 & is expected to be published in FR by end of May EISENHUT, D G Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR\$0 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 1tr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8004030237 Responds to NRC 800331 ltm re LNG contingency plan Informs NRC that due to difficult, time consuming nature of cable routing installation of monitor expected to be completed & sys operational by 800413

 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/30 ip
- 8006060317 Requests extension to B00715 for submission of guard training & qualification plan revisions & add1 info requested by NRC 800513 ltr
 EVANS, V R Baltimore Gas & Electric Co 80/06/02 lp
- 8006170439 Forwards revised emergency response plan Plan upgraded per draft NUREG-0654 requirements Summary of relationship of plan to draft NUREG encl LUNDVALL.A E Baltimore Gas & Electric Co 80/06/10 43pp
- ---8006170441 Revised emergency response plan
 * Baitimore Gas & Electric Co 80/06/30 350pp
- B006240320 Forwards response to Items 3 1 t3.3 2 t.3 2 2.3 2 4 & 3 2 5 of NRC B00519 ltr re fire protection safety evaluation & amends to DL Certification statement for fire detection & suppression alarm sys encl LUNDVALL.A E Baltimore Gas & Electric Co 80/06/20 10pp
- J Insurance & indemnity information
- BOO518035B Forwards Endorsements 12 & 13 to NELIA Policy NS-348 SHDEHAKER.C L Baltimore Cas & Electric Co BO/05/13 3pp
- P Operating license stage documents & correspondence
- 8006020532 Comments on proposed rule 10CFR50 items of lesser importance should not be mixed of requirements to report items of actual potential hazard to public Separate & distinct reporting mechanism should be established RUSBELL.L B Baltimore Gas & Electric Co 80/05/02 2pp
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Flan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 3D days EISENHUT.D O Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PNR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D G Division of Licensing 80/05/19 72pp
- B006240085 Confirms 800522 telcon to plans to establish adequate neutron monitoring program in support of required entries into reactor bldg ALARA evaluation must be established & documentation submitted to Region 1 ORIER.8 H Region 1. Philadelphia, Office of the Director 80/05/22 2pp
- 8006240063 Advises that interim reliability evaluation program resulting from TMI action plan will be implemented Requests attendance at 800604 meeting in Bethesda, MD to discuss details

 EISENHUT, D G Division of Licensing 80/05/23 5pp

- 8006020149 Responds to NRC ltr re request for add1 info on partial loop operation info required in support of 790405 application for amend to OLs to allow operation w/less than four reactor coolant pumps
 LUNDVALL.A F Baltimore Gas & Electric Co 80/05/27 10pp
- 8006050217 Notification of 800605 meeting w/vtil in Bethesda.MD to discuss improvements in offsite power sources for facilities
 CONNER.E.L. Operating Reactors Branch 3 80/05/27 2pp
- 8006030244 Notifies that implementation of emergency procedures & retraining re accidents & transients will be completed within three months of NRC review & approval of guidelines submitted on 800401 LUNDIVALL. A E Baltimore Gas & Electric Co 80/05/30 2pp
- 8006040209 Submits add1 info requested by NRC re application for amend of Licenses DPR-53 & DPR-69 Electropolishing method will be used in decontaminating racks Reanalysis of spent fuel pool structure indicates no problem exists w/increased loads ASH.R F Baltimore Gas & Electric Co 80/05/30 1p
- BOO6180104 Discusses review of 800521 proposal Proposal is satisfactory re NUREC-0578.Category B requirements for high range effluent monitors Monitors should be provided for release paths measuring from 0 1-1000 uCi/Cubic centimeter CLARK,R A Operating Reactors Branch 3 80/06/04 2pp
- 8006240165 Notification of 800612 meeting w/utils in Bethesda.MD to discuss interim reliability evaluation program QLGHAN.L N Operating Reactors Branch 1 80/06/09 29p
- BOO6270011 Submits trip rept of participation in MD Commission on Intergovernmental Cooperation 800603 meeting in Annapolis, MD re nuclear waste mgt & disposal CONNER, E. L. Operating Reactors Branch 3 80/06/13 2pp
- --8004270016 Requests participation in MD Commission on Intergovernmental Cooperation 800603 & 17 meeting in Annapolis, MD re nuclear waste mgt problem Specific questions enci EASTER.J K Maryland, State of 80/04/28 2pp
- --80062700iB Confirms arrangements for participation in MD Commission on Intergovernmental Cooperation hearing in Annapolis,MD re spent fuel storage Revised agenda encl ROBART.A Office of State Programs, Director 80/05/29 Spp
- ---8006270020 Testimony at MD Commission on Intergovernmental Cooperation 800603 hearing in Annapolis,MD re spent fuel storage Outline of EL Conner comments and I LONG.5 M Georgia. State of 80/06/03 8pp
- ---8008270027 Testimony at MD Commission on Intergovernmental Cooperation BOQ863 hearing re spent fuel storage Background info for hearing encl CRITZ,H G Energy,Dept of 80/08/03 41pp
- 8006180260 Responds to NRC 800515 itr requesting info re possibility of cracking in low pressure turbine discs Site specific generic info nominal water chemistry & steam generator chemistry is provided.
 - LUNDVALL, A E Baltimore Gas & Electric Co 80/06/15 8pp
- BO06260001 Notification of BO061B meeting w/util & NES in Bethesda.MD to discuss structural design of proposed mode to spent fuel pool GONNER.E L Operating Reactors Branch 3 80/06/16 lp
- 8006190530 Forwards nonproprietary info re LOCA portion of application for amend to OL Affidavit untl Proprietary version withheld (ref 10CFR2 790)
 OLSON,R C Baltimore Gas & Electric Co 80/06/17 9pp
- 8006230270 Submits responses to add1 TMI-2 related requirements per
- BO05020270 Submits responses to add1 TM1-2 related requirements per B00507 request LUNDVALL.A E Baltimore Gas & Electric Co B0/06/18, 3pp
- G Inspection reports. IE Bulletins & correspondence
- 8004170810 Forwards IE Insp Repts 50~317/80-03 & 50~318/80-03 on B00310-28 No noncompliance noted BRUNNER, E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/25 2pp

- --8006170816 IE Insp Repts 50-317/80-03 & 50-318/80-03 on 800310-28 No noncompliance noted Major areas inspected control room & accessible portions of auxiliary, turbine, svc & intake bldgs, radiation protection, physical security & fire protection ARCHITZEL R Region 1. Philadelphia, Office of the Director MCCABELE C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/24 Spp
- BOO6270239 Forwards IE losp Repts 50-317/80-04 & 50-319/80-04 on BOO317-21 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN, N G Region 1, Philadelphia, Safeguards Branch 80/05/05
- --B004270245 IE Insp Repts 50-317/B0-04 & 50-318/B0-04 on B00317-21 Noncompliance noted failure to report changes to security plan & failure to positively control access to vital areas Details withheld (ref 10CFR2 790)
 DEVLIN.J W Region i, Philadelphia, Safeguards Branch BAILEY,R J , MCKEOWN,L M Region 1, Philadelphia, Office of the Director 80/05/01 2pp
- 8006240011 Responds to IE Bulletin 79-03A re longitudinal weld defects in ABME 8A-312 Type-304 stainless steel pipe Stress calculations performed on specified pipe Results indicated no pieces loaded to any value greater than code allowable LUNDVALL.A E Daltimore Qas & Electric Co 80/05/20 ip
- 800.6240.020 Updates response to IE Bulletin 79-01B, "Environ qualification of Class IE Equipment" Forwards list of safety-related equipment installed below elevation is ft 10 inches Outstanding insp items to be completed by 800.630 LUMBVALL.A E Baltimore Cas & Electric Co 80/05/27 3pp
- 8006200038 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/05/28 ip
- BOOAGOOSIG Forwards response to IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Scenario of Davis-Besse incident would not cause loss of shutdown cooling w/air binding of sys at facilities GRE, J W Baltimore Gas & Electric Co 80/06/09 Spp
- B006240339 Forwards add1 response to IE Info Notice 79-04, providing verification of accuracy of electric distribution sys voltage tests Results confirm calculations GLBON, R C Baltimore Gas & Electric Co 80/06/20 2pp
- 8 Reportable occurrences. LERs & related correspondence
- 800.606.582 RO on 800.416, NRC Div of Project Mgt advised util of possible generic deficiency in FSAR Section 4 3 Boron dilution incident analysis does not analyze when RCS may be drained to middle of hot leg w/1% shutdown margin DAVIS, S M Pacific Gas & Electric Co 80/04/16 lp
- 8005190447 Forwards comments re NUREG-0654, "Criteria for Preparation & Evaluation of Radiological Emergency Response Plans & Preparedness in Support of Nuclear Power Plants " LUNDVALL.A E Baltimore Gas & Electric Co 80/05/13 20pp
- 8006050063 PNO-1-80-081 on 800521. while taking routine readings, suction pressure for auxiliary feed pumps discovered reading zero Incident under investigation MCCABE.E C. BRUNNER, E. J. Region i. Philadelphia, Office of the Director 80/05/21 ip
- BOD6090451 PNG-I-80-081 on BOO520, auxiliary feedwater sys used to remove reactor decay heat loads Operator reported that suction pressure on auxiliary feed pumps was reading Zero BRUNNER, E. J. Region I. Philadelphia, Reactor Operations Nuclear Supports Branch MCCABE. E. C. Region 1. Philadelphia, Office of the Director 80/05/21 2pp
- 8006120262 RO on 800520, while operating at full power, low pressure alarm on 11 & 12 svc water subsys annunicated Reactor manually tripped Both sys air bound Caused by tube degradation in 11 instrument air compressor RUSSELL, L. B. Baltimore Gas & Electric Co. 80/05/21 lp
- 8006120276 RG on 800520, suction pressure for auxiliary feed pump read zero Caused by improper valve realignment following manual trip due to degradation of svc water sys Valves properly realigned & verification check list formulated RUSSELL, L B Saltimore Gas & Electric Co 80/05/21 Spp

- 8006050413 PNO-1-80-081A on 800520, manual reactor trip was initiated because of high turbing bearing temp resulting from loss of both svc water sys Licensee procedures have been modified to require add1 checking MCCABE, E.C., BRUNNER, E.J. Region 1, Philadelphia, Office of the Director 80/05/22 ip
- 8006050028 Forwards LER 80-024/03L-0 RUBSELL,L B Baltimore Gas & Electric Co 80/05/30 tp
- ---B006050035 LER 60-024/03L on 800430, while making containment insp. discovered cracked weld on 118 reactor coolant pump control bleedoff line Caused by metal fatigue induced by vibration fipe replaced 2 weld repair performed DAVIS.S M , HUSEBY.D E Baltimore Gas & Electric Co 80/05/30 tp
- 8006180612 PNO-I-80-086 on 800602.utils informed NRC of tornado watch in vicinity of plants Forecast included potential for severe thunderstorms.large half & damaging winds Licensees implemented energency procedures

 MCCABE.E C , BRUNNER.E J Region 1, Philadelphia, Office of the Director 80/06/02 2pp
- B006070344 Forwards LER B0-027/01T-0 RUBSELL,L B Baltimore Qas & Electric Co B0/06/03 1p
- ---8006090348 LER 80-027/017-0 on 800520, following routine tube cleaning on saltwator side of two water heat exchanger 12, low pressure alarms were received on subsys if & 12 Caused by failed tube in exchanger 11 instrument compressor cooler DAVIS.S M Baltimore Gas & Electric Co 80/06/03 Rpp
- 8006070365 Forwards LER 80-026/01T-0 RUSSELL, L B Baltimore Gas & Electric Co 80/06/03 ip
- --8006090368 LER 80-026/01T-O on 800520. while in hot standby, realignment of condensate storage tank header supply valves resulted in isolation of water supply to auxiliary feedwater pumps Caused by error of transposed valve numbers in log.

 DENTON, R E Baltimore Gas & Electric Co 80/06/03 3pp
- BOO6180433 Forwards LER 80-028/03L-0 RUSSELL, L B Baltimore Gas & Electric Go BO/06/13 1p.
- ---B0051B0443 LER B0-02B/03L-0 on B00B15 during performance of routine test diesel generator 12 failed to reach rated speed in less than 10-s until third attempt Caused by intermittent Female pin & crack in bakelite spacer of anphenol connector HEIBEL.R P . BAVER.E R Baltimore Gas & Electric Co 80/06/13
- DOCKET 50-318 CALVERY CLIPFS NUCLEAR POWER PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8004040192 Forwards request for addl info re incomplete fire protection items per review required by 791113 SER Response should include commitments necessary to resolve all items by 801001 & be submitted within 30 days

 CLARK.R A Operating Reactors Branch 3 80/05/19 23pp
- BODA090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Boction 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D Q. Division of Licensing, BO/05/19 44pp
- 8006:30063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D G Division of Licensing 80/05/22 73pp
- 8006030237 Responds to NRC 800331 ltr re LNO contingency plan Informs NRC that due to difficult, time consuming nature of cable routing installation of monitor expected to be completed & sys operational by 800613 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/30 1p
- 8006060317 Requests extension to 800715 for submission of guard training & qualification plan revisions & addl info requested by NRC 800513 ltr EVANS.V R Baltimore Oas & Electric Co 80/06/02 ip
- 8006170439 Forwards revised emergency response plan. Plan upgraded per draft NUREG-0654 requirements Summary of relationship of plan to draft NUREG encl LUNDVALL.A E Baltimore Gas & Electric Co 80/05/10 43pp

- --B006170441 Revised emergency response plan
 * Baltimore Gas & Electric Co B0/06/30 350pp
- 8006240320 Forwards response to Items 3 1 13,3 2 1.3 2 2,3 2 4 & 3 2 5 of NRC 800519 ltr refire protection safety evaluation & amends to 01 Certification statement for fire detection & tuppression alarm sys enci LUNDYALL.A E Baltimore Gas & Electric Co 80/06/20 10pp
- J Insurance & indemnity information
- 8006180398 Forward: Endorsements 12 & 13 to NELIA Policy N8-348 SHOEMAKER.C L Baltimore Gas & Electric Co 80/06/13 3pp.
- P Operating license stage documents & correspondence
- 800A020832 Comments on proposed rule 10CFR50 items of lesser importance should not be mixed w/requirements to report items of actual potential hazard to public Separate & distinct reporting mechanism should be established RUSBELL.L B Baltimore Gas & Electric Co 80/05/02 2pp
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D © Division of Licensing 80/05/07 150pp
- 8006:301:22 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT, D © Division of Licensing 80/05/19 72pp
- 8006240085 Confirms 800522 telcon re plans to establish adequate nautron monitoring program in support of required entries into reactor bldg ALARA evaluation must be established & documentation submitted to Region I ORIER, B H Region I. Philadelphia. Office of the Director 80/05/22 2pp
- 8006240063 Advises that interim reliability evaluation program resulting from TMI action plan will be implemented Requests attendance at 800604 meeting in Bethesda, MD to discuss EISENHUT.D G Division of Licensing 80/03/23 5pp
- 8006020149 Responds to NRC ltr re request for add1 info on partial loop operation Info required in support of 790405 application for amend to DLs to allow operation w/less than four reactor Cuclant pumps
 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/27 10ep
- 8QQ6050217 Notification of 800405 meeting w/util in Bethesda, MD to discuss improvements in offsite power sources for facilities CONNER.E.L Operating Reactors Branch 3 80/05/27 2pp
- BOO6030244 Notifies that implementation of emergency procedures & retraining re-accidents & transients will be completed within three months of NRC review & approval of guidelines submitted on BOO401 LUNDVALL.A E Baltimore Oss & Electric Co 80/05/30 2pp Baltimore Gas & Electric Co 80/05/30 2pp
- BOO6040209 Submits add1 info requested by NRC re application for amend of Licenses DPR-53 & DPR-69 Electropolishing method will be used in decontaminating racks Reanalysis of spent fuel pool structure indicates no problem exists w/increased loads ASH:R F Baltimore Gas & Electric Co 80/05/30 ip
- 8006180104 Discusses review of 800521 proposal Proposal is satisfactory re NUREC-0578. Category B requirements for high range affluent monitors. Monitors should be provided for release gaths measuring from 0 1-1000 ucli/cubic centineter CLARK. R A Operating Reactors Branch 3 80/06/04 2pp
- BOO6180435 Forwards "Summary of Startup Testing for Third Cycle " LUNDVALL:A E Baltimore Gas & Electric Co 80/06/12 2pp
- --8006180436 "Bummary of Startup Testing for Third Cycle " * Baltimore Oas & Electric Co 80/06/12 7ap
- BOO6270011 Submits trip rept of participation in MD Commission on Intergovernmental Cooperation 800603 meeting in Annapolis, MD re nuclear waste mgt & disposal CONNER, E.L. Operating Reactors Branch 3 80/06/13 2pp

- --B006270016 Requests participation in MD Commission on Intergovernmental Gooperation B00603 & 17 meeting in Annapolis.MD re nuclear waste mgt problem Specific questions encl EASTER.J H Maryland, State of B0/04/2B 2pp
- --8006270018 Confirms arrangements for participation in MD Commission on Intergovernmental Cooperation hearing in Annapolis.MD re spent fuel storage Revised agenda encl ROBART, A Office of State Programs. Director 80/05/29 5pp
- ---B006270020 Testimony at MD Commission on Intergovernmental Cooperation 800603 hearing in Annapolis MD re spent fuel storage Outline of EL Conner comments encl LONG,S M Georgia. State of 80/06/03 8pp
- --B006270027 Testimony at MD Commission on Intergovernmental Cooperation B00603 hearing re spent fuel storage Background info for hearing encl CRITZ,H G Energy.Dept of 80/06/03 41pp
- 8006260001 Notification of 800618 meeting w/util & NES in Bethesda.MD to discuss structural design of proposed mode to spent fuel CONNER,E L Operating Reactors Branch 3 80/06/16
- 8006190530 Forwards nonproprietary info re LOCA portion of application for amend to OL Affidavit encl Proprietary version withheld (ref 10CFR2 790)
 CLSON-R C Baltimore Gas & Electric Co 80/06/17 9pp
- 8004230270 Submits responses to add1 TMI-2 related requirements per 800507 request LUNDVALL,A E Baltimore Gas & Electric Co 80/06/18 3pp
- @ Inspection reports, IE Bulletins & correspondence
- 800&170810 Ferwards IE Insp Repts 50-317/80-03 & 50-318/80-03 en 800310-28 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/25 2pp
- -- 8906170816 IE Insp Repts 50-317/80-03 & 50-318/80-03 on 800310-28 No noncompliance noted Major areas inspected control room & accessible portions of auxiliary, turbine, svc & intake bldgs, radiation protection, physical security & fire protection ARCHITZEL, R Region 1, Philadelphia, Office of the Director MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/24 Spp
- 8006270239 Forwards IE Insp Repts 50-317/80-04 & 50-318/80-04 on 800317-21 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN:N G Region 1. Philadelphia. Safeguards Branch 80/08/05
- --B006270245 IE Insp Repts 50-317/80-04 & 50-318/80-04 on B00317-21
 Noncompliance noted failure to report changes to security
 plan & failure to positively control access to vital areas
 Details withheld (ref 10CFR2 790)
 DEVLIN,J W Region 1. Philadelphia. Safeguards Branch
 BAILEV.R J. MCKECHN,L M Region 1. Philadelphia. Office of the
 Director B0/05/01 2pp
- 8006240011 Responds to IE Bulletin 79-02A we longitudinal weld defects in ASME 8A-312 Type-304 stainless steel pipe Stress calculations performed on specified pipe Results indicated no pieces loaded to any value greater than code allowable LUNDVALL.A E Baltimore Gas & Electric Co 80/05/20 ip
- 8006240020 Updates response to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment "Forwards list of safety-related equipment instabled below elevation 16 ft 10 inches Outstanding insp. Items to be completed by 800630 LUNDVALL.A E 'Baltimore Gas & Electric Co 80/05/27 3pp
- 8005200038 Forwards IE Circular BO-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- 8006300313 Forwards response to IE Bulletin 80-12, "Decay Heat Removal Bys Operability " Scenario of Davis-Besse incident would not cause loss of shutdown cooling w/air binding of sys at facilities Baltimore Gas > Flectric Co 80/06/09 5pp
- 8006240339 Forwards add1 response to IE Info Notice 79-04, providing verification of accuracy of electric distribution sys voltage tests Results confirm calculations
 OLSON,R C Baltimore Gas 5 Electric Co 80/06/20 2pp

- S Reportable occurrences, LERs & related correspondence
- 8006060582 RO on 800416, NRC Div of Project Mgt advised util of possible generic deficiency in FSAR Section 4 3 Boron dilution incident analysis does not analyse when RCS may be drained to middle of hot leg w/17 shutdown margin DAVIS, S M Pacific Gas & Electric Co 80/04/16 ip
- 8006040347 Forwards LER 80-027/03L-0 RUSSELL, L B Baltimore Cas & Electric Co BD/06/02 ip
- --8006040352 LER 80-027/03L-0 on 800506 during performance of surveillance testing discovered channel B axia: flux offset not indicating properly Caused by dirty connector on deviation cand A-5 Connector cleaned LAGIEMSKI.J S . HINXLE.L S Baltimore Gas & Electric Co BD/06/02 1P
- 8006050037 Forwards LER 80-028/031-0 RUSSELL,L B Baltimore Gas & Electric Co 80/04/02 1p
- ---8006050045 LER 80-028/C3L-0 on 800512, during steady state operation, discovered plant computer had falled Caused by I/O power fallure due to generation of noise spike LAOTEMSKI, L., HINKLE, L.S. Baltimore Gas & Electric Co. 80/Ob/O2 in
- 8006180612 PND-1-80-086 on 800602,utils informed NRC of tornade watch in vicinity of plants forecast included potential for severe thunderstoims, large half & damaging winds Licensees implemented energency procedures

 MCCABE.E C . BRUNNER.E J Region 1, Philadelphia, Office of the Director 80/06/02 2pp
- 8004180473 Forwards LER 80-031/03L-0 RUSSELL.L B Baltimore Gas & Electric Co B0/06/13 1p
- ---9006180480 LER 80-031/03L-0 on 800522.containment gaseous & particulate radiation monitors failed Caused by electrician accidently grounding motor phase causing pumps to trip Control circuit failed due to armature not being replaced in solenoid valve DAVIS.S M . BAUER.E R Ballimore Gas & Electric Co 80/06/13 200
- BO06180483 Forwards LER 80-029/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/06/13 ip
- ---BOOA1BO470 LER 80-029/03L-0 on 800515 during routine surveillance test, reactor coolant hot leg sample valve indicated intermediate position Valve position could not be verified Cause not determined DAVIS.8 M. HINKLE, L. Baltimore Gas & Electric Co BO/04/13 ip
- 8006180515 Forwards LER 80-030/031-0 RUSSELL.L D Baltimore Gas & Electric Co 80/06/13 1p
- --8006180518 LER 80-030/031-0 on 800517.containment gaseous & particulate monitors failed due to ground in instrument control power Caused by water in plant page unit Monitor pumps bridged to keep pumps running while trouble shooting continued DAVIS.S M . BAUER.E R Baltimore Gas & Electric Co 80/06/13 lap
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 D NRC Draft/Final Environmental Statements, suppls & correspondence
- B006130315 Forwards Dechtel Drawing FSK-TC-000-10, Revision A to assist in pregaration of programmatic EIS for TMT-2 recovery operations Oversize drawing available in Central Files only LEHHAM, L J Metropolitan Edison Co B0706707 lp
- F Security, medical, emergency & fire protection plans
- B005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 itr Addl specific criteria for facilities under development EISENHUT, D 0 Division of Operating Reactors B0/04/25 61pp
- 800612052B Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/05/13 2pp

- G006020106 Requests that badges assigned by Unit I & II security be returned immediately to util Security Unit II.in Middletown. PA.due to employment termination MAUDHAN,F J Metropolitan Edison Co G0/05/15 1p
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May E
- B006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790i01," transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D 0 Division of Licensing 80/05/22 73pp
- BOO4110071 Forwards util BOO527 ltr to PA Dept of Environ Resources re request for open burning permit in order to conduct training for TMI fire brigade personnel Due to small amount of fuel involved, environ impact will be minimal HERBEIN.J G Metropolitan Edison Co 80/06/04 3pp
- 8006110182 Forwards util 800527 ltr sent to PA Dept of Environ Resources requesting permit to conduct fire fighting brigade training Expects minimal unviron impact due to small amount of fuel-gasoline & lumber used HERBEINJ G Metropolitan Edison Co 80/06/04 App
- 8006060262 Correction to licensess' 800428 brief on disposition of alleged Deficiency i Cortificate of Svc encl
 BILBERG.J E Metropolitan Edison Co SILBERG.J E Metcalf & Eddy.
 RADER.R M Conner. Moore & Corber 80/05/20 Spp
- G Adjudicatory correspondence
- 8004050090 Advises of intention not to file post-hearing memorandum Certificate of Svc encl CARTER,K W Pennsylvania, State of 80/04/30 2pp
- 8006090199 Memorandum re aircraft crash probability (ssue Urges consideration of issue in proceeding OL must be withdrawn for reasons advanced in JE Sharfman dissenting opinion from ALAB-486 Certificate of Syc encl KEPFORD, C Kepford, C 80/04/30 9pp
- 8006060245 Request for extension until 800618 for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy 5 intervenors have other commitments made prior to Feb 1780 Certificate of Syc encl KEPFORD, C Citizens for Bafe Environment 80/05/20 4pp
- BOOAOAO262 Correction to licensees' 800428 brief on disposition of alleged Deficiency 1 Cortificate of Svc encl Stuberg. J E Matropolitan Edison Co RADER, R M Philadelphia Electric Co RADER, R M Public Service Electric & Qas Co of Naw Jersey 80/05/20 5pp
- 8004060547 Response to intervenors. York Committee for Safe Environ & Citizens for Safe Environ request for extension until 800518 to file proposed findings of fact in generic radon proceeding Hany delays in proceeding are cause for concern CONNER.T B Philadelphia Electric Co CONNER.T B Conner, Moore & Corber TRAVIESO-DIAZ Metropolitan Edison Co 80/03/23 11pp
- 8006060532 Suppl to B00515 motion to quash subpoems for expedited consideration Encl subpoems of JO Herbein indicates Grand Jury investigation is inextricably intertwined w/790328 incident at TMI VOIGT.H L. Hetropolitan Edison Co VOIGT.H L. LeBoeuf, Lamb, Leiby & MacRae 80/05/27 2pp
- 8004020489 Memorandum & order denying motion to quash IE 800502 subposenss directed to six util employees to give testimony on 800520-21 re particular knowledge of 790228 incident CHILK, S.J. Office of the Secretary of the Commission 80/05/28
- 8006020550 Grder granting extension until 800618 for York Committee for Safe Environ & Citizens for Safe Environ to file proposed findings of fact & conclusions of law NRC findings due on 800703 & intervenors' & applicants' responses on 800718 BISHOP, C. J. Atomic Safety and Liconsing Appeal Panel 80/03/28.

- 8006020320 Corrective natice directed to recipients of Commission 800328 memorandum & order CLI under title should be CLI-80-22
 - * Docksting & Services Branch 80/05/27 ip
- 8006030219 Forwards first officer of US Flight 170 undated ltr re info on Aircraft crash probability issue NRC will await aircraft pliot reply prior to characterizing effect on Johnsrud testimony or offering ltr in evidence CHANDLER: L J Hearing Branch 1 80/05/30 2pp
- --8006030224 Denies that 800124 statement attributed to US Air Flight 170 pilot was made by JR Dryer or other crew members Direct flights over plant are rarely if ever made DRYER, JR Affiliation Unknown 80/05/01 ip
- --8004030232 Confirms teleon re 800124 US Air Flight 170 from Pittsburgh to Harrisburg Urges response to J Johnsrud testimony alleging that plane fleu directly over TMI-2 facility Pages 607-609 of testimony encl CHANDLER
- B006090013 Discusses aircraft crash probability issue & testimony re US Air Flight 170 over TMI Ltr from first officer of Flight 170 & NRC 8000429 inquiry encl NRC will not comment on ltr until reply from pilat is received CHANDLER, L J Hearing Branch 1 80/05/30 2pp
- 8006110160 Notice advising that 800707 special prehearing conference will be held in US Federal Bldg & Courthouse in Harrisburg, PA MOLF, J.F. Atomic Safety and Licensing Board Panel 80/06/04 lp
- 8006160078 Notices of appearances in OL amend proceeding Certificate of Svc encl
 TROMBRIDOE, G F . CHURCHILL, B W . RIDOMAY, D A Metropolitan Edison
 Co 80/06/11 5pp
- 8006190549 Petition for Commonwealth of PA to participate as interested state Notice of appearance & Certificate of Svc encl CARTER.K W Pennsylvania. State of 80/06/11 4pp
- BOObi90537 Order amending Tech Specs App B.Section 2 1 2 to set forth max individual exposures
 CHILK.B J Office of the Secretary of the Commission BO/06/12
- --8006190539 Memorahdum & order directing decontamination of TMI-2 containment atmosphere to be carried out promptly by purging method recommended by NRC Separate views of PA Bradford encl
 - * Office of the Secretary of the Commission 80/06/12 13pp
- 8006180534 Answer stating no objection to State of PA 800611 petition to participate as interested state in proceeding Cartificate of Svc enci
 TROUBRIDGE, C.F. Metropolitan Edison Co TROUBRIDGE, G.F. Shaw, Pittman, Potts & Troubridge 80/06/13 3pp
- 8006300304 Forwards 800612 memorandum & order & negative declaration re release of Kr-85 from reactor bldg atmosphere by controlled purging SNYDER.B J TMI Program Office 80/05/13 4pp
- CHILDREN OF THE TRUSH GREATER GOVERNEY THE
- --B00630030B Memorandum 2 order authorizing commencement of controlled purging of reactor blog atmosphere to remove remaining radioactive Kr-85 Separate views of Commissioner Bradford encl
 CHILK.S J Office of the Secretary of the Commission 80/06/12 1300
- --8006300311 Negative declaration re proposed decontamination of Unit 2 reactor bidg atmosphere Action will not result in any significant health effects or environ impacts SNYDER:B J TMI Program Office 80/06/13 2pp
- 8006190563 Statement of policy, "Further Commission Guidance for Power Reactor OLs"

 CHILK, B. J. Office of the Secretary of the Commission 80/06/16
 14np
- 8006240422 Suppl to request for hearing & patition to intervene submitting contentions alleging that design pressure set in Tech Specs is no longer valid due to extraordinary occurrence & that neutron flux should be monitored LOCHSTET.W A Affiliation Unknown 80/06/17 2pp

- B006240343 Joint metion for reconsideration of B00612 orders for temporary mod of license Orders do not consider possible presence of radionuclides other than Kr-B5 in containment atmosphere DJ Bross B00619 ltr to SC Sholly encl EHQLLY, S C Affiliation Unknown CUNNINGHAM, J Newberry Township, York Haven, PA HOSSLER, D People Against Nuclear Energy B0/06/23
- B006240470 Response in support of State of PA 800611 petition to participate in OL amend proceeding Certificate of Svc encl CHANDLER: L J Hearing Branch 1 80/06/23 3pp
- 8006250224 Requests hearing per 10CFR2 714 to address temporary mod of Tech Specs imposed by temporary order MTLLER, K.L. Affiliation Unknown 80/06/23 2pp
- 8006260209 Memorandum & order advising that Sterling issue is no longer germane to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 800702
 BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/06/23
 300
- 8006270216 Response in opposition to KL Miller 800620 postmarked ltr requesting hearing & reconsideration of order for temporary mod of license Order reflects Commission careful consideration of record including public comments TROMBRIDGE, G F Metropolitan Edison Co TROMBRIDGE, G F Shaw, Pittman, Potts & Troubridge 80/06/24 2pp
- --8006270220 Requests hearing re Commission 800612 order for temporary mod of license Certificate of Svc encl MILLER, K. L. Affiliation Unknown 80/06/20 5pp
- 800&3003&6 Order denying intervenors' 800&23 joint motion for reconsideration of Commission 800&12 memorandum & order. CLI-80-25, & accompanying order for temporary mod of license to permit faster purpe Evaluation of 800&12 rept encl CHILK.S J Office of the Secretary of the Commission 80/06/24
- H Quneral correspondence
- 8006190413 Discusses 790328 accident at facility Submits history of personal exposure to radioactivity
 DUNHAM.L E Affiliation Unknown 79/03/31 2pp
- 8006120433 Responds to 800125 ltr to President Carter urging startup of nuclear power plants Action plan is being prepared resteps to be taken for protection of health & safety prior to startup DENION.H R Office of Nuclear Reactor Regulation, Director 89/04/11 7pp
- 8006020157 Responds to 800226 Itr to President Carter re licensing nuclear plants Provides statement made by President on 791207 NRC is in process of preparing action plan specifying actions for review b approval DENTON.H R Office of Nuclear Reactor Regulation, Director 80/04/21 2pp
- 800&020162 Responds to 800220 itr to President Carter re licensing nuclear power plants Provides President's statement made on 791207 NRC is in process of preparing action plan specifying actions for review & approval DENION.H R Office of Nuclear Reactor Regulation, Director ROYAL21 Soo
- 8006020181 Responds to encl 800228 ltr to President Carter re licensing nuclear plants Provides statement made by President on 791207 NRC is in process of prepaping action plan specifying precise actions to be taken for review & approval DENION,H R Office of Nuclear Reactor Regulation, Director 80/04/21 4pp
- 800617019B Forwards proposed response to encl JA Stewart 800401 ltr re Harrisburg,PA City Council resolution on emergency planning BIRCKS,H J Office of the Executive Director for Operations 80/04/24 Spp
- 8004300244 Responds to 800327 ltr ra nuclear energy after TMI NUREG~ 0642:addressing krypton venting encl W/o encl DENTON.HR Office of Nuclear Reactor Regulation, Director 80/05/08 2pp
- ---8006300270 Questions future of US nuclear energy program after TM1, Requests info on Kr-85 venting ΚΑΕULEN: S Affiliation Unknown 80/03/29 4pp

: 1

- 8006170250 Discusses NRC participation in 800514 panel discussion re cleanup or THI-2 reactor Chesapeake EPA deserves public appreciation for conducting discussion Opposes article which appeared pilot to meeting SHOER.B J
- 8006300224 FOIA request for written communications between NRC & Congress since 800322 concerning facility
 FIDELL.E R LeBoeuf, Lamb, Leiby 3 MacRae 80/05/21 1p
- 8004020039 Responds to encl 800403 itr to President Carter concerning safety of nuclear power plants Forwards TMI-2 Action Plan, implementing recommendations of President's Committee on TMI W/o encl YGUNGBLOOD, B J Licensing Branch 1 80/05/22 3pp
- 8004020126 Responds to 800374 itr to DDE expressing dismay at decision to reinstate licensing of nuclear power plants Criteria for improved safety have been developed following TMT-2 accident Every effort being made to ensure public safety DENION.H.R. Office of Nuclear Reactor Regulation, Director 80/05/22 1p
- 8004060224 Ack receipt of 800406 ltr to NRC commenting on NUREQ-0462 Comments from public state & local officials & federal agencies will be addressed in final environ assessment DENTON.H R Orfice of Nuclear Reactor Regulation, Director 80/05/22 lp
- 8004130364 Ack receipt of 800403 ltr to President Carter re concern that no action has been taken to make existing nuclear reactors safe Enci action plan implements recommendations & studies resulting from accident W/o enci YOUNGBLOOD, B J Licensing Branch 1 80/09/22 3pp
- 8006200500 Responds to 800428 ltr to President Carter re concern that safety of nuclear power is not being properly perceived from sys safety design standpoint NRC action plan responds to Presidential Commission rept on THI accident MATTSCN.R J Division of Safety Technology 80/05/27 5pp
- 8006200596 Responds to 800425 ltr to HR Denton requesting Heidelberg Rept NUREG-0662 & NUREG-0673 encl NRC comments in response to Heidelberg Rept will be issued in late June & may be purchased from GPO W/o encl SNYDER, B J TMI Program Office 80/06/03 1P
- --8004200599 Requests copies of Heidelberg Rept & EI8 study re TMI BOOKS.P A Affiliation Unknown 80/04/25 ip
- BOO6190634 Ack receipt of ltm supporting Kr-85 venting Analyses of alternatives to remove Kr-85 are complete Decision will be made promptly HEMDRIE.J M Commission 80/06/04 1p
- ---8006190644 Supports Kr-85 venting Plant should be cleaned up & maintained as soon as possible, to lower cost of electricity for customers
 SHANNON, M D Affiliation Unknown 80/06/03 ip
- 8006270046 Ack receipt of ltr supporting venting of Kr-85 from bidg atmosphere HENDRIE.J M Commission 80/06/04 lp
- --8006270052 Supports venting of Kr-85 from plant State of PA needs nuclear energy SHANNON M D Affiliation Unknown 80/06/03 1p
- 8006270115 Responds to 800410 ltr re J Shider telcon expressing concern about safe removal of krypton gas from reactor hldg Cyrogenic process would not be ready for operation for at least 20 months Decontamination should be expedited DIRCKS.W J Office of the Executive Director for Operations 80/06/05 3pp
- BOO6240168 Ack receipt of ltr expressing concern about delay in TMI-1 restart Commission ordered that TMI-1 remain in cold shutdown condition until further order by NRC & stated that public hearing be held prior to restart DENION, HR Office of Nuclear Reactor Regulation, Director 80/06/10 2pp
- BOO6300473 Responds to FDIA request for all written communications between NRC & Congress since BOO322 re facility Forwards documents referenced in App A Search for documents is still underway List of NRC correspondence to Congress encl FELTON.J M Division of Rules and Records BO/06/14 11pp.

- --8006300481 Forwards J Look 800407 ltr re loan of cryogenic processing sys to remove Kr-85 from facility reactor bldg Requests comments JL Gring 800401 ltr to Congress & response encl ERTEL.A E House of Rep 80703/18 5pp
- --8006300484 Forwards S Martin 800311 ltr re monitoring of radiation levels around facility Requests review & comment YATRON, Q House of Rep 80/04/14 2pp
- --80063004BB Responds to 800414 ltr to C Kammerer re B Martin 600311 ltr re monitoring of radicactivity levels around facility EPA & util monitor area around facility Lists responsible organizations to monitor releases if purging is authorized DIRCKS.W J Office of the Executive Director for Operations 80/06/03 2pp
- 8006300503 Forwards CW Hostetter 800327 request concerning hypothetical fuel melting accidents addressed in Recommendation D 4 of Kerneny Rept Requests review & comments KAMMERER. C Difice of Congressional Affairs 80/04/11 & Rep
- --8004300505 Forwards J Piccolo 800307 itr re purging of krypton from facility Requests review & comments
 GOODLING, B House of Rep 80/03/21 2pp
- --8006300510 Forwards E Conley 800416 ltr re possible relationship between doaths of several farm animals & farm location near facility Requests review & comments GOODLING.B House of Rep 80/04/16 3pp
- --8004300515 Forwards record of H Donley 800324 telcon re conflicting info about whether facility is in cold shutdown condition Requests review & comments GOUDLING: B House of Rep 80/04/17 2pp
- --8006300518 Forwards record of O Kelloy 800327 telcon re removal of krypton in reactor bldg by vacuum pumps & long-term storage in containers Requests review & comments ERTELIA E House of Rep 80/03/28 2pp
- ---8006300522 Forwards 800330 ltr re restoration of undamaged reactor at facility Requests review & comments SARBANES,P S Senate 80/04/15 App
- --8004300525 Forwards 800402 ltr re disposal of krypton gas from facility Requests review & comments GDODLING.B House of Rep 80/04/09 4pp
- --8006300527 Forwards H Donley 800321 request for info re release of radioactive gases at facility Requests review & comments SCHWEIKER,R S Senate 80/04/16 3pp
- --8006300534 Forwards 800415 ltr re NRC intentions to release 57.000 Ci Kr-85 from facility Requests review & comments 8CHULIE.R T Senate 80/04/22 7pp
- --B006300538 Forwards HB Hurst 800411 ltr re questions posed concerning proposed venting of Kr-85 from facility Requests review & comments HEINI.J Senate B0/05/09 5pp
- --8005300541 Forwards DE Mattaon 800417 ltr re animal problems & possible link to facility incident Requests review & comments HEINZ.J. Senate 80/05/14 4pp
- --8004300547 Forwards TA Behney, HW Fisher & E Arnold 800408 ltr to
 President re psychological & financial effects of THI
 accidents Requests comment RS Walker 800422 forwarding ltr
 encl
 SEAL, M M President of US & Executive Offices 80/05/12 5pp.
- --8005300551 Forwards CM Emerick B00425 ltr re venting of radiation from facility Requests review & comments HEINZ,J Senate 80/05/29 2pp
- ---8006300557 Forwards RC Oray B00521 ltr re issues concerning damaged reactor at facility Requests review & comments WALKER, R S House of Rep 80/05/28 3pp
- --8004300562 Forwards A Thompson B00218 ltr re delay in placing facility back in operation Requests review & comments PROXMIRE, W Benate 80/02/28 4pp
- --8006300565 Forwards PJ Schlundt 800229 ltr re facility restart Requests review & comments. HYDE.H J Senate, 80/03/03 2pp

- --8006300571 Forwards MK Shanten 800307 request for review of use of cryogenic traps & RJ Gray radiation monitoring program Requests review & comments ERTEL.A E House of Rep 80/03/13 3pp
- --800A200577 Request for action under 10CFR2 206 re installation of cryogenic traps prior to venting of radioactive gas from containment bldg GRAY,R J Affiliation Unknown 80/02/27 7pp
- BOOA300220 Additesponse to FOIA request for written communications between RRC & Congress since BOO3R2 concerning facility Forwards documents in App A FELTON.J H Division of Rules and Records BO/06/20 3pp
- --8006300231 Forwards announcement re ACRS 800408 technical meeting in Washington.DC to continue review of NRC study on whether equipment changes should be made on Bold plants Announcement will be sent to news media on 800325 M/o encl KAMMERER.C Office of Congressional Affairs 80/03/25 ip
- ~-8006300237 Forwards announcement re NRC appointment of BJ Snyder as program manager of facility cleanup operations W/o encl KAMMERER.C Office of Congressional Affairs 80/03/25 1p
- --B006300245 Forwards announcement re NRC publication of notice of availability for public comment of draft environ assessment concerning decontamination of facility reactor bldg atmosphere H/o encl KAMMERER.C Office of Congressional Affairs 80/03/26 ip
- --8006300254 Forwards announcement re ACRS 800409 meeting in Washington. BC to discuss implications of facility incident in relation to applications for CPs Announcement will be mailed to news media on 800326 W/o encl
 KAMMERER.C Office of Congressional Affairs 80/03/26 ip
- --B006300263 Responds to Subcommittee on Energy, Nuclear Proliferation & Federal Svcs 800312 ltr re OA Winter concern about facility restart delay Many problems must be resolved prior to restart Decision will possibly occur in late 1980 KAMMERER, C. Office of Congressional Affairs 80/04/01 2pp
- --8008300315 Ack receipt of 800325 ltr submitted on behalf of J Schmidt Rogavin rept is available for purchase by public at NRC, Sales Mot Ofc in Washington.DC KAMMERER,C Office of Congressional Affairs 80/04/02 1p
- --8006300321 Forwards announcement re NRC issuance for public comment of Addendum 2 to draft rept. "Environ Assessment for Decontamination TMI-2 Reactor Bldg Atmosphere " W/o encl KAMMERER,C Office of Congressional Affairs 80/04/02 ip
- --8006300326 Forwards announcement re V Stello confirmation that IE has been actively pursuing inquiries into allegations made by H Hartman, former facility control room operator H/o ancl KAMMERER, C Office of Congressional Affairs 80/04/17 ip
- --8006300337 Forwards announcement.w/attached NRC determination.that facility incident did not constitute ertraordinary nuclear occurrence as defined by Price-Anderson Act & Commission regulations N/o encl
 KAMMERER.C Office of Congressional Affairs 80/04/17 ip
- --8008300345 Forwards announcement re NRC approval of util plans to make manned entry into facility containment bldg H/o encl
 KAMMERER.C Office of Congressional Affairs 80/04/22 1p
- --B006300352 Responds to B00409 ltr re JL Gring concern about venting of radioactive gases from containment bldg Venting of radioactive trypton gas from containment bldg is not permitted until Commission holds public meeting KAMMERER, C Office of Congressional Affairs 80/04/25 ip
- --8006300354 Ack receipt of 800410 itr re J Mulligan suggestions concerning alternatives for dispusing of facility krypton gas Forwards NRC environ assessment considering alternatives for disposing of krypton gas H/o encl
 KAMMERER, C Office of Congressional Affairs 80/04/28 ip
- --BO06300339 Ack receipt of 800408 ltr re D Anzolut concerns about timing of venting of trupton gas from facility containment bldg No decision has been made re venting of krypton gas Commission has been notified of of D Anzolut concerns KAMMERER.C Office of Congressional Affairs 80/04/28 ip
- --B006300367 Forwards announcement re NABLB 800513 prehearing conference in Harrisburg:PA concerning proposed restart of facility W/o encl KANNERER.C Dffice of Congressional Affairs 80/05/01 1p

- --B00630042B Responds to 800423 postcard re EJ Sternglass paper, "Infant Mortality Changes Foliowing TMI Accident " Forwards analyses of radiobiological, epidemiological & physiological aspects of paper concluding that allegations are not valid KAMMERER,C Office of Congressional Affairs 80/05/02 ip
- --8006300431 Ack receipt of 800418 ltr re D Thumpson request for Regovin rept Rept can be purchased from GPO Sales Program at NRC in Washington DC or Natl Info Syc. Springfield, VA KAMMERER, C Office of Congressional Affairs 80/05/05 ip
- --8006300437 Ack receipt of 800415 ltr re 8 Denison concerns about facility NRC was not affiliated w/Presidential Commission or responsible for investigation findings Forwards W Stratton Study, "Alternative Event Sequences " W/o encl KAMMERER.C Office of Congressional Affairs 80/05/07 1p
- --8006300445 Forwards announcement re extension until 900516 for public comment on draft environ assessment for decontamination of reactor bldg atmosphere W/o encl KAMMERER, C Office of Congressional Affairs 80/05/08 ip
- 8006260150 Responds to 800508 itr re nuclear power in US after TMI No evidence exists linking hypothyroidism to radiation leak Supporting documentation encl DENTON H R Office of Nuclear Reactor Regulation, Director 80/06/23 2pp
- B006300450 Requests public hearing on Commission B00412 order for temporary mod of license Expresses concern re method of purging krypton gas
 D000LASIM H Affiliation Unknown 80/06/24 ip

I Financial information

- 8006170711 Forwards 780927 operating agreement & 701102 Memorandum of Agreement re sharing of facility const costs, between Met Ed, JCPL & Penelec GENTIEU.L P General Public Utilities GPU Service Corp 80/06/11 17ap
- 8006200371 Forwards "General Public Utilities Cash & Earnings Forecast.June 1980-Dec 1981" HERBEIN.J G Metropolitan Edison Co 80/06/16 19pp
- 8006240303 Forwards "General Public Utils Sys Cash & Earnings Forecast" for Jun 1980-Dec 1981 per teicon between util & NRC HERBEIN,J G Metropolitan Edison Co 80/04/16 2pp
- --8006240304 "General Public Utils Sys Cash & Earnings Forecast" for Jun 1980-Dec 1981 * Metropolitan Edison Co 80/06/05 18pp

J Insurance & indemnity information

- B006190033 Orants extension until B00601 for compliance w/Price-Anderson Act financial protection requirements DENTON-MR Office of Nuclear Reactor Regulation. Director 80/04/08 | Ip
- 8006030380 Confirms that, effective 790801, supplemental limit of ANI Policy NF-220 was extended in accordance w/800329 ltr to Marsh & McLennan Confirms that, effective 800601, liability limit will be restored Ltr to Marsh & McLennan encl QUATTROCCHI. J American Nuclear Insurers 80/05/29 3pp
- 800&090315 Confirms that effective 790501,MAELU has extended application of supplemental policy limit re TMI site in accordance u/provisions in oncl 800527 ltr 0'CONNELL,J M Mutual Atomic Energy Liability Underwriters 80/05/27 3pp
- 800A030411 Forwards Endorsement 36 to MAELU Policy MF-73 GERETY.H F General Public Utilities - GPU Service Corp 80/05/30
- 8004050344 Responds to NRC 800408 ltr re financial protection Nuclear liability insurance pools will provide twenty million dollars primary insurance for TMI-2 as well as reinstating that amount expended for claims & expenses HERBEIN, J Q Metropolitan Edison Co 80/05/30 3pp
- 800618040B Forwards 800612 ltr to M2M w/endorsements that pools propose to use binder to implement coverage contained in 800520 ltr to C Bollman Endorsements sent to NRC for consideration of financial protection at plant GUATTROCCHI, J American Nuclear Insurers 80/06/12 5pp

- 8006300676 Responds to 800530 ltr re compliance w/financial protection requirements for Unit 2 Since endorsement for addl \$20 million not received.NRC unable to determine compliance Info re alternatives to insulance requested SALTZMAN-J Utility Finance Branch 80/06/13 2pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7908290496 Forwards recommendations for studies to improve reactor sarety in areas of accident analysis reduction of accident probability, operating procedures review of design, const & operation, decay heat removal sys in ECCS & other items CARBON. M W ACRS Advisory Committee on Reactor Safeguards 79708/14 4pp
- 8006130181 Summary of ACRS Ad Hoc Subcommittee on TMI-2 Accident Implications 800409 meeting in Washington: DC re-accident implications as relating to CP applications List of attendees encl ACRS Advisory Committee on Reactor Safeguards 80/04/29 22pp
- P Operating license stage documents & correspondence
- 8006110503 Discusses need to upgrade reliability of power operated relief valve % to define function of valve Reliability can be improved % demonstrated by testing Studies would include input from NSSS vendor % valve manufacturer DIIANNI.D C Operating Reactors Branch 4 (Pre 800428) 80/02/19
- 8009130109 Submits info re LWR primary coolant sys pressure isolation valves as significant contributor to risk from Event 5 accidents Outlines data required to dotermine whether license should be modified EISENHUT. D. G. Division of Operating Reactors 80/02/23 60pp
- BOOG180577 Lists sys mods necessary to support fast purge of reactor bldg identified by licensee Estimate is optimistic Hydrogen control subsys preferred due to fewer mods required GREENBURG:M TMI Program Office BO/04/28 3pp
- 8004090091 Notifies that comment period for NUREG-0442 extended until B00514 Ack receipt of 800411 comments AHEARNE.J F Commission 80/05/05 1p
- ---8006690099 Requests extension of comment period to reflect UCS study on Kr-85 venting THORNBURGH, R Pennsylvania, State of 80/04/11 3pp
- 8006200529 Forwards A Ohki 800423 ltr recommending Hitachi staff member for temporary position w/Met Ed cleanup staff Response should be directed to A Ohki at Hitachi re F Nakashita participation LAFLEUR. J D Office of International Programs. Director 80/05/06
- ---8006200533 Ack receipt of 800212 ltr to M Hayakawa re TMI cleanup program Proposes sending F Nakashita as participant Background & qualification encl Requests details about cleanup program

 OHKI.A Japan 80/04/23 2pp
- 8006090100 Responds to 800321 ltr re util possible financial failure Financial failure provides grounds for license revocation No contingency plans completed to cover possibility of financial failure
 AMEARKE, J F Commission 80/05/07 2pp
- --8006090102 Inquires as to aftermath of util financial failure SHANAMAN,S M Pennsylvania, State of 80/03/21 2pp
- 8004090165 Forwards add1 TMI-2 related requirements to operating reactors Licensee requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8004020232 Responds to questions posed by JF Ahearne re proposed purging of facility containment bldg atmosphere Recommends that slow purging method be used to assure that doses to public are low DENION-HR Office of Nuclear Reactor Regulation, Director, SECY-80-1320 80/05/08 15pp
- 8006040047 "Decontamination of Kr-85 from TMI Nuclear Plant," rept to Governor of PA KENDALL,H W , REYEA,J , BRIDENBAUOH,D Union of Concerned Scientists 80/05/15 71pp

- BOOA040113 Requests drawings & specs for evaluation of EPICOR-II liners re waste handling storage, transportation & disposal Info & matls should be received by BOO530 to resolve matter Forwards BNL rept

 COLLINS.J T TMI Program Office BO/05/15 Spp
- ---B006040117 Forwards BNL rept re disposal of first stage EPICOR-II organic resin wastes Other reactor operators should be alerted for solidification efforts
 BROWNING.R E Division of Waste Management 80/05/03 2pp
- --B006040i1B Forwards "Status Rept on Leachability, Structural integrity & Radiation Stability of Ion Exchange Resins Sulidified in Cement & Coment W/Additives "
 SCHWEITZER IN C Brookhaves National Laboratory B0/05/05 ip
- --800&040ii9 "Status Rept on Leachability, Etructural Integrity & Radiation Stability of Organic Ion Exchange Resins Solidified in Cement & Coment Widditives "BARLETTA.R E. DAVIS.R E. & ONGWER.T E Brookhaven National Laboratory 80/05/31 24pp
- 8006020521 Advises that NRC will assess published repts & data re animal health effects in site vicinity Requests draft pathological symptoms rept by 800606 Paper will be used in larger rept being prepared by NRC MULLER.D R Assistant Director for Environmental Technology 80/03/16 ip
- 8006060349 Approves 800430 request to use Mine Safety & Appliances Cobreathing units in lieu of Bio Marine Bio Pak 60 units One entry may be made into reactor bldg Related correspondence COLLING.J T TMI Program Office 80/05/16 4pp
- --8006060351 Requests add1 info to complete review of 800410 rept on submerged demineralized sys by 800406 Related correspondence COLLINS.J T MI Program Office 80/05/16 9pp
- SOO6110510 Forwards request for addl info for evaluation of util BO0410 technical evaluation rept re submarged demineralised sys CQLLINS, J T TMI Program Office 80/05/16 9pp
- 8006i105i9 Responds to 800430 request for mod to reactor bldg re use of Mine 8afety & Appliances Co breathing units Grants approval to make 800520 entry into reactor bldg Local officals should be given early notification COLLINGIJT TRI Program Office 80/05/14, 4pp
- 8006020354 Forwards Vikem Industries 800803 memo re present status of fuel handling & auxiliary bldg decontamination program MENCINSKY: O J General Public Utilities — GPU Bervice Corp 80/05/19 17pp
- 8006130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Conlant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D. G. Division of Licensing 80/05/19 72pp
- 8006030137 Forwards staff rept. "Answers to Questions about Removing Krypton from TMI-2 Reactor Bldg " Rept responds in question-answer format to frequently asked questions about venting Kr-85 M/o encl SNYDER.B J THI Program Office 80/05/20 ip
- 8006070033 Forwards guidance for implementing 800407 interim criteria for radiological effluents from TM1-2 data gathering & maint operations SNYDER, B.J. TMI Program Office 80/05/20 3pp
- 80D&090036 Submits T Cochran 800507 statement re TMI-2 containment atmospheric cleanup Public health risks insignificant TRAVERS.W TMI Program Office 80/05/20 ip
- BOOA030325 Forwards "Analysis of Hypothetical Accidents Technical Evaluation Rept, Submerged Demineralizer Sys." App 1 calculations supporting statements in "Technical Evaluation Rept," Chapter 7 HDVEY. 9 K Metropolitan Edison Co BO/05/27 2pp
- ---8004030327 "Analysis of Hypothetical Accidents. Technical Evaluation Rept. Submerged Damineralizer Sys." App i * Metropolitan Edison Co 80/05/23 15pp
- 8006090369 Requests specific info for status & schedule of installation re implementation of more sensitive instrument for monitoring of RCS water chemistry & corrosion control COLLINS.J T TMI Program Office 80/05/27 4pp

- 8006120072 Act receipt of 800409 ltr describing cryogenic separation process for removal of Kr-85 from reactor bldg All contamination alternatives are being evaluated Proposal being considered as comment on NUREO-0662 SNYDER. 8 J TMI Program Office 80/05/27 ip
- --8006120075 Discusses cryogenic separation process developed for removal of Kr-85 from reactor containment bldg Basic process scheme is to link cryogenic air separation plant"to bldg atmosphere in closed recycle LYTTON, M Mitre Corp 80/04/09 8pp
- 800&030362 Forwards recovery operations plan Change Request 1 re elimination of BOP diesels & 13 2kv line surveillance requirements Request made subsequent to Tech Spec Change Request 22 HBVEY, G K Metropolitan Edison Co 80/05/28 5pp
- 80060\$0038 Forwards final version of Hittman Nuclear Development Corp "Resin Solidification Test Program for EPICOR II Resins" HOVEY. G X Metropolitan Edison Co 80/05/28 1p
- 8006090106 Informs that, since proposed cleanup sys not NRC approved, installation b purchase of equipment at util risk Contingency plan re transfer of untreated water to onsite tanks should be quickly completed DENTOW, HR Office of Nuclear Reactor Regulation, Director BO/05/28 4pp
- 9006120250 Advises that approval of submerged deminsralizer sys for decontaminating containment bldg water must be preceded by NRC programatic EIB Util should complete contingency plan to transfer untreated water to suitably shielded onsite tanks DENTON.H R Office of Nuclear Reactor Regulation, Director 890/05/28 5pp
- 8006050368 Recovery operation plan Tech Spec Change Request 1 re elimination of balance of plant diesels & 13 2 tV line surveillance requirements Replacement Pages 4 8-1 to 4 8-3 to plan encl HDVEY, G K Metropolitan Edison Co 80/05/29 3pg
- 8006050327 Revises submittal date to second quarter of 1981 for long-term solid radwaste staging facility recommendations Recommendations will be in form of design criteria document HOVEY, 8 K. Hetropolitan Edison Co. 80/05/30 ip
- 8004050380 Responds to NRC 800410 ltr re use of term "operable" as applied to single failure criterion for safety sys in power reactors Requests extension until 800930 for TMI-1 Tech Specs change No change required for TMI-2 HERBEIN, J G Metropolitan Edison Co 80/05/30 1p
- 8004040304 Responds to NRC 800515 request for info re design & matl for EPICOR II lines & resins info will be provided by 800430 KOVEY. G K. Metropolitan Edison Co. 80/05/30 lp
- B006090364 Responds to B00410 ltr re use of term operable applying to single failure criterion for safety sys in power reactors. Performing review of Unit 1 Tech Specs to determine need for mod Unit 2 operating under recovery Tech Specs. HERBEIN, J 0 Metropolitan Edison Co 80/05/30 2pp
- 8006110204 Notifies that date for submittal of recommendations for long-term solid radwasto staging facility, has been changed to second quarter.1981 HOVEY.Q K. Metropolitan Edison Co. 80/05/30 2pp
- 8006110317 Responds to 800515 ltr requesting info re design,matl & preparation of specific data concerning EPICOR-II liners & resins Info will be provided by 800630 HOVEY, 0 S Metropolitan Edison Co B0/05/30 2pp
- 9006200601 Ack receipt of Council Resolution 118 sent to Commissioner Absence Assures that resolution will be considered NRC is currently preparing final environ assessment of alternatives to decontaminating facility DENION, HR Office of Nuclear Reactor Regulation, Director 80/05/30 lp
- --8006200605 Forwards copy of Council Resolution 118, adopted 800327 Resolution memorializes Governor of PA & NRC to prevent further venting of radioactivity into environ H/o enci SCHWARTZ.G X Philadelphia PA 80/05/05 ip

- 800&240034 Provides add1 info re questions on NRC-proposed purging of containment bidg atmosphere Recommendations were given in BECY-B0-1320 Supplemental slow purge info encl DENTON, HR Office of Nuclear Reactor Regulation, Director SECY-B0-1320 80/03/30 3pp
- 8006020348 "Comparison of Controlled Purge & Application of Selective Absorption Process Alternatives for Decontamination of TMI-2 Reactor 31dg Atmosphere," preliminary draft THOMAS.C D., VOILLEQUE,P. G., CLINE,J. E. Science Applications, Inc 80/05/31 49pp
- 8006300187 "Environ Assessment of Radiological Effluents from Data Gathering & Maint Operation on TMI Unit 2" * TMI Program Office NUREG-0681 80/05/31 10pp Available at NTIS
- 8005110070 Notifies that filter housing purge test has been modified to add dynamic test w/rapid closing of inlet to filter housing w/automatic fan shut off functioning at negative 15 inches water gauge HDVEY, 6 K Metropolitan Edison Co 80/06/03 ip
- 8006:10300 Advises that filter housing testing program has been modified to add dynamic test w/rapid closing of inlet to filter housing w/automatic fan shutoff functioning at minus 15 inches water gauge HOVEY.G K Metropolitan Edison Co 80/06/03 2pp
- 8006110106 Advises that response to 800516 request, re submarged demineralizer sys technical evaluation rept, will be submitted by 800613

 HDVEY.O K Metropolitan Edison Co 80/06/04 1p
- 8006i101i4 Advises of intent to remove plant ventilation stack cap & discontinue use of supplemental ventilation sys atop auxiliary bldg on or about 8006i0 Airborne radioactivity lavels have decreased to point that sys no longer justified MDVEY.G X Metropolitan Edison Co 80/06/04 3pp
- 8006i10145 Forwards "Transient Boron Concentration Analysis in TMI-2 Mini-Decay Heat Removal Sys (MDHRS)," providing results of analysis of transient & steady state effects on boron concentration that can be anticipated w
- --B005110148 "Transient Boron Concentration Analysis in TMI-2 Mini-Decay Heat Removal Sys (MDHRS) " SHEU, J P. JASANI, K M Metropolitan Edison Co B0/09/23 18pp.
- 8006:10167 Forwards "Resin Bolldification Test Program." in response to 791221 ltr re proposed method for solidification of EPICOR-11 resins Progress summary & 800318 scope of work w/Hittman Nuclear & Development Corp encl HOVEY.6 K Metropolitan Edison Co 80/06/05 13pp
- ---B006110179 "Resin Solidification Test Program"

 * Metropolitan Edison Co 80/05/15 46pp
- BOD6120374 Forwards EPICOR-II soludification progress summary, description of scope of work w/Hittman Nuclear & Development Corp & Hittman rept, "Resin Soludification Test Program," per util 781221 commitment HOVEY.6 K Metropolitan Edison Co 80/06/05 13pp ,
- --8006120377 "Resin Solidification Test Program " ANSI/ASTM stds encl * Hittman Nuclear & Development Corp (subs Hittman Corp) 80/06/03 45pp
- 8006130256 Forwards "TMI-2 Planning Study for Phase II Reactor Internals Disassembly Fuel Removal & Sys Cleanup " Rept available in Central Files only LEHMAN'L J Metropolitan Edison Co BD/06/07 1p
- 8006170495 Forwards data re General Public Utils sys capabilities, peak load, reserve margins, net sys requirements & interchange RUNIE, W G General Public Utilities GPU Service Corp 80/06/11

.

1

- 8006230344 Advises that work efforts are proceeding on generating design criteria for interim solid radwaste staging facility Facility will provide area to assemble low level radwaste prior to offsite shipment Design will be submitted Jul 1980 HOVEY. G K Metropolitan Edison Co 80/06/12 ip
- 8006270290 Forwards Tech Spec Change Request 25, requesting amend to App A of License DPR-73 Amend doletes requirement for operationally functional interlock between HP-R-225 %/or HP-R-226 t purge exhaust dampers ARNDLD.R C Metropolitan Edison Co 80/06/23 3pp

- --8006270296 Application to amend License DPR-73.consisting of Tech Spec Change Request 25 Deletes requirement for operationally functional interlock between HP-R-225 b/or HP-R-226 & purge exhaust dampers Amend fee entl + Metropolitan Edison Co 80/06/23 2pp
- --8006270297 Proposed Tech Spec Change Request 25 re limiting conditions for operation of monitoring requirements 4 Metropolitan Edison Co 80/06/23 ip
- 8006300647 Confirms SW Porter 800623 telcon re change in TMI site discharge water composite sampling frequencies & requests that continuous composite sampling be changed from 4-h period to 24-h period HOVEY, G K Metropolitan Edison Co 80/06/25 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8006180059 Forwards Waste Packaging Insp Rept 80-24 on 800204-15 No
- --8006180082 Waste Packaging Insp Rept 80-24 on 800204-15 No noncompliance noted Hajor areas inspected compliance of waste shipments w/NRC & DOT regulations, including vehicle placarding & package marking & labeling PECK.C C. BOOK, H & Region 5. San Francisco, Fuel Facility & Materials Safety Branch 80/04/02 10pp
- 8006190157 Forwards Waste Packaging Insp Rept 80-04 on 800107-18 No noncompliance noted SMITH, G H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- ---8006:90169 Waste Packaging Insp Rept 80-04 on 800107-18

 No noncompliance noted Major areas inspected compliance of waste shipments w/NRC & DOT regulations including vehicle placarding, package conditions & marking & labeling PECK, C C Region 3, Chicago, Fuel Facility & Materials Safety Branch HUMMGR D. 800K, N E Region 5, San Francisco, Fuel Facility & Materials Safety Uranch 80/03/25 7pp
- 8006090155 Ack receipt of 800403 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-320/79-25 & 50-289/79-19 GRIER, B H Re BO/04/27 2pp Region 1. Philadelphia. Office of the Director
- --8006090157 Responds to 800205 ltr re violations noted in IE Insp Repts 50-320/79-25 t 50-289/79-19 Requests submittal of corrective actions re Item 2 Util 800205 ltr will be withheld (ref 10CFR2 790) GRICR, B H. Region 1, Philadelphia, Office of the Director 80/03/18 2pp
- --8004090140 Forwards IC Insp Repts 50-320//9-25 & 50-289/79-19 on 790914-21.24-28 & 1002-04 & notice of violation Notice of violation withheld (ref 10CFR2 790) MARTIN W G Region 1, Philadelphia, Safeguards Branch 80/01/14
- --8006090170 IE Insp Repts 50-320/79-25 & 50-289/79-19 on 790916-21,24-28 & 1002-04 Noncompliance noted licensee vehicle not escented in protected area & safety equipment on vital area physical barrier not meintained Details withheld (ref 100FR2 790) DEVLIN: J W Region 1, Philadelphia, Safeguards Branch LADUN: R H; SHEPHERD: R E Region 1, Philadelphia, Office of the Director 80/01/09 2pp
- 8006120259 Forwards response to IC Insp Rept 50-320/79-10 per 800306 meeting w/NRC Recovery mode surveillance procedures will be reviewed Access to high radiation areas controlled & emergency monitoring equipment placed at locations ARNGLD.R C Metropolitan Edison Co 80/05/19 23pp
- 8006200040 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/05/28, 1p
- 8004030359 Responds to NRC 800417 ltr re IE Bulletins for TM1-2 by providing guidelines for establishing short-term & long-term action on current & future bulletins
 HDVEY, Q K Metrapolitan Edison Co 80/05/29 Spp
- 8006090374 Forwards response to 800417 ltr re IE builetins Quidelines encl for establishing action on past & future bulletins Same builetins are undergoing further investigation & classification will be provided by 800603 HDVEY, C K Metropolitan Edison Co 80/05/29 Bpp

- 8004040111 Forwards util 800519 ltr directed to IE re civil penalty imposed on licensee
 SWARTZ,Lat Antitrust Davision 80/06/02 3pp
- --8006040112 Forwards plans for achieving corrective actions for items of noncompliance per util 800306 meeting w/IE re IE Investigation Rept 50-320/7910 Corrective actions for Unit 1 will be subj to schedule commensurate w/restart ARNOLD.R C Metropolitan Edison Co 80/05/19 23pp
- 8004170583 Informs NRC that util response to IE Bulletin 60-12, "Decay Heat Removal Sys Operability," will be provided by 800708 due to present workloads HOVEY.0 K Metropolitan Edison Co 80/06/09 2pp ent workloads Metropolitan Edison Co - 80/06/09 - 2pp
- BOO6300699 Responds to IE Bulletin BO-12, "Decay Heat Removal Bys Operability "Portions of short-term nature will be responded to by BOO70B Delay due to present workloads HOVEY. 6 K Metropolitan Edison Co BO/06/09 IP
- R Periodic operating reports & related correspondence
- 8004090040 Forwards Status rept for wk of 800510-17 COLLINS, J T TMI Program Office 80/05/19 4pp
- 8006020118 Forwards TMI Program Ofc status rept for wk of 800517-23 COLLINS, J T TMI Program Office 80/05/27 App
- 8006020275 Forwards liquid & gaseous effluent release repts for Mar 1980 & first quarter 1980 Tables 1-5 provide addl data for liquid discharges to Susquehanna River for 1980 Explanation of monthly summary included PCRTER.S W Porter-Gertz Consultants, Inc. 80/05/27 19
- --B006020303 Liquid & gaseous releases for Mar 1980 & first quarter 1980 Tables 1-9 provide addl date for liquid discharges into Susquehanna River for 1980 Explanation of monthly summary Porter-Gert: Consultants, Inc. 80/05/27 Bpp
- GOOG120029 Forwards TMI Program Ofc status rept for wk of 800517-23.
- 8004160165 Forwards status rept for wk of 800524-30 COLLINS, J T TMI Program Office 80/06/02 4pp
- 8006110103 EPA preliminary data rept on water sampling for 800522-30 COSTA, C F Environmental Protection Agency 80/06/03 ia
- 8006190690 Forwards status rept for wk of 800531-0606 COLLING.J T TMI Program Office 80/06/09 App
- BOO6250335 Forwards status rept for wk ending 800613 COLLINS.J T TMI Program Office 80/06/16 App
- S Reportable occurrences. LERs & related correspondence
- 7812270073 Confirms RO 78-71/1P on 781208 control logic discrepancy existed for make-up (HPE) pumps. KUNDER, O A Metropolitan Edison Co 78/12/11 1p
- 8006060197 PNO-TMI-80-029 on 800520, licensee plans to make first entry into reactor bldg Personne! afflock will be purged on 800519 in preparation for entry Estimated airlock purge will release approx 25 Ci Kr-85 to environ KALMAN, C. FASANO, A. COLLING, O. Region 1, Philadelphia, Office of the Director 80/03/16 ip
- BOOG160144 RO BO-19/1P condition exists where in once-through steam generator level transmitter B is inoperable Probably caused by plugged leg line Effort underway to correct problem HOVEY, O K Metropolitan Edison Co BO/08/19 ip
- 8006060206 PND-TMI-80-030 on 800520, licensee attempted to enter reactor bidg for first time since 790328 accident Procedure was terminated after repeated attempts failed to open inner door Probable causes include corrosion & suction, CONTE.R J , FASANO.A N , COLLINS, J T Region 1: Philadelphia, Office of the Director 80/05/21 ip
- 8004030459 RO 80-20/1P on 800520, small purge valve opening on outer hatch bulkhead technically violated containment integrity. Caused by procedural error Valve closed & procedures will be revised HOVEY. G K Metropolitan Edison Co BO/05/23 3pp

- BOOG130219 PNO-TMI-80-031 on BOO520, licenses determined that containment integrity not maintained for period of 2-5 minutes Caused by purge valve on outer door left open, permitting flow from atmosphere into reactor bldg CONTE.R J . SHANDAKY, M M . COLLINS, J T Region 1, Philadelphia, Office of the Director 80/05/23 ip
- 8006130226 PNO-TMI-80-032 on 800523 worker experiencing chest pains laft site in ambulance Diagnosis was possible heart attack Unknown if individual was in radiological area CONTER J. SHANBAKY.M M. COLLING.J T Region 1. Philadelphia, Office of the Director 80/05/23 ip
- 8006030465 Forward: LER 80-015/03L-0 HDVEY: 0 K Metropolitan Edison Co 80/05/28 ip
- --8006030472 t.ER 80-015/03L-0 on 800428 boric acid mix tank boron contentraction exceeded Tach Specs Caused by concentrating effects from evaporation due to use of air sparger mixing apperatus Hater added & use of air sparger discontinued CHAPLIN.8 D Metropolitan Edison CO 80/05/28 2pg
- 8004040263 Porwards LER 80-014/03L-0 HQVEY.O K Metropolitan Edison Co 80/05/30 1p
- --8006080271 LER 80-016/03L-0 on 800501, during recovery mode operation, fuel oil tank level found below Tech Spec requirement Caused by misrecording of level during previous check Oil added & insp frequency increased CHAPLIN.S D Metropolitan Edison Co 80/05/30 2pp
- BOO6160024 Forwards LER BO-018/03L-0
 HBVEY.G K Metropolitan Edison Co BO/06/10 lp
- --8006160027 LER 80-018/03L-0 on 800509, while loading white belance of plant diesel generator, oscillations observed in generator frequency, followed by total loss of frequency indication Caused by mechanical shock blowing two fuses Fuses replaced CHAPLIN.S D. Ketropolitan Edison Co. 80/06/10 lp
- 9006250189 PNO-V-80~050 on B00610, of 12B drums of 1cm level radwaste received one had broken locking ring & four had loose locking rings No significant radioactive contamination MA cancelled burjal permit & banned util from use of site THOMAS.R D Region 5, San Francisco, Office of the Director 80/06/10 lp
- 8006230324 Forward* LER 80-019/01L-0 HOVEY, 0 % Metropolitan Edison Co 80/06/17 ip
- --8006230335 LER 80-019/01L-0 on 800518 during recovery mode, 8 once through steam generator level instrumentation became imperable Apparently caused by dirt in root valve Sensing line backflushed returned to see on 800528 CHAPLIM.S B Metropolitan Edison Co 80/06/17 2pp
- 8006240504 Forwards LER 80-022/032-0 HOVEY, 9 K Metropolitan Edison Co 80/06/17 1m
- --w006240510 Lkm MU-0R2/03Z-0 on 800518 during recovery mode operation fuel handling bidg exhaust flow discovered below limit Caused by failure of universal coupling on manual inlet dapper for fans AH-E-10A & B causing damper to close.

 CHAPLIN.S D Metropolitan Edison Co 80/06/17 2pp
- T Hearing transcripts on non-antitrust matters
- 8006160205 Transcript of 800521 public meeting in Washington, DC re TMI-2 action plan Pp 1-74 \star Commission 80/05/21 75pp
- 8005180633 Transcript of 800605 public meeting in Washington, DC re TMI venting Pp 1-79 # Commission 80/05/05 114pp
- 8006250194 Transcript of 800615 Affirmation Session 80-28 re TMI action plan in Washington DC Pp 1-4 Commission 80/06/15 4pp
- .W. Congressional/Executive Correspondence
- 8006120110 Ack receipt of 800508 & 09 ltrs providing availability list of critical components for selective absorption sys & assessment of min time needed to install sys at facility for Kr-B5 removal itrs will be considered w/related comments AHEARNE.JF Commission 80/05/14 ip

- --8006120114 forwards availability list of critical components for selective absorption sys & assessment of min time needed to install sys at facility for Kr-85 removal, discussed in rept prepared by Committee & NASA ERTEL, A E House of Rep. Science & Technology 80/05/08 3pp
- --8006120117 Comments on Kr-85 removal time requirements identified by KRC overstated Selective absorption sys discussed in encl memo could be installed & operating within & months ERTEL, A E House of Rep , Science & Technology 80/05/09 App
- 6006200087 Submits requested info for 800522 hearing re TMI-2 cleanup Congressman Ertel 800515 ltr is incorrect in stating that MiTRE proposal was never afforded serious consideration by NRC Chronology of NRC cleanup actions being prepared SNYDER: 8 J TMI Program Office 80/05/19 3pp
- --B006200091 Recommends that necessary preparations begin so that Citizens'Advisory Panel for consulting & advising NRC on decontamination & decommissioning of TMI-2 can be established Proposed legislative amend encl KOSTMAYER, P. H., UDALL, M. K., LUJAN, M. House of Rep. B0/05/13 Spp.
- 8006130170 Ack receipt of 800515 ltrs commenting on rept to Governor of PA on Kr-85 removal methods & providing Mitre Corp proposal for cryogenic separation process Concerns & info will be considered w/public comments prior to final decision AHEARNE, J. F. Commission 80/05/29 1p
- --9006130173 Discusses rept to Governor of PA re Kr-85 removal methods Rept should help NRC in decision method for Kr-85 removal ERTEL.A E House of Rep . Science & Technology 80/05/15 2pp
- ---9006130176 Forwards discussion on possibility of expediting installation & use of cryogenic process possibly applicable for removal of Kr-85 from reactor Rept should be given fair consideration ERTEL.A E House of Rap . Science & Technology 80/05/15 2pp
- DOCKET 50-321 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8006070487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFRSO & is expected to be published in FR by end of May EISENHUT, b G Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 b new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 Itr Page 14a not encl EISENRUT.D 6 Division of Licensing 80/05/92 73pp
- 8006030241 Forwards revised guard training & qualification plan Plan withheld (ref 10CFR2 790) WIDNER, N A Georgia Power Co 80/05/28 1p
- 8006240582 Requests review of emergency plan against evaluation criteria of NUREG-0654 Addl info required before Emergency Preparedness Review Team can conclude that program is acceptable Revised plan should be provided by 800718 REID.R W. Operating Reactors Branch 4 80/06/06 2pp
- I Financial information
- BOO6170310 Forwards Annual Financial Repts 1979 WIDNER, W.A. Georgia Power Co. 80/06/11 1p
- --8006170314 Annual Financial Rept 1979 * The Southern Co 80/03/10 43pp
- --8006170318 Annual Financial Rept 1979 * Georgia Power Co 80/02/28 38pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07 150pp

- 1006030514 Summary of 8004P2-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis I testing programs concerning Mark I containment long-term program GRIMES C I Assistant Director for Plant Systems B0/05/09 Spp
- BOO6130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Yearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule enc! ETSENHUT, D G Division of Licensing 80/05/19 72pp
- 8006060376 Advises that response to 0E generic analysis re effect of dc power supply Failure on ECCS performance will be provided by 800606 per NRC 800425 request WIDNER.WA Georgia Power Co. 80/05/30 ip
- 8006110239 Forwards unique analysis rept comparing effects of ac power failure of ECCS performance w/GE generic analysis WIDNER, W.A. Georgia Power Co. 80/06/03 opp
- BOOG300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREO-0619, "BWR Feedwater Nozile & Control Rod Drive Return Line Nozile Cracking " Comments will be evaluated by NRC prior to final implementation U/o enci EISENWUT, D O Division of Licensing 80/06/05 22pp
- 800.6170640 Submits info re turbine rotor disc cracking in response to NRC 800513 request Unit 1 has experienced approx 81 turbine trips 8 approx five overspeeds Unit 2 has experienced approx 52 turbine trips & approx two dverspeeds HIDNER.N A Georgia Pawer Co 80/06/10 4pp
- 8006240193 Forwards Amend 76 to License DPR-57, safety evaluation & notice of issuance & availability
 REID,R W Operating Reactors Branch 4 80/06/10 2pp
- --8004240203 Amend 76 to License DPR-57, changing Tech Specs to remove current restriction on operating limit min critical power ratios REID.R W. Operating Reactors Branch 4 80/06/10 Bpp
- --B00624020B Safety evaluation supporting Amend 76 to License DRF-57 * Office of Nuclear Reactor Regulation, Director B0/06/10 19pp
- --8004240212 Notice of issuance & availability of Amend 76 to License DPR-57 REID.R W Operating Reactors Branch 4 80/06/10 2pp
- BOO6250269 Forwards Amend 75 to License DPR-57 % notice of issuance & availability REID.R W Operating Reactors Branch 4 BO/06/10 3pp
- ---8006290271 Amend 75 to License DPR-57, requiring diesel fuel sampling at least once every 92 days REID.R W Operating Reactors Branch 4 80/06/10 5pp
- --8006250274 Notice of issuance & availability of Amend 75 to License PPR-57 REID.R W Operatino Reactors Branch 4 80/06/10 2pp
- 8006300221 Forwards draft NRC licensing position, "Safety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating repts REID, R W Operating Reactors Branch 4 80/06/12 10pp
- Q Inspection reports. If Bulletins & correspondence
- 8006200095 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/18
- BO06170767 Forwards IE Insp Repts 50-321/80-12 & 50-346/80-12 on BO0310-19 & notice of violation STOMR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/04/22 app
- --8006170772 Notice of violation from insp on 800310-19 * Region 2. Atlanta, Office of the Director 80/04/22 1p

- ---8006170775 IE Insp Repts 50-321/80-12 & 50-366/80-(2 on 800310-19 Noncompliance noted failure to start environ monitoring when required JENKINS, G Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM A L, MACARTHUR, T C Region 2, Atlanta, Office of the Director 80/04/22 7pp
- B006170779 Forwards IE Insp Repts 50-321/80-15 & 50-364/80-15 on B00402-04 No noncompliance noted MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Bupport Branch B0/04/30 2pp
- --8006170784 IE Insp Repts 50-321/80~15 & 50-366/80-15 on 800402-04 No noncompliance noted Major areas inspected installed equipment per IE Bulletin 79-01B response CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARDWICK.R J Region 2. Atlanta. Office of the Director 80/04/29 App
- 8006060575 Forwards (E Bulletin 80-11, "Masonry Hall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 200
- B006040226 Forwards IE Bulletin B0-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl D'REILLY.J P Region 2, Atlanta, Office of the Director B0/05/09 2pp
- 8006249066 Forwards IE Insp Repts 50-321/80-21 & 50-366/80-21 on B00419-18 No noncompliance noted LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/12 2pp
- --8006240071 IE insp Repts 50-321/80-21 & 50-366/80-21 on 800415-18 No noncompliance noted Major areas inspected surveillance activity on pipe support & restraint sys.procedure test results.installed restraints & records

 UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch JOHNSON.A H Region 2. Atlanta, Office of the Director, 80/05/06 Jpp
- 8006130018 Requests info re ultrasonic insps of low pressure turbines to learn more about underlying reasons for indications found & probable rate of growth, indications & effects on turbine disc integrity
 REID,R W Operating Reactors Branch 4 80/05/13 3pp
- 8006300119 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REJLLY, J P Region 2. Atlanta. Office of the Director 80/05/13 200
- 8006170337 Informs NRC that limit switches used for position indication were not included in 45-day response to IE Bulletin 79-018 Environ qualification of switches should be addressed AE is in process of specifying qualified replacement switches MANRY, M Georgia Power Co 80/05/15 ip
- 8006090528 Ack receipt of 800428 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80-06 & 50-366/80-06 LEWIS R C Region i, Philadelphia, Reactor Operations Nuclear Support Branch 60/05/21 1p
- --B006090535 Responds to NRC 800331 ltr re deviations noted in IE Insp Repts 50-321/80-06 & 50-366/80-06 Corrective actions revised Procedures HNP-1 & 2-1902 & HNP-1 & 2-1904 to delineate immediate operator action section WIDNER, W A Georgia Power Co. 80/04/28 2pp
- --800A090540 Forwards IE Insp Repts 50-321/80-06 & 50-366/80-06 on 800219-21 & notice of deviation LEWIG.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/31 2pp
- ---8006090542 Nutice of deviation from insp on 800219-21.
 * Region 2, Atlanta, Office of the Director 80/03/28 ip
- --8006090547 IE Insp Repts 50-321/80-06 & 50-366/80-06 on 800219-21.
 Noncompliance noted failure to ensure that licensed operators have committed to memory immediate emergency procedure actions
 KELLOGG,P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch SAUER,R C , ROGERS,R F Region 2, Atlanta, Office of the Director 80/03/28 Spp

- 8006250072 Summarizes responses to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" Based on GE estimate for completion of review of GE-supplied equipment.complete response will be submitted by 810403
 HIBNER.W A Georgia Power Co 80/05/22 900pp
- 8006090408 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-13 & 50-365/80-13 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/23 ip
- ---8004090415 Responds to NRC 800421 ltr re violations noted in IE Insp Repts 50-321/80-13 & 50-366/80-13 Corrective actions project plan reviewed & found acceptable & personnel performing insp certified WIDNER.W A Georgia Power Co 80/05/09 2pp
- --8006090422 Forwards IE Insp Repts 50-321/80-13 & 90-364/80-13 on 800311-14 & 25-28 & notice of violation MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/21 2pp
- --8006090427 Notice of violation from insp on 800311-14 & 25-28

 * Region 2. Atlanta, Office of the Director 80/04/17 ip
- ---B006090435 IE Insp Repts 50-321/80-13 & 50-366/80-13 on 800311-14 & 25-28 Noncompliance noted failure to approve inservice insp plan & failure to certify welding & NDE inspectors HERDIAR R. CRIMLEY, B. R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/04/17 9pp
- 8006180317 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-321/80-11 t 50-326/80-11 LRHIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/02 lp
- --B004180323 Responds to NRC 800429 ltr re violations noted in IE Insp Repts 50-321/80-11 & 50-346/80-11 Corrective actions control rod movement procedures revised & large scale drawings replaced w/microfilmed prints in control room HIDNER: W A Georgia Power Co 80/05/27 4pp
- --8006180327 Forwards IE Insp Repts 50-321/80-11 & 50-366/80-11 on B00202-0307 & notice of violation O'REILLY.J P Region 2, Atlanta, Office of the Director B0/04/27 2pp
- --8005180332 Notice of violation from insp on 800202-0307
 * Region 2. Atlanta, Office of the Director 80/04/15 3pp
- --8006:80338 IE Insp Repts 50-321/80-11 & 50-366/80-11 on 800202-0307 Noncompliance noted failure to operate RSCS properly to limit rod motion w/RSCB inoperable to evaluate procedure change & to provide updated plant drawings in control room RDOERS;R F Region 2. Atlanta, Office of the Director DANCE,H (Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/15 9pp
- B006230210 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-321/80-18 & 50-326/80-18
 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 ip
- --8006230218 Responds to NRC 800430 ltr re violations noted in IC Insp Repts 50-321/80-18 & 90-366/80-18 Written & approved functional test was not necessary because operability could have been demonstrated through existing plant procedures HIDNER: H A Georgia Power Co 80/05/27 2pp
- --8006230222 Forwards corrected cover page for IE Insp Repts 50-321/80~18 & 50-366/80-18 on 800331-0402 LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/08 tp
- --8006230226 Corrected cover page for 1E lnsp Repts 50-321/80-18 & 50-366/80-18 on 800331-0402 LEHIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/08 Ip
- ---8004230228 Forwards IE Insp Repts 50-321/80-18 & 50-344/80-18 on B00331-0402 & notice of violation LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/04/30 2pp
- ~-8006230232 Notice of violation from insp on 800331-0402
 * Region 2, Atlanta, Office of the Director 80/04/30 in

- --8006230237 IE Insp Repts 50-321/80-18 % 50-366/80-18 on 800331-0402 Noncompliance hoted failure to perform post-mod testing DANCE,H C , BURNETT,P T Region 2. Atlanta, Office of the Director 80/04/30 4pp
- 8006290245 Ack receipt of 800514 % 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-03, 50-346/80-04 % 50-366/80-16 KENNA,W B Region 2, Atlanta, Safeguards Branch 80/06/11 1p
- --8006250249 Responds to NRC 8004(8 ltr re violations noted in IE lnsp Repts 50-321/80-03 % 50-366/80-03 Requests that 800514 ltr be withheld (ref 10CFR2 790) WIDNER, W A Georgia Power Co 80/05/29 ip
- --8006250250 Forwards IE Insp Repts 50-321/80-03 & 50-366/80-03 qn 800107-11 & notice of violation Notice of violation withheld (ref 10CFR2 790) 87REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/18 2pp
- --B006250254 IE Insp Repts 50-321/B0-03 & 50-366/B0-03 on 800107-11
 Noncompliance noted failure to follow procedures for
 documenting security incidents & to perform vital area
 patrols as committed Details withheld (ref 10CFR2 770)
 TOBIN:W J Region 2, Atlanta, Safeguards Granch PERNY, C D
 Region 2, Atlanta, Office of the Director 80/04/08 ip
- --8006250258 Forwards IE Insp Repts 50-321/80-16 t 50-366/80-16 on 800326-28 t notice of violation Notice of violation withheld (ref 10CFR2 770) KENNA, U B Region 2. Atlanta, Safeguards Branch 80/04/29 2pp
- ---B006250264 IE Insp Repts 50-321/B0-16 & 50-366/B0-16 on B00326-28
 Noncompliance noted failure to control all points of
 personnel access into vital areas & to maintain lighting
 equipment as committed Details withheld (ref 10CFR2 790)
 GILLESPIE.F P Region 2, Atlanta, Safeguarda Branch TILLMAN, A,
 PERNY, C D Region 2, Atlanta, Office of the Director 80/04/29
- BOD6240296 Responds to 1E Bulletin BO-06. "Engineered Safety Feature Reset Controls " Discusses automatic depressurization sys & hydrogen & oxygen analyzer sys Forwards details of functional tests & sys testing frequencies per Tech Specs WIDNER, W A Georgia Power Co 80/06/12 Spg
- 8006240325 Responds to Item 2 of IE Bulletin 79-27 Emergency procedures re loss of dc busses & loss of essential vital & instrument ac busses exist Revisions & new procedures re loss of hon-essential ac busses placed in effect
 WIDNER, N A Georgia Power Co 80/06/17 2pp
- R Periodic operating reports & related correspondence
- 8006180438 Forwards monthly operating rept for May 1980 MANRY, M Georgia Power Co 80/06/10 ip
- --8006180439 Monthly operating rept for May 1980 RODEN, J W Georgia Power Co 80/06/10 14pp
- S Reportable occurrences, LERs & related correspondence
- 8004050347 Forwards LER 80-043/03L-0 MANRY,M Georgia Power Co 80/05/20 ip
- --B006050373 LER B0-043/03L-0 on B00503,while at steady state power, torus air 3 water temp recorder was discovered to be stamping erratic & upscale Caused by faulty balancing motor in recorder Malancing motor replaced 4 Georgia Power Co 80/05/23 2pp
- 8006030413 Forwards LER 80-045/01T-0 MANRY.M Georgia Power Co 80/05/22 1p
- --8004030432 LER 60--045/01T-0 on 800510, while operating RHR syc water pump, 1E11-C001B, major bearing cooling water supply valves to pumps A & B found closed Caused unknown Valves for all four pumps locked open BAXLEY, B X Georgia Power Co 80/05/22 2pp
- 8006030458 Forwards LER 80-044/03L-0 MANRY,M Georgia Power Co 80/05/22 1p

```
--8006030462 LER 80-044/03L-0 on 800506.during normal full power
          DUBOSU462 LER BU-V44/UJL-V on BUU305 during normal full power operation primary containment oxygen concentration exceeded allowable limit Caused by operator failure to initiate dinitrogen makeup to drywell prior to reaching limit a Georgia Power Co 80/05/22 2pp
```

8006£303Bi PNO-II-80-095 on 80052A, facility shut down to repair leakage past seat of LPC! valve Licensee previously closed adjacent valve to stop leakpe TAYLOR, P.A., DANCE, H.C. Region 2. Atlanta. Office of the Director 80/05/27 ip

800.6230548 RO 50-321/1980-053 on 600524, discovered that loss of essential motor control ctr 18(R24-5011) or loss of diesel generator 14 during loss of offsite power will cause RHR & core spray A loops to be inoperable Caused by faulty valve MANRY, M Georgia Power Co 60/05/27 2pp

8006050347 Forwards LER 80-048/03L-0 MANRY.M Georgia Power Co 80/05/29 1p

--8006050349 LER 80-048/03L-0 on 800509, while performing ASME inservice pump operability test on plant svc water pump 18, discovered that max attainable flow was 3600 gpm Caused by faulty pressure indicator on pump discharge * Georgia Power Co 80/05/29 2pp

8006230574 RO 50-321/1980-054 on 800530 nondivisional cables H21-P173-C010 & H21-P173-C013 found routed w/div I & II type cables/raceways Caused by design & installation error Design Change Request 80-166 submitted for cable rerouting MANRY.M Georgia Power Co 80/05/30 1p

8006070327 Forwards LER 80-047/03L-0 MANRY.M Georgia Power Co 80/06. 80/06/02 1p

--B006070333 LER 80-047/03L-0 on 800404, during review of normal surveillance testing data sheets, RHR pumps A & C flow rate did not neet Tech Spec requirements Cause not stated RHR pump surveillance procedure will be revised BAXLEY, S X Georgia Power Co 80/06/02 2pp

800.6230522 RG 30-321/1980-055 on 800531, snubber 36 on X32-1F7, i-inch instrument line from recirculation A loop, appeared locked up during visual insp Caused by snubber corrosion Snubbers failing surveillance test will be replaced prior to startup MANRY, M Georgia Power Co 80/06/02 2pp

8006170674 Forwards LER 80-050/03L-0 MANRY,M Georgia Power Co 80/06/03 tp

--8006170680 LER 80-050/03L-O on 800514, while performing reactor startup, reactor core isolation cooling turbine tripped while attempting manual start Cause unknown Trip may have been due to overspeed Special committee will perform in-depth study NIX.R T Georgia Power Co 80/06/05 2pp

8006170673 Fowards LER 80-093/01T-0 MANRY, M Georgia Power Co 80/06/04 1p

--8006170677 LER 80-053/01T-0 on 800524, during normal operation, discovered that loss of power to essential motor control ctr 18 w/recirculation discharge line break would render both loops of RHR & loops of core spray inoperable CQQOIN.C L Georgia Power Co 80/06/06 2PP

B006190578 Forwards LER 80-051/03L-0 MANRY, M Georgia Power Co 80/06/09 1p

--8004190588 LER 80-051/03L-0 on 800514.while investigating tubing layout, run of tubing that lapes into primary containment not supported seismically as required Caused by installation error Tubing will be resupported per seismic specs COGGIN.C L Georgia Power Co 80/06/08 2PP

6006170566 Forwards LER 80-054/01T-0 MANRY, M Georgia Fower Co 80/06 80/04/10 1p

--8006190574 LER 80-054/01T-0 on H00529, while repairing RHR inboard injection valve, engineering staff confirmed that cable separation problem existed re containment atmospheric control sys Caused by design 3 installation error COGGIN.C L Georgia Power Co 80/06/10 2pp

8006190607 Forwards LER 80-052/03L-0 MANRY, M Georgia Power Co 80/04/11 1p

--8006190619 LER 80-052/03L-0 on 800520, during unit startup, HPCI pump was in progress prior to declaring HPCI operable Caused by defective ramp generator on Woodward turbine controls Ramp generator & EGM control box replaced NIX,R T Georgia Power Co 80/06/11 2pp

8006200441 Forwards LER 80-055/01T-0 MANRY, M Georgia Power Co 80/06/11 1p

---8004200447 LER 80-055/01T-0 on 800531.w/Unit 1 in cold shutdown insp of mechanical snubbers was performed 2 45 out of 61 snubbers werp found locked up Caused by internal corrosion Snubbers Georgia Power Co 80/06/11 2pp

8006230580 RD 50-321/1980-062 on 800612.w/facility in cold shutdown. Investigation began to determine cause of payement deflection which occurred beneath crane outrigger pad at intake structure Cause of fill separation from pipe unknown MANRY, M Georgia Power Co 80/06/12 2pp

8006200452 Forwards LER 80-057/03L+0 MANRY,M Georgia Power Co 80/06 80/06/13 ip

~~8006200461 LER 80-057/03L-0 on 800525, while performing procedure UNAZONASI LER BUTUST/VOLTO UN UNOSCIMITE PERFORMING PIT HNP-1-114 RHR shutdown cooling mode shutdown cooling suction volve failed to open Caused by Faulty auxiliary contact block Contact block replaced NIX,RT Georgia Power Co 80/06/13 2pp

8006300344 EN-80-23 notice of violation & notice of proposed imposition of civil penalty will be issued on or about 800617 Action based on alleged noncompliance re radiation levels in truck cab Will issue news release BROCKETT.T W. THOMPSON.D Diffice of Inspection & Enforcement, Office of the Director 80/06/17 lp

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

BOO6230110 Advises BWR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria entl EISENHUT.D G Division of Licensing BO/05/20 13pp

BOO6090839 Notification of BOO613 meeting w/util in Bethesda.MD to discuss specific T-quencher load definition WILSON,J H Licensing Branch 1 BO/05/29 App

8006230001 Summary of 800410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU,T M Containment Systems Branch 80/05/30. App

HOD6200067 Forwards requests for add1 info to complete review of application H/o encl
YOUNDBLOOD B J Licensing Branch 1, 80/06/02 ip

BOO6180007 Summary of BO0508-09 meeting w/util in Long Island.NY restatus of facility const WILSON.J N Licensing Branch 1 BO/06/03 App

8004300047 Forwards "For Comment" edition of NUREG-0617, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Rept provides NRC resolution of Generic Technical Activity A-10 W/A encl EIBENHUT.D Q Division of Licensing 80/06/04 3pp

B006170261 Forwards responses to NRC 790327 & 800303 info requests
Info provided to be included in future FSAR amend
NOVARRO, J P Long Island Lighting Co 80/06/09 30pp

800618062; Notification of 800613 meeting w/BWR Licensing Resolution Group in Bethesda,MD to discuss progress WILBON.J N Licensing Branch 1 80/06/09 10pp

8006250321 Summary of 800514 meeting w/utils in Bethesda: HD re organization & objectives of BNR licensing resolution group Agenda & Viewgraph enci WILBON.J N Operating Reactors Branch 4 80/06/17 11pp

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8006270040 FES for facility * Office of Nuclear Reactor Fegulation, Director NUREG-0285 77/10/31 265pp Available at NTIS
- F Security, medical, emergency & fire protection plans
- BOO5130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT, D.Q. Division of Operating Reactors 80/04/25 61pp
- G Adjudicatory correspondence
- 8006130020 Notice of appearance in proceeding Certificate of Svc encl QILMARTIN,D J Suffolk County, NY 80/05/05 3pp
- BOOGOGOZTO Forwards ASLB BOOSSO memorandum & order re TMI-1 hydrogen control contentions & NRC FR notice on interim policy statement re nuclear power plant accident considerations under NEPA W/o encls
 BORDENICK, B M. Hearing Branch 4 BO/O6/04 is
- 8006090242 Forwards documents on loan basis in response to request to assist MM Goldsmith in developing Suffolk County position on certain contrations W/o encl BGRBENICK.B M Hearing Branch 4 80/06/05 5pp
- 8006110311 Forwards NUREG-0860. "NRC Action Plan Developed as Result of THI-2 Accident." Vols 1 & 2. to be used for Shoreham Opponents Coalition Contention 7 M/o encl BORDENICK, 8 M Rearing Branch 4 80/06/06 1p
- 800.6190570 Forwards Shoreham Opponents Coalition & NRC stipulation in response to ASLB 800421 order granting extension until 800606 for intervenor to submit particularized contentions Stipulation contains request for add
- 8006130159 Forwards NRC, util & intervenor Suffolk County 800610 third atipulation re certain Suffolk County contentions BORDENICK, B M Hearing Branch 4 80/06/il ip
- --8006130162 Third stipulation re certain Suffolk County contentions
 Specifies contentions that have been resolved contentions
 that have been merged & contentions that are retained,
 pending NRC action
 DEMPSEV.P Suffolk County, NY REVELEY,WT Long Island Lighting
 Co BURDENICK.BM Hearing Branch 4 80/06/10 3pp
- 8006160083 Forwards first stipulation re Shoreham Opponents Coalition contentions & request for add1 time BORDENICK, B. K. Hearing Branch 4 BO/06/12 2pp
- --B005160087 First stipulation re Shoreham Opponents Coalition contentions & request for addit time Particularizes certain contentions Further meeting necessary to formulate others. Requests 60-day extension to reach final agreement LAYHAM. B B Shoreham Opponents Coalition BORDENICK. B M Hearing Branch 4 80/06/12 7pp
- H General correspondence
- 8006300425 Requests verification of address Related correspondence REVELEY, W T Hunton & Williams 80/06/12 ip
- M Antitrust correspondence
- 8006500246 Requests update of antitrust info per encl Reg Guide 9 3 SALTIMAN, J Utility Finance Branch 80/06/16 ip
- @ Inspection reports. IE Bulletins & correspondence
- 9006030093 Forwards IE Insp Rept 50-322/80-04 on B00218-0323 No noncompliance noted BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 80/04/17 2pg

- B006250202 Forwards IE lnsp Rept 50-322/80-05 on 800317-20 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8006250205 IE Insp Rept 50-322/80-05 on 800317-20 No noncompliance noted Major areas inspected observation of work, review of quality records & action on previous insp findings MCGAUGHY, R W Region 1, Philadelphia. Reactor Construction & Engineering Support Branch NARROW, L, PAGLINO, R J Region 1, Philadelphia, Dffice of the Director 80/05/09 9pp
- 8006300055 Forwards IE Insp Rept 50-322/80-06 on 800324-0427 No noncompliance noted BRUNNER.E J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/19 2pp
- --8006300060 IE Insp Rept 50-322/80-06 on 800324-0427 No noncompliance noted Major areas inspected work activities, prependional testing, procedure review & previous insp findings KISTER.H B. Region i. Philadelphia. Reactor Operations Nuclear Support Branch HIGGINS.J C., NICHGLAS.H H. Region i. Philadelphia. Office of the Director 80/05/14 10pp
- 8006300267 Responds to IE Bulletin 80-02, "Inadequate GA for Nuclear Supplied Equipment" Improved interference fit spargers & thermal sleeves mfg for facility, but not yet installed No performance history available NOVARROLJ P Long Island Lighting Co 80/05/29 2pp
- 8006250071 Requests submittal of info relactions taken to preclude occurrence of cracking of jet pump holddown beams described in IE Bulketin 80-07 Util should also provide commitment to adopt long-term solution TEDESCO.R L. Assistant Director for Licensing 80/06/04 Gpp
- 8006170601 Forwards "GA Program Plan for Inservice Insp Program," Revision 7.per NRC Request 121 16 NOVARRO.J P Long Island Lighting Co 80/06/09 2pp
- --8006170606 "GA Program Pian for Inservice Insp Program," Revision 7 * Nuclear Energy Service, Inc. 80/05/09 14pp
- S Reportable occurrences, LERs & related correspondence
- 8004200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement investigations conducted & closed at 46 listed facilities SEAV, J. C. Chemtron Corp., Tube Turns Div. 80/06/06 3pp
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8004030195 Forwards Matls Engineering Branch input to water chemistry programs M/o encl KNIOHT, J P Assistant Director for Engineering 80/04/07 ip
- 8006230110 Advises IMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D 0 Division of Licensing 60/05/20 13pp
- 8004020345 Advises that installation of insp ports & plugging of first row tubes are not prudent & should not be required Control rod guide tube support pin replacement has been completed for Unit 1 & will be done for Unit 2 CRANE.P A Pacific Gas & Electric Co 80/05/22 2pp
- 8006090190 Discusses underclad cracking in reactor vessel nozzles Requests addl info re nozzle base metal matl spec type & grade.clad process type.electrode size & number of clad layers & heat input for each clad SCHNENCER.A Licensing Branch 2 80/05/23 5pp
- 800602016B Forwards "Description of Bys Interaction Program for Beismically-Induced Events." as suppl to 800507 rept CRANE.P A Pacific Gas & Electric Co 80/05/27 tp
- --800602017f "Description of Bys Interaction Program for Beismically-Induced Events " * Pacific Gas & Electric Co 80/05/27 76pp

- 8006030330 Requests meeting w/NRC to discuss 800507 request for additing or automatic switchover of ECCS Info not sufficient to conclude that switchover is either necessary or desirable CRANE,P A Pacific Gas & Electric Co 80/05/28 2pp
- BOO6130119 Notification of BOO604 meeting w/util in Bethesda,MD to discuss mpt organization shift staffing requirements & low power test program
 BUCKLEY.B C Licensing Branch 3 BO/06/02 4pp
- 8006190403 Comments on tacility licensing NRC should expedite licensing of nuclear power plants that meet NRC stds to meet future US energy needs
 HENDERSON, R Affiliation Unknown 80/06/02 1p
- 8006160040 Forwards Amend 83 to application for OL re Chapters 4A,5 & 8 of Hosgri rept Certificate of Svc encl CRANE,P A Pacific Gas & Electric Co 80/05/06 2pp
- --B006160044 Amend 83 to application for OL, re Chapters 4A, 5 & B of Hosgri rept
 LANGLEY, E, B, , CRANE, P A Pacific Gas & Electric Co 80/06/06
- 8006180627 Notification of 800617-19 meeting w/util in San Luis Obispo. CA to audit seismic sys interaction program BUCKLEY.3 C Licensing Branch 2 80/06/06 4pp
- 8006240102 Forwards request for additional info re shielding design review, containment monitors & rodine sampling & analysis sys Add1 info required to continue review of response to NUREQ-0578 SCHNERCER, A Licensing Branch 3 80/06/06 8pp
- BOO6190488 Advises that 12-inch containment pressure/vacuum relief valves will be limited.prior to fuel loading to prohibit opening more than 50 degrees Limit effective until valve can be closed from more open position following postulated LOCA CRANE,P A Pacific Gas & Electric Co 80/06/13 1p
- 8006300295 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt licensing matters w/respect to facilities have been assigned to B Duckley Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/13 12pp
- 8006240416 Advises NRC that 800229 rept. "Response to NUREG-0978 Short-Term Lessons Learned Requirements," is util comprehensive response to TMI-2 incident & supersedes Jul 1979 voluntary rept CRANE, P A Pacific Oas & Electric Co 80/06/18 ip
- 8006250228 Responds to NRC 800123 ltr requesting consultation per Section 7 of Endangered Species Act of 1973 re effects of facility operation on five endangered species Operation not likely to jeopardize species Recommends monitoring MARTINGON.R K Interior.Dept of Fish & Wildlife Service 80/04/19
- F Security, medical, emergency & fire protection plans
- 8005i303i7 Forwards clarification of NRC requirements for emergency response facilities defined in 7909i3 ltr Addi specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors BO/04/25 6ipp
- 8006120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AHEARNE, J F Commission 80/05/13 2pp
- BOO6250067 Advises that safeguards contingency plan submitted on BOO542 is acceptable & approved Plan withheld (ref 10CFR2 790)

 8CHMFNCER, A Licensing Branch 3 BO/06/06 4pp
- 8006160039 Discusses location of principal nearsite emergency operations facility Distance factor is not critical parameter in selection of location Approval of location at San Luis Obispo County sheriff of crequested CRANE,P A Pacific Gas b Electric Co 80/06/09 2pp

G Adjudicatory correspondence

- 8004040194 Motion for stay of proceedings pending review of affidavit of nondisclosure petitioned per present motion Affidavit implied per ASLAB 800411 second prehearing conference order is unconstitutional.violating guarantees of free speech JUNES.Y, I . BALDWIN.W A San Luis Obispo Mothers for Peace BALDWIN.W A Baldwin.W A 80/04/23 5pp
- --8004040196 Executed affidavit of nondisclosure re documents & info obtained from PG&E Certificate of Svc encl JONES: Y I San Luis Obiapo Mothers for Peace 80/04/04 Spp
- 800404D199 Response in opposition to Hendrie 800421 memorandum reparticipation in proceeding NRC regulations prevent participation of employee who had investigatory role on same or related case M/notice of appearance & Certificate of 8vc FLEISCHAKER, D. JCHNSTON, M.P. Sam Luis Obiago Mothers for Peace JCHNSTON, M.P. Center for Law in the Public Interest. 80/05/05
- 8006110417 Response in opposition to intervenor San Luis Obispo Mothers for Peace motion to stay proceedings & petition for review of nondisclosure affidavit Petitioner failed to satisfy burden of proof Certificate of Svc encl NORTON.B. GEHR, A.C., FURBUSH, M.H. Pacific Oas & Electric Co 80/05/05 8pp
- 8006020522 Advises that ASLAP no longer requires executed Baldwin affidavit since original notarized affidavit of mondisclosure has been received TOMPKING.B A Atomic Safety and Licensing Appeal Panel 80/05/06 in
- 8004040031 Corrects MP Johnston 800505 natice of appearance, improperly listing Ctr for Law in Public Interest as client San Luis Obispo Mothers for Peace, Scenic Shoreline Preservation. Ecology Action Club et al are actual clients FLEISCHAKER, D Fleischaker, D S 80/05/21 ip
- 800A240313 Opposes, on behalf of San Luis Obispo Mothers for Peace, 800519 notice of intent to permit Nordlinger participation in OL proceeding Potential conflict of interest may arise due to prior involvement w/ACRS consultant witnesses JONES, Y I Jones, Brown & Clifford 80/05/23 2pp
- 8006110210 Motion to revise NRC 809905 response to joint intervenors' motions to reopen 800328 record Presents RL Rothman & PT Kuo 800517 joint affidavit as revision to 800505 joint affidavit Change involved does not invalidate design KETCHEN:E 9 Hearing Branch 4 80/06/06 3pp
- --B00611022B Affidavit pointing out error in previous affidavit filed w/
 NRC response to intervenors' joint motion to reopen Imperial
 Valley earthquake data does not invalidate Nemark design
 response spectra for facility Certificate of Svc encl
 KUC.P T . ROTHMAN,R Office of Nuclear Reactor Regulation,
 Director 80/05/19 7pp
- 8006;80519 Advises ASLAB that recent as-built audit demonstrates significant breakdown in util GA grogram Breakdown is magnified because pipe supports 5 anchors were supposedly 100% reinspected in response to NRC 1974 5 78 audits FLEISCHAKER, D Fleischaker, D 8 80/06/10 3pp
- --B0061B0522 Responds to Items 2.3 & 4 of IE Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Bys " Plant procedures for as-built documentation will assure strict conformity between sys configuration & design documents LUCKE:R F Pacific Oas & Clectric Co B0/04/17 3pp
- 8006120332 Notifies ASLAB that CA Governor EO Brown intends to participate in hearing re security plan issue Brown was admitted to proceeding as participant by ASLB 791116 order BROWN.H H Hill Christopher & Phillips KLINE.J A. OEOROIQU.8 8 California, State of 80/06/11 3pp
- --BOO6120334 Submits names of attys appearing on behalf of CA Governor EO Brown for security plan hearing Brown was admitted to proceeding as participant by ASLB 791116 order Certificate of Svc encl BROWN-H H Hill Christopher & Phillips 80/06/11 6pp
- BOO6130-271 Memorandum & order CLI-80-24 re intervenor Ban Luis Obispo Mothers for Peace access to util physical security plan Endorses ALAB-410 guidelienes for making plans available, w/one exception Addl views of Commissioner Bradford encl CHILK/S J Office of the Secretary of the Commission 80/06/i1 Bpp

- 8006190609 Memorandum directed to parties, advising that author participation in proceeding does not violate Commission regulations or due process requirements Author will continue to take part in seismic issues

 HENDRIE, J M Commission 80/06/16 5pp
- 8006190559 Agrees to intervenor objection to M Nordlinger assignment as counsel resecutity plan proceeding per M Nordlinger commitment to intervenor BICKMIT.L Office of the General Counsel 80/06/17 ip
- 8005230474 Discusses forwarding of public comments re operation of facilities Messages tend to be repetitive Fails to see need to serve on all parties Ltrs not already in public record should be placed in PDR 2 local PDR in San Luis Obispo, CA BOMERS.E 8 Atomic Safety and Licensing Board Panel 80/0.
- 8006230357 Memorandum advssing parties that author did not participate in Commissioner Kennedy decision re recusancy & Commissioner Hendrie decision to take part in proceeding Author will take part in other license application matters BICKWIT, L. Dffice of the General Counsel 80/06/18 ip
- 8006260159 Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petation to require preparation of supplemental environ statements on Class 9 accidents at Diablo Cangon, Rancho Seco & Palo Verde DENTON, H R Office of Nuclear Reactor Regulation. Director 80/06/19 2pp
- ~-8005260159 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at facilities No special corcumstances exist which would warrant reopening proceedings Request denied DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- ~-8006260161 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS on Class 9 accidents No special circumstances exist which would warrant reopening environ proceedings DENTON:HR Defice of Nuclear Reactor Regulation, Director 80/06/19 17pp
- ~-8006260163 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 7 accidents DEATON-H R Defice of Nuclear Reactor Regulation, Director 80/06/19 2pp
- 8006260269 Bacision ALAB-598, granting intervenors' motion to respen record to admit Imperial Valley earthquake data Holds decision on remaining appeal in abegance until data is evaluated New data may affect key seismit findings BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/06/24
- BOO6270305 Response stating no objection to Governor EQ Brown of State of CA participation in security plan hearing before ASLAB re OL proceeding Certificate of Svc encl TOURTELLOTTE, J Hearing Branch 4 80/06/25 4pp
- 8006300432 Order directing parties to inform ASLAB.by 800707.of option that should be selected from Commission 800611 ruling, CLI-80-24, remanding protected info issue to ASLAB Requests State of CA views, although not yet participant in OL issue BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/25

H General correspondence

- 8006060504 Advises that 800512 ltr is being forwarded to Washington, DC headquarters for inclusion in appropriate public docket file
 HANGHETT.J O Region 5, San Francisco, Office of the Director
 - B0/05/15 1p
- --8004040507 Suggests that facility EL be granted as expeditiously as possible Further felay will cause rotating outages & inconveniences Unused facility burns abundant nuclear fuel & wastes precious oil BACCI,R R Affiliation Unknown 80/08/12 2pp
- ---B006060513 Suggests further seismic research before consider:
 OL for facility Possibility exists for major earthquake in
 San Luis Obispo area Opposes opening of plant
 LING.D Affiliation Unknown 80/05/09 ip

- --8004040516 Requests specific info on granting of OL for facility per Wischoenfelder inquiry Constituent believes unused plant wastes millions of barrels of oil every month & should be opened w/o further delay LAGOMARSINO,R House of Rep 80/05/08 ip
- ---B006040519 Forwards 800402 transcript of in camera hearing on security plan in San Luis Obispo.CA Applicant concerned that no special handling or identification made for security info Requests that NRC inform court reporters W/o encl NORTON.B Affiliation Unknown B0/04/28 (p
- --8006060522 Requests that facility DL not be granted Too many unanswered questions still remain No analysis of effects of Class 9 accident has been made Affiliation Unknown 80/04/22 1p
- ---8006060528 Urges early licensing of facility to save rate paying citizens of CA added cost for imported oil & to save US undestrable consequences of importing approx 20 million barrels of oil per yr BASHFORD.A L Affiliation Unknown 80/04/29 1p
- --B004060530 Advises that B00402 ltr is being forwarded to Washington.DC headquarters for inclusion in appropriate public docket file HANCHETT. J G Region 5. San Francisco. Office of the Director 80/04/28
- --8004040537 Requests that NRC consider feasibility of converting facility to natural or methane gas Inherent risk exists for nearby population if huclear accident triggers major earthquate or vice versa CLANCY, P Affiliation Unknown 80/04/02 1p
- 8006300663 FOIA request for documents re JM Hendrie participation in facility licensing proceeding Hosgii fault or offshore faulting & USGS studies JOHNSTON, M P Genter for Law in the Public Interest BD/05/15
- 8006190575 Opposes licensing of facility due to Hosgri fault & 800528 earthquake proving that fault is active Facility licensing would be criminally irresponsible RAMLS:N Affiliation Unknown 80/05/27 1p
- 8006190519 Opposes licensing of facility due to location near Hosgri fault Earthquake in CA is very real danger KLOPPING.J Affiliation Unknown 80/06/02 ip
- BOO6190597 Requests that N/C reopen seismic hearings before granting facility OL due to recent Hosgri fault earthquake Plant was not designed to bear force of earthquake Fault might be ALLINA, A Affiliation Unknown 80/06/02 1p
- 8006200540 Responds to encl 800418 ltm to President Carter expressing concern re licensing delays Delays caused by post-TMI efforts 8 subsequent application of "lessons learned" Facility is one of four high principy plants
 DENTON-H R Office of Nuclear Reactor Regulation, Director bsequent application or "lessons learned" one Of fout high priority plants Office of Nuclear Reactor Regulation, Director 80/05/02 200
- 8006170592 Requests that GL be denied due to earthquake along Hosgri fault BENNFTT, J. BENNETT, M. Affiliation Unknown 80/06/03 1p
- 8006190597 Urges that OL be denied due to 800528 earthquake on Hosgri fault JOHNSON, I Affiliation Unknown 80/06/04 1p
- 8006300347 Forwards constituent Anson 800507 comments re wind speed assumptions used in development of nuclear emergency regulations NRC plans for public evacuation based on absolute fantasy CRANSTON,A Senate 80/06/04 Spp
- 8006190460 Opposes issuance of GL due to prevalence of seismic activity BANDERON, J. L. Affiliation Unknown 80/06/05 ip
- 8006190465 Forwards RH Leddy 800508 ltr expressing concern for plant safety due to provinity to earthquake fault Requests response directed to constituent LAGOMARSINO, R J House of Rep 80/06/05 3pp
- 8006190490 Opposes issuance of CL due to proximity of active fault STEELE.Γ , STEELE.M Affiliation Unknown 80/06/07 ip

- 8006180424 Forwards updated description of util corporate structure. or onsite safety review group & mgt oversight group for incorporation into FSAR Pacific Gas & Electric Co 80/06/09 16pp
- 8006170514 Opposes licensing of Pacility due to location near Hosgri fault NRC criteria recommend that nuclear reactors should not be sited nearer than 12 1/2 miles to earthquake fault Facility is located practically on fault CATTOIR.M Affiliation Unknown 80/06/10 1p
- 8006230463 Responds to itr re position on low power testing permit for facilities Proposed study to consider alternative approaches to energy problems will not result in delay in licensing, but will give better info on which to base decisions PANETTA.L E House of Rep 80/06/12 2pp
- BOO6190441 Opposes granting of OL due to proximity to Hosgri fault Plant should be converted to non-nuclear fuel immediately MDRATEZ:P Affiliation Unknown 80/06/16 1p
- 8006300662 Responds to FOIA request for documents re JM Hendrie participation in facility licensing proceeding. Hosgri fault or offshore faulting & USOS studies Forwards documents listed in App A & NURE-75/087 W/o encis
- G Inspection reports, IE Bulletins & correspondence
- 8006180299 Forwards response to IE Bulletins 79-06A & 79-06A Revision
 1. "Review of Operational Errors & Sys Misalignments During
 TMI Incident "Operating procedures have been revised to
 incorporate Westinghouse owners group guidelines
 CRANE,P A Pacific Gas & Electric Co 80/05/02 6pp
- S Reportable occurrences, LERs & related correspondence
- B006250068 PNS-V-80-005 on B00602, contractor received bomb threat for facility from unknown caller Licensee advised & search conducted CCHUBTER, M D , NORDERHAUG, L R Region 5, San Francisco, Office of the Director 80/06/02 1P
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D C Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 t new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101;" transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006070562 Forwards request for addl info re review of safeguards contingency plan, submitted 790383 Info should be submitted within 30 days to maintain review schedule Request withheld (ref 10CFR2 770) IPPOLITO, T A Operating Reactors Branch 2 80/05/27 2pp
- 8006200070 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices, including visit to facility to interview security mgt personnel IPPOLITO, T A Operating Reactors Branch 2 80/06/03 2pp
- 8004240315 Forwards descriptions of plant emergency ctrs to mast and-of-yr requirements & commitments Util not planning to construct new facilities Existing bldgs will serve functions UTLEY,E E Carolina Power & Light Co 80/06/18 10pp
- I Financial information
- BG0612D011 Responds to B0050B request for comment on util 8-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w//RC CHRISTENGURY, E Hearings Division 80/05/29 1p

- P Operating license stage documents & correspondence
- 8006120503 "Degraded Grid Protection for Class IE Power Sys at Brunswick Steam Electric Plant, Units 1 & 2." technical evaluation rept CLEVELAND, C J EG&G Idaho, Inc FIN A-6256 8006120503 80/02/29
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Liconsees requirements for TMI Action Plan include shift manning, licensing exams \$\tilde{t}\$ licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07 150pp
- 8004030514 Summary of 800422-23 meeting w/Mart I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolani Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D G Devision of Licensing 80/05/19 72pg
- BOO6190126 Responds to BOO318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur w/util approach Procurement of spare or replacement parts subj to OA controls HAABS,W P Quality Assurance Branch BO/05/23 2pp
- 8006030470 Application to amend License DPR-62, submitted as change to Tech Specs Fee encl UTLEY,E E Carolina Power & Light Co 80/05/27 2pp
- ---8006030475 Proposed revision to Tech Spec Table 3 7 5-1 for safety-related hydraulic snubbers + Carolina Power & Light Co 80/09/27 lp
- 8006050370 Discusses analysis of dc power supply failure on ECC8 performance requested in NRC 800425 ltr Analysis rapt will be submitted by 800827 Analysis of ECCS equipment qualification re flooding will be submitted by 800917 UTLEY.E E Carolina Power & Light Co 80/05/27 lp.
- BOOA030251 Forwards revised response to 791231 ltr re implementation of short-term Lessons Learned Task Force Item 2 2 1 C, shift & relief turnover procedures
 UTLEY, E E Carolina Power & Light Co 80/05/30 2pp
- 80D6300604 Ltr to all BNR licensees forwarding "For Comment" edition of NUREO-0617. "BWR Feedwater Nozzie & Control Rod Drive Return Line Nozzie Cracking " Comments will be evaluated by NRC prior to final implementation W/O encl EISENHUT, D Q Division of Licensing 80/06/05 22pp
- 8006170841 Notifies of fee requirement for 790628 route approval request Invoice will be sent under separate cover MILLER.W O License Fee Management Branch 80/06/06 ip
- 8006240576 Advises that Ofc of Controller has been notified to issue invoice re 790628 request for route approval to cover shipments of irradiated reactor fuel from HB Robinson Plant to facilities

 MILLER.W O License Fee Management Branch 80/06/06 1p
- 8006270034 Forwards Amends 28 % 51 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability
 IPPOLITO, T.A. Operating Reactors Branch 2 80/06/11 3pp
- --8006270037 Amends 28 % 51 to Licenses DPR-71 & DPR-62 respectively.
 changing Tech Specs to establish revised safety & operating
 limits for operation in fuel Cycle 4 & revising table of
 safety-related hydraulic snubbers
 IPPOLITO, T A Operating Reactors Branch 2 80/06/11 175pp
- --8006270039 Safety evaluation supporting Amends 28 & 51 to Licenses DPR-71 & DPR-62, respectively Suppl 2 to fire protection safety evaluation encl # Operating Reactors Branch 2 80/06/11 5pp
- --8006270042 Notice of issuance & availability of Amends 28 & 51 to Licenses DPR-71 & DPR-62 respectively BEVAN,R B Operating Reactors Branch 2 80/06/11 3pp

- BOO6230389 Application for amend to Licenses DPR-71 & DPR-62, clarifying term operable as followup to 800512 response re single failure criteria for safety sys in power reactors UTLEY, E.E. Carolina Power & Light Co. 80/06/18 2pp
- --B006230390 Revised Tech Specs re single failure criteria for safety sys in power reactors • Carolina Power & Light Co 80/06/18 8pp
- 8006240475 Forwards info re GE turbine disks in response to NRC 800516 Itr Stress corrosion cracks have not been observed Hater erosion found in keyways of wheels is being studied Erosion process should not require replacement of wheels UTLEF, E E Carolina Power & Light Co 80/06/20 14pp
- O Inspection reports. |E Bulletins & correspondence
- B006020573 Forwards IE Insp Repts 50-324/80-09 & 50-325/80-10 on 800317-20 No noncompliance noted MVRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/04/14 2pp
- --8006020575 IE Insp Repts 50-324/80-09 \$ 50-325/80-10 on 800317-21 No noncompliance noted Major areas inspected inservice insp work observation & data review. Inservice insp program review & torus mod work observation HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAKE.J Region 2. Atlanta. Office of the Director 80/04/14 23pp
- 8006200092 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/18 2pp
- 800618000B Forwards Waste Packaging Insp Rept 80-06 on 800414-15 No noncompliance noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 2pp
- --8006180012 Waste Packaging Insp Rept 80-06 on 800414-15 No noncompliance noted Major areas inspected shipping paper requirements. DDT placarding requirements, radiation levels & removable contamination TROUP.O L , MCARTHUR.T C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 5pp
- 800&0&0583 Forwards RE Bulletin 80-11, "Masonry Hall Design " Requires action & written response RE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8006050311 Forwards IE Bulletin 80-12, 'Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit I While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/05/09
- 8006170851 Ack receipt of 800501 supplemental response providing new completion dates for revising safety & nonsafety-related sys descriptions per 1E Insp Repts 50-324/79-02 & 50-325/79-02 LENIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/13 1p
- --8006170857 Advises that nine safety-related sys descriptions completed, nine rewritten in draft form & work on final four in progress Rewrite will be completed by 800630 Other sys descriptions will be completed by 810430
 TOLLISON.A C Carolina Power & Light Co 80/05/01 ip
- 8006300128 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/13 286

r addl info re cracks in keyway & bore house low pressure turbines uring next major outage IE documents encl s Branch 2 80/05/16 3pp

50-324/80-14 & 50-325/80-17 on ed eactor Operations Nuclear Support

- --8004300266 IE Insp Repts 50-324/80-14 % 50-325/80-17 on 800331-0502 No noncompliance noted Major areas inspected control room observations radiation % fire protection CUZTS.JE Region 2, Atlanta, Office of the Director KELLOGO,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 Spp
- 8006180228 Responds to IF Bulletin 80-06 Adequate response cannot be prepared on requested schedule Sixty-day extension, until B00811.necessary to allow for adequate review of as-built drawings & performance of addl testing FURR. B J Carolina Power & Light Co 80/05/23 ip
- 8004030374 Forwards revised "Inservice Insp Program, Pump & Valve Testing," & related drawings Info re standby gas treatment sys not included Drawings available in Central Files only UTLEY, E E Carolina Power & Light Co 80/05/27 ip
- --8006030376 "Inservice insp Program Pump & Valve Testing "
 * Carolina Power & Light Co 80/05/27 78pp
- 8006i80365 Responds to IE Insp Repts 50-324/80-10 & 50-325/80-11 Procedure will be implemented by 800701 to assure that all procedures are revised to reflect healy installed valves within two wks of being declared operational TOLLISON.A C Carolina Power & Light Co 80/06/10 2pp
- BO06240047 Forwards notice of violation & notice of proposed imposition of civil penalties re 800222 unmonitored, uncontrolled release of airboine radioactive matl to environ from facilities
 BIELLO.V Office of Inspection & Enforcement, Office of the Director BO/06/11 2pp
- ---8006240051 Notice of violation from insp on 800310-14 & 0402-03 Noncompliance noted failure to determine magnitude of release of airborne radioactive matt from auxiliary boiler stack & failure to report release to NRC within 14 days a Office of Inspection & Enforcement, Office of the Director 80/06/11 App
- ---8006240057 Notice of proposed imposition of civil penalties in amount of \$24,000 re 800222 unmonitored uncontrolled release of airborne radioactive matl to environ from facilities

 4 Office of Inspection 5 Enforcement, Office of the Director 80/06/11 to
- R Periodic operating reports & related correspondence
- BOO6110092 Forwards monthly operating repts for May 1980 TOLLISON.A C Carolina Power & Light Co BO/06/06 Ip
- --8006110075 Monthly operating repts for May 1980 WIELIS,E Carolina Power & Light Co 80/06/03 9pp
- 8 Reportable occurrences, LERs & related correspondence
- BOOA040307 Forwards updated LER 79-093/03L-2 TGLLISON A C Carolina Power & Light Co BO/05/15 to
- ---B004040310 Updated LER 79-093/03L-2 on 791120, during startup, rods 42-33 & 26-07 rod overtrayel alarmed when withdrawn to notch 4B Causes by incorrect placement of uncoupling pin in spud IWR 6 uncoupling pins will be used to prevent problem TQLLISQN.A C Carolina Power & Light Co B0/05/18 2pp
- 8006030331 Forwards "Meteorological Analysis of Brunswick Steam Electric Plant Release on 800221-22 " Includes offsite dose calculations TOLLIEDN, A C Garolina Power > Light Co 80/05/27 30pp
- --8006030332 "Meteorological Analysis of Brunswick Steam Electric Plant Release on 800221-22 " Includes offsite dose calculations * Carolina Power & Light Co 80/05/27 245pp
- 8006030352 Responds to 800522 telcon & submits info re scram discharge vol float ruitch failure on 771114 Insp of level switches revealed float ball on rod block switch crushed & float ball stem on high level switch bent Ball & ball stem replaced TGLLISON.A C Caralina Power & Light Co 80/05/28 2pp
- 8006030395 Forwards LER 80-037/03L-0 TBLLISDN.A C Carolina Power & Light Co 80/05/30 tp

- --8004030397 LER 80-037/03L-0 on 800502, while removing control rod driveline for maint, metal bracing fell on cable for intermediate range monitor 8, causing separation from connector Cause not, stated Connector replaced TOLLISON, A C Carolina Power & Light Co 80/05/30 ip
- --8006090355 LER 80-043/03L-0 on 800507 during current refueling outage, standby gas treatment operability test was not performed by required 800425 date Caused by administrative oversight Satisfactorily performed on 800507
 TOLLISON.A C Carolina Power & light Ca 80/06/03 1p
- 8006200024 Final Part 21 rept re miled heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement investigations conducted & closed at 46 listed facilities SEAV.J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006180496 Forwards LER 80-044/03L-0 TOLLISOM, A C Carolina Power & Light Co 80/06/11 ip
- ---8006180505 LER 80-044/03L-0 on 800516, during source range monitor (SRM) operability PT 1 7 1, full in 3 out indication of SRM A not received & SRM D produced erratic indications Caused by blown drive circuit fuse & moisture in detector connection TOLLISON. A C Carolina Power & Light Co 80/06/11 2pp
- 8006240134 EN-80-020 on 800613 order imposing civil penalties issued based on six alleged items of noncompliance to 800222 unmonitored, uncontrolled release of airborne radwaste BROCKETT, T W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/06/11
- 8006180425 RO while performing required insps per IE Bulletin 79-018, determined that documentation did not exist to prove that splices connecting Automatic Valve Co solenoids are environmentally qualified Splices being evaluated TOLLISON A C Carolina Power & Light Co 80/06/12 2pp
- 8006250267 RO 2-80-46 on 800611, insp per IE Bulletin 790918 revealed tack of environ qualification documentation of splices connecting solenoid pigtail leads on safety-relief valves to power tables
 TOLLISON, A C Carolina Power & Light Co 80/06/12 2pp
- BCO6180455 Forwards LER 80-021/03L-0 TOLLISON:A C Carolina Power & Light Co 80/06/13 1p
- --8006180465 LER 90-021/O3L-0' on 800516 during performance of reactor low pressure channel calibr functional test switches 1 & 2 of 2-821-P5-NO2ID were found out of calibr Caused by instrument drift Buitches recalbir TQLLISON.A C Carolina Pawer & Light Co 80/06/13 2pp
- DOCKET 50-325 BRUNSWICK STEAM FLECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- E006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 10CRSD & is expected to be published in FR by end of May EISENHUT, D G Division of Licensing E0/09/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101." transmitted by NRC 800319 ltr.Page 14a not enci EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006090562 Forwards request for add1 info re review of safeguards contingency plan submitted 790323 Info should be submitted within 30 days to maintain review schedule Request withheld (ref 10CFR2 790)

 IPPOLITO. Y A Operating Reactors Branch 2 80/05/27 2pp
- 8006200070 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices, including visit to facility to interview security mpt personnel IPPOLITO, T.A. Operating Reactors Branch 2 80/04/03, 2pp

- 8004240315 Forwards descriptions of plant emergency ctrs to meet end-of-yr requirements & commitments Util not planning to construct new facilities Existing bldgs will serve functions
 UTLEY.E.E. Carolina Power & Light Co. 80/06/18 10pp
- I Financial information
- 8006120011 Responds to 800508 request for comment on util 5-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC CHRISTENBURY. E. Hearings Division 80/05/29 lp
- P Operating license stage documents & correspondence
- BOO6120503 "Degraded Grid Protection for Class IE Power Bys at
 Brunswick Steam Electric Plant. Units 1 & 2," technical
 evaluation rept
 CLEVELAND. C J EG&G Idaho, Inc FIN A-6256 8006120503 80/02/29
 1200
- 8006090165 Forwards addl TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include whift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D.G. Division of Licensing 80/03/07 150pp
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose,CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES,C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Cenerator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule enci EISENHUT, D. G. Division of Licensing 80/05/19 72pp
- 8006020230 Application for amend to License DPR-71 requesting Tech Spec changes to complete second refueling 4 begin Cycle 3 aperation "Supplemental Reload Licensing Submittal for Brunswick Steam Electrical Flant Unit 1 Reload 2." encl UTLEY.E E Carolina Power & Light Co 80/05/23 1pp
- --8006020237 Tech Spec changes to Section 3/4 2 re power distribution & average planar linear heat generation rate
 -- Carolina Power & Light Co 80/05/23 9pp
- ---8006020243 "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant Unit 1 Reload 2 " ENGEL.R E General Electric Co NEDO-24239 80/01/31 32pp
- 8006170126 Responds to 800318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur w/util approach Procurement of spare or replacement parts subj
- 8004050370 Discusses analysis of dc power supply failure on ECC8 performance requested in NRC 800425 ltr Analysis rept will be submitted by 800827 Analysis of ECC8 equipment qualification re flooding will be submitted by 800917 UTLEY, E E Carolina Power & Light Co 80/03/27 ip
- 8006050251 Forwards revised response to 771231 ltr re implementation of short-term Lessons Learned Task Force Item 2 2 1 C.shift & relief turnover procedures

 UTLEY.E E Carolina Power & Light Co 80/05/30 2pp
- 8006070325 Application to amend Tech Specs, implementing temporary change in setpoint values of three RSEP-1 safety relief valves fee encl
 UTLEY.E E Carolina Power & Light Co 80/05/30. 2pp
- --8006090329 Revised Page 3/4 4 2 to Tech Specs for reactor coolant sys, implementing temporary change in setpoint values of three BSEP-1 safety relief valves
 * Carolina Power & Light Co 80/05/30 1p
- 8006110127 Requests that NRC review of outage-related technical issues be expedited so that appropriate license amends can be issued prior to scheduled 800625 criticality
 UTLEY/E E Carolina Power & Light Co 80/06/04 ip

- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREO-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT, D & Division of Licensing. 80/06/05. 22pp
- 8006170841 Notifies of fee requirement for 790628 route approval request Invoice will be sent under separate cover MILLER, W.O. License Fee Management Branch 80/06/06 ip
- 8006240576 Advises that Ofc of Controller has been notified to issue invoice re 790628 request for route approval to cover shipments of irradiated reactor fuel from HB Robinson Plant to facilities MILLER, N O License Fee Management Branch 80/06/06 ip
- 800&180481 Discusses App J of 10CFR50 re testing schedule Confirms understanding that Type C testing may be performed during Fall 1980 meint portion of refueling outage TOLLISON A C Carolina Power & Light Co 80/06/11 ip
- 8006270034 Forwards Amends 28 & 51 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability IPPOLITO.T A Operating Reactors Branch 2 80/06/11 3pp
- --9006270037 Amends 28 & 51 to Licenses DPR-71 & DPR-62, respectively, changing Tech Specs to establish revised safety & operating limits for operation in fuel Cycle 4 & revising table of safety-related hydraulic snubbers

 IPPOLITO.T A Operating Reactors Branch 2 80/06/11 175pp
- --8004270039 Safety evaluation supporting Amends 28 & 51 to Licenses DPR-71 & DPR-62, respectively Suppl 2 to fire protection safety evaluation enc! * Operating Reactors Branch 2 80/06/11 5pp
- --800&270042 Notice of issuance & availability of Amends 28 % 51 to Licenses DPR-71 & DPR-62, respectively BEVAN,R B Operating Reactors Branch 2 80/06/11 3pp
- 8006230389 Application for amend to Licenses DPR-71 & DPR-62, clarifying term operable as followup to 800512 response re wingle failure criteria for safety sys in power reactors UTLEY,E E Carolina Power & Light Co 80/06/18 2pp
- --8006230390 Revised Tech Specs re single failure crateria for safety
- 8006240475 Forwards info re GE turbine disks in response to NRC 800516 ltr Stress corrosion cracks have not been observed Water erosion found in keyways of wheels is being studied Erosion process should not require replacement of wheels UTLEY.E E. Carolina Power & Light Co. 80/06/20 14pp
- 9 Inspection reports, 1E Bulletins & correspondence
- 8008230330 Forwards waste packaging insp rept on 8003i3-14 No noncompliance notes 8TOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pg
- --8005230341 Waste packaging inspired on 800313-14 No noncompliance noted Major areas inspected licensee-shipper vehicles inspected for compliance w/DDT & NRC regulations including shipping paper & DOT placarding requirement POTTER-J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch BO/03/28 4pp
- 8006020573 Forwards IE insp Repts 50-324/80-09 & 50-325/80-10 on 800317-20 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 80/04/14 2pp
- --8004020575 IE Insp Repts 50-324/80-09 & 50-325/80-10 on 800317-21 No DUBDIEDTS IE insp Repts 30-344/30-07 & 30-329/80-10 on HOUSI/-21 N noncompliance noted Major areas inspected inservice insp work observation & data review. Inservice insp program review & torus med work observation
 HERDI-A R Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch BLAKE.J Region 2. Atlanta, Office of the Director 80/04/14 23pp
- 8006200092 Forwards IE Gircular 80-08 "BWR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/18

- 8005180008 Forwards Waste Packaging Imap Rept 80-06 on 800414-15 No noncompliance noted STOHR.JF Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/05/01 2pp
- --8006180012 Waste Packaging Insp Rept 80-06 on 800414-15 No noncompliance noted Major areas inspected shipping paper requirements, DDT placarding requirements, radiation levels & removable contamination
 TROUP.O.L. MCARTHUR.T.C. Region 2. Atlanta, Fuel Facility &
 Materials Safety Branch 60/05/01 Spp
- 8006060593 Forwards IE Bulletin 80-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads' enci
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 80060503i1 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 Uhile in Refueling Mode" encl 9/REILLY, J.P. Region 2 Atlanta, Office of the Director 80/05/09
- BOQ4170B51 Ack receipt of BOOS01 supplemental response providing new completion dates for revising safety & nontafety-related sys descriptions per IE Insp Repts 50-324/79-02 & 50-325/79-02 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/09/13 ip
- 8006300128 Forwards IE Circular 80-11. 'Emergency Diesel Generator Lube Dil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/05/13
- BOO4020060 Forwards request for add1 info re cracks in keyway & bore sections of discs in Westinghouse low pressure turbines Recommends ultrasonic insp during next major outage IE Info Notice 79-37 & related documents encl IPPOLITO, T A Operating Reactors Branch 2 80/05/16 3pp
- 8004300261 Forwards IE Insp Repts 50-324/80-14 & 50-325/80-17 on RODGGI-O502 No nencompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/09/20 2pp
- --8006300266 IE insp Repts 50-324/80-14 / 50-325/80-17 on 800331-0502 No noncompliance moted Major areas inspected control room observations radiation & fire protection OUZTB.JE Region 2, Atlanta. Office of the Director KELLOGG.P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/20 Spp
- 8005180228 Responds to IE Bulletin 80-05 Adequate response cannot be prepared on requested schedule Sirty-day extension, until 800811, necessary to allow for adequate review of as-built drawings & performance of addl testing FURR.B J Carolina Power & Light Co 80/05/23 ip
- BOO6030374 Forwards revised "Inservice Insp Program, Pump & Valve Testing," & related drawings Info re standby gas treatment sys not included Brawings available in Central Files only UTLEY.E E Carolina Power & Light Co 80/05/27 ip
- --B00&030376 "Inservice Insp Program.Pump % Valve Testing "
 * Carolina Power & Light Co B0/05/27 /Bpp
- 8006060336 Advises that long-term mods resulting from seismic reanalysis re IE Bulletins 79-07 > 79-14 will be completed by end of maint outage scheduled for mid-Sept 1980 Revises 790723 completion schedule FURR.B J Carolina Power > Light Co 80/06/02 2pp
- BD06190638 Revises response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys" > IE Bulletin 79-07, "Seismic Safety Analyses of Safety-Related Piping " Mod will be completed by and of Sapt 1930 maint outage FURR, B J Carolina Power & Light Co 80/06/02 2pp

í

- 9006180365 Responds to 1E Insp Repts 50-324/80-10 \$\delta\$ 50-325/80-11 Procedure will be implemented by 800701 to assure that all procedures are revised to reflect newly installed valves within two wks of being declared operational TOLLISON, A C Carolina Power & Light Co 80/06/10 2pp
- 8006240047 Forwards notice of violation & notice of proposed imposition of civil penalties re 800222 unmonitored. uncontrolled release of allborne radioactive matl to environ from factilities

 STELLO.V Office of Inspection % Enforcement, Office of the Director 80/06/11 2pp
- --8004240031 Notice of violation from insp on 800310-14 & 0402-03 Noncompliance noted failure to determine magnitude of release of airborne radioactive matl from auxiliary boiler stack & failure to report release to NRC within 14 days > Office of Inspection > Entorcement, Office of the Director 80/06/11 4pp
- --8006240057 Notice of proposed imposition of civil penalties in amount of \$24,000 re 800222 unmonitored, uncontrolled release of airborne radioactive mail to environ from facilities * Office of Inspection > Enforcement, Office of the Director 80/06/11 ip
- R Periodic operating reports 3 related correspondence
- 8004110092 Forwards monthly operating repts for May 1980 TOLLISON: A C Carolina Power & Light Co 80/06/06 ip
- --8006110075 Monthly operating repts for May 1980 WILLIS.E Carolina Power & Light Co 80/06/03 7pp
- S Reportable occurrences, LERs & related correspondence
- 8006030331 Forwards "Meteorological Analysis of Brunswick Steam Electric Plant Release on 800221-22 " Includes offsite dose calculations TOLLIBON, A C Carolina Power & Light Co 80/05/27 30pp
- ---8006030332 "Meteorological Analysis of Brunswick Steam Electric Plant Release on 800221-22 " Includes offsite dose calculations * Carolina Power & Light Co 80/05/27 245pp
- 8006030332 Responds to 800522 telcon & submits info re scram discharge vol float switch failure on 791114 Insp of level switches revealed float ball on rod block switch crushed & float ball stem on high level switch bent Ball & ball stem replaced TOLLISON.A C Carolina Power & Light Co 80/05/28 2pp
- 8004040335 Forwards LER 60 047/03L-0 TQLL160N.A C Carolina Power & Light Co 80/05/28 Ip
- --8006040339 LER 80-047/03t-0 on 800501.RHR flow indicator LEi1-FI-333B on remote shutdown panel showed 6,200 gpm w/sys shut down Caused by malfunctioning indicator Indicator & transmitter calibr & sys returned to svc
 YQLLISON.A C Caroline Power & Light Co 80/05/28 IP
- 8006050009 Forwards LER 80-038/03L-0 TOLLISON,A C Carolina Power & Light Co 80/05/28 ip
- --8004050015 LER 80-03B/03L-0 on 800501, during normal operation,1A reactor recirculation pump tripped on motor generator set low oil pressure Caused by PCV-1739 controlling erratically during radom periods & possible set
- 8006090314 RD 800422, fire protection alarm for Zone 9,50-ft elevation of reactor bldg, annunciated & would not reset Caused by ionization detector reacting to steam from local steam leak Leak with be repaired TOLLISON, A C Carolina Power & Light Co 80/06/02 ip
- 8004090392 Forwards LER 80-049/031-0 TGLL1SDH.A C Carolina Power 5 Light Co 80/04/03 1p
- --8006090398 LER 80-049/03L-0 on B00516, during routine surveillance, position OB for rod 14-15 did not indicate Probably caused by ground in prototypic injet piping Problem under investigation
 TOLLISON, A C Carolina Power & Light Co 80/06/03 ip
- 8004i10184 Forwards LFR 80-048/03L-0 TQLL180N.A C Carolina Power & Light Co 80/04/05 ip

- --8005110198 t.ER 80-048/03L-O on 800508 during normal surveillance calibr adjustment screw cap on reactor level instrument was leaking water Caused by snoperable switch 2 Calibr adjustment screw cap gasket was replaced & switch 2 contacts cleaned TOLLISON.A C Carolina Power & Light Ca 80/06/05 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities

 SEAY, J. L. Chemtron Corp., Tube Turns Div. 80/06/06 | 3pp
- 8006180447 Forwards LER 80-052/03L-0
 TOLLISDN, A C Carolina Power & Light Co 80/06/11 in
- --8006180449 LER 80-052/03L-0 on 800514 during normal surveillance, primary containment oxygen analyzer, 1-CAC-ATH-1259-2, found giving erratic indications Caused by Corrosion in magnetic analyzer sample cell Unit replaced & returned to svc TQLLISON, A C Carolina Power & Light Co 80/06/11 2pp
- BOO6240134 EN-80-020 on BOO613, order imposing civil penalties issued based on six alleged items of noncompliance re BOO222 unmonitored, uncontrolled release of airborne radwaste BROCKETT.T W. THOMPSON. D. Office of Inspection & Enforcement, Office of the Director 80/06/11
- 8006180425 RD while performing required insps per IE Bulletin 79-018, determined that documentation did not exist to prove that splices connecting Automatic Valve Co solenoids are environmentally qualified Splices being evaluated TOLLISON, A C Carolina Power & Light Co 80/06/12 2pp
- 8006250267 RD 2-80-46 on 800611.insp per IE Bulletin 77071B revealed lack of environ qualification documentation of splices connecting solenoid pigtail leads on safety-relief valves to power cables
 TOLLISON.A C Carolina Power & Light Co 80/06/12 2pp
- --8006180454 LER 80-051/OGL-O on 800515, during normal surveillance, containment atmosphere dilution tank vol observed less than required limit Caused by Inability to open CAC tank manual outlet isolation valve. CAC-HV-44
 TOLLISON.A C Carolina Power & Light Co 80/06/13 2pp
- DOCKET 50-327 SEGUDYAK NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8006190327 Discusses review of FSAR Table 17 2-1, "Critical Structures, Sys & Components," re operational GA program Forwards request for add info to be transmitted to util HAASS.W P Quality Assurance Branch 80/06/05 4pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 770913 ltr Addl specific criteria for facilities under development EISENHUT. D G Division of Operating Reactors 80/04/25 61pp
- BOO6060294 Forwards add1 info to training & qualification plan Info withheld (ref 10CFR2 790) MILLS.L M Tennessee Valley Authority B0/06/02 2pp
- BOO6130307 Forwards revised schedule for responses to Auxiliary Sys Branch fire protection review questions Proposed Train B circuit reroute scheme shown on enci marked up oversize drawings Drawings available in Central Files only, MILLS.L M Tennessee Valley Authority BO/06/11 10pp
- 8006260164 Forwards TVA radiological emergency plan & TN multijurisdictional radiological emergency response plan Three cross refs encl MILLE; L M Tennosser Valley Authority 80/06/19 40pp
- ---8006260165 TVA radiological emergency plan # Tennessee Valley Authority 80/06/09 250pp
- --B006260166 TN multi-jurisdictional radiological emergency response plan
 * Tennessee: State of 80/06/19 400pp

H Gameral correspondence

- B006020157 Responds to B00226 itr to President Carter of licensing nuclear plants Provides statement made by President on 791207 NRC is in process of preparing action plan specifying actions for review & approval DENTON: #R Office of Nuclear Reactor Regulation, Director B0/04/21 2pg
- K Utility Final Safety Analysis Report (FSAR) & amends
- B006110257 Application for Amend 65 to Licenses DPR-72 & CPPR-73, containing revisions to Chapter 3 of FSAR
 MILLS:L W Tennessee Valley Authority 80/06/06 3pp
- --8006110262 Revisions to Chapter 3 of FSAR providing responses to NRC requests for add1 info re foundation engineering diesel generators & inservice insp programs Constitutes Amend 65 to Licenses DPR-73 & CPPR-73

 * Tennessee Valley Authority 80/06/06 44pp
- 8006190391 Forwards proposed revisions to facility F6AR, Question 5 9A re inservice imap program Revises request for relief from ASME Section 11.covering third party inspectors pressure retaining welds in piping & steam generator nortles MILLS.L M Tennessee Vailey Authority 80/06/13 5pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- E006230227 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant Units i & 2 800428 meeting in Washington.DC to continue review of TVA application for license to operate HOYLE.J C Office of the Secretary of the Commission 80/04/04
- 8006190206 Notice of indefinite postponement of ACRS Subcommittee 800428 meeting re Sequeyah Nuclear Plant Units 1 % 2 HDYLE,J C ACRS Advisory Committee on Reactor Safeguards 80/04/16 1p
- 8006280074 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant 800602 meeting in Washington,DC to review DL application Some closed sessions may be needed to explore matters involving proprietary info HOYLE,J C Office of the Secretary of the Commission 80/05/12
- 8006240595 Notice of ACRS 800605-07 meeting in Hashington DC to discuss facility GL Some closed sessions necessary to prevent frustration of responsibilities HDYLE.J C Dffice of the Secretary of the Commission 80/05/19
- 8006060608 Transcript of ACRB Subcommittee on Sequoyah Nuclear Power Station meeting on 800602 in Washington.DC Pp 1-231 Morning session Vieugraphs & rolated matis encl * ACRS - Advisory Committee on Reactor Safeguards 80/06/02 300ms
- P Operating license stage documents & correspondence
- 6006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8006040098 Advises that Ofc of Nuclear Reactor Regulation will take lead in reviewing OL prior to authorization of full power Objectives include clarity, enforceability. TMI-related requirements, review of Tech Specs & movement toward STS DENION.H R Office of Nuclear Reactor Regulation, Director 80/03/08, 2pp

Advises that Commission intends to use facility GL as model or clarity & enforceability Project manager should set Spacs in conjunction w/IE & group working on 1 paper re Tech Specs Mano encl of the Secretary of the Commission 80/04/11

uggestion to make facility OL model license for pility IE should also be involved to help fting Tech Specs to fit facility Marked—up

ion 80/03/18 3pp

- ---8005060112 Proposes that facility QL be used as model license for clarity 5 enforceability Task force from various depts would review full power license prior to Commission BECY is requested to poll Commissioners & respond by 800318 BRADFORD,P Commission 80/03/11 ip
- BOO6130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D Q Division of Licensing 80/05/19 72pp
- 8005230276 Forwards "Flood Insurance Study" > seven oversize drawings in response to 800505 ltr to hydrologic engineering questions re Executive Order 11988 MILLS,L M Tennessee Valley Authority 80/05/20 10pp
- --8005230283 "Flood Insurance Study," Hamilton County,TN

 * Housing > Urban Development.Dept of Federal Disaster Assistance
 Admin 79/02/28 49pp
- B006030417 Forwards proposal for seismic margin program, required by NUREO-0611 Program provides basis for NRC to complete evaluation of seismic qualification of structures & squipment necessary for safe shutdoun MILLS.L M Tennessee Valley Authority 60/05/27 3pp
- 800±02017B Application for amend to License DPR-77 Proposed Tech Spec changes encl.consisting of mod to several action statements to allow entry into Modes 3 & 4 before completion of action listed in 0'Reilly 800429 itr MILLS.L M Tennessee Valley Authority 80/05/28 ip
- --8004020183 Proposed Tech Spec changes re mods to several action statements to allow entry into Modes 3 & 4 before completion of actions listed in D'Reilly 800429 1tr * Tennessee Valley Authority 80/05/28 8pp
- 8006:90778 Submits status rept Plant is currently in cold shutdown Ali image & any required hanger re-work will be completed by 800621 Initial criticality is estimated to be 800704 One wk of std tero power physics tests will be conducted STAHLE.C Licensing Branch 2 80/06/06 2pp
- 8006190615 Advises that Westinghouse responded to NRC questions re Barton Lot 2 transmitters in 800521 ltr.N8-TMA-2248 info applicable to unusual behavior of transmitters at plant during qualification testing MILLS.L M Tennessee Valley Authority 80/06/13 ipp
- 8006200321 Application to amend License DPR-77, clarifying meaning of term "operable" & application to single failure criterion for safety sys Reasons & justification encl
 MILLS.L. M Tennessee Valley Authority 80/06/13 ip
- ---8006200326 Proposed Tech Spec 3/4 O re limiting conditions for operation for License DPR-77

 * Tennessee Valley Authority 80/06/13 10pp
- B006250308 Notification of B00619 meeting w/utils in Bethesda, MD to discuss issuance of full power license for facilities
 DROMERICK, A W Licensing Branch 1 KERRIGAN, J D Licensing Branch 3 BTAHLE, C R Licensing Branch 2 B0/06/16 6pp
- 8006240323 Forwards revised response to Question 12 16 re employee access to high radiation areas Revision includes description of administrative procedures controlling access to areas adjacent to fuel transfer tube
 MILLS.L M Tennessee Valley Authority 80/06/17 2pp
- BOO6240472 Requests change to Tech Specs to permit plant heatup w/ inoperable hanger RCH-118 located on pressurizer relief line MILLS,L M Tennessee Valley Authority BO/06/20 ip
- 8006300387 Forwards add1 info requested by NRC re changes to Tech Bpec 2 2 1 for reactor trip sys instrumentation setpoints & 3 9 1 for boron concentration refueling MILLS.L M Tennessee Valley Authority 80/06/23 11pp
- 8006300391 Forwards revised responses to Questions 031 127,040 &0 & 031 129 of NRC 790801 ltr re seismic qualification of Class IE electrical equipment Repts re cable samples & IEEE-323-1794 qualification encl MILLS,L II Tennessee Valley Authority 80/06/23 10pp
- ---8006300377 "Delphi Preumatic Test Procedure " LEWIS.G Comsip. Inc., Delphi Systems Div 75/06/18 2pp

- --8006300400 "Radiation Testing of Cell Number 885, Final Rept "
 HILLIS, D.E. IRT Corp. 79/08/23 7pp
- --8006300407 "Seismic Vibiation Test of E10 Series Transmitters "
 SEARS.J A . MCCASLAND.V . RAMSELL.R Actan Environ Testing Corp
 76/03/22 30pp
- --80063G0414 "Test Procedure for Seismic Vibration, Qualification Test of E10 Series MCA/RRW Transmitters " SEARS, J A . MCCASLAND, K G Acton Environ Testing Corp 73/09/30
- --8006300422 "Gage & Differential Pressure Transmitters Type E10 Series "
 SCHREINER.W., CASAUBON.M., TOLF.N.L. Acton Environ Testing Corp
 73/30/31 10pp
- --8006300429 "Qualification Test of Electrical Cables Under Simulated LOCA/DBE By Sequential Exposure to Environs of Radiation, Thermal Aging Steam & Chemical Spray "

 I Isomedia. Inc. (subs. of Maesfield Enterprises, Inc.)
 78/06/30 42pp
- 8006300248 Application to amend License DPR-11, modifying Tech Spec 3 4 10. re RCS structural integrity to permit plant heatup w/imaperable pipe hanger on pressurizer relief line Forwards proposed changes to Tech Specs MILLS.L.M Tennessee Valley Authority 80/06/24 2pp
- --8006300257 Proposed changes to Tech Specs Section 3 4 10 re RCS structural integrity, permitting plant heatup w/inoperable pipe hange on pressurizer relief line Reasons & Justifications for proposed changes encl. * Tennessee Valley Authority 80/06/24 4pp
- Q Inspection reports, IF Bulletins & correspondence
- 8004090516 Forwards IE Insp Rept 50-327/80-13 on 800301-31 & notice of violation of Vibiación LEWIS.R C Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/04/28 2pp
- ---8006090519 Notice of violation from insp on 800301-31
 * Region 2, Atlanta, Office of the Director 80/0 80/04/28 1p
- ---8006090521 IE Insp Rept 50-327/80-13 on 800301-31 Noncompliance noted failure to maintain & implement procedure required by Teck Specs re fuel loading DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch COTTLE.W T Region 2. Atlanta, Office of the Director B0/04/28 9pp
- 8004040159 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support enc l O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/08
- 6006040267 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit I Whije in Refueling Mode" encl 0'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09
- 8006120034 Forwards IE Circulai 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/13
- B006170193 Ack receipt of 800506 ltr informing NRC of steps taten to correct deviations noted in IE Insp Repts 50-327/80-10 & 50-328/80-06 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/05/23 2pp
- --B006170211 Responds to NRC 800414 ltr re deviations noted in IE Insp Repts 50-327/80-10 & 50-328/80-06 Corrective actions' detailed instructions 2 procedures prepared Plant fire brigade reconstructed 3 Security Instruction 13 revised MILLS.L M Tennessee Valley Authority 80/05/06. 4pp
- --8004170215 Forwards IE Insp Repts 50-327/80-10 & 50-328/80-04 on 800318-21 & notice of deviation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/14 2pp
- --8006170222 Notice of deviation from insp on 800318-21 * Region 2. Atlanta, Office of the Director 80/0 80/04/11 1p

- ~~9006170228 IE Insp Repts 50~327/80-10 & 50~328/80-06 on 8003;8-21
 Noncompliance noted fire fighting procedures not provided
 for all safety-related areas
 CONLOIL: T F Region 2, Atlanta, Reactor Construction & Engineering
 Support Blanch MILLER, H H Region 2, Atlanta, Office of the Support Branch MILLER, W H Director 80/04/11 7pp
- 8004230249 Ack receipt of 800523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/80-14 & correct violations noted in in intermediate Society of the Society
- --8006230267 Responds to NRC 800501 ltr re violations noted in IE Insp Repts 50-327/80-14 % 50-328/80-08 Corrective actions Surveyllance Instruction 114 will be revised to require examination of Class 2 pressure retaining bolting MILLS,L M Tennessee Valley Authority 80/05/23 3pp
- --B006230273 Forwards IE Insp Repts 50-327/80-14 & 50-328/80-0B on B00331-0403 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/05/01 2pp
- --B006230341 Notice of violation from insp on 800331-0403
 * Region 2, Atlanta, Reactor Construction & Engineering Support
 Branch 80/04/28 1p
- --8006230350 IE Insp Repts 50-327/80-14 & 50-328/80-08 on 800331-0403 overacosous is insprepts 30-327/80-14 & 50-328/80-08 on 800331-0403 Noncompliance noted failure to comply w/preservice/inservice insprequirements & failure of records to adequately define practical exam criteria HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch ZAJAC, D Region 2, Atlanta, Office of the Director 80/04/28 6pp
- 8008200099 Ack receipt of 800822 ltr informing NRC of steps taken to correct violations noted in IE Ensp Repts 50-327/79-34 & 50-328/79-19 90-328/77-17 MURPHY, C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/06/04 2pp
- 800A170582 Responds to IE Insp Repts 50-327/80-14 & 50-328/80-08 All of Bection 3 of facility surveillance Instructions 114 reviewed for compliance w/Section XI of ASME boiler & pressure yeasel MILLS,L M Tennessee Valley Authority 80/06/09 1p
- B006240254 Responds to IE Bulletin B0-12 re decay heat removal systeliability Forwards results of investigation Administrative procedural changes instituted to require at least two independent means of supplying adequate heat removal CROSS.J I Tennessee Valley Authority 80/06/09 3pp
- 8006240260 Forwards response to IE Bulletin B0-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequoyah & Watts Bar is provided by redundant heaters & tank insulation MILLS.L M Tennessee Valley Authority 80/06/09 8pp
- 8006190586 Forwards response to NRC 800321 ltr re noncompliances noted in IE Imap Rept 50-327/80-19 Corrective actions detailed review of 450 supports on safety sys outside containment inibiated & imap of piping configuration undertaken MILLS.L M Tennessee Valley Authority 80/06/12 2pp
- R Periodic operating reports & related correspondence
- BOQ6030080 "NPDES Discharge Monitoring Rept for Feb 1980." * Tennesses Valley Authority 80/03/01 100pp
- 8006130295 Forwards monthly operating rept for May 1980 BALLENTINE, J M Tennessee Valley Authority 80/06/06
- --8006130276 Monthly operating rept for May 1980 * Tennessee Valley Authority 80/06/03 9
- S Reportable occurrences. LERs & related correspondence
- BOO6110250 RO on BOO427/2-inch containment spray test lines analyzed using incorrect outside diameter for pipe resulting in analytical model being more rigid than actual pipe Caused by error in input not found during checking BALLENTING.J M Tennessee Valley Authority BO/05/02 ip

- BOD661031B RO SQRC-50-327/BB049 on BOD514.insufficient clearance found between Support Guide 1-SIH-316 & 4-inch safety injection pipe Apparently caused by incorrect installation due to misinterpretation of specs Guide support repaired BALLENTINE.J M Tennessee Valley Authority BO/05/15 1p
- 8006030397 Forwards LER 60-049/017-0 CALMOUN, J.R. Tennessee Valley Authority 80/03/27 ip
- --8006030408 LER 80-049/01T-O on 800514.support guide, t-81H-87, found w/no clearance at top & bottom or 4-inch safety injection pipe Improper installation caused by misinterpretation of installation specs Support modified SHEARINGEN, J D Tennessee Valley Authority 80/05/22 2pp
- 8006030480 Forwards LER 60-047/017-0 CALHOUN, J R Tennessee Valley Authority 80/05/27 1p
- ---8004030490 LER 80-047/01T-0 on 800513, two support members found to be reversed for hangers Caused by confusion of side by side lines during installation & subsequent reversal Supports removed & reinstalled in proper orientation SMEARINGEN.J D Tennesser Valley Authority 80/05/27 2pp
- 8006030427 Forwards LER 80-043/03L-0 CALHOUN, J R Tennessee Valley Authority 80/05/28 1p
- --8006030447 LER 80-043/03L-0 on 800430, flow suitches FS-90-212 & i41 found inoperable Caused by debris collecting on switch preventing actuation Switch cleaned 3 returned to operable status Dasign change request initiated HEREFORD, J M Tennessee Valley Authority 80/05/28 1p
- 8006030453 Forwards LER 80-051/01T-0 CALHOUN, J R Tennessee Valley Authority 80/05/28 ip
- --8006030460 LER 80-051/01Y-0 on 800516 during IE Bulletin 79-14 support intp.discovered that 1-CVCH-300 was improperly designed Pipe iugs had moved out of hanger due to thermal expansion Caused by design error Lugs lengthened EMEARINGEN, J D Tennessee Valley Authority 80/05/28 2pp
- 8006030457 Forwards LER 80-041/03L-0 CALHOUN, J. R Tennessee Valley Authority 80/05/27 Ip
- --8006030463 LER 80-041/03L-0 on 800430, while in Mode 5, valve 0-FCV-32-10 isolated on low essential air pressure causing valves 1-FCV-90-108, 115, 109, 116, 114 & 110 to close Caute unknown MCORIFF, J N Tennessee Valley Authority 80/05/29 1p
- BOO6050026 Forwards first interim deficiency rept re design of spent fuel pool gates not meeting Seismic Category I requirements MILLS.L M Tennessee Valley Authority 80/05/29 1g
- --800A050031 First interim deficiency rept re spent fuel pool gates not designed to Seismic Category I requirements Cause not stated Evaluation being conducted Complete corrective action will be forwarded by Unit 1 Initial criticality # Tennessee Valley Authority 80/05/29 19
- 800&040394 Forwards LER 80-048/017-0 CALHOUN, J. R. Tennessee Valley Authority 80/05/29 ip
- --800404030 LER 80-048/017-0 on 800515, w/Unit 1 in Mode 3, test switches on containment purge exhaust radiation monitors were discovered to be in test position making monitor inoperable Caused by personnel error Monitors restored OAULT.0 W Tennessee Valley Authority 80/05/28 2pp
- 8006050412 Forwards LER 80-050/03L-0 CALMOUN, J. R. Tennessee Vailey Authority 80/06/02 ip
- --8006060416 LER 80-050/03L-0 on 800505, flow switches F9-90-225 & F9-90-134 found inaperable, which resulted in placing plant into Action 29 Caused by debris collecting on flow switch, preventing actuation Switch cleaned & returned to svc HEREFORD, J M Tennessee Valley Authority 80/06/02 2pp
- 8004090330 Forwards final deficiency rept re Ruskin fire dampers MILLS,L M Tennessee Valley Authority 80/05/02 1p
- --B006090336 Final deficiency rept to Ruskin fire dampers Ruskin developed alternate fix to correct problem w/vertical spring closure & potential for Jammed blades # Tennesses Valley Authority 80/06/02 3pp

- 8006110270 Forwards LER 80-052/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/04 1p
- --BOO6110276 LER BO-052/O3L-O, on BOO506, svc bldg vent monitor was declared inoperable when alarm would not clear in conjunction w/erratic upscale readings Probably caused by high frequency welding Design change has been initiated HEREFORD, J M Tennessee Valley Authority BO/06/04 2pp
- 8006110173 Forwards LER 80-056/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/06/05 ip
- --B006110193 LER B0-056/03L-0 on B00508.common circuit breaker feeding radiation monitors found opened, causing loss of electrical power Caused by personnel overloading circuit Breaker was closed Personnel instructed on proper procedures ROMINE.P F Tennessee Valley Authority 80/06/05 2pp
- 8006110219 Forwards LER 80-064/03L-0 CALMOUN, J R Tennessee Valley Authority 80/06/06 ip
- --8006110223 LER 80-064/03L-0 on 80050S, all zones of ice condenser were giving open door alaims Probably caused by warm air leaking into lower portion of ice condenser Affected doors were blocked closed
 RECORD, D.J. Tennessee Valley Authority 80/06/06 2pp
- 8006110283 Forwards LER 80-054/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/06 1p
- --8006110294 LER 80-054/03L-0 on 800509, design review revealed discrepancies between as-installed insulation weights & those actually used during piping sys analysis Caused by unavailability of drawings
 PREVO.J C Tennessee Valley Authority 80/06/06 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A234WPB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY, J.L. Chemtron Corp., Tube Turns Div. 80/06/06. 3pp
- 8006160069 Notifies of noncompliance w/effluent limitations of NPDES permit Operational sewage treatment plant effluent sample collected on 800521 exceeded 45 mg/liter Caused by accumulation of effluent in sand rifter EE-ABHRY.M T Tennessee Valley Authority 80/06/10 1p
- 8006170554 Forwards LER 80-057/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/10 ip
- --8006170561 LER 80-057/03L-O on 800512, while PT-68-322 out of svc. sense line blew loose at compression fitting taking channel out of svc & leaving less than three operable channels Reactor coolant sys pressure forced line from fitting CURTIS, J W Tennessee Valley Authority 80/04/10 ip
- 800&17053& Forwards LER 80-059/09L-0 GALHOUN, J R Tennessee Valley Authority 80/06/11 1p
- --B006170541 LER 80-059/03L-0 on 800514, during routine exam of process instruments, cooling tower blowdown effluent flow monitor found indicating flow greater than pumps could deliver Cause not stated Flow element will be removed & inspected CURTIS.J W Tennesser Valley Authority B0/06/ii 1p
- 8006170685 Forwards LER 80-063/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/11 ip
- --8006170691 LER 80-063/03L-0 on 800513 operator mistakenly tripped normal feeder from 6 9 kV unit board 28-8 w/o putting synchroscope switches to "on" position Loss of power to 6 9 kV shutdown board 28-A resulted Caused by operator error RECORD, D J Tennessee Valley Authority 80/06/11 2pp
- 8006180521 Forwards LER 80-044/01T-0 CALHOUN, J. R. Tennessee Valley Authority 80/06/11 lp
- --8006180524 LER 80-044/01T-0 on 600507, four Ruskin Mfg Co fire dampers were identified that could potentially fail due to problem in spring closure mechanism Caused by design error in reinforcing bracket All four dampers modified .

 CRAIGOE, E. A. Tennessee Valley Authority 60/06/11 2pp
- 8006(89527 Forwards LER 80-062/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/11 1p

- --8004180533 LER 80~062/03L-0 on 800513 while in Mode 3.2 pairs of containment purge sys lines discovered open Caused by instrument deficiency SOI 30 2A allowing operator to open lower purge valves valves closed upon discovery RECORD, D.J. Tennessee Valley Authority 80/06/11 2pp
- 8006170543 Forwards LCR 80-058/03L-0 CALMOUN, J. R. Tennessee Valley Authority 80/06/12 ip
- --8006170549 LER 80-058/03(-0 on 800514, radiation monitor RM-90-1018 declared inoperable due to erratic upscale readings Caused by arch in microsuit/h in continuous advance operating mode of filter paper drive mechanism
 HEREFORD, J M Tennessee Valley Authority 80/06/12 ip
- BOO6170599 NPDES noncompliance notification on BOO605, pH value of yard drainage discharge OO7 exceeded max permit limitations Cause is unknown investigation will be made 2 corrective measures taken if problem recurs

 EL-ASHRY, M T Tonnessee Valley Authority BO/06/12 ip
- 8006180484 Forwards LER 80-067/03L-0 CALMOUN, J R lennessee Valley Authority 80/06/12 1p
- --8006180487 LER 80-067/03L-0 on 800515, while control room emergency air cleanup fan 8-0 was out or svc. B train ventilation sys rendered inoperable Caused by need to replace substitute equivalent motor w/original Sys ieturned to svc.

 WATSON, W.A. Tennessee Valley Authority 80/06/12 ip
- 8006180530 Forwards LER 80-055/OGL-O CALHOUN, J. R. Tennessee Valley Authority 80/06/12 ip
- --BOO6180535 LFR 80-055/03L-0 on BO0515,duxing Mode 3 testing,loop 2 hot leg resistance temp detector found in error by 3 degrees Caused by higher-than-normal resistance between resistance Lemp detector & process instrument rack FRYE.M E Tennessee Valley Authority BO/06/12 ip
- 8006200451 Forwards LFR 80~066/03L-0 CALMOUN, J R Tennessee Valley Authority 80/06/13 ip
- ---8006200457 LER 80-066/03L-0 on 800516, containment isolation valves FCV1-7, -14, -25 & -32 determined not protected against steam jet resulting from crack in loop 1 main steam riser Caused by design error Action initiated to install proper supports SMEARINGEN, J D Tennossee Valley Authority 80/06/13 2pp
- 80062004BB Forwards LER 80-068/01T-0 CALHGUN, J. R. Tennessee Valley Authority 80/06/13 1p
- --8006200497 LER 80-068/01T-0 on 800530, informed that wide range steam generator level transmitters not qualified to withstand post-accident environ Caused by design error Qualified transmitters being obtained for installation REYNGLDS,R H Tonnessee Valley Authority 80/06/13 2pp
- B006200475 Forwards LFR 80-071/03L-0
 CALHDUN, J R Tennessee Valley Authority B0/06/16 ip
- --B006200484 LCR B0-071/03L-0 on 800517, rupture disc on baric acid evaporator found ruptured, providing path for contents of waste gas decay tank to escape into room Cause unknown Event not immediately discovered due to no radioactivity in tanks RECORD. D J Tennessee Valley Authority 80/06/16 2PP
- 8006240425 Forwards LER 80-0/0/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/16 1p
- --8006240433 LER 80-070/031-0 on 800517.during cooldown from Mode 3. refueling water storage tank water level fell below required limit Caused by failure to initiate early makeup Makeup immediately initiated RECORD.D J Tennessee Valley Authority 80/06/16 2pp.
- 8006240363 Forwards LER 80-075/01T-0 CALHOUN, J R Tennessee Valley Authority 80/06/17 ip
- --8006240367 LER 80-075/017-0 on 600524 auxiliary essential raw cooling pump B-B failed during surveillance testing Caused by personnel error in calculating pump differential pressure Instrumentation recalibr & pump retested SULLIVAN, J H Tennessee Valley Authority 80/06/17 2pp
- 8006240308 Forwards supplemental LER 80-045/017-1 CALHOUN, J R Tennessee Valley Authority 80/06/17 ip

- ---8006240376 Supplemental LER 80-045/017-1 on 800509, gate between spent fuel pool & cask loading area found not to be designed or constructed to Category 1 requirements Caused by overlooking loading effects in sersic analysis MAEHR.5 R Tennessee Valley Authority 80/06/18 2pp
- 8006240328 Forwards final deficiency rept re spent fuel pool gates MILLS-L M Tennessee Valley Authority 80/06/18 ip
- --BOO6240330 Final deficiency rept re spent fuel pool gates QA aspects of gate integrity will be verified Midheight restraints will be attached to pool wall gate to prevent damage to spent fuel elements during seismic event * Tennessee Valley Authority BO/06/18 2pp
- 8006240372 Second interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Review of mod proposed by Westinghouse is not complete Next rept will be submitted by 800724 MILLS, L. M. Tennøssee Valley Authority 80/06/18 ip
- 8006240412 Forwards LER 80~072/03L-0 CALHOUN, J R Tennessee Valley Authority 90/06/18 1p
- ---B006240423 LER 80-072/03L-0 on 80052R, essential raw cooling water effluent menitors O-RE-90-134/141 declared inoperable Caused by spurious high rad spikes & high rad alarm Changeout of relay & further investigations planned HEREFORD, J M Tennessee Valley Authority 80/06/18 ip
- 8006260160 Forwards suppl info for deficiency rept re DBA movements of steel containment vessel
 MILLE, L. M Tennossee Valley Authority 80/06/18 1p
- --9006260162 Suppl info for final deficiency rept re DBA movements of steel containment vessel All addl lines reanalyzed New supports & changes to existing supports needed for RHR spray header piping * Tennessee Valley Authority 80/06/18 ip
- 8004240374 Forwards LER 80-074/03L-0 CALHOUN, J. R. Tennessee Valley Authority 80/06/19 1p
- --8006240380 LER 80-074/03L-0 on 800521.voltage & frequency failed to stabilize while performing surveillance test on diesal generator IB-B Cause unknown Diesel allowed to cool down for 1-h & voltage & frequency stabilized RDMINE,D Tennessee Valley Authority 80/06/19 ig
- 8006240410 Forwards LER 80-061/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/19 ip
- --BDO6240420 LER 80-061/03L-O on 800521.auxiliary bldg.vent radiation monitor.O-RM-90-10B.declared inoperable due to spurious high rad spikes Caused by defective 24-volt power supply Power supply replaced & monitor returned to svc HEREFORD.J M Tennessee Valley Authority 80/06/19 ip
- 8006300516 Forwards LER 80-077/03L-0 CALHOUN, J. R. Tennessee Valley Authority 80/06/24 1p.
- --B006300523 LER-B0-077/03L-O on B00525,8 train RHR & 8 train containment spray pumps were inoperable because valve FCV-63-73 failed to open Caused by valve failing to actuate interlock limit switch RECORD.D J Tennessee Valley Authority 80/06/24 2pp
- V Operator Examinations
- 8006240161 Ack receipt of 800414 ltr requesting review of addl training for future applicants for licenses Concurs w/proposal to licenses nine senior operators at Sequoyah for participation as licensed personnel at Watts Sar SCHWENGER.A Licensing Branch 2 80/06/03 2pp
- DOCKET 50-328 SEGUCYAH NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8006030417 Forwards proposal for seismic margin program, required by NUREG-0611 Program provides basis for NRC to complete evaluation of seismac qualification of structures & equipment necessary for safe shutdown MILLG.L M Tennessee Valley Authority 80/03/27 3pp

- BOO6190327 Discusses review of FSAR Table 17 2-1, "Critical Structures, Sys & Components," re operational GA program Forwards request for addl info to be transmitted to util HAASS, N P Guality Assurance Branch BO/O6/05 4pp
- 8006190615 Advises that Westinghouse responded to NRC questions re Barton Lot 2 transmitters in 800521 ltr.NS-TMA-2248 info applicable to unusual behavior of transmitters at plant during qualification testing MILLS.L.M Tennessee Valley Authority 80/06/13 ipp
- 8006250308 Notification of 800619 meeting w/utils in Bethesda.MD to discuss issuance of full power license for facilities DROMERICK, A. W. Licensing Branch 1 80/06/16 App
- 8006240323 Forwards revised response to Question 12 16 re employee access to high radiation areas Reviston includes description of administrative procedures controlling access to areas adjacent to fuel transfer tube MIELS.L R Tennessee Vatley Authority 80/06/17 2pp
- 8006300391 Forwards revised responses to Questions 031 127.040 60 & 031 127 of NRC 790801 ltr re seismic qualification of Class IE electrical equipment Repts re cable samples & IEEE-323-1974 qualification encl HILLS.L M Tennessee Valley Authority 80/06/23 10pp
- --8006300397 "Delphi Pneumatic Test Procedure " LEWIS: G Comsip. Inc , Delphi Systems Div 75/06/18 2pg
- --8006300400 "Radiation Testing of Cell Number 885, Final Rept " WILLIS, D.E. IRT Corp. 79/08/23 7pp
- --8004300409 "Seismic Vibration Test of Ei0 Series Transmitters " SEARS.J A Acton Environ Testing Corp 76/03/22 30pp
- --B006300414 "Test Procedure for Seranic Vibration, Qualification Test of E10 Series MCA/RRW Transmitters" SEARS.J A. Acton Environ Testing Corp. 73/09/20 25pp
- --B006300422 "Gage & Differential Pressure Transmittors Type E10 Series " SCHREINER,W Acton Environ Testing Corp 73/10/31 10pp
- --8006300429 "Guslification Test of Electrical Cables Under Simulated LOCA/DBE By Sequential Exposure to Environs of Radiation, Thermal Aging, Steam & Chemical Spray "
 * Isomedix, Inc (subs of Maesfield Enterprises, Inc)
 78/06/30 42pp
- F Becurity, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 Itr Add1 specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 61pp
- 8006120528 Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AMEARME.J F Commission 80/05/13 2pp
- 8006050294 Forwards addl info to training & qualification plan Info withheld (ref 10CFR2 790) MILLS.L N Tennessee Valley Authority 80/06/02 2pp.
- 800A130307 Forwards revised schedule for responses to Auriliary Sys Branch fire protection review questions Proposed Train B circuit remoute scheme shown on encl marked up oversite drawings Drawings available in Central Files only MILLS:L K Tennessee Valley Authority 80/06/11 10pp
- 8006260164 Forwards TVA radiological emergency plan & TN multijurisfictional radiological emergency response plan Three cross refs encl MILLS-L M Tennessee Vailey Authority 80/06/17 60pp
- --8006260165 TVA radiological emergency plan
 * Tennessee Valley Authority 80/06/09 250pp
- --B006260166 TN multi-jurisdictional radiological emergency response plan * Tennessee, State of B0/06/19 400pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006110259 Application for Amend 65 to Licenses DPR-72 & CPPR-73, containing revisons to Chapter 3 of FSAR
 MILLS, L N Tennessee Valley Authority 80/06/06 3pp
- --8006110262 Revisions to Chapter 3 of FBAR, providing responses to NRC requests for add1 info re roundation engineering diesel generators 1 inservice insp programs Constitutes Amend 65 to Licenses DRR-72 to CPR-73

 * Tennessee Valley Authority 80/06/06 44pp
- 8006190391 Forwards proposed revisions to facility FSAR, Question 5 9A re inservice insp program Revises request for relief from ASME Section 1), covering third party inspectors, gressure retaining welds in piping 2 steam generator noilles MILLS, L.M. Tennessee Valley Authority 80/06/13 Spp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BOO6230227 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant Units 1 & 2 BOO428 meeting in Washington.DC to continue review of TVA application for license to operate HOYLE, J C Office of the Secretary of the Commission BO/04/04
- 8006190206 Notice of indefinite postponement of ACRS Subcommittee 800428 meeting re Sequoyah Nuclear Plant Units 1 & 2 HOYLE, J C ACRS ~ Advisory Committee on Reactor Bafeguards 80/04/16 1p
- BOO6250074 Notice of ACRS Subcommittee on Sequoyah Nuclear Plant BOO602 meeting in Washington, DC to review OL application Bome closed sessions may be needed to explore matters involving proprietary info HDYLE, J C Office of the Secretary of the Commission 80/05/12 Spn
- 800606060B Transcript of ACRS Subcommittee on Sequoyah Nuclear Power Station meeting on 800402 in Washington DC Pp 1-231 Morning session Viewgraphs & related mattis encl # ACRS Advisory Committee on Reactor Safeguards 80/06/02 300pp
- P Operating license stage documents & correspondence
- BOO6300430 Requests exemption from performing preoperational reduced pressure containment integrated leak rate test Establishment of correlation between full & reduced pressure tests unnecessary MILLS, L H Tennessee Valley Authority BO/06/23 1p
- G Inspection reports. IE Bulletins & correspondence
- 8006060157 Forwards 1E Bullstin 80-11, "Masonry Hall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" enci O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8004180393 Forwards IE Insp Rept 50-328/80-09 on 800421-23 No noncompliance noted MURPHY,C E Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/05/08 2pp
- ---8006180397 IE Insp Rept 50-320/80-09 on 800421-23 No noncompliance noted Major areas inspected licenses identified items & QA audits CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch MACFARLAND.C R Region 2, Atlanta, Dffice of the Director 80/05/08 5pp
- 8006040267 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 Uhile in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta. Office of the Director 80/05/09
- 8005120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13

- 8006170173 Ack receipt of 800506 ltr informing NRC of steps taken to correct deviations noted in 16 Insp Repts 50-327/80-10 & 30-328/80-06 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8006170211 Responds to NRC 800414 ltr re deviations noted in IE Insp Repts 50-327/80-10 \$ 50-328/80-06 Corrective actions detailed instructions 5 procedures prepared Plant fire brigade reconstructed \$ Security Instruction 13 revised MILLS.L M Tennessee Valley Authority 80/05/06 4pp
- --8006170215 Forwards IE Insp Repts 50-327/80-10 & 50-328/80-06 on 800318-21 / natice of deviation MURPHY,C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/14 2pp
- --8006170222 Notice of deviation from insp on 800318-21 * Region 2, Atlanta, Office of the Director 80/04/11 ip
- --B00617022B [E Insp Repts 50-327/80-10 % 50-328/80-06 on B00318-21 Noncompliance noted fire fighting procedures not provided for all safety-related areas CONLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch MILLER.W.H. Region 2. Atlanta, Office of the Director 80/04/11 7pp
- 8006230249 Ack receipt of 800523 ltr informing NRC of eteps taken to correct violations noted in IE Insp Repts 50-327/80-14 & 50-328/80-08 RURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/03 Zpp
- --8006230267 Responds to NRC 80050) Itr re violations noted in IE Insp Repts 50-327/80-14 & 50-328/80-08 Corrective actions Surveillance Instruction 114 will be revised to require examination of Class 2 pressure retaining boltting MILLS,L M Fennessee Valley Authority 80/05/23 3pp
- ---B006230273 Forwards IE Insp Repts 50-327/80-14 & 50-328/80-08 on 800331-0403 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --8006230341 Natice of violation from insp on 800331-0403 * Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/28 10
- 8006200099 Ack receipt of 800522 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/79-34 & 50-327/79-19 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/04 2pp
- 8006170582 Responds to IE insp Repts 50-327/80-14 & 50-328/80-08 All of Section 3 of facility surveillance Instructions 114 reviewed for compliance w/Section XI of ASMC boiler & pressure vessel code MILLS, L. M. Tennessee Valley Authority 80/06/09 1p
- 8006240260 Forwards response to LE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequoyah & Watts Bar is provided by redundant heaters & tank insulation MILLS,L M Tennessee Valley Authority 80/06/09 App
- A Periodic operating reports & related correspondence
- 8006030080 "NPDES Discharge Monitoring Rept for Feb 1980 " * Tennessee Valley Authority 80/03/01 100pp
- S Reportable occurrences, LERs & related correspondence
- 8006030392 Eqrwards final deficiency rept re temp effect on main steam safety valve setpoint MILLS.C. G. Tennessee Valley Authority 80/05/27 1p.

- --8006030398 Final deficiency rept re temp effect on main steam safety valve setpoint Ambient temp affects steam generator temp Valve room temp adjusted by exhaust fan Thermostat added to valve room to limit temp range to 80-120 F # Tennessee Valley Authority 80/05/27 ip
- 8006040306 Forwards fine) deficiency rept re amitted piping rupture protective devices MILLS.L M Tennessee Valley Authority 80/05/29 1p
- ---800604030B Final deficiency rept re pipe rupture protective devices omitted from diawing of 2-inch upper head injection line & steam generator blowdown line Devices will be installed Drawings will be revised to reflect changes

 ★ Tennessee Valley Authority 80/05/29 ip
- 8006050026 Forwards first interim deficiency rept re design of spent fuel pool gates not meeting Seismic Category I requirements MILLS.L M Tennessee Valley Authority 60/05/29 ip
- --8004050031 First interim deficiency rept re spent fuel pool gates not designed to Seismic Category I requirements Cause not stated Evaluation being conducted Complete corrective action will be forwarded by Unit I initial criticality * Tennessee Valley Authority 80/05/27 1p
- B006090330 Forwards final deficiency rept re Ruskin fire dampers MILLS, L M Tennessee Valley Authority 80/06/02 ip
- --8004070334 Final deficiency rept re Ruskin fire dampers. Ruskin developed alternate fix to correct problem w/vertical spring closure & potential for jammed blades
 * Tennessee Valley Authority 80/06/02 3pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by UB Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities SEAY, J. L. Chemtron Corp., Tube Turns Div. 80/06/06 3pp
- BOO6:60069 Notifies of noncompliance w/effluent limitations of NPDES permit Operational sewage treatment plant effluent sample collected on BOO52; exceeded 45 mg/liter Caused by accumulation of effluent in sand filter
 EL-ASHRY, M T Tennessee Valley Authority 80/06/10 1p
- 8006170545 Forwards first interim deficiency rept re design criteria for secondary side pipe breaks Next rept will be submitted by 800904 MILLS.L M Tennessee Valley Authority 80/06/11 1p
- --B004170552 First interim deficiency rept re design criteria for secondary side pipe breaks Criteria does not provide for propagation of main steam cracks to other lines Evaluation underway of pipe rupture interaction * Tennessee Valley Authority 80/06/11 ip
- 8006170659 Forwards revision to 800527 final deficiency rept re temp effect of main steam valve setpoint MILLS,L M Tønnessee Valley Authority 80/06/11 ip
- --8006170672 Revision to 800527 final deficiency rept re temp effect of main steam valve setpoint Heating, ventilation & air conditioning sys for valve rooms being modified to provide narrower temp range of 80-120 f

 * Tennessee Valley Authority 80/06/11 ip.
- 8006170599 NPDES noncompliance notification on 800605,pH value of gard drainage discharge CO7 exceeded max permit limitations.

 Cause is unknown investigation will be made & corrective measures taken if problem recurs

 EL-ASHRY, M T Tennessee Valley Authority 80/06/12 ip
- 8006240328 Forwards final deficiency rept re spent fuel pool gates. MILLS:L M Tennessee Valley Authority 80/06/18 ip
- --8006240330 Final deficiency rept re spent fuel pool gates QA aspects of pate integrity will be verified Midheight restraints will be attached to pool wall gate to prevent damage to spent fuel elements during seismnc event * Tennessee Valley Authority 80/06/i8 2pp
- 8006240372 Second interim deficiency rept re UHI hydraulic isolation valve accumulator weighing sys Review of mod proposed by Westinghouse is not complete Next rept will be submitted by 800724 MILLS, L. M. Tennessee Valley Authority 80/06/18 ip

- 8006260160 Forwards suppl info for deficiency rept re DBA movements of steel containment vessel HILLS.L M Tennessee Valley Authority 80/06/18 ip
- -8006260162 Suppl info for final dericiency rept re DBA movements of steel containment vessel All additions reanalyzed New supports & changes to existing supports needed for RHR spray header piping * Tennessee Valley Authority 80/06/18 1p
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure 5 acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006200062 Notification of 800613 meeting w/util in Bethesda.MD to discuss resumption of & schedule for licensing review Agenda & background info enci HOOD.D S Operating Reactors Branch 3 80/06/02 5pp
- 8006250010 Notification 800613 meeting w/util in Bethesda.MD to discuss resumption of schedules for facility licensing
- HOOD, D B Licensing Branch 2 80/06/02 7pp
- BOO6200361 Forwards new application page as replacement for original submitted 800530 Replacement page necessitated by clerical error consisting of incorrect amend number COOK.J W. Consumers Power Co. 80/05/11 2pp
- --8006200365 Amend 78 to application for CP & OL, revising application page to correct amend number COUK, J N Consumers Power Co 80/06/11 ip
- 8006300650 Forwards requests for addl field explorations & info Corps of Engineers has requested addl borings & soil data to permit verification of util conclusions re plant fill settlement problem & foundation design KNIGHT.JP Assistant Director for Components & Structures Engineering 80/06/13 7pp
- --8006300655 Forwards revised Encl 1 to 900327 request for addl borings & MCCALLIBTER,P Army,Dept of, Corps of Engineers 80/04/30 App
- 8006240409 Advises NRC that util has developed tentative timetable for submitting cost & const schedule revisions Info will be incorporated into Revision II of environ rept & submitted to NRC by 800915 CDDK.J W Co Consumers Pawer Co 80/05/20 1p
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Add1 specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 6ipp
- 8006230031 Notification of 800611 meeting w/util in Bethesda, MD to discuss facility security plan HOOD, D S Licensing Branch 3 80/06/10 3pp
- G Adjudicatory correspondence
- 8006120045 Response in opposition to M Sinclair 800402 motion to produce documents Reserves Fight to move for protective order if campelled to produce Request is too broad & outside scope of proceeding Certificate of Svc encl FARNELL.A S Consumers Power Co FARNELL.A S Isham, Lincoln & Beale 80/05/07 App
- 8004050044 Answer in support of NRC 800400 motion for issuance of amended notice of hearing re 791206 order modifying CPs. Beconds NRC request to serve copies of amend when granted, to all OL proceeding parties Centificate of Svc encl FARNELL, A S Consumers Power Co FARNELL, A S Isham, Lincoln Beale 80/05/15 3pp Isham, Lincoln &
- 8006050565 Advises that CPC answer to NRC motion for amended notice of hearing & CPC answer to notice of hearing re CP mod have been incorrectly served SMITH, I W Atomic Safety and Licensing Board Panel 80/05/20 1p

- 8004180586 Forwards display advertisement re hearing on order for mod or CP Advertisement will be printed in local newspapers FR notice of hearing A amended notice of hearing were published 800320 1 0928, respectively SCHMERCER, A Licensing Branch 3 80/05/30 1p
- 800ái10261 Requests permission for Mapleton intervenor consultants to attend 800ái3 meeting in Bethesda,MD MARSHALL,W H Affiliation Unknown 80/06/09 ip
- 8006180302 Response to CPC 800527 motion for partial consolidation of discovery Moves for permission to postpone further response until determination of intervention Urges permission for 800627 filing if postponement denied W/Certificate of Svc PATON.W D Hearing Branch 4 80/06/16 8pp
- 8004230365 Petition to intervene re order for mod of CPs Alleges inefficient exercise of atomic energy use which will create adverse environ effects on Cities of Midland, Saginaw & Bay City Certificate of Svc encl GILBERT. C Affiliation Unknown 80/06/16 3pp
- 8006300423 Requests admittance as intervenor in hearing re CP mod Admittance on previous occasions accepted MARSHALL.W H hapleton Intervenors 80/06/23 1p
- H General correspondence
- 8006110073 Requests that future correspondence be mailed to JW Cook at 1945 West Parnall Road. Jackson. Hi COOK. J. W. Consumers Power Co. 80/06/05 ip
- B00611025B Praises NRC position re insp % testing of safety-related sto concrete items & objections due to exceptions taken in concrete const Requests info re implication in NRC 800522 ltr to util that exceptions in QC requirements made MARHSALL,W H Mapleton Intervenors 80/06/05 2pp
- BOD6170569 Notifies of inability to attend BO0613 meeting in Bethesda,MD due to lack of timely info Requests that timely notification be given in future MARSHALL,W H Mapleton Intervenors BO/06/14 ip
- 8006300392 Forwards WH Marshall 800410 ltr re const of facility Requests copy of reply DURENBERGER, D. Senate, Finance 80/06/18 1p
- --8006300395 Urges Commission to take action to halt facility const Citizen rights are being overlooked by imposing future radioactive abuses & conditions in violation of Constitution Ltr will be sent to all senators & news media MARSHALL, W H Affiliation Unknown 80/04/10 2pp
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8006090308 Forwards Revision 28 to FSAR & supplemental piging & instrument ref diawings Amend 77 to combined CP & CL application encl Brawings available in Central Files only COUK. J W Consumers Power Co 80/05/30 ip
- --B006090309 Amend 77 to combined CP & DL application, revising & adding UNAVOCATA AMERICA // to committee or a dispersion info to FSAR COOK.J N Consumers Power Co 80/05/30 1p
- --8006090312 Revision 28 to FSAR, providing changes in various sections resulting from routine design developments & re-review program Constitutes Amend 77 to combined CP & OL application

 * Consumers Power Co 80/09/30 550pp Consumers Pawer Co 80/09/30 550pp
- BOO6180362 Forwards Certificate of Svc for Amend 78 to CP & OL applications.consisting of Revision 28 to FBAR BACON, J L Consumers Powet Co 80/06/09 2pp
- 8004240397 Forwards Certificate of Syc for 800611 ltr submitting Amend 78 to application for CPs \$ DLs, consisting of Revision 28 to FSAR BRUNNER.J F Consumers Power Co 80/06/20 2pp
- M Antitrust consespondence
- BOO62303BO Responds to BOO530 ltr seeking status of proposed settlement consideration ASLB unable to predict date of formal decision but decision process is entering final phase CLARK. H K Atomic Safety and Licensing Board Panel BO/06/16 lp

- G Inspection reports. 1€ Bulletins > correspondence
- 8006170755 Forwards IE lnsp Repts 50-327/80-10 % 50-330/80-10 on 800201-29 & notice of violation FIDRELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006170758 Notice of violation from insp on 800201-29
 Region 3. Chicago, Office of the Director 8070 80/04/22 1p
- ---8006170763 IE Insp Repts 50-329/80-10 * 50-330/80-10 on 800201-29 Noncompliance noted failure to properly follow work procedure for trail fit-up of internal core support assembly Assembly (COOK.R) Region 3, Chicago, Office of the Director (87/04/22 6pp
- 8006060017 Advises that complete review of certain ASME safety-related pipes was subnitted in 790716 response to IE Bulletin 79-03 Actions & conclusions described close out IE Bulletin 79-HOWELL, S H Consumers Power Co 80/05/07 1p
- 8006060223 Forwards corrected pages to IE Imap Repts 50-329/80-09 & 50-330/80-10 FIORELLI, G Region 3, Chicago. Reactor Construction & Engineering
- Support Branch
- --8005050225 Corrected Pages 1 % 3 to IC Insp Repts 90-329/80-07 & 50-330/80-10 on 800201-27 COCK.R J. KNOP.R C Region 3. Chicago, Office of the Director 80/05/09 2pp
- 8006250306 Forwards IE Insp Repts 50-329/80-11 & 50-330/80-12 on S00430-0507 No noncompliance nated FIGRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/16 2pp
- --8006250310 IE Insp Repts 50 329/80-11 % 50-330/80-12 on 800430-0502
 No noncompliance noted Major areas inspected installation of safety-related hangers % restraints / review of GC records DANIELEGN.D H Region 3. Chicago. Reactor Construction & Engineering Support Branch YIN.I T Region 3. Chicago. Defice of the Director 80/05/15 5pp
- 8006300139 Forwards IE Insp Repts 50-329/80-14 & 50-330/80-15 on 800502 No noncompliance noted REPPLER. J. G. Region 3, Chicago, Office of the Director 80/05/22
- --B004300152 IE Insp Repts 50-329/80-14 & 50-330/80-15 on B00502 No NUMBER OF SET INSP. Repus 30-32/780-14 & 30-33/780-15 on 600302 No noncompliance noted Major areas inspected reactor vessel heldown anchor bolts ? Region 3 findings on allegations re heating ? ventilation installation NNDP.R C. Region 3, Chicago, Office of the Director fidReLLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Dranch 80/05/21 4pp
- 8006230213 Responds to IE Bullotin 79-03A. "Longitudinal Weld Defects in ASME BA-312. Type 304 Stainless Steel Pipe "Further review of manufacturers of ASME SA-312. Type 300 Series welded pipe indicates ief in util 800507 ltr is incorrect COOK. J W Consumers Power Co B0/06/04 Ip
- 8006240585 Forwards interim response to IE Bulletin 80-05, "Vacuum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tanks" Vacuum relief valves will be covered by periodic maint program List of insp results encl COOK. J W Consumers Power Co 80/06/09 6pp
- GOD6200527 Ack receipt of 800515 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-329/80-01 t 50-339/80-01 FIGRELI, & Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/06/10 1p
- --B006200537 Responds to NRC B00418 ltr re violations noted in IE lnsp Repts 50-329/B0-01 & 50-330/B0-01 Corrective actions freeze will be placed on implementing design changes 90 days prior to scheduled turnover Consumers Power Co 80/05/15 3pp
- 8006260325 Ack receipt of 800522 ltr informing NRC of ateps taken to correct violation noted in IE Insp Repts 50-329/80-09 & 50-330/80-10 FIDRELLI-Q Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/ii 1p

- --8006260342 Responds to NRC 800426 ltr re violation nated in IE Insp Repts 50-329780-09 & 50-339780-10 Corrective actions noncommonce rept re failure to approve acceptance criteria mod for reactor vessel levelness was issued CDOK J W Consumers Power Co 80705722 3pp
- R Periodic operating reports & related correspondence
- 8006300437 Forwards Bechtel, 82W & CPC nonconformance repts, Bechtel nonconformance rept log sheets & GR requests & CPC corrective action repts for month ending 800531 CDDK.J W Consumers Power Co 80/06/12 400pp
- S. Reportable occurrences, LERs & related correspondence
- 800620000B Part 21 rept re classification of dampers Bechtel Power Corp classifies dampers as nonsafety-related equipment Dampers do not have potential to create substantial safety hazard & do not fall under Part 21 reporting requirements SLOAM:DE American Warming & Ventilating, Inc 80/06/03 2pp
- 8006200024 Final Part 21 rept is mised heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tass were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities Chemtron Corp , Tube Turns Div 80/04/06 3pp
- BOOM180266 Interim deficiency rept re internal containment coatings having loss of adhesion between successive layers of coating sys Procedures? tosting methods for removal of failed coatings under preparation Next rept will be sent by BOO915 COOK.J W. Consumers Power Co. 80/06/11 3pp
- 8006290200 Ack receipt of 800516 interim rept re reactor vessel broken anchor bolts FIGRELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/05/11
- 8006250360 Ack receipt of 800522 interim deficiency rept re N888 component identification Will review final rept on matter upon receipt FIORELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/06/11 is
- 8006160009 Interim deficiency rept re Unit 1 reactor vessel broken anchor bolt Forwards Addendum 1. "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Studs "Next rept will be sent by 800801 CDCK.J W Consumers Power Co 80/06/12 2pp
- --8006160008 Addendum 1. "Investigation of Preservice Failure of Midland Reactor Pressure Vassel Anchor Studs," for Bachtel Corp * Teledyne Engineering Services TR-3887-1 ADD1 80/06/06
- 8006180467 Interim deficiency rept re component qualification test documentation re-review Util developing program & schedule to complete review & provide associated documentation requested Interim or final rept will be sent by 800919 COOK, J W Consumers Power Co 80/06/13 60pp
- 8006300277 Interim deficiency rept re potential overstressed condition in letdown cooler supports B&W analysis of nozzle idads for effects on support structure is complete Loads are confirmed to exceed allowable loads Redesign planned CODK.J W Consumers Power Co 80/06/19 ip
- V Operator Examinations
- 8006240161 Act receipt of 800414 itr requesting review of addl training for ruture applicants for licenses Concurs w/proposal to license nine senior operators at Sequeyah for participation as licensed personnel at Watts Bar SCHMENCER, A Licensing Branch 2 80/06/03 2pp
- DOCKET 50-330 MIDLAND PLANT: UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D & Division of Licensing 80/05/20 ISpp

- 8006200062 Notification of 800613 meeting w/util in Bethesda.MD to discuss resumption of % schedule for licensing review Agenda % background info encl HODD.D S Operating Reactors Branch 3 80/06/02 5pp
- 80062500iO Notification 800613 meeting w/util in Bethesda,MD to discuss resumption of schedules for facility licensing review HOOD,D S Licensing Branch 2 80/06/02 7pp
- 8006200361 Forwards new application page as replacement for original submitted 800530 Replacement page necessitated by clerical error consisting of incorrect amend number COOK.J W Consumers Power Co 80706/11 2pp
- --8006200365 Amend 78 to application for CP & OL, revising application page to correct amend number COOK, J W. Consumers Power Co. 80/06/11 ip
- 8006180242 Forwards "Independent Piging Analysis, Midland Unit 2 (Current Design Info)," in response to NRC 800410 request Oversize drawings encl CODK.J W Consumers Power Co 80/06/12 100pp
- 8006300650 Forwards requests for addl field explorations & info Corps of Engineers has requested addl borings & soil data to parmit verification of util conclusions re plant fill settlement problem & foundation design KNIGHT.J P Assistant Director for Components & Structures Engineering 80/06/13 7pp
- --8006300655 Forwards ravised Encl 1 to 800327 request for Addl borings & soil data MCCALLISTER, P. Army, Dept of, Corps of Engineers 80/04/30 App
- 8006240409 Advises NRC that util has developed tentative timetable for submitting cost & const schedule revisions Info will be incorporated into Revision II of environ rept & submitted to NRC by 800919 CDDK, J W Consumers Power Co 80/06/20 ip
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addi specific criteria for facilities under development EISENHUT, D O Division of Operating Reactors 80/04/25 41pp
- 8006230031 Notification of 800611 meeting w/util in Bethesda, MD to discuss facility security plan H00D, D. S. Licensing Branch 3 80/06/10 3pp
- G Adjudicatory correspondence
- 800A120045 Response in opposition to M Sinclair 800402 motion to produce documents Reserves right to move for protective order if compalled to produce Request is too broad & outside scope of proceeding Centificate of Svc encl FARNELL. A S Consumers Power Co FARNELL, A S Isham. Lincoln & Beale 80/05/07 App
- 8006050044 Answer in support of NRC 800430 motion for issuance of amended notice of hearing re 791206 order modifying CPs Seconds NRC request to serve copies of amend-when granted to all GL proceeding parties Certificate of Svc encl FARNELLIA S Consumers Power Co FARNELLIA S Isham, Lincoln & Beale 80/05/15 3pp
- BOOSO5655 Advises that CPC answer to NRC motion for amended notice of hearing & CPC answer to notice of hearing re CP mod have been incorrectly served SMITM.I W Atomic Safety and Licensing Board Panel BO/05/RO 1p.
- BOO4:BOSBA Forwards display advertisement re hearing on order for mod of CP Advertisement will be printed in local newspapers PR notice of hearing & amended notice of hearing were published BOO520 & O52B; respectively BCHWENCER: A Licensing Branch 3 BO/O5/30 1p

- 8006230365 Petition to intervene re-order for mod of CPs Alleges inefficient exercise of atomic energy use which will create adverse environ effects on Cities of Midland, Saginaw & Bay City Certificate of Svc encl GILBERT, C Affiliation Unknown 80/06/16 3pp
- 8006300423 Requests admittance as intervenor in hearing re CP mod Admittance on previous occasions accepted MARSHALL.W H Mapleton Intervenors 80/06/23 1p
- H General correspondence
- 8004110073 Requests that future correspondence be mailed to JH Cook at 1945 Nest Parnall Road Jackson MI CODY. J H Consumers Power Co 60/06/05 1p
- 8006110258 Praises NRC position relins & testing of safety-related state oncrete items & objections due to exceptions taken in concrete const Requests info relimplication in NRC 800522 ltr to util that exceptions in GC requirements made MARHSALL, W. H. Mapleton Intervenors 80/06/05 2pp
- 8006170569 Notifies of inability to attend 800613 meeting in Bothesda.MD due to lack of timely info Requests that timely notification be given in future MARSHALL.N H Mapleton Intervenors 80/06/14 ip
- 8006300392 Forwards WH Marshall 800410 ltr re const of facility Requests copy of reply DVRENBERGER,D Senate, Finance 80/06/18 lp
- --BOO4300395 Urges Commission to take action to halt facility const Citizen rights are being overlooked by imposing future radioactive abuses & conditions in violation of Constitution Ltr will be sent to all senaturs & news media MARSHALL,W H Affiliation Unknown BO/04/10 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 800607030B Furwards Revision 2B to FSAR & supplemental piping & instrument ref drawings Amend 77 to combined CP & OL application encl Drawings available in Central Files only GOBK, J W Consumers Power Co 80/05/30 ip
- --B006090309 Amend 77 to combined CP & DL application, revising & adding info to FSAR COCK, J W Consumers Power Co 80/05/30 ip
- --8006090312 Revision 28 to FSAR, providing changes in various sections resulting from routine design developments & re-review program Constitutes Amend 77 to combined CP & OL application # Consumers Power Co 80/05/30 550pp
- 8006180062 Forwards Certificate of Svc for Amend 78 to CP & GL applications, consisting of Revision 28 to FGAR BACON, J.L. Consumers Power Co. 80/06/09 Rpp
- 8006240399 Forwards Certificate of Svc for 800611 ltr submitting Amend 78 to application for CPs & DLs. consisting of Revision 28 to FBAR BRUNNER.J F Consumers Power Co 80/06/20 2pp
- M Antitrust correspondence
- 8006230380 Responds to 800530 itr seeking status of proposed settiment consideration ASLB unable to predict data of formal decision but decision process is entering final phase CLARK, H K Atomic Safety and Licensing Board Panel 80/04/16 is
- Q Inspection reports. IE Bulletins & correspondence
- 8006020080 Forwards IE Insp Rept 50-330/80-09 on 800325-27 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006020084 IE Insp Rept 50-330/80-09 on 800325-27 No noncompliance noted Major areas inspected containment prestressing work procedures, work activities & quality records HAYES, D W Region 3. Chicago, Reactor Construction & Engineering Support Branch GALLACHER, E J Region 3. Chicago, Defice of the Director 80/04/18 4pp

- 8006170755 Forwards JE Insp Repts 50-329/80-10 & 50-330/80-10 on 800201-29 % notice of violation FIDRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006170758 Notice of violation from insp on 800201-29

 * Region 3, Chicago, Office of the Director 80/04/22 1p
- --8004170743 IE Insp Repts 50-329/80-10 & 50-339/80-10 on 800201-29 Noncompliance noted failure to properly follow work procedure for trail fit-up of internal core support assembly KNDP,R C. CODK,R J. Region 3. Chicago. Office of the Director RG/244/22 400
- 8006060017 Advises that complete leview of certain ASME safety-related pipes was submitted in 790716 response to IE Bulletin 79-03 Actions 3 conclusions described close out IE Bulletin 79-03A-HOWELL,S-H Consumers Power Co
- 8006040223 Forwards corrected pages to I€ Insp Repts 50-329/80-09 & 50-330/80-10 FIORELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/12 tp
- --8004060226 Corrected Pages 1 & 3 to IE Insp Repts 50-329/80-09 & 50-330/80-10 on 800201-29 CCDK.R J. KNOP.R C Region 3. Chicago. Office of the Director 80/05/09 2pp
- 8006250306 Forwards IE insp Repts 50-329/80-i1 & 50-330/80-i2 on 800430-0592 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/16 2pp
- ---8006250310 IE Insp Repts 50-327/80-11 & 50-330/80-12 on 800430-0502
 No huncompliance noted Major areas inspected installation of safety-related hangers & restraints / review of 0C records
 DANIELSON.D H Region 3. Chicago, Reactor Construction & Engineering Support Branch YIN.I T Region 3. Chicago, Office of the Director 80/05/15 5pp
- 8006300139 Forwards IE Insp Repts 50-329/80-14 & 50-330/80-15 on 800502 No noncompliance noted KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/22 2pp
- --8006300152 IE Insp Repts 50-329/80-14 & 50-330/80-15 on 800502 No noncompliance noted Major areas inspected reactor vessel holdown anchor bolts & Region 3 findings on allegations re heating & ventilation installation KNDP, R C Region 3. Chicago. Office of the Director FIGRELLI, Q Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/21 4pp
- 8006230213 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe "Further review of manufacturers of ASME SA-312. Type 300 Series welded pipe indicates ref in util 800507 itr is incorrect COOK. J N Consumers Power Ca 80/06/04 1p
- 8006240585 Forwards interim response to IE Bulletin 80-05,"Vacuum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tanks "Vacuum rolief valves will be covered by periodic maint program List of insp results encl COOK.J W Consumers Power Co 80/06/09 App
- 8006200527 Ack receipt of 800515 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/80-01 & 50-330/80-01 FIORELULG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/10 ip
- --8006200537 Responds to NRC 800418 ltr re violations noted in IE Insp. Repts 50-329/80-01 & 50-330/80-01 Corrective actions freeze will be placed on implementing design changes 90 days prior to scheduled turnover CODK, J W Consumers Power Co 80/05/15 3pp
- BO06260325 Ack receipt of 800522 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-329/80-09 & 30-330/80-10 FIGRELLI.6 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/11 ip
- Support Branch 80/06/11 1p

 ---8006260342 Responds to NRC 800426 ltr re violation noted in IE Insp
 Repts 50-329/80-09 % 50-330/80-10 Corrective actions
 noncomformance rept re failure to approve acceptance
 criteria mod for reactor vessel levelness was issued
 CDQK.J W Consumers Power Co 80/05/22 3pp

- R Periodic operating reports & related correspondence
- 8006300437 Forwards Bechtel, B&W & CPC nonconformance repts, Bechtel nunconformance rept log sheets & GA requests & CPC corrective action repts for month ending 800931 CODK, J W Consumers Power Co 80706/12 400pp
- S Reportable occurrences. LERs & related correspondence
- 800620000B Part 21 rept re classification of dampers Bechtel Power Corp classifies dampers as nonsafety-related equipment Dampers do not have potential to create substantial safety hazard & do not fail under Part 21 reporting requirements SEOAN.D E American Warming & Ventilating, Inc. 80/06/03 Rpp
- B006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A2344PB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY.JL Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8004180266 Interim deficiency rept re internal containment coatings having loss of adhesion between successive layers of coating sys Procedures & testing methods for removal of failed coatings under preparation Next rept will be sent by 800915 CODM.JW Consumers Power Co 80/06/11 3pp
- 8006250200 Ack receipt of 800516 interim rept re reactor vessel broken anchor bults FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8006250360 Ack receipt of 800522 interim deficiency rept re NBS8 component identification Will review final rept on matter upon receipt FIORELLI. G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8006i60005 Interim deficiency rept re Unit 1 reactor vessel broken anchor bolt Forwards Addendum 1. "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Studs "Next rept will be sent by 800801 C
- --8006160008 Addendum i. "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Studs," for Bechtel Corp * Teledyne Engineering Services TR-3887-1 ADDI 80/06/06 23pp
- 8006180469 Interim deficiency rept re component qualification test documentation re-review. Util developing program & schedule to complete review & provide associated documentation requested interim or final rept will be sent by 800919. COOK. J W Consumers Power Co 80/06/13 60pp
- 8006300277 Interim deficiency rept re potential overstressed condition in letdown cooler supports B&N analysis of noizle loads for effects on support structure is complete Loads are confirmed to exceed allowable loads Redusign planned COOK.J W Consumers Power Co 80/06/19 ip
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

 F Security, medical, energency & fire protection plans
- 8006020247 Notifies that new telephone sys called Health Physics Natwork (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER.J G Region 3. Chicago. Office of the Director 80/04/18 200
- BOO6040144 Forwards review of emergency plan against criteria contained in NUREQ-0654 Per BO0423 meeting.glan will be revised to incorporate NRC review 4 resubmitted by BO0623.
 IPPOLITO: A Operating Reactors Branch 2 80/05/15 16pp
- BOO6090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May.

 EISENHUT.D G Division of Licensing 80/05/19 · 44pp
- 8006030365 Forwards fire protection review. Item 3 2.3 re fire barrier penetration test data.

 HALL-R E Brookhaven National Laboratory 80/05/22 2pp.

- BOO6130063 Forwards revised Pages I-14 % new Page 14a for proposed role 100FRSO "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC B00519 ltr Page 14a not encl EISENHUT, D O Division of Licensing 80/05/22 73pp
- 8006190113 Requests participation in study of people-related problems in nuclear safeguards NRC representatives will visit facility & interview security mgt personnel ippOLITO, T A Operating Reactors Branch 2 80/06/03 2pp
- 8006160133 Discusses commitments made during 800430 meeting Revised emergency plan will be submitted by 800722 Response to NRC 800307 itr re radiological & environ monitoring will be provided by 800627 ROUTLD lower Electric Light & Power Co 80/06/04 ip
- R006:90:22 Forwards status summary of fire protection safety evaluation open issues.NRC positions on issues & BNL evaluations of fire protection review IPPOLITO.T A Operating Reactors Granch 2 80/06/04 5pp
- 8006170539 Forwards partial response to 791022 ltm re alternate safe shutdown capability Response partial & should be considered preliminary Detailed analysis in process of final review Final review of analysis should be completed within two wks ROOT, L D I lowa Electric Light & Power Co 80/06/05 Jpp
- 8006180400 Submits special rept re standby diesel generator day tank room fire protection sprinkler sys Rept describes sprinkler mods & corrective actions taken during sys imperability to ensure plant safety & restore sprinkler sys capability MINECK,D L. Iowa Electric Light & Power Co. 80/06/09 2pp
- 8006250270 Summary of 800529 meeting w/util in Dethesda.MD re emergency preparedness for facility
 KEVERN.T A Operating Reactors Branch 2 80/06/11 4pp
- 8006240183 Forwards page changes to modified amended security plan Changes withheld (rof 100FR2 770) ROOT,L D Iowa Electric Light & Power Co 80/06/17 1p

Q Adjudicatory correspondence

- 8006160091 Order granting extension until 800625 for Commission to slect whether to review Director's 800213 decision denying patition re Mark 1 containment under 100FR2 206 CHILKS J Office of the Socretary of the Commission 80/06/11
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing erams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D O Division of Licensing 80/03/07 150pp
- 8004030514 Summary of 800922-23 meating w/Mark I owners group in San Jose CA To confirmatory analysis & testing programs concerning Mark I containment long-term program GRIMES-C I Assistant Director for Plant Systems 80/05/07 8pp
- BOO6130122 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D G Division of Licensing 80/05/19 72pp
- BOO6300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREO-0619, "BUR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking 'Comments will be evaluated by NRC prior to final implementation W/o encl £18ENHUT.D O Division of Licensing 80/05/05 22pp

- --8006250282 Safety evaluation supporting average power range monitor channel gain adjustments during reactor startup & approach to full power * Operating Reactors Branch 2 80/06/11 3pp
- 8006230370 Submits schedule for response to NRC 800425 ltr re effect of dc power supply failule on ECCS performance Response will be provided by 800731 RDGT.L D Towa Electric Light & Power Co 80/06/16 ip
- 8008230501 Forwards proposed changes to facility Tech Specs per MRC H00410 request & 10CFR50 59 & 10CFR50 90 requirements ROOTAL D lowa Electric Light & Power Co 80/06/17 2pp
- --B006230504 Proposed reactor Tech Spoc change 121, amending App A of License DPR-49 Reflects request for more detailed definition of "operable," deletes single recirculation loop license amend? updates facility starting section # lowa Electric Light & Power Co B0/06/17 32pp
- Q Inspection reports: IF Bulletins & correspondence
- 8004200102 Forwards IE Circular 80-08, "BWR Tech Spot Inconsistency Reactor Protection Sys Response Time " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/10
- 8008170781 Forwards IF Insp Rept 80-331/80-04 on 800407-10 No noncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/05 2pp
- ~-B006170766 IE Insp Rept 50-331/80-06 on 800407-10 No noncompliance noted Major areas inspected specs, procedures, observation of work, internal torus mods & ultrasonic exam of jet pump beams
 DANTELSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branch KEY.N J Region 3, Chicago, Office of the Director 80/05/02 App
- BOOA030467 Forwards supplementary response to IE Bulletin 77-18 re audibility problem encountered during personnel evacuation Evaluation of alarm sys in inaccessible areas of plant identified two areas where alarm is not audible ROOT, L.D. Iowa Electric Light & Power Co. 80/05/06. 2pp
- 8006030483 Forwards response to Item 3 of IE Bulletin 79-26, "Beron Loss from BWR Control Blades " Shutdown margin test verified that full withdrawal of any control blade from xenon-free core will not result in criticality ROOT,L D Jowa Electric Light & Power Co 80/05/08 2pp
- B006060003 Forwards request for add1 info re turbine disc cracking to learn more about underlying reasons for indications & probable growth rate IE Info Notice 79-37 & summary of 800109 meeting w/GE encl IPPOLITO.T A Operating Reactors Branch 2 80/09/16 3pp
- 8006020062 Ack receipt of 800508 ltr informing NRC of steps taten to currect violations noted in IE Insp Rept 50-331/80-05 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Beanch B0/05/21 ip
- ~-8004020044 Responds to NRC 800421 ltr re violations noted in IE Irja
 Rept 50-331/80-05 Corrective actions plant supervisors given
 training on notification of unplaumed releases & batch
 sampling requirements
 ROOT.L D Towa Electric Light & Power Co 80/05/08 3pp
- B006230205 Act receipt of B00430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/80-04 HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch B0/05/30 2pp
- --8006230209 Responds to NRC 800408 ltr re violations noted in IE [mij Rept 50-331/80-04 Corrective actions plant managers were advised of requirements of Tech Spec 6 8 3 that temporary procedure changes be only minor in nature RODT.L D lowa Electric Light & Power Co 80/04/30 3pp
- BOO6240255 Responds to [E Bulletin BO-O6, "Engineered Safety Fisiums (ESF) Reset Controls " Test procedures are being developed to test engineered safety feature equipment Forwards oversize drawings brawings available in Central Files only ROOT, L D lowa Electric Light & Power Co 80/06/1/ 32pp
- --8006260344 "Reactor Care Cooling Sys " Sheet 42 * Bechtel Corp 7884 73/12/04 1p

- --8006260363 "Reactor Core Looling Sys " Sheet 58 * Bechtel Corp 7884 74/01/15 19
- --8006260395 "Nuclear Steam Supply Shutoff Sys " Sheet 24 (ACTUAL REVISION STATUS DCR 706.800304) * Bechtel Corp 7884 74/04/11 1p
- ---8006260401 "Nuclear Steam Supply Shutoff Sys " Sheet 10 (ACTUAL REVISION STATUS DCR 908,800219) * Bechtel Corp 7884 75/11/17 1p
- --8006260431 "Elementary Diagram Nuclear Steam Supply Shutoff Sys " Sheef 7 * General Electric Co 74/02/24 1p
- ---8006260499 "Elementary Diagram Nuclear Steam Supply Shutoff Sys "
- * General Electric Co 73/06/15 ip
- R Persodic operating reports & related correspondence
- 8006190461 Forwards monthly operating rept for May 1980 MINECK.D L lows Electric Light & Power Co 80/06/13 ip
- --B006190464 Monthly operating rept for May 1980 VAN BICKEL, J. Towa Flectric Light & Power Co. 80/06/13 7pp
- S Reportable occurrences, LERs & related correspondence
- 8006110335 RO on 800227, during refueling outage insp of reactor core isolation cooling turbine governor end & pump end journal bearings upper caps found partially wiped Gause undetermined Governor end & pump end journal replaced MINECK.D L. Iowa Electric Light & Power Co 80/05/23 App
- 8006030277 Forwards LER 80-018/017-0 MINECK,D L. lowa Electric Light & Power Co. 80/05/27 ip
- ---9006030298 LER 80-018/01T-0 on 800519.oil drain petcock on hydraulic governor found open w/no oil indication on sight glass Causa unknown Petcock closed & oil added TUDKER.D W Iowa Electric Light & Power Co 80/05/27 2pp
- --BOO6030441 LER 80-019/01T-0 on BO0520, three 5-amp fuses servicing A, B & C annunciator cabinets in panel 1003 blew during shift alarm testing Resulted in loss of both channels of core spray spanger break detection alarm sys Cause unknown TOCKER, D W Jowa Electric Light & Power Co 80/05/27 2pp
- 8006030467 Forwards LER 80-017/03L-0 MINECK.D L. Iowa Electric Light & Power Co 80/05/27 ip
- --8006030473 LER 80-017/03L-0 on 800430.A reactor circulation pump motor generator set tripped Caused by electrical short in motor Cause of short unknown Motor removed & rewound TDDKER.D W lowa Electric Light & Power Co 80/05/27 ip
- 6006090339 Forwards updated LER 78-021/03X-1 MINECK.D.L. lawa Electric Light & Power Co 80/06/02 ip
- ---8006090346 Updated LER 78-021/03X-1 on 780401 during performance of preventive maint, two control rod drive hydraulic control unit water level switches would not respond Caused by switch plastic float becoming stuck
 DUBOST, E L lowa Electric Light & Power Co 80/06/02. 1p
- BOO6090371 Forwards updated LER 79-016/01X-1 MINECK,D L lowa Electric Light & Power Co 80/06/02 1p
- --8006090380 Updated LER 79-016/01X-1 on 790725, during normal operation, plant heat rates & efficiencies determined to be better than normally expected investigation revealed leaking instrument causing measurement error DUBOST, E. L. Iowa Electric Light & Power Co 80/06/02 2pp
- 8006170658 Forwards updated LER 79-014/01X-1 MINECK.D L Iowa Electric Light & Power Co 80/06/09 1p

- --8006170665 Updated LER 79-014/01X-1 on 790703, results of testing re IE Bulletin 79-02 indicated potential generic problem w/anchor bults not meeting seismic design criteria Caused by faulty installation & inadequate design DUBGST.E lowa Electric Light & Power Co 80/06/09 2pp
- 8006230432 RO on 800515, standby diesel generator day tank room sprinkler sys removed from svc for mod Mod work took longer than anticipated & sprinkler sys inoperable for more than 14 days Fire watch established until mod completion MINECK.D L lowa Electric Light & Power Co 80/06/09 2pp
- 8006270258 Forwards LER 80-021/03L-0 MINECK.D L lowa Electric Light & Power Co 80/06/20 ip
- --8006270261 LER 80-021/03L-0 on 800524, while performing HPCI operability testing, HPCI turbine would not reach rated speed within required time Caused by component failure Leather hydraulic seal in stop valve replaced wi80MA-M seal TODXER.D W Jowa Electric Light & Power Co 80/06/20 ip
- B006R70R64 Forwards LER 80-020/03L-0 MINECK.D L lowa Electric Light & Power Co B0/06/20 ip
- --80D6270267 LER 80-020/03L-0 on 800523 during normal surveillance testing of emergency bus tame delay relays seven Gould ITE-27D undervoltage relays found to have excessive delays Caused by instrument drift Relays recalibr RAGER.M Iowa Electric Light & Power Co 80/06/20 1p
- 8008270271 Forwards updated LER 79-004/03X-1 MINECK.D L Iowa Electric Light & Power Co 80/06/20 1p
- --8006270274 Updated LER 79-004/03X-1 on 790311.subsequent to startup, drywell to suppression chamber differential pressure failed to achieve psid within required time Caused by leakage through containment purge butterfly valve
 DUBOST.E lowa Electric Light & Power Co 80/06/20 Ip
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- 8006090407 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 100FR50 & is expected to be published in FR by end of May EISENHUT, D 0 Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800517 ltr Page 14a not encl EISENHUT, D O Division of Licensing 80/05/22 73pp
- 8006090546 Forwards request for add1 info re 800430 Revision 1 of safeguards contingency plan Request withheld (ref 10CFR2 770)

 IPPOLITO T A Operating Reactors Branch 2 80/05/28 2pp.
- 8006190316 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices including visit to facility to interview security mgt personnel IPPOLITO T A Operating Reactors Branch 2 80/06/03 2pp
- BOO6300440 Responds to ARC 800603 ltr rs cooperation w/people-related security problem study interested in participating during Fall 1980 after refueling outage & for as long as info is received MALTESE, M J. Power Authority of the State of New York 80/06/23
- H Owneral correspondence
- BOOA2601BO Requests that following names be included on correspondence distribution list OT Berry, JP Bayne, OM Wilverding, CM Pratt & RJ Pasternak
 BAYNE, J P Power Authority of the State of New York BO/06/20
- P Operating license stage documents & correspondence
- 8006070165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning. Licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D. 9 Division of Licensing 80/05/07 150pp

- 8006030514 Summary of 800422-23 meeting @/Mark I owners group in San Jose-CA re-confirmatory analysis & testing programs concerning Mark I containment long-term program QRIMES.C I Assistant Director for Plant Systems 80/05/09 Spp
- 8005130122 Requests comments on NUREC-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Fump Supports " Proposed review procedure & implementation schedule! anc! EISENHUT.D @ Division of Licensing 80/05/19 72pp
- 8006300604 Ltr to all BAR licensees forwarding "For Comment" edition of NUREQ-0619. "BUR Fredwater Notice & Control Rod Drive Return Line Notice Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT.D G Division of Licensing 80/06/05 22pp
- 8006160137 Advises that util will provide required info re affect of dc power supply failure on ECCS performance by 800715 EARLY,P. J Power Authority of the State of New York 80/06/09 ip
- 8006:80499 Responds to NRC 8006:10 & 11 requests for info re containment vent & purge sys Licensee will install stops to limit travel of 20 & 24-inch containment vent & purge sys isolation valves to less than 50 degrees open BAYNE. J P Power Authority of the State of New York. 80/06/13
- BOO6240501 Requests discussion w/NRC re alternatives to strict interpretation of add1 TMI-2 related requirements as forwarded by NRC BOO507 ltr Flexibility necessary in implementation schedules for good cause shown BAYNE.J P Power Authority of the State of New York 80/06/19
- 4 inspection reports: IE Bulletins & correspondence
- 8006050493 Discusses IE Insp Rept 50-333/78-14 re collection, storage & maint of GA records, Util is meeting previously stated commitments Requests suspension of implementation requirements until NRC rules on proposed 5-yr schedule LEONARD, J D Power Authority of the State of New York 79/09/06
- -8006030478 Discusses JE Insp Rept 50-333/78-14 re collection storage & maint of QA records NRC denies 5-yr extension to implement computerised records mgt sys Requests alternative corrective action.

 ORIER, B H Region 1, Philadelphia, Office of the Director 79/08/20 2pp
- ---8006050505 Discusses IE Insp Rept 50-333/78-i4 re collection, storage & maint of QA records Full implementation of computerized records mgt sys will require 5 yrs Sys placed in syc on 780828.

 LEONARD. J D Power Authority of the State of New York 79/06/22
- 8005230330 Forwards waste packaging insp rept on 800313-14 No noncompliance noted STOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/07 2pp.
- BOO6200077 Forwards IE Circular 80-08, "BWR Tech Spec Inconsistency Reactor Protection Sys Response Time." No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/18 ip.
- 9006180607 Forwards wasta packaging insp rept on 800313-14, No noncompliance noted SMITM, O H Region 5, Philadelphia, Fuel Facility & Materials Bafety Branch 80/04/24 2pp.
- --8006180611 Waste packaging insp rept on 800313-14 No noncompliance noted Hajor areas inspected:licenses-shipper vehicles for compliance w/NRC & DOT regulations including shipping papers, placerating & radiation levels.
 POTTER, J.P., BROHN, R.A. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/03/28 App

- 8006020072 Ack receipt of 800402 % 10 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/80-01 GRIER, B H Region 1. Philadelphia, Office of the Director 80/05/03 Ip
- --8006020076 Responds to NRC 800311 ltr re violations noted in IE Insp. Rept 50-333/80-01 Corrective actions failure to perform shutdown margin test discussed w/operations superintendent & shift supervisor on duty at time of event PASTERNAK, R. J. Power Authority of the State of New York Зрр 80/04/02
- --8008020081 Advises that corrective action per 800408 telcon to correct
 Item A violation noted in IE Insp Rept 50-333/80-01 has
 commenced Maint activity will be discussed w/operating
 shifts by 800501
 PASTERNAK, R J Power Authority of the State of New York
 80/04/10 2pp
- --8006020085 Forwards IE Insp Rept 50-333/80-01 on 800204-08 % 15 & notice of violation BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/03/11 2pp
- --8006020088 Notice of violation from insp on 800204-08 & 15 * Region 1, Philadelphia, Office of the Director 80/00 80/03/04 La
- --8006020092 IE Insp Rept 50-333/80-01 an 800204-08 & 15 Noncompliance noted failure to comply w/Tech Specs prior to making control rod imperable & to control release of liquid w/pH outside Tech Spec range STETKA:TF Region 1. Philadelphia, Office of the Director KISTER:NB Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/04 13pp
- 8006030246 Responds to IE Bulletin 80-07 re BWR jet pump assembly failure Continued operation to end of current fuel cycle is justified Data evaluation does not indicate significant degradation or inoperability of any jet pump PABTERNAK, R J Power Authority of the State of New York 80/05/07 2pp
- 8006250188 Forwards IE Insp Rept 50-333/80-04 on 800331-0404 No noncompliance noted BRUNNER E J Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/03/07 2pp Support Branch
- --8004250190 IE Insp Rept 50-333/80-04 on 800331-0404 No noncompliance noted Major areas inspected previous insp items, plant operations & IE Bulletin 79-018
 KISTER, H B Region 1. Philadelphia. Reactor Operations Nuclear Support Branch STETKA.T F. BAUNACK, W H. Region 1. Philadelphia. Office of the Director 80/05/05 8pp
- 8006060589 Forwards request for add1 info re turbine disc integrity Response requested within 30 days of receipt of 1tr Recommends development of schedule for performing full ultrasonic insp of low pressure turbine during next outage, IPPOLITO.T A Operating Reactors Branch 2 80/05/16 3pp
- --8005050590 "Steam Purity Stress Corresion Cracking "
 4 General Electric Co. GEK-72281 79/08/31 11pp.
- 8005130076 Add) response to FDIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J ff Division of Rules and Records 80/05/23 3pp
- -8006130096 Discusses IE Insp Rept 50-393/75-03 on 750224-0305 Forwards notice of violation Except only encl D'REILLY.J P Atomic Energy Commission, Directorate of Regulatory Operations 75/04/16 3pp
- 8006R40013 Advises that AE has undertaken revision of rept responding to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "Expects to submit response by 800607 PASTERNAK, R.J. Power Authority of the State of New York, 80/05/23
- 8006250220 Confirms areas needing clarification in response to IE Bulletin 79-018 per 800514 sits insp Requests written response within 24-h of receipt of ltr if actual plans & actions differ from described requirements ORIER.B. H. Region 1. Philadelphia, Office of the Director 80/05/23 2pp

- R Periodic operating reports & related correspondence
- BOO6110181 Forwards monthly operating rept for May 1980
 PASTERNAK.R J Power Authority of the State of New York BO/06/03
- --8006110188 Monthly operating rept for May 1980 ZUFELT, E Power Authority of the State of New York B0/06/03
- S Reportable occurrences, LERs & related correspondence
- 8006020308 Forwards LER 80-041/04F-0
 PASTERNAK, R J Power Authority of the State of New York 80/05/27
- --8006020318 LER 80-041/04T-0 on 800513 during normal refueling, release of I-131 approx 30% in excess of ETS occurred following filling of refueling cavity Cause not stated Release occurred via normal ventilation sys to environ CHILDS.H V Power Authority of the State of New York 80/05/27
- 8006020355 Forwards LER 80~042/03L-0 PASTERNAK,R J Power Authority of the State of New York 80/05/27
- --8006020361 LER 80-042/03L-0 on 800428, during normal shutdown operations, recorder pen for source-range monitors 8 & D stuck Caused by normal wear & tear Bearing replaced & recorder recalibr Recorder returned to svc within 24-h CHILDS.W V Power Authority of the State of New York 80/05/27
- 9006020367 Forwards LER 80-046/03L-0 PABTERNAKIR J Power Authority of the State of New York 80/05/23 1p
- --8006020370 LER B0-046/03L-0 on 800430, during normal operation, surveillance testing to satisfy Tech Spot 4 2-1 revealed two shutdown cooling permissive suitches were set in excess of limit Caused by instrument drift Buitches recalibr 4 Pawer Authority of the State of New York 80/05/27 ip
- 8004020372 Forwards LER 80-047/03L-0 PABTERNAK.R J Power Authority of the State of New York 80/05/27 10
- --8006020377 LER 80-047/03L-0 on 800501, while surveillance testing to satisfy Tech 8pec 4 2-2, reactor core isolation cooling high ambient temp switch.10-TE-878, failed to operate Caused by wire broken during hookup of test equipment Wire repaired * Power Authority of the State of New York 80/05/27 ip
- 9006020383 Forwards LER 80-044/03L-0 PASTERNAK:R J Power Authority of the State of New York 80/05/27
- ---8006020387 LER 80-044/03L-0 on 800428, during normal operation surveillance, off-gas timer was set at 15 minutes 20-s, exceeding Tech Spec limits Caused by accidental humping or loosening of adjustment knob lock Timer was readjusted, * Power Authority of the State of New York 80/05/27. 1p
- 8004020391 Forwards LER 80-045/03L-0 PASTERNAK,R J Power Authority of the State of New York 80/05/27 ip
- --8006020396 LER 80-045/03L-0 on 800429, during normal operation, rod to block monitor A became inoperable when control rod 26-19 was selected due to inadequate number of low power range monitor inputs Caused by age Monitor strings will be replaced CHILDS, M. V Power Authority of the State of New York 80/05/27 ip
- 8006020412 Forwards LER 80-043/03L-0 PABTERNAK.R J Power Authority of the State of New York 80/05/27
- --8006020417 LER 80-043/031-0 on 800428 during shutdown operations, surveillance to satisfy safety requirements of Tech Spec 4 1-1 revealed average power range monitor 8 scram & rod block setpoint above limit Caused by Instrument drift.

 * Power Authority of the State of New York 80/05/27 1p
- 8006110006 Forwards LER 80-049/03L-0
 PASTERNAK, R J Power Authority of the State of New York 80/06/06
 1p

- ---B006110010 LER 80-049/03L-O on 800507. during plant shutdown & cooldown for refueling torus water level exceeded Tech Bpsc limit Caused by release of drywell to torus differential pressure Addition of water to torus restored level within limit CHILDS.W V Power Authority of the State of New York 80/06/06 ip
- 8006110016 Forwards LER 80-050/03L-0 PASTERNAK, R J Power Authority of the State of New York 80/06/06 In
- ~-8006110021 LER 80-050/03L-0 on 800509.MSIV failed leak tightness limit of Tech Spec Caused by packing leakage due to age Valve repacked CHILDS.W V Power Authority of the State of New York 80/06/06 1p
- 8006i10069 Forwards LER 80-048/03L-0 PASTERNAK, R I Power Authority of the State of New York 80/06/06 ip
- --8006:10077 LER 80-048/03L-0 on 800307.personnel discharged contents of laundry drain tank w/o obtaining permit Operating procedures are being modified to more clearly indicate requirement to obtain discharge permit prior to start of discharge CHILDS.W V Power Authority of the State of New York 80/06/06 in
- 8006180500 Forwards LER 80-051/03L-0
 PARTERNAK, R J Power Authority of the State of New York 80/06/13
- --8006180503 LER 80-051/03L-0 on 800521.during surveillance testing, recorder for SRM channels A & C found operating in degreded mode Caused by instrument drift Recorder recalibr & tested satisfactorily in SRM functional test

 * Power Authority of the State of New York 80/06/13 1p
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 800.6090.487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 100FR30 & is expected to be published in FR by end of May EISENHUT, D Q Division of Licensing, 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 1tr Page 14s not encl EISENHUT, D Q Division of Licensing 80/05/22 73pp
- BOOA240291 Forwards suppl to physical security plan Suppl withheld (ref 10CFR2 790)
 DUNN.C N Duquesne Light Co 80/06/20 1p
- H General correspondence
- 8006200450 Notifies of change in mailing address NRC mailing label encl BIBSERT,F. J Duquesne Light Co 80/06/13 2pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Bteam Generator & Reactor Collant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D O Division of Licensing 80/09/19, 72pp
- 8006170532 Responds to 800507 ltm & schedule for implementation of TMI-2-related requirements. Discusses shift manning, scope & criteria for licensing exam. procedures for feedback of operating experience & control room habitability BUNN.C N Duquesne Light Co 80/06/09 4pp.

- 8006200310 Forwards response to NRC 800501 ltm re adequacy of station electric distribution sys voltages Low voltage condition will be maintained only during operation time of undervoltage relay & will have no effect on plant safety DUNN,C N Duquesne Light Co 80/06/17 7pp
- G. Inspection reports: [E Bulletins & correspondence
- 8004190274 Forwards IE Insp Rept 50-334/80-ti on 800415-17 No noncompliance hoted CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --8006190278 IE insp Rept 50-334/80~11 on 800415-17 No noncompliance noted Major areas inspected wolding & nondestructive exam associated w/recirculation spray & low head safety injection sys mad TRIPPLE Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCBREARTY, R Region 1, Philadelphia, Office of the Director 80/04/29 4pp
- 8008020018 Ack receipt of 800205 ltr ra number of inspa/audits being performed Inspa are intended to occur infrequently & will involve minimal duplication of insp effort STELLOV Office of Inspection & Enforcement, Office of the Director 80/05/05 2pp
- --8006020021 Responds to NRC 791204 ltr re performance & appraisal function Good sys of checks 5 balance via GA audit is desirable, though possibly too demanding on key personnel SCHAFFER, S O Duquesne Light Co 80/02/05 2pp
- 8006090137 Provides add1 info re extension of time to complete response to Item 4, IE Bulletin 79-018 Pursuing program to establish environ conditions which Class IE electrical equipment may experience following HELB > to determine aging factors DUNN, C N Duquesne Light Co 80/05/08 2pp
- B006300037 Forwards IE Insp Rept 50-334/80-08 on 800324-28 No noncompliance noted BRUNNER: E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/09 2pp
- --8006300043 IE Insp Rept 50-334/80-08 on 800324-28 No noncompliance noted Major areas inspected OA program review, GA/GC administrative design change & mod control, measurement & test & previous insp items
 GREENMAN.E O Region 1. Philadelphia. Reactor Operations Nuclear Support Branch NAPUDA-9 Region 1. Philadelphia, Office of the Director BELKE.W Guality Assurance Branch 80/05/07 lips
- 8004030254 Ack receipt of 800429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/80-01 QRIER.B H Region 1, Philadelphia, Office of the Director 80/05/10 ip
- --8006030262 Responds to NRC 800403 ltr re violations noted in IE lnsp Rapt 50-334/80-01 Corrective actions operating manual change notice issued to provide addl theck of alarm/trip setpoint Computer scheduling card format will be changed DUNN.C N Buquesne Light Co 80/04/29 6pp
- --8006030264 Forwards IE Insp Rept 50-334/80-01 on 600114-0208 & notice of violation.

 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/03 2pp
- --8006030266 Notice of violation from insp on 800114-0208 * Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/04/02 3pp
- ---800603026B IE Insp Rept 50-334/80-01 on G00114-020B Noncompliance noted inadequate implementation of administrative controls for Jumpers/lifted leads & radiation monitor setpoints set in excess of Tech Spec limits MCCABE.E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BECKMAN, D A . RHOADS, Q Q Region 1, Philadelphia, notice of the Director G0/04/02 27pp

- ---BOO6110194 "Insp Rept Inside Recirculation Spray Pumps"
 SEIBER. J D , CAREY, J J Doquesne Light Co 80/05/31 7pp
- B006110061 Responds to IE Bulletin 80-07, "Hydromotor Actuator Deficiencies" No hydromotor actuators installed at plant DUNN, C N Duquesne Light Co B0/06/04 ip
- 8006110275 Responds to IE Bulletin 80-06 Test for demonstration that all equipment remains in emergency mode upon removal &/or manual resetting of various isolating or actuation signals will be completed prior to scheduled startup in Jul DUNN,C N Duquesne Light Co 80/06/04 4pp
- 8006300552 Responds to [E Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Lists equipment that does not remain in emergency mode > lists proposed corrective action & implementation schedule DUNN.C N Duquesne Light Co 80/06/04 4pp
- 8006i10360 Responds to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Review of LERs completed Operating manual procedures will be modified prior to startup Facility will be adequately safeguarded against degradation DUNN.C N Duquesne Light Co 80/06/06 App
- 8006240429 Responds to NRC 800921 ltr re violation noted in IE Insp Rept 50-334/80-06 Corrective artions maint work request initiated to repair fire doors Closure linkages adjusted &/or replaced w/heavy-duty mechanisms DUNN.C N Duquesne Light Co 80/06/18 3pp
- R Periodic operating reports & related correspondence
- 8006050379 Forwards NPDES discharge monitoring rept for Apr 1980 MODRE, G W Duquesne Light Co 80/05/30 2pp
- ~-8004040381 NPDES discharge monitoring rept for Apr 1980 MODRE, G W Duquesne Light Co 80704/30 12pp
- 8005050370 Forwards monthly operating rept for Feb 1980 DUNN.C N Duquesne Light Co 80/06/02 lp
- --B006060371 Monthly operating rept for Feb 1980 TIMKO,D R Duquesne Light Co 80/03/07 4pp
- BOO6160014 Furwards monthly operating rept for May 1980 DUNN.C N Duquesme Light Co BO/05/10 1p
- --B006160016 Monthly operating rept for May 1980 TIMKO,D R Duquesne Light Co 80/06/02 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006120268 RQ on 800519, during diesel driven fire pump test, high temp alarm received Pump shut down three times upon activation Cause not stated Pump out of svc & temperary fire pump hooked up WERLING-J A Duquesne Light Co 80/05/20 1p
- 8006020358 Forwards LER 80-026/03L-0 WEXLING, J A Duquesne Light Co 80/05/21 1p
- --8006020362 LER 80-026/03L-0 on 800492, pump being used to start liquid waste discharge observed to have higher than normal flow Caused by leaking effluent valves Corrective actions scheduled to be completed as soon as possible WERLING.J A Duquesne Light Co 80/03/21 4pp
- 8005120265 RQ on 800521, during routine containment tour, leaking welf on high point vent nipple found During repair, suction valve closed causing loss of RHR flow Caused by false high pressure signal due to instrument loop de-energizing WERLING, J A Duquesne Light Co 80/05/21 2pp
- 8006030406 Forwards LER 80-027/03L-0 WERLING, J A Duquesne Light Co 80/05/28 2pp
- --8006030415 LER 80-027/03L-O on 800430, during maint on dieset gemerater lube oil cooler, internals of river water flapper-type check valve were disrovered in cooler Caused by eroded hinge pin guides on valves Valves will be replaced LACEY, W.S. Duquesne Light Co. 80/05/28 2pp
- 8006060365 Forwards LERs 80-003/01T-0 & 80-030/01T-0 WERLING, J. A Duquesne Light Co 80/06/02 1p

- --8006060374 LER 80-003/01T-0 on 800124, overstress condition was confirmed to exist during postulated seismic event w/pipe support H-95 on component cooling water sys line CC-323 Caused by use of incorrect method of pipe stress analysis LACEY.W S Duquesne Light Co 60/06/02 ip
- --8006060385 LER 80-030/01T-0 on 800519 plant operators testing dieseldriven fire pump when high temp alarm was received & diesel dverheated Caused by brittle fan belt slipping LACEY.W S Duqueene Light Co 80/06/02 ip
- 8004090373 Forwards LERs 80 032/03L-0 \$ 80-028/03L-0 WERLING, J A Duquesne Light Co 80/05/02 2pp
- --8006090362 LCR 80-032/03L-O on 800503, during control board insp.vol control tank outlet valve was found shut Caused by short circuited lead in level comparator Shorted wire replaced iACEY.M S Duquesne Light Co 80/06/02 ip
- --8006090389 LER 80-028/03L-0 on 600504, power was lost to vital bus inverter 4 due to blown main power supply fuse Cause unknown Fuse & loctifier replaced Frequency adjusted LACEY.N S Duquesne Light Co 80/06/02 ip
- 8006180612 PNO-1-80-086 on 800602.utils informed NRC of tornado watch in vicinity of plants forcast included potential for severe thunderstorms.large hail & damaging winds Licensees implemented energency procedures MCCABE.E C Region 1. Philadelphia. Office of the Director 80/06/02 2pp
- 8006110108 Forwards LER 80-040/01T-0 WERLING, J A Duquesne Light Co 80/06/04 2pp
- -0006110112 LER 80-040/01T-0 on 800603 questions on quality of radiographs at facility led to radiograph reinsp Caused by personnel error in interprotation of radiograph prints Defects repaired & le-radiographed LACEY.W S Duquesne Light Co 80/06/04 2pp
- 8006110121 Forwards LER 90-031/01T-0 WERLING, J A Duquesno Light Co 80/06/04 2pp
- --B006110126 LER B0-031/OIT-O on B00921, upon finding leaking RHR system vent valve weld evaluation commenced to re-energize RHR isolation valve in case of gross failure Caused by de-energized process control signal & vent weld leak LACEY, H S Duquesne Light Co B0/06/04 2pp
- 8006160041 RO on 800529, meteorological instrumentation computer channels found not responding properly to automatic calibr signals Caused by output resistors not being removed during 800515 move Resistors removed & sys calibr verified WERLING, J.A. Duquesne Light Co. 80/06/09 2pp
- 8004170598 Forwards LERs 80-034/03L-0.80-035/03L-0 & 80-036/03L-0 WERLING J A Duquesne Light Co 80/06/09 2pp
- --8006170563 LER 86-034/03L-0 on 800512, during air flow surveillance test on fire suppression sys, approx 50% of sprinkler nozzles found plugged Caused by rust & unidentified math Nozzles will be cleaned & sys blown down w/air LACEY.N S Duquesne Light Co 80/06/09 1P
- --8006170571 LER 80-035/03L-0 on 800512 during fuel bldg surveillance test, internal pressure found to be less than negative 1/8 inch water column relative to atmospheric pressure Caused by unmarked damper which drifted shut Damper removed LACEY.N 5 Duquesne Light Co 80/06/09 IP
- --8006170576 LER 80-036/07L-0 on 800514, boric acid buildup noticed around soc-o-let weld on RHR pump.RH-P-1A, vent valve.RH-211 Pipe weld found cracked Caused by vibration, pipe nipple length & valve weight which combined to provide bend LACEY,W S Duquesne Light Co 80/06/07 1P
- 800623055/ Forwards LER 80-038/03L-0 WERLING.J A Duquesne Light Co 80/06/16. 2pp
- ---8006230562 LCR 80--038/03L-0 on 800517, gaseous waste tank, 0W-TK-1A, pressure decreased from 18 to 6 psig Caused by leaks on flanges of flow orifice & pressure transmitter Tanks manually isolated until maint & testing can be completed LACEY, W S Duquesne Light Co 80/06/16 1p

- 8006240379 Forwards followup to LER 80-025 re status of work being performed on safety-related tanks Repairs to one or more seam welds on each tank inspected to date should be performed CAREY, J. J. Duquesne Light Co. 60/06/18. 4pp
- BOO6250260 RO BO-037/01T during review of radiographs of reactor containment liner seam welds, portion of one weld is code rejectable Authenticity of other seam weld radiographs questionable Investigation continuing WERLING, J. A. Duquesne Light Co. BO/06/20 1p
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B0060904B7 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 4B 2 App R to 10CFR50 & 1s expected to be published in FR by end of May CISENHUY.D G Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 79010!." transmitted by NRC 800519 ltr Page 14a not enci EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006170301 Forwards security plan. Revision 2
 Plan withheld (ref 10CFR2 770)
 UHRIG.R E Florida Power & Light Co 80/06/10 1p
- 8006250203 Forwards safeguards contingency plan, Revision 1, in response to NRC 800418 request for add1 info Revision withheld (ref 100FR2 790)

 UHRIG.R E Florida Power & Light Co 80/06/19 ip
- J Insurance & indemnity information
- 8006030421 Forwards Endorsement 35 to NELIA Policy NF-227 FIELDER, J. Marsh & McLonnan, Inc., M & M Nuclear Consultants, Inc. DIV 80/05/29 2pp
- 8006160113 Forwards Endorsement 28 to MAELU Policy MF-88 FIELDER: J. Marsh & McLennam, Inc., M & M Nuclear Consultants, Inc. Div 80/06/09 2pp
- M Antitrust correspondence
- 8006240137 Notice by Orlando Utils Commission to withdraw intervention & request to institute proceeding re Commission 780727 order City of Orlando, petitioner & util 800505 settlement resolved issues Waffidavit & Certificate of Svc WISE.W C Orlando.FL WISE.W C Wise. W C 80/06/20 4pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 3D days EISENHUT, D G Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coulant Pump Supports "Proposed review procedure & implementation schedule encl EISENHUT, D G Division of Licensing 80/05/19 72pp
- BOO6050235 Advises that vendor analyses supporting proposed mod to automatic initiation of auxiliary feedwater sys flow will be delayed Submittal expected by BOO620 Operational date will coincide w/safety analysis transmittal
 UHRIG.R E Florida Power & Light Co 80/05/29 2pp
- ROOAO&O310 Forwards five C-E repts re code for calculating PWR scram activities control element assembly group withdrawal & three-part rept for statistical combination for uncertainties Proprietary version withheld (ref 190FR2 790) UHRIG.E E Florida Power & Light Co 80/05/29 1p
- ---8006060315 "CEAW Method of Analyzing Sequential Control Element
 Assembly Group Withdrawal Event for Analog Protected Sys,"
 nonproprietary version
 ** Combustion Engineering, Inc. CEN-126(F)-NP 80/01/31 100pp

- --8004060319 "FIESTA One Dimensional Two Group Space-Time Kinetics Code for Calculating PWR Scram Activities " DECHER, U Combustion Engineering, Inc CEN-122(F) 79/11/30 7300
- --8006060321 "Statistical Combination of Uncertainties Methodology,Part 1 C-E Calculated Local Power Density & Thermal Margin/Low Pressure LSSS for St Lucie Unit 1," nonproprietary version * Combustion Engineering, Inc. CEN-123(F)-NP PT1 79/12/31 1000c
- --8006060326 "Statistical Combination of Uncertainties Methodology, Part 2 Combination of Sys Parameter Uncertainties in Thermal Margin Analyses for St Lucie Unit 1," nonproprietary version * Combustion Engineering, Inc. CEN-123(F)-NP PT2 80/01/31 10000
- --8006060329 "Statistical Combination of Uncertainties Methodology, Part 3 C-E Calculated Departure From Nucleate Boiling & Linear Heat Rate Limiting Conductions for Operation for St Lucie Unit 1." nonproprietary version & Combustion Engineering, Inc. CEN-123(F)-NP PY3 80/02/29 iOOpp
- BOO6190120 Discusses util 791109 submittal re degraded grid voltage Forwards request for add1 info CLARK, R A Operating Reactors Branch 3 80/05/29 3pp
- 800618047: Forwards info re TMI-related requirements, in response to NRC 800507 ltr
 URRIG.R E Florida Power & Light Co 80/06/13 3pp
- BODA300337 Notification of BOOA20 meeting w/util & C-E in Bethesda, MD to discuss history, indications & analysis of voiding & corrective actions re BOOA11 event at facility CONNER.E. L. Operating Reactors Branch 3 80/06/19 2pp
- BOOA2401B9 Discusses main steam line break analysis Results show that peak containment pressure is not influenced by assumed addition of auxiliary feedwater ruptured steam generator Forwards assumptions used in analysis

 UHRIO,R E Florida Power & Light Co 80/06/20 10pp
- 8006270311 Application for amend to App A of License DPR-67, modifying definition of operability & applicability of limiting conditions for operation to coincide w/words in STS per NRC 800410 ltr
 UHRIGAR E Florida Power & Light Co 80/06/20 lp
- --good270314 Safety evaluation supporting amend to App A of License DPR-67
 - # Florida Power & Light Co €0/06/20 ip
- ---8006270317 Revised Tech Specs per proposed amend to App A of License DPR-67, modifying definitions of operability & applicability of limiting conditions for operation to coincide w/words in STS.
 - * Florida Power & Light Co 80/06/20 7pp
- G Inspection reports, IE Bulletins & correspondence
- BOO6(30035 Forwards IE Insp Rept 50-335/80-09 on 800408-10 No noncompliance noted MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/04/30 2pp
- ---8006/30038 IE Insp Rept 50-335/80-09 on 800408-10 No moncompliance noted Major areas inspected; installed equipment review per IE Bulletin 79-018 CONLON.T E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. RUFF.A B Region 2. Atlanta, Office of the Director 80/04/29 2pp
- 8006060369 Forwards IE Bulletin 80-11, "Masonry Hall Design " Requires action & written response IE info Notice 79-28, "Overloading of Structural Elements Bue to Pipe Support Loads" encl.
 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/05/08
 2pp
- 8006050286 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability," Requires action & response within 30 days IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Dayis-Besse Unit i While in Refueling Mode" entl CYREILLY, J. P. Region 2. Atlanta, Office of the Director 80/05/07

- 8006300107 Forwards IE Circular 80-11. "Emergency Diesel Generator till dil Cooler Failures " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/05/13
- BO06300269 Forwards IE Insp Rept 50-335/BO-13 on B00429-0502
 No noncompliance noted
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/05/16 2pp
- --8006300273 IE Insp Rept 90-335/80-13 on 800429-0502 No noncompliance noted Major areas inspected inservice insp 5 licensee responses to IE Builetin 79-17 CROWLEY, B R Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/15 App
- 800A040013 Ack receipt of 800118.0321 & 0501 ltrs informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-250/79-35.50-251/79-35.50-335/79-33 & 50-389/79-22 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/05/19 lp
- --8004040021 Responds to NRC /91219 ltr re violations noted in [E inj Repts 50-250/79-35, 50-251/79-35, 50-335/79-33 \$ 50-389/79-22 Corrective actions GA piccedures will be revised w/full compliance achieved by 800731 UMRIG.R E Florida Power & Light Ca 80/05/01 ip
- --8006040025 Responds to NRC 791219 & 800220 ltrs re violations noted in IE Insp Repts 50-250/79-35 50-251/79-35, 50-335/79-33 & 50-389/79-22 Corrective actions GA procedures will be revised re implementation of lOCFR21 UHRIG.R & Florida Power & Light Co 80/03/21 3pp
- 8006230159 Ack receipt of 800513 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 50-335/80-08 LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 ip
- --8006230166 Responds to NRC 800418 ltr re violations noted in IE Insp Rept 50-335/80-00 Corrective actions interim measures taken to supply audible flux count to refueling area UHRIO.R E Florida Power 3 Light Co 80/05/13 2pp
- --8006230171 Forwards IE Insp Rept 50-335/80-08 on 800401-03 & notice of violation LEKIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/18 2pp
- --8006230173 Notice of violation from insp on 800401-03 * Region 2: Atlanta: Reactor Operations Nuclear Support Branch 80/04/15 1p
- --8006230179 IE Insp Rept 50-335/80-08 on 800401-03 Noncompliance metal failure to have flux monitor indication audible in containment during core alterations

 * Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/15 4pp
- BOO6250274 Forwards response to IE Bulletin 80-12 Failure of any single active component during decay heat removal sys operation will not result in loss of cooling UMRIGRE Florida Power & Light Co BO/O6/11 4pp
- B006230307 Responds to IE Bulletin 80-05 Existing measures for vacuum protection are adequate 2 no further mods are required UMRIO:RE Florida Fower & Light Co 80/06/11 3pp
- R. Periodic operating reports & related correspondence
- 8006170467 Forwards monthly operating repts for May 1980 8CHMIDT.A D Florida Power & Light Co 80/06/07 ip
- ---8006170479 Monthly operating rept for May 1980 CHILSON,V T Florida Power & Light Co 80/06/07 App
- S Reportable occurrences, LERs & related correspondence
- 8006050325 RO 335-BO-27 on 800514,C-E informed util that partial draining of RCS while in Mode 5 is condition not analyzed for boron dilution event Plant operating procedures revised to increase shutdown margin WETHY.C M Florida Power & Light Co 80/05/15 ip
- 8004030443 Forwards LER 80-027/09T-0 SCHMIDT, A D Florida Power & Light Co 80/05/21 1p

- --8006030447 LER 80-027/09T-0 on 800514 during shutdown for maint, NSSS notified util that partial draining of RCS while in Mode 5 is condition that has not been analyzed for boron dilution event Procedures revised to increase win shutdown margin SCHOPPMAN.M A Florida Poue: & Light Co 80/05/21 2pp
- 8006110037 Forwards LER 80-025/017-0 SCHMIDT.A D Florida Power & Light Co 80/05/26 1p
- --8006110042 LER 80-025/01T-0 on 800512 during planned secondary shutdown for turbine maint, steam header would not depressurize following steam stop closure due to sheared bypass valve stems Cause undetermined Valve stems replaced SCHOPPMAN, M A Florida Power & Light Co 80/05/26 2pp
- 800&170&75 Forwards LER 80-019/03L-0 SCHMIDT,A D Florida Power & Light Co 80/05/31 ip
- --BCO6170686 LER BO-019/03L-O on BO0501, during normal refueling operations, leak check of personnel air lock indicated leakage in excess of Tech Specs Caused by defective air lock handwheel shaft packing gland Packing gland; adjusted SCHOPPMAN:M A Fierida Power & Light Co 80/05/31 ip
- 8006170542 Forwards LER 80-021/03L-0 8CHMIDT.A D Florida Power & Light Co 80/06/06 ip
- --8006170551 LER 80-021/03L-0 on 800507; during normal surveillance & post-maint testing, 1A diesel' generator failed to synchronize to emergency bus Caused by frequency permissive relay being set incorrectly Relay setpoint corrected SCHOPPMAN.M A Florida Power & Light Co 80/06/06 1P
- 8006170647 Forwards LER 80-020/03L-0 SCHMIDT, A D Florida Power & Light Co 80/06/06 ip
- --8006170652 LER 80-020/03L-0 on 800507, during heatup following refueling, auxiliary feed pump governor found out of adjustment Caused by drifting of speed setting potentiometer Potentiometer readjusted SCHOPPMAN, M A Florida Power & Light Co 80/06/06 ip
- 8004230483 Forwards LER 80-023/03L-0 SCHMIDT, A D Florida Power & Light Co 80/04/10 ip
- --8006230495 LER 80-023/03L-0 on 800511 during power ascension, control element assemblies 19 % 58 dropped to full insertion Caused by failure of 15-volt power supply units Noth control element assemblies were restored SCHOPPMAN M A Florids Power & Light Co 80/06/10 ip
- 8006230405 RO 335-80-27 on 800611, ground accurred on bus 18 dc causing containment isolation valve HCV-14-6 to fail closed Apparently caused by water in solenoid from steam leak Cooldown continuing Damaged valve seals will be replaced WETHY, C M Florida Power & Light Co 80/06/11 2pp
- 8006230464 Forwards LER 80-024/03L-0 SCHMIDT, A D Florida Power & Light Co 80/06/15 1p
- --B006230476 LER 80-024/031-0 on B00516, while shut down for refueling, periodic test of engineered safety features showed 10 diesel generators load sequence timors were out of tolerance Caused by setpoint drift Maladyusted relays caused other problems BCHOPPMAN, M A Florida Power & Light Co 80/06/15 2pp.
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8006060426 Forwards request for addl info re facilities' emergency plans Plans should be evaluated against NUREG-0654 & encl comments by 800630 CRUTCHFILED,D M Operating Reactors Brench 5 80/05/12 36pp
- BOOA090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 ½ App R to 10CFR50 ½ is expected to be published in FR by end of May EISENHUT.D 9 Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101;" transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D G Division of Licensing 80/05/22 73pp

- 8006060367 Submits info to reaffirm adequacy of current fire protection plans to fulfill SER commitments One oversize drawing encl GOUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.G. Connecticut Yankee Atomic Power Co. BO/05/29 Bpg.
- H General correspondence
- 8006170464 Advises of personnal change EJ Mrotika relieved JF Opeka as station superintendent on 800601 MROCZKA/E J Northeast Utilities 80/06/02 1p
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D 9 Division of Licensing 80/05/07 150pp
- BOO6130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactor Coolant Pump Supports" Proposed review procedure & implementation schedule encl
 EISENMUT.D Q Division of Licensing 80/05/19 72pp
- 8004020203 Application to amend License DPR-65 by incorporating revisions to Tech Specs for Millstone 2 in response to NRC 800410 request Proposed changes are necessary for safe operation of facility Millstone 2 is only unit w/Tech Specs COUNSIL.N G Connecticut Yankee Atomic Power Co COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/21 3pp
- --8006020211 Proposed revisions to Tach Specs for Milistone 2, incorporating requirements of NRC 800410 ltr to all power reactor licensees

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/31 7pp
- 800.6060306 Forwards proprietary version of basic safety rept addendum.
 "Nuclear Uncertainties," supplementing rept Section 4 0
 Describes power peaking factor uncertainty analysis used in
 reload fuel design Rept withheld (ref 10CFR2 790)
 COUNSIL,N 0 Northeast Nuclear Energy Co (subs of Northeast
 Utilities) 80/05/28 2pp
- 8006180416 Forwards Amend 58 to License DPR-65 & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 80/05/29 3pp
- --8006180417 Amend 58 to License DPR-65, changing Tech Bpecs to permit storage of fuel assemblies containing 3 35% by weight U-235 in high density spent fuel storage racks in spent fuel storage pool CLARKIR A Operating Reactors Branch 3 80/05/29 5pp
- --8006180418 Notice of issuance & availability of Amend 58 to License DPR-65 CLARK,R A Operating Reactors Branch 3 80/05/29 2pp
- BOO4030474 Forwards addendum to "Basic Safety Rept" re nuclear uncertainties, nonproprietary version CQUNSIL,N O Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/05/30 ip
- --B006030474 Addendum to "Basic Safety Rept" re nuclear uncertainties, nonproprietary version * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/09/31 22pp
- BOD6110407 Nutification of B00604 meeting w/util & Hestinghouse in Bethesda.MD to discuss core power distribution, setpoint methodology, uncertainty analysis & proposed Tech Bpec changes no Cycle 4 reload w/Westinghouse fuel CONNER.E L Operating Reactors Branch 3 80/05/30 2pp
- 8006i10307 Discusses small break LOCA ECCS performance results
 Primarily effect function of sys characteristics such as
 ECCS flow rates, safety (njection tank actuation pressures
 6 core power level Supporting info enci
 COUNSIL(# G Northeast Utilities 80/06/02 14pp
- 8006160045 Provides descriptive info & design assessment of proposed low level redwaste storage facility onsite No IRC review required Facility will be operational late 1980 COUNSTL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/02 9pp

- 8005160047 Forwards 'Reload Safety Analysis," demonstrating that Cycle 4 reload assures continued conformance to design & safety limits of facility COUNSIL.N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/03 2pp
- --8006i60048 "Reload Safety Analysis "

 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/06/30 23pp
- BOO624059B Forwards Amends 68 % 59 to Licenses DPR-21 % DPR-65, respectively & notice of issuance & availability CLARK.R A Operating Reactors Branch 3 80/06/03 4pp
- ---8006240604 Anends 68 & 59 to Licenses DFR-21 & DFR-65, respectively, deleting Sections 4 1 & 4 2 from ETS CLARK.R A Operating Reactors Branch 3 CRUTCHFIELD.D C Operating Reactors Branch 5 80/06/03 7pp
- r-8006249507 Notice of issuance & availability of Amends 68 & 59 to Licenses DPR-21 & DFR-65, respectively CLARK, R A Operating Reactors Branch 3 80/06/03 2pp
- BOO4190457 Forwards info re five add1 TMI-2 related requirements applying to operating reactors per BOO507 request Integrated assessment of collective impact of all requirements should be conducted COUNSIL. H O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. H O Connecticut Yankee Atonic Power Co BO/06/10 30pp
- 8006190602 Forwards "Large Break LOCA/ECCS Performance Results "
 Analysis showed double-ended cold leg guillotine break at
 pump discharge to be limiting large break Review of results
 determined that applicable fee was submitted 800509
 COUNSIL:# G Northeast Nuclear Energy Co (subs of Northeast
 Util;ties) COUNSIL:# G Northeast Utilities 80/06/11 1p
- --800&190&10 "Large Break LOCA/ECCS Performance Results "

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) *
 Northeast Utilities 80/06/30 38pp
- 8006190408 Forwards info re design basis transient & accident conditions providing basis for auxiliary feedwater sys flow requirements in response to NRC 791022 request Based on analyses, auxiliary feedwater sys complies w/Section 1 4 COUNSIL/N 0 Northeast Utilities COUNSIL/N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/16 30pp
- BOO6240466 Forwards info requested by NRC BOO515 ltr re low pressure turbine discs Scheduled insp program at facility will confirm absence of turbine disc cracking in low pressure rotors

 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Ut(lities) SO/06/16 11pp
- BOO530052 Summary of BOO318 meeting w/util & Westinghouse re Cycle 4 reload w/Mestinghouse fuel CONNER.E L Operating Reactors Branch 3 80/06/18 29pp
- G Inspection reports. IE Bulletins & correspondence
- BOO6050519 Forwards IE Insp Repts 50-243/79-21 & 50-336/79-22 on 790804-0901 No nancompliance noted BRUNNER,E J Region I. Philadelphia, Reactor Operations Nuclear Support Branch 79/11/01 2pp
- --BO06050524 IE Insp Repts 50-245/79-21 & 50-336/79-22 on 790804-0901 No noncompliance noted Major areas inspected plant tours, physical security, exam of feedwater piping per IE Bulletin 79-13. Fire protettion & surveillance testing MCCABE, E.C. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch SHEDLOSKY, J.T. Region 1. Philadelphia, Office of the Director 79/10/30 Spp
- BOOA040055 Forwards 1E Insp Repts 50-245/80-03 \$ 50-336/80-02 on 800201-29 No noncompliance noted RRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch BO/04/18 2pp
- ---BD06040059 IE Insp Repts 50-245/80-03 t 80-336/80-02 on B00201-29 No noncompliance noted Hajor areas inspected control rooms & accessible portions of Unit 1 reactor, turbine; radwaste, gas turbine generator & intake bldgs
 SHEDLOSKY, J T, ZIMERIANN, R P Region 1, Philadelphia, Defice of the Director KEINIG, R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/14, 10pp

- BOOLD90191 Forwards IE Investigation Rept 50-293/80-12 on 800305-07 & 19-20.in response to allegations re illegal shipments of spent fuel MARTIN.N G Region 1. Philadelphia. Safeguards Branch 10/04/18 ip
- 8006250152 Forwards IC Insp Repts 50-245/80-04 \$ 50-336/80-03 on 800301-29 No poncompliance noted BRUNNER, E J Region i, Philadelphia, Reactur Operations Nuclear Support Branch 80/05/02 2pp
- --8006250157 IE insp Repts 50-245/80-04 % 50-336/80-03 on 800301-29 No noncompliance noted Major areas inspected plant operations, logs & records, previous insp findings, radioactive matt shipments, maint & IE builetins & circulars KEINIG, R Region 1, Philadelphia, Reactor Operations Nuclear Support Branch SHEDLOSKY, J T , ZIMIERNIAN, R P Region 1, Philadelphia, Office of the Director 60/05/01 13pp
- 8006040011 Responds to 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks " Review of all sys has been completed Adequate vacuum profection exists for sys under potentially damaging vacuum conditions COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/07 3pp
- 8006240611 Ack receipt of 800500 its informing NRC of incorrect statements made in IE Insp Rept 50~273/80~12 Corrected pages encl W/o encl MARTIN.U G Region 1. Philadelphia, Safeguards Branch 80/05/22
- ---8006240617 Responds to HRC 800410 ltr Northeast Nuclear Energy to incorrectly identified as util licensod to operate Haddom Neck Plant COUNSIL.W G Northeast Nuclean Energy Co (subs of Northeast Utilities) 80/05/08 200
- 8006200037 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required GRIER, B H Region t, Philadelphia, Office of the Director 80/05/28 lp
- R Periodic operating reports & related correspondence
- 8006230506 Forwards monthly operating rept for May 1780 MROCZKA, E J Northeast Utilities 80/06/16 1p
- --8006230515 Monthly operating rept for May 1780 HDWLETT,G H Northeast Utilities 60/06/02 5pp
- S Reportable occurrences, LERs & related correspondence
- 8006020386 Forwards LER 80-018/017-0 OPEKA, J F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/05/22 ip
- --8006020392 LER 80-018/017-0 on 800508 during ongoing hanger baseplate analysis for IE, Rulletin 79-02, both svc water headers inoperable Caused by inadequate hanger baseplate supports Redesign & mod of supports begun Seven hangers completed CRISCIONE, J Northeast Nuclear Fnergy Co (subs of Northeast Utilities) 80/05/22 2pp
- 8006040275 Forwards LER 80-020/03L-0 GPEKA.J F Northeast Utilities 80/05/29 2pp
- --B004040285 LER B0-020/03L-0 on B00427, during power operation, RCS pressure was too low due to stuck pressurer spray valve % reactor tripped on low steam generator level during load reduction Caused by loose valve seat Valve repaired GURNEY, PV Northeast Utilities B0/05/27 ip
- 8006110248 Forwards LER 80-021/03L-0 MRGCZKA.E J. Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/04 ip
- --8004i10254 LER 80-02i/03L-0 on 800504, during routine testing to prove dissel operability, 13U dissel generator breaker closed after manual opening Caused by loose bolt in generator spring charging sys causing latch to fail Bolt tiphtened FOSTER, E.R. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/04/04 1p
- B006170657 Forwards LER 80-011/03L-1 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/06 ip

- --B0061/0661 LER B0-011/03L-1 on B00508, following shutdown, broken saddle clamp bolt found on hydraulic snubber hanger 490002 Caused by fatigue & high impact loading Bolts replaced w/high strength bolts for high temp svc CLEMENT, C Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/06 ip
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 800602001) Forwards request for addl info needed to complete NRC review of gward training & qualification plan submitted by util 780818 ltr Info request withheld (lef 100FR2 790) CLARK.R A Operating Reactors Branch 3 80/05/19 2pp
- BOOGO90487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 100FR50 & is expected to be published in FR by end of May EISENHUT, D 6 Division of Licensing 80/05/19 44pp
- 8006130063 Forwards revised Pages 1-14 to new Page 14a for proposed rule 100FR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT.D G Division of Licensing 80/05/22 73pp
- B006030016 Responds to NRC 8005)9 ltr re guard training & requalification program Response will be forwarded by 800714 SYLVIA.B R Virginia Electric & Power Co 80/05/28 lp
- 8006110005 Forwards Revision 1 to emergency plan Section 4 utl1 require mod resulting from 800570 meeting w/NRC & will be forwarded upon completion Commonwealth of VA 800520 ltr encl BAUM,E A Virginia Electric & Power Co 80/06/06 Spp
- --8006110007 Revision 1 to emergency plan
 # Virginia Electric % Power Co 80/06/09 100pp
- 8006240469 Forwards addl changes to station emergency plan.completing response to IW Roe 800515 comments BAUM.E A Virginia Electric & Power Co 80/06/20 2pp
- --8006240478 Emergency plans Revision 2

 * Virginia Electric > Power Co 80/06/18 27pp
- 8006260193 Forwards Revision 3 to emergency plan, discussed w/NRC on B00620 Also forwards Sheriff of Hamover County, VA 800605 ltr of agreement & List of changes to emergency plan BAUM. EA Virginia Electric & Power Co 80/06/25 ip
- --8006260184 Revision 3 to emergency plan Sheriff of Hanover County, VA 800605 itr of agreement & list of changes encl * Virginia Electric & Power Co 80/06/25 23pp
- G Adjudicatory correspondence
- 8006190018 Notifies that time has elapsed for Commission consideration of petitions for review of ALAB-584 Since Commission has not granted petition, petition is deemed denied CHILM,S J. Office of the Secretary of the Commission 80/05/29
- 8006180429 Recommends that ASLAD composition be changed to remove imbalance between lawyer 2 technical members 2 that unnecessary logalistic burdens, procedules 2 requirements be eliminated Valentine B Deale 80/05/09 DEALE, V.B.
- 8006240347 Advises of change in info in 800324 ltr Westinghouse exit energy E probability analyses will not be ready until Oct 1980 SkH analyses will require six addl wks Crack sire tables withheld (ref 10CFR2 790) CIRISTMAN. J N Hunton 3 Williams 80/06/20 2pp
- 8006300413 Ack receipt of 800620 ltm re turbine missile issue Oblay in Mestinghouse analyses is not matter of serious concern to ASLAB ASLAB must be promptly notified if disk cracking image is postponed beyond Dec 1980
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/24

- P Operating license stage documents & correspondence
- 8006070165 Forwards add1 THI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D O Division of Licensing 80/05/07 130pp
- 8006090925 Forwards Amend 18 to License NPF-4, safety evaluation & notice of issuance & availability
 CLARK.R A Deprating Reactors Branch 3 60/05/19 2pp
- -8006090529 Amend 18 to License NPF-4.correcting administrative err presently existing in Tech Spets re max response time expected from onset of detected degraded offsite power sys CLARK.R A Operating Reactors Branch 3 80/05/19 5pp
- --8006090534 Safety evaluation supporting Amend 18 to License NPF-4

 * Office of Nuclear Reactor Regulation, Director 80/05/19
- --8006090537 Notice of issuance & availability of Amend 18 to Licens CLARK, R A Operating Reactors Branch 3 80/05/18 2pp
- 8006130122 Requests comments on NUREG-0577. "Pobential for Low Fract Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EIBENHUT,D G Division of Licensing 80/05/19 72pp
- BOO6020173 Advises that contrary to date stated in BOO428 ltr.tempor post-accident containment atmospheric sys will be installed by BOO630.per NUREO-0578 Permanent sys will be installed by BIO101 Systches and SYLVIA.B R Virginia Electric & Power Co BO/05/28 App
- 8005050223 Application to amend DL w/Tech Spec Change 38, removing Snubber 103, installed on safety injection sys in safegua area, from Table 3 7-4 Proposed Change 38 & Class III fee FERGUSON, J H Virginia Electric & Power Co 80/08/02 3pp
- ---80050227 Proposed Change 38 to Tech Specs, removing Snubber 104 f Table 3 7-4 * Virginia Electric & Power Co 80/06/02 ip
- BOO6250006 Confirms BOO602 telcon authorizing amend to OL Tech Space License NPF-4 is amended deleting snubber 103 on Page 3/4 7-34 Formal copies of amend & FR notice forthcoming NDVAR.T M Assistant Director for Operating Reactors BO/06/02
- 8006110063 Provides commitment to meet addl TM1-2 related requirement identified in NRC 800807 ltm.providing equipment procurement schedules do not impact implementation of hardware changes SYLVIA, B R Virginia Electric & Power Co 80/06/06 lp
- 8006130334 Proposes multiphase plan to address NRC concerns re multistructure amplified response spectra being used to analyze piping sys in low head & high head safety injection lines List of multistructure problems & sample problem encl SYLVIA,B R Virginia Electric & Power Co 80/06/06 18pp
- 8006250139 Forwards "North Anna Operational Background Chemistry Review " Add1 info concerning Westinghouse boric acid treatment program to be forwarded within few whs SYLVIA:B R Virginia Electric & Power Co 80/06/18 ip
- --8006250143 "North Anna Operational Background Chemistry Review " SANDCHKA, S.O., PEARL, W.L. NWT Corp. 80/06/30 46pp
- BOOAGOOGOB Confirms agreement re review criteria for control rod bar reactivity worth tests Modified Table A 2 of VEP-FRD-34.
 "Control Rod Reactivity Worth Determination by Rod Swap Technique" encl THOMAS, U.N. Vi Virginia Electric & Power Co 80/06/26 6pp
- BOO6300456 Forwards history of experienced total & partial power outages at facilities.per NRC 800507 request BYLVIA.B R Virginia Electric & Power Co 80/06/26 4pp
- Q Inspection reports. IE Bulletins & correspondence
- 8006160181 Forwards (E Insp Repts 50-338/80-16 & 50-339/80-17 on 800303-041; No noncompliance noted LEMIS.A C Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/04/29 Rep

- --8006160186 IE Insp Repts 50-338/80-16 % 50-339/80-17 on 800303-0411 No noncompliance noted Major areas inspected short-term Lessons Learned (NUREG-0578), TMI-2 action plan (NUREG-0660) % plant readiness for fuel loading
 KELLOGO:P J Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch KIDD:M S Region 2, Atlanta, Office of the Director
 80/04/29 13pp
- 800Δ090082 Forwards IE Insp Repts 50-338/80-18 & 50-339/80-19 on 800413-1Δ No moncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/02 2pp
- --8004090088 IE Insp Repts 50-338/80-18 & 50-339/80-19 on 800413-16 No
 - JUDDYCUBB IE Insp Repts 30-339/80-18 & 30-339/80-19 on BOU413-16 No noncompliance noted Major areas inspected initial fuel leading of Unit 2
 UPRIGHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch BURNETT.P T , DONAT.T J Region 2, Atlanta, Office of the Director BO/05/01 Spp
- 8006060515 Forwards IE Bujletin 80-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support encl
- O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 200
- 8006200105 Forwards IE Insp Repts 50-338/80-17,50-404/80-02 & 50-405/80-02 on 800409 & 10 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/08 2pp
- --B006200114 IE insp Repts 50-338/80-17,50-404/80-02 & 50-405/80-02 on 800409 & 10 No noncompliance noted Major areas inspected IE Bulletins 79-17 & 80-09 activities re cracks in borated water sys & containment liner penetration welds HERDT.AR Region 2, Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2, Atlanta, Office of the 80/05/07 Director
- BOOAO4024B Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Operability " Requires action & response within 30 days IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Days-Besse Unit i While in Refueling Mode" encl CIMEILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09
- 8006300137 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oll Cooler Failures" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/09/13
- 8006200604 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "
 No equipment on other instrument & control power buses is needed to maintain hot or cold shutdown condition SYLVIA.B R Virginia Electric & Power Co 80/05/30 54pp
- 8006240238 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in demage to holdup tanks Two potential problem areas involving boron evaporator bottoms tank & boric acid storage tanks identified 84444 storage tanks identified 8444
- 8006120386 Forwards response to notice of violation contained in IE Insp Repts 50~338/80-20 & 50~339/80-21 Corrective action all equipment will respond to safeguards engineered actuation resets in FSAR
 SYLVIA.B R Virginia Electric & Power Co 80/06/10 5pp
- 8006300253 Forwards response to 1E Bulletin 80-09 Hydramotor actuator Models AH-90 & NH-90 are not used at facility SYLVIA.B R Virginia Electric & Power Co 80/06/10 3pp
- 8006900235 Forwards response to IR Bulletin 80-12 re decay heat removal sys operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if subsystem is operable SYLVIA:B R Virginia Electric & Power Co 80/06/11 App
- 8006300349 Responds to IE Bulletin 80-06 requesting review of drawings for all sys serving safety-related functions at schematic level-yerification of controls & proposed design mods Actions & schedules delineated in Item 3 BYLVIA:B R Virginia Electric & Power Co B0/06/12 10pp
- R Periodic operating reports & related correspondence
- 8004090262 Forwards "Special Tests & Design Changes 1979 BYLVIA:B R Virginia Electric & Power Co 80/06/05

- --8004070253 "Special Tests & Design Changes 1979 * Virginia Electric & Power Co 80/06/05 2
- 8006120301 Forwards monthly operating repts for May 1980 SYLVIA:B R Virginia Electric & Power Co 80/06/09
- --8006120304 Monthly operating repts for May 1980 HARVEY, S.L. Virginia Electric & Power Co. 8
- S Reportable occurrences, LFRs & related correspondence
- 8004130370 PND-11-80-093 on 800523, safety injection actuation occurred when vital electrical bus was lost while plant was shutdom of the plant was shutdom following unplanned reactor trip Caused by C steam generator feedwater regulating valve failure to open HEBSTER.E H. KELLOGO.F J Region 2. Atlanta. Office of the Director 80/05/23 10
- 8004050304 Forwards RO 80-47/01T-0 24-h followup rept MADISON,W R Virginia Electric & Power Co 80/05/27 1p
- --800605030B RO 80-47/01T-0 on 800523, activation of ECCS was initiated by high steam line flow/io-lo Tave signal Vital Bus i-III was de-energized at time of ECCS initiation Caused by frequency oscillations in dc to ac inverter for Vital Bus i-III

 * Virginia Electric & Power Co 80/05/27 2pp
- 8004060407 Forwards LER 80~041/03L~0 CARTWRIGHT, W R Virginia Electric & Power Co 80/05/30
- -8006060410 LER 80-041/03L-0 on 800503, during review of operations periodic test schedule, quarterly inservice insp of B LHSI pump check valves determined not performed within required interval Caused by inadvertent deletion from schedule CARTWRIOHT, W R Virginia Electric & Power Co 80/05/30 2pp
- 8006090359 Forwards LER 80-047/01T-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/04 ip
- --8006090361 LER 80-047/01T-O on 800823, safety injection occurred due to high steam line flow signal coincident w/lo-lo tave Caused by loss of vital 8us 1-III which removes power from feedwater flow/steam flow comparators for steam generators CARTWRIGHT,W R Virginia Electric & Power Co 80/06/04 App
- 8006f10324 RO several lines in low head & high safety injection sys were not analyzed for effects of fluid temp below 70 F Review of hew nozzle loads showed load on pump exceeded vendor allowable load Multiphase program proposed SYLVIA.B R Virginia Electric & Power Co 80/06/06 18pp
- 8006230499 Proposes multi-phase plan to address NRC concerns re amplified response spectra curves used as basis for analyses when piping sys is subjected to more than one spectra BYLVIA:BR Virginia Electric & Power Co 80/06/06 11pp
- 8006120331 Forwards LER 80-043/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/06/09 1p
- --B006120333 LER B0-043/OSL-O on B00510, while performing monthly surveillance test 1-PT-36 I on solid state protection train Apprmissive P-11 failed Caused by failure of logic card, universal card 411 Logic card replaced CARTHRIOHT.W R Virginia Electric & Power Co B0/06/O9 ⊋pp
- 8006120359 Forwards LER 80-044/03L-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/06/09 ip
- --B006120362 LER B0-044/03L-0 on B00510 control power fuses for containment particulate & gas radiation monitors blew when restarting sample pump Possibly caused by current feedback from motor contactor CARTHRIOHT.W R Virginia Electric & Power Co. B0/06/09 Virginia Electric & Power Co. 80/06/09 2pp
- 8006130174 Deficiency mept me safeguards area exhaust sys Exhaust sys modified to ensume operability following seismic event Mod consisted of installing mechanical means of opening central area exhaust ductwork on auxiliary bldg moof SYLVIA.B R Virginia Flectric & Power Co 80/06/09 3pp
- 8006230444 Updates 791031.1115.30 & 1228 repts re safeguards area exhaust sys not being entirely seismically designed Lists essential equipment which might not receive adequate cooling Affected equipment modified to assure operability SYLVIA.B R Virginia Electric & Power Co 80/06/07 3pp

- BOO6170643 Forwards LER 80-045/03L-0
 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/11 1p
- --8006170650 LER 80-045/O3L-0 on 800513, deviation of plus 3% between auxiliary shutdown panel indicator LI-1459C & control room indicator LI-1-461 was exceeded Caused by packing leak on isolation valve 1-RC-129 Valve repaired CARTWRIGHT, W R Virginia Electric & Power Co 80/06/11 2pp
- 8006230503 Forwards LER 80~048/03L~0 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/18 1p
- --8006230509 LER 80-048/03L-0 on 800520, one of two flow paths from refueling chemical addition tank to RMST was isolated to perform maint on leaking drain valve Caused by leak through valve packing & valve seat requiring removal of drain valve CARTWRIGHT, W R Virginia Electric & Power Co 80/06/18 2pp
- 8004230514 Forwards LER 80-051/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 80/06/19 1p
- --8006230524 LER 80-051/03L-0 on 800523, w/unit at hot standby, fuel oil vol in 1J emergency diesel generator day tank found w/less than min vol of 750 gallons Caused by neither fuel oil transfer pump refilling day tank CARTHRIGHT, W R Virginia Electric & Power Co 80/06/19 2pp
- 8006270262 Forwards LER 80-053/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/06/20 1p
- ---8006270265 LER 80-053/03L-0 on B00601, w/unit in cold shutdown, RHR pumps de-energized for more than 1-h Caused by need to repair valve packing leek resulting from personnel error Pump returned to svc following repair CARTWRIGHT. WR Virginia Electric & Power Co B0/06/20 2pp
- BO06270310 Forwards LER 80-049/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/20 ip
- --B006270315 LER 80-049/03L-0 on 800524, in Mode 3-mechanical chiller that maintains temp of containment bldg failed Caused by air voids in chilled water sys due to leaking valves & previously secured recirculation fans CARTWRIGHT, W R Virginia Electric & Power Co 80/06/20 2pp
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8006170518 Notifies that util efforts to satisfy requirements for issuance of full power SER & OL amend will be complete by early Jul 1980
 FERQUSON.J Virginia Electric & Power Co 80/06/12 p
- F Security, medical, emergency & fire protection plans
- BOOS130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Add1 specific criteria for facilities under development EISENHUT.D G Division of Operating Reactors BO/04/25 Aipp
- BOO612052B Requests that FEMA review of state & local emergency plan be provided consistent w/encl schedule to avoid potential delays in licensing decisions AMEARNEL J.F. Commission BO/05/13 2pp
- BOO6020011 Forwards request for additho needed to complete NRC review of guard training & qualification plan, submitted by util 780B18 lt info request withheld (ref 10CFR2 790) CLARKIR A Operating Reactors Branch 3 BO/05/19 2pp
- 8006030016 Responds to NRC 800519 Itr re guard training & requalification program Response will be forwarded by 800714 SYLVIA. B R Virginia Electric & Power Co 80/05/28 ip
- 8006090063 Notification of 800530 meeting w/ytil in Bethesda.MD to discuss emergency plan PROMERICK.A W Licensing Branch 1 80/05/30 3pp
- 8006130155 Summary of 800530 meeting u/util re facility emergency plan DROMERICK, A W Licensing Branch 1 80/06/02 4pp

- 8006110005 Forwards Revision 1 to emergency plan Section 4 will require mod resulting from 800530 meeting w/NRC & will be forwarded upon completion Communuealth of VA 800520 ltr enc1
 BAUM.E A Virginia Electric & Power Co
- --8006110007 Revision 1 to emergency plan * Virginia Electric & Power Co 80/06/09 100pp
- B006250361 Notification of 800619 site visit to discuss emergency operating procedures

 DROMERICK, A W Litensing Branch 1 80/06/17 4pp
- 8006240449 Forwards addit changes to station emergency plan, complating response to IW Ros 800515 comments
 BAUM, E. A. Virginia Electric & Power Co. 80/06/20. 2pp
- --8006240478 Emergency plan. Revision 2
 * Virginia Electric & Power Co 80/06/18 27pp
- 8008240183 Forwards Revision 3 to emergency plan, discussed w/NRC on 800820 Also forwards Sheriff of Hanover County,VA 800805 ltr of agreement & list of changes to emergency plan BAUM, R.A. Virginia Electric & Power Co. 80/06/25 lp
- --8005260184 Revision 3 to emergency plan Sheriff of Hanover County, VA 800605 ltr of agreement & list of changes enci * Virginia Electric & Power Co 80/06/25 23pp
- Q Adjudicatory correspondence
- 8006190018 Notifies that time has elapsed for Commission consideration of petitions for review of ALAR-584 Since Commission has not granted petition, petition is deemed denied CHILK-S J Office of the Secretary of the Commission 80/05/29.
- BOO6180429 Recommends that ASLAB composition be changed to remove imbalance between lawyer & technical members & that unnecessary legalistic burdens, procedures & requirements be eliminated DEALE.V 8 Valentine B Deale 80/06/09 4pg
- B006240347 Advises of change in info in 800324 ltr Westinghouse exit energy & probability analyses will not be ready until Oct 1980 S&W analyses will require six addl wks Crack size tables withheld (ref 100FR2 790) CIRISTMAN.J N Hunton & Williams 80/06/20 2pp
- 8006300413 Ack receipt of 800620 ltr re turbine missile issue Delay in Wastinghouse analyses is not matter of serious concern to ASLAB ASLAB must be promptly notified if disk cracking inspis postponed beyond Dec 1980

 BIBHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/06/24
- P Operating license stage documents & correspondence
- BOOGO90165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D Q Division of Licensing BO/05/07 150pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PMR Steam Generator & Reactur Coolant Pump Supports " Proposed review procedure & implementation schedule enc! EISENHUT,D G Division of Licensing 80/05/19 72pp
- 8006030087 Notification of 800528 meeting w/util in Bethesda,MD to discuss environ qualifications of Class IE electrical equipment & instrumentation DROMERICK,A W Licensing Branch i 80/05/22 3pp.
- 8006020173 Advises that contrary to date stated in 800428 ltr, temporary post-accident containment atmospheric sys will be installed by 800620.per NUREO-0578 Permanent sys will be installed by 810101 Stetches encl
 SYLVIA, B R Virginia Electric & Power Co 80/05/28 4pp
- 8006050329 Forwards revised Emergency Procedures 2-EP-1 through 2-EP-5 reflecting recent analyses & NSSS vendor recommendations Submittal also addresses NUREG-0660, Items 1 C 7 & I C 8 BYLVIA, B R Virginia Electric & Power Co 80/05/30 Ip
- --8006050330 "Reactor Trip," revised emergency procedures, HARVEY,S L. Virginia Electric & Power Co. 79/12/15 BPF,

- ~~8004050333 "LQCA," revised emergency procedures

 MARVEY, B L , CARTHRIGHT, W Virginia Electric & Power Co
 80/05/22 28pp
- --8004050333 "Loss of Secondary Coolant," revised emergency procedures HARVEY, S.L., KELLAME, J.D. Virginia Electric & Power Co. 80/05/22
- --8004050339 "Steam Generator Tube Rupture," revised emergency procedures
 HARVEY B L . CAPTURIGHT, W Virginia Electric & Power Co
 BO/05/22 25pp
- --8006050341 "Bafety Injection," revised emergency procedures HARVEY, B L , KELLAME, J D Virginia Electric & Power Co 80/03/13
- 8006120081 Notification of 800605 meeting w/util in Louisa.VA to discuss use of masonry walls DROMERICK.A W Licensing Branch 1 80/05/30 3pp
- 8006200302 Forwards request for addi info re high range monitors to continue review of FSAR Requests submittal by 800615 DROMERICK:A H Licensing Branch 1 80/05/31 App
- 8006200602 Forwards request for add1 info re containment sump performance Requests info be submitted by 800620 DRDMERICK, A W Licensing Branch 1 80/05/31 9PP
- 8006130025 Summary of 800528 meeting w/util & S&W re environ qualification of sefety-related electrical equipment DROMERICK, A W Licensing Branch 1 80/06/02 5pp
- 8006090341 Requests that Tests 8,7a & 7b be deleted from proposed test program Proposes to adapt TVA results from tests to simulator to augment operator training Test similar to Test 7b will be performed using decay heat SYLVIA, B R Virginia Electric & Power Co 80/06/05, 2pp
- 800A2300AB Approves request to withhold 800A29 application supplementing 791107 submitted re guide tube wear cree 10CFR2 790)
 YOUNDBLOOD, B. J. Licensing Branch 1 80/0A/05 2pp
- BOOA110063 Provides commitment to meet add1 TMI-2 related requirements, identified in NRC BOO507 ltr.providing equipment procurement schedules do not impact implementation of hardware changes SYLVIA.B R Virginia Electric & Power Co BO/06/06. 1p
- 8006130334 Proposes multiphase plan to address NRC concerns re multistructure amplified response spectra being used to analyze piping sys in Low head & high head safety injection lines List of multistructure problems & sample problem enci SYLVIA.B R Virginia Electric & Power Co 80/06/06 18pp
- BOO6120388 Confirms comptiance w/TMI-2 Bulletins & Orders Task Force final recommendations (Items C.3 9 through C 3 12). Proportional integral differential controller on pressurizer power operated relief valve modified BYLVIAB R Virginia Electric & Power Co '80/06/09 2pp.
- 8004120395 Forwards addi info re NUREG-0578. Item 2 i A a. Integrity Bus Dutaide Containment Likely to Contain Radioactive Matis.
 Leakage test results indicate elimination of leakage after
 maint & completes leakage evaluation for NVREC-0660
 SYLVIA:8 R Virginia Electric & Power Co 80/06/09 2pp. 80/04/09 200
- 8006120378 Forwards evaluation of battery room ventilation sys which exhausts into control room Neither hydrogen accumulation nor loss of battery electrolyte will pose safety hazard or control room habitability problem

 8YLVIA:B R. Virginia Electric & Power Co 80/06/10 9pp

- 8006170611 Forwards final Procedures 2-ST-8.2-ST-11.2-ST-6 & 2-ST-9 for special (low power) test program, incorporating Westinghouse & NSSS vendor comments Also forwards variation of Tests 2 & SYLVIA.B R Virginia Electric & Power Co 80/04/13 3pp
- --B006170615 "Natural Circulation Verification," final procedure for special (low power) test program
 KANN,G A Virginia Electric & Power Co B0/06/12 48pp
- --8006170621 "Effect of Steam Generator Secondary Side Isolation on Natural Circulation," final procedure for special (low power) test program KANN,O A Virginia Electric & Power Co 80/06/12 44pp
- --8006170626 "Cooldown Capability of Chemical & Vol Control Sys." final procedure for special (low power) test program
 KANN.G A Virginia Electric & Power Co 80/06/12 16pp
- ---B006170633 "Natural Circulation W/Simulated Loss of Power Conditions," final procedure for special (low power) test program KANN.G A Virginia Electric & Power Co 80/06/12 14pp
- 8006180532 Forwards description of containment high range radiation monitors required per NUREG-0578, Item 2 1 B b.in response to NRC 800531 Itr Floor plan drawing encl 8YLVIA:B R Virginia Electric & Power Co 80/06/16 4pp
- BOO6250308 Natification of BOO619 meeting w/utils in Bethesda,MD to discuss issuance of full power license for facilities DROMERICK.A W Licensing Branch 1 KERRIGAN,J D Licensing Bran 3 STAHLE,C R Licensing Branch 2 BO/06/16 App Licensing Branch
- 8006200480 Submits suppl to util 800610 ltr re proposed indicator circuit relamping for facility control room Further discussions have decided relamping unnecessary Lamp failures will be replaced per 800610 ltr info BROWN.8 C Virginia Electric & Power Co 80/06/17 1p
- BOO6190463 Forwards safety analysis & discussion of required exemptions to Tech Specs for special low power test program Requests amend to license which would permit performance of special test program by temporarily exempting certain Tech Specs FERGUSON.J H Virginia Electric & Power Co 80/06/18 & 40pp
- B006300259 Forwards request for addl info for review of FSAR re branch technical position RSB 5-1 Requests advisement if info will not be available by B00630 YOUNOBLOOD, BJ Licensing Branch 1 80/06/18 5pp
- 8006300303 Notification of 800626 meeting w/util in Louise County, VA to discuss battery room ventilation sys DROMERICK, A W Licensing Branch i 80/06/18 4pp
- 8006250128 Forwards "Electrical Equipment Qualification, NUREG-0588 Review," in response to NRC 800219 ltr & 800528 meeting in Bethesda, MD Rept is complete except for info not yet supplied by vendor BROWN, 8 C Virginia Electric & Power Co 80/06/20 ip
- --8006250129 "Electrical Equipment Qualification, NUREG-0588 Review "

 * Virginia Electric & Power Co 80/06/20 300pp
- 8006250289 Forwards response to request for addl info for review of FBAR Oversize drawings encl SYLVIA.B R Virginia Electric & Power Co 80/06/23 13pp
- --8006250293 "Typical Arrangement Containment Sump Screen "
 * Virginia Electric & Power Co 80/06/23 2pp
- --- B006250300 "Machine Location Reactor Containment, Plan Elevation 291 * Stone & Webster Engineering Corp 79/10/11 ip
- --8006250302 "Machine Location Reactor Containment,Plan Elevation 262 Ft.10 Inches " Sheet 2 * Stone & Webster Engineering Corp 79/10/11 ip
- --8006250307 "Machine Location Reactor Containment,Plan Elevation 241 Ft " Sheet 3 * Stone * Webster Engineering Corp 79/10/11 1p
- --8006250312 "Machine Location Reactor Containment, Plan Elevation 216 Ft. 11 Inches " Sheet 4 * Stone & Webster Engineering Corp 80/04/12 1p

- --8006250314 "Machine Location Reactor Containment, Sections 1-1,7-7, 8-8 & 9-9 " Sheet 5 * Stone & Webster Engineering Corp 79/10/11 1p
- --8004250318 "Machine Location Reactor Containment, Sections 2-2 5-5 &
 - 6 "Sheet 6 Stone & Webster Engineering Corp 79/10/11 1p
- --8006280316 "Machine Location Reactor Containment, Sections 3-3 & 4-4 "
 - Stone & Webster Engineering Corp 80/04/12 1p
- BOO4250120 Forwards comparison of auxiliary feedwater sys w/BRP as required by NUREO-0460 Submits supplemental info requested by NRC Unit P auxiliary feedwater sys is essentially identical to Unit I sys
 - Virginia Electric & Power Co 80/06/24
- 8006300501 Forwards revisions to Procedures 2-ST-9,2-ST-9 & 2-ST-11 renatural circulation verification training plan for conduct of tests submitted SYLVIA,B R Virginia Electric & Power Co 80/06/24 2pp
 - Virginia Electric & Power Co 80/06/24 2pp
- --8004300507 Changes to Procedure 2-ST-B, "Natural Circulation
 - Verification " * Virginia Electric > Pawer Co 80/06/24 ip
- --8006300509 Changes to Procedure 2-ST-9. "Natural Circulation w/Bimulated Loss of Circulation Verification "

 * Virginia Electric & Power Co 80/06/24 1p
- --8006300512 Changes to Procedure 2-97-11. "Effect of Steam Generator Becondary Side Isolation on Natural Circulation " * Virginia Electric & Power Co 80/06/24 1p
- 8006300388 Confirms agreement to review criteria for control rod bank reactivity worth tests Modified Table A 2 of VEP-FRD-36.
 "Control Rod Reactivity Worth Determination by Rod Swap Technique" encl THOMAS, W.N. Virginia Electric & Power Co. 80/06/26 - 6pp
- @ Inspection reports, IE Builetins & correspondence
- 8006160181 Forwards IE Insp Repts 50-338/80-16 & 50-339/80-i7 on 800303-04il No noncompliance noted LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/27 2pp
- --8006160186 IE Insp Repts 50-338/80-16 \$ 50-339/80-17 on 800303-0411 No noncompliance noted Major areas inspected short-term Lessons Learned (NUREG-0578) TMI-2 action plan (NUREG-0660) \$ plant readines s for fuel loading
 KELLOGO.P J Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch KIDD.M S Region 2, Atlanta, Office of the Director
 80/04/29 13pp
- 8004090082 Forwards IE Insp Repts 50-338/80-18 & 50-339/80-19 on 800413-16 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support 80/05/02 2pp
- --80040700BB IE Insp Repts 50-338/80-18 \$ 50-337/80-17 on 800413-14 No noncompliance noted Major areas inspected initial fuel loading of Unit 2

 UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch SURNETT, P T , DONAT, T J Region 2, Atlanta, Office of the Director 80/05/01 5pp
- 800±00±0418 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- B006200126 Forwards IE Insp Rept 50-339/80-18 on 800419-18 No NORCODIES FORMERS IN THE REPORT OF STATE OF STAT
- --8006200128 IE Insp Rept 50-339/80-18 on 800415-18 No noncompliance noted Major areas inspected containment & startup testing procedures
 UPRIGHT, C M Region 2, Atlanta. Reactor Operations Nuclear Support Branch FORD, E J Region 2, Atlanta, Office of the Director 80/07/08 300 Branch FORD, E J 80/05/08 3pp

- 8006040261 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Dperability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Qavis-Besse Unit 1 While in Refueling Mode' encl C'REJLLY, J P Region 2, Atlanta, Office of the Director 80/05/09
- 8006300137 Forwards 1E Circular 80-11, "Emergency Diesel Generator Luba Oil Couler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8006200604 Responds to IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " No equipment on other instrument & control power buses is needed to maintain hot or cold shutdown condition SYLVIA, B R Virginia Electric & Power Co 80/05/30 54pp
- 8006240238 Forwards response to 1E Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Two potential problem areas involving boron evaporator bottoms tank & boric acid storage tanks identified SYLVIA B R Virginia Electric & Power Co 80/06/09 3pp
- 8006120386 Forwards response to notice of violation contained in IE Insp Repts 50-338/80-20 & 50-339/80-21 Corrective action all equipment will respond to safeguards engineered actuation resets in FSAR BYLVIA, B R Virginia Electric & Power Co 80/06/10 5pp
- 8006300253 Forwards response to IE Bulletin 80-09 Hydramotor actuator Models AH-90 & NH-90 are not used at facility SYLVIA:B R Virginia Electric & Power Co 80/06/10 3pp
- 8006300235 Forwards response to IE Bulletin 80-12 re decay heat removal sys operability Current procedures provide adequate safeguards for redundancy or diversity requirements but will be changed if subsystem is inoperable BYLVIA.B R Virginia Electric & Power Co 80/06/11 App
- 8006300349 Responds to IE Bulletin 80-06 requesting review of drawings for all sys serving safety-related functions at schematic level.verification of controls & proposed design mods. Actions & schedules delineated in Item 3

 SYLVIA.B R Virginia Electric & Power Co 80/06/12 10pp
- 8006250132 Forwards Westinghouse rept re low pressure turbine disc ultrasonic insp Insp performed to address concerns about disc-to-shaft keyway cracking detected at other facilities SYLVIA-B R Virginia Electric & Power Co 80/06/24 43pp
- R Periodic operating reports & related correspondence
- 8006120301 Forwards monthly operating repts for May 1980 SYLVIA.B R Virginia Electric & Power Co 80/06/09
- --8006120304 Monthly operating repts for May 1980 HARVEY, S L. Virginia Electric & Power Co. B 80/06/02 Bpp
- 8 Reportable occurrences, LERs & related correspondence
- 8006160261 Part 21 rept re defective emergency diesel generator exhaust silencer support sys Seismic design calculated w/base support plate Drawings did not indicate base plate Util informed NRC of defect on 790302 Problem corrected WILD,P A Stone & Webster, Inc 80/05/29 Spp
- 8006050351 RD 80-io/017-0 on 800605 during review of ECCS piping, loading on low head safety injection pump notales was discovered to exceed design stress allowable Caused by deficiency in piping sys stress analysis

 * Virginia Electric & Power Co 80/06/05 ip
- 8006110252 Forwards LER 80-010/01T-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/06/05 ip
- --8006ii0287 i.ER 80-0i0/0iT-O on 800523, during review of ECCS piping for fluid temp below 70 F, determined that loadings on both low head safety injection pump notiles exceeded design stress allowables Caused by deficiency in sys stress analysis CARTWRIGHT.W R Virginia Electric & Power Co 80/06/05 3pp
- BOO6110324 RD several lines in low head & high safety injection sys-were not analyzed for effects of fluid temp below 70 F Review of new nozzle loads showed load on pump exceeded vendor allowable load Multiphase program proposed SYLVIA, B R Virginia Electric & Power Co 80/06/06 18pp

DOCKETED ITEMS

- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities
 SEAY, J. L. Chemtron Corp., Tube Turns Div. 80/06/06 Spp
- 8006230499 Proposes multi-phase plan to address NRC concerns re amplified response spectra curves used as basis for amalyses when piping sys is subjected to more than one spectra BYLVIA.B R Virginia Ejectric & Power Co 80/06/06 lipp
- 8006130174 Deficiency rept re safeguards area exhaust sys Exhaust sys modified to ensure operability following seismic event Mod consisted of installing mechanical means of opening central area exhaust ductuork on auxiliary bldg roof
 BYLVIA:BR Virginia Electric & Power Co 80/06/09 3pp
- B006230444 Updates 791031.1115.30 & 1228 repts re safeguards area exhaust sys not being entirely seismically designed Lists sssential equipment which might not receive adequate cooling Affected equipment modified to assure operability SYLVIA.8 R Virginia Electric & Power Co 80/06/09 3pp
- 8006160053 Forwards LER 80-008/03L-0 CARTWRIGHT, N. R. Virginia Electric & Power Co. 80/06/10 ip
- --8006160056 LER 80-008/03L-0 on 800521, during Mode 3 operation, redundant channel protection was lost Caused by personnel not placing Tave protection loop falled channel in trip mode within required time Failed channel placed in trip mode GARTWRIGHT, W Virginia Electric & Power Co 80/06/10 2pp
- 8006160076 Forwards LER 80-004/03L-0 CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/06/10 ip
- --8005160077 LER 80-004/03L-0 on 800519, during Mode 3 operation, steam generator level channel LT-2475 indicated level 9% lower than two redundant channels Caused by voltage drift Channel was placed in trip mode CARTWRIGHT, W R Virginia Electric & Power Co 80/06/10 2pp
- BOOSI70380 Forwards LER 80-007/03L~O CARTHRIGHT.W R Virginia Electric & Power Co BO/05/11 1p
- ---8006170587 LER 80-007/03L-O on 800521, during mode 3 operation, channel in tave protection loop 2 failed in high direction Cause is unknown Failed channel was removed from svc & replaced by spare CARTHRIGHT, W R Virginia Electric & Power Co 80/06/11 2pp
- 8004170694 Forwards LER 80~005/03L~0 CARTWRIGHT:W R Virginia Electric & Power Co 80/06/11, ip
- --8006170701 LER 80-005/03L-0 on 800517.2J emergency diesel generator tripped after starting & operability of 2H diesel generator was not verified within 1-h Caused by existing procedures not specifying test connections required to test diesel CARTWRIGHT,W R Virginia Electric & Power Co 80/06/11 2pp
- 6006230417 Forwards LER 80-013/03L-0 CARTURIGHT.W R Virginia Electric & Power Co 80/06/18 1p
- --8006230418 LER 80-013/03L-0 on 800520 & 27, w/unit in hot standby, samples of boron injection tank & "C" boric acid storage found to contain less than 20,000 ppm boron Caused by leaks past inlet valves MOV-2867 A & B Buttch settings increased CARTHRIGHT, W R Virginia Electric & Power Co 80/06/18 2pp
- 8006230442 Forwards LER 80~020/03L~0 CARTWRIGHT, W.R. Virginia Electric & Power Co. 80/06/18 ip
- ---8006230447 LER 80-020/03L-0 on 800529 during Mode 3 condition, 72-h
 periodic test of containment personnel hatch was not
 accomplished due to failure of doors to close Caused by
 failure of limit switch on inner door Switch replaced
 CARTHRIGHT.M R Virginia Electric & Power Co 80/06/18 2pp
- 8006230544 Forwards LER 80~009/03L~0 CARTWRIGHT.W R Virginia Electric & Power Co 80/06/18 1p
- --8006230551 LER 80-009/03L-0 on 800822 power supply for main stead pressure protection channel III failed high causing steam line pressure mismatch Caused by failed card in power supply Card was replaced & calibr CARTWRIGHT.W R Virginia Electric & Power Co 80/06/18 2pp
- 8006230494 Forwards LER 80-011/03L-0 CARTHRIOHT.W R Virginia Electric & Fower Co 80/06/19 1p

- --8006230500 LER 80-011/03L-0 on 800520, personnel air lock doors would not seal completely, causing air leakage while performing surveillance test 2-PT-62 4 Caused by leakage past seals on inner & outer doors New seals were installed CARTWRIGHT.W R Virginia Electric & Power Co 80/06/19 Rep
- 8004230534 Forwards LER 80-006/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co 80/06/19 1p
- --8006230537 LER 80-006/03L-0 on 800520 during startup testing in Mode 3, B steam generator narrow range level channel III was observed reading below redundant level channels & drifting low Caused by air pocket in steam generator sensing line CARTWRIGHT.W R Virginia Electric & Power Co 80/06/19 2pp
- 8006270236 Forwards LER 80-003/03L-0 CARTWRIGHT,W R Virginia Flectric & Power Co 80/06/20 1p
- --8006270241 LER 80-003/03L-0 on 800528.2H diesel generator frequency & voltage response was not verified every 8-h.contrary to Tech Spec Caused by faulty lead on monitoring instrumentation Offsite power sources verified & found acceptable CARTHRIGHT.N R Virginia Electric & Power Co 80/06/20 2pp
- 8006270270 Forwards LER 80-015/03L-0 CARTWRIGHT,W R Virginia Electric & Power Co 80/06/23 1p
- --8006270275 LER 80-015/03L-0 on 800525 personnel air lock outer door could not be closed due to hydraulic sys failure Caused by broken pressure gauge connection Connection repaired, tested & returned to svc CARTHRIOHT, W R Virginia Electric & Power Co. 80/06/23 2pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8006230ii0 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures Ceneral operating reactor review procedure & acceptance criteria encl EISENHUT, D O Division of Licensing 80/05/20, 13pp
- 8006120016 Forwards request for add1 info for review of FBAR FBAR should be amended to comply w/encl requirements Requests nottfication if info will not be available by 800801 BCHWENCER.A Licensing Branch 2 80/03/27, 14pp.
- 8006180621 Notification of 800613 meeting w/BWR Licensing Resolution Group in Bethesda,MD to discuss progress WILSON,J N Licensing Branch 1 80/06/09 10pp
- 8006250321 Summary of 800514 meeting w/utils in Bethesda, MD re organization & objectives of BWR licensing resolution group Agenda & viewgraph encl WILSON.J N Operating Reactors Branch 4 80/06/17. 11pp
- F Security, medical, emergency & fire protection plane
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 1tr Add1 specific criteria for facilities under development EISENHUT, D 0 Division of Operating Reactors 80/04/25 61pp
- H General correspondence
- 8006200504 Forwards IE Investigation Rept 50-341/80-02 on 800121-23 & 0211-12 PHILLIPS, C A Region 3, Chicago, Office of the Director, 60/05/28 19
- BOOA170281 Responds to enci BOO321 ltr to President Carter expressing concern w/NRC investigation of media allegations that serious problems exist at facility Resumes of certain people did contain false info but were not relied on in hiring DIRCKS W J Office of the Executive Director for Operations BO/05/29 3pp
- 8006190015 Responds to B00321 lir to President Carter re qualifications of design personnel qualifications of design personnel adequate although util has not established requirements Notice of violation was issued THGRN80460 P Division of Reactor Construction Inspection B0/06/02 7pp

- 8006240089 Responds to 800327 ltr to President Carter re qualification of design personnel Qualifications were adequate for performance of job function. Although util failed to establish personnel requirements THORNBURG. 80/06/05
- 8006270126 Responds to 800421 ltr ie M8 Nelson concerns about NRC investigation of alleged problems at constiste Investigation revealed that certain util activities failed to comply u/small bore piping suspension design controls DIRCKS.W J Office of the Executive Director for Operations 80/06/02 2pp
- --8006270127 Requests response to encl MB Nelson 800414 itr re NRC investigation of alleged problems at const site PURSELL.C D House of Rep 80/04/21 3pp
- 8006230093 Responds to 800323 ltr to Representative P Findley re 206233093 Responds to 800323 itr to Representative P Findieg investigation at const site Investigation prompted by ABC television allegations of unqualified personnel employed as designers NRC investigation butl response encl STELLO.V Office of Inspection & Enforcement, Office of the Director C 80/06/03 2pp

I Financial information

- BOOG170404 Forwards Northern MI Electrics Cooperative, Inc. Wolverine Electric Cooperative & Detroit Edison Annual Financial Repts 1979 THOMAS E B LeBoeuf, Lamb. Leiby & MacRae 80/06/13 1p
- ---8006170405 Annual Financial Rept 1979

 * Northern Michigan Electric Cooperative, Inc. 80/02/22 30pp
- --8004170407 Annual Financial Rept 1979

 * Volverine Electric Cooperative 80/02/01 21pp

- P Operating license stage documents & correspondence
- 8006030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose CA re confirmatory analysis & testing programs concerning Mark I containment long-teim program GRIMES: C I Assistant Director for Plant Systems 80/05/07 8pp.
- G Inspection reports. 1E Bulletins & correspondence
- 8006040253 Responds to IE Bulletin 80-02. "Inadequate GA for Nuclear Supplied Equipment "Thermal sleeves for feedwater nozzles prise Equipment "incrmal sideves for reedmater not: e mfg by Marvin Engineering Spargers were not mfg by vin GE supportive itr and ES:E Detroit Edison Co BO/05/13 3pp
- 8006200256 Forwards 1E Insp Rept 50~341/80-05 on 800421-23 No noncompliance noted
 HEIBHMAN.R F. Region 3, Chicago, Reactor Operations Nuclear Support
 Branch 80/05/14 2pp
- --8006200266 IE Insp Rept 50-341/80-05 on 800421-23 No noncompliance noted Major areas inspected preoperational testing GA program 5 action on previous insp findings LITICLN 8. SHANSONE R Region 3. Chicago. Office of the Director 83/05/12 3pp
- 8006300030 Forwards 1E Insp Rept 50-341/80-07 on 800430-0502 Na noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branco 80/05/20 2pp
- --B00&300033 IE Insp Rept 50-341/B0-07 on B00430-0502 No noncompliance noted Major areas inspected environ protection emergency planning t confirmatory measurements EBS10.T H . OESTMANN, M J Region 3. Chicago. Office of the Director B0/05/16 App
- 8006300148 Forwards IE Insp Rept 50-341/80-08 on 800508 No noncompliance noted KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/21

- --8006300156 IE Insp Rept 50-341/80-08 on 800508 No noncompliance noted Major areas discussed communications between licensee & Region 3 re public affairs KEPPLER.J G , NORELIUS, C E Region 3, Chicago, Diffice of the Director FidRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/20 2pp
- BOOA2404BI Submits add1 info requested by NRC 800324 ltr re IE Insp Rept 50-341/79-25 Procedures developed include deviation disposition request corrective action, project audit response & reorganization HINES.E Detroit Edison Co 80/06/09 3pp
- 8006230681 Forwards response to 1E Bulletin 80-09, "Hydramotor Actuator Deficiencies " Present preoperational testing program sufficient to demonstrate functional adequacy HINES.E Detrost Edison Co 80/06/13 6pp
- 8006300566 Forwards 800529 internal memo in response to IE Bullatin 80-09 Present preoperational testing program is sufficient to demonstrate hydramotor actuator adequacy Test program mod Detroit Edison Co 80/06/13 App
- 8004270982 Forwards attachment to util response to IE Insp Rept 50-341/80-02 Attachment was omitted from original response due to error FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/17 7pp
- S Reportable occurrences, LERs & related correspondence
- 8006270282 Forwards final deficiency rept re use of improper seismic design criteria for design of QA Level I 3/8-inch & 5/8-inch instrumentation & control tubing FAHRNER.W J Detroit Edison Co 80/06/10 ip
- --8006270286 Final deficiency rept re use of improper seismic design criteria for design of GA Level I 3/8-inch & 5/8-inch instrumentation & control tubing Improperly designed tubing sys already installed will receive appropriate mode CASIGLIA.J H Detroit Edison Co 80/06/10 3pp
- 8006290363 Ack receipt of 800523 interim deficiency rept re cut reinforcing bar Will review final rept on matter upon receipt FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/11 ío
- 8006250369 Ack receipt of 800506 interim deficiency rept re defective Westinghouse switches Hill review final rept on matter Upon receipt FIORELLIG Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/06/11 ip
- 8006290370 Ack receipt of 800914 interim deficiency rept re seismic Category I instrumentation & control tubing Will review final rept on matter upon receipt FIDRELLIA Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8006270230 Interim defitiency rept re nonseismic equipment installed over or in close proximity to safety-related equipment Repair of affected equipment not yet begun final rept will be delayed until 800715
 FAHRNER, W J Detroit Edison Co 80/06/12 1p
- 8006270330 Forwards final deficiency rept re defective Westinghouse switches
 FAHRNER, W.J. Detroit Edison Co. 80/06/13 ip
- DUCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergancy & fire protection plans
- 8006090487 Forwards proposed rule entitled. "Fire Protection Frogram for Nuclear Power Plants Operating Prior to 790101," Rule adds new Section 50 48 % App R to 10GFR50 & is expected to be published in FR by end of May EISENHUT, D @ Division of Licensing 80/05/19. 46pp.

- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Frior to 790101," transmitted by NRC 800519 ltr Page 14a net encl EISENHUT, D Q Division of Licensing 80/05/22 73pp
- BOO&170516 Forwards util draft responses to NRC & DR DDE review of facility security plan Requists BOO&26 & 27 meeting w/NRC & OR DOE to discuss review comment responses & proposed security plan revisions Plan withheld (ref 10CFR2 790) BROEHLD J Portland General Electric Co BO/06/13 2pp
- 8006240401 Requests presence of C Gaskin at util & OR DDE meeting in Fortland. OR Requests meeting w/NRC & OR DDE to coordinate responses to areas of concern prior to 800703 GOODHIN.C Portland General Electric Co 80/06/20 tp

Q Adjudicatory correspondence

- 8006170139 Forwards list of requests for design changes associated w/control bldg design mods proceeding Util will inform ASLB of further activities per 770330 prehearing conference W/Certificate of 5vx Related correspondence JOHNSON.R W Portland General Electric Co 80/05/05 5pp
- 8006030552 Forwards technical rept re effects of volcanism & landslides from Mount St Helens on facility RB McMullen affidavit encl DENTON.H R Office of Nuclear Reactor Regulation, Director BO/05/09 3pp
- ---8006030557 Fechnical rept to possible impact of Mount St Helens on facility in form of affidavit filed w/ASLB in spent fuel pool proceeding HCHULLEN.R B 78/04/12 20pp
- --8006030572 Expresses concern for public health & safety due to proximity of volcanic activity at Mount St Helens to facility Requests shutdown & relocation of fusionable matl in event of impending disaster WHITE,D Lane County,OR 80/04/08 ip
- 8006060533 Forwards State of OR proposed findings of fact & conclusions of law re design mods for facility & memo of points & authorities in support of State of OR proposed findings of fact & conclusions of law DSTRANDER.F W Oregon, State of 80/05/19 ip
- --8004040539 State of CR proposed findings of fact & conclusions of law re design mods for facility If proposed findings are included by ASLB in initial decision. State of CR will concur w/proposed licensee findings & conclusions OSTRANDER.F W Oregon, State of 80/05/19 7pp
- --8005060544 Memo of points & authorities in support of State of OR proposed findings of fact & conclusions of law Proposed findings are intended to increase likelihood that mods to facility will neet seismic safety sids
 OSTRANDER.F W Oregon, State of 80/05/19 6pp
- 8006020500 Order instituting corrections to 800331-0403 & 0416-17 evidentiary hearing transcripts Pp 3,640-4,828 MILLER, M.E. Atomic Safety and Licensing Board Panel 80/05/22 47pp
- 800&060497 Response to NRC & State of QR proposed findings of fact & conclusions of law Reporting requirement will detract from other licensee responsibilities & should not be imposed NRC agrees to Footnotes 2.3 & 4 Certificate of Svc encl CARR.A V . AXELRAD.M Portland General Electric Co CARR.A V Lowenstein, Newman, Reis, Axelrad & Toll 80/09/29 13pp
- 8006030135 Admits & corrects error in NRC 800519 proposed findings of fact & conclusions of law on control bldg mod.stated in Footnute 34 on Page 134 GRAY.J R Hearing Branch i 80/05/30 3pp
- 800&060293 Order requesting licensee to supply affidavit re licensee B00519 rept on discovery of inadequate connection in auxiliary bidg wall Cause of occurrence & Other related matters should be identified Certificate of Svc encl MILLER, M E Atomic Safety and Licensing Board Panel 80/06/02
- 8004110221 Certifies svc of licensee ltr w/LER 80-07 on 800602 JOHNSON,R W Fortland General Electric Ca 80/06/02 2pp

- 8006i1033B Responds to NRC 800602 order requesting licensee to supply info by affidavit re LER 80-07 submitted 8005i9 to Region 5 Licensee plans to complete insp by 800606 Certificate of Svc encl AXELRAD,M Lowenstein,Newman,Reis,Axelrad & Toll 80/06/05 3pp
- B006120153 States no objections to NRC 800530 proposed correction of Footnote 34 on Page 134 of NRC 800519 proposed findings Concerns analysis of displacements at interface between control 8 turbine bidgs Centificate of Svc encl AXLERAD.M Lowenstein.Neuman.Reis.Axelrad & Toll 80/06/09 2pp

H General correspondence

- 8006240632 Expresses concern re proximity of facility to Mount St Helens volcano Facility should be closed down RARD.C Affiliation Unknown 80/05/13 2pp
- I financial information
- 8006190625 Forwards Chase Manhattan Bank 800505 acknowledgement re extension of credit until 810507 TR Selliken 800515 ltr re secondary financial protection also encl SNEDECOR.E Portland General Electric Co 80/06/12 App
- --8006190645 Reconfirms obligation on behalf of Eugene Water & Electric Board concerning retrospective premiums under Price Anderson Act Bonneville Power Administration obligated to pay retrospective premiums HITTLE, L G Energy, Dept of 80/06/03 2pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning, licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D Q Division of Licensing 80/05/07 150pp
- 8006050536 Forwards request for add1 info re review of 791005 & 800225 ltrs concerning adequacy of station electric distribution sys voltages Response should be submitted within 49 days to maintain review schedule CLARK
- BOO6060247 Forwards request for addl info re NRC requirements for auxiliary foodwater sys Rosponse requested within 45 days to maintain review schedule CLARK.R A Operating Reactors Branch 3 80/05/14 7pp
- 8006060217 Disregard summary of 800501-02 meeting w/util & Bechtel re wall w/seismic anchor attached being structurally inadequate to resist earthquake Purpose was to develop evaluation criteria for masonry walls list of attendees encl
 TRAMMELL.C M Operating Reactors Branch 3 80/05/16 8pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implomentation schedue; oncl EISENHUT,D G Division of Licensing 80/05/19 72pp
- 8006060363 Forwards requests for design changes re mod program described in rept on design mods.involving piping supports to qualify piping sup for response spectra

 MCCARREL, S F Portland General Elettric Co 80/05/20 5pp
- 8006190166 Ack receipt of 800327 ltr describing program for removal of Rous 1 & 2 U-bend samples from D steam generator Proposed steam generator evaluation program found acceptable Provides schedule for reporting results of Hestinghouse lab analyses CLARK.R A Operating Reactors Branch 3 80/05/22 2pp
- 8006030391 Informs that interim procedural changes for nonconservative features identified in rod drop analysis will remain in effect until longer term solutions have been developed via Westinghouse topical rept due mid-1980 GEODWIN, C Portland General Electric Co 80/05/28 2pp
- 8006090321 Forwards application to amend License NPF-1, providing increased operational flexibility to deal w/steam generator tube corrosion, submitted as Revision i to License Change Application 20 Certificate of Syc encl GOODWIN, C Portland General Electric Co 80/06/02 2pp

- --8006050324 Application to amend License NPF-1, incorporating secondary water chemistry monitoring program submitted as Revision 1 to License Change Application 20. in response to NRC 790801
 - GOODWIN, C Portland General Electric Co 80/04/02 1p
- --8006050326 Tech Spec change request for Tech Spec Section 2 c ii re secondary water chemistry monitoring program, replacing Tech Specs Sections 3 7 i 3,4 7 i 3 t Table 4 7-3 concerning limiting condition & surveillance requirements * Portland General Electric Co B0/06/02 2pp
- 8006240171 Forwards Amend 44 to License NPF-1.safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 80/06/06 3pp
- --B006240179 Amend 44 to License NPF-1.revising power distribution & control rod insertion limits for reactor tore CLARK.R A Operating Reactors Branch 3 80/06/06 10pp
- --8006240177 Safety evaluation supporting Amend 44 to License NPF-1 * Office of Nuclear Reactor Regulation, Director 80/06/06
- --8006240179 Notice of issuance 3 availability of Amend 44 to License NPF~1 CLARK.R A Operating Reactors Branch 3 BD/06/06
- 8006i60124 Natifies that comments on NUREG/CR~1280, "Power Plant Btaffing," will not be submitted by 800609 Requests 60~6ay extension of comment period GOODMIN,C Portland Conceral Electric Co 80/06/09 2pp
- 8006230409 Forwards response to NRC 800507 ltr re implementation of five add1 TMI-2 related action items
 GDDDWIN.C Portland General Electric Co 80/06/16 5pp
- 8006230625 "Schematic Diagram Auxiliary Feedwater Pump Auto Start Steam Generator Bloudown Isolation " Sheet 2 * Bechtel Corp 6478 78/11/24 ip
- BOO6230604 Forwards add1 info re containment purge mys requested by NRC BOO318 ltr Provides response to questions & "as-built" tabulation of engineered safety features aquipment required to operate automatically following accident GOODWIN.C Portland General Electric Co 80/06/16 17pp
- ---8006230605 "Schematic Diagram Auxiliary Feedwater Pump Diesel Controls," as-built Sheet 1 * Bechtel Corp 4478 79/01/09 1p
- --8006230606 "Schematic Diagram Feedwater Control Valves," as-built Sheet * Bechtel Carp 6478 77/01/10 1p
- --8006230607 "Schematic Diagram Containment Spray Valve " Sheet 3, * Bechtel Corp 6478 79/10/30 ip
- ~-8006230608 "Schematic Diagram Diesel Generator Control," as-built * Bechtel Corp 6478 78/06/08 ip
- ~-8006230609 "Schematic Diagram RHR Pumps "
 * Bechtel Corp 6478 77/01/10 ip
- ~-8006230610 "Behematic Diagram Component Cooling Water Sys Isolation Valves," as-built * Bechtel Corp 6478 77/01/10 ip
- ~~8004230411 "Schematic Diagram Main Steam Line Ivolation Valves." as-built Sheet 1 * Bechtel Corp 6478 77/01/10 1p
- --8006230612 "Schematic Diagram Component Cooling Water Bys Containment Isolation Valves," as-built Sheet 3 * Bechtel Corp 6478 77/01/10 ip
- --8004230413 "Schematic Diagram 4,140 Volt Diesel Generator, ACB, "
 - # Bechtel Corp 6478 77/09/20 1p
- --8006230614 "Bechematic Diagram Component Cooling Water Pumps " Bheet 3 * Bechtel Corp 6478 75/10/21 1p
- ---8006230615 "Schematic Diagram Reactor Coolant Drain Tank Bample Isolation Valve " * Bechtel Corp 6478 77/01/10 ip

- --8006230616 "Schematic Diagram Steam Line Drain Valves," as-built * Bechtel Corp 6478 77/01/10 ip
- ---8004230418 "Schematic Diagram Reactor Coolant Pumps "
 * Bechtel Corp 4478 78/09/27 ip
- --8008230820 "Schematic Diagram Chemical & Vol Control Sys Valves."
 as-built Sheet 6
 # Bechtel Corp 6478 77/01/10 ip
- --8006230621 "Schematic Diagram Component Cooling Water Pumps " Sheet 2 * Bechtel Corp 6478 75/10/21 1p
- --8006230622 "Schematic Diagram Steam Generator Blowdown Sample Valves "
 # Bechtel Corp 6478 75/05/30 ip
- --8006230623 "Schematic Diagram Heating & Ventilation, West Dissel Generator Damper & Condensate/Recirculating Valve Circuit," as-built * Bechtel Corp 6478 78/09/28 ip
- --8006230624 "Schematic Diagram Unit Generator Back-Up Protection." Bachtel Corp 6478 78/09/20 1p
- --8004230626 "Schematic Diagram Feedwater Turbine Trip & Reset Circuit " Sheet 2 * Bechtel Corp 6478 75/08/14 1p
- --8006230627 "Schematic Diagram Component Cooling Water Pumps " Sheet 1 * Bechtel Corp 6478 75/10/21 1p
- --8006230628 "Schematic Diagram Chemical & Vol Control Sys Valves " Sheet 2 * Bechtel Corp 6478 79/11/05 1p
- --8006230629 "Schematic Diagram Feedwater Turbine Trip & Reset Circuit." ex-built Sheet 1

 # Bechtel Corp 6478 79/03/29 1p
- --8006230630 "Schematic Diagram Auxiliary Feedwater Pump Auto Start & Steam Generator Blowdown Isolation," as-built Bheet 1 * Bechtel Corp 6478 79/04/18 ip
- --8006230631 "Schematic Diagram Charging Pumps (Centrifugal) " * Bechtel Corp 6478 75/07/14 1p
- --8006230633 "Schematic Diagram Heating & Ventilation Motor Control Bys. Control Bldg "
 * Bechtel Corp 6478 79/12/20 tp
- ---8006230634 "Schematic Diagram Auxiliary Feedwater Pump Turbine Steam Inlet Valves " * Bechtel Carp 6478 75/09/05 1p
- --8006230635 "Schematic Diagram Chemical & Vol Control Bys Valves "
- Sheet i * Bechtel Corp 6478 79/11/05 ip
- --8006230636 "Schematic Diagram Sample Isolation Valves," as-built, * Bechtel Corp 6478 77/01/10 ip
- --8006230637 "Schematic Diagram Feedwater Control Valves," as-built Sheet * Bechtel Corp 4478 77/01/10 ip
- --8006230638 "Schematic Diagram Feedwater Bypass Control Valves." ## Bechtel Corp 6478 77/01/10 1p
- ---B006230637 "Schematic Diagram Svc Water Pumps " Sheet 3 * Bachtel Corp 6478 75/10/21 1p
- --- 8006230640 "Schematic Diagram Feedwater Control Valves: " as-built Sheet * Bechtel Corp 6478 77/01/10 ip
- ~-8006230641 "Schematic Diagram Main Steam Line Isolation Bypass Valves," as-built * Bechtel Corp 6478 77/01/10 1p
- ---8006230643 "Schematic Diagram Containment Air Coolers "
 * Bechtel Corp 6478 74/06/07 1p

- --8005230644 "Stheratic Diagram Svc Water Pumps ' Sheet 2 * Bechtel Corp 6478 77/02/to 1p
- --- GCDA230645 "Schematic Diagram Containment Isolation Valve," as-built = Dechtel Corp. 6478 77/01/\$0 1p
- ~-8006230646 "Schematic Diegram Main Steam Line Isolation Valves," 4s-built Sheet 2 Bechtel Corp 6478 77/01/10 ip
- --BOO6230648 "Schematic Diagram Steam Generator Blowdown Isolation
 - * Bachtel Corp 6478 75/11/24 1p
- --8005230549 "Schematic Diagram Feedwater Control Valves." as-built Sheet
 - 1 * Bechtel Corp 6478 77/01/10 lp
- ~-8006230650 "Schematic Diagram Containment Sump Pumps Discharge Isolation Valve MD4180," as-built Sheet 2 * Bechtel Corp 6478 77/01/10 ip
- --0006230651 "Schematic Diagram Svc Water Pumps " Sheet 1 Bechtel Corp 6478 77/02/10 ip
- ~-8005230652 "Schematic Diagram Safety Injection Pumps " Becktel Corp 6476 73/08/17 ip
- ~-8035230553 "Schematic Diagram Chemical & Vol Control Sys Valves:" as-built Sheet 13 4 Bechtel Corp 6478 77/01/10 1p
- ~~80064230&55 "Schematic Diagram Containment Spray Pumps," as-built * Bechtel Corp 6478 77/01/10 ip
- ~-8006230657 "Schematic Diagram Chemical & Vol Control Sys Valves," #1-built Sheet II # Bechtel Corp 6478 77/01/10 ip
- ~-8006230658 "Schematic Diagram Containment Isolation Valve," as-built Sheet 1 e Bechtel Carp 6479 77/01/10 1p
- --8006230659 "Schematic Diagram Chemical & Vol Control Sys Valves," as-built Sheet 12 # Bachtel Corp 6478 77/01/10 1p
- --8006230861 "Schematic Diagram Engineered Safeguards Initiation on Preferred or Standby Power." as-built Sheet 3 # Bechtel Corp 6478 78/06/08 ip
- --8006230662 "Schematic Diagram Chemical & Vol Control Sys Valves," as-built Sheet 10 4 Bechtel Corp 6478 77/01/10 ip
- ---8006230863 "Schematic Diagram Safety Injection Sys Valves," as-built Bechtel Corp 6478 77/01/10 1p
- --8006230664 "Schematic Diagram Containment Purge Isolation Hotor Operated Valves," as-built s Bechtel Corp 6478 79/08/10 19
- ---8006230865 "Schematic Diagram Safety Injection Sys Valves," as-built Bechtel Corp 6478 77/01/10 1p
- ---BOO6230666 "Schematic Diagram Containment Sump Pumps Discharge Isolation Valve.CV4181," as-built Sheet i # Bechtel Corp 6478 77/01/10 Ip
- Sheet B # Bechtel Corp 6478 77/01/10 1p
- --8006230668 "Schematic Diagram RCS Valves " Sheet 3 * Becktel Corp 6478 75/07/25 1p
- --- 8006230669 "Schemetic Diagram Bafety Injection Sys Valves." as-built Sheet 4 • Becktel Corp 6478 79/08/10 ip

- --8006230670 "Schematic Diagram Engineered Safeguards Initiation on Preferred or Standby Power." as-built Sheet 2 * Bechtel Corp 6478 78/06/08 1p
- ---8006230672 "Schematic Diagram RCS Valves," as-built Sheet 2 * Bechtel Corp 6478 77/01/10 ip Bechtel Corp
- --8006230675 "Schematic Diagram Safety Injection Bys Valves," as-built Sheet 3 * Bechtel Comp 6478 77/01/10 1p
- ~-8004230678 "Schematic Diagram Containment Vent Radiation Monitor Isolation Valve," as-built * Bechtel Corp 6478 77/01/10 ip
- ~-8006230679 "Schematic Diagram Component Cooling Dater Bys, Containment Isolation Valves." as-built Sheet 4 * Bechtei Corp 6478 77/01/10 1p
- ---80062306B2 "Schematic Diagram Containment Room Emergency Ventilation Nobervold "Schematic Plagram Containmen Sys," as-built * Bechtel Comp 6478 77/01/10 1p
- ~~8006230684 "Schematic Diagram RCS Valves," as built Sheet 4 * Bethtel Corp 6478 77/01/10 ip
- ~-8006230585 "Schematic Diagram Engineered Safety Features Initiation on Preferred or Standby Power," as-built Sheet I * Bechtel Corp 6478 79/10/30 1p
- --8006230687 "Schematic Diagram Heating & Ventilation Motor Control Siys CB-2, Control Bldg," as-built Sheet i * Bechtel Corp 6478 77/01/10 1p
- --8006230689 "Schematic Diagram Engineered Safeguards Component Cooling & Svc Water Solemoid Valves," as-built Sheet 2 * Bechtel Corp 6478 76/10/18 ip
- --8006230690 "Schematic Diagram Containment Purge Isolation Control Valves," as-built * Bechtel Corp 6478 77/01/10 ip
- ---8006230697 "Schematic Diagram Engineered Safeguards Component Cooling & Evc Water Solehoid Valves." as-built Sheet 1 * Bechtel Corp 6478 77/01/10 ip
- ---8006230704 "Schematic Diagram Svc Water to Auxiliary Feedwater Power Pump Cooler Valves: " as-built * Bechtel Corp 647B 79/01/09 1p
- --8006230707 "Schematic Diagram Containment Spray Valve," at-built Sheet * Bechtel Corp 6478 77/Q1/10 1p
- 8006240082 Forwards list of requests for design changes per mod program described in "Rept on Design Mods for Troyan Control Bldg (POE-1020) " Items are mods involving piping supports necessary to qualify piping sys response spectra MCCARREL, S.F. Portland General Electric Co. 80/06/18 Spp
- 8006230590 Forwards application to amend License NPC-1, submitted as License Change Application 59, Revision 2, Incorporating Tech Specs for alternate shutdown capability min shift crew & fire protection Certificate of Syc ancl COCOMIN, C Portland General Electric CO 80/06/19 2pp
- --8006230593 Application to amend License NPF-1, submitted as License Change Application 59. Revision 2, incorporating Tech Bases for alternate shutdown capability, min shift craw & revisions to std Tach Bases on fire protection Safety evaluation encl GDODWIN, C Portland General Electric Co 80/06/19 App.
- --8006230597 Tech Specs 3/4 7 9 & 4 0 & Tables 3 3-10.3 7-4 & 6 2-1 re alternate shutdown capability min shift crew & fire protection * Portland General Electric Co. 80/06/19 11pp
- BOO6240329 Forwards application for amend of License NPF-1, submitted as License Change Application 57, Revision 1, changing Tech Bpecs for limiting conditions for operation, surveillance requirements & bases
 OCCOMMIN.C Portland General Electric Co 80/06/19 1p

- --B006240331 Application for amend to License NPF-1, submitted as License Change Application 57, Revision 1, changing Tech Specs for limiting conditions for operation, surveillance requirements & bases. Safety evaluation encl GDDDWIN C Portland General Electric Co B0/06/19 5pp
- ---8006240333 Toch Specs 3 i 2 7.4 i 2 7.3/4 i 2-3.3/4 7 2-3/4 B 2.3 7 8 2 & 4 7 8 2 for limiting conditions for operation, surveillance requirements b bases of borated water & fire protection sys * Portland General Electric Co 80/06/19 App
- BOO6240365 Forwards response to BOO515 request for info re turbine disc cracking Licensee has developed schedule for performing ultraponic wheel bore insp of at least one low pressure turbine during 1981 refuelling outage OCODWIN.C Portland General Electric Co BO/06/19 7pp
- G Inspection reports: IE Bulletins & correspondence
- B006250080 Forwards IE Insp Rept 50-344/80-09 on 800421-24 No noncompliance noted CREMEJ L Region 5, San Francisco, Reactor Operations Nuclear Support Branch B0/05/15 2pp
- --8006250083 IE Insp Rept 50-344/80-07 on 800421-24 No noncompliance noted Major areas inspected onsite review committee QA/QC program, procedures, procurement & test equipment STERNBERO, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch HORN, A J , BAGAGLIO, M J Region 5, San Francisco, Office of the Director 80/05/13 App
- 80062500BB Forwards IE Insp Rept 50-344/80-10 on 800401-30 No noncompliance noted CREMS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/05/15 2pp
- --8006230093 IE Insp Rept 50-344/80-10 on 800401-30 No nancompliance noted Major areas inspected plant operations maint, surveillance testing physical security review & audit, refueling & LeR followup STERNBERO, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch MALKROS M H . JOHNSON O W Region 5, Ban Francisco, Office of the Director 80/05/12 6pp
- 8006130076 Add1 response to FOIA request for six categories of documents re CPC Forwards documents listed in app FELTON, J M Division of Rules and Records 80/05/23 3pp
- ---8006130083 Discusses results of special inspire discovery of pipe caps on containment pressure sensing lines Lists reasons why imposition of civil penalty for violation would not be appropriate CREMS. J. L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 78/01/04 3pp
- 8006200049 Forwards IF Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/05/28 ip
- 8006240003 Grants interim relief from certain inservice insp & testing ASME Section XI reqlrements in response to util 790814 & 1224 requests forwards related FR notice CLARK,R A Operating Reactors Branch 3 80/06/10 4pp
- --8004260007 Notice of granting of interim relief from ASME Section XI inservice insp & testing requirements CLARK.R A Operating Reactors Branch 3 80/06/10 2pp
- 8006260026 Requests that encl 1E Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment," be forwarded to facility control bldg licensing board & listed parties
 EISENHUT, D G Division of Licensing 80/Q6/12 3pp
- --8006260040 Requests written response to IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment," since deficiencies found at other plants may have bearing on seismic qualification of equipment CLARK.R A Operating Reactors Branch 3 80/06/12, 1p
- 8006180472 Responds to IE Bulletin 80-06. "Engineered Safety Feature (EBF) Reset Controls " All safety-related equipment remains in whergency mode upon removal or reset of actuation signal Concern raised in bulletin not applicable BRUEHL.D J Portland General Electric Co 80/06/13 3pp

- 8006230423 Responds to IE Bulletin 80-04, "Engineered Safety Features (ESF) Reset Controls " Mod to control circuit of steam line drain isolation valves will be completed before conclusion of next refueling outage in 1981

 LENISCH.J W. CHRISTENSEN.S Portland General Electric Co 80/06/13 3pp
- R Periodic operating reports & related correspondence
- 8006110273 Forwards monthly operating rept for May 1980 YUNDT, C P Portland General Electric Co 80/06/02 1p
- --B006110277 Monthly operating rept for May 1980 BAIR,0 0 Portland General Electric Co G0/06/02 4pp
- B Reportable occurrences, LERs & related correspondence
- 8006050236 PND-V-80-037 on 800518, Mount St Helen erupted Unit 2 has approx I/B-inch of ask on ground, some ask dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive matis in sys components underway BISHOP.T W Region 5, San Francisco, Office of the Director 80/05/19 2pp
- 800A0A034B Forwards util 800519 ltr directed to NRC Region 5 re discovery of auxiliary bldg wall inadequately connected to interfacing structural elements Detailed rept w/corrective action 5 possible stmilar conditions will be provided AXELRAD.M Lowenstein.Newman.Reis.Axelrad & Toll 80/05/20 2pp
- --8006060350 Submits followup to 800516 rept re discovery of auxiliary bldg wall inadequately connected to interfacing structural elements Detailed rept w/corrective action & possible similar conditions will be provided BRDEHL, D Portland General Electric Co 80/05/19 App
- 8004040411 Forwards LER 80-007/01T-0 BROEHL,D J Portland General Electric Co 80/05/30 is
- --B004060415 LER 80-007/01T-0 on 800516 masonry wall in auxiliary bldg was discovered not connected to interfacing structures at top Caused by misinterpretation of design drawings Positive connection being made w/grouted reinforcing steel ERICKSON.L Portland General Electric Co 80/05/30 16pp
- 8006090379 Forwards LER 80-008/01T-0 YUNDT.C P Portland General Electric Co 80/05/30 2pp
- --8006070384 LER 80-008/01T-0 on 800516, during refueling operations, discovered that containment integrity was breached Caused by personnel error Two separate maint activities were being performed w/no coordination PARRY, J C Portland General Electric Co 80/05/30 ip
- 8006i103i3 Notifies that effects of wall problem, in LER 79-15, have been evaluated Changing modes from 6 to 5 prior to return to power operations would not reduce established safety margin Certificate of 5vc encl
 GOODWIN.C Portland General Electric Co 80/06/04 4pp
- 8006240319 Forwards Suppl 4 to LER 79-15, providing criteria & methodology for Bechtel evaluation of out-of-plane loads on heavy double withe masonry walls BROEHL:D J Portland General Electric Co 80/06/10 2pp
- ~~8006240321 Suppl 4 to LER 79~15, providing interim structural evaluation criteria for out-of-plane loads on heavy weight double wythe masonry wails Supportive mati encl # Portland General Electric Co 80/06/10 97pp
- 8006200498 Forwards Suppl 1 to LER 80-007/017-0.providing description of engineering review.reportable noncomformances & related evaluation results
 BROEHLID J Portland Operal Electric Co 80/06/16 6pp
- 8006300486 Forwards LER 80-009/03L-0 YUNDT,C P Pacific Qas & Electric Co 80/06/20 2pp.
- ~-8006300492 LER 80-009/03L-0 on 800522 following refueling spent fuel pool was partially drained while draining refueling cavity Caused by personnel error Personnel have been reinstructed & procedure changed PERRY, J C Pacific Gas & Electric Co 80/06/20 1p

- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8006020250 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during energencies to link all power plants & NRC Emergency Notification Sys hotime will also be used KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18 2pp
- 8006060584 Advises that revised 800327 emergency plan meets requirements except for long-term onsite capability for detection of inadequate core cooling & for improved accident sampling Deficiencies should be eliminated by 810101 REID.R H Operating Reactors Branch 4 80/05/19 2pp
- 8006090487 Forwards proposed rule entabled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT.D O Division of Licensing 80/05/19 4App
- 8006130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 10CFR30 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 ltr Page 14s not encl EISENHUT, D O Division of Licensing 80/05/22 73pp
- 8006060303 Forwards addl info 5 revisions for safeguards contingency plan Encis withheld (ref 100FR2 790) CROUSE,R P Teledo Edison Co 80/08/02 3pp
- 8006300448 Notification of B00627 meeting w/util in Bethesda, MD to discuss util proposals for fulfilling NRC requirements re emergency planning faculities GARNER, D J Operating Roactors Branch 4 80/06/20 2pp
- H General correspondence
- 8006060288 Forwards constituent J Branum 800407 ltr requesting info re expansion of power plant Related correspondence CLENN, J Senate, Governmental Affairs 80/05/20 2pp
- M Antitrust correspondence
- 8006060314 Requests that deadline for requests for hearings be extended to 800709 re availability of transmission svc Extension will allow NRC & intervenor to work out language discord between FERC Opinion 84 & NRC 800513 order ODLDBERO, R Cleveland, OH COLDBERO, R Goldberg, Fieldman & Letham, P C 80/06/02 2pp
- 8006170555 Motion for mod of NRC 800513 order to require filing of transmission schedule per FERC 800505 order Requests hearing on 800513 order if NRC denies mod Certificate of Syc enc! URBAN, J R Justice. Dept of 80/05/07 13pp
- P Operating license stage documents & correspondence
- 8006060283 Forwards documents for Auxiliary Sys Branch review of auxiliary feedwater reliability analysis for B&W operating plants H/o encis
 CAPRA, R A Light Water Reactors Branch 3 80/01/17 3pp
- 8006090165 Forwards add1 TML-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 3D days EISENHUT,D G. Division of Licensing 80/05/07 150pp
- 8006020119 Requests extension to 800619 for completion of activities re screening of contractor employees. CROUSE,R P Toledo Edison Co 80/05/19 ip
- 8006:30122 Requests comments on NUREO-0577. "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D.O Division of Licensing, 80/05/19 72pp
- 8006190173 Confirms arrangements for 800604 meeting in Olen Ellyn, IL to discuss mgt control & outage activities KEPPLER. J G. Region 3. Chicago, Office of the Director 80/05/27.

- BOOA1902BO Notification of 800610 meeting w/util & B&W in Bethesda.MD to discuss status of findings re fuel assembly holddown spring failures GARNER.D J Operating Reactors Branch 4 80/06/04 2pp
- 8006300052 Discusses licensee plans to increase onsite waste storage Requests reviews of onsite storage additions in monthly operating rept following period in which evaluation was completed Draft NRC onsite storage licensing position encl REID.R W Operating Reactors Branch 4 80/06/12 10pp
- 8006170456 Forwards application for amend to License NPF-3, modifying ETS CROUSE.R P Toledo Edison Co 80/06/13 1p
- --8006170463 Application for amend to License NPF-3, modifying ETS Eliminates Bections 2 1.2 2.2 3.3 1.4 0.5 4 1 Part A & changes table of contents, lists of figures & table, & Section 1 0 of App B to Tech Specs CROUSE, R P Toledo Edison Co 80/06/13 3pp
- --8006170472 Mod to ETS eliminating Sections 2 1.2 2.2 3,3 1.4 0.5 4 t
 Part A & changing table of contents.lists of figures &
 table. % Section 1 0 of App B to Tech Specs
 * Toledo Edison Co 80/06/13 7pp
- 8006240494 Responds to NRC 800905 request for info re loss of offsite power Two incidents of total loss & three incidents of partial loss of offsite power have occurred at facility Events were previously reported in LERs CRDUSE.R P Taledo Edison Co 80/06/17 3pp
- 8006230460 Forwards info re low pressure turbino wheel cracks, in response to NRC 800513 ltr CROUSER P Toledo Edison Co 80/06/18 6pp
- Q Inspection reports: IE Bulletins & correspondence
- 8006170795 Forwards IE Insp Rept 90-346/80-06 on 800310-14,17-21,24-28 & 0401-04 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/03/01 2pp
- --B006170797 IE Insp Rept 50-346/80-06 on B00310-14.17-21.24-28 & B00401-04 No noncompliance noted Major areas inspected followup on evious insp findings operational safety info meeting w/local officials & radiation protection REVES.L A. TAMBLING,T N. Region 3, Chicago, Office of the Director B0/04/27 7pp
- 8004050522 Forwards response to IE Bulletin 80-04 Existing FSAR analysis of reactivity increase following MSLB inside or outside containment considers & conservatively models all potential water sources
 CROUSE.R P Toledo Edison Co 80/05/05 4pp
- 9006030210 Forwards supplemental response to IE Bulletin 79-27 Procedures reviewed & revised to detail operator action in event of loss in indication 8/or function CROUSE.R P Toledo Edison Co 80/05/06 3pp
- 8006050527 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Design changes requested to further decrease non-nuclear instrumentation/integrated control sys vulnerability CROUSE, R P Toledo Edison Co 80/05/06 3pp
- 800609053R Forwards IE Info Notice 79-37 w/errata sheet Requests add1 Info re turbine discs Recommends that schedule be developed to perform full ultrasonic test of at least one low pressure turbine before next major outage REID.R W Operating Reactors Branch 4 80/05/13 3pp
- 8006030081 Forwards IE Insp Rept 50-346/80-13 on 800430-0502 & notice of violation Notice of violation withheld (ref 10CFR2 770) HIND, J A Region 3, Chicago, Safeguards Branch 80/05/21 2pp
- ""8004030083 IE Insp Rept 50-346/80-i3 on 800430-0502 Areas inspected physical barriers & access contrl Details withheld (ref 10CFR2 770)
 HIND, J A Region 3, Chicago, Safeguards Branch MADEDA, T J. CHRISTOFFER, O M Region 3, Chicago, Office of the Director 80/05/20 ip
- 8006180543 Discusses NRC 800502 immediate action ltr & util 800520 response NRC has no comments or questions re actions taken to correct Items B & C NRC comments on Item A contained in enci Encl withheld (ref 100FR2 770)
 KEPPLER, J & Region 3, Chicago. Diffice of the Director 80/06/05

- 800.6230201 Forwards response to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Review described in Encl 1 revealed error Decay heat pump suction was not isolated by containment isolation actuation as stated in Page 2 CROUSE, R P Toledo Edison Co 80/06/05 8pp
- 8006200379 Responds to Item 48 of IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Bys " Forwards description of results of follow-on analysis identified discrepancies for normally accessible safety-related piping CROUSE.R P Toledo Edison Co 80/06/16 4pp
- R Periodic operating reports & related correspondence
- BOOA030311 Informs NRC that typographical errors were discovered in section of recently submitted "1979 Annual Environ Operating Rept " Corrected Pages B-3 & B-15 encl CROUSE, R P Toledo Edison Co 80/05/27 2pp
- --8006030313 Revised Pages B-3 & B-15 to "1979 Annual Environ Operating Rept " Typographical errors corrected * Toledo Edison Co 80/05/27 2pp
- 8006130274 Forwards monthly operating rept for May 1980 MURRAY, T.D. Toledo Edison Co. 80/06/09 ip
- --8006130275 Monthly operating rept for May 1980 SARSDUR, 8 Toledo Edison Co 80/06/09 8pp
- S Reportable occurrences, LERs & related correspondence
- BOQ6060061 PND-III-80-075 on 800513, licensee discovered hold down spring on fuel assembly in core was broken More insps on 800516-17 revealed 11 cracked or potentially broken springs Plant shut down since 800408 Investigation continuing REYEGL A. TAMBLINO, T.N. HEISHMAN, R.F. Region 3, Chicago, Office of the Director 80/05/19 2pp
- 8006030372 Forwards repts NP-02-80-01 & NP-02-80-01A to provide 30-day written notification of overexposure rept W/o NP-02-80-01A CROUSE.R P Toledo Edison Co 80/05/23 ip
- --8006030377 RO on 800430, chemistry & health physics individual received dose of 4 7 rems Cause of exposure was erroneously low reading on meter or misreading of Teletector Individual was removed from working in radiation controlled areas * Toledo Edison Co 80/05/23 ip
- 8006120354 Forwards revised LER 79-118/03L-1 MURRAY, T D Toledo Edison Co 80/06/03 ip
- --B006120357 Revised 79-118/03L-1 on 791126, when reactor coolant pump tripped, reactor protection on sys high flux setpoint reduced to 78 5% full power, exceeding limit Caused by procedural deficiency due to incorrect info KGCIS, R Toledo Edison Co 79/12/21 2pp
- 8006120343 Forwards LER 80~041/03L-0 MURRAY,T D Toledo Edison Co 80/06/06 1p.
- --8006120344 LER 80-041/03L-0 on 800511, during performance of ST 5091 01 source range functional test, source range Channel 1 found out of tolerance & declared inoperable Caused by component failure in test module New module installed NERNER J Toledo Edison Co 80/06/06 3pp
- BOO6120345 Forwards LER 80-042/03L-0 MURRAY, T D Toledo Edison Co 80/06/06 1p
- --8006120347 LER 80-042/O3L on 800510, during performance of local leak rate test, combined leakage for all penetrations tested to date exceeded combined allowable leakage Caused by buildup on valve preventing good seal Valve seats will be relapped ROMREN.E H Toledo Edison CO 80/06/08 2pp,
- HOO6120350 Forwards revised LER 79-124/03L-1 MURRAY, T D Toledo Edison Co 80/06/09 1p
- --8006120352 Revised LER 79-124/03L-1 on 791208 during routine pump swicthing component cooling water pump L would not start from control room Caused by failure of breaker AC113 on essential switchgear bus C1 to close Breaker replaced RUDDLPH, J P Toledo Edison Co 80/01/05 3pp
- BOO6160082 Forwards LER 80-036/03L-1 MURRAY, T D Toledo Edison Co 80/06/09 1p

- --8006160085 LER 80-036/03L-1 on 800407, reactor protection sys initiated high flux trip of reactor Channel 2 trip module reflected trip signals from only three of four sys channels Caused by failure of trip relay K1 in Channel 2 trip module WERNER, B J Toledo Edison Co 80/05/06 2pp
- 8006170351 Forwards revised Page 2 to LER 79-088/03L-0 MURRAY.T D Toledo Edison Co 80/06/10 ip
- --8006170354 LER 79-088/03L-1 Revised Page 2 of LER 79-088/03L-0 * Toledo Edison Co 80/06/10 1p
- 8006300333 EN-80-25 notice of violation & notice of proposed imposition of civil penalty will be issued on or about 800620 Action based on alleged noncompliance re employee overexposure Will issue news release BROCKETI, TW., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/06/18 ip
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

 F Becurity, medical, emergency & fire protection plans
- 8006090497 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Bection 50 48 & App R to 10CFR50 & is expected to be published in FR by end of May EISENHUT, D @ Division of Licensing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14s for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," transmitted by NRC 800519 itr Page 14s not encl EIBENHUY.D 0 Division of Licensing 80/05/22 73pp
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensee requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D @ Division of Licensing 80/05/07 150pp
- 8006:301:22 Requests comments on NUREG-0577. "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT,D G Division of Licensing 80/05/19 72pp
- BOO6030312 Responds to NRC 800408 ltr requesting addl info re auxiliary feedwater sys Clarification of util 791120 response to recommendation 08-6 encl CLAYTON F. L. Alabama Power Co. 80/05/27 23pp
- 8006050350 Application to amend OLrauthorizing changes to Tech Specs Tech Spec 3 0 5 re operability of equipment w/o certain electrical power sources is added per NRC request Spec 3 8 2 2 is in error re number of volt load cts required CLAYTON: FL Alabama Power Co 80/05/30 3pp
- ---8006050353 Tech Spec 3 0 5 re operability of equipment w/o certain electrical power sources & Tech Spec 3 8 2 2 re ac distribution-shutdown + Alabama Power Co 80/05/30 5pp
- BOO6110017 Forwards add1 info re seismic qualification of safetyrelated non-NBSS electrical & mechanical equipment,in response to NRC BO0523 request CLAYTON.F L Alabama Power Co 80/06/05 59pp
- --8004110022 "Final Seismic Response Spectra, Joseph M Farley Nuclear Units I & 2.AL Power Co. Containment & Internal Structure " * Bechtal Corp 72/12/31 325pp
- --8006110027 "Beismic Response Spectra, Joseph M Farley Nuclear Plant, Units 1 & 2, AL Power Co. Auxiliary Bldg " # Bechtel Corp 72/08/31 75pp
- 8006190493 Advises that response to 800507 request re TMI-2 related requirements will be submitted by 800626 CLAYTON.F L Alabama Power Co 80/06/12 ip

@ Inspection reports, IE Bulletins & correspondence

- B004050414 Forwards IE Bulletin B0-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" entl
 O'REILLY, J P Region 2: Atlanta, Office of the Director 80/05/08
- 8006060525 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-07 & 50-364/80-04 LEMBAR C Region 2, Atlantar Reactor Operations Nuclear Support Branch 80/05/08 20p
- --B004040531 Responds to NRC 800410 ltr re violations noted in IE Insp Repts 50-348/80-07 & 50-344/80-04 Corrective actions cleaning stainless stoel pipes w/Bootch-brite pads was stopped Cleaning pads returned to warehouse CLAYTOM:FL Alabama Power Co 80/04/28 2pp
- --8006060534 Forwards IE Insp Repts 50-348/80-07 & 50-364/80-04 on 800204-27 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/10 3pp
- --8006060542 Notice of violation from insp on B00204-29

 + Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip
- --B006060550 IE Insp Repts 50-348/80-07 & 50-364/80-04 on 800204-29 Noncompliance noted unauthorized use of Scotch-brite pads for final cleaning of stainless steel pips surfaces & failure to perform work w/approved procedure MARTIN,R D Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 Opp
- 8006200076 Forwards IE Insp Repts 50-348/80-09 & 50-364/80-09 on 800421-25 No noncompliance noted BTOHR. J P Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/05/08 2pp
- --8006200094 IE Insp Repts 50-348/80-09 & 50-364/80-09 on 800421-25 No noncompliance noted Major areas inspected radwaste mgt. preoperational test procedures, chemistry & health physics procedures & security training BTOHR.JP Region 2. Atlanta. Fuel Facility & Materials Safety Branch TROUP.O L. WRAY.JR Region 2. Atlanta, Office of the Director 80/05/08 Spp
- 8006050291 Forwards IE Dulletin 80-12, "Decay Heat Removal Sys Operability " Requires action & response within 30 days IE info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 20s
- 8006300074 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 20s
- 8006250015 Forwards response to IE Bulletin 80-05 re vacuum conditions in chemical & vol control sys holdup tanks Vol control tank receives letdown from RCS & provides suction for charging back into RCS CLAYTON,F L. Alabama Power Co. 80/06/04 3pp
- 8005230182 Responds to IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Redundancy may be provided by having two RHR trains operable Diversity may be provided in Hodes 2-5 by having operable steam generators CLAYTON,F L Alabama Power Co 80/06/09 4pp
- 8006300572 Responds to IE Bulletin 80-06 Bafety-related components at schematic level have been reviewed to determine whether equipment remains in emergency mode following reset of signals CLAYTON,F L. Alabama Power Co. 80/06/12 3pp
- R Periodic operating reports & related correspondence
- 8006180440 Forwards monthly operating rept for May 1980 CLAYTON,F L. Alabama Power Co. 80/06/09 2pp
- --8006180442 Monthly operating rept for May 1980 HAIRSTON: N G Alabama Power Co 80/06/01 Spp

- S Reportable occurrences. LERs & related correspondence
- 8006050033 Forwards LERs 80-027/03L-0 & 80-030/03L-0 CLAYTON F L Alabama Power Co 80/05/28 1p
- --B006050036 LER B0-029/03L-0 on 80043D, intermediate range NIB channel N-35 declared inoperable due to loss of power Caused by loss terminal screw on 120-volt vital ac panel 1A molded case breaker Wire reconnected HAIRSTON, W Q Alabama Power Co B0/05/28 1p
- --8006050043 LER 80-030/03L-0 on 800501/radiation monitor R25A (fuel storage pool area) declared inoperable due to power loss Caused by blown fuse Connecting & disconnecting test equipment cause for blown fuse Fuse replaced HAIRSTON.W © Alabama Power Co 80/05/28 ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234kPD requirement investigations conducted & closed at 46 listed facilities SEAY, J.L. Chemtron Corp., Tube Turns Div. 80/06/06. 3pp
- 8006170598 Forwards LER 80-031/03L-0 CLAYTON: F & Alabama Power Co 80/06/10 1p
- --8006170604 LER 80-031/03L-0 on 800511, digital rod position indication sys (DRPI) declared inoperable following loss of train A & B DRPI caused by loss of DRPI indication during trouble shouting Train A returned to svc following card replacement HAIRSTON, W O Alabama Power Co 80/06/10 Ip
- 8006180432 Interim deficiency rept re unreacted lime in waste settling pond causing pH to exceed upper limit Caused by discharge of clarified water which dissolved calcium sulfate layer over lime Discharge terminated & acid will be added CLAYION.Ft Alabama Power Co 80/06/13 3pp
- 8006230348 Forwards LER 80-032/03L-0 & LER 80-033/03L-0 CLAYTON: F L Alabama Power Co 80/04/13 1pp
- --BOO6230363 LER 80-033/03L-0 on 800516.1-2A diesel generator declared inoperable due to speed control failure Caused by personnel error in installing do recorder which blew ac fuse Fuse replaced, personnel instructed HAIRSTON, W G Alabama Power Co 80/06/13 ip
- --8006230376 LER 80-032/03L-0 on 800515 both chlorine detectors were inoperable Caused by plastic strip lodged in B detector & cracked diaphram in A detector Strip removed & B made operable on 800515 Pump replaced & A operable on 800516 HAIRSTON,W Q Alabama Power Co 80/06/13 1p
- 8006240348 Forwards LERs 80-034/03L-0 & 80-039/03L-0 CLAYTON: F L Alabama Power Co 80/06/17 1p
- --8006240375 LER 80-034/03L-0 on 800519 diesel generator 10 was declared inoperable when generator failed to reach rated speed within time specified by Tech Spec Probably caused by leaky check valve in fuel oil sys Valve replaced HAIRSTON, W O Alabama Power Co 80/06/17 1p
- --8006240376 LER 80-035/03L-0 on 800519, diesel generator 2C would not auto-start >> was declared inoperable Caused by switch being inadvertently placed in run position rather than auto gosition Buitch placed in auto HAIRBTON, W O Alabama Power Co 80/06/18 2pp
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B006020330 Notifies of delay,until late June or early Jul 1980,for response to NRC 791218 request for comparison of blast response spectra w/OBE response BRADLEY,E J Philadelphia Electric Co 80/05/20 ip
- BOOARRO110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D Ø Division of Licensing 80/05/20 13pp
- 8006120121 Summary of 800521 meeting w/util in Bethesda,MD re risk evaluation study per encl NRC 800506 ltr SELLS,D Licensing Branch 2 80/05/23 App

- B004230001 Summary of 900410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU,T M Containment Systems Branch 80/05/30 4pp
- 8006190330 Notification of 800616 meeting w/util & General Physics in Silver Spring,MD to observe & receive orientation on simulator SELLS,D Licensing Branch 2 80/06/03 2pp

H General correspondence

- 8006020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated areas HAMM.K Affiliation Unknown 80/03/19 lp
- 8006020336 Comments on evacuation plan for facility area Philadelphia Electric Co should not be granted license Human safety should come before economic consideration MORRIS, S.W. Affiliation Unknown 80/05/28 ip
- 800&120089 Responds to litr to DDE re constituent inquiry about relationship of Merrili Creek Project to facilities NRC has no info re relationship Facilities use water from DE River Basin
 DIRCKS.W J Office of the Executive Director for Operations 80/05/30 6pp
- BOD6230469 Forwards Philadelphia City Council 800529 resolution that all const at facilities should cease to protect health & safety of area residents & ratepayers
 SCHMARTZ.G X Philadelphia PA 80/06/10 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8096120348 Responds to IE Bulletin 80-02 Util feedwater spargers & thermal sleaves not mfg by Marvin Engineering Co Equipment not Q-listed nor part of or welded to RCPB KEMPER, JS Philadelphia Electric Co 80/05/20 2pp
- 8006240091 Forwards Mgt Meeting Repts 50-352/80-06 & 50-353/80-06 on CARLEON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/29 1p CARLEON R T
- --8006240098 Mgt Meeting Repts 50-352/80-06 & 50-353/80-06 on 800321
 Areas covered status of FSAR, resident insp program, QA
 program, recent NRC insps. current organization of licensee &
 NRC & project status
 CARLSON, R T Region I, Philadelphia, Reactor Construction &
 Engineering Support Branch MATTIA.J C , MCOAUGHY, R W Region I
 Philadelphia, Office of the Director 80/05/20 2pp Region 1.
- 8 Reportable occurrences. LERs & related correspondence
- 8006670053 Ack receipt of 800424 ltr forwarding final deficiency rept re-electrical raceway separation Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/14 Ip
- ---8004090062 Final deficiency rept re electrical raceway separation Field const identified exposed seismic Class 1 raceway.conduit & junction box Caused by GC error GC procedure revised by indoctrination of GC engineers conducted # Philadelphia Electric Co = 80/04/30 4pp
- 800611632? Forwards final deficiency rept re electrical connections on back pressure steam isolation dampers
 KEMPER.J S Philadelphia Clectric Co 80/06/06 1p
- --8004110332 Final defictency rept re electrical connections on back pressure steam isolation dampers mfg by American Harming & Ventilating, Inc Mfg has agreed to 100% insp & replacement program, to be completed by 801231.

 * Philadelphia Electric Co 80/06/06 4pp
- BOO6200024 Final Part 21 rept re mixed heat of steel supplied by UB Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities
 BEAY, J.L. Chemtron Corp., Tube Turns Div BO/06/06 3pp
- 8006270217 Forwards final deficiency rept re defect in 4 kV switchgear circuit breaker auxiliary switch crank assembly KEMPER.J S Philadelphia Electric Co 80/06/20 ip

- ---B006270224 Final deficiency rept re defect in 4 kV switchgear circuit breaker auxiliary switch crank assembly Insp will be conducted on switchgear 5 nuts will be secured on assembly studs to prevent loosening, by B01231

 * Philadelphia Electric Co B0/06/20 4pp
- V Operator Examinations
- 8006200058 Notification of 800618 meeting w/util in Bethesés.MD to discuss current requirements for operator qualification & licensing SELLS.D E Licensing Branch 2 90/06/02 3pp

DOCKET 50-353 LIMERICK GENERATING STATION: UNIT 2

- A Application/construction stage documents & correspondence
- 8006020330 Notifies of delay, until late June or early Jul 1980, for response to NRC 791218 request for comparison of blast response spectra w/GBE response BRADLEY, E. J. Philadelphia Electric Co. 80/05/20 1p
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D O Division of Licensing BO/05/20 i3pp
- 8006120121 Summary of 800521 meeting w/util in Bethesda.MD re risk evaluation study per encl NRC 800506 1tr SELLS.D Licensing Branch 2 80/05/23 4pp
- 8006230001 Summary of 800410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T.M. Containment Systems Branch 80/05/30 App
- 8006190330 Notification of 800616 meeting w/util & General Physics in Silver Spring, MD to observe & receive orientation on SELLS, D Licensing Branch 2 80/05/03 2pp
- H General correspondence
- 8006020014 Requests public debate re evacuating large populations near power plants Opposes plants located in densely populated HAMM, K Affiliation Unknown 80/03/19 is
- BOO602033& Comments on evacuation plan for facility area Philadelphia Electric Co should not be granted license Human safety should come before economic consideration MORRIS:S W Affiliation Unknown BO/05/28 ip
- 800&120087 Responds to ltr to DOE re constituent inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Facilities use water from DE River DIRCKS, U J Office of the Executive Director for Operations 80/05/30 App
- BOO6230469 Forwards Philadelphia City Council BO0529 resolution that all const at facilities should cease, to protect health & safety of area residents & ratopayers BCHWARTZ, O X Philadelphia, PA BO/O6/10 5pp
- @ Inspection reports: IE Bulletins & correspondence
- BDOA120348 Responds to IE Bulletin 80-02 Util feedwater spargers & thermal sleeves not mfg by Marvin Engineering Co Equipment not 0-listed, nor part of or welded to RCPB

 KEMPER, J B Philadelphia Electric Co 80/05/20 2pp
- 8006240091 Forwards Mgt Meeting Repts 50-352/80-06 & 50-353/80-06 on 800321 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/29 1p
- --8006240098 Mgt Heeting Repts 50-352/80-06 & 50-359/80-06 on 8003R1 Areas covered status of FBAR, resident insp program, GA program, recent NRC insps, current organization of licenses & Project status

 CARLBON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MATTIA.J C. MCGAUGHY.R W Reg
 Philadelphia, Office of the Director 80/05/20 2pp

- S Reportable occurrences. LERs & related correspondence
- B006090053 Ack receipt of B00424 ltr forwarding final deficiency rept re electrical raceway separation Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/14 1p
- --8006090062 Final deficiency rept re electrical raceway separation Field constidentified exposed seismic Class I raceway conduit & junction box Caused by GC error GC procedure revised by indoctrination of GC engineers conducted Philadelphia Electric Co 80/04/30 4pp
- 8006(10329 Forwards final deficiency rept re electrical connections on back pressure steam isolation dampers
 KEMPER.J 5 Philadelphia Electric Co 80/06/06 ip
- --8006i10332 Final deficiency mept me electrical connections on back pressure steam isolation dampers mfg by American Warming & Ventilating, Inc Mfg has agreed to 100% insp & replacement program to be completed by 801231

 * Philadelphia Electric Co = 80/06/06 4pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by UB Bisel from which 4-inch elbows & 2-inch tees were mfg to AR34MPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J L Chemtron Corp . Tube Turns Div 80/06/06 3pp
- 8006270217 Forwards final deficiency rept re defect in 4 kV switchgear circuit breaker auxiliary switch crank assembly KEMPER.J S Philadelphia Electric Co BO/06/20 ip
- --8006270224 Final deficiency rept re defect in 4 kV switchgear circuit breaker abziliary switch crank assembly insp will be conducted on switchgear & nuts will be secured on assembly study to prevent loosening, by 801231

 * Philadelphia Electric Co 80/06/20 4pp

V Operator Examinations

8006200058 Notification of 800618 meeting w/util in Bathesda, MD to discuss current requirements for operator qualification & licensing SELLS.DE Licensing Branch 2 80/06/02 3pp

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B005030514 Bummary of B00422-23 meeting \(\omega / \text{Mark I owners group in San Jose, CA re confirmatory analysis & testing programs concerning Mark I containment long-term program ORIMES, C I Assistant Director for Plant Systems B0/05/09 Bpp
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT.D 0 Division of Licensing 80/05/20 13pp
- 8006260057 Forwards "For Comment" edition of NUREG-0619 Comments should be forwarded by 800707 W/o encl EISENHUT, D 0 Division of Licensing 80/06/09 2pp
- 8006060262 Correction to licensees' 800428 brief on disposition of alleged Deficiency i Certificate of Svc encl SilbeRG.J E Metcalf & Eddy RADER,R M Conner, Knore & Corber 80/05/20 Spp

O Adjudicatory correspondence

- 8004040245 Request for extension until 800418 for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy & intervenors have other commitments made prior to Feb 1980 Certificate of Syc encl
 KEPFORD, C Citizens for Safe Environment, 80/05/20 4pp
- 8006060547 Response to intervenors. York Committee for Bafe Environ & Citizens for Bafe Environ request for extension until 800618 to file proposed findings of fact in generic radon proceeding Many delays in proceeding are cause for concern CONNER.T B Philadelphia Electric Co TRAVIESO-DIAZ Shaw, Pittman, Potts & Troubridge CONNER.T B Public Service Electric & Qas Co of New Jersey 80/05/23 11pp

- 8004020550 Order granting extension until 800418 for York Committee for Safe Environ & Citizens for Safe Environ to file proposed findings of fact & conclusions of law NRC findings due on 800703 & intervenors' 3 applicants' responses on 800718 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/05/28 2pp
- 8006260209 Memorandum & order advising that Sterling issue is no longer germane to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 800702
 BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/06/23
 Sao

H General correspondence

- 8006120089 Responds to lir to DDE re constituent inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Facilities use water from DE River Basin
 DIRCKS, M J Office of the Executive Director for Operations 80/05/30 6pp
- @ Inspection reports, IE Bulletins & correspondence
- 8006020475 Responds to IE Bulletin 80-02. "Inadequate QA for Nuclear Supplied Equipment" Bulletin is not applicable since GE has not purchased reactor feedwater spargers & thermal sleeves for facility MARTIN.T J Public Service Electric & Gas Co of New Jersey 80/05/12 1p
- 8004250223 Ack receipt of 800418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80~01 & 50-355/80-01 CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/22 1p
- ---8006250226 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-354/80-01 & 50-355/80-01 Corrective actions GC procedures will be revised to address amended QA manual, Section 4 MARTIN.T J Public Service Electric & Oas Co of New Jersey 80/04/18 2pp
- ---B006250227 Forwards IE Insp Repts 50-354/80-01 & 50-355/80-01 on B00114-17 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/14 2pp
- ---9006250231 Notice of violation from insp on 800114-17

 Region i, Philadelphia, Office of the Director 80/03/11 ip
- --8006250233 IE Insp Repts 50-354/80-01 & 50-355/80-01 on 800114-17
 Noncompliance noted failure to take prompt corrective action re protection of equipment from weather & ring grooves left unprotected from damage in high activity area MCGAUDHY,R W. VARELA,A A. BATEMAN,W H. Region 1, Philadelphia, Office of the Director 80/03/11 Spp
- 8 Reportable occurrences. LERs & related correspondence
- GOO6020407 Second interim rept re potential deficiency in primary containment relief valves Initial analysis indicates binge block mounting stude inadequate Revised analysis by BOO630 MARTIN.T J Public Service Electric & Oas Co of New Jersey BO/05/23 2pp
- 8006300005 Ack receipt of 800502 final deficiency rept re weld wire documentation CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 60/06/04 ip
- B006250407 Ack receipt of 800523 interim deficiency rept re primary containment relief valves CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 IP
- S TINU ,NOITATB RABLOUM MEERS EACH CEE-OC TEMPOOL
- A Application/construction stage documents & correspondence
- 8004030514 Summary of 800422-23 meeting w/Mark I owners group in San Jose-CA re confirmatory analysis & testing programs concepning Mark I containment long-term program GRIMES,C I Assistant Director for Plant Systems 80/05/09 8pp

- 800.6230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D O Division of Licensing 80/05/20 13pp
- BOO6260057 Forwards "for Comment" edition of NUREG-0619 Comments should be forwarded by BOO707 W/o encl EISENHUT.D G Division of Licensing BO/06/09 2pp
- 8004040262 Correction to licensees' 800428 brief on disposition of alleged Deficiency 1 Certificate of Svc encl SILBERG, J E Metropolitan Edison Co SILBERG, J E Metcalf & Eddy RADER, R M Conner, Macre & Corber 80/05/20 5pp
- G Adjudicatory correspondence
- 8006060245 Request for extension until 800618 for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy & intervenors have other commitments made prior to Feb 1980 Certificate of Svc encl
 KEPFORD, C Citizens for Sefe Environment 80/05/20 App
- 8006060547 Response to Intervenors, York Committee for Bafe Environ & Citizens for Safe Environ request for extension until 800618 to file proposed findings of fact in generic radon proceeding Many delays in proceeding are cause for concern CONNER, T B Philadelphia Clectric Co TRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge CONNER, T B Public Service Electric & Qas Co of New Jersey 80/05/23 11pp
- BO04020550 Order granting extension until B00618 for York Committee for Safe Environ & Citizens for Safe Environ to file proposed findings of fact & conclusions of law NRC findings due on B00703 & intervenors' & applicants' responses on 800718 BIEHOP, C J Atomic Safety and Licensing Appeal Panel B0/05/28 200
- B006260209 Memorandum & order advising that Sterling issue is no longer germane to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 800702
 IISHQP,C J Atomic Safety and Licensing Appeal Panel 80/06/23
- H General correspondence
- BOO61200B7 Responds to ltr to DDE re constituent inquiry about relationship of Merrill Creek Project to facilities NRC has no info re relationship Facilities use water from DE River Dasin DERCKS, W.J. Office of the Executive Director for Operations BO/09/30 6pp
- G Inspection reports, IE Bulletins & correspondence
- 800b020475 Responds to IE Bulletin 80-02. "Inadequate GA for Nuclear Supplied Equipment " Dulistin is not applicable since GE has not purchased reactor feedwater spargers & thermal steeves for facility MARTIN.T J Public Service Electric & Gas Ca of New Jersey GOOGE J 1800
- 8006250223 Ack receipt of 800418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-354/80-01 & 50-355/80-01 & GARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/22 ip
- --8006250226 Responds to NRC 800314 ltr re violations noted in IE Insp Repts 50-354/80-01 & 50-355/80-01 Corrective actions. GC procedures will be revised to address amended GA manual, Section 4 MARTIN.T J Public Service Electric & Oas Co of New Jersey 80/04/18 2pp
- --B006250229 Forwards IE Insp Repts 50-354/80-01 & 50-355/80-01 on B00114-17 & notice of violation CARLSDIA T Region i. Philadelphia, Reactor Construction & Engineering Support Branch B0/03/14 2pp
- --B006250231 Notice of violation from insp on 800114-17
 * Region 1. Philadelphia, Office of the Director 80/03/11 1p
- --B004250233 IE Insp Repts 50-394/80-01 / 50-355/80-01 on B00114-17
 Noncompliance noted failure to take prompt corrective action
 re protection of equipment from weather & ring grooves left
 unprotected from Jamage in high activity area
 MCGAUGHY, R W , VARELA: A A , BATEMAN, W H Region 1, Philadelphia,
 Office of the Director B0/03/11 Spp

- S Reportable occurrences, LERs & related correspondence
- 8006300005 Ack receipt of 800502 final deficiency rept re weld wire documentation CARLSONR T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/04 ip
- 8006250407 Ack receipt of 800523 interim deficiency rept re primary containment relief valves CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 1P
- DOCKET 50-357 UNIV OF CALIFORNIA
- A Application/construction stage documents & correspondence
- B006180621 Notification of 800613 meeting w/BWR Licensing Resolution Group in Bethesda. MD to discuss progress MILSON.J N Licensing Branch 1 80/06/07 10pp
- DDCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8006020122 Notifies that time of B00604 meeting in Bethesda, MD w/ util to discuss steps taken to mitigate silting problem at facility intake structure has been changed PELTIER. I Licensing Branch 2 80/05/02 1g
- BOOA230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 80/05/20 13pp
- 8006230001 Summary of B00410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Btudy concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T M Containment Systems Branch B0/03/30 App
- 8006200575 Notifies of change in date & location of 800624 meeting wouth in Bethesda. MD re facility intake structure Meeting will be held on 800624 in Room 6110 of MD Nati Bank Bldg PELTIER: I Licensing Branch 2 80/06/02 ip
- B006250168 Notification of 800618 meeting w/util in Bethesda.MD to discuss UL review schedule PELTIER: I Licensing Branch 2 80/06/10 4pp
- BOO6170682 Submits result of audit re separation of electrical equipment & sys per NRC 791130 ltr Review showed one cable in violation of separation requirements, lying against fire wall Cable tied back
 BORGMANN, E.A. Cincinnati Gas & Electric Co. 80/06/11 2pp
- 8006300287 Requests advisement re submittal date for info requested in NRC 800421 itr re Category 1 masonry wall employed by plants under CP & OL review SCHMENCER.A Licensing Branch 2 80/06/12 3pp
- BOO6250321 Summary of 800514 meeting w/utils in Rethesda.HD re organization & objectives of BWR licensing resolution group Agenda & viewgraph entl WILEDN.J N Operating Reactors Branch 4 80/06/17 11pp
- F Security, medical, emergency & fire protection plans
- 8006020228 Notifies that new telephone sys called Health Physics Network (HPH) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/18
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addi specific criteria for facilities under development EISENHUT, D G Division of Operating Reactors 80/04/25 41pp

Q Adjudicatory correspondence

- 6305170355 Petition to participate in proceeding by political aubdivision of State of OH having greatest population concentration within 10 mile radius of plant Wigoard of County Commissioners resolution & Certificate of Svc CRESHELL, R., HEISENHAHN, J. Clermont County, OH. 80/05/12 5pp
- G006130021 Notice of appearance in proceeding Certificate of Svc encl CERNISON.A B . HERMAN T R ECKERSON M Zimmer Area Citizens — Zimmer Area Citizens of MY 80/05/15 4pp
- 8005050371 Brief in opposition to applicant 800508 notice of appeal which requested reversal of ASL8 800422 memorandum & order & denial of intervenors' petition Appeal premature & failed to establish good cause Certificate of Svc encl GENNISON. A B Zimmer Area Citizens Zimmer Area Citizens of KY 80/05/19 15po
- 8006160136 Answer to Clermont County, CH 800512 petition to participate as interested state in proceeding Urges imposition of same conditions imposed on City of Hentor & State of KY, if participation granted Certificate of Svc encl
 CONNER.T B . HETTERHAHN, H J . Cincinnati Gas & Electric Co
- UOOA020110 Motion for estension until 800616 for Zimmer Area Citizens to file comments SARTH.C A Hearing Branch 3 80/05/29 ip
- ~-BOO6020116 Ack receipt of Zimmer Area Citizens BOO515 contentions
 Motion seeking extension until BOO616 for intervenor to file
 contentions & MRC & applicant to file comments has been
 subatted to ASLB Certificate of Svc encl
 BARTH, C A Hearing Branch 3 BO/05/29 3pp
- 8005020123 Forwards 800315 contentions w/agreed changes Advises that NRC moved ASLB for extension until 800616 for Zimmer Area Citizens to file contentions CA Barth will initiate 800611 conference to discuss contentions M/o encl BARTH.C A Hearing Branch 3 80/05/29 ip
- 8005020307 Order granting extension until 800616 for Zimmer Area Citizens to file contentions & for NRC & applicants to file comments per ASLB 800422 memorandum & order, LBP-80-14 BECHOEFER. C Atomic Safety and Licensing Board Panel 80/05/29 Ip
- 8006020146 Repsonse in support of County of Clermont 800501 petition to participate in emergency preparedness & radiological aconitoring issue Recommends admission on same terms imposed on State of KY & City of Mentor Certificate of Svc encl BARTH.C A Hearing Branch 3 80/05/30 5pp
- 8006120353 Memorandum & order ALA8-595 re util 800508 appeal for denial of Zimmer Area Citizens & Zimmer Area Citizens of KY petition to intervene Appeal is denied w/o prejudice to renewal 818HQP.C J Atomic Safety and Licensing Appeal Panel 80/06/07
- 8006130272 Memorandum & order admitting Clermont County. DH as interested county in proceedings Participation is granted if county agrees not to relitigate issues on which hearing is complete
 BECHHORFER. C Atomic Safsty and Licensing Board Panel 80/06/11
 2pp
- 8006180297 Comments in lieu of response stating no objection to admission of Zimmer Area Citizens encl contentions remembers by radiological monitoring Reserves right to argue on merits & validity W/Certificate of Svc BARTH.C A Hearing Branch 3 80/06/16 13pp
- 8006190501 Response in opposition to Zimmer Area Citizens 800515 proposed contentions Intervenors failed to demonstrate good cause under policy stated in Commission decision overruling ALAB-990 Certificate of Svc encl CONNER.T B . METIERHAMILM J Cincinnati Gas & Electric Co CONNER.T B . Conner. Moore & Corber 80/06/16 11pp

H Ceneral correspondence

SOO6120126 Provides Subcommittee on Energy, Nuclear Proliferation & Federal Svcs w/facility status. In response to 800418 ltr re 8 Little John Concerns Facility const completion delayed due to several factors S Little John ltr enci DIRCKS.W J Office of the Executive Director for Operations.

- --8006120127 Forwards S Littlejohn itr concerning facility status OLENN, J Senate, Covernmental Affairs 80/04/18 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8006200109 Forwards IE lnsp Rept 50-358/80-07 on 800319-21 & notice of violation FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- --8006200111 Notice of violation from these on 800317-21 # Region 3. Chicago. Reactor Construction & Engineering Bupport Branch 80/04/15 1p
- --8006200113 IE Insp Rept 50-358/80-07 on 800319-21 Noncompliance noted two portable rod warmers not electrically plugged in & QA instructions deficient HUGHES, J. NESCOTT, M. M. KNDP, R.C. Region 3, Chicago, Office of the Director 80/04/15 11pp
- 8006170742 Forwards IE Insp Rept 50-358/80-11 on 800415-17 No noncompliance noted HEIBHMAN F F Region 3, Chicago, Reactor Operations Muclear Bupport Branch 80/05/06 2pp
- ~-8006170749 IE Insp Rept 50-358/80-11 on 800419-17 No noncompliance noted Major areas inspected fire protection prevention program BAKER,K R Region 3, Chicago, Reactor Operations Nuclear Bupport Branch FORNEY,W L , DRANCH,M W Region 3, Chicago, Office of the Director 80/05/05 3pp
- 8006230082 Forwards IE Insp Rept 50-358/80-08 on 800403-05,07,08,11. 14-18.21-24 & 30 & notice of violation HCISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/13 2pp
- ~-8006230087 Notice of violation from insp on 800403-05,07.08,11,14-18, 21-24 & 30 4 Region 3, Chicago, Office of the Director 80/05/09 2pp
- ~-8005230092 IE Insp Rept 90~358/80~08 on 000403~05,07,08,11,14~18,21~24 & 30 Noncompliance noted failure to notify NRC in 24~h of reportable deficiency & failure to follow storage requirements for new fuel TAMBLING.T; DANIELS.FT Region 3, Chicago, Office of the Director 80/05/09 Spp
- 8006120481 Responds to IE Bulletin 80-02 re presence of serious deficiencies in GA program of Marvin Engineering Co Vendor has not supplied any NSSS hardware to util BORGMANN,E A Cincinnati Gas & Electric Co 80/05/20 1p
- 8006240060 Ack receipt of 800805 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/79-36
 HEISHMAN F F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/06 lp
- ~~8006240064 Responds to NRC ltr re violations noted in IE Inap Rept 50-388/79-36 Corrective actions welded-in relief valves properly tagged & equipment will be obtained for verifying relief valve set pressures BORGMANN.E A Cincinnati Gas & Electric Co 90/05/05 2pp
- 8006240606 Advises that IE Bulletin 80~07 re cracking of jet pump holddown beams at Dresden 3 is being considered open item in license review of BWRs Response should be provided for encl request for info SCHWENCER.A Licensing Branch 2 80/06/06 4pp
- 8006260288 Ack receipt of 800328 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-338/80-07 FIGRELLI, G. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/12 ip
- ~-8006260293 Responds to NRC 800423 ltr re violations noted in IE Insp Rept 50-358/80-07 Corrective actions instructions sign advising welder to plug in portable rod warmers in work area posted in window BORGMANN,E A Cincinnati Oas & Electric Co 80/05/28 2pp.
- 8006300242 Responds to 1E Bulletin 80-08 Correct spring meth installed in mid-Jul 1980 Tests of several possibilities of undersized actuators being conducted BDROMANN, E. A. Cincinnati Gas & Electric Co. 80/06/12 ip.

- S Reportable occurrences. LERs & related correspondence
- 8006090478 Part 21 rept re misoperation of K-6008 circuit breaker at facility Possiblity of small number of K-6008 & K-DON6008 circuit breakers assembled w/ondersized secondary latch bushing during 1969-77 Results of tests oncl RHOADS, E W Gould-Brown Bovers 80/05/19 4pp
- 8004200024 Final Part 21 rept re mired heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities SEAY,J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006240084 Ack receipt of 800521 interim deficiency rept re Ruskin fire dampers FIGRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 1p
- BO06250366 Ack receipt of BO0523 interim deficiency rept re mishandled piping assemblies Will complete review of matter during future insp future insp FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/06/ii 1p
- 8006300563 Ack receipt of 800522 deficiency rept re control rod drive pumps Matter will be reviewed during future insp. FIDRELLI.O Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/06/18 ip
- DOCKET 50-341 SAN ONOFRE NUCLEAR STATION: UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures Ceneral operating reactor review procedure & acceptance criteria enci EISENHUT.D O Division of Licensing 80/05/20 13pp
- 8006020547 Responds to 800110 ltrs re environ radiological sampling program being conducted at facilities Disagrees w/Marine Review Committee allegations that program is inadequate Forwards detailed responses to Marine Raview Committee rept DENION, H R Office of Nuclear Reactor Regulation, Director 80/05/23 2pp
- ---8006020559 "Radiological Effluent Tech Specs for PWRs "
 * Commission NUREO-0472 80/02/01 80pp
- --8006020566 Informs NRC that CA Coastal Commission found program for monitoring radiological discharges from facilities to be grossly inadequate Requests that NRC work w/Bouthern CA Edison to correct deficiencies in monitoring program FISCHER.M L. California, State of 80/01/10 ip
- 8006110431 Forwards requests for add1 info for review of FSAR Approval of CENPD-178 re methods for determining fuel assembly loads has been suspended pending receipt of add1 info from C-E SCHWENCER.A Licensing Branch 3 80
- BOO4090037 Approves request for withholding util documents containing structural calculations (ref 10CFR2 790) Documents contain trade secrets & highly technical calculations that could be taken out of context or misinterpreted SCHMENCER. A Licensing Branch 2 80/05/28 2pp
- BOO4060395 Submits add1 info re Geosciences Branch Question 361 63 re seismic reflection profiles within 25 km of plant Applicants proceeding to collect add1 offshore geophysical data along tract lines Drawings available in Central Files DIETCH, R Southern California Edison Co 80/06/06 2pp
- 8006130301 Forwards responses to NRC Questions 361 63 & 361 64 to be incorporated in Amend 19 to FSAR Geophysical data referenced in Section 2 4 of response to Question 361 63 enc!

 BABKIN.K P Bouthern California Edison Co 80/06/11 220pp
- 8006250392 Forwards request for addl into for NRC review of FBAR. 8CHWENCER.A Licensing Branch 3 80/06/16 10pp

- 8006230319 Forwards addl piping design info requested by Mechanical Engineering Branch, in order to proceed w/confirmatory piping analysis BASKIN.K P Southern California Edison Co 80/06/18 dpp
- --8006230526 "Calculation Sheet Shutdown Cooling Line.Histogram "
 Sheet 1 of 2
 BHAH.P R Bechtel Corp 10079003 80/06/05 1p
- --B004230531 "Calculation Sheet Shutdown Cooling 1201-017 Histogram " Sheet 2 of 2 KOTKOFF, D N Bechtel Corp 10079003 B0/04/05 ip
- --8006230538 "Mechanical Penetration.Type 1.Number 9 " Sheet 1 of 1 * Ametei.Inc 80/06/05 ip
- --8004230543 "Piping Assembly." Revision 4
 * Combustion Engineering, Inc 77/01/03 1p
- ---8006230547 "Nozzle Details," Revision 5 * Combustion Engineering, Inc. 76/01/12 lp
- --8004230554 "Certification of Design Spec DB-1201, RCS Piping Components For San Onofre Nuclear Generating Station, Units 2 & 3 " KINNSCH, D L Bechtel Corp 80/01/31 375pp
- --8006230558 Package of drawings re pipe support assembly * Bechtel Corp 10079 80/06/18 100pp
- 8006250214 Forwards geophysical drawings & data of area offshore from site, per 800604 commitment Sixty-nine seismic & sub-hottom profiles encl.available in hard copy only DIETCH:R Bouthern California Edison Co 80/06/20 70pp
- --8004250216 "Shot Point Base Map " WILLIAMS: O Nekton: Inc 80/06/19 1p
- --8006250218 "Shot Point Base Map " Williams, G. Nakton, Inc. 80/06/19 ip
- BOD6240440 Responds to NRC BO0421 request for info re use of concrete mesonry walls in any seismic Category 1 plant structure No concrete mesonry walls exist in any facility seismic Category 1 plant structure BASKIN.K P Southern California Edison Co. 80/06/24 1p
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EIBENHUT.D G Division of Operating Reactors 80/04/25 dipp
- 8006020340 Advises that add1 90 days is required to respond to comments in NRC 800425 ltr re util 790923 guard training & qualification plan Add1 time required to establish physical exercise program Response will be submitted by 800901 BASKIN,K P Southern California Edison Co 80/05/23. 1p
- 9 Adjudicatory correspondence
- BOO6iiOOl4 Forwards applicants' motion for summary disposition of intervenor Friends of the Earth et al Contentions is & 9 re dewatering wells & U fuel costs FIGOIT, D R Chickering & Oregory 80/06/06 ip
- ---8006110017 Hotion for summary disposition of intervenor Friends of the Earth et al Contention is re dewatering wells & Contention 9 re U fuel costs, admitted in proceeding by ABLE 780127 memorandum & order Proposed order encl.
 PIGGIT, D.R. Bouthern California Edison Co. PIGGIT, D.R. Ban Disgo Cas & Electric Co. PIGGIT, D.R. Chickering & Gregory 80/06/06 5pp
- --8006110024 Brief in lisu of pleading in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention ia rs dewatering mells & Contention 9 re U fuel costs List of project refs supporting motion enel PIGOTT.D R Southern California Edison Co PIGOTT.D R. Ban Diego Cas & Electric Co PIGOTT.D R Chickering & Gregory 80/06/06 35pp

- --8004110028 Statement of mat1 racts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et al Contention ia on dewatoring wells Analysis indicates that const cavities have no adverse effect on structures PIODIT.D R Southern California Edison Co PIODIT.D R San Diego Gas & Electric Co PIODIT.D R Chickering & Gregory 80/06/06 5pp
- --8004110031 Statement of matl facts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et al Contention ? on U fuel costs Applicants' projection of fuel costs includes escalation or U prices
 PIGOTY.D R Southern California Edison Co PIGOTY.D R San Diego
 Gas & Electric Co PIGOTY.D R Chickering & Gregory 80/06/06
 5pp
- --B006110035 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention ia re dewatering wells Calculated component stress within allowable limits W/supporting documentation HERSH. L. Bechtel Power Corp. (subs. of Bechtel Corp.) 80/06/03 440p
- --8006110039 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention ia re dewatering wells Subsurface cavities will have no detrimental effect on seismic structures
 BARNEICH.J.A. Hoodward-Clyde Consultants. Inc. 80/06/03 20pp
- --8006110041 "Rept on Results of Analyses Performed on Well B at 80NOS Units 2 & 3.8an Onofre.CA" BARNEICH.J A Woodward-Clyde Consultants. Inc 78/08/25 84pp
- ---8006i10046 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention la re dewatering wells Cavities will have no adverse effect on structure Wisupporting documentation MCNEILL,R L Sandia Laboratories 80/06/04 34pp
- --B006ii0047 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention ia re dewatering wells Supporting documentation encl
 BMITH, J. Affiliation Unknown 80/06/02 14pp
- ---9006110052 Affidavit in support of applicants' motion for summary disposition of intervenor friends of the Earth et al Contention la re dowatering wells Subsurface cavities will have no adverse effect on structures

 BASKIN.K P American Nuclear Society 80/06/05 7pp
- --BOO6110055 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention 9 re U fuel costs U cost component in costratentian and the supporting documents BRIDENBECKER.R Southern California Edison Co. 80/06/05 10pp
- --B006110059 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et all Contention 9 re U fool costs Util has adequately accounted for U price escalation Certificate of Svc encl JAYES S M Stoller Corp (subs of Arthur D Little, Inc.) 80/06/02 13pp
- BOOS11009B Motion for order establishing BOO715 prehearing conference PIGOTT.D R Southern California Edison Co PIGOTT.D R San Diego Gas & Electric Co PIGOTT.D R Chickering 5 Gregory BO/06/05 2pp
- --8005110107 Brief in lieu of pleading in support of motion for order establishing 800715 prehaaring conference Failure to license facility at const completion date would result in unwarranted add Looste Mydraft order & Certificate of Svc PIGOTT, D R Southern California Edison Co PIGOTT, D R Ban Diego Oas & Clectric Co PIGOTT, D R Chickering & Gregory 80/06/05 12pp
- 8006300342 Forwards 800616 "Further Commission Guidance for Power Reactor DLs, Statement of Policy " GHANDLER.L J Hearing Branch 1 80/06/23 1p
- 8006260197 Notice & order for 800717 prehearing conference in US
 District Court, San Diego, CA, re further identification of
 issues & actions Recommendations may be served by 800707
 Public invited w/o opportunity for participation
 SMITH, I W Atomic Safety and Licensing Board Panel 80/06/24 1p

I Financial information

- 8006190522 Forwards responses to Questions 1 through 9 re financial analysis contained in NRC 791221 ltr.financial statements & Annual Financial Repts 1979 for Cities of Anaheim & Riverside.CA
 8ASKIN.K P Southern California Edison Co 80/06/16 183ps
- --8006190525 Annual Financial Rept for yr ending 790630 FERRONE, 9 Anaheim, CA 79/11/16 69pp
- --8006190532 Annual Financial Rept for yr ending 800630 for Public Utils Dept HOYT, G W Anaheim, CA 79/11/16 27pp
- --8006190538 Annual Financial Rept for yi ending 790630 BREWER, H E Riverside, CA 79/11/20 74pp

P Operating license stage documents & correspondence

- 8006110011 Requests notification of Aug 1980 issuance of SER is not achievable Fuel loading for San Onofre scheduled for 810415 DIETCH.R Southern California Edison Co 80/05/30 2pp
- O Inspection reports. IE Bulletins & correspondence
- 800&050405 Forwards 1E Insp Rept 50-361/80-07 on 800415-17 No noncompliance noted CREMS, J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/07 2pp
- ---B0060504i1 IE Insp Rept 50-36i/B0-07 on 8004i5-17 No noncompliance noted Major areas inspected preoperational test program & procedures FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch JOHNSON, A D . CARLSON, J D Region 5, San Francisco, Office of the Director 80/05/05 4pp
- S Reportable occurrences, LERs & related correspondence
- B006060337 Forwards final deficiency rept re lack of measuring & test equipment recalibr PAPAY.L T Southern California Edison Cu 80/05/21 ip
- --9006060340 Final deficiency rept re measuring & test equipment recalibr Records of equipment performance not maintained & did not transmit to Bechtel performance data reflecting condition of equipment calibr at receipt Procedures revised * Southern California Edison Co 80/05/21 2pp
- 800&0&0359 Forwards final deficiency rept re safety-related lines in proximity to nonseismic Category 1 tanks
 PAPAY,L T Southern California Edison Co 80/05/27 ip
- --8004060360 Final deficiency rept re inadequate design considerations for safety-related lines in proximity to Category I tank at plant Design change package issued defining necessary physical changes Review confirms limit of deficiency * Southern California Edison Co 80/05/29 2pp
- B006180099 Comments on AO rept to Congress for first quarter CY80 Suggests change of wording re saltwater cooling sys gumps MICHELSON, C Director's Office 80/06/04 1p
- 8006200024 Final Part 21 rept re mixed "Lat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement investigations conducted & closed at 46 listed facilities SEAY.J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8005190440 Forwards amend to 791212 final deficiency rept re lack of qualification testing documentation for repaired GE power cable PAPAY, L T Southern California Edison Co 80/06/11 ip
- --8006190444 Amend to 791212 final deficiency rept re lack of qualification testing documentation for repaired power cable GE cable will be replaced New cable will undergo LOCA qualification testing Testing to be completed by Dec 1980 * Southern California Edison Co 80/06/11 3pp

T Hearing transcripts on non-antitrust matters

- 8006110455 Forwards transcript of 800520 meeting w/util,NRC & intervenor AS Carstens in Bethesda,MD re need to obtain addl offshore seismic profiles in vicinity of site RODDH Licensing Branch 3 80/05/28 3pp
- --8006110458 Transcript of 800520 meeting w/util.NRC & intervenor AS Carstens in Bethesda.MD re need to obtain addl offshore seismic profiles in vicinity of site Pp 1-16

 Assistant Director for Environmental Technology 80/05/20
 17a
- 8006070541 Summary of 800521 meeting w/util & consultant,USQS, in Bethesdar ND re need for addl offshore exploration in vicinity of site Meeting transcript encl
 ROOD; H Licensing Blanch 3 80/05/29 3pp
- --8006090544 Transcript of 800521 meeting w/util & consultant.US9S.
 In Bethesda.MD re need for addl offshore seismic profiles
 near site Pp 1-82

 * Division of Licensing 80/05/21 83pp
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR \$ PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- 8006020547 Responds to 800110 ltrs re environ radiological sampling program being conducted at facilities Disagrees w/Marine Review Committee allegations that program is inadequate Forwards dotailed responses to Marine Review Committee rept DENTON. H R Office of Nuclear Reactor Regulation. Director 80/05/23 2pp
- ~~8004020554 "Detailed Responses to Marine Review Committee Rept "
 * Radiological Assessment Branch 80/05/23 13pp
- --8006020559 "Radiological Effluent Tech Specs for PWRs "
 * Commission NUREG-0472 80/02/01 80pp
- --B006020566 Informs NRC that CA Coastal Commission found program for monitoring radiological discharges from facilities to be grossly inadequate Requests that NRC work w/Bouthern CA Edison to correct deficiencies in monitoring program FISCHER: M L California. State of 80/01/10 ip
- 8006110431 Forwards requests for add1 info for review of FSAR Approval of CEMPD-178 re methods for determining fuel assembly loads has been suspended pending receipt of add1 info from C~E SCHWENCER.A Licensing Branch 3 80/05/23 12pp
- 8006090037 Approves request for withholding util documents containing structural calculations (ref 10CFR2 790) Documents contain trade secrets & highly technical calculations that could be taken out of context or misinterpreted SCHWENCER. A Licensing Branch 2 80/05/28 2pp
- B00&040395 Submits add1 info re Geosciences Branch Guestion 361 63 re seismic reflection profiles within 25 km of plant Applicants proceeding to collect add1 offshore geophysical data along track lines Drawings available in Central Files DIETCM.R Southern California Edison Co 80/06/06 2pp
- 8006130301 Forwards responses to NRC Questions 361 63 & 361 64 to be incorporated in Amend 19 to FEAR Geophysical data references in Section 2 4 of response to Question 361 63 enc!

 BASKIN. K P Southern California Edison Co 80/06/11 220pp
- 8G04250392 Forwards request for add1 info for NRC review of FSAR SCHWENCER.A Licensing Branch 3 60/06/16 10pp,
- HOO623D519 Forwards addit piping design info requested by Mechanical Engineering Branch.in order to proceed w/confirmatory piping analysis
 BABKIN.K P. Southern California Edison Co. 80/06/18 6pp
- --8006230524 "Calculation Sheet Shutdown Cooling Line.Histogram " Sheet 1 of 2 SHAH.P R Bechtel Corp 10079003 80/06/05 1p

- --8006230531 "Calculation Sheet Shutdown Conling 1201-017 Histogram " Sheet 2 of 2 KGTKOTF.D N Bechtel Corp 10079003 B0/04/09 1p
- --8005230538 "Mschanical Penetration.Type 1.Number 9 " Sheet 1 of 1 * Ametek.Inc 80/06/05 ip
- --8006230547 "Nozzle Details." Revision 5
 * Combustion Engineering, Inc. 76/01/12 ip
- --B006230554 "Certification of Design Spec DS-1201.RCB Piping Components For San Onofre Nuclear Congrating Station, Units 2 % 3 " KINNSCH, D i. Bechtel Corp. 80/01/31 375pp
- --8006230558 Package of drawings re pipe support assembly
 * Bechtel Corp 10079 80/06/18 100pp
- 8006280214 Forwards geophysical drawings & data of area offshore from site.per 800604 commitment Sixty-nine seismic & sub-bottom profiles enti-available in hard copy only DIETCH.R Southern California Edison Co 80/06/20 70pp
- --8006250216 "Shot Point Base Map " WILLIAMS, G Nekton, Inc 80/06/19 ip
- --8006250218 "Shot Point Base Map " WILLIAMS: 0 Nekton: Inc 80/06/17 1p
- BOO6240440 Responds to NRC BOO421 request for info re use of concrete masonry walls in any seismic Category 1 plant structure No concrete masonry walls exist in any facility seismic Category 1 plant structure
 BASKIN.K P Southern California Edison Co 80/06/24 lp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISEMHUT. D 0 Division of Operating Reactors 80/04/25 6ipp
- BOO6020340 Advises that add1 90 days is required to respond to comments in NRC BO0425 ltr re util 790923 guard training & qualification plan Add1 time required to establish physical exercise program Response will be submitted by BO0901 BASKIN.K P Southern California Edison Co 80/05/23 ip
- G Adjudicatory correspondence
- 8006110014 Forwards applicants' motion for summary disposition of intervenor Friends of the Earth et al Contentions 1a & 9 re dewatering wells & U fuel costs PIGOTT,D R Chickering & Gregory 80/06/06 ip
- --800A110019 Motion for summary disposition of intervenor Friends of the Earth et al Contention la re dewatering wells & Contention 9 re U fuel costs; admitted in proceeding by ASLB 780127 memorandum & order Proposed order encl PIGOTT, D R Southern California Edison Co PIGOTT, D R Ban Diego Qas & Electric Co PIGOTT, D R Chickering & Gregory 80/06/06
- ~-8006110024 Brief in liew of pleading in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention is re dewatering wells & Contention 9 re U fuel costs List of project refs supporting motion encl PIGOTT. D R Southern California Edison Co PIGOTT. D R San Diego Qus & Electric Co PIGOTT. D R Chickering & Gregory 80/06/06 95pp
- --8006110028 Statement of matl facts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et all Contention Is on dewatering wells Analysis indicates that comst cavities have no adverse effect on structures PIGOIT, D.R. Southern California Edison Co. PIGOIT, D.R. San Diego Gas & Electric Co. PIGOIT, D.R. Chickering & Gregory 80/06/06 Spp
- --B006110031 Statement of matl facts as to which no genuine issue exists to be heard re intervenor Friends of the Earth et al Contention ? on U fuel costs Applicants' projection of fuel costs includes escalation of U prices
 PIGCIT.D R Southern California Edison Co PIGOIT.D R San Diego
 Das & Electric Co PIGOIT.D R Chickering & Gregory 80/06/06
 Spp

- --B006i10035 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al. Contention 1a re dewatering wells Calculated component stress within allowable limits W/supporting documentation HERSH.L. Bechtel Power Corp. (subs. of Bechtel Corp.) 80/06/03 44ap.
- --B006110039 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention ia re devatering wells Subsurface cavities will have no detrimental effect on seismic structures
 BARNEICH.J A Woodward-Clyde Consultants. Inc 80/06/03 20pp
- --8006110041 "Rept on Results of Analyses Performed on Well 8 at SONGS Units 2 & 3.5an Onofre.CA " BARNEICH.J A Woodward-Clyde Consultants, Inc 78/08/25 84pp
- ---8006110046 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention la re dewatering wells Cavities will have no adverse effect on structure Wisupporting documentation MONEILL, R. L. Bandia Laboratories 80/06/04 34pp
- --B006i10047 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention la re dewatering wells Supporting documentation encl
 BNITH-J L Affiliation Unknown B0/06/02 1400
- ---8006110052 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention (a re dewatering wells Subsurface cavities will have no adverse effect on structures
 BASKIN.K P American Nuclear Society 80/06/05 7pp
- ---BOO6i10055 Affidavit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention 9 re V fuel costs U cost component in cost-benefit analysis relatively small W/supporting documents BRIDENBECKER, R Southern California Edison Co 80/06/05 10pp
- ~~800&1100\$9 Affidevit in support of applicants' motion for summary disposition of intervenor Friends of the Earth et al Contention 9 re U fuel costs Util has adequately accounted for U price escalation Certificate of Svc encl JAYE. 5 S M Stoller Corp (subs of Arthur D Little, Inc.) BO/06/02 13pp
- 8006110098 Motion for order establishing 800715 prehearing conference PIGOTT.D.R Southern California Edison Co. PIGOTT.D.R. San Diego Gas & Electric Co. PIGOTT.D.R. Chickering & Gregory 80/06/06 2pp
- ~*B006:10107 Brief in lieu of pleading in support of motion for order establishing B007:5 prehearing conference Failure to license facility at const completion date would result in unwarranted add1 costs W/Graff order & Certificate of Svc FIGOTT.D R Southern California Edison Co PIOUTT.D R San Diego Oas & Electric Co PIOUTT.D R Chickering & Gregory B0/06/06 12pp
- 9006300342 Forwards 900616 "Further Commission Guidance for Power Reactor OLs. Statement of Policy " CHANDLER, L. J. Hearing Branch 1 BO/06/23 1p
- 8006260197 Notice & order for 800717 prehearing conference in US District Court, San Diego, CA, re further identification of issues & actions Recommendations may be served by 800707. Public invited w/o opportunity for participation SNITH, I W Atomic Safety and Licensing Board Panel 80/06/24 ip

I Financial information

- 8006190522 Forwards responses to Questions 1 through 9 re financial analysis contained in NRC 791221 ltr.financial statements & Annual Financial Repts 1979 for Cities of Anaheim & Riverside CA
 BASKIN, K.P. Southern California Edison Co. 80/06/16 183pp
- --8006190525 Annual Financial Rept for yr ending 790630 FERRONE: G Anaheim: CA 79/11/16 69pp
- --8006190532 Annual Financial Rept for yr ending 800630 for Public Utils Pept HDYT.O W Anaheim CA 79/11/14 27pp.
- --8006190538 Annual Financial Rept for gr ending 770630 BREWER, R. E. Riverside, CA 79/11/20 74pp

- S Reportable occurrences. LERs & related correspondence
- B006060337 Forwards final deficiency rept re lack of measuring & test equipment recalibr PAPAY.L T Southern California Edison Co 80/05/21 1p
- --8006060340 Final deficiency rept re measuring & test equipment recalibr Records of equipment performance not maintained & did not transmit to Bechtel performance data reflecting condition of equipment calibi at receipt Procedures revised * Southern California Edison Co 80/05/21 2pp
- 8006040359 Forwards final deficiency rept re safety-related lines in proximity to nonseismic Category 1 tanks
 PAPAYL T Southern California Edison Co 80/05/29 ip
- --8005060360 Final deficiency tept to inadequate design considerations for safety-related lines in proximity to Category 1 tank at plant Design change package issued defining necessary physical changes Review confirms limit of deficiency * Southern California Edison Co 80/05/29 2pp
- 8006180099 Comments on AO rept to Congress for first quarter CYBO Suggests change of wording re saltwater cooling sys pumps MICHELSON, C Director's Office 80/06/04 1p
- 8006200024 Final Part 21 rapt re mixed heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A234MPB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY.J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006190440 Forwards amend to 791212 final deficiency rept re lack of qualification testing documentation for repaired GE power cable PAPAY.L T Southern California Edison Co 80/06/11 1p
- --B006190444 Amend to 791212 final deficiency rept to lack of qualification testing documentation for repaired power cable of cable will be replaced New cable will undergo LOCA qualification testing Testing to be completed by Dec 1980 * Bouthern California Edison Co 80/06/11 3pp
- T Hearing transcripts on non-antitrust matters
- 8006110455 Forwards transcript of 800520 meeting w/util.NRC & intervenor AS Carstens in Bethesda,MD re need to obtain add1 offshore seismic profiles in vicinity of site ROGD,H Licensing Branch 3 80/05/28 3pp
- ---B006110459 Transcript of 800520 meeting w/util.NRC & intervenor AS Carstens in Bethesda.ND re need to obtain addl offshore weismic profiles in vicinity of site Pp 1-16

 * Assistant Director for Environmental Technology 80/05/20
 17pp
- 8006090541 Summary of 800521 meeting w/util & consultant,U908, in Bethesda,MD re heed for addl offshore exploration in victnity of site Meeting transcript encl ROOD,H Licensing Branch 3 80/05/29 3pp
- --8006090544 Transcript of 800521 meeting w/util & consultant.U908. in Bethesda:MD re need for addl offshore seismic profiles near site Pp 1-82 * Division of Licensing 80/05/21 83pp
- DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- @ Inspection reports, IE Bulletins & correspondence
- 8006200033 Forwards IE Circular 80-13, "Orad Strap Damage in Wastinghouse Fuel Assemblies " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 ip

- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D © Division of Licensing 80/05/20 13pp
- BOOGOOG4 Requests branches complete review of Q-list,FBAR Section 3 2.by 800620 SCHMENGER A Licensing Branch 2 80/05/21 ip
- 8006030312 Responds to NRC 800408 ltr requesting add1 info re auxiliary feedwater sys Clarification of util 791120 response to recommendation 95-6 encl CLAYTON.F L Alabama Power Co 80/05/27 23pp
- 8004030272 Forwards modified startup physics test program, confirming nuclear design & correct core fuel loading, validating analytical model, providing instrumentation calibr date & demonstrating abnormal core condition sensitivity CLAYTON, F. L. Alabama Power Co. 80/05/28 12pp
- 8004030370 Forwards add1 info requested by Hydraulic Engineering Branch re Executive Order 11788 questions on floodplain mgt Oversize drawings encl CLAYTON.F.L. Alabame Power Co 80/05/28 8pp
- BOO6110260 Forwards response to 800519 request for info re util responses to radiological questions concerning FBAR, Min quantities of respiratory protection devices added to FBAR Tables 12 3-1 \$ 12 3-2 CLAYTON.F L Alabama Power Co 80/06/03 4pp
- B006110017 Forwards addit info re seismic qualification of safetyrelated non-NBSS electrical & mechanical equipment in response to NRC 800523 request, CLAYTOWNF L. Alabama Power Co. B0/06/05 57pp
- --8006110022 "Final Seismic Response Spectra Joseph M Farley Nuclear Units 1 & 2.AL Power Co.Containment & Internal Structure " * Bechtel Corp 72/12/31 325pp
- --B00619027 "Seismic Response Spectra, Joseph & Farley Nuclear Plant, Units 1 & 2, AL Power Co. Auxiliary Bldg " * Sechtel Corp 72/08/31 75pp
- B006i904i0 Forwards info documenting control room human factors & operations review Personnel will be available to accompany NRC representatives during review scheduled for B006i6-20 CLAYTON.F L Alabama Power Co B0/06/i0 12pp
- BOO6180415 Forwards util response to NRC position re control rod guide tube support pins Although not required, util will replace existing guide tube support pins mfg w/2.000 F solution heat treatment temp CLAYTON,F L. Alabama Power Co. 80/06/11 3pp
- 8006250343 Notification of 800624 meeting w/util in Bethesda. MD to discuss applicant plan for managing plant operation & to review GL application Agenda encl KINTER. L. Licensing Branch 2 80/06/13 4pp
- B006240414 Forwards add1 info re util review of special low power testing program in response to NRC request To achieve better operator training. Test 1 should be performed prior to full power liceusing of facility CLAYTON.F.L. Alabama Power Co. B0/06/17 Opp
- 8006240334 Advises that ATMS emergency operating procedure has been developed in accordance w/guidelines set forth in NRC 800613 ltr Procedure is available for NRC insp at facility CLAYTON:F L Alabama Power Co 80/06/20 Ip
- F Security, medical, emergency & fire protection plans
- BO05130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT, D 0 Division of Operating Reactors B0/04/25 6ipp.
- 8006120528 Requests that FEMA review of state \$ local emergency plan be provided consistent w/encl schedule to evoid potential deleys in licensing decisions AHEARNE.J F Commission 80/05/13 2pp

- 8006030305 Ack receipt of 800505 itr requesting walkdown of 10% of Class IE equipment cables & associated circuits More complete Jan 1980 walkdown will be summarized in fire protection program re-evaluation CLAYTON, F. L. Alabama Power Co. 80/05/27 2pp
- J Insurance & indemnity information
- 8006250142 Forwards signed copy of Amend & to Indemnity Agreement B-81 CLAYTON F L Alabama Power Co 80/03/27 2pp
- P Operating license stage documents & correspondence
- 8006190163 Notification of 800616-20 meeting w/util in Dothan AL, to discuss human factors having impact on operator effectiveness
 KINTNER L Licensing Branch 2 80/06/05 4pp
- B006230130 Notification of B00624 meeting w/util to discuss outstanding issues re licensing review & plans for staffing & managing operation KiNTER.L L Licensing Branch 2 B0/06/10 2pp
- 8006240176 Forwards response to TMI-2 action plan Info addresses fuel loading, low power testing license requirements & fuel-power license requirements CLAYTON.F L Alabama Power Co 80/06/20 117pp
- G Inspection reports. IE Bulletins & correspondence
- 8006050431 Forwards IE Insp Rept 50-364/B0-06 on 80040B-11.No noncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/23 2pp
- --B006050434 IE Insp Rept 50-364/B0-06 on B0040B-i1. No noncompliance noted Major areas inspected thermal expansion & vibration testing of piping sys & piping sysphorts & restraints UPRIOHT C M Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch WHITENER, H. L. CHABE, J W Region 2. Atlanta, Office of the Director B0/04/25 Spp
- 8006060448 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pips Support Loads" soci Q'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006060525 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/80-07 & 50-364/80-04 LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/05/08 2pp
- --8004040931 Responds to NRC 800410 ltm re violations noted in IE Insp. Repts 50-348/80-07 & 50-344/80-04 Corrective actions cleaning stainless steel pipes w/Scotch-brite pads was stopped Cleaning pads returned to warehouse CLAYTON.FL Alabama Power Co. 80/04/28 2pp
- --8004060534 Forwards IE Insp Repts 50-348/80-07 & 50-364/80-04 on 800204-29 & notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch 80/04/10 3pp
- --8004060542 Notice of violation from inep on 800204-29

 * Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/04/02 ip.
- --8006060550 IE Insp Repts 50-348/80-07 & 50-364/80-04 on 800204-29.
 Noncompliance noted unauthorized use of Scotch-brite pada
 for final cleaning of stainless steel pipe surfaces &
 failure to perform work w/approved procedure
 MARTIN.R.D Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch 80/04/02 App
- B006200076 Forwards IE Insp Repts 50~348/80-09 & 50~364/80-09 on 800421-25. No noncompliance noted.
 STOHR.JP Region 2. Atlanta. Fuel Facility & Materials Sefety Branch 80/05/08 2pp
- --B006200074 iE Insp Repts 50-348/B0-09 & 50-364/B0-09 on B00421-25 No noncompliance noted Major areas inspected redwaste mpt, preoperational test procedures, chemistry & health physics procedures & security training BTOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch. TROUP, 9 L, WRAY, J R Region 2, Atlanta, Office of the Director B0/05/08 5pp

- 8006050309 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09 20p
- 8006300074 Forwards IE Circular 80-ii. "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/13 20p
- 8006030066 Ack receipt of IEflasp Rept 50-364/80-08 on 800409-11 No progrietary info CLAYTON: F L Alabama Power Co 80/05/14 ip
- --8006030u68 Forwards IE Insp Rept 50-364/80-08 on 800409-11 No nancompliance noted MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --8006030073 IE Insp Rept 50-364/80-08 on 800409-11 No noncompliance noted Major areas inspected pipe support baseplate designs, per IE Bulletin 79-02 bearsnic analysis for as-built safety-related piping per IE Bulletin 79-14 ANO.W P Region 2. Atlanta. Office of the Director HERDY.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/23 3pp
- 8006300272 Forwards IE Insp Rept 50-364/80-10 on 800428-0501 No noncompliance noted LEHIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/19 2pp
- --800630027B JE Insp Rept 50-364/80-10 on B0042B-0501 No noncompliance noted Major areas inspected safety-related piping support & restraint sys WHITEMER.H L . MODN.B T Region 2. Atlanta, Office of the Director URIOHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/03/19 4pp
- 8006250015 Forwards response to IE Bulletin 80-03 re vacuum conditions in chemical 5 vol control sys holdup tanks Vol control tank receives letdown from RCS & provides suction for charging back into RCS CEAYTON.F.L. Alabama Power Co. 80/06/04. 3pp
- 8006230192 Responds to IE Bulletin 80-12. "Decay Heat Removel Sys Operability " Redundancy may be provided by having two RHR trains operable Diversity may be provided in Modes 2-5 by having operable steam generators CLAYTON,F L. Alabams Power CO 80/06/09 4pp
- 8006300159 Ack receipt of IE Insp Rapt 50-364/80-12 No proprietary info CLAYTON:F L Alabama Power Co 80/06/12 1p
- --8008300184 Forwards IE Insp Rept 50-384/80-12 on 800506-09 No noncompliance noted MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/22 2pp
- --8006300176 IE Insp Rept 50-364/BO-12 on 800506-08 No noncompliance noted Major areas inspected IE bulletins & circulars, electrical cable records & inspector followup HUNT.# D Region 2. Atlanta, Office of the Director RAUSCH, J X Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/22 Spp
- BOOA300572 Responds to IE Bulletin 80-0A Safety-related components at schematic level have been reviewed to determine whether equipment remains in emergency mode fallowing reset of signals CLAYTON, F. L. Alabama Power Co. 80/06/12 3pp
- 8 Reportable occurrences, LERs & related correspondence
 - 1024 Final Part 21 rept re mixed heat of steel supplied by US from which 4-inch elbows & 2-inch tees were mfg to 18 requirement investigations conducted & closed at

- DOCKET 50-346 EDWIN : HATCH NUCLEAR PLANT, UNIT 2
 F Security, modical, emergency & fire protection plans
- BOO6090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 % App R to 100FR30 & is expected to be published in FR by end of May EISENH97.D G Division of Liconsing 80/05/19 46pp
- 8006130063 Forwards revised Pages 1-14 & new Page 14a for proposed vule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800519 ltr Page 14a not encl EISENHUT, D & Division of Licensing 80/05/22 73pp
- 8006030241 Forwards revised guard training & qualification plan Plan withheld (ref 10CFR2 790) WIDNER, W.A. Georgia Power Co. 80/05/28 ip
- 8006240592 Requests review of emergency plan against evaluation criteria of NUREG-0654 Addl info required before Emergency Preparedness Review Team can conclude that program is acceptable Revised plan should be provided by 800718 REID.R W Operating Reactors Branch 4 80/06/06 2pp
- I Financial information
- 8006170310 Forwards Annual Financial Repts 1979 NIDNER, W A Georgia Power Co 60/06/11 1p
- ---8006170314 Annual Financial Rept 1979 * The Southern Co 80/03/10 43p
- --8006170318 Annual Financial Rept 1979 * Penisia Power Co 80/02/28 38pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TML-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D G Division of Licensing 80/05/07 150pp
- BOO4030514 Summary of B00422-23 meeting w/Mark I owners group in San Jose. CA re confirmatory analysis? testing programs concerning Mark I containment long-term program ORIMES. C I Assistant Director for Plant Systems 80/05/09 8pp
- 8006130122 Requests comments on NUREG-0577, "Potential for Low Fracture Toughness & Lampllar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl
 EISENHUT, D O Division of Licensing 80/05/17 72pp
- 8006060376 Advises that response to 0E generic analysis re effect of dc power supply failure on ECCS performance will be provided by 800405 per NRC 800425 request WIDNER, N A Georgia Power Co 80/09/30 Ip
- 8006110288 Application to amend License NPF-5, submitted as proposed change to Tech Specs to exempt HPCI sys from Section 3 0 4 in order to permit one time test of turbine generator set for seven days
 WIDMERLW A Georgia Power Co 80/06/02 2pp
- ---8006110271 Proposed changes to exempt HPCI sys from requirements of Tech Specs Section 3 O 4 in order to permit one time test of generator set for seven days * deorgia Power Co = 60/04/02 | 3pp
- 8006110237 Forwards unique analysis rept comparing effects of ac power failure of ECCS performance w/GE generic analysis WIDNER, W.A. Georgia Power Co. 80/06/03 App
- 8006240121 Confirms oral authorization of 800602 teleon to temporarily amend Fech Specs Amend revises HPCI section to permit startup w/inoperable HPCI for special test Formal amend forthcoming Revised Tech Specs encl NDVAK.T M Assistant Director for Operating Reactors 80/06/03 200
- --8006240149 Revised Tech Spec Pages 3/4 5-1 & 3/4 5-1a for HPCI Amend issued orally by BQ0602 telcon.permitting startup w/ inoperable HPCI for special test

 4 Assistant Director for Operating Reactors 80/06/03 2pp

- 8006110053 Submits info re inservice testing of standby liquid control pumps Plant has been using flow measurements due to delta P measurement problems Instrumentation is not installed on sys to measure flow Procedure 100156d WIDNER, W A Georgia Power Co 80/06/04 2pp
- 8006300604 Lti to all BWR licensees forwarding "For Comment" edition of NUREG-0617, "BWR Feedwater Noizle & Control Rod Drive Return Line Noizle Cracking " Comments will be evaluated by NRC prior to final implementation W Division of Licensing
- 8006170640 Submits info re turbine rotor disc cracking in response to NRC 800513 request Unit 1 has experienced approx 81 turbine trips & approx five overspeeds Unit 2 has experienced approx 52 turbine trips & approx two overspeeds WIBNER.W A Georgia Power Co 80/06/10 4pp
- 8006300221 Forwards draft NRC licensing position, "Safety Considerations for Temporary Onsite Storage," used in evaluating low level waste storage criteria Requests reviews for onsite storage additions in monthly operating repts REID, R W Operating Reactors Branch 4 80/06/12 10pp
- @ Inapection reports, IE Bulletins & correspondence
- 8006200095 Forwards IE Circular 80-08, "BUR Tech Spec Inconsistency -Reactor Protection Sys Response Time " No written response required O'REJLLY, J.P. Region 2, Atlanta, Office of the Director 80/04/18
- 8006170767 Forwards IE Insp Repts 50-321/80-12 & 50-366/80-12 on 600310-19 & notice of violation STDMR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/22 2pp
- --8006170772 Notice of violation from insp on 800310-19 # Region 2, Atlanta, Office of the Director 80/0 80/04/22
- --8006170775 IE Insp Repts 50-321/80-12 & 50-366/80-12 on 800310-19 Noncompliance noted failure to start environ monitoring when required O R Region 2. Atlanta, Fuel Facility & Materials Safety CUNNINGHAM.A L , MACARTHUR.T C Region 2. Atlanta, Office irector 80/04/22 9pp JENKINS, G R the Director
- 8006170779 Forwards IE Insp Repts 50~321/80-15 & 50-366/80-15 on 800402-04 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/30 2pp
- --B006170784 IE Insp Repts 50-321/80~19 & 50-366/80-15 on 800402-04 No noncompliance noted Major areas inspected installed equipment per IE Bulletin 77-01B response CUNLON.TE Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARDNICK.R J Region 2. Atlanta. Office of the Director 80/04/27 4pp
- 8006060575 Forwards IE Bulletin 80-11. "Masonry Wall Design " Requires action & written response IE Info Notice 79-28.
 "Overloading of Structural Elements Due to Pipe Support D'REILLY, J P Region 2: Atlanta, Office of the Director 80/05/06
- 8006040226 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Openability " No written response required IE Info Notice

 80-20, "Loss of Docay Heat Removal Capability at Davis-Besse
 Unit 1 While in Refueling Mode" encl

 6'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09
- 800624(:066 Forwards lE Insp Repts 50-321/80-21 & 50-346/80-21 on 800415-19 No noncompliance noted LEWIG:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/12 2pp
- --8006240071 IE Insp Repts 50-321/80-21 & 50-366/80-21 on 800415-19 No No.2400/1 LC Insp Repts 50-321/60-21 & 50-366/80-21 on SU0415-16 No noncompliance noted Major areas inspected surveillance activity on pipe support & restraint sys.procedure test results installed restraints & records

 UPRIGHT.C M Region 2. Atlanta. Reactor Operations Nuclear Support Branch JOHNSON.A M Region 2. Atlanta. Office of the Director 80/05/06 3pp
- 8006130018 Requests info re ultrasonic insps of low pressure turbines to loarn more about underlying reasons for indications found 8 probable rate of growth indications & effects on turbine disc integrity REID.R W Operating Reactors Branch 4 80/05/13 3pp

- 8006300119 Forwards IE Circular 80-11, "Emergency Diesel Generator Lub* Oil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- 8006170337 Informs NRC that lamit switches used for position indication were not included in 43-day response to IE Bulletin 79-018 Environ qualification of switches should be addressed AE is in process of specifying qualified replacement switches MANRY, M. Georgia Power Co. 80/03/15 1p
- 8006090528 Ack receipt of 800428 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80~06 & 50-366/80-06 LEMIS, R C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/21 1p
- --BOO6090535 Responds to NRC 800331 ltr re deviations noted in IE Insp Repts 50-321/80-04 & 50-366/80-04 Corrective actions revised Procedures HNP-1 & 2-1902 & HNP-1 & 2-1904 to delineate immediate operator action section WIDNER, W.A. Georgia Power Co. 80/04/28 2pp
- --8006090540 Forwards IE Insp Repts 50-321/80-06 & 50-366/80-06 on 800219-21 & notice of deviation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/03/31 2pp
- ---8006090542 Notice of deviation from insp on 800219-21 * Region 2, Atlanta, Office of the Director 80/0 80/03/2B 1n
- --8006090547 IE Insp Repts 50-321/80-06 & 80-366/80-06 on 800217-21
 Noncompliance noted failure to ensure that licensed operators have committed to memory immediate emergency procedure actions
 KELL000.P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch SAUER.R C. ROGERS,R F Region 2, Atlanta, Office of the Director 80/03/28 Spp
- 8006250072 Summarizes responses to 1E Bulletin 79-01B, "Environ Gualification of Class IE Equipment " Based on GE estimate for completion of review of GE-supplied equipment, complete response will be submitted by B10403 HIDNER, W A Georgia Power Co 80/05/22 900pp

Support Branch

- 8006090408 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-13 & 50-366/80-13 Region 2, Atlanta, Reactor Construction & Engineering MURPHY C F
- --8004090415 Responds to NRC 800421 ltr re violations noted in IE Insp Repts 50-321/80-13 & 50-366/80-13 Corrective actions project plan reviewed & found acceptable & personnel performing insp certified WIDNER.W A Georgia Power Co 80/05/09 2pp
- --8006090422 Forwards IE Insp Repts 50-321/80-13 & 50-364/80-13 on 800311-14 & 25-28 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/21 2pp
- --B006090427 Notice of violation from insp on B00311-14 & 25-28 * Region 2, Atlanta, Office of the Director B0/04/17 ip
- --8006090435 IE Insp Repts 50-321/80-13 & 50-366/80-13 on 800311-14 & 25-28 Noncompliance noted failure to approve inservice insp plan & failure to certify welding & NDE inspectors.
 HERDTA R. CROWLEY, B. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/17 9pp
- 8006180317 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts \$0-32i/80-11 & 50-326/80-11 LEWISR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/02 ip
- -8006180323 Responds to NRC B00427 ltr re violations noted in IE Insp Repts 50-321/80-11 & 50-366/80-11 Corrective actions control rod movement procedures revised & large scale drawings replaced w/mitrofilmed prints in control room WIDNER,W A Georgia Power Co 80/05/27 4pp
- -8006180327 Forwards IE Insp Repts 50-321/80-11 & 50-366/80-11 on 800202-0807 & notice of violation O'REILLY.J P Region 2, Atlanta, Office of the Director 80/04/27 2pp
- --8006180332 Notice of violation from insp on 800202-0307
 * Region 2, Atlanta, Office of the Director 80/04/ 80/04/15

- --8006180338 IE Insp Repts 50-321/80-11 & 50-366/80-11 on 800202-0307
 Noncompliance noted failure to operate RBCS properly to
 limit rod motion w/RSCS inoperable, to evaluate procedure
 change & to provide updated plant drawings in control roum
 RDOERS, R F Region 2. Atlanta, Office of the Director DANCE, H C
 Region 2. Atlanta, Reactor Operations Nuclear Support Branch
 80/04/15 9pp DANCE, H C
- 8006230210 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-18 & 30-366/80-18 LENIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/02 lp

- -800.4230218 Responds to NRC 800.430 ltr re violations noted in IE Insp Repts 50-321/80-18 & 90-366/80-18 Hritten & approved functional test was not necessary because operability could have been demonstrated through existing plant procedures WIDNER, H A Georgia Power Co 80/08/27 2pp
- --8006230222 Forwards corrected cover page for IE Inap Rapts 50-321/80-18 & 50-366/80-18 on 800331-0402 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/08 ip
- --8006230226 Corrected cover page for IE Insp Repts 50-321/80-18 & 50-366/80-18 on 800331-0402 LEMIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/08 1p
- --8005230228 Forwards IE Insp Repts 50-321/80-18 & 50-366/80-18 on 800331-0402 & notice of violation LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/30 2ps
- --8006230232 Notice of violation from insp on 800331-0402 * Region 2. Ablanta, Office of the Director 80/04/3 B0/04/30 1o
- --8006230237 IE Insp Repts 50-321/80-18 & 50-366/80-18 on 800331-0402 Noncompliance noted failure to perform post-mod testing. DANCE, H C . BURNETT, P T Region 2. Atlanta. Office of the Director 80/04/30 4pp
- 8006250245 Ack receipt of 800514 & 27 ltrs informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-321/80-03, 50-321/80-16 & 50-366/80-16 KENNA, # 8 Region 2, Atlanta, Safeguards Branch 80/06/11 ip
- --8006250249 Responds to NRC 800418 ltr re violations noted in IE Insp Repts 50-321/80-03 t 50-366/80-03 Requests that 800514 ltr be withheld (ref 10CFR2 790) HIDNER-N A Georgia Power Co 80/05/29 ip
- --8006250250 Forwards IE Insp Repts 50-321/80-03 & 50-346/80-03 on B00107-11 % notice of violation Notice of violation withheld (ref 100FR2 770) D'RELLLY.J.P. Region 2. Atlanta, Office of the Director B0/04/18 Rpp
- -800A250254 IE Insp Repts 50-321/80-03 & 50-366/80-03 on 800107-11 Noncompliance noted failure to follow procedures for documenting security incidents & to perform vital area patrols as committed Details withheld (ref 100FRZ 790) TOBIN.W. J. Region 2. Atlanta, Bafeguards Branch. PER Region 2. Atlanta, Office of the Director 80/04/08 PERNY C. D
- --8006250258 Forwards IE Insp Repts 50-321/80-16 & 50-366/80-16 on 800326-28 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta. Bafeguards Branch 80/04/29 2pp

- R Periodic operating reports & related correspondence
- BOO6180494 Forwards monthly operating rept for May 1980 MANRY, M Georgia Power Co 80/05/10 1p
- --8006180497 Monthly operating rept for May 1980 RODEM, J W Georgia Power Co 80/06/10 Spp
- S Reportable occurrences, LERs & related correspondence
- 8006030435 Forwards LER 80-076/03L-0 MANRY, M Coorgia Power Co 80/05/23 ip
- --8006030445 LER 80-076/03L-O on 800429, during performance of control rod driveling hydraulic control unit pressure indicator & switch callbr procedure. HNP-2-5329, high percentage of pressure switches found outside | innit Caused by instrument drift NIX.R T Georgia Pawer Co 80/05/23 2pp
- 8004080338 Forwards LER 80-080/03L-0 MANRY: M Georgia Power Co 80/05. 80/05/27 In
- --8006050340 LER 80-080/03L-0 on 800508, during surveillance testing, found that Bartsdale pressure switches 2031-N018A & B were not within allowable Tech Specs Caused by instrument drift Switches recalibr Georgia Power Co 80/05/27 2pp
- 8006050360 Forwards LER 80-082/03L-0 MANRY M Georgia Power Co 80/05/ 80/05/27 1p
- --8004050346 LER 80-082/03L-0 on 800509, during normal reactor shutdown, primary containment purge sys operation exceeded Tech Spec limits for primary containment integrity Caused by personnel BAXLEY, S X Georgia Power Co 80/05/27
- 8004050348 Forwards LER 80-077/031-0 MANRY,M Georgia Power Co 80/05/28 ip
- --8006050355 LER 80-077/03L-0 on 800430, w/reactor at 79% power, A reactor bldg chiller failed to maintain average drywell temp when B chiller tripped Causad by broken guide vane arm Arm replaced & temp decreased to within limits.

 NIX.R T Georgia Power Co 80/05/28 2pp
- 8004050334 Forwards LER 80-077/03L-0 MANRY-M Georgia Power Co 80/05/ 80/05/29 1s
- --8006050335 LER 80-079/03L-0 on 800507, inboard isolation valve 2E41-F006 JOOUNGS LER 80-077/05.-0 on 80000/,indoard isolation value opened but failed to close automatically Caused by steam leaking around pressure seel allowing water to enter & collect in motor,causing windings to short out # Georgia Power Co 80/05/29 2pp
- BOD6050365 Forwards LER 80-055/03L-0 MANRY,M Georgia Power Co 80/05 80/05/29 1p
- --8006050372 LER 80-055/03L-0 on 800506, while performing reactor core isolation cooling steam line pressure instrument functional test, outboard steam supply line isolation valve, 2E51-F60B, failed to operate Caused by failed operator torque switch NIX/R T Georgia Power Co 80/05/27 2pp
- 8005170593 Forwards LER 80-083/03L-0 MANRY.M Georgia Power Co 80/06/03 1p
- --8006170687 LER 80-083/03L-0 on 800514.w/reactor in startup mode.
 personnel observed that indicating lights for 2D RHR pump
 suction valves were extinguished Valves were not operable
 from control switches, Caused by broken limit switch rotors
 NIX.R T Georgia Power Co 80/06/05 2pp
- 8006200437 Forwards LER 80-086/03L-0 MANRY.M. Georgia Power Co 80/06 80/06/10 1p.
- --B006200444 LER B0-086/03L-0 on B00323 during power increase PSW flow was throttled to reduce dilution flow, reducing cooling capacity DW temp exceeded specs Caused by operator throttling svc water flow through plant BAXLEY, B X Georgia Power Go 80/06/10 2pp
- 800620046B Forwards LFR 80-085/03L~0 MANRY-M, Georgia Power Co 80/06/11, 1p

~-80062C0474 LER 80-085/03L-0 on 800521. w/reactor in hot shutdown, RMR svc water pumps 2E11-C001B & D started to put torus cooling in svc Caused by bad seal in air release valve. Allowing vent on discharge line Valve reassembled NIX.R T Georgia Power Co 80/06/11 2pp

8006200476 Forwards updated LER 80-053/03X-2 MANRY, M Georgia Power Co 60/06/11 1p

~-8006200481 Updated LER 80-053/03X-2 on 800505 during normal operation, notification received from Comsip. Inc of design defect on primary containment hydrogen-oxygen analyzers Caused by absence of design to prevent beadheading CO00IN.C L. Georgia Power Co. 80/05/19 2pp

8006200478 Forwards LER 80-081/03L-0 MANRY,M Georgia Power Co 80/06/12 ip

~-8004200483 LER 80-081/03L-0 on 800521. W/reactor near rated power. LUCA signal accidentally initiated resulting in reactor scram Dutboard MSIV failed to auto close Gaused by faulty 0-ring in valve air operating solenoid NIX.R T Georgia Power Co 80/04/13 2pp

8006240431 Forwards LER 80-054/03L-0 MANRY.M Georgia Power Co 80/06/17 1p

--8006240436 LER 80-094/03L-0 on 800524.while performing calibr of both primary containment purge vacuum breaker pressure switches. 2748-N211 found inoperable Caused by personnel error Stuck switch removed & repaired Switch wiring corrected NIX:R T Georgia Power Co 80/06/17 2pp

BOD6240454 Forwards LER 80-084/03L-0 MANRY, M Georgia Power Co 80/06/17 1p.

--8006240458 LER 80-084/03L-0 on 800521 unit scremmed while operating at steady state Reactor core isolation cooling tripped on high water level 8ys maunally restarted but tripped on mechanical overspeed trip COGOIN.C L Georgia Power Co 80/06/17. 2pp

8006300344 EN-80-23 notice of violation & notice of proposed imposition of civil penalty will be tasued on or about 800619 Action based on alleged noncompliance re radiation levels in truck cab Will issue news release BROCKETT,T W , THOMPSON.D Office of Inspection & Enforcement, Office of the Director 80/06/17 ip

B006240442 Forwards LER 80-088/03L-0 MANRY, M Georgia Power Co B0/06/19 ip.

--8006240455 LER 80-088/03L-0 on 800529, while performing HNP-2-3154, reactor pressure vessel level instrument (LPCI) FT&C, switch 2 on 2821-NO31A failed Caused by switch being out of adjustment due to loose screw Switch readjusted NIX.R T Georgia Power Co 80/06/19 2pp

8006240507 Forwards LER 80-087/03L-0. MANRY.M Georgia Power Co 80/06/19 1P

---B006240514 LER 80-0B7/03L-0 on 800528 during surveillance procedure HNP-2-3154 reactor pressure vessel level instrument (LPCI) FT&C on 2B21-NO31B Switch 4, had double actuation. Caused by slipped magnets on pointer sh

DOCKET 50-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

BOOA230110 Advises BWR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing. BO/05/20 13pp.

BOD6020470 Forwards request for add1 info re util 1978 proposal to install shorter piles for foundation. Question relates to calculations of pile group uplift capacity Water will rise above piles when const dewatering operations cease YOUNGBLOOD, B J Licensing Branch 1 80/05/22 5pp

8006110331 Forwards add1 info re pile group capacity per 800516 & 22 requests
SHORB.E.M. Northern Indiana Public Service Co 80/05/28 6pp.

8006230001 Summary of 800410 meeting w/Mark 11 owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation 8U.T M Containment Systems Branch 80/05/30 4pp

8006300009 Forwards "For Comment" edition of NUREC-0619 "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Rept provides NRC resolution of Generic Technical Activity A-10 W/O encl EIBENHUT, D @ Division of Licensing 80/06/06 3pp

O Adjudicatory correspondence

8006090251 Comments on transcript of B00312-13 prehearing conferencequality of transcript very poor If transcript cannot be improved, another hearing to cover contentions of intervenors or another prehearing conference should be held ROBBINS, R.L. Lake Michigan Federation 80/04/08 ip

B006190392 Advises that State of IL has instituted request for action per 10CFR2 206 to revoke, suspend or modify CP Requests that meeting be held to discuss issue.after issuance of FEMA rept on emergency planning within 10-mile radius, due on B00620 HANSELL.D Illinois, State of 80/05/08 2pp

800616020R Provisional order re 800312-13 special prehearing conference, advising that ASLB will admit petitioners who can allege injury-in-fact, if qualified for intervention. Final order will be issued after comments W/Centificate of Svc QROSEMAN, H Atomic Bafety and Licensing Board Panel 80/05/30 5300

BOO6110427 Notice of change of address LAUDIO:8. Laudig: 8 BO/05/31 2pg

8006110354 Notifies that City of Dary, IN United Steelworkers of America-Local 5787, Bailly Alliance, Save the Dunes Council & Critical Mass Energy Project join State of IL request to suspend or revoke CP & request for meeting w/MRC CDHN, B R , 8CHULTZ, W B Public Citizen Litigation Oroup, 80/06/05

---8006110376 City of Gary, IN, United Steelworkers of America, Local 6787, Bailly Alliance, Save the Dunes Council & Critical Mass Energy Project join State of IL request under 10CFR2, 206 for suspension or revocation of CP Certificate of Svc encl COHN, D B Public Citizen Litigation Group 80/06/05 7pp

--8006110378 Petition to intervene and request for hearing re util request for amend to CP, submitted by City of Cary, In. United Steeluorkers of America, Local 6787, Bailup Alliance, Bave the Dunes Council & Critical Mass Energy Project CONN.D B . BCHULTZ, W B Public Citizen Litigation Group 800/06/05 7pp

---BOO61103B2 Response to NRC & util reply to petition to intervene, submitted by City of Gary, IN, United Steelworkers of America. Local 6787. Bailly Alliance. Save the Dunes Council & Critical Mass Energy Project. Draft affidavits encl. GCHN-D B., SCHULTZ.W B Public Citizen Litigation Group BO/02/26 20pp

8006280239 Objections to ASLB 800830 provisional order following special prehearing conference, ruling on contentions, Urgea deferrel of final ruling until positions on admissibility are submitted by parties Certificate of Svc entl, QOLDBERG, S C Hearing Branch 2 80/06/24, 14pp

8006300396 Disjection to ABLE 800500 provisional order Urges reconsideration of order concluding that City of Gary. IN. et al contention is subside scope of proceeding BECY 80-275 kdvises adoption of interior rules re emergency planning COHN.D B Gary. IN COHN.D B Critical Mass Energy Project. COHN.D B Cohn.D B B0/06/24 Opp.

~~8006300399 Discusses finalization of emergency planning rule changes, including consideration of public comments.Recommends FR publication re final rulemaking, HINOQUE,R B. Office of Standards Development, Director SECY-80-275 80/06/03 7pp

R. Periodic operating reports & related correspondence

8006030371 Forwards well charts for 800507-14.Bailly Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings & USOS wells for 800514 BOHN,R J Northern Indiana Fublic Service Co. 80/05/23 34pp.

- 8006040314 Forwards Bailly wells w/o recorders, pand levels, pneumatic pressure transducers, Jater meter readings & USOS well for 800521; well charts for 800514-21; chart recorder calibres of 800519 & Lake MI levels for 800115-0501 BDHN, R J Northern Indiana Public Service Co 80/05/30 35pp
- 8006110146 Forwards "Winter 1980 Guarterly Rept.Bailly Nuclear-1 Bite," Jan-Mar 1980, prepared by TX Instruments. Inc PURCELL, J.F. Northern Indiana Public Service Co. 80/06/04 1p
- --8006110152 "Winter 1980 Quarterly Rept.Bailly Nuclear-1 Site," Jan-Mar 1980 * Taxes Instruments, Inc. 80/05/31 188pp
- 8005110119 Forwards well charts for 800521-28, Bailly wells w/o recorders, pond levels, proumatic pressure transducers, water meter readings & USOS wells for 800528 Wells 550 & 56C cable hung up an 800528 & water meter out of svc on 800528 80HN, R J Northern Indiana Public Service Co 80/05/06 34pp
- 8006200370 Forwards well charts for 800528-0604, Bailly wells w/o recorders, USGS wells for 800606 & pand levels, pneumatic pressure transducers & water meter readings for 800604 BOHN,R J Northern Indiama Public Service Co 80/06/13 34pp
- 8006260195 Forwards well charts for 800404-11.8ailly wells w/o recorders, pond levels, pneumatic pressure transducers & water aster rasdings for 800611 & USGS wells for 800610 BONN, R J Northern Indiana Public Service Co
- U Congressional/Executive Correspondence
- 8006300389 Expresses concern re NRC consideration of CP renewal Encl Late MI Federation Mar 1980 study challenges NRC 800410 brief re interrelationship between ash pond seepage & const dewatering VATES,8 R House of Rep 80/04/03 is
- --8006300393 "Mow Bailly Nuclear Plant Could Dry Up Dunas Natl Lakeshore " NEWCOMB.C , ROBBINS.R L Lake Michigan Federation 80/03/31 24eo
- DOURCE DU-JAB ARKANSAS NUCLEAR ONE, UNIT 2

 D NRC Draft/Final Environmental Statements, supple & correspondence
- 8006300599 FES for AR Nuclear One.Unit 2 * Office of Nuclear Reactor Regulation, Director NUREG-0234 77/06/30 150pp Available at NTIS \$6.75
- F Security, medical, emergency & fire protection plans
- 8006070027 Forwards request for add1 info re security personnel training & qualification plan Enc1 withheld (ref 100FR2 790)
 REID.R W Operating Resctors Branch 4 80/05/19 2pp.
- 8006090487 Forwards proposed rule entitled, "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 t App R to 10CFR50 & is expected to be published in FR by end of May.

 EISENHUT, D © Division of Licensing. 80/09/19 46pp
- 8006130063 Forwards revised Pages 1-i4 & new Page 14a for proposed rule 10CFR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 770101," transmitted by NRC 800510 ltm Page 14a not entl
 EISENHUT, D 0 Division of Licansing. 80/05/22 73pp
- 8006110242 Forwards revisions to proposed util safeguards contingency plan per RM Reid 800411 request Plan withheld (ref 10CFR2 790)
 TRIMBLE,D C Arkansas Power & Light Co 80/05/30 ip
 - Ack receipt of NRC 800519 ltr requesting info on security ltraining & qualification plan Requests copy of EE-0674 dealing w/subject.prior to response to ltr l Arkansas Power & Light Co 80/06/13 ip

- H General correspondence
- 8006270171 Responds to 800430 request to comment on R Lacewell concerns re spent fuel storage pool expansion Util indicated that no plans for expansion anticipated until 1982 or 1983 NRC approval & public consideration would precede expansion DIRCKS.N J Office of the Executive Director for Operations 80/06/07 2pp
- P Operating license stage documents & correspondence
- 8006090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift mamning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT, D 0 Division of Licensing 80/05/07 150pp
- 8006130122 Requests comments on NURCG-0577. "Potential for Low Fracture Toughness & Lemellar Yearing on PWR Steam Generator & Reactor Coolant Pump Supports "Proposed review procedure & implementation schedule encl EISENHUT, D G Division of Licensing 80/05/19 72pp
- 8006130326 Submits info re potential missles involving reactor cavity annulus seal ring & biological shielding in response to 790310 ltr (dtd 780510) No safety-related components will be affected by biological shielding in event of LOCA TRIMBLE.D C Arkansas Power & Light Co 80/06/06 2pp
- 8006120315 Forwards "AR Nuclear 1 Steam Electric Station.Unit 2 Startup Rept," Suppl 3 for period ending 800430 TRIMBLE.D C Arkansas Power & Light Co 80/06/09 ip
- --8006120316 "AR Nuclear 1 Steam Electric Station, Unit 2.8tartup Rept." Suppl 3 for period ending 800430 * Arkansas Power & Light Co 80/04/30 48pp
- B006170700 Forwards response to NRC 800505 ltr re loss of offsite power events
 TRIMBLED C Arkansas Power & Light Co 80/06/11 3pp
- 8006180828 Responds to NRC 800505 ltr re loss of offsite power events Details of 750222.1205 & 800407 events indicate weather conditions were responsible on all occasions Only momentary losses of power were experienced TRIMBLE.D C Arkansas Power & Light Co 80/06/11 3pp
- 8006230401 Submits response to 800507 request for commitment to TMI-2 related requirements Response to Items II K 3 25,27 & 44 uill be delayed because util did not receive errata sheets until 800616 TRIMBLE.D C Arkansas Power & Light Co 80/06/18 3pp
- G Inspection reports, IE Bulletins & correspondence
- BO05240036 Forwards IF Insp Repts 50-313/80-06 & 50-368/80-06 on 800322-0421 & notice of violation MADBELO G L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/05/05 2pp
- --8006240042 Notice of Violation from insp on 800322-0421 * Region 4, Dallas: Reactor Operations Nuclear Support Branch 80/05/02 3pp
- --R004240046 IE Insp Repts 50-313/80-06 & 50-368/80-06 on 800322-0421
 Noncompliance noted no control of combustibles & finding
 that waste control operator entered high radiation areas w/o
 using radiation survey instrument
 MESTERMAN, T F Region 4, Dallas, Reactor Operations Nuclear
 Support Branch 80/05/02 16pp
- 8006060597 Forwards IE Bulletin 80-11, "Masonry Wall Design " Requires action & written response IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/08
- 8006050317 Forwards IE Bullstin 80-12, "Decay Heat Removal Sys Operability " Requires actions & response within 30 days IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Dosse Unit 1 While in Refueling Mode" encl SEYFRIT, K V Region 4, Dallas, Office of the Director 80/09/09

- 8004056331 Responds to violations noted in IE Insp Repts 50-313/80-04 006050331 Responds to viblations noted in 1E Insp Repts 30-3: \$ 50-360/80-06 Corrective actions doors to high radiation areas locked or repaired & locked Combustibles removed from prohibited areas % maint personnel notified TRIMBLE,D C Arvansas Power & Light Co B0/05/29 App
- BOO6240184 Ack receipt of BOO606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/80-05 & 50-368/80-05 MADSEN, G.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch BO/06/06

- --8006240186 Responds to NRC ltr re violations noted in IE Insp Repts 50-313/80-05 % 50-368/80-05 Corrective actions revised Procedure 1304 23 % 2304 15 requiring specific sign-off for each leak rate test following containment entries TRIMBLE.D C Aikansas Power & Light Co 80/05/09 5pp
- 8006200489 Responds to IE Hulletin 80-12, "Decay Heat Removal Sys Operablility " Analyses of procedures for safeguarding against loss of sys capability should be completed by CAVANAUCH.W Arkansas Power & Light Co 80/04/12 3pg
- R Feriodic operating reports & related correspondence
- 8006110142 Forwards "Annual Environ Momitoring Rept" TRIMBLE, D.C. Arkansas Power & Light Co. 80/05/12 ip
- --8006110154 "Annual Environ Honitoring Rept " Oversize drawing encl 4 Arkansas Power & Light Co 80/05/12 400pp
- B006190983 Forwards monthly operating rept for May 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/13
- --BOO5190587 Monthly operating rept for May 1980 PENDERGRAFT, R Arkensas Power & Light Co 80/06/13 5pp
- S Reportable occurrences, LERs & related correspondence
- 8006090386 Forwards updated LER 80-022/03X-1 TRIMBLE,D C Arkansas Powor & Light Co 80/06/02 ip
- --B006090394 Updated LER 80-022/03X-1 on 800806, while performing testing on steam driven emergency feedwater pump, 2P7A, pump tripped three times due to overapeed Caused by mechanical adjustments to pump b driver controller Reduced idle speed, PENDERGRAFT,R Arkansas Power & Light Co 80/06/02 2pp
- 8006230450 Forwards LER 80-025/03L-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/04 1p
- ---B006230457 LER B0-025/03L-0 on B00507; during Mode 1 operation, control room alarm indicated valve 2CV-5657 to be open when valve was closed Caused by position switch misalignment due to loose screw Switch realigned PENDERGRAFT, R Arkansas Power & Light Co B0/06/04 ip
- 8006230530 RD 50-368/80-037 on 800603, safety injection tank boron concentrations reported out of Tech Spec condition Possibly caused by boron stratification Boron concentration adjusted & cause being investigated O'HANLON.J P Arkansas Power & Light Co 80/06/04 2pp
- 8006180458 Forwards LER 80-026/03L-0 TRIMBLE,D C Arkansas Power & Light Co 80/06/11 ip
- --8006180460 LER 80-026/03L-0 on 800514, control room air conditioner compressor. 2VE-1A, tripped Caused by unit tripping on freeze protection due to too small of load for chiller when providing cooling for core protection computer room SHIVELY, C N Arkansas Power & Light Co 80/06/11 1p
- B006170625 Forwards LER 80-027/03L-0 TRIMBLE, D.C. Artensas Power & Light Co 80/06/12 1p.
- -8006170634 LER 80-027/03L-0 on 800516, during Mode 1 operation, svc water hanger 2HCB-33-10 on loop 1 found broken Caused by improper installation Hanger roo had only one thread engaged & could not hold load Hanger reinstalled properly SHIVELY,C N Arkansas Power & Light Co 80/06/12 1p
- 8005180456 Forwards updated LER 80-012/03X-2

- --8006180459 Updated LER 80-012/03X-2 on 800222, while performing 18-month surveillance test on dissel generator 1 unit load oscillation & vibration became apparent Caused by broken generator rotor shaft generator rotor shaft SHIVELY:C N Arkansas Power & Light Co 80/04/12 ip
- 8006180463 Forwards LER 80-028/03L-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/12 to
- --8006180467 LER 80-028/03L-0 on 800916, during Mode 1 operation, A steam generator high level protrip/trip signal received on channel C PPS Caused by power supply failure on bistable card Cord replaced % channel tested SHIVELY, C N Arkansas Power & Light Co 80/06/12 ip
- 8006200359 Forwards LER 80-030/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/06/16 ip
- --8006200363 LER 80-030/03L-0 on 800520 during Mode 1 operation, steam driven emergency feedwater pump 2P7A tripped on overspeed following manual start signal Investigation did not reveal exact rause of pump trip Pump trip reset PENDERGRAFT, R Arkansas Power & Light Co 80/05/16 1p
- 8006200430 Forwards LER 80-029/03L-0
 TRIMBLE, D C Arkansas Power & Light Co 80/06/16 ip
- --BOO6200434 LER BO-029/O3L-O on BOO520.during Mode 1 operation, 2 diasal generator deluge sys rendered inoperable Caused by deluge valve being intentionally removed from svc to facilitate needed fire sys mode PENDERGRAFT.R Arkansas Power & Light Co 80/06/16 ip
- 8006200485 Forwards LER 80-037/01T-0
 TRIMBLE.D C Arkansas Power & Light Co 80/06/17 ip
- --8006200493 LER 80-037/01T-0 on 800603 during Mode 1 operation, safety injection tanks C & D. found to have boron concentrations of 1.711 ppm & 1.620 ppm respectively Caused by design error Caused by boron stratification in safety injection tanks SHIVELY, C N Arkansas Power & Light Co 80/06/17 1p
- DOCKET 50-369 WILLIAM B MCGWIRE NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8006030175 Forwards Matls Engineering Branch input re water chemistry programs W/o enci KNIOHT.JP Assistant Director for Engineering 80/04/07 ip
- 8004020015 Notification of cancelled 800519-23 meeting w/util in Mecklenburg County, NC to perform design review of control BIRKEL,R A Licensing Branch 1 80/04/30 3pp
- 8006230110 Advises NWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 80/05/20 13pp
- BOOAOAO345 Amend 64 to CPPR-B3 & CPPR-B4 updating "Electrical Schematics," Vols 1-3 Schematic drawings available in Central Files only PARKER, N O Duke Power Co 80/05/22 700pp
- 8006090194 Notification of 800602-06 meeting w/util in Macklanburg County, NC to perform design review of plant control room BIRKEL, R A Licensing Branch 1 80/09/23 3pp
- 8004090264 Forwards response to TMI concerns, superseding previous TMI submittals transmitted 791119,1226 & 800129 PARKER, W O Duke Power Co 80/05/23 300pp
- 8006130127 Notification of 800602 meeting w/util in Bethesda.MD to discuss facility staffing, testing & related matters BIRKEL,R A Licensing Branch 1 80/05/30 3pp
- 8006170033 Notification of 800606 meeting w/util to discuss facility staffing, testing & related matters BIRKEL, R.A. Licensing Branch 1 80/05/30 3pp
- 8006200623 Forwards request for add1 info re radiological assessment. Info should be provided by 800630 YOUNGBLEDD,B J Licensing Branch 1 80/06/04 5pp

- BOO6110354 Responds to NRC 800409 itr requesting independent plant-wide audit of installation of safety-related equipment Facility procedures provide adequate assurance that separation criteria properly implemented Add1 audit unwarranted PARMERIN D Dute Power Co 80/06/05 2pp
- 8006110327 Forwards response to NRC 800512 request for info re reactor vessel notices PARKER.N O Duke Power Co 80/06/06 4pp
- 8006120367 Forwards "Westinghouse Multiple Aperture Small Break ECCS Analyses," in response to NRC 800407 request Multiple aperture breaks are bounded by analyses performed in FSAR where only single break location assumed PARKER.H D Duke Power Co 80/06/06 2pp
- --8006120370 "Westinghouse Multiple Aperture Small Break ECCS Analyses "

 Duke Power Co 80/05/31 277pp
- BOO6200612 Summary of 800606 meeting cojutil in Bethesda, MD re status of application YOUNGBLOOD, B J Licensing Branch 1 80/06/10 Spp
- BOO6240485 Forwards supplemental info on program to monitor & control secondary water chemistry
 PARKER: N D Duke Power Co BO/06/19 Spp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- BDO&O&O221 Forwards Suppl 3 to SER Ofc of Nuclear Reactor Regulation issued evaluation in connection w/OL application H/o ancl YOUNGBLOOD, B J Licensing Branch 1 80/05/23 2pp
- BO06180049 Suppl 3 to SER for facility # Office of Nuclear Reactor Regulation, Director NUREQ-0422 S3 BO/05/31 22pp Available at NTIS
- F Security, medical, emergency & fire protection plans
- BDD5130317 Forwards clarification of NRC requirements for emergency response facilities defined in 770913 ltr Add1 specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 dipp
- BOO6160074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 10CFR2 790)
 PARKER, W.O. Duke Power Co. 80/06/09 1p
- BOO6230:35 Notification of BO0617 meeting w/util to evaluate upgrading of smergency planning Region 2 BO0530 press release encl BIRKEL.R A Licensing Branch 1 BO/06/10 4pp
- 9 Adjudicatory correspondence
- BOO6240594 Forwards Lincoln County, NC Board of County Commissioners 791001 & 800408 resolutions affirming position that spent nuclear fuel should be transported from Oconse to McGuire on interstate highways MOUSER:F M North Caroline, State of 80/04/17 3pp
- 8005230577 Advises that util is to submit proposed findings of fact by 800519.non-NRC parties by 800529 & NRC by 800609 MCGARRY.J M Debevoise & Liberman 80/04/30 1p.
- BOO6060269 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J. H. Debevoise & Liberman 80/05/19 ip
- --8004060281 Submittal of proposed findings of fact & conclusions of law in form of initial decision HCCARRY, J M Duke Power Co 80/05/19 1p
 - cision containing findings of fact & amend to authorize storage of Environ radiological monitoring '/Certificate of Byc 89pp
 - 3 initial decision du
 - expeditious issuance of full-term DL & commencement of initial fuel loading in late sugger M/Certificate of Syc MCGARRY, J M Dute Power Co MCGARRY, J M Dabavoise & Libergan SO/OS/30. Spp

- B006180317 Response in apposition to Carolina Environ Study Group B00527 proposed elements of fact & conclusions of law toward initial decision No good reason presented for not approving application re spent fuel shipment U/Cortificate of Svc MCGARRY, J M Duke Power Co B0/06/13 21pp
- BOO6190593 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to & storage at McQuire KETCHEN.E 0 Hearing Branch 4 80/06/17 1p
- --8006190606 Proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Ocones spent fuel transportation to & storage at McQuire Proposed transcript corrections & Certificate of Syc encl KETCHEN, E O Hearing Branch 4 80/06/17 155pp
- 8006200317 Motion for extension until 800710 to respond to util 800530 motion to terminate stay of ASLB 790418 initial decision & to respond to Carolina Environ Study Group motion to admit new cuntentions & to reopen record W/Certificate of Syc KETCHEN.E 9 Hearing Branch 4 80/06/17 5pp
- 8006240435 Order granting extension until 800710 for NRC to respond to outstanding motions in GL proceeding LAZO.R M Atomic Safety and Licensing Board Panel 80/06/19 2pp
- 8004250253 Request for extension until 800707 to respond to Carolina Environ Study Group 800609 motions to admit new contentions & reopen record Possibility of stipulation is being discussed w/intervenor Certificate of Svc encl MCGARRY, J M. PORTER, M. L. Duke Power Co. MCGARRY, J M. Debevoise & Liberman 80/04/24 Spp
- Q Inspection reports, 12 Bulletins & correspondence
- B006060427 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Dyerloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09
- BOOA040273 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Resse Unit 1 White in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Defice of the Director 80/05/09 289.
- BO06300110 Forwards IE Circular BO-11. "Emergency Diess! Generator Lubs Oil Cooler Failures " No written response required. O'REILLY, J. P. Region 2. Atlanta. Office of the Director BO/05/13 200
- BD0A090540 Ack receipt of IE Insp Rept 50-349/80-03 No proprietary info PARKER, W D Duke Power Co 80/05/21 1p
- --B006090561 Forwards IE Insp Rept 50-369/80-03 on 800327-0404 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/01 2pp
- --8006090565 IE Insp Rept 50-369/80-03 on 800327-0404 No noncompliance moted Major areas inspected preoperational testing review of licensee response to bulletins & circulars & followup on items from previous repts MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch DDNAT.T J. ORAHAM.M J Region 2, Atlanta, Office of the Director 80/04/30 App
- 8006180237 Ack receipt of IE Insp Rept 50-369/80-06 No proprietary info PARKER, N O Duke Power Co 80/05/28 ip
- ---8006180240 Forwards IE Insp Rept 50-369/80-06 on 800423-25.No noncompliance noted LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/08 2pp
- --8006180246 IE Insp Rept 90-369/80-06 on 800423-25 No noncompliance noted Major areas inspected reactor protection sys. preoperational test procedure, engineered safety feature test package & signal separation criteria implementation MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch DONAT,T J. Region 2, Atlanta, Office of the Director 80/05/08 4pp.

- 8006230360 Ack receipt of IE Insp Repts 50-369/80-07 & 50-370/80-14 on 800430-0302 No proprietary inro PARKER, N G Duke Power Co 80/06/05 tP
- --B006230367 Forwards IE Insp Repts 50-367/80-07 & 50-370/80-14 an B00430-0502 No noncampliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/16 2pp
- --8006230371 IE Insp Repts 50-369/80-07 & 50-370/80-14 on 800430-0502 No noncompliance noted Major areas inspected installed electrical equipment & review of near-term operating licensing facilities re NUREC-0588
 HARDMICK,R J Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 4pp
- BOO6300016 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Tank design provides acceptable protection against failure due to vacuum conditions No tank mods are required PARKER, W D. Duke Power Co. 80/06/05 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006170637 Refers to 800110 ltr which forwarded Significant Deficiency Rept 369-370/79-13 Completion of insp has been delayed until 800725 Schedule for completing insp of Unit 2 equipment remains unchanged PARKER, W O Duke Power Co 80/06/09 1p
- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8006030195 Forwards Matls Engineering Branch input re water chemistry programs W/o encl KNIGHT.JP Assistant Director for Engineering 80/04/07 ip.
- 800A020015 Notification of cancelled 800519-23 meeting w/util in Macklenburg County,NC to perform design review of control room BIRKEL,R A Licensing Branch 1 80/04/30 3pp
- 8006230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREC-0577 readequecy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 80/05/20 13pp
- 8004050345 Amend 64 to CPPR-B3 & CPPR-B4 updating "Electrical Schematics," Vols 1-3 Schematic drawings available in Central Files only PARKER, W O Duke Power Co 80/05/22 700pp
- 8006050194 Notification of 800602-06 meeting w/util in Mecklenburg County.NC to perform design review of plant control room BERKEL.R A Licensing Branch 1 80/05/23 3pp
- 8006090266 Forwards response to TMI concerns, superseding previous TMI submittals transmitted 791119,1226 & 800129 PARKER, N O Duke Power Co 80/05/23 300pp
- BOO6130127 Notification of BOO602 meeting w/util in Bethesda,MD to discuss facility staffing, testing & related matters #BIRKEL,R A Licensing Branch i BO/05/30 3pp
- 800Ai70033 Notification of 800A06 meeting w/util to discuss facility staffing, testing & related matters BiRKEL.R A Licensing Branch 1 80/05/30 3pp
- 8006200623 Forwards request for addl info re radiological assessment Info should be provided by 800630 YOUNGBLOOD,8 J Licensing Branch 1 80/06/04 9pp.
- 8006i10354 Responds to NRC 800409 ltr requesting independent plant-wide audit of installation of safety-related equipment Facility procedures provide adequate assurance that separation criteria properly implemented Add1 audit unwarranted PARKER, W O Duke Power Co 80/06/05 2pp
- 8006110327 Forwards response to NRC 800512 request for info re reactor vessel novites
 PARKER, W D Duke Power Co 80/06/06 4pp

- BOO6120367 Forwards "Westinghouse Multiple Aperture Small Break ECCS Analyses," in response to NRC 800409 request Multiple aperture breaks are bounded by analyses performed in FSAR where only single break location assumed PARKER, W D Duke Power Co 80/04/06 2pp
- --8005120370 "Westinghouse Multiple Aperture Small Break ECCS Analyses "
 Unke Power Co B0/05/31 277pp
- BOD6200612 Summary of 800606 meeting w/util in Bethesda.HD re status of application YOUNOBLOOD.B J Licensing Branch 1 B0/06/10 5pp
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8006060221 Forwards Suppl 3 to SER Oft of Nuclear Reactor Regulation issued evaluation in connection w/DL application W/o encl YOUNDBLDDD:B J Licensing Branch 1 80/05/23 2pp
- 8006180049 Suppl 3 to SER for facility * Office of Nuclear Reactor Regulation. Director NUREO-0422 83 80/09/31 22pp Available at NTIS
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT, D G Division of Operating Reactors 80/04/25 61pp
- 8006160074 Forwards revision to nuclear security training & qualification plan Plan withheld (ref 100FR2 790)
 PARKER.W O Duke Power Co 80/06/09 1p
- 8006230135 Nutification of 800617 meeting w/util to evaluate upgrading of emergency planning Region 2 800830 press release encl BIRKEL, R A Licensing Branch 1 80/06/10 4pp
- @ Adjudicatory correspondence
- 8006240574 Forwards Lincoln County,NC Board of County Commissioners 791001 & 800408 resolutions affirming position that spent nuclear fuel should be transported from Oconee to McQuire on interstate highways HOUSER,F M North Carolina, State of 80/04/17 3pp
- 8005230577 Advises that util is to submit proposed findings of fact by 800519.mon-NRC parties by 800529 & NRC by 800609 MCGARRY, J M Debevoise & Liberman 80/04/30 is
- 8006040269 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J K Debevoise & Liberman 80/05/19 1p
- ---8006060281 Submittal of proposed findings of fact & conclusions of law in form of initial decision MCGARRY, J M Duke Power Co 80/05/19 ip
- --8000060286 Proposed initial decision containing findings of fact & conclusions of law, approving amend to authorize storage of Oconce spent fuel at McGuire Environ radiological monitoring program shall be maintained W/Certificate of Svc MCGARRY, J M Duke Power Co 80/05/19 88pp
- 8006110205 Motion to terminate stay of ASLB 800418 initial decision due to NRC 800523 issuance of Suppl 3 to SER Requests expeditious issuance of full-term OL & commencement of initial fuel loading in late summer W/Certificate of Svc MCGARRY, J M Debevoise & Liberman 80/05/30 5ps
- BOO6180517 Response in opposition to Carolina Environ Study Group SOO529 proposed elements of fact & conclusions of law toward initial decision No good reason presented for not approving application re spent fuel shipment W/Certificate of Svc MCGARRY. J M Duke Power Co 80/06/13 21pp
- 8004190893 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to & storage at McGuire
 KETCHENE O Hearing Branch 4 80/06/17 ip

- --8006190606 Proposed findings or fact & conclusions of law in form of initial decision approving license amend to authorize Occurse spent fuel transportation to & storage at McGuire Proposed transcript corrections & Certificate of Svc sucl KETCHEN. E G Hearing Branch 4 80/06/17 155pp
- 8006200317 Mation for extension until 800740 to respond to util 800530 notion to terminate stay of ASLB 770418 initial decision & to respond to Carolina Environ Study Group mation to admit new contentions & to respen rec
- BOO6240435 Order granting extension until 800710 for NRC to respond to outstanding motions in OL proceeding LAZO.R M. Atomic Safety and Licensing Board Panel BO/O6/19 2pp
- 8006250253 Request for extension until 800707 to respond to Carolina Environ Study Group 800607 motions to admit new contentions & reopen record Possibility of stipulation is being discussed w/intervenor Certificate of Svc encl 4006087. J M. PORTER, H. L. Duke Power Co. MCGARRY, J M. Debevoise & Liberman 80/05/24 3pp
- O Inspection reports, IE Bulletins & correspondence
- 8006060427 Forwards IE Bulletin 80-11. "Masonry Nall Design " No action or written response required IE Info Natice 79-28. "Overloading of Structural Elements Due to Fipe Support Loads" encl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 800612012B Ack receipt of 800410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/80-01 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/08 ip
- --B006120134 Responds to NRC B00211 ltr re violations noted in IE Insp Rept 50-370/80-01 Corrective actions weld buildup of undersized welds underway w/completion by 800516 PARKER.W O Duke Power Co B0/04/10 2pp
- --8006120139 Responds to NRC 800211 ltr re violations noted in IE Insp Rept 50-370/E0-01 Corrective actions complete rainsp made of socket weld flanges using greater than schedule 40 pips All rejected welds documented & will be repaired PARKER.W O Duke Power Co 90/03/27 2pp
- --8006120145 Forwards IE Insp Rept 50-370/80-01 on 800109-11 & notice of viplation BRYANT.J C Region 2, Ablanta, Reactor Construction & Engineering Support Branch 80/02/11 2pp
- --8006120148 Notice of violation from insp on 800109-11
 * Region 2, Atlanta, Office of the Director 80/02/08 2pp
- --8005/2015/ IE Insp Rept 50-370/80-0/ on 800109-1/ Noncompliance noted undersize sucket welds, missing drawing & improper subassembly dimension Inspector did not know offset requirement for final welded joint HERDT, A Region 2, Atlanta, Reactor Construction & Engineering Support Branch GIRARD, E H Region 2, Atlanta, Office of the Director 80/02/08 5pp
- 8004040275 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Bessa Unit i While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07
- 8006300:10 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/05/13 200
- 8006230360 Ack receipt of IE Insp Repts 50-369/80-07 & 50-370/80-14 on 800430-0502 No proprietary info 800400-0502 No Power Co. 80/06/05 IP
 - its 30-369/80-07 & 50-370/80-14 on noted a, Reactor Construction & Engineering

- --8006230371 IE Insp Repts 50-369/80-07 & 50-370/80-14 on 800430-0502 No noncompliance mated Hajor areas inspected installed electrical equipment & review or near-term operating licensing facilities to NUREG-0588 HARDMICK.R J Region 2. Atlanta. Office of the Director COMLONITE. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/15 4pp
- 8006300016 Responds to IF Bulletin 80-09 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Tank design provides acceptable protection against failure due to vacuum canditions No tank mods are required PARKER, W D Duke Power Co 80/06/05 2pp
- S Reportable occurrences. LERs % related correspondence
- BD06170637 Refers to B00110 ltm which forwarded Significant Deficiency Rept 369-370/79-13 Completion of insp has been delayed until B00725 Schedule for completing insp of Unit 2 equipment romains unchanged PARKER.N Q Dyko Power Co S0/06/07 1p
- DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- B006020515 Requests info re nozzle base metal matl spec type & grade, clad process type, electrode size & number of clad layers & heat input for each layer to define potential for cracking in reactor vessel nozzles
 YOUNGBLOOD, [] J Licensing Branch 1 80/05/22 2pp
- 8006230001 Summary of 800410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T.M. Containment Systems Branch 80/05/30 App
- 8006180278 Forwards "Mark II Design Assessment Rept, "Revision 8 Revision updates Chapter 6 re suppression pool water tump response PEOPLES, D L Commonwealth Edison Co 80/06/05 Ip
- --8006180281 "Mark II Design Assessment Rept," Revision 8 * Commonwealth Edison Co 80/06/01 37pp
- 8006190087 Forwards trip rept 3 summary of B00424 & 25 meeting w/ Sargent & Lundy in Chicago. IL re soil structure interaction BGURNIA.A Licensing Branch 1 80/06/05 3pp
- --8006190095 Trip rept & summary of 800424 & 25 meeting w/Sargent & Lundy in Chicago, IL re soil structure interaction CHAN.S P Structural Engineering Branch 80/06/03 3pp
- 9006250107 Forwards "For Comment" edition of NUREO-0617 Describes technical issues studies & analyses performed by GE.
 Comments should be forwarded to NRC by BOD707 W/a encl
 EISENHUT.D G Division of Licensing 80/06/06 2pp
- 8006180621 Notification of 800613 meeting w/BWR Licensing Resolution Group in Bethesda.MD to discuss progress WILSON, J. M. Licensing Bianch 1 80/06/09 10pp
- 8006250138 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to A Bournia Reorganization charts enci TEDESCO,R L Assistant Director for Licensing 80/06/12 1ipp
- 8006250321 Summary of 800514 meeting w/utils in Bethesda,MD re organization & objectives of BWR licensing resolution group Agenda & viewgraph encl WILSON,J N Operating Reactors Branch 4 80/06/17 lipp
- 8006300453 Submits update of scheduled commercial svc dates for facilities, reflecting delays & scheduled OL fuel load dates Stresses importance of continued licensing process for Byron & Braidwood PEOPLES, D. L. Cammonwealth Edison Co. 80/06/20 2pp

- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations " Revised Revision 11 includes basis on which equivalent education requirements will be established PEOPLES.D L. Commonwealth Edison Co. 80/06/23 1p
- F Security, medical, emergency & tire protection plans
- 8006020254 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during energencies to link all power plants & NRC Emergency Notification Sys hattine will also be used KEPPLER.J G Region 3. Chicago, Office of the Director 80/04/18
- BOOSISORIF Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addi specific criteria for facilities under development
 EISENNUT.D G Division of Operating Reactors 80/04/25 61pp
- 8006030004 Notifies util that 800324 safeguards contingency plan needs revision b add1 info Details of required add1 info enc! Enc! withheid (ref 10CFR2 790) YQUNGBLQQD,B J licensing Branch 1 80/05/23 2pp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES.D L Commonwealth Edison Co 80/06/04 2pp
- --B0061B0324 Draft emergency glan annex
 * Commonwealth Edison Co 80/07/31
- --8006180347 Revision 1 to draft emergency plan
 * Commonwealth Edison Co 60/07/31 137pp
- 8006240490 Responds to NRC 800425,30,0501.09 & 20 ltrs requesting addl info re guard training % qualification plans Requests that response submittal date be extended to 800804 PEOPLES,D L. Commonwealth Edison Co 80/06/18 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004180364 Forwards Amend 49 to FSAR, including responses to seven second found questions, voluntary text % response revisions PEOPLES, D.L. Commonwealth Eduson Co. 80/06/05 1p
- --8006180369 Amend 49 to FSAR Oversize drawings enc1
 * Commonwealth Edison Co 80/06/05 1000pp
- Q Inspection reports, IE Bulletins & correspondence
- 8004060325 Forwards IE Insp Repts 50-373/80-16,50-374/80-11, 50-454/80-06,80-445/80-06,50-456/80-02 & 50-457/80-02 from meeting on 800328 No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/24
- --8004040333 IE Insp Repts 50-373/80-18.80-3/4/80-11.50-454/80-06. 30-455/80-06.50-456/80-02 % 50-457/80-02 from meeting on 800328 Areas inspected status of three stations under const FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch SCHMEIBINZ.C R , BARRETT.P A Region 3. Chicago. Office of the Director 80/04/14 4pp
- 8006130255 Forwards IE lasp Repts 50-373/80-12 & 50-374/80-09 on 800312-14 & 18-19 & notice of violation FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 Zpp
- --8006130257 Notice of violation from insp on 800312-14 & 18-19
 * Region 3, Chicago, Office of the Director 80/04/14 1
- --8004130259 IE Insp Repts 50-373/80-12 & 50-374/80-08 on 800312-14 & 18-19 Noncompliance noted deficient design control for small bore piping suspension sys
 YIN, I T Region 3, Chicago, Office of the Director
 DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/14 7pp
- 8006170756 Forwards 12 Insp Repts 50-373/80-20 & 50-374/80-13 on 800401-03 & 08 & notice of violation FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006170764 Notice of violation from insp on 800401-03 & 08
 * Region 3, Chicago, Office of the Director 80/04/22

- --8006170774 IE insp Repts 50-373/80-20 % 50-374/80-13 on 800401-03 % 08
 Noncompliance noted inadequate design controllack of work
 procedures % lack of OA audits
 DANIELSON, D H . YIM, I T Region 3, Chicago, Office of the
 Director 80/04/22 6pp
- BOO6170726 Forwards lE Insp Rept 50-373/80-14 on 800303-31 No noncompliance noted HEISHhAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch BO/05/05 2pp
- --8006170736 IE Insp Rept 50-373/80-14 on 800303-31 No noncompliance noted Major areas inspected procedures, preoperational test program b actions on previous insp findings SPESSARD.R L. MALKER, R D. Region 3. Chicago, Office of the Director 80/05/02 7pp
- 8006190177 Forwards IE Insp Rept 50-373/80-22 on 800415-16 No nancompliance noted

 No nancompliance noted

 FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering

 Support Branch 80/05/07 2pp
- --8006190182 IE insp Rept 50-373/80-22 on 800415-16 No noncompliance noted Major areas inspected instrument line hangars & nonconformance control
 KNOP,R C . BARRETT,P A Region 3. Chicago. Office of the Director
 BO/05/05 3pp
- B006190357 Forwards 1E Insp Repts 50-373/B0-21 & 50-374/B0-14 on B00408-10 No moncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/05/09 2pp
- --8006190366 IE Insp Repts 50-373/80-21 & 50-374/80-14 on 800408-10 No JUDITYONG IE INSPINENTS SU-3/3/80-21 & SD-3/4/80-14 on NOVAOI noncompliance noted Major areas inspected action on previously identified items, receiving documentation for reactor reset holddown bolts & recirculation piping status DANIELSON, D. H. ERB, C. M. Region 3, Chicago, Office of the Director 80/05/08 App
- 9006200131 Forwards IE Insp Rept 50-373/80-15 on 800219-22,26-29,0304-07 & 19-22 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/09 2pp
- --8006200136 Notice of violation from insp 800219-22, 26-29, 0304-07 &
 - Region 3. Chicago, Office of the Director 80/05/09 4pp
- --B00A200141 IE Insp Rept 50-373/00-15 on 800215-22,2A-27,0304-07 & 19-22 Nuncompliance noted failure to have program to maintain cleanliness & inadaquate procedural requirements HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch MAURA,F. REIMANN,F Region 3, Chicago, Office of the Director 80/05/09 10pp
- 8006230055 Forwards IE Insp Repts 50-373/80-19 & 50-374/80-12 on 800401-03 & 15-17 No nancompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/13 2pp
- -8006230060 IE Insp Repts 50-373/80-19 & 50-374/80-12 on 800401-03 & 15-17 No noncompliance noted Major areas inspected rework procedures, receipt insp. weld rod control & action on grevious items Williams, C.C., JONES, C.E. Region 3, Chicago, Office of the Director 80/05/09 App
- B006240032 Forwards IE Insp Repts 50-373/80-23 & 50-374/80-15 on 900430-0501 No noncompliance noted FIORFLLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/16 2pp
- --8006240041 IE Insh Rents 50-373/80-23 & 50-374/80-15 on 800430-0501 No noncompliance noted Major areas inspected suppression pool mod 8 installation of radiation seals Williams, C c. NEISLER, J H Region 3, Chicago, Office of the Director 80/05/14 4pp
- 8006180547 Ack receipt of 800430 & 0515 ltrs providing addl clarification re actions taken to correct noncompliance noted in IE Insp Repts 50-373/80-04 & 50-374/80-03 FIORELILLO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/04 lp
- --B006iB0550 Responds to 800411 request for clarification relactions taken to correct noncompliance noted in IE Insp Repts 50-373/B0-04 & 50-374/B0-03 Engineering change notices will be identified in monthly A/E spec status rept PEOPLES.D.L. Commonwealth Edison Co. 80/04/30 4pp

- --8006180552 Responds to 800411 request for clarification relactions taken to correct noncompliance noted in IE Insp Repts 50-373/80-03 Engineering change notice status rept will be reviewed by AE for accuracy & completeness PEOPLES, D.L. Commonwealth Edison Co. 80/05/15 2pp
- 8006230104 Forwards request for info on BHR cracking of jet pump holddown beams, described in 1E Bulletin 80-07 YCUNG8LOOD, B J Procedures & Test Review Branch 80/06/04 3pp
- 8006250263 Ack receipt of 800529 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-373/80-12 & 50-374/80-08 FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06//1 1p
- --8006250266 Responds to NRC 800426 ltr re violation noted in IE Insp Repts 50-373/80-12 & 50-374/80-08 Corrective actions design instructions are being revised to provide clearer responsibilities & work procedures PEOPLES, D. L. Commonwealth Edison Co. 80/05/29 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234WPB requirement investigations conducted & closed at 46 listed facilities SEAY.J L Chemtron Corp , Tube Turns Div 80/06/06 3pp
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BMR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re afrquacy of applicable support structures General operating reactor review procedure & acceptance criteria anci EISENHUT, D O Division of Licensing 80/05/20 13pp
- 8006020515 Requests info re notile base metal mati spec type & grade, clad process type, electrode size & number of clad layers & heat input for each layer to define potential for cracking in reactor vessel notiles
 YOUNOBLOOD, 8 J Licensing Branch 1 80/05/22 2pp
- 8006230001 Summary of 800410 meeting w/Mart II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T M Containment Systems Branch 80/05/30 4pp
- 8006180278 Forwards "Mark II Design Assessment Rept, "Revision & Revision updates Chapter 6 re suppression pool water tempressionse PEOPLES, b L Commonwealth Edison Co 80/06/05 1p
- ---8006180281 "Mart II Design Assessment Rept." Revision 8 Commonwealth Edison Co 80/06/01 37pp
- S006190089 Forwards trip rest & summary of 800424 & 25 meeting w/ Sargent & Lundy in Chicago, IL re soil structure interaction BOURNIA.A Licensing Branch 1 80/06/05 3pp
- --8004190075 Trip rept & summary of B00424 & 25 meeting \(\omega/\text{Bargent & Lundy}\) in Chicago, IL re-soil structure interaction CHAN.S.P Structural Engineering Branch 80/06/03 3pp
- 8006250137 Forwards "For Comment" edition of NUREO-0619 Describes technical issues studies & analyses performed by CE Comments should be forwarded to NRC by 800707 H/o enci EISENHUT.D Q Division of Licensing 80/06/06 2pp.
- 8006230138 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to A Bournia Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/12 11pp
- 8006300453 Submits update of scheduled commercial syc dates for facilities reflecting delays & scheduled GL fuel load dates Stresses importance of continued licensing process for Byron & Braidwood PEOPLES, D. L. Commonwealth Edison Co. 80/06/20 2pp

- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed OA Program for Nuclear Generating Stations " Revised Revision II includes basis on which equivalent education requirements will be established PEOPLES, D L Commonwealth Edison Co 60/06/23 1p
- F Security, medical, emergency & fire protection plans
- 8006020294 Notifies that new telephone sys called Health Physics Natwork (HPN) has been installed at site Eqs intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER, J Q Region 3. Chicago, Office of the Director 80/04/18 2pp
- BOO5130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 bt Addl specific criteria for facilities under development EISENHUT, D G Division of Operating Reactors BO/04/25 61pp
- 8006030004 Notifies util that 800324 safeguards contingency plan needs revision & addl info Details of required addl info encl Encl withheld (ref 10CFR2 790) YOUNOBLOOD: B J Licensing Branch 1 80/05/23 2pp
- 8006180293 Forwards Revision I to draft emergency plan Emergency plan station annexes also encl PEOPLES, D L Commonwealth Edison Co 80/06/04 2pp
- --B0061B0324 Draft emergency plan annex * Commonwealth Edison Co 80/07/31 50pp
- --8006180347 Revision 1 to draft emergency plan # Commonwealth Edison Co 80/07/31 139pp
- BO06240490 Responds to NRC 800425, 30, 0901, 09 & 20 ltrs requesting addlinfo re guard training & qualification plans Requests that response Submittal date be extended to 800804 PEOPLES, D L Commonwealth Edison Co 80/06/18 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006180364 Forwards Amend 49 to FSAR, including responses to seven second round questions, voluntary test & response revisions PEOPLES, D. L. Commonwealth Edison Co. 80/06/05 ip
- --8006180369 Amend 49 to FBAR Oversize drawings encl * Communuealth Edison Co 80/06/05 1000pp
- @ Inspection reports. IE Bulletins & correspondence
- 8006040325 Forwards IE lnsp Repts 50-373/80-18, 90-374/80-11, 50-454/80-06, 80-445/80-06, 50-456/80-02 & 50-457/80-02 from meeting on 800328 No noncompliance noted KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/24 2pp
- --B006060333 IE lnsp Repts 50-373/80-18,50-374/80-11,50-454/80-06, 50-455/80-06, 50-456/80-02 & 50-457/80-02 from meeting on B00328 Areas inspected status of three stations under const FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ, E R , BARRETT, P A Region 3, Chicago, Office of the Director B0/04/14 App
- 8006130295 Forwards IE insp Repts 50-373/80-12 & 50-374/80-08 on 800312-14 & 18-19 & notice of violation FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8005130257 Notice of violation from insp on 800312-14 & 18-19 * Region 3, Chicago, Office of the Director 80/04/14 Ip
- ~~8006130259 IE Inep Repts SO-373/80-12 & 50-374/80-08 on 800312-14 & 18-19 Noncompliance noted deficient design control for small bare ejging suspension sys
 YIN. 1 T Region 3. Chicago. Office of the Director DANIELBON. D H Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/14 7pp
- 8006170786 Forwards 1E Insp Repts 50-373/80-20 & 50-374/80-13 on 800401-03 & 08 & notice of violation FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch, 80/04/26, 2pp
- ~-8004170744 Natice of violation from insp on 800401-03 & 08 * Region 3. Chicago, Office of the Director 80/04/22 2pp

- --8006170774 IE Insp Repts 50-373/80-20 % 50-374/80-13 on 800401-03 & 08 Noncompliance noted inadequate design control, lack of work procedures & lack of QA audits DANIELSON, D. H., FIN, I. T. Region 3, Chicago, Office of the Director 80/04/22 opp
- 9006190357 Forwards IE Insp Repts 50-373/80-21 & 50-374/80-14 on 800408-10 No noncompliance noted FIDRELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/07 2pp
- ---BOO6190366 IE Insp Repts 50-373/80-21 \$ 50-374/80-14 on 800408-10 No noncompliance noted Major areas inspected action on previously identified items, receiving documentation for reactor vessel holddown bolts & recirculation piping status DAMIELSON, D H. ERB.C H. Region 3, Chicago, Office of the Director 80/05/08 4pp
- B004230055 Forwards IE Insp Repts 50-373/80-19 & 50-374/80-12 on B00401-03 & 15-17 No noncompliance hoted FIGRELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch B0/05/13 2pp
- --8006230060 IE Insp Repts 50-373/80-19 & 50-374/80-12 on 800401-03 & 15-17 No noncompliance noted Major areas inspected rework procedures receipt insp.weld rod control & action on previous items
 HILLIAMS,C C , JONES,C E Region 3, Chicago, Office of the Director 80/05/09 6pp
- 8006240032 Forwards IE Insp Repts 50-373/80-23 & 50-374/80-15 on 800430-0501 No noncompliance noted FIGRELLI, G Region 3: Chicago. Reactor Construction & Engineering Support Branch 80/05/16 2pp
- ~-8006240041 IE Insp Repts 50-373/80-23 & 50-374/80-15 on 800430~0501 No noncompliance noted Major areas inspected suppression pool mod 8 installation of radiation seals HILLIAMB.C C . NEISLER.J H Region 3. Chicago, Office of the Director 80/05/14 App
- 8006180547 Ack receipt of 800430 & 0515 ltrs providing add1 clarification re actions taken to correct noncompliance noted in IE Insp Repts 30-373/80-04 & 50-374/80-03 FIORELLIA Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/04/04 ip
- ~-8006:80550 Responds to 8004:11 request for clarification relactions taken to correct noncompliance noted in IE Insp Repts 50-373/80-04 & 50-374/80-03 Engineering change notices will be identified in monthly A/E spec status rept PEQPLES.D L Commonwealth Edison Co. 80/04/30 4pp
- --B0061B0552 Responds to 800411 request for clarification relactions taken to correct noncompliance noted in IE Insp Repts 50-373/80-04 & 50-374/80-03 Engineering change notice status rept will be reviewed by AE for accuracy & completeness PEOPLES.D L. Commonwealth Edison Co. 80/05/19 Rpp
- BOO6230104 Forwards request for info on BWR cracking of jet pump holddown beams, described in IE Bulletin 80-07 YOUNGBLOOD, B J Procedures & Test Review Branch BO/06/04 3pp
- BOOG250263 Act receipt of BOO529 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-373/80-12 & 50-374/80-08 FIORELLI-0 Region 3, Chicago, Reactor Construction & Engineering Support Branch BO
- --8006250266 Responds to NRC 800426 ltr re violation noted in 1E Insp Repts 50-373/80-12 & 50-374/80-08 Corrective actions design instructions are being revised to provide clearer responsibilities & work procedures PEOPLES.D L Commonwealth Edison Co 80/05/29 Rpp
- S Reportable occurrences. LERs & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbous & 2-inch tees were mfg to A234WB requirement Investigations conducted & closed at 46 listed facilities SEAY.J. L. Chembron Corp., Tube Turns Div 80/06/96. 3pp

- DOCKET 50-376 NORTH COAST NUC PLANT

 G Adjudicatory correspondence
- 8006190132 Petition urging ASLB to hold evidentiary hearings to request applicant to show cause why application should not be dismissed due to lack of intention to build Requests costs by damages W/Certificate of Svc & supporting documents FERNDS.0 Citizens for the Conservation of Natural Resources, Inc 80/04/30 12pp
- --8006190154 Interim rept of Committee on Future Energy Alternatives in Puerta Rica, by Energy Engineering Board, Assembly of Engineering Supporting ducumentation enci * National Academy of Sciences 79/12/31 9pp
- BOO618015B Response in opposition to intervenor 0 Fernos BOO430 request for issuance of order to show cause why application should not be dismissed No time frame requirements exist for license processing W/Certificate of Svc AXELRAD, M Puerto Rico Electric Power Authority AXELRAD, H. Lowenstein, Newman, Reis, Azelrad & Toll 80/05/19 lipp
- 8006060577 Order denying 0 Fernos & Citizens for Conservation of Natural Resources 800430 petition requesting evidentiary hearings relack of intention to build ASLB has no authority to rule on motion for show cause order LINEBERGER.O., COLE.R.F., WOLFE.S.J. Atomic Safety and Licensing Board Panel 80/05/29 4pp
- 8006090302 Order directing applicant & NRC to provide memoranda by 800627 re intervenors' suspicion that applicant no longer intends to construct facility Intervenors may respond to NRC & applicant by 800718
 BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/06/04
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 800A230110 Advises DWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT.D G Division of Licensing 80/05/20. 13pp
- 8006200513 Forwards Round One requests for add1 info re reactor sys Request based on review of SRP & NRC guidance prior to TMI~2 accident SCHMENCER:A Licensing Branch 2 80/05/30 32pp
- 8006110307 Submits info to clarify conformance w/insp requirements of ASME code, Section 11, in response to NRC 800207 ltr re FSAR Code N-symbol has been applied to Quality Groups A&B components State of IL 730117 ltr encl ASMELL, D. L. Louisiana Power & Light Co. 80/05/02 Spp.
- --8006110316 Forwards IE Insp Rept 50-382/79-01 on 790109-12 No noncomptiance noted BEIDLE, W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/01/31 2pp
- ---BOOAii0325 IE Insp Rept 50-382/79-01 on 790i09-12 No nencompliance noted Major areas inspected const activities re GA/GC documentation of final setting 8 installation of reactor vessel & ASME. Class 3 code commitments. CROSSMAN, W A . STEWART, R C Region 4. Dalias, Office of the Director 79/01/31 App
- 8006250334 Forwards request for add1 info re power instrumentation & control flys for FBAR
 SCHWENCER.A Licensing Branch 2 80/06/10 3ipp
- 8006300637 Forwards Savannah River Lab preliminary draft review repts per 800613 telcon Info should assist in review M/o encl ROSA.F Power Systems Branch 80/06/20 ip
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for *mergency response facilities defined in 790913 itr Addl specific criteria for facilities under development EISENHUT, D.O. Division of Operating Reactors 80/04/25.
- 8006240635 Forwards request for add1 info for NRC review of 800129 safeguards contingency plan Enci withheld (ref 10CFR2 790).
 TEDESCO.R L Assistant Director for Licensing 80/06/09. 2pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006170283 Forwards Amend 9 to FSAR Amend includes small break LOCA analysis.responses to Hydrology Branch & GA Branch questions, changes to Section 2 2 3 1 3 2 & update of Table 1 7-1 Oversize electrical drawings encl ASHELL.D L Louisiana Power & Light Co 80/06/10 1p
- --B006170290 Amend 9 to application for OL Amend includes small break LOCA analysis, responses to Hydrology Branch & GA Branch questions, changes to Section 2 2 3 1 3 2 & update of Table 1 7-1 ASMELL, D.L. Louisiana Power & Light Co. 80/06/10 2pp
- --8006170293 Amend 9 to FSAR Oversize electrical drawings enci & Louisiana Power & Light Co 80/06/10 1400pp
- 800&180389 Certifies svc of Amend 9 to FSAR on 800&14 * Louisiana Power & Light Co 80/06/16 ip
- O Inspection reports, IE Bulletins & correspondence
- 8006300042 Forwards IE Carcular 80-05, "Emergency Diesel Generator Lubricating Dil Addition & Onsite Supply " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/04/01
- 8006090090 Forwards IE Insp Rept 50-382/80-08 on 800407-iO No noncompliance moted SEIDLE.W C Region 4, Dailas, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- --B008079097 IE Insp Rept 50~3B2/B0-0B on B00407-10 No noncompliance noted Major areas inspected const activities re safety-related cable pulling & terminations CROSSMAN,W A Region 4. Dalias. Reactor Operations Nuclear Support Branch KELLEY,D L , WESTERMAN,T F Region 4. Dalias. Office of the Director B0/04/22 App
- 8006170154 Forwards IE Insp Rept 90-302/80-08 on 600407-10 No noncompliance noted SEIDLE:N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- --8006170159 IE Inspire, Superior Of on 800407-10 No noncompliance noted Major areas inspected const activities safety-related cable pulling & terminations MELLEY,D L., STEWART,R C. Region 4, Dallas, Reactor Construction & Engineering Support Branch CROSSMAN,W A. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/04/22 4pp
- 8006040166 Ack receipt or 800328 ltr in response to NRC 791204 ltr. confirming mgt appraisal insp procedures Insp designed to determine how licensee manages licensed activities Following interviews w/personnel.findings will be sent to licensee STELLOV Office of Inspection & Enforcement. Office of the Director 80/05/06 2pp
- --8006040169 Advises that util has reviewed NRC 791204 ltr presenting performance appraisal Concern expressed to interviewing const personnel, biased regional inspectors & documenting nonregulatory aspects WYATT.J M Louisiana Power & Light Co 80/03/28 1p
- GO06040292 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Dperability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" enci SEYFRIT, K V Region 4, Dallas, Office of the Director 60/05/07 is.
- 8005050297 Responds to violation noted in IE Insp Rept 50-382/80-05 Corrective actions piping & subassemblies removed & each penetration vacuumed of debris Openings sealed for protection MCLENDON.G D Louisiana Power & Light Co 80/05/09 2pp
 - t 50-382/80-11 on 800429-0501 No eactor Operations Nuclear Support
 - -11 on BOO429-0501 No noncompliance rational staffing & overall
 - Region 4. Dallas: Office of the

- 8006230107 Responds to IC Sujletin 79-28 ie possible malfunction of NAMCO limit switches NAMCO limit switches are installed at facility Licensee has initiated program to locate, inspect & correct defective limit switches
 ASNELL, D.L. Louisiana Power & Light Co. 80/05/14 2pp
- 8006300060 Forwards IE Circular 80-12, "Valve-Bhaft-To-Actuator Key May Fall Out of Place When Mounted Below Horizontal Axis " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/14
- 8006110449 Ack receipt or 800509 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 90-382/80-06 BEIDLE.W C Region 4. Dailas. Reactor Construction & Engineering Support Branch 80/05/20 ip
- 5 Reportable occurrences. LERs & related correspondence
- 8006200024 Final Part 21 rept to mixed heat of steel supplied by UA Steel from which 4-inch olbows \$ 2-inch tees were mfg to A2344PB requirement Investigations conducted & closed at 46 listed facilities
 SEAY, J.L. Chemtron Corp., Tube Turns Div. 80/06/06. 3pp
- BOO6190313 Final rept of Significant Const Deficiency 7 re loose control element drive mechanism guide cones C-E completed corrective repairs during we ending BOO315 Guide cones were firmly locked in place, torqued & spot welded CRNICH. J. MILHISER, R. J., HART, J. Louisiana Power & Light Co 80/06/10 3pp
- 8006180384 Forwards final deficiency rept re loose control element drive mechanism guide cones. ABMELLD L. Louisiana Power & Light Co. 80/06/13 1p
- --B0061B0391 Final deficiency re loose control element drive mechanism guide cones C-E secured & tightened each guide cone to 40 ft.1b torque value Completed spot & tack welds visually inspected & approved CRNICH, J, MILHIESER, R J, HART, J Louisiana Power & Light Co 60/06/10 3pp
- A Application/construction stage documents & correspondence
- 8004040049 Ack recuipt of 800408 ltr describing results of util investigation of specific employee concerns GRIER.B H Region I. Philadelphia. Office of the Director 80/05/06 | 1p
- --800606095 Informs NRC that investigation of 139 items mentioned in util 790625 ltr have been completed Findings & actions taken re items investigated are available at const site & util general ofc CURTIS,N W Pennsylvania Power & Light Co 80/04/08 ip
- --8006060064 Discusses util efforts to encourage employee & const worker feedback re concerns about quality of design matl or workmanship at plant Personnel were sent questionnaire which revealed 139 specific items requiring investigation CURTIS.N W Pennsylvania Power & Light Co 79/06/25 2pg
- 8006i20387 Advises that util has consistently maintained positive attitude se archaeological work in const area Util has allowed surveying in 1967 & funded 1978 archaeological work Oilbert Associates now contracted to further survey area SMITH. If Pennsylvania, State of 80/05/19 ip
- 8006050435 Forwards request for add1 info re refueling platform transrails per review of facility application for OL YOUNGBLOOD.B J Licensing Branch 1 80/05/20 3pp
- B006120002 Summary of 800501 site visit to review reactor sys & instrumentation List of attendees encl STARK.R Licensing Branch i 80/05/20 3pp
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EIGENHUT, D © Division of Licensing 80/05/20 13pp
- BOOA060369 Discusses summary of Case Load Forecast Panel BO0320-21 sits visit to facilities re util scheduling methods & present problems THI impacts not included in schedule GC/GA reviews & documentation require 4 wks CURTIS.N W Pennsylvania Power & Light Co 8D/05/23 2pp

- 8006060618 Requests encl add1 info re instrumentation & control sys to complete review of application for DL YOUNGBLOOD, B J Licensing Branch 1 80/05/27 App
- 8006230001 Bummary of 800410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T M Containment Systems Branch 80/05/30 4pp
- 8008250163 Forwards "For Comment" edition of NUREO-0619 Describes technical issues, studies & analyses performed by QE Comments should be forwarded to NRC by 800707 N/o encl EISENHUT.D O Division of Licensing 80/06/06 2pp
- 8006110222 Forwards "Design Assessment Rept.Revision 2" Proprietary version withheld (ref 10CFR2 790) CURTIS.N 4 Pennsylvania Power & Light Co 80/06/09 2pp
- --8006110227 "Design Assessment Rept, Revision 2," nonproprietary version * Pennsylvania Power & Light Co 80/05/31 205pp
- 8006180621 Notification of 800613 meeting w/BWR Licensing Resolution Group in Bethesda. MD to discuss progress MILSON.J N Licensing Branch 1 80/06/09 10pp
- BOOASIODS89 Forwards request for add1 info re instrumentation & control sys YOUNDBLOOD, B J Licensing Branch 1 80/04/12 3pp
- 8006250321 Summary of 800514 meeting w/utils in Bethesda.MD re organization % objectives of BWR licensing resolution group Agenda % viewgraph encl WILEON.J N Operating Reactors Branch 4 80/06/17 11pp
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- BOO60203BO Notifies that Bureau of Radiological Health,FDA.has reviewed fraft suppl to DES,NUREG-0364 No applicable comments WEAVER.C L. HEW,Dept of, US Public Health Service BO/05/20 Ip
- --8006020382 Responds to NRC 730119 ltr re request for comments on draft EIS Project does not appear to represent hazard to public health & safety SEGGEL.R L. Health. Education & Welfare, Dept of 73/03/09 Ip
- 800612035) Forwards comments re draft EIS for facility Recommends that PA Fish Commission be given opportunity to comment on project
 KETCHUM.A @ Pennsylvania. State of 80/05/20 2pp
- 8004020399 Submits comments re DES draft suppl review Clean Water Act conditions & mgt practices re proposed dam encl Document should address flood hazard of spillway evertopping TRIESCHMAN.W E Army.Dept of 80/05/27 Jpp
- 8004030307 Comments on draft suppl to EIS re facility operation Provided that util implements mgt plans in consultation w/PA Fish & Game Commissions.no objections offered to const as proposed RAYHLESHEROER.J Interior.Dept of 80/05/29 3pp
- 8006060490 Forwards comments on draft suppl to DES re NUREO-0564 Encl drawings in Central Files only CURTIS.N W Pennsylvania Power & Light Co 80/05/29 15pp
- 8006030363 Forwards comments on draft suppl to draft E16 re operation of facilities, specifically Pond Hill Creek Reservoir DAVIS.R S Environmental Protection Agency 80/05/30 App
- 8006130308 Responds to NRC requests for comments re draft suppl to draft EIS Review indicates use of Cowanesque project currently under const would provide better water storage than building new reservoir LINDSAY.W W Federal Energy Regulatory Commission 80/06/10 2pp.
- 8006170503 Forwards comments on draft suppl to DES, add1 comments on DES & util news release Draft suppl to DES re Pond Hill Reservoir is inadequate & incomplete News release bulsters contention that need for plant was inadequately assessed MANN,D., SADE,T. Susquehanna Alliance 80/06/10 8pp

- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT, D G Division of Operating Reactors 80/04/25
- 8005070510 Notification of 800616 meeting w/util in Bethesda, MD to discuss NRC emergency preparedness requirements technical support ctr criteria & emergency response plan criteria STARK.R M Licensing Branch 1 80/05/20 3pp

G Adjudicatory correspondence

- 8006060487 Motion to reclassify Contentions 2.16 & 17 in public health & safety category Responds to NRC remaining interrogatories re witnesses & evidential documents Certificate of Svc & supporting documentation encl HALLIGAN.T J. Citizens Against Nuclear Dangers. 80/04/29 12pp
- 8006060486 Motion requesting that applicants be required to amend DES in form of supplemental publication that discusses consequences of sorious accidents Certificate of Svc encl Related correspondence HALLIGAN. T J Citizens Against Nuclear Dangers 80/04/30 5pp
- 8006060264 Add1 responses to applicants' & NRC interrogatories in compliance w/ASLB 800327 memorandum & order Includes discussion re Rn-222 releases during fuel cycle,por NEPA requirements W/Certificate of Svc Related correspondence JDHNSRUD, J H Environmental Coalition on Nuclear Power 80/05/01 15pp
- 8006120027 Supplemental answers to util first round of interrogatories Allegue radiological health effects of isotopes were underestimated due to reliance on southwest sector rather than northeast sector BCHULTZ.OR Susquehanna Environmental Advocates 80/05/01 4pp
- BOO6170328 Forwards response to first round discovery requests as supplement to applicant answers to Environ Coglition on Nuclear Power Certificate of Svc and BNAPP.B A Pennsylvania Power & Light Co 80/03/01 3pp
- 8006170733 Response in apposition to Citizens Against Nuclear Danger 800427 & 30 motions & replies to interrogatories Contentions remain litigable under NEPA Policy re accident analysis not yet changed Certificate of Svc encl SILBERG, J E Pennsylvania Power & Light Co SILBERG, J E Allegheny Electric Cooperative. Inc SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/03/14 6pp
- 8006060377 Suppl to responses to applicants' interrogatories Intervenor 800211 response to applicants' 800204 motion re Contention 4 should be included as integral part of responses to interrogatories W/Certificate of 8vc Related correspondence JOHNSRUD. J H Environmental Coalition on Nuclear Power 80/05/20
- 8006090002 Response to ALAB-593 No substantial changes have been made by rulings cited in ALAB-593 intervenor is unable to respond to interrogatories due to continuous procedura) harrassment by NRC Certificate of Svc encl KEPFORD, C Environmental Coalition on Nuclear Power 80/05/30
- 8006180262 Requests to make limited appearance statement at licensing prehearing BRODKEY, J. R. Affiliation Unknown 80/05/30 1p
- 8006180311 Response to ASLAB 800321 memorandum & order ALAB-393 re Environ Coalition on Nuclear Power allegations of extreme harassment in discovery Intervenor has not provided valid basis for blanket protective orders Certificate of Svc encl CUTCHIN.J M Hearing Branch 3 80/06/12 15pp
- 8005190484 Response to ASLAB 800521 memorandum & order ALAB-573, requesting Environ Coalition on Nuclear Power to inform ASLAB of extent of relief sought Intervence 800530 request must be dismissed as most Certification of Svc encl TRAVIESO-DIAZ Pennsylvania Power & Light Co TRAVIESO-DIAZ Allegheny Electric Cooperative, Inc TRAVIESO-DIAZ Shaw, Pittman, Potts & Troubridge 80/06/13 12pp
- 8006260283 Memorandum & order grouping Citizens Against Nuclear Danger Contentions 2.16 & 17 Wenviron issues denying intervenor requests for supplement to DES, for clarification & for extension BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/06/24

- G Inspection reports. IE Bulletins & correspondence
- 8006020293 Forwards IE Insp Rept 50-387/80-03 on 800304-07 No noncompliance noted CARLEON, R. T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80/04/11 2pp
- --8006020259 IE Insp Rept 50-387/80-03 on 800304-07 No noncompliance noted Major areas inspected preservice insp activities & recirculation sys mod TRIPP, L. E. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch MCSREARTY, R.A. Region 1. Philadelphia, Office of the Director 80/03/20 App
- 800A090283 Forwards IE Insp Rept 50-387/80-08 of 800416 mgt meeting CARLSQN.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/07 ip.
- --8006090277 IE insp Rept 30-387/80-08 of 800416 mgt meeting Areas discussed quality-related activities during const & preoperational testing CARLSON, R T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch MCCAUCHY, R W , CALLOR, W Region 1, Philadelphia, Office of the Director 80/05/08 2pp
- 8006240569 Act receipt of 800417 ltr informing NRC of steps talen to correct violations noted in IE Insp Rept 50-387779-20 CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/29 ip
- --8006240575 Responds to NRC 800304 ltr re violations noted in IE Insp Rept 50-387/79-20 Corrective actions:reviewed past practices & inspector assessment of adequacy & directed GA organization to improve procedures BABOL.A R Pennsylvania Power & Light Co. 80/04/17 Spp
- --8006240579 Forwards IE Inap Rept 50-387/79-20 on 790726-27,0802.09 & 23,1029-30,1102 & 06-09 & notice of violation CARLEON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/04 2pp
- --8006240581 Notice of violation from insp on 790724-27,0802,09 & 23, 1029-30,1102 & 06-09 * Region i: Philadelphia. Office of the Director 80/03/03 ip
- --B006240584 IE Insp Rept 50-387/79-20 on 790726-27.0802.09 & 23,1029-30, 1102 & 06-09 Nuncompliance noted failure to provide independence to persons performing OA functions OAOE, L. Region I. Philadelphia. Office of the Director EBNETER, 9 Region I. Philadelphia, Reactor Construction & Engineering Support Branch B0/03/03. 1App
- 8 Reportable occurrences, LERs & related correspondence
- 800&120102 Ack receipt of 800430 ltr re PGCC cable connector deficiency Awaiting Jul 1980 final rept. CARLEGN.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/14 ip
- --8006120106 Advises that final deficiency rept re damaged PGCC cable connectors will be delayed Util & Bechtel are still evaluating cause & corrective actions Final rept anticipated in Jul 1980.

 CURTIS,N W Pennsylvania Power & Light Co 80/04/30 2pp
- 8006200183 Ack receipt of 80041B final deficiency rept re Cutler Hammer E-30 pushbutton switches Rept will be reviewed & evaluated CARLSON.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/19 ip

- BO06250397 Ack receipt of 800520 interim deficiency rept re use of isometrics to locate supports CARLSGN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 IP
- 8006250414 Ack receipt of 800523 interim deficiency rept re Hilti shell-type expansion anchors CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 IP
- 8006300041 Ack receipt of 800519 interim deficiency rept re American Marming & Ventilation, Inc dampers CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 ip
- 8006200163 Update to 800201 deficiency rept re unauthorized welding of attachment to reactor pressure vessel Caused by human error & unclear const drawings Craftsmen & foremen instructed that welding & burning on pressure vessel is prohibited CURTIS.N W Pennsylvania Power & Light Co 80/06/13 2pp
- 8006200171 Forwards final rept of deficiency on Limitorque motor operated valve stem nut staking CURTIS,N W Pennsylvania Power & Light Co 80/06/16 2pp
- --8006200179 final rept for Limitorque motor operated valve stem lock nut staking All suspect valves inspected & staked Ltrs sent to all suppliers informing of potential problem POSER, E. B. HOLLINGSHAUS, H., BURDEN, H. Bechtel Power Corp (subs of Bechtel Corp.) BO/OS/13 Spp
- 8006200366 Forwards final deficiency rept re failure to stake stem lock nuts when installing Limitorque motor operators on valves Suspect valves were identified 8 measures taken to inspor stake valves CURTIS.N W Pennsylvania Power & Light Co 80/06/16 7pp
- 8006270321 Interim deficiency rept re small diameter pipe bent in field, exceeding allowable ovality tolerance values Caused by bending method Criteria will be established for personnels setting limits for ovality & conditions for acceptance GURTIS.N W Pennsylvania Power & Light Co 80/06/20 2pp
- 8006270342 Notifie's of Potential Deficiencies ER 100450 & ER 100508 re States Co sliding links Failure occurs in form of crack between threaded screwhole & side of U-shaped link Will advise of date of final rept CURTIS, N W Pennsylvania Power & Light Co 80/06/23 2pp
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 83034060047 Ack receipt of 800408 ltr describing results of util investigation of specific employee concerns ORIER, B H Region 1. Philadelphia, Office of the Director 80705706 ip
- ---800&0&0055 Informs NRC that investigation of 139 items mentioned in util 790&25 ltr have been completed Findings & actions taken re items investigated are available at const site & util general ofc CURTIS.N W Pennsylvania Power & Light Co 80/04/09 ip
- --8006060064 Discusses util efforts to ancourage employee & const worker feedback re concerns about quality of design,matl or workmanship at plant Personnel were sent questionnaire which revealed 199 specific items requiring investigation CURTIS,N W Pennsylvania Power & Light Co 79/06/25 2pp
- 8006120397 Advises that util has consistently maintained positive attitude re archaeological work in const area Util has allowed surveying in 1967 & funded 1978 archaeological work Gilbert Associates now contracted to further survey area.

 BMITM I F Pennsylvania. State of 80/05/19 1p
- 8005050435 Forwards request for add1 info re refueling platform crane rails per review of facility application for GL YOUNOSLOOD, B J Licensing Branch 1 80/05/20 3pp
- 8006120002 Summary of 800501 sits visit to review reactor sys & instrumentation List of attendees encl BTARK.R Licensing Branch 1 80/05/20 3pp
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp

- B006060369 Discusses summary of Case Load Forecast Panel 800320-21 site visit to facilities re util scheduling methods & present problems TMI impacts not included in schedule QC/0A reviews & documentation require 4 wks
 CURTIS,N W Pennsylvania Power & Light Co 80/05/23 2pp
- B006060618 Requests encl addi info re instrumentation & control sys to complete review of application for OL YOUNGBLOOD, B J Licensing Branch 1 80/08/27 App
- 8006230001 Summary of 800410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T M Containment Systems Branch 80/05/30 4pp
- 8006250163 Forwards "For Comment" edition of NUREO-0619 Describes technical issues, studies & analyses performed by GE Comments should be forwarded to NRC by 900707 M/o encl EISENHUT, D & Division of Licensing 80/06/06 2pp
- BOOG110222 Forwards "Design Assessment Rept.Revision 2 " Proprietary version withheld (ref 100RR2 790) CURTIS.N.W. Pennsylvania Power & Light Co. BO/06/09 2pp.
- --8006110227 "Design Assessment Rept, Revision 2." nonproprietary version * Pennsylvania Power & Light Co 80/05/31 205pp
- 8006300589 Forwards request for add1 info re instrumentation & control sys YOUNOBLOOD, 8 J Licensing Branch 1 B0/06/12 3pp
- D NRC Braft/Final Environmental Statements, suppls & correspondence
- B006020380 Notifies that Bureau of Radiological Health.FDA.has reviewed draft suppl to DES.NUREG-0564 No applicable comments MEAVER.C L HEW.Dept of, US Public Health Service 80/05/20 ip
- ---8006020382 Responds to NRC 730119 ltr re request for comments on draft E18 Project does not appear to represent hazard to public health & safety SEOGEL,R L. Health, Education & Walfare, Dept of 73/03/09 ip
- 8006120351 Forwards comments re draft EIS for facility Recommends that PA Fish Commission be given apportunity to comment on project KETCHURLA O Pennsylvania. State of 80/05/20 2pp.
- 800&020399 Submits comments re DES draft suppl review Clean Water Act conditions & mgt practices re proposed dam and Document should address flood hazard of spillway overtopping TRIESCHMAN.W E Army.Dept of 80/05/27 3pp
- 8006030307 Comments on draft suppl to EIS re facility operation Provided that util implements mgt plane in consultation W/PA Fish & Game Commissions no objections affered to const as proposed RATHLESHERGER, J Interior, Dept of 80/05/29 3pp.
- 8006060490 Forwards comments on draft suppl to DEG re NUREQ-0564. Encl drawings in Central Files only CURTIB-N W. Pennsylvania Power & Light Co 80/05/29 15pp
- 6006030363 Forwards comments on draft suppl to draft EIS re operation of facilities, specifically Pond Hill Creek Reservoir BAVIS,R S Environmental Protection Agency 80/05/30, App
- 8006130308 Responds to NRC requests for comments re draft suppl to draft EIS Review indicates use of Cowanesque project currently under const would provide better water storage than building new reservoir LINDSAY,W W Federal Energy Regulatory Commission 80/06/10 2pp
- 8006170503 Forwards comments on draft suppl to DES, addl comments on DES \$ util news release Draft suppl to DES re Pond Hill Reservoir is inadequate & incomplete News release bolsters contention that need for plant was inadequately assessed. MANN.D , SADE.T Susquehanna Alliance BD/06/10 Spp
- F. Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT. D O Division of Operating Reactors 80/04/25 61pp

- 8005070510 Notification of 800515 meeting w/util in Bethesda, MD to discuss NRC emergency preparedness requirements technical support ctr criteria & emergency response plan criteria BTARK.R M Licensing Branch I 80/05/30 3pp
- O Adjudicatory correspondence
- 8006060487 Motion to reclassify Contentions 2.16 & 17 in public health & safety category Responds to NRC remaining interrogatories re witnesses & evidential documents Certificate of Svc & supporting documentation encl HALLIOAN.T J Citizens Against Nuclear Dangers 80/04/29 12pp
- 8006060486 Motion requesting that applicants be required to amend DES in form of supplemental publication that discusses consequences of surface accidents Certificate of Svc and Related correspondence
 HALLIGAN.T J Citizens Against Nuclear Dangers 80/04/30 5pp
- 8006060264 Add1 responses to applicants' & NRC interrogatories in compliance w/ASLB 800327 memorandom & order Includes discussion re Rn-222 releases during fuel cycle, per NEPA requirements W/Certificate of Suc Related correspondence JOHNSRUD. J H Environmental Coalition on Nuclear Power 80/05/01.
- BOOGIZOOZ/ Supplemental answers to util first round of interrogatories
 Alleges radiological health effects of isotopes were
 underestimated due to reliance on southwest sector rather
 than northeast sector
 BCHULTZ, O. R. Susquehanna Environmental Advocates 80/05/01 4pp
- 8006170328 Forwards response to first round discovery requests as supplement to applicant answers to Environ Coalition on Nuclear Power Certificate of Svc encl
 SNAPP.B A Pennsylvania Power & Light Co 80/05/01 3pp
- SOO6170733 Response in opposition to Citizens Against Nuclear Danger 800429 & 30 mations & replies to interragatories Contentions remain litigable under NEPA Policy re accident analysis not get changed Certificate of Svc encl SILBERO, J E Pennsylvania Power & Light Co SILBERO, J E, Alleghent Electric Cooperative, Inc. SILBERO, J E Shaw, Pittman, Potts & Trowbridge 80/05/14 App
- 8006050377 Buppl to responses to applicants' interrogatories Intervenor B00211 response to applicants' 800204 motion re Contention 4 should be included as integral part of responses to interrogatories W/Certificate of Byc Related correspondence JBNNSRND, J H Environmental Coalition on Nuclear Power 80/05/20 209
- 8006090002 Response to ALAB-593 No substantial changes have been made by rulings cited in ALAB-593 Intervenor is unable to respond to interrogatories due to continuous procedural harrassment by NRC Certificate of Svc enc!
- 8006180262 Requests to make limited appearance statement at licensing prehearing BRODNEY, J.R. Affiliation Unknown 80/05/30 ip
- 8006(803)1 Response to AGLAB 800521 memorandum & order,ALAB-593,re Environ Coalition on Nuclear Power allegations of extreme harassment in discovery intervenor has not provided valid basis for blanket protective orders Certificate of Evc encl CUTCHIN,J.M. Hearing Branch 3 80/06/12 15pp
- 8005190484 Response to ABLAB 800521 memorandum & order ALAB-593, requesting Environ Coalition on Nuclear Power to inform ABLAB of extent of relief sought Intervenor 800530 request must be dismissed as moot Certification of Svc encl TRAVIESO-DIAZ Pennsylvania Power & Light Co TRAVIESO-DIAZ Allegheng Electric Cooperative, Inc. TRAVIESO-DIAZ Shaw, Pittman, Potts & Troubridge 80/06/13 12pp
- 8006260283 Memorandum & order grouping Citizens Against Nuclear Danger Contentions 2.16 & 17 w/environ issues denying intervenor requests for supplement to DES, for clarification & for extension BECHMOEFER.C Atomic Safety and Licensing Board Panel 80/06/24, 7pp
- S Reportable occurrences, LERs & related correspondence
- 8006200183 Ack receipt of 800418 final deficiency rept re Cutier Hammer E-30 pushbutton switches Rept will be reviewed & evaluated CARLSON,R T Region 1. Philadelphia. Reactor Construction & Englowering Support Branch 80/05/17 Ip

- BOOG20D232 Ack receipt of 800430 interim deficiency rept re cable pulling activities
 CARLEDONR T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 60/05/20 ip
- 8006200200 Ack receipt of 800430 interim deficiency rept re separation criteria for electrical equipment Rept will be reviewed & evaluated CARLGON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/21 lp
- 80040703ii Interim deficiency rept to pipe supports to containment liner plate Installation of supports w/o having civil design group review structural adequacy resulted in overstressing liner plate CURTIS.N W Pennsylvania Power & Light Co 80/05/29 2pp
- 8006250399 Ack receipt of 800320 interim deficiency rept re use of isometrics to locate supports CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 IP
- 8006290414 Ack receipt of 800523 interim deficiency rept re Hilts shell-type expansion anchors CARLEON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 IF
- 8006308041 Ack receipt of 800519 interim deficiency rept re American Warming & Ventilation Inc dampers CARLEON R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 Ip
- 8006200171 Forwards final rept of deficiency on Limitorque motor operated valve stem but staking CURTIS:N W Pennsylvania Power & Light Co 80/06/16 2pp
- --8006200179 Final rept for Limitorque motor operated valve stem lock not staking All suspect valves inspected & staked Ltrs sent to all suppliers informing of potential problem POSER.E B. HOLLINGSHAUS.H. BURDEN.H Bechtel Power Corp (subs of Bachtel Corp.) 80/05/15 5pp
- 8006200366 Forwards final deficiency rept re failure to stake stem lock nuts when installing Limitorque motor operators on valves Buspect valves were identified & measures taken to inspor stake valves

 CURTIS.N W Pennsylvania Power & Light Co 80/06/i6 7pp
- 8006270321 Interim deficiency rept re small diamater pipe bent in field, exceeding allowable ovality tolerance values Caused by bending method Criteria will be established for personnel, satting limits for ovality & conditions for acceptance CURTIS,N W Pennsylvania Power & Light Co 80/06/20 2pp
- 8006270342 Notifies of Potential Deficiencies ER 100450 & ER 100508 re States Co sliding links Failure occurs in form of crack between threaded screwhole & side of U-shaped link Hill advise of date of final rept CURTIS,N
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8006160232 Notification of contract execution Mod 1 to "Engineering Assistance re Antitrust Hearings for St Lucie 2 Nuclear Generating Station " Contractor JR Lundberg & Associates GLAODLA, A F Administrative Contracts Branch NRC-03-80-158 80/03/30 1p
- --8006160234 Hod 1.extending period of performance to "Engineering Assistance re Antitrust Hearings for St Lucie 2 Nuclear Generating Station"
 BOUGHERTY, D. Technical Assistance Contracts Branch NRC-03-79-158 80/03/30 tp
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify immlementation plan presented in Section 4 of NUREO-0577 re uacy of applicable support structures Ceneral operating for review procedure & accupitance criteria encl.

 HUT, D O Division of Licensing 80/05/20 13pp
 - ds application to amend CPPR-144, transferring partial cility & site to City of Griando, FL & Griando in Info for antitrust review also encirida Power & Light Co 80/06/13 ip

- --8006170273 Application to amond CPPR-144, transferring partial cw-f's' of facility & site to City of Orlando.FL & Orlando Utils Commission Supportive Vinencial math, contracts & amond fee encl ADDMAT, & A Florida Power & Light Co ADAMS, N S , NILLER, G M Orisando.FL 80/06/13 387pp
- F Security, medical, emergency & fire protection plans
- 8006190301 Forwards security plan.Revision 2 Plan withheld (ref 10CFR2 790) UHRIO.R E Florida Power & Light Co 80/06/10 1p
- 8006250203 Forwards safeguards contingency plan Revision Lin respects to NRC 600418 request for addl info Revision withheld (ref 10CFR2 790)
 UHRIO,R E Florida Power & Light Co 80/06/19 ip
- I Financial information
- 8006170267 Forwards application to amend CPPR-144, transferring partial ownership of facility 8 site to City of Orlando. FL & Orlando Utils Commission Info for antitrust review also encl UHRIO,R E Florida Fower & Light Co 80/06/13 ip
- ---8006170273 Application to amend CPPR-144, transferring partial cardets of facility & site to City of Orlando.FL & Orlando Utils Commission Supportive financial math.contracts & amend fee enci
 ABOMAT.E A Florida Power & Light Co ADAMS.M 8 . HILLER.Q M Orlando.FL 80/06/13 387pp
- 8006230578 Forwards Parts A & B of info requested in Reg Quide 9 2 J*fa consists of SEC prospectus, annual rept, rate schedules, interchange agreements, spinning & installed receive info & maint schedules Info available in Central Files UHRIG,8 E Florida Power & Light Co 80/06/18 1p
- J Insurance & indemnity information
- 8006030421 Forwards Endorsement 35 to NELIA Policy NF-227 FIELDER. J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Irc Div. 80/05/29 * 2pp
- 8006160113 Forwards Endorsement 28 to MAELU Policy MF-88 FIELDER: J Marsh & McLennan, Inc , M & M Nuclear Consultants, inc DIV 80706/09 2pp
- M Antitrust correspondence
- 8006/70493 Forwards executed settlement agreement between City of Orlando.FL,Orlando Utils Commission & util providing for transfer of 6 08951% ownership share of facility to Utils Commission Application for NRC approval will be submitted BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/06/12 ip
- ~-8006170499 Settlement agreement between City of Orlando, FL. Orlanto
 Utils Commission & util providing for transfer of 6 08951X
 ownership share to Utils Commission Release & Certificate
 of Svc enc!
 # Orlando Utilities Commission ADAMS, M S Orlando, FL #
 Florida Power & Light Co 80/06/05 23pp
- 8006170267 Forwards application to amend CPPR-144, transferring partial ownership of facility & site to City of Orlando, FL & Orlando Utils Commission info for antitrust review also encl UHRIO,R E Florida Power & Light Co 80706/13 ip
- --8006170273 Application to amend CPPR-144, transferring partial cunffits of facility & site to City of Orlando.FL & Orlando Utils Commission Supportive financial math.contracts & amend fits encl ADDMAT, E. A. Florida Power & Light Co. ADAMS, M.S. MILLER.O M. Orlando.FL 80/06/13 387pp
- 8006240137 Notice by Orlando Utils Commission to withdraw interventles & request to institute proceeding re Commission 780727 order City of Orlando, petitionor & util 800606 settlement resolved issues W/affidavit & Certificate of Svc WISE.W C Orlando,FL 80/06/20 4pp
- 8006240468 Notifies that antitrust info submitted 800613 re City of Orlando.FL & Orlando Utils Commission is acceptable for docketing & distribution NICKOLSON,P Utility Finance Branch 80/06/20 ip

- --8006240473 Ack recoipt of antitrust info received 800613 re City of Orlando.FL & Orlando Utils Commission Requests that appropriate notice be published as soon as possible NICHOLSON.P Utility Finance Branch 80/06/20 Ip
- 8004300328 Forwards info re util 800405 application seeking amend of CP to include City of Orlando,FL & Orlando Utils Commission as co-owners of unit Data sent to afford BDJ opportunity to render advice per 1954 Atomic Energy Act W/o encl
 SHAPAR,H K Office of the Executive Legal Director 80/06/26 1p
- O Inspection reports, IE Bulletins & correspondence
- B006050423 Forwards IE Insp Rept 50-389/80-03 on 800402-04 No noncompliance noted MURPHY, C E. Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/04/25 2pp
- --8006050425 IE Insp Rept 50-389/80-03 on 800402-04 No mancompliance noted Major areas inspected const progress,inspector failowup,licensee identified items & IE Bulletins 79-02, 79-25 & 79-28

 RAUSCH.J K Region 2, Atlanta, Reactor Construction & Engineering Support Branch BRADLEY,R D Region 2, Atlanta, Office of the Director 80/04/24 6pp
- 8006170789 Forwards IE Insp Rept 50-389/50-04 on 800408-11 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp
- ---8006170774 IE Insp Rept 50-389/80-04 on 800408-11 No noncompliance noted Major areas inspected welding activities, radiographic insp, magnetic particle insp & followup of noncompliance HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch VANDOURN, P K Region 2. Atlanta, Office of the Director 80/04/30 5pp
- 8006060500 Forwards IE Bulletin 80-ii. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Bupport Loads" and O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- 8006040274 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09
- 800630010/ Forwards IE Circular 80-11, 'Emergency Diesel Generator Lube Dil Cooler Failures " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- 8006040013 Ack receipt of 800118,0321 % 0501 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-35,50-251/79-35,50-365/79-33 % 50-389/79-22 MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 1p
- --B004040021 Responds to NRC 791219 ltr re violations noted in IE Insp Repts 50-250/79-35,50-251/79-35,50-335/79-33 & 50-389/79-22 Corrective actions GA procedures will be revised w/full compliance achieved by 800/31 UHRIG.R E Florida Power & Light Co 80/05/01 1p
- --8004040025 Responds to NRC 791219 & 800220 ltrs re violations noted in IE insp Repts 50-250/79-35.50-251/79-35.50-335/79-33 & 50-389/79-22 Corrective actions GA procedures will be revised re implementation of 10CFR21 UHRIG.R E Florida Power & Light Co 80/03/21 3pp
- S Reportable occurrences, LERs & related correspondence
- 8006160073 Forwards PNG-II-80-104 re 800611 loss of component cooling water to reactor coolant pumps NRC will supplement BL Spiegel Dec 1970 testimony re loss of cooling water to cartridge seal assembly PATON,W D Hearing Branch 4 80/06/13 1p
- --B006160077 PND-II-B0-104 on B00611, unit experienced loss of componet coaling water to reactor coalant pumps Caused by control solenoid failure on isolation valves Cooling water restored Investigation underway Press release will be issued ELROD.S., GUICK, D.R. Region 2, Atlanta, Office of the Director B0706/11 1p

- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 i3pp
- 8006300391 Forwards revised responses to Questions 031 127.040 60 & 031 127 of NRC 770801 ltr re seismic qualification of Class IE electrical equipment Repts re cable samples & IEEE-323-1974 qualification encl MILLS.L M Yennessee Valley Authority 80/06/23 10pp
- ---8006300397 'Delphi Preumatic Test Procedure " Comsip.Inc . Delphi Systems Div 75/06/18 2pp
- ---8006300400 "Radiation Testing of Cell Number 685,Final Rept " WILLIS,D E IRT Corp 79/08/23 7pp
- --B0063004UY 'Seismic Vibration Test of E10 Series Transmitters "
 SEARS.J A . MCCASLAND, K . RAMSELL, R Acton Environ Testing Corp
 76/03/22 30pp
- --8006300414 "Test Procedure for Seismic Vibration Qualification Test of E10 Beries MCA/RRW Transmitters" SEARS.J A . MCCASLAND.K Q Acton Environ Testing Corp 73/09/30 2550
- --8006300422 "Gage & Differential Pressure Transmitters Type E10 Series "
 BCHREINER, W . CASAUBON, H . TOLF, M L Acton Environ Testing Corp
 73/10/31 10pp
- --8006300429 "Gualification Test of Electrical Cables Under Simulated LDCA/DBE By Sequential Exposure to Environs of Radiation, Thermal Aging, Steam 3 Chemical Spray "
 * Isomedix. Inc (subs of Maesfield Enterprises, Inc)
 78/06/30 42pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT.D G Division of Operating Reactors 80/04/25 61pp
- B004040294 Forwards add1 info to training & qualification plan Info withheld (ref 10CFR2 790) MILLS.L M Tennessee Valley Authority 80/06/02 2pp
- O Inspection reports, IE Builetins & correspondence
- 8006030592 Forwards IE Insp Rept 50-390/80-09 on 800219-0331 No noncompliance noted LEWIS:R C Region 2. Atlanta: Reactor Operations Nuclear Support Branch 80/04/21 2pp
- ---8004030393 IE Insp Rept 30-390/80-09 on 800219-0331 No noncompliance noted Major areas inspected const verification, sys transfers & inspector familiarization DANCE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch MCDONALD.J A Region 2. Atlanta, Office of the Director 80/04/21 3pp
- 8006160200 Forwards IE Insp Repts 50-390/80-11 & 50-391/80-08 on 800409-11 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/04/30 2m
- --8004160206 IE Insp Repts 50-390/80-11 & 50-391/80-0B on 800409-11. No moncompliance noted Major areas inspected pipe supports w/concrete expansion bolts per IE Bulletin 79-02 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch MDDENOS.L. Region 2. Atlanta, Office of the Director E0/04/29 5pp
- 8006060159 Forwards IE Bullotin 90-ii, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl.

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08

- 8005040257 Forwards IE Bulletin 80-12, "Decay Maat Removal Sys
 Operability "No written response required IE Info Notice
 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse
 Unit 1 While in Refueling Mode" ench
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09
- BOO5190246 Forwards IE Insp Repts 50-390/80-10 & 50-391/80-07 on 800408-11 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/09 2pp
- --B006190257 IE Insp Repts 50-390/80-10 & 50-391/80-07 on B00408-11 No noncompliance noted Major areas inspected preservice insp. welding records & worker concerns HERDT. A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 018480.E M , COLEY, J L Region 2, Atlanta, Office of the Director B0/05/08 7pp
- 8005120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Dil Cooler Failure: " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13 3ss
- 8006250212 Forwards IE Insp Repts 50-390/80-12 & 50-391/80-09 on 800422-24 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8004230215 IE Insp Repts 50-390/80-12 & 50-391/80-09 on 800422-24 No noncompliance noted Major areas inspected 10CFR30 59 items. IE bulletins & circulars.QA audits & general const activities CANTRELLES Region 2. Atlanta. Reactor Construction & Engineering Support Branch THOMAS.M Region 2. Atlanta. Office of the Director 80/03/14 4pg
- 8006230030 Ack receipt of 800601 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/80-05 & 50-391/80-04 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --B006230033 Responds to NRC 800324 ltr re violations noted in IE Insp. Repts 50-390/80-05 & 50-391/80-04 Corrective actions angineering unit supervisors directed to develop insp. Programs for all safety-related features re fillet welds. MILLS, L. M. Tennessee Valley Authority. B0/05/23 3pp.
- 8006130246 Forwards requests for relief from ABHE Section XI preservice & inservice insp requirements for facility TVA will revise greservice & inservice insp program to reflect exceptions Requests comments by 800701 MILLS,L M Tennessee Valley Authority 80/06/09 14pp
- 8006240260 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequoyeb & Natts Bar is provided by redundant heaters & tank involation HILLS.L M Tennessee Valley Authority 80/06/07 8pp.
- BOO6i60054 Forwards response to NRC 800502 ltr re violations noted in IE Insp Rept 50-390/80-08 Corrective actions labrication of valves verified & data sheets revised to indicate valve stems Employees instructed & GC procedure addendum issued MILLS.L N Tennessee Valley Authority 80/06/10 3pp
- 8006270206 Responds to NRC 800527 ltr re violations noted in IR Insp Rept 50-390/80-13 Corrective actions procedure to clarify design intent for flushing instrument sensing times being prepared & drawing discrepancies corrected MILLS.L.M. Tennessee Valley Authority 80/06/23 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006030392 Forwards final deficiency rept re temp affect on main steam safety valve setpoint MI(LS.L H Tennessee Valley Authority 80/05/27 ip

- ~-8004040298 First interim deficioncy topt to safety injection 1 flow Train 8 cold log injection rate found to be only 4,000 gpm, compared to required 4,500 to 5,000 gpm limited tost completed to determine limitation of flow control * Tennessee Valley Authority 807097.00 lp
- --BOOOOOOO final interim deficiently tent to MHR pump motor ove RHR pump motors exceeded allowable over factor of 1 15 during low head operational modes flow restrictions added in each RHR pump hot log & cold log injection headen # Tennessee Valley Authority ROCON/40 1p
- Q006060484 Forwards Final deficiency tent to shock arrestor strussembly interference
 MILGAL M Tennessee Volley Authority 80/05/70 1p
- --ROQ4040409 final deficiency rept re-shock arrestor strut asseminterference Assembly does not provide sufficient clearance for arrestor to function freely when installed at off-axis angle greater than Di-degrees Assemblies will be replaced a Telinessee Valley Authority 80/05/30 Ip
- 8006110036 Forwards final deficiency rept re Ruskin fire dampers MHLB.L M. Tennessee Valley Authority 80768703 in
- ~~BOOM110043 Final deficiency rept re Huskin file dampers Rushin daveloped alternate fir providing positive stop for spring h snap-in strip ensuring complete closure Hods will be completed by (800610 hawings one) * Tannessee Valley Authority (8070670) (App
- BOOAL70929 Third interim deficiently tent re-control rod drop even yielding less conservative DNBRs Review of corrective actions recommended by Restinghouse underway Next rept to be submitted by BOO703

 MELLS/L M Tennessee Valley Authority BO/06/06 Ip.
- B006170396 Forwards final deficiency rept re inchirect bore in Dri transmitter boss MILLB.L.M. Tennessee Valley Authority (10/06/06) ip
- --8006170605 Final deficiency reptile incorrect bare in Dravo transcess Five bosses out of 40 Pound to be deficient riow restrictor installed between buss & root valve to Isali flow Future bosses will be examined prior to Installation HILLB.L.H. Tennesses Valley Authoristy 80/06/06 2pp
- GOOGLYOGS Forwards revision to 800007 final deficiency rapt re to affect of main steam valve setpoint HILLBIL. M. Tennessee Valley Authority 80706711 ip
- --8004170672 Revision to 600987 final deficiency rept re temp effe main steam valve setpoint heating, vestilation & air conditioning sys for valve rooms being modified to provide narrower temp range of 60 120 ft. * Tennessee Valley Authority 50/06/11. ip
- BO061903B5 Fourth interim deficiency rept re surface cracks in look steam generator Hestinghouse corrective actions reviewed to appropriate preventive actions taken Next rept will be submitted B00909 MILLS.L.M. Tennessee Valley Authority. (10/06/12 ip.
- 8006240453 Fifth interim deficiency tept to refueling water storage tank overflow line not rabricated to AiM code Fittsburgh.

 Des Moines Steel Co & nill presently discussing repairs Nest rept will be submitted by 800705 HILLBIL H Tennessee Valley Authority 80/06/18 [p
- 8006R40377 (Second interim deficiency rept re UHT hydraulic isolation waive accumulator weighing by Review of mod proposed by Hestinghouse is not complete Add1 info will be supplied by 800808
 - HILLERL H Tennessee Valley Authority 80/06/19 1p
- 8006240370 Forwards second interim deficiency rept re breakdown in Brave 8A program MILLB:(M. Tennessee Valley Authority 80/06/19 1p
- 8006250198 Third interim deficiency rept re steam generator water level ref column arror Util is investigating feasibility of initially installing temp compensation to not utilizing insulation for Sequeyah ? & Watto Bar MILLS, L. H. Tannessee Valley Authority (10/06/20 2pp

- 8005250234 Submits add1 info for 800213 final deficiency rept re welds bypassed by GC All nonconformance repts reviewed & 23 instances found of failure to comply w/procedural requilements Two instances occurred after GA training given MILLS, L M Tennessee Valley Authority 80/06/20 tp
- V Operator Examinations
- 8006240161 Ack receipt of 800414 ltr requesting review of add1 training for future applicants for licenses Concurs w/proposal to license mine senior operators at Sequoyah for participation as licensed personnel at Watts Bar SCHWENCER.A Licensing Branch 2 80/06/03 2pp
- DUCKET 50-391 WATTE BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B006250062 Forwards application for license to receive, possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility
 HILLS.L.M Tennessee Valley Authority 80/05/13 2pp
- --8006250065 Application for license to receive possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility

 * Tennessee Valley Authority 80/05/13 20pp
- 600.6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- 8006300391 Forwards revised responses to Questions 031 127,040 60 & 031 129 of NRC 790801 ltr re seismic qualification of Class IE electrical equipment Repts re cable samples & IEEE~323-1974 qualification encl MILLS.L M Tennessee Valley Authority 80/06/23 10pp
- --8006300397 "Delphi Pneumatic Test Procedure" LEWIS.G Commip.Inc., Delphi Systems Div 75/06/18 2pp
- --B006300400 "Radiation Testing of Cell Number 885 Final Rept" WILLIS, D E RTT Corp 79/08/23 7pp
- --8004300409 "Seismic Vibration Test of E10 Series Transmitters " SEARS.J A , MCCASLAND.K , RAMSELL.R Acton Environ Testing Corp 74/03/22 30pp
- --8004300414 "Test Procedure for Seismic Vibration, Gualification Test of E10 Series MCA/RRW Transmitters " SEARS, J A , MCCASLAND, K G Acton Environ Testing Corp 73/09/30 2500
- --8006300422 "Gage & Differential Pressure Transmitters Type E10 Series " BCHREINER.W., CABAUBON.M., TOLF.M.L. Acton Environ Testing Corp 73/10/31 10pp
- --B006300427 "Qualification Test of Electrical Cables Under Simulated LDCA/DBE By Sequential Exposure to Environs of Radiation.

 Thermal Aging, Steam & Chemical Byray "
 * Isomedix, Inc (subs of Maesfield Enterprises, Inc)
 78/06/30 42pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards cignification of NRC requirements for emergency response facilities defined in 790913 its Addi specific criteria for facilities under development EISENHUT, D. G. Division of Operating Reactors 80/04/25 61pp
- 8006080096 Forwards fuel storage physical security plan Plan withheld (ref 100ff2 790)
 MILLS.L M Tennessee Valley Authority 80/05/29 2pp
- 8006060294 Forwards add1 info to training & qualification plan Info withheld (ref 10CFR2 790) MILLS,L M Tennessee Valley Authority 80/06/02 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8006160200 Forwards IE lnsp Repts 50-390/80-11 & 50-391/80-08 on 800409-11 No nuncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/30 2pp

- --8006160206 IE Insp Repts 50-390/80-11 & 50-391/80-08 on B00409-11 No noncompilance noted Major areas inspected pipe supports w/concrete expansion bolts per IE Bulletin 79-02 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Buppart Branch MODENOS, L Region 2. Atlanta. Office of the Director 80/04/29 Spp
- 8006060157 Forwards IE Bulletin BO-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" enci O'REILLY: J P Region 2, Atlanta. Office of the Director 80/05/08 Jpp
- 8004040267 Forwards IE Bulletin 80~12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80~20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Hode" and O'REILLY.J.P Region 2. Atlanta, Office of the Director 80/05/09 3pp
- 8006190246 Forwards IE Insp Repts 50-390/80-10 & 50-391/80-07 on B0040B-11 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/09 2pp
- --8006190257 IE Insp Repts 50-390/80-10 & 50-391/80-07 on 800408-11 No noncompliance noted Major areas inspected preservice insp, welding records & worker concerns
 HERDIA R Region 2, Atlanta, Reactor Construction & Engineering Support Branch GIRAD,E H, COLEY, J L Region 2, Atlanta, Office of the Director 80/05/08 9pp
- 8006290212 Forwards IE Insp. Repts 50-390/80-12 & 50-391/80-09 on 800422-24 No noncompliance noted, MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- ---8006250215 IE Insp Repts 50-390/80-12 & 50-391/80-09 on 800422-24 No noncompliance noted Major areas inspected 10CFR50 55 items. IE bulleting & circulars. QA audits & general const activities CANTRELLE B Region 2. Atlanta. Reactor Construction & Engineering Support Branch THOMAS.M Region 2. Atlanta. Office of the Director 80/03/14 App
- 8006230030 Ack receipt of 800601 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50~390/80~05 & 50~391/80-04 MWRPHY.C E Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/06/06 29p
- --8006230033 Responds to NRC 800324 ltr re violations noted in IE Insp Repts 50-390/80-05 & 50-391/80-04 Corrective actions' engineering unit supervisors directed to develop insp programs for all safety-related features re fillet welds MILLS.L M. Tennessee Valley Authority 80/05/23 3pp
- BOO6130244 Forwards requests for relief from ABME Section XI preservice & inservice insp requirements for facility. TVA will revise preservice & inservice insp program to reflect exceptions. Requests comments by 800701 MILLS.L M Tennesses Valley Authority 80/04/09 14pp
- 800624026Q Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequouah & Watts Bar is provided by redundant heaters & tank insulation MILLS.L M Tennessee Valley Authority 80/06/09 8pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO6030392 Forwards final deficiency rept re temp effect on main steam safety valve setpoint MILLS.L M Tennessee Valley Authority 80/05/27 ip
- ---8006030398 Final deficiency rept re temp effect on main steam safety valve setpoint Ambient temp effects steam generator temp Valve room temp adjusted by exhaust fan Thermostat added to valve room to limit temp range to 80-120 F

 * Tehnessee Valley Authority 80/05/27 ip
- 8006060270 Forwards first interim deficiency rept re safety injection sys Train B flow deficiency Next rept to be filed by 800804 MILLS,L.M Tennessee Valley Authority 80/05/30 ip
- --8006060305 Final interim deficiency rept re RHR pump motor syc factor RHR pump motors exceeded allowable syc factor of 1 15 during low head operational modes Flow restrictions added in each RHR pump hot leg & cold leg injection header a Tennessee Valley Authority, 80/05/30 ip

- 8006060484 Forwards final deficiency rept re shock arrestor strut assembly interference MILLS.L M Tennessee Valley Authority 80/05/30 1p
- --8006060489 Final deficiency rept re shock arrestor strut assembly interference Assembly does not provide sufficient clearance for arrestor to function freely when installed at offracis angle greater than 83 dugrees Assemblies will be replaced * Tennessee Valley Authority 80/05/30 ip
- 9006110036 Forwards final deficiency tept re Ruskin fire dampers MILLG.L M Tennessee Valley Authority 80/06/03 ip
- --8005110043 Final deficiency rept to Ruskin fire dampers Ruskin has developed alternate fix providing positive stop for spring & snaprin strip ensuring complete closure Mods will be completed by 800410 Drawings encl
 Tennessee Valley Authority 80/04/03 3pp
- 8004170525 Third interim deficiency rept re control red drop events yielding less conservative DNBRs Review of corrective actions recommended by Westinghouse underway Next rept to be submitted by 800905
 MILLS.L M Tennessee Valley Authority 80/06/06 1p
- 8006170689 Forwards revision to 800527 final deficiency rept re temp effect of main steam valve setpoint MILLS, (11 Tennessee Valley Authority 80/04/11 1p
- --8006170672 Revision to 800527 final deficiency rept re temp effect of main steam valve setpoint Hoating, ventilation & air conditioning sup for valve rooms being modified to provide narrower temp range of 80-120 F

 * Tennessoe Valley Authority 80/06/11 ip
- 8006240453 Fifth inturim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code Pittsburgh-Das Moines Steel Co & util presently discussing repairs Next rept will be submitted by 800905 MILLB.L M Tennessee Valley Authority 80/06/18 ip
- 8006240377 Second interim deficiency rept re UHI hydrauli- isolation valve accumulator weighing sys Review of mod proposed by Heatinghouse is not complete Addl info will be supplied by 800808 MILLER, L M Tennessee Valley Authority 80/06/19 ip
- 8006240390 Forwards second interim deficiency rept re breakdown in Dravo GA program MILLS-C, M Tennessee Valley Authority 80/06/19 ip
- ~-8006240377 Second interim deficiency rept re breakdown in Dravo GA program Caused by lack of documentation ASME code cause initiated Dravo & util are reviewing radiographic tilm of all shop & field welds for Class 1 & 2 piping # Tennessee Valley Authority 80/06/17 ip
- 800625019B Third interim deficiency rept re steam generator water level ref column error Util is investigating feasibility of initially installing temp compensation & not utilizing insulation for Sequoyah 2 & Natts Ber MILLS,L M Tennesses Valley Authority 80/06/20 2pp
- 8008250234 Submits addi info for 800213 final deficiency rept re welds bypassed by GC All nonconformance repts reviewed & 23 instances found of failure to comply w/procedural requirements Two instances occurred after GA training given MILLS:L M Tennessee Valley Authority 80/06/20 Ip
- V. Operator Examinations
- BOO6240161 Ack receipt of BO0414 ltr requesting review of addl training for future applicants for licenses Concurs w/proposal to licensed nine senior operators at Bequoyah for participation as licensed personnel at Watts Bar BCHMENGER, A Licensing Branch 2 80/06/03 2pp
- DOCKET 50-.542 CHIN-8HAN POWER REACTOR, UNIT 1
 P. Operating license stage documents & correspondence
- 8006120510 Application for Amend 4 to License XR-8D, extending expiration date to 830701. Marked up license amend encl HILBON, B D General Flectric Co 80/05/13 2pp

- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8006030195 Forwards Matis Engineering Branch input re water chemistry programs W/o encl KNIGHT.JP Assistant Director for Engineering 80/04/07 ip
- BOOA230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci CISENHUT.D G Division of Licensing 80/05/20 13pp
- 8006030358 Submits description of activities in response to NRC 800505 request for detailed field audit of installed electrical equipment
 CREMS.E H Southern California Edison Co 80/05/28 2pp
- 8006030477 Requests acceptance of outlined audit & insp programs as verification of electrical equipment & sys conformance w/FSAR separation criteria per NRC 800505 request CREWS E H South Carolina Electric & Gas Co 80/05/28 2pp
- BOO6090511 Notification of 800613 meeting w/utils in Bethesda, MD to discuss structural engineering review HOUOHTON, T C Licensing Branch 3 80/05/30 3pp
- 8006110391 Forwards requests for add1 info re level measurement errors due to environ temp effects on level instrument ref legs & steam generator mods & control rod guide pin placement SCHMENCER.A Licensing Branch 2 NRC 80/05/30 8pp
- 8006170365 Forwards Drawing B-208-004, Sheet 247, Revision 2 of reactor bldg purge exhaust butterfly isolation valve Drawing available in Central Files only KRAMER.C G , YOCOM.H E Gilbert/Commonwealth Cos 80/06/11 ip
- 8006170641 Forwards Drawing E-511-208, Revision 1 re miscellaneous steel for fuel transfer canal shielding Drawing available in Central Files only BARNISHWM A . VOCOM. H E Gilbert/Commonwealth Cas 80/06/11 lp
- 6006240624 Forwards request for addl info on radiological assessment in order to continue review of CL application BCHWENCER, A Licensing Branch 2 80/06/11 8pp
- BOO6250389 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt licensing matters w/respect to facility have been assigned to T Houghton Reorganization charts enci TEDESCO,R L. Assistant Director for Licensing 80/06/13 12pp
- 8006270009 Requests add1 info to determine potential underclad cracking in reactor vessel noirles Info must be submitted within 2 wks
 SCHWENCER, A Licensing Branch 3 80/06/18 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 8006050023 Significant deficiency rept re omission of shelf life of tapes used for 490-volt terminations from site procedures. Shelf lives obtained from manufacturers & included in site storages procedures.

 ** Southern California Edison Co 80/05/27 2pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT,D G Division of Operating Reactors 80/04/25
- BOO6060343 Forwards radiation emergency plan
 CREMB.E H South Carolina Electric & Gas Co BO/06/04 ip
- --B006060344 Radiation emergency plan
 # Bouth Carolina Electric 8 Gas Co 80/06/04 200pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8006230186 Forwards Amend 19 to FSAR CREWS.E R Southern California Edison Co 80/04/18 2pp

- --8004230190 Amend 19 to FSAR
 * Southern California Edison Co 80/06/30 2,000pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006160216 Forwards IE Insp Rept 50-395/80-10 on 800414-17 No nuncompliance moted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/02 2pp
- --8006160219 IE Insp Rept 50-395/80-10 on 800414-17 No mencompliance noted Major aleas inspected const activities.util audit program & IE Bulletins 79-13 & 80-03 & IE Circulars 80-03, 80-09 & 80-07 CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch BURDETTE, T E Region 2, Atlanta, Office of the Director 80/05/02 Spp
- 8006060485 Forwards IE Bulletin BO-11, "Masonry Hall Design" No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 800606048B Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006050305 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Sesse Unit I While in Refueling Mode" encl O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/09
- BOO6050307 Forwards IE Bulletin BO-12. "Decay Heat Removal Bys Operability " No written response required IE Info Notice BO-20. "Loss of Docay Heat Removal Capability at Davis-Besse Unit I Uhile in Refueling Mode" enci O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/09
- 8004240045 Forwards IE Insp Ropt 50-395/80-09 on 800421-25 No noncompliance noted STONR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/12 2pp
- --8006240032 IE Insp Rept 50-399/80-09 on B00421-29 No noncompliance noted Major areas inspected preoperational surveillance programs, implementation of CP requirements & environ protection

 JERNING, G R Region 2, Atlanta, Fuel Facility & Materials Bafety Branch CUNNINGHAMA L Region 2, Atlanta, Office of the Director 80/05/12 App
- 8006300087 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/13
- 8006300690 Forwards IT Circular 80-11, "Emergency Diesel Generator Lube Bil Cooler Failures" No written response required C'REILLY, J. P. Region 2, Atlanta, Défice of the Director 80/05/13 2nn
- 8006250107 Forwards IE Insp Rept 50-395/80-13 on 800301-0430 No noncompliance noted LEMIG.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/16 2pp
- BOOG190694 Notifies that no proprietary info is contained in NRC Audit Rept 50-395/BO-10 JDHNSGN.M C Bouth Carolina Electric & Gas Co BO/05/30 ip
- 8006240276 Responds to IE Bulletin 79-03A re defects in ABME SA-312 Type 304 stainless stocl pipe Facility design does not permit use of pipe described in bulletin CREMS,E H South Carolina Electric & Oas Co 80/06/09 ip

- 8006300320 Ack receipt of IE Insp Rept 50-395/80-12 on 800422-25 Ne proprietary info DHR80N,M C South Carolina Electric & Oas Co 80/06/12 ip JOHR80N,M C South Carolina Electric & Oas Co
- --8006300322 Forwards IE (nsp. Rept 80-375/80-12 on 800422-25 No moncompliance noted MMRHY.C E. Region 2, Atlanta, Reactor Construction & Engineerin Support Branch 80/05/21 2pp
- ~~800630325 IE Insp Rept 50~395/80~12 on B00422-25 No noncompliance noted Major areas inspected open itoms & review of radiography GIRARD,E H . ZAJAC,L D Region 2, Atlanta, Office of the Direct HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/05/16 Bpp
- S Reportable occurrences, LERs & related correspondence
- BOO6230426 Deficiency rept to ASMF Code Class 1 piping ordered w/o stipulating proper testing Caused by misinterprotation of FSAR requirements Purchase order changed to require examination JOHNSON:M C South Carolina Electric & Oas Co (NO/05/19 Jpp
- 8006090019 Forwards significant deficiency rept to whelf life of tape used for 480-volt terminations . CREUS.E H Southern California Edison Co ED/05/27 ip
- 8006230455 Final deficiency reptile shelf life of tapes used for 400 voit terminations not being addressed in site procedures. Terminations are being regions Shelf Lives have been obtained are included in site storage procedures Details end: CREWS,E H. South Carolina Electric & Oas Co. 80/05/27. 3pp
- 8006040241 Final deficiency rept to broken insulators on 7kV speed & transfer switches diff will provide new heavier shafts on operating mechanism & welded cranks to reduce deflection Operating angle of cranks will also be changed CREWS,E H. South Carolina Electric & Oas Co. 80/05/20. 3pp
- 8006040304 Final deficiency maptine incorrect current sensor in 480 volt load ctrictoris breaker Safety—seleted 480-volt breakers inspected visually One sensor ruplaced Manufacturer notified CREMS.E.H. MACTOR.J.A. South Carolina Electric & Gas Co. 60/05/5 30p
- 8006050042 Forwards final deficiency tept re inadequate electrical separation GREMS E H South Carolina Electric A Gas Co 80/09/20 ip
- --8006050047 Final deficiency rept no impdequate electrical separable Power feeder circuit (dc) was routed from safety-related distribution panel to nonsafety-related ganel who isolation device Design control program requirements reviewed # South Carolina Electric & Gas Co (80/08/28) App
- 8006110254 Significant deficiency ropt on 800222, discovered chiller unit could not be fully loaded before unit would trip out on low evaporator pressure tow syc water flow cutnut deleted CREMS, E H Southern California Edison Co 80/05/29, 2pp
- 8006200012 Part 21 rept re failed engine thrust bearing Diesel generator sets were inspected in accordance u/uritten procedures & revised drawings Generators are free of reported potential defect MORIARTY.J M Colt Industries, Inc., Fairbanks Morse Engine Div 80/06/06 2pp
- 8006180401 Deficiency rept re substantial safety hazard in Hestinghor centrifugal charging pump operation Interim mode suggested CREWS,E H South Carolina Electric & Gas Co 80/06/13. Spp
- --8006180404 Confirms 800808 tolton u/f Blackwood re substantial safe hazard notification per 100FR21 Discusses Westinghouse charging pump operation & interim mods for 3-loop & 4-loop, operating & nonoperating plants ANDERSON.T M Westinghouse Electric Corp 80/08/08 7pp
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT &

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of MUREG-057/ ra adequacy of applicable support structures General operating reactor review procedure & acceptance criteria entle EISENHUT,D 0 Division of Licensing 80/05/20 13pp

- 8006110414 Notification of 800529 meeting w/util.QE & SRI in Bethesda. MD to discuss revised Chapter 7 of FSAR LYNCH.H D Licensing Branch 1 80/05/28 2pp
- 800A230001 Summary of B00410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Study concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU.T M Containment Systems Branch 80/05/30 App
- BOO6090540 Forwards responses to Questions 360 004 & 360 005 open items from Round 1.8et 2 Questions will be incorporated in FBAR.Amend 10 References, prepared by Shannon & Wilson & Woodward-Clyde Consultants, will be forwarded RENBERGER, D.L.: Washington Public Power Supply System 80/06/02 2300
- BOO6i10278 Notifies that lab will be conducting add1 moisture testing on low hydrogen electrodes using technique required in AHB A3 5.Bection 25 Electrode coating moisture testing results will be applied only to Units 1 & 4 RENBERGER, D L Washington Public Power Supply System 80/06/06
- 8006300013 Forwards "For Comment" edition of NUREG-0619, "BHR Faedwater Norrle & Control Rod Drive Return Line Norrle Cracking " Rept provides NRC resolution of Generic Technical Activity A-10 V/a encl EISENHUT, D G Division of Licansing 80/06/06 2pp
- 8006130305 Forwards responses to Round 1,9et 8 questions from Instrumentation & Controls Sys Branch Questions will be incorporated into FBAR in next amend RENBERGER, D.L. Washington Public Power Supply System 80/06/09 12459
- 8006180621 Notification of 800613 meating w/8HR Licensing Resolution Group in Bethesda, MD to discuss progress HIL80N:J N Licensing Branch 1 80/06/09 10pp
- BOO6250321 Summary of 800514 meeting w/utils in Bethesda.MD re organization & objectives of BMR licensing resolution group Agenda & viewgraph encl WILSON.J N Operating Reactors Branch 4 BO/06/17 lipp
- BOO6900587 Forwards regional evaluation of licensee performance & supporting data re activities authorized by CPPR-93 Areas of concern & required corrective actions delineated in NRC BOO617 to ENGELKEN.R H Region 5. San Francisco. Office of the Director
- --8006300591 Discusses regional evaluation of project activities for Apr 1977-Apr 1980 Strong measures required to provide adequate assurance that completed safety-related work was properly accomplished Evaluation form for period encl PODDS:RT Region 5. San Francisco, Reactor Construction & Engineering Support Branch BISHGP.TW, KIRSCH.DF Region 5, San Francisco, Office of the Director 80/03/13 12pp
- BOO63003B1 Forwards add1 info required for NRC to complete review of partial penetration weld substitution for sacrificial shield wall Includes documents re shielding correction for shim gaps at elevation 341 inches to 3 ft & detailed drawings RENBERGER, D.L. Washington Public Power Supply System BO/06/20 35pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of MRC requirements for emergency response facilities defined in 790913 ltr Add1 specific criteria for facilities under development EIBENHUT, D 0 Division of Operating Reactors 80/04/25
- 9006240404 Forwards drawings re location for near-site emergency ctr Requests immediate review & response so that site-specific design work can proceed & site preparation begin "Preconceptual Site Plan" available in Central Files only. REMBERGER, D.L. Washington Public Power Supply System 80/06/16
- --800624040B "Hind Rose for MPPS-2 for Apr 1974 to Mar 1975 at 33 Ft Level " * Washington Public Power Supply System 75/03/31 1p
- --B006240413 "Combined Plant Sycs & Emergency Coordination Facility Bite Location,1,930 Meter Radius Exclusion Areas & Property Lines "
 - # Washington Public Power Supply System 79/01/12 1p

- ---8006240418 "Environ Programs Base Map -- Hanford Area "

 * Washington Public Power Supply System 79/01/12 1p
- K Utility Final Bafety Analysis Report (FSAR) & amends
- BOO6110135 Forwards Amend 9 to FBAR RENBERGER D L Washington Public Power Supply System 80/05/27 2pp
- --8006110139 Amend 9 to FSAR
 * Washington Public Power Supply System 80/04/30 375pp
- BOD6170509 Forwards 800609 transmittal ltr & Certificate of Svc for Amend 9 to FSAR Amend was sent to Benton County MA Board of Commission's Energy Facility Site Evaluation Council & EPA RENBERGER.D L. Washington Public Power Supply System 80/06/09
- 9 Inspection reports, IE Bulletins & correspondence
- 8006250169 Forwards IE Insp Rept 50-397/80-06 on 800415-18 No noncompliance noted SPENCERC S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/12 2pp
- --8006250172 IE Insp Rept 50-397/80-06 on 800415-18 No noncompliance noted Major areas inspected followup on previous insp findings, structural steel welding, instrumentation work & IE bulleting & circulars
 DODDS:R T Region 5. San Francisco: Reactor Construction & Engineering Support Branch BISHOP:T W , KIRBCH, D F Region 5, San Francisco: Office of the Director 80/05/09 12pp
- 8006060480 Forwards response to IE Bulletin 77-08, "Events Relevant to BWRs Identified During TMI Incident" & plant unique data re MEDD-24708 RENBERGER,D L Washington Public Power Supply System 80/05/23 96pp
- 8006240083 Expresses concern re quality of const of sacrificial shield wall & pipe whip restraints at site Requests info re steps taken to provide reasonable assurance that approved QA program has been implemented STELLO.V Office of Inspection & Enforcement, Office of the Director 80/06/17 3pp
- ~-8006240086 Discusses items of noncompliance re sacrificial shield wall & pipe whip restraints identified during IE investigation on 791127 & 800228 Response to itr required in 25 days Notices of violation & proposed imposition of civil penalties encl BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/06/17 2pp
- ~~B006240090 Notice of violation from investigation on 791127 & 800228
 Investigation revealed deficiencies re sacrificial shield
 wail & pipe whip restraints Assigns monetary penalties for
 each deficiency
 # Diffice of Inspection & Enforcement, Office of the Director
 80/06/17 14pp
- --8006240093 Notice of proposed imposition of civil penalties in amount of \$61,000 for items of noncompliance identified in notice of violation Util may pay penalty or submit written protest * Office of Inspection & Enforcement, Office of the Director 80/06/17 ip
- 8 Reportable occurrences. LERs & related correspondence
- 8006050236 PNU-V-80-037 on 800518. Mount St Helen erupted Unit 2 has approx 1/8-inch of ash on ground, some ash dust incide plant Filtration sus operability confirmed Monitoring to detect abrasive matis in sus components underway BISHOP, T W Region 5, San Francisco, Office of the Director 80/05/19 2pp
- 8006300219 EN-80-021 on 800617, notice of violation & notice of proposed imposition of civil penalties will be issued to util Action based on alleged items of noncompliance redeficiencies in GA program during period of 1976-78 HENDERSON. J. THORNBURG. H D Office of Inspection & Enforcement, Office of the Director 80/06/13 ip

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D O Division of Licensing 80/05/20 13pp
- 8006190126 Responds to 800318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur w/util approach Procurement of spare or replacement parts subj to OA controls HAASS, W P Guality Assurance Branch 80/05/23 2pp
- BO06160145 Forwards revised periphyton/plankton biological monitoring program to provide preimpoundment phytoplankton data for comparison w/post-impoundment data MCDUFFIE, M A Carolina Power & Light Co 80/06/10 ip
- --8006160147 Revised biological monitoring program * Carolina Power & Light Co 80/06/10 Spp

I Financial information

- B006120011 Responds to 80050B request for comment on util 8-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC CHRISTERBURY.E Hearings Division 80/05/29 ip
- 9 Inspection reports. IE Bulletins & correspondence
- 8006060458 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J F Region 2, Atlanta, Office of the Director 80/05/08
- BO06050311 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operabliity " No written response required IE Info Notice BO-20, "Loss of Decay Heat Removal Capability at Davis-Beess Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2. Atlanta, Office of the Director BO/05/09 2pp
- 8006300128 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/05/13 2pp
- 8006090182 Ack receipt of 800502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07 MVRPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 ip
- --8004070202 Responds to NRC 800413 ltr re violations noted in IE Inap Repts 50-400/80-07,50-401/80-07,50-402/80-07 & 50-403/80-07 Corrective actions persons requisitioning perishable items will receive notice five days prior to expiration date HOHE,P H Carolina Power & Light Co 80/05/02 2pp
- 8006190664 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" No questionable NAMCO EA180 limit switches sent to const site MCDUFFIE, M A Carolina Power & Light Co 80/05/30 lp
- 8006240285 Responds to IE Bulletin BO-05, "Vacuum Conditions Resulting in Damage to Chemical Vol Gontrol Eys Holdup Tank " Forwards list of tanks & measures taken to protect tanks against vacuum conditions MCDUFFIE,M A Carolins Power & Light Co. BO/06/09 2pp
- B Reportable occurrences. LERs & related correspondence
- BOOG110234 Notifies that evaluation of potential reportable deficiency re-welding defects in Bergen Patterson Co supplied hangers for in-core instrumentation, will be completed by 800616 CHIANGI,N J. Carolina Power & Light Co. 80/05/22 1p
- 8006110244 Notifies that evaluation of potential reportable deficiency re-welding defects in AFCO supplied embeds, will be completed by 800616 CHIANGIIN J Carolina Power & Light Co 80/05/22 ip.

- 8004070304 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads investigation revealed 467 plates requiring corrective action CHIANGI.N J Carolina Power & Light Co 80/05/30 2pp
- 8006160070 Forwards final deficiency rept re omission of rebar in reactor auxiliary bldg CHIANOI.N J Carolina Power & Light Co 80/06/09 ip
- --8006160075 Final deficiency rept re omission of reinforcing steel in reactor auxiliary bldg 2 south, exterior, shear wall Caused by human error Holes drilled & bars grouted into previously placed concrete Special tests conducted to validate repairs * Carolina Power & Light Co. 80/06/04 App
- 8006240383 Confirms 800606 telcon which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10CFR50 55(e) & 10CFR21 Evaluation would involve duplicity of action CHIANOI.N J Carolina Power & Light Co 80/06/12 1p
- DOCKET 30-401 SHEARON HARRIS NUCLEAR POHER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EIBENHUT.D G Division of Licensing 80/05/20 13pp
- 8006190126 Responds to 800318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur u/util approach Procurement of spare or replacement parts sub; to BA controls HAASS, W.P. Quality Assurance Branch 80/05/23 2pp
- 8006160145 Forwards revised persphyton/plankton biological monitoring program to provide preimpoundment phytoplankton data for comparison w/post-impoundment data MCDUFFIE,M A Carolina Power & Light Co 80/06/10 ip
- ---8006160147 Revised biological monitoring program
 * Carolina Power & Light Co 80/06/10 5pp

I Financial information

- 8006120011 Responds to 800500 request for comment on util 8-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC CHRISTENBURY, E Hearings Division 80/05/29 ip
- **G** Inspection reports, IE Bulletins & correspondence
- 8006060458 Forwards (E Bulletin 60-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006050311 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09
- 8006300128 Forwards 1E Circular 80-ii, "Emergency Diesel Generator Lube Oll Cooler Failures " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/i3. 2pp
- BOOA0901B2 Ack receipt of BOO502 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/21 ip
- --B006090202 Responds to NRC 800415 itr re violations noted in IE Insp. Repts 50-400/80-07.50-401/80-07.50-402/80-07 & 50-403/80-07 Corrective actions persons requisitioning perishable items will receive notice five days prior to expiration date HOME.P W Carolina Power & Light Co. 80/05/02 2pp

- 8006190664 Responds to IE Sulletin 79-29. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No questionable NAMCO EA180 Limit switches sent to const site MCDUFFIE.M A Carolina Power & Light Co 80/05/30 Ip
- 8006240285 Responds to IE Bulletin 80-05, "Vacuum Conditions Resulting in Damage to Chemical Vol Control Sys Moldup Tank " Forwards list of tanks & measures taken to protect tanks against vacuum conditions
 MCDUFFIE M A Carolina Power & Light Co. 80/06/09 | Rep
- S neportable occurrences, LERs & related correspondence
- 8006110234 Notifies that evaluation of potential reportable deficiency re welding defects in Bergen Patterson to supplied hangers for in-core instrumentation, will be completed by 800616 CHIANGI,N J Carolina Power & Light to 80/05/22 Ip
- 8006110244 Notifies that evaluation of potential reportable deficiency re welding defects in AFCO supplied embeds will be completed by 800616 CHIANGIN J Carolina Power & Light Co 80/05/22 ip
- 8005070306 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Investigation revealed 469 plates requiring corrective action CHIANOI.N J Carolina Power & Light Co 80/05/30 2pp
- 8006160070 Forwards final deficiency rept re omission of rebar in reactor auxiliary blog CHIANOIN J Carolina Power & Light Co 80/06/09 ip
- --B006i60075 Final deficiency rept re omission of reinforcing steel in reactor auxiliary bldg 2 south exterior, shear wall Caused by human arror Holes drilled & bars grouted into previously placed concrete Special tests conducted to validate repairs * Carolina Power & Light Co 80/06/04 6pp
- 6006240383 Confirms 600606 telcon which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10CFR50 5516+0 & 10CFR21 Evaluation would involve duplicity of action CHIANGI,N J Carolina Power & Light Co 80/06/12 Ip
- BOCKET 50-402 SHEARON MARRIS NUCLEAR POHER PLANT, UNIT 3

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BUR & PUR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 ra adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- 9006190126 Responds to B00319 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur w/util approach Procurement of spare or replacement parts subj to GA controls HAASS.W P Guality Assurance Branch 80/05/23 2pp
- 8006160145 Forwards revised periphyton/plankton biological monitoring program to provide preimpoundment phytoplankton data for comparison u/post-impoundment data MCDUFFIE.H A Carolina Power & Light Co 80/06/10 1p
- --8006160147 Revised biological monitoring program * Carolina Power & Light Co 80/06/10 Spp
- I Financial information
- 8006120011 Responds to 800508 request for comment on util S-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w/NRC CHRISTENBURY, E Hearings Division 80/05/29 lp
- G Inspection reports. IE Bulletins & correspondence
- BOO6060458 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" and O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/08

- 8006080311 Forwards IE Bulletin BO-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Resse Unit 1 While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/07
- 8006300128 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oll Cooler Failures " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/13 200
- 8006090182 Ack receipt of 800502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-400/80-07, 50-401/80-07, 50-402/80-07 & 50-403/80-07 MURPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 ip
- ---8006090202 Responds to NRC 800415 ltr re violations noted in IE Insp Repts 50-400/80-07,50-401/80-07,50-402/80-07 & 50-403/80-07 Corrective actions persons requisitioning perishable items will receive notice five days prior to expiration date HOHE.P W Carolina Power & Light Co 80/05/02 2pp
- 6006170664 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No questionable NAMCO EA180 limit switches sent to const site MCDUFFIEM A Carolina Power & Light Co 80705730 Ip
- 8006240285 Responds to IE Bulletin 80-05, "Vacuum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tank " Forwards list of tanks & measures taken to protect tanks against vacuum conditions
 MCDUFFIEM A Carolina Power & Light Co 80/06/07 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006110234 Notifies that evaluation of potential reportable deficiency re welding defects in Bergen Patterson Co supplied hangers for in-core instrumentation, will be completed by 800616 CHIANGI, N J. Carolina Power & Light Co. 80/05/22 Ip
- BOO6110244 Notifies that evaluation of potential reportable deficiency re welding defects in AFCO supplied embeds, will be completed by BOO616 CHIANDI,N J Carolina Power & Light Co 80/05/22 1p
- 8006090306 Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embadment & support of safety-related loads Investigation revealed 469 plates requiring corrective action CHIANGI,N J Carolina Power & Light Co 80/05/30 2pp
- 8006160070 Forwards final deficiency rept to unission of rebar in reactor auxiliary bldg CHIANGI.N J Carolina Power & Light Co 80/06/09 ip
- --8006160075 Final deficiency rept re omission of reinforcing steel in reactor auxiliary bldg 2 south, exterior, shear wall Caused by human error Holes drilled & bars grouted into previously placed concrete Special tests conducted to validate repairs & Carolina Power & Light Co 80/06/04 6pp
- BOG62403B3 Confirms BO0606 telcon which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10cFR50 55(e) & 10cFR21 Evaluation would involve duplicity of action CHIANGI,N J Carolina Power & Light Co BO/06/12 1p
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D 0 Division of Licensing 80/05/20 13pp.
- BOD6190126 Responds to BOO318 ltr re NRC position on util approach of applying AIF position paper for procurement of off-the-shelf items NRC does not concur w/util approach Procurement of spare or replacement parts subj to QA controls HAASS,W P Quality Assurance Branch 80/05/23 2pp
- 8006160145 Forwards revised periphyton/plankton bibliogical monitoring program to provide preimpoundment phytoplankton data for comparison w/post-impoundment data MCDUFFIE.M A Carolina Power & Light Co 80/06/10, 1p

- ---8006160147 Revised biological monitoring program
 * Carolina Power & Light Co 80/06/10 5pp
- I Financial information
- 8006120011 Responds to 800908 request for comment on util 8-7 registration statement Review identified no inaccurate statements re NRC regulatory requirements or financial info filed w//RC CHRISTENBURY, E Hearings Division 80/05/29 1p
- G. Inspection reports, IE Bulletins & correspondence
- 8006060458 Forwards IF Bulletin 80-11. "Masonry Wall Design " No action or written response required 1E Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/08
- 8006050311 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Bassa Unit 1 While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09
- 8006300128 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- BOOA070182 Ack receipt of BOO502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-07, 50-401/80-07, 50-402/80-07 5 50-403/80-07 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch BO/05/21 1p
- --8006090202 Responds to NRC 800415 ltr re violations noted in IE Insp Repts 50-400/80-07,50-401/80-07,50-402/80-07 & 50-403/80-07 Corrective actions persons requisitioning perishable items will receive notice five days prior to expiration date HOWE,P W Carolina Power & Light Co 80/05/02 2pp.
- 8006190664 Responds to 1E Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No questionable NAMCO EA180 limit switches sent to const site MCDUFFIE.H A Carelina Power & Light Co 80/05/30 1p
- 8006240285 Responds to IE Bulletin BO-05. "Vacuum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tank " Forwards list of tanks & measures taken to protect tanks against vacuum conditions
 WCDUFFIE,M A Carplina Power & Light Co 80/06/09 %FF
- 8 Reportable occurrences, LERs & related correspondence
- BOO6:10234 Notifies that evaluation of patential reportable deficiency re welding defects in Bergen Patterson Co supplied hangers for in-core instrumentation, will be completed by 800616 CHIANGI,N J Carolina Power 3 Light Co 80/05/22 ip
- 8006110244 Notifies that evaluation of potential reportable deficiency re-welding defects in AFCO supplied embeds, will be completed by 800616 CHIAKGIN J Carolina Power & Light Co 80/05/22 ip.
- 8006090306 Interim deficiency rept re procurement fabrication & insp of engineered plates for concrete embedment & support of safety-related loads investigation revealed 469 plates requiring corrective action CHIANGI.N J Carolina Power & Light Co 80/05/30 2pp
- 8006160070 Forwards final deficiency rept re emission of rebar in reactor auxiliary bidg CHIANGI,N J Carolina Power & Light Co 80/06/09 ip
- --8006160075 Final deficiency rept re omission of reinforcing steel in reactor auxiliary bldg 2 south.exterior.shear wall.Caused by human error Holes drilled 2 bars grouted into previously placed concrete Special tests conducted to validate repairs * Carolina Power & Light Co 80/06/04 App
- 80062403B3 Confirms 800606 telcon which clarified that deficiencies identified during NRC audit need not be evaluated for reportability per 10CFR50 55(e) & 10CFR21 Evaluation would involve duplicity of action CHIANGI.N J Carolina Power & Light Co 80/06/12 1p

- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR 5 PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D 6 Division of Licensing BO/05/20 13pp
- G Inspection reports: IE Bulletins & correspondence
- 8006060418 Forwards IE Bulletin 80-11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" enci O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/08 2pp
- 8006200105 Forwards IE Insp Repts 50-33B/80-17.90-404/80-02 & 50-405/80-02 on 800409 ½ 10 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/08 2pp
- --8006200114 IE Insp Repts 50-338/80-17.50-404/80-02 & 50-405/80-02 on 800407 & 10 No noncompliance noted Major areas inspected IE Bulletins 77-17 & 80-08 activities re cracks in borated water sys & containment liner penetration welds HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONDMOS, N Region 2. Atlanta, Office of the Director 80/05/07 4pp
- 8006040261 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Dperability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Basse Unit 1 While in Refueling Mode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 2pp
- 8006300137 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required O'REILLY, J P Region 2. Atlanta, Diffice of the Director 80/05/13 2pp
- 8006020277 Advises of suspension of IE Bulletin 80-08 review due to ongoing feasibility study Review will resume if study indicates continuing wifacilities as nuclear units BROWN B C Virginia Electric & Power Co 80/05/28 ip
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Sectson 4 of NUREG-0877 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp
- Q Inspection reports. IE Bulletins & correspondence
- 8006060418 Forwards IE Bullstin 80-ii, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Qverloading of Structural Elements Due to Pipe Support Loads" and O'REILLY, J P' Region 2, Atlanta, Office of the Director 80/05/08
- B006200105 Forwards IE Insp Repts 50-338/80-17, 50-404/80-02 & 50-405/80-02 on 800409 t 10 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/08 2pp
- --B006200114 IE Insp Repts 50-338/80-17.50-404/80-02 & 50-405/80-02 on 800409 & 10 No noncompliance noted Major areas inspected IE Bulletins 79-17 & 80-08 activities re cracks in borated water sys & containment liner penetration welds HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS. N Region 2. Atlanta, Office of the Director 80/05/07 4pp
- 8006040261 Forwards IE Bulletin 80-12, "Decay Meat Removal 8ys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit I While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07

- 8006300137 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY.J P Region 2, Atlanta. Defice of the Director 80/05/13 280
- 8006020277 Advises of suspension of IE Bulletin 80-08 review due to ongoing feasibility study Review will resume if study indicates continuing w/facilities as nuclear units BROWN.SC Virginia Electric & Power Co 80/05/28 ip
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8006110264 Confirms 800529 conversation re request for extension until 800617 for comments on NUREO-0191, final E18 for facility Extension needed due to possible inadequary of discussions on benefit/cost ratio & radiological impacts MCCASE.J M Environmental Protection Agency 80/06/04 ip
- 8006160094 Comments on FES WI Pollution Discharge Elimination Syspermit for discharging wastewaters to Genoa 1 ashpit has not been issued Ammonium hydroxide, rather than morpholine, should be used as boiler feedwater additive for pH adjustment DRUCKENMILLER Wisconsin, State of 80/06/06 2pp
- 8006170437 Notifies that Dept of Army permit not required for final EIS No communts re EIS PAREDNS.W D Army, Dept of 80/06/10 ip
- 8006300564 Forwards corrected Pages 5-ji.5-i2.5-i7 & 5-31 to FES.NUREG-0191.re occupational radiation exposure CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 5pp
- --8006300573 Revised Pages 5-11,5-12.5-17 & 5-31 to FEB for facility

 * Office of Nuclear Reactor Regulation, Director 80/06/11 4pp
- 8006260193 Submits followup to 800606 ltr re add1 comments on FEB for facility Recommends that format used in responding to comments or questions be modified to specifically identify area addressed DRUCKENMILLER, H Wisconsin, State of 80/06/19 2pp
- F Security, medical, emergency & fire protection plans
- 8006020236 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC. Emergency Notification Sys hotline will also be used KEPPLER.J G Region 3, Chicago, Office of the Director. BO/04/18 2pp
- 8006090487 Forwards proposed rule entitled. "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101" Rule adds new Section 50 48 & App R to 1005FR50 & is expected to be published in FR by end of May EISENHUT.D 0 Division of Licensing 80/05/19 46pp
- 800&1300&3 Forwards revised Pages 1-14 & new Page 14a for proposed rule 10CR50 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101." transmitted by NRC 800019 1tr Page 14a not encl EISENHUT.D 0 Division of Licensing 80/05/22 73pp
- 8006110343 Forwards revised modified amended security plan Plan withheld (ref 190FR2 790) LINDER,F Dairyland Power Cooperative 80/06/06 2pp
- O Adjudicatory correspondence
- 8006170125 Response to NRC interrogetories Contrary to draft EIS, LACBWR fuel & maint costs will rise faster than non-nuclear power Decommissioning has negative effect on cost benefit Certificate of Svc encl Related correspondence MORRELA.X. NYOAARD, G.R. Coulse Region Energy Coalition 80/04/24 3pp
- 8006040026 Advises of request for hearing on B00225 order to show cause NRC evaluating licensee responses to order & has requested addl info DENTON, HR Office of Nuclear Reactor Regulation, Director B0/05/16 1p
- --8006040029 Forwards corrected Pages 3 & 6 to util 800325 answer to order to show cause HIESTAND.O 6 Morgan, Lewis & Bockius 80/04/03 ip

- --8006040031 Corrected Pages 3 % 6 to util 800325 answer to order to show cause LINDER: F Dairyland Power Cooperative 80/03/25 Bpp
- ---8006040033 Advises that requests for hearing on order to show cause & related documents should be referred to Commission for resolution
 SHAPAR, H K Office of the Executive Legal Director 80/05/12
 3ne
- B00612028B Notice of withdrawal from proceeding Certificate of Svc encl OWEN.R H Owen, R H 80/05/19 3pp
- 8006020313 Order for commencement of 800619 prehearing conference at Univ of MILLa Crosse. MI re 100FR2 752 matters & ABLB 800521 memorandum & order No limited appearances allowed BECHOEFER. C Atomic Safety and Licensing Board Panel 80/05/23
- 8006120418 Advises that NRC plans to delete name from svc list for receipt of correspondence from NRC to licensee re 1975 gool expansion proceeding CRUTCHFIELD.D Operating Reactors Branch 5 80/05/20 ip
- 8006090210 Motion for summary disposition of intervenor Coulee Region Energy Coalition Contentions 2A, 2B, B, 9, 19 & 22 re environ issues, due to absence of genuine issue of matl fact supporting contentions WOODHEAD, C P Hearing Branch 3 80/06/06 22pp
- --8006090213 Addidavit re intervenor Coulee Region Energy Coalition Contentions 2A & 8 Testing methodology in facility radiological environ monitoring program meets basic requirements W/prof qualifications & supporting documents BRANAGAN, E F Radiological Assessment Branch 80/05/20 31pp
- --8006090219 Affidavit re intervenar Coulee Region Energy Coalition Contention 2B Facts do not support contention that LACBUR offpas emissions are inimical to health & safety Prof qualifications encl NEHEMIAB.J V Radiological Assessment Branch 80/05/15 5pp
- --8006090223 Affidavit re intervenor Coulee Region Energy Coalition Contention 9 Radiological & toxic impacts would be additive rather than synergistic 5 would not be inimical to health & safety Prof qualifications encl GOTCHY.R L Radiological Assessment Branch 80/06/05 App
- ~-800609022B Affidavit re intervenor Coulee Region Energy Coalition Contention 19 None of Contention 19 cost factors would outweigh benefits of continued operation Prof qualifications encl NASH.D A Utility Finance Branch 80/05/21 8pp.
- ~-8006090235 Affidavit re intervenor Coulee Region Energy Coalition Contention 22 Measures outlined in contention would not eliminate need for LACBWR Prof qualifications & Certificate of Stoc encl FELD:S E Utility Finance Branch 80/05/16 7pp
- 80061203B9 Forwards 800609 FR notice re nuclear plant accident considerations under NEPA of 1969 Parties are invited to comment at 800619 prehearing conference on effect of new policy statement on OL proceeding BECHHDEFER.C. Atomic Safety and Licensing Board Panel BO/06/10
- --8006120393 FR notice re nuclear plant accident considerations under NEPA of 1967 Revises NRC policy for considering Class 9 accidents from environ point of view Supplementary info encl
 CHILK, S. J. Office of the Secretary of the Commission 80/06/09, 12nn
- BOO6160140 Memorandum inviting parties to comment at BOO609 prehearing conference re Commission BOO609 FR publication approval of polity statement on Class 9 accident probabilities & consequences
 BECHNDEFER.C Atomic Safety and Licensing Board Panel NRC BO/08/10 2pp
- ---8005160142 "Nuclear Power Plant Accident Considerations Under NEPA of 1969," 10CFR50 & 51 statement of interim policy. Hithdraws proposed annex to App D of 10CFR50 & suspends rulemaking CHILK.8 J Office of the Secretary of the Commission 80/06/09 12pp

- 8006170413 Forwards RP Geckler 800616 affidavit & 1979 NUREG-0594 in response to questions of ASLS 800321 memorandum & order W/o NUREG
 - WOODHCAD, C.P. Hearing Branch 3 80/06/16 1p
- --8006170417 Affidavit in response to questions of ASLR 800521 memorandum & order re LACBUR FES Supporting documentation & prof qualifications encl
 GECKLER.R P Environmental Engineering Branch 80/06/16 31pp
- → Insurance & indemnity information
- $8006170468\ Forwards$ Endorsement 35 to ANI Policy NF-217 per Agreement B-62
- DEVINE.H F Dailyland Power Cooperative 80/06/11 2pp
- P Operating license stage documents & correspondence
- BOO6090165 Forwards add1 TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning.licensing exams & licensee dissemination of operating experiences Response requested within 30 days EISENHUT.D O Division of Licensing 80/05/07 150pp
- 8006260067 Forwards MUREQ-0654 Vols I & II W/g encl CRUTCHFIELD.D Operating Reactors Branch 5 80/05/16 2pp.
- 8006120006 Forwards request for add1 info for App J review of containment leakage testing CRUTCHFICLD.D Operating Reactors Branch 5 80/03/19 5pp
- 8006130122 Requests comments on NUREQ-0377. "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Proposed review procedure & implementation schedule encl EISENHUT.D C Division of Licensing. 80/05/19 72pp
- BCO4070316 Forwards completed questionnaire for epidemiologic studies on health effects of low level ionizing radiation exposure per DL Ziemann BO0304 request LINDER:F Darryland Fower Cooperative BO/06/02 12pp
- 8006180354 Advises that reorganization of Ofc of Nuclear Reactor Regulation became effective on 800428 Project manager J Shea Will coordinate licensing activities for facility Reorganization is described in encl CRUTCHFIELD, 0 Operating Reactors Branch 5 80/06/02 35pp
- 8006300604 Ltr to all BWR licensees forwarding "For Comment" edition of NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments will be evaluated by NRC prior to final implementation W/o encl EISENHUT,D O Division of Licensing 80/06/05 22pp
- 8006180523 Forwards addl info re TMI Lessons Learned Areas requiring post-accident entry were identified as control room post-accident sampling station health physics lab & technical support ctr. to be permanently located in turbine bidg LINDER, F Dairyland Power Cooperative. 80/06/12 2pp
- 8006200420 Submits info in response to NRC 791023 ltr requesting verification of containment purging & venting during normal operation Design adequacy of containment valves confirmed in Nov 1977 scale model valve qualification test program, LINDER, F Dairyland Power Cooperative, 80/06/12 20pp
- @ Inspection reports: IE Bulletins & correspondance
- 8006230085 Forwards IE Insp Rept 50-409/80-03 on 800428-29 No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8006230091 IE Insp Rept 50-409/80-03 on 800428-29 No noncompliance noted Major areas inspected spent fuel rack QA & QC programs

 DANIELBON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3, Chicago, Office of the Director 80/05/13, App
- EOOGO20545 Responds to IE Bulletin 79-26, "Boron Loss from BWR Control Blades " Each control blade was fully withdrawn Procedure demonstrated that reactor was subcritical w/any control blade withdrawn 3 other 28 blades fully inserted LINDER,F Dairyland Power Cooperative 80/05/15 2pp

- 8006050363 Advises that insp of containment bldg reveals that all safety-related 4 nonsafety-related electrical equipment does have positive anchorage Response action to IE Info Notice 80-21 & drawings encl LINDER, F Dairyland Power Cooperative 80/05/30 14pp.
- 8006170073 Forwards IE 3msp Rept 50-409/80-01 on 800319-20 & 0505-09 & notice of violation
 HEISHMANLR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/05 2pp
- --8006170083 Notice of violation from insp on 800319-20 & 0505-09 * Region 3, Chicago, Office of the Director 80/05/30. Ip
- --B006170088 IE Insp Rept 50-409/80-01 on B00319-20 & 0505-09
 Noncompliance noted failure to make prompt telephone
 notification of significant event to NRC operations ctr.
 BAKER, K. R., BRANCH, M. W., FORNER, M. L. Region 3, Chicago, Office of
 the Director 80/05/30 10pp
- R Periodic operating reports & related correspondence
- 8006130273 Forwards monthly operating rept for May 1980 LINDER:F Dairyland Power Cooperative 80/06/03 ip
- --8006130276 Monthly operating rept for May 1980 GQODMAN.L S Dairyland Power Cooperative. 80/06/03 7pp
- 8 Reportable occurrences, LEAs & related correspondence
- 8006300274 Discusses turbine governing sys secondary relay valve sticking, which causes initial pressure regulator to respond improperly immediate red phone reporting is not necessary, unless Tech Specs are exceeded HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/16 1p
- T Hearing transcripts on non-antitrust matters
- 8006260090 Transcript of 800619 prehearing conference in La Crosse, HI. Pp 1,004-1,144 * Atomic Safety and Licensing Board Panel 80/06/19 14ipp
- 8006270202 Forwards transcript of 800619 prehearing conference W/o encl WOODHEAD,C P Hearing Branch 3 80/06/25 ip
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8004230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequaty of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT,D O Division of Licensing 80/05/20 13pp
- BOOAOAO384 Responds to BOO215 & 0509 requests for review of plant geotechnical investigations Util should evaluate safety implications of crack in reactor bidg north wall HILKINSON.T A Army Dept of, Corps of Engineers, BO/05/30 2pp
- BOO4230001 Summary of BOO410 meeting w/Mark II owners group re suppression pool temp response to safety/relief actuations Brudy concluded that limit on temp not needed Requests that applicants submit detailed info for evaluation SU:T K Containment Systems Branch 80/03/30 App
- 8006130150 Notification of 800610 meeting w/util in Hethesda. MD to discuss welding defects in biological shield KIPER.K.L. Licensing Branch i 80/06/02 3pp
- BOO6300012 Forwards "For Comment" edition of NUREO-0619, "BWR Feedwater Nozzle & Control Red Drive Return Line Nozzle Cracking " Rept provides NRC resolution of Generic Technical Activity A-10 Wo encl EISENHUT, D. G. Division of Licensing 80/06/Q6 2pp
- 8006160090 Submits anomalous geologic conditions per 800130 commitment. Small, low-angle thrust fault previously encountered in intale shaft intersected in East Lake water tunnel Fault & associated splay faults noted intermittently RHODE, & K. Niagara Mohawk Power Corp. 80/06/09 1p

- 6006170323 Forwards final responses to geologic info Requests 0361 1, 2, 13, 14 % 24 per 791001 request RHODE:0 K Niagara Mohawk Power Corp 80/06/10 31pp
- 8006230550 Forwards "DYWIDAG Threadbar Spince Bys," per 800325 addiinfo request re util reinforcing steel bar splicing method
 RHODE, G.K. Niagara Mohawk Power Corp. 80/06/17 Epp
- 8006300284 Responds to 800421 request for authorization to use 790412 ASME Code Case N-242 "Matl Certification Section III.Div 1, Classes 1, 2, 3, MC & CS Const ' Code case is acceptable subj to condition stated in 1tr YOUNGBLOOD, B J Licensing Branch t 80/06/17 2pp
- F Security, medical, emergency & fire protection plans
- 8006190039 Requests participation in NRC study of people-related problems in nuclear safeguards Involves collection of data on licensee security forces & practices including visit to facility to interview security mgt personnel IPPOLITO, T A Operating Reactors Branch 2 80/06/03 2pp
- O Inspection reports, IE Bulletins & correspondence
- B006240012 Responds to IE Bulletin 80-02. "Inadequate QA for Nuclear Supplied Equipment " Feedwater spargers & thermal sleeves mfg by CBI-Nuclear RHODE.C K Niagara Hohawk Power Corp 80/05/23 ip
- S Reportable occurrences. LERs & related correspondence
- 8006200024 Final Part 21 rept re mized heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A234WPB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY.J L Chemtron Corp. Tube Yurns Div 80/06/06 3no
- 8006240406 Supplements 800415 interim deficiency rept re biological shield wall Forwards agenda 8 presentation from 800610 meeting & discussion re frame mechanics evaluation Bample fracture mechanic calculations encl RHODE.0 K Niagara Mohawk Power Corp 80/06/18 48pp
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B006230110 Advises EWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENKUT,D G Division of Licensing 80/05/20 13pp
- 8006230134 Discusses reorganization of Ofc of Nuclear Reactor Regulation & Advises that mgt responsibilities re facility have been assigned to K Jabbour Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/13 lipp
- G Inspection reports, IE Bulletins & correspondence
- 8006020018 Ack receipt of 800205 ltm ne number of insps/audits being performed insps are intended to occur infrequently & will involve minimal duplication of insp effort STECLO, V Office of Inspection & Enforcement, Office of the Director 80/05/03 2pp
- ~-8006020021 Responds to NRC 771204 ltr re performance & appraisal function good sys of checks & balance via GA audit is destrable though possibly too demanding on key personnel SCHAFFER:S O Duquesne Light Co 80/02/05 2pp
- 8004040184 Ack receipt of 800416 ltr informing NRC of steps taken to correct substantiated allegations noted in IE Insp Rept 50-412/80-02 CARLSON,R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/14 ip
 - wards IE Insp Rept 50-412/80-02 on 800107-11
 tion 1 Philadelphia, Reactor Construction &
 nch 80/03/13 2pp

- --8006060200 IE Insp Rept 50-412/80-02 on 800107-11 No noncompliance noted Two allegations were substantiated internal audits not conducted in required time period 3 training program inadequate

 TRIPP.L E Region 1, Philadelphia, Reactor Construction & Engineering Support Branch PURR.J P Region 1. Philadelphia, Office of the Director 80/02/21 7pp
- 8006250207 Forwards IE Insp Rept 50-412/80-03 on 800325-28 No noncompliance noted CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 60/05/14 2pp
- ~-8004250209 IE Insp Rept 50-412/80-03 on 800325-28 No noncompliance noted Major areas inspected GC programs for concrete placement & maint, settlement monitoring program & previous insp findings MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch NARROW, L, VARELA, A A Region 1, Philadelphia, Office of the Director 80/05/09 9pp
- 8006200042 Forwards IE Circular 80-13, "Grid Strap Damage in Mestinghouse Fuel Assemblies" No written response required GRIER.8 H Region 1, Philadelphia. Office of the Director 8D/05/28 1p
- BOO6110168 Responds to IE Bulletin BO-OS. "Vacuum Condition Resulting in Damage to Chemcial Vol Control Bys (CVCS) Holdup Tanks "
 Design features ensure that low pressure process or holdup tanks are adequately designed against vacuum conditions HODLEVER,E J Duquesne Light Co BO/O6/O6 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006300287 Ack receipt of 800501 final deficiency rept re cable tray galvanizing deficiency CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/03 1p
- 8006190315 Forwards final Bignificant Deficiency 79-05 re weld discrepancies in reactor vessel structural support WOOLEVER,E J Duquesne Light Co 80/06/16 lp
- --8006190321 Final Significant Deficiency 79-05 re weld discrepancies found during insp of reactor vessel structural support Cause unstated Weld excavations in skirt-to-base flange weld to be weld-repaired & magnetic particle inspected by 801130 # Duquesne Light Co 80/06/16 4pp
- DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D 0 Division of Licensing 80/05/20 13pp
- BOO6200594 Summary of BO0423-24 meeting w/util & NC Municipal Power Agency Number 1 & site visit to assess const schedule List of attendees, agenda, presentation summary, handouts & test program summary and I HOOD, D S Licensing Branch 3 80/06/06 26pp
- O Inspection reports, IE Bulletins & correspondence
- 8006060427 Forwards IE Builetin 80-11, "Masonry Wall Design," No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8004040275 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 Nhile in Refueling Mode" encl O'REILLY, J P Region 2, Atjanta, Office of the Director 80/05/09 2pp
- 8006300i10 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures," No written response required O'REELLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13

- 8006130050 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-413/80-06 & 50-414/80-06 MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 ip
- --9006130053 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-413/80-06 & 50-414/80-06 Corrective actions weld control sheet re-examined & legible heat code re-established PARKER W O
- --8006130056 Forwards IE Insp Repts 90-413/60-06 & 50-414/60-06 on 800401-04 & notice or violation MURPHY,C E Ragion 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --8006130060 Notice of violation from insp on 800401-04 * Region 2, Atlanta, Office of the Director 80/0 80/04/23 1p
- --B006130065 IE Insp Repts 50-413/80-06 & 50-414/80-06 on B00401-04 Noncompliance noted failure to provide identifiable heat number on weld record HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch KLEINSDROE, N P Region 2. Atlanta, Office of the Director 80/04/23 Bpp
- 8006240282 Responds to IE Bulletin 80-05. "Varoum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tanks " Lists low pressure & holdup tanks which are normally valved to contain primary sys water PARKER.W O Duke Power Co 80/06/09 2pp
- 8006270219 Ack receipt of IE Insp Repts 50-413/80-07 & 50-414/80-07 on BOO401-30 No proprietary info PARKER, N O Duke Power Co 80/05/09 1p
- ---8006270222 Forwards IE Insp Repts 50-413/80-07 & 50-414/80-07 on 800401-30 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 2pp
- --8006270228 Notice of violation from imap on 800401-30 * Region 2, Atlanta, Office of the Director 80/0 80/05/16 in
- --8006270231 IC Insp Repts 50-413/80-07 & 50-414/80-07 on 800401-30
 Noncompliance noted failure to follow drawing requirements
 MAXWELL.OF Region 2. Atlanta. Office of the Director
 RAUSCHIJ K Region 2. Atlanta. Reactor Construction & Engineering
 Support Branch 80/05/16 5pp
- S Reportable occurrences, LERs & related correspondence
- 8006050337 Forwards Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel equipment hatch
 - PARKER, W O Duke Power Co 80/04/01 1p
- --8006050345 Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel equipment hatch Hatch mfg by Lakeside Bridge & Steel Co & initially radiographed by McMannus Testing Lab Repairs by 800501 * Dute Power Co 80/04/01 2p
- 8006020074 PND-II-80-085 NC news media printed allegations by const worker involving onsite safety hazards Worker contacted OSHA on 800506 following NRC referral OSHA contacted again on 800508 withdrawing previous rept RAUSCH.J K Region 2. Atlanta. Office of the Director 80/05/15
- 8006090343 Forwards Significant Deficiency 413-414/80-06 re improper radiography on steam generator enclosures PARKER, W.O. Duke Power Co. 80/06/02 1
- --8006090347 Significant Deficiency 413-414/80-06 re improper radiography on steam generator enclosures mfg by Lakeside Bridge & Steel Co Cause unstated Welds radiographed in accordance w/ASME. Close surveillance instituted to prevent recurrence * Duke Power Co 60/06/02 ip
- BOO62404ii Informs that all Unit i safety-related motor control ctr equipment has been inspected for proper power wire connections Nacessary mods were completed Insp of Unit 2 is scheduled for completion by 801231 PARKER.W D Duke Power Co 80/06/18 ip

- DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006200594 Summary of 800423-24 meeting w/vtil & NC Municipal Power Agency Number | > site visit to assess const schedule List of attendees, agenda, presentation summary, handouts & test program summary encl HODD, D S Licensing Branch 3 80/06/06 26pp
- G Inspection reports, IE Bulletins & correspondence
- 8006060427 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" enci G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- B006040275 Forwards IE Bulletin B0-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice B0-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl G
- 8006300110 Forwards IE Circular 80-11, "Emergency Diesel Generator Lubs Oil Gooler Failures " No written response requires O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- 8006130050 Ack receipt of 800520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-413/80-06 & 50-414/80-06 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/29
- ---8006130053 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-413/80-06 & 50-414/80-06 Corrective actions weld control sheet re-examined & legible heat code remestablished
 PARKER, W.O. Duke Power Co. 80/05/20 2pp
- --8004i30056 Forwards IE Insp Repts 50-4i3/80-06 & 50-4i4/80-06 on 80040i-04 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --B006130060 Notice of violation from insp on 800401-04 * Region 2, Atlanta, Office of the Director 80/0 B0/04/23 lp
- --B006i30065 IE Insp Repts 50-4i3/B0-06 & 50-4i4/B0-06 on B0040i-04 Noncompliance noted failure to provide identifiable heat number on weld record HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch KLEINSDROE.H P Region 2. Atlanta. Office of the Director 80/04/23 Bpp
- 8006240282 Responds to IE Bulletin 80-05, "Varuum Conditions Resulting in Damage to Chemical Vol Control Sys Holdup Tanks " Lists low pressure & holdup tanks which are normally valved to contain primary sys water PARKER.W O Duke Power Co 80/06/09 2pp.
- 8006270219 Ack receipt of IE Insp Repts 50-413/80-07 & 30-414/80-07 on 800401-30 No proprietary info PARKER, W O Duke Power Co 80/06/09 1p
- -8006270222 Forwards IE Insp Repts 50-413/80-07 & 50-414/80-07 on 800401-30 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/05/20 2pp
- --8006270228 Natice of violation from insp on 800401-30
 * Region 2, Atlanta, Office of the Director 80/05 80/05/16 ip
- --8006270231 IE insp Repts 50-413/80-07 & 50-414/80-07 on 800401-30 Noncompilance noted failure to follow drawing requirements MAXWELL.OF Region 2. Atlanta. Office of the Director RAUSCH,J K. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/16 5pp

- S Reportable occurrences, LERs & related correspondence
- 8006050337 Forwards Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel equipment hatch PARKER, N O Duke Power Co 80/04/01 1p
- --8005050345 Significant Deficiency Repts 413/80-04 & 414/80-04 re improper radiography of containment vessel squipment hatch Hatch mfg by Lakeside Bridge & Steel Co & initially radiographed by McMannus Testing Lab Repairs by 800501 Bulle Power Co 80/04/01 2p
- 8006020074 PNO-II-80-085 NC news media printed allegations by const worler involving onsite safety hazards Worker contacted OSHA on 800506 following NRC referral OSHA contacted again on 800508 withdrawing previous rept RAUSCH.J K Region 2. Atlanta. Office of the Director 60/05/15
- 8006090343 Forwards Significant Deficiency 413-414/80-06 re improper radiography on steam generator enclose PARKER, W D Dute Power Co 80/06/02
- --8006090347 Significant Deficiency 413-414/80-06 re improper radiography on steam generator enclosures mfg by Lakesido Bridge & Steel Co Cause unstated Welds radiographed in accordance w/ASME Close surveillance instituted to prevent recurrence # Duke Power Co 80/06/02 1p
- 8006240411 Informs that all Unit 1 safety-related motor control ctr equipment has been inspected for proper power wire connections Necessary mods were completed firsp of Unit 2 is scheduled for completion by 801231 PARKER.W O Duke Power Co 80/06/18 1p
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BOO6120261 Expresses appreciation re visit to facilities during previous wk Mark III containment appears to be considerable improvement over Mark I & Mark II HENDRIE, J & Commission BO/04/30 ip
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria ent1 EISENHUT.D 0 Division of Licensing 80/05/20 13pp
- 8006090533 Forwards request for add1 info as result of review of FSAR & editorial comments on Soctions 7 & & 7 7 Requests that FSAR be amended to reflect responses
 BCHWENGER, A Licensing Branch 2 80/05/28 9pp
- 8006110192 Forwards drawings to support BNWL confirmatory piping analysis of Number 16 safety relief valve discharge line, in response to NRC 800214 ltr
 DALE,L F Mississippi Power & Light Co 80/06/02 2pp
- ---8006110197 "Pipe Supports Containment Main Safety Relief Valve Line-14" Sheet i of i # Bachtel Power Corp (subs of Bechtel Corp) 9545 80/04/21
- --8006110202 "Pipe Supports Containment. Main Safety Relief Valve Line-O Sheat 1 of 1

 Bechtel Power Corp (subs of Bechtel Corp.) 9445 80/04/21
- --8006110203 "Pipe Supports Containment, Main Safety Relief Valve Lins-16," Sheet 1 of 1 # Bechtel Power Corp (subs of Bechtel Corp) 9645 80/04/21
 - Pipe Supports Containment. Main Safety Relief Valve Line-Power Corp (subs. of Bechtel Corp.) 9645 80/04/21
- -8005110211 "Pipe Supports Containment, Main Safety Relief Valve Line-The supports containment, Main Bafety Relief Valve Line 16 " Skeet 1 of 2 " Bechtel Power Corp (subs of Bechtel Corp) 9643 80/04/21 ip

- --8006110215 "Pipe Supports Containment. Main Safety Relief Valve Line-16" Shoot 2 of 2 Bechtel Power Corp (sub4 of Bechtel Corp) 9645 80/04/21
- --B006110220 "Pipe Supports Containment, Hain Safety Relief Valve Line-16" Sheet 1 of 1 Bechtel Power Corp (subs of Bechtel Corp) 7645 80/04/21
- ---8004110227 "Pipe Supports Containment, Main Safety Relief Valve Line-
 - "Shagt 1 of 1 Bechtel Power Carp (subs of Bechtel Carp) 90/04/21 lp
- --8006110230 "Pipe Supports Containment, Main Safety Relief Valve Line-16" Sheet 1 of 1
 - 6" Sheet 1 of 1 Bechtel Power Corp (subs of Bechtel Corp) 80/04/21 1p
- 8006190632 Summary of 800317-21 meeting w/util & Bochtel Power Corp in Gaithersburg, ND re structural engineering audit of facilities List of attendees, request for addl info & related documentation encl HOUGHTON, T.C. Operating Reactors Branch 3 80/06/04 8pp
- BOD6190360 Forwards proprietary version of technical info requested by NRC to support review of nuclear plant structural design Proprietary affidavit encl Info withheld (ref 100FR2 790) HUFFMAN.D E Bachtel Power Corp (subs of Bechtel Corp) 4թը՝ 80/06/06
- B006260070 Forwards "For Comment" edition of NUREG-0619 Comments should be forwarded by B00707 W/o encl EIBENHUT.D G Division of Licensing B0/06/09 2pp
- 8006180462 Forwards correction to 800514 ltr which misrepresented fuel load date for Unit 1 Correct date is 810831 DALE.L F Mississippi Power & Light Co 80/06/11 lp
- --8006:80468 Corrected version of 8005:4 ltr re rescheduled fuel load date for Unit : Correct date is 81083: Requests most up-to-date & complete schedule for NRC safety review DALE, L F Mississippi Power & Light Co 80/06/11 1p
- 8006300299 Notification of 800624 meeting w/util in Bethesda.MD to discuss applicant approach to task action plan HDUGHTON,T C Licensing Branch 2 80/06/17 3pp
- 8006300467 Requests 800708-10 meeting w/NRC & consultants in Gaithersburg. MD to discuss open items of SER re FSAR Sections 3 6-3 10. inclusive Forwards proposed agenda DALE, LF Mississippi Power & Light Co 80/06/20 5pp
- 8006300637 Forwards Savannah River Lab preliminary draft review repts per 800613 telcon Info should assist in review W/o encl ROSA,F Power Systems Branch 80/06/20 ip
- C Utility Environmental Report (ER), amends & correspondence
- 8006030223 Forwards Amend 4 to final environ rept for facility Drawings available in Central Files only
 STAMPLEY,N L Mississippi Power & Light Co 80/05/27. 3pp
- --8006030229 Amend 4 to final environ rept for facility

 * Mississippi Power & Light Co * Middle South Utilities, Inc
 Middle South Services, Inc 80/05/27 13pp
- 8006160058 Forwards affidavit of svc on distribution of Amend 4 to final environ rept in accordance w/Encl 1 to NRC 780627 ltr DALE.L F Mississippi Power & Light Co 80/06/09 2pp
- F Security, medical, emergency & fire protection plans
- 8005i303i7 Forwards clarification of NRC requirements for emergency pesponse facilities defined in 7909i3 ltr Addl specific criteria for facilities under development EISENHUT, D O Division of Operating Reactors 80/04/25 61pp
- 8006300375 Forwards Amend 40 to application for DLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR, App 9B STAMPLEY, N L. Mississippi Power & Light Co. 80/06/27 ip
- --8006300382 Amend 40 to application for DLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR App 98, Certificate STAMPLEY, N L Mississippi Power & Light Go 80/06/27 2pp

- ---8006300384 Amend 40 to FSAR.providing revisions to fire protection plan & emergency plan & Mississippi Power & Light Co 80/06/27 85pp
- H General correspondence
- 8006i10310 Expresses concern that no methodology exists for citizen input to development of evacuation plan MILLER.J Affiliation Unknown 80/06/02 2pp
- BD06200381 Dutlines recent organizational changes Title of director of power production changed to assistant vice president nuclear production Production engineering section renamed nuclear plant engineering section Notification per GA manual REAVES.TE Mississippi Power & Light Co 80/06/17 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006930003 Forwards Amend 39 to FSAR & application for OLs STAMPLEY, N.L. Mississippi Power & Light Co 80/05/30 lp
- --8006030005 Application for Amend 39 to application for Ols.consisting of Amend 39 to FSAR Centificate of Svc encl
 STAMPLEY.N L. Mississippi Power & Light Co. 80/05/28 2pp
- --8004030007 Amend 39 to FSAR
 * Mississippi Power & Light Co 80/05/30 200pp
- 8006160128 Forwards affidavit of svc on distribution of Amend 39 to application for OL re FBAR per 780627 ltr
 DALE.L F Mississippi Power & Light Co 80/06/09 2pp
- BOO6300375 Forwards Amend 40 to application for OLs for Licenses GPPR-118 & CPPR-119, consisting of revisions to FBAR, App 98 STAMPLEY, N L Mississippi Power & Light Co BO/06/27 1p
- --B0063003B2 Amend 40 to application for ULs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FBAR App 9B Certificate of Storenci BTAMPLEY, N L Mississippi Power & Light Co B0/06/27 2pp
- --8006300384 Amend 40 to FSAR, providing revisions to fire protection plan
 - & emergency plan + Mississippi Power & Light Co 80/06/27 85pp

- 8006120443 Forwards notice of receipt of add1 antitrust info re proposed add1 ownership by Bouth MS Electric Power Association Legal notice for publication in various newspapers also enci BCHMENCER, A Licensing Branch 2
- --B006120447 Notice of receipt of add1 Antitrust info time for submission of views on antitrust matters
 SCHWENCER,A Licensing Branch 2 80/05/16 4pp
- 8006030350 Comments on proposed amend to CP allowing Bouth MS Power & Light Co to become co-curser No antitrust hearing necessary re-proposed amend to CP FAVRETTO, R J Justice, Dept of 80/05/23 ip
- 8006240035 Forwards notice of violation of antitrust license conditions including refusing to offer City of Clarksdale, MS & Municipal Energy Agency of MS opportunity to participate in facilities
 DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/29 3pp
- ---B004240043 Notice of violation of antitrust license conditions including refusing to offer City of Clarksdale MS & Municipal Energy Agency of MS opportunity to participate in facilities
 DENTON-N R Office of Nuclear Reactor Regulation, Director B0/05/29 12pp
- 8006190232 Forwards Atty General 800523 ltr furnishing addl antitrust info Ltr will be sent to Ofc of FR Petitions to intervene & requests for hearings may be filed by interested parties within 30 days after FR publication SALTZMAN.J Utility Finance Branch 80/05/30 [p.
- --8006190240 Advises that review of info submitted for antitrust review provides no basis to conclude that South MS Electric Power Association participation would create situation inconsistent w/antitrust laws FAVRETTO,R J Justice.Dept of 80/05/23 ip

- 8006230088 Forwards DGJ 800523 ltr containing Atty Oeneral advice that no antitrust hearing is necessary for proposed amend to CP SALTZMAN, J Utility Finance Branch 80/06/03 2pp
- 8006200345 Responds to 800529 notice of violation of CP antitrust Conditions 4(a).5(a) & 6 Denies allegation & suggests settlement to avoid delay in licensing NL Stampley 800618 ltr to Clarksdale City encl STAMPLEY.N L Mississippi Power & Light Co 80/06/18 16pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006180045 Forwards IE Insp Repts 50-416/80-02 & 50-417/80-02 on 800304-07 & notice of violation D'REILLY. J P Region 2. Atlanta, Office of the Director 80/04/14 3bb
- --8006180048 Notice of violation from insp on 800304-07
 * Region 2, Atlanta, Office of the Director 80/04/14. 1p
- --8006180051 IE Insp Repts 50-414/80-02 & 50-417/80-02 on 800304-07.

 Noncompliance noted failure to evaluate & report const deficiency in accordance w/10CFR50 55(e). Paragraph 5 GDUGE, M J. Region 2. Atlanta, Defice of the Director.

 CANTRELL.F 9 Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/14 7pp
- BO06060439 Forwards IE Bulletin BO-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-20, "Overloading of Structural Elements Due to Pipe Bupport Loads" enci O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 2pp
- 8006180386 Forwards IE Insp Repts 50-416/80-09 & 50-417/80-07 on 800415-18 No noncompliance noted MURPHY, C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/05/08 2pp
- ---8006180370 IE Insp Repts 50-416/80-07 & 50-417/80-07 on 800415-16 No noncompliance noted Major areas inspected RCPB welding, preservice & inservice insp & housekeeping HERDT. A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAME. J Region 2. Atlanta, Office of the Director 80/05/05 4pp
- BOO5040244 Forwards IE Bulletin BO-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice BO-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'RETILLY, J P Region 2, Atlanta, Office of the Director BO/05/09
- 8006300075 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/13 Don
- 8006090428 Ack receipt of 800506 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/80-02 & 50-417/80-02 MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch.
- --8006090438 Informs NRC of possible defective mat1 shipment to power plant Notification was received per encl vendor 800402 ltr.
 REILLY,M K Liberty Equipment & Supply Go 80/04/04 4pp
- 8006260343 Ack receipt of [E Insp Repts 50-416/80-10 & 50-417/80-03, No proprietary info MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/05 ip
- --8006260353 Forwards IE Insp Repts 50-416/80-10 & 50-417/80-03 on 800429-0502 No noncompliance noted MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/16 2pp
- --8006260357 IE Insp Repts 50-416/80-10 & 50-417/80-03 on 800427-0502. No noncompliance noted Major areas inspected instrumentation work: work activities & 8C records GIBBONS.T D Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/03/15 3pp
- BOO62404B7 Forwards revised response to notice of violation from insp on 800303-06, providing more detailed & updated status of notice concerns MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/17 7pp

- R Periodic operating reports & related correspondence
- 8006030375 Forwards "Summary of Environ Protection Program Respecting Const of Grand Gulf Nuclear Station Units 1 & 2 for Six Months Ending 800430 "Months Ending 800430" MC9AUGHTy JP Mississippi Power & Light Co 80/05/27 4pp
- S Reportable occurrences. LERs > related correspondence
- 8006050266 Potentially Reportable Deficiency 80/12 re design nomograph used in sizing & selection of hydramotor electrohydraulic actuators Revises 800328 cept to correctly identify ITT General Controls as vendor final rept by 800721 DALE.L F Mississippi Power & Light Co 80/04/25 2pp
- 8006060267 Part 21 rept re design nomographs used in sixing & selection of ITT General Control hydramotor electtrohyraulic actuator Nomographs may be incorrectly interpreted resulting in incorrect sixing & selection of actuators DALE, L F Mississippi Power & Light Co 80/04/25 2pp
- 8004050316 Status deficiency rept re improper bolt torque values noted on HPCS pump Vendor initiated changes to torque values Adequacy of original torquing requirements under review Final rept expected by 800804 DALE, L F Mississippi Power & Light Co 80/09/09 2pp
- 8004050387 Third interim deficiency rept re defective topaz inverters Complete corrective action plan unresolved Proposed OE mods, re installation of protective filtering devices on inverter input, under evaluation Final rept to be submitted by 800818 DALE, L F Mississippi Pawer & Light Co 80/05/15 Zpp
- BOO6110109 Interim deficiency rept re carbon filters, Type NPP-2, supplied by Farr Co Vondor reported that test equipment used for qualifying filters was unreliable Filters returned for verification of quality & reliability MCGAUGHY, J P Mississippi Power & Light Co BO/05/30 2pp
- BOO6110130 Forwards final deficiency rept for PRD-BO/24 re Commip. Inc containment gas analysis sys & BOO403 itr to NRC MCGAUGHY. J P Mississippi Power & Light Co BO/05/30 2pp
- --BOD6110166 Notifies NRC of defective Comsig. Inc containment gas analysis sys During testing. Pump K deadheaded for approx 20-s & pressure at pump outlet exceeded 150 psig Pump discharge bypass lime to be fitted VARINDIG.C Comsip. Inc., Delphi Systems Div 80/04/03 4pp
- ---800Ai10178 Final deficiency rept for PRD-80/24 re Comsip. Inc containment gas analysis sys Vendor proposed installation of bypass line on pump discharge to prevent overpressurization installation will be complete by 800B31 whississippi Power & Light Co 80/05/30, 1p
- BOO6110303 Interim deficiency rept re nonconformances associated w/ Computer Sciences Corp calibr svcs Evaluation of representative sample of calibr equipment revealed no significant deficiencies Final rept provided by BOO722 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/05/30 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to AZ34WPB requirement Investigations conducted & closed at 46 listed facilities
 BEAY, J. Chemtron Corp., Tube Turns Div. 80/06/06. 3pg
- 8006160103 Forwards interim deficiency rept re damaged instrumentation cables under reactor pressure vessel Final rept will be sent by 800811
 MCGAUGHY.J P Mississippi Power & Light Co 80/06/09 1p
- ~-8006160106 Interim deficiency rept re damaged instrumentation cable under reactor pressure vessel Approx 130 cables damaged during installation of control rod drive hydraulic eye & neutron monitoring sys Caused by restricted working area = ****-**(ssippi Power & Light Co 80/06/09 ip
 - s final deficiency rept re loose key in Bettis robot stalled on Henry Pratt butterfly valves 10CFR50 55(e) for Units 1 & 2 & 10CFR21 for
 - i Power & Light Co 80/06/11 2pp

opt re loose key in Bettis robot arm terfly valves Operators will be corientation not possible, new or installed t Co BO/O6/11. 3pp

- BOO6190577 Deficiency rept (PRD-BO/26) re GE Type SB-12 switches Questions rationals that safety function of breaker was to trip on signal from reactor protection sys Re-evaluation will be conducted & final rept filed by BOO710 MCGAUGHY, J P Mississippi Power & Light Co BO/06/12 2pp
- BOO6180287 Forwards third interim deficiency rept re failure to provide qualified instrumentation in safety-related sys Final rept will be submitted by BI0110 MCOAUGHY. J.P. Mississippi Power & Light Co. BO/06/13 2pp
- --8006:80291 Third interim deficiency rept re failure to provide qualified instrumentation in safety-related sys Corrective actions in process Action plan will be completed by 800711
 # Mississippi Power & Light Co 80/06/13 4pp
- 8006240384 Notifies that final rept & determination of potentially reportable deficiency, concerning failure of GE handswitch CR2940-US203E, will be provided by 800918 MCGAUGHY, J P Mississippi Power & Light Co 80/06/18 2pp
- 8006270284 Deficiency rept re failure of radiographs to meet ABME Code requirements Sample review of radiographs has been performed Vendor plans to make inquiry w/ABME code body & discuss w/NRC Final lept will be provided by 801020 MCOAUOHY, J P Mississippi Power & Light Co 80/06/20 2pp
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8005120261 Expresses appreciation re visit to facilities during previous wk Mark III containment appears to be considerable improvement over Mark I b Mark II HENDRIE. J M Commission 80/04/30 ip
- 8006230i10 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D Q Division of Licensing 80/05/20 13pp
- BOO6090533 Forwards request for add1 info as result of review of FBAR & editorial comments on Sections 7 & & 7 7 Requests that FSAR be amended to reflect responses SCHMENCER.A Licensing Branch 2 80/05/28 9pp
- BOO6110192 Forwards drawings to support BNML confirmatory piping analysis of Number 16 safety relief valve discharge line, in response to NRC 800214 ltr
 DALE, LF Mississippi Power & Light Ca B0/06/02 2pp
- 8006190632 Summary of 800317~21 meeting w/util & Bechtel Power Corp in Galthersburg,MD re structural engineering audit of facilities List of attendees, request for addl info & related documentation encl HOUGHTON,T C Operating Reactors Branch 3 80/06/04 8pp
- 8006190360 Forwards proprietary version of technical info requested by NRC to support review of nuclear plant structural design Proprietary affidavit encl Info withheld (ref 10CRR2 790) HUFFMAN D E Bechtel Power Corp (subs of Bechtel Corp) 80706706 4pp
- 8006260070 Forwards "For Comment" edition of NUREG-0619 Comments should be forwarded by 800707 W/o encl ECSENHUT.D G Division of Licensing 80/06/09 2pp
- 8006180462 Forwards correction to 800514 ltr which migrepresented fuel load date for Unit 1 Correct date is 810831 DALE, L.F. Mississippi Power & Light Co. 80/06/11 1p
- ---BOO61BO46B Corrected version of BOO514 ltr re rescheduled fuml load date for Unit 1 Correct date is B10B31 Requests most up-todate & complete schedule for NRC safety review DALE,LF Mississippi Power & Light Co BO/06/11 1p
- BOOA300279 Notification of 800624 meeting w/util in Bethesda.MD to discuss applicant approach to task action plan HDUQHTON.T C Licensing Branch 2 80/06/17 3pp
- BOOA300469 Requests 80070B-10 meeting w/NRC & consultants in Gaithersburg, MD to discuss open items of BER re FBAR Sections 3 6-3 10. inclusive forwards proposed agenda DALE, L.F. Mississippi Power & Light Co. 80/06/20 Spp

- 8006300637 Forwards Savannah River Lab proliminary draft review repts per 800613 telcon Info should assist in review W/o encl ROSA.F Power Systems Branch 80/06/20 1p
- C Utility Environmental Report (ER), amends & correspondence
- 8006030223 Forwards Amend 4 to final environ rept for facility Drawings available in Contral Files only STAMPLEY,N L. Mississippi Power 5 Light Co. 80/05/27 3pp
- --8006030229 Amend 4 to final environ rept for facility

 * Kississippi Power & Light Co * Middle South Utilities, Inc *
 Middle South Services, Inc 80/05/27 13pp
- BOO6160088 Forwards affidavit of svc on distribution of Amend 4 to final environ rept in accordance w/Encl 1 to NRC 780627 1tr DALE, L.F. Mississippi Power & Light Co 80/06/09 2pp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltm Addl specific criteria for facilities under development CISENHUT.D G Division of Operating Reactors 80/04/25 41pp
- 8006300375 Forwards Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSRR, App 98 STAMPLEV.N L Mississippi Power & Light Co 80/06/27 1p
- --80063003B2 Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR App 9B Certificate of Svc encl
 STAMPLEY, N L Mississippi Power & Light Co 80/06/27 2pp
- --8004300384 Amend 40 to FSAR, providing revisions to fire protection plan & emergency plan * Mississippi Power & Light Co 80/06/27 85pp
- H General correspondence
- 8006110310 Expresses concern that no methodology exists for citizen input to development of evacuation plan MILLER, J. Affiliation Unknown 80/06/02 2pp
- BOO62003B1 Outlines recent organizational changes Title of director of power production changed to assistant vice president, nuclear production Production engineering section renamed nuclear plant engineering section Notification per QA manual REAVES, T.E. Mississippi Power & Light Co. 80/06/17 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8004030003 Forwards Amend 39 to FGAR & application for OLs STAMPLEY.N L Mississippi Power & Light Co 80/05/30 ip
- --B006030005 Application for Amend 39 to application for OLs.consisting of Amend 39 to FSAR Certificate of Svc encl BTAMPLEY.N L Mississippi Power & Light Co 80/05/28 2pp
- --8004030007 Amend 39 to FSAR
 * Mississippi Power & Light Co 80/05/30 200pp
- B00616012B Forwards affidavit of svc on distribution of Amend 39 to application for OL re FBAR per 780627 ltr
 DALE.L F Mississippi Power & Light Co 80/06/09 2pp
- M Antitrust correspondence
- 8006120443 Forwards notice of receipt of addl antitrust info re proposed addl ownership by South MS Electric Power Association Legal notice for publication in various newspapers also encl SCHWENGER, A Licensing Branch 2
- --B006120447 Notice of recoipt of addl antitrust info time for submission of views on antitrust matters

 SCHWENCER, A Licensing Branch 2 60/05/16 4pp
- 8006030350 Comments on proposed amend to CP allowing Bouth MS Power & Light Co to become co-curren No antitrust hearing necessary re-proposed amend to CP FAVRETTO:R J Justice:Dept of 80/05/23 1p

- 8006240035 Forwards notice of violation of antitrust license conditions including refusing to offer City of Clarksdale.MS & Municipal Energy Agency of MS opportunity to participate in facilities

 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 800/05/29 300
- --8006240043 Notice of violation of antitrust license conditions including refusing to offer City of Clarkedale, MS & Municipal Energy Agency of MS opportunity to participate in facilities

 DENTON, HR Defice of Nuclear Reactor Regulation, Director 80/05/29 12pp
- 8006190232 Forwards Atty General 800523 ltr furnishing addit antitrust info Ltr will be sent to Ofc of FR Petitions to intervene & requests for hearings may be filed by interested parties within 30 days after FR publication SALTZMAN, J Utility Finance Branch 80/05/30 ip
- --8006190240 Advises that review of info submitted for antitrust review provides no basis to conclude that South MS Electric Power Association participation would create situation inconsistent w/antitrust laws FAVRETTO.R J Justice.Dept of 80/05/23 ip
- 800623008B Forwards DDJ 800523 ltr containing Atty General advice that no antitrust hearing is necessary for proposed amend to CP SALTZMAN.J Utility Finance Branch 80706703 2pp
- 8006200345 Responds to 800529 notice of violation of CP antitrust Conditions 4(a), 5(a) & 6 Denies allegation & suggests settlement to avoid delay in licensing NL Stampley 800618 ltr to Clarksdale City encl
 STAMPLEY.N L Mississippi Power & Light Co 80/06/18 16pp
- G Inspection reports. IE Bulletins & correspondence
- 8006180045 Forwards IE Insp Repts 50-416/80-02 & 50-417/80-02 on 800304-07 & notice of violation O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/14 3pp
- --8006180048 Notice of violation from insp on 800304-07
 * Region 2, Atlanta, Office of the Director 80/04/14 ip
- --B006180051 IE Insp Repts 50-416/80-02 & 50-417/80-02 on \$00304-07 Noncompliance noted failure to evaluate & report const deficiency in accordance w/10CFR30 55(e).Paragraph 5 OOUGE.M J Region 2. Atlanta. Office of the Director CANTRELL.F 9 Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/14 7pp
- 8006060439 Forwards IE Bulletin 80-11. "Masonry Hall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- 9006180386 Forwards IE Insp Repts 50-416/80-09 & 50-417/80-07 on 800415-18 No noncompilance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/08 Rpp
- --B006iB0370 IE Insp Repts 50-4i6/B0-09 & 50-4i7/B0-07 on 8004i5-iB No noncompliance noted Major areas inspected RCPB welding, preservice & inspervice insp & housekeeping HERDT.A R Region 2. Ablanta, Reactor Construction & Engineering Support Branch BLAKE.J Region 2. Atlanta, Office of the Director 80/05/05 4p
- 8006040244 Forwards IE Builetin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/09 200
- 800&300075 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube 011 Cooler Failures" No written response required 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/13 2pp
- BOOA090428 Ack receipt of B00306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/80-02 & 50-417/80-02 MMRPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/23 ip

- --8005090438 Informs NRC of possible defective matl shipment to power plant Notification was received per encl vendor 800402 ltr REILLY,M K Liberty Equipment & Supply Co 80/04/04 4pp
- 8006260343 Ack receipt of IE Insp Repts 50-416/80-10 & 50-417/80-03 No proprietary info HCGAUGHY, J P Mississippi Power & Light Co 80/06/05 ip
- --8008280353 Forwards IE Insp Repts 50-416/80-10 & 50-417/80-03 on 800429-0502 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/16 2pp
- --8006260337 IE Insp Repts 50-416/80-10 & 50-417/80-03 on 800429-0502 No noncompliance noted Major areas inspected instrumentation work work activities & GC record of the Director OTBEONS.T D Region 2. Atlanta. Office of the Director CCM.CON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/15 3pp
- 8006240487 Forwards revised response to notice of violation from inspon 800303-06, providing more detailed & updated status of notice concerns

 MCGAUGHY, J.P. Mississipp: Power & Light Co. 80/06/17. 7pp
- R Periodic operating reports & related correspondence
- BOOA030375 Forwards "Summary of Environ Protection Program Respecting Const of Grand Gulf Nuclear Station Units 1 & 2 for Six Months Ending BO0430" MCOAUGHY, J P Mississippi Power & Light Co 80/05/29 App
- S Reportable occurrences, LERs & related correspondence
- B006050266 Potentially Reportable Deficiency B0/12 re design nomograph used in sizing & selection of hydramotor electrohydraulic actuators Revises B00328 rept to correctly identify ITT Centeral Controls as vendor Final rept by B00721 DALE, L F Mississippi Power & Light Co B0/04/25 2pp
- 8004040247 Part 21 rept re design nomographs used in sizing & selection of ITT General Control hydramotor electrohyraulic actuator. Nomographs may be incorrectly interpreted resulting in incorrect sizing & selection of actuators DALE.L F Mississippi Power & Light Co 80/04/25 2pp
- 8006050316 Status deficiency rept re improper bolt torque values noted on HPCB pump Vendor initiated changes to torque values Afequacy of original torquing requirements under review, Final rept expected by 800804 DALE, LF Mississippi Power & Light Co 80/05/09 2pp
- BOO4090357 Third interim deficiency rept re defective topar inverters. Complete corrective action plan unresolved Proposed OE mode: re installation of protective filtering devices on inverter input-under evaluation Final rept to be submitted by BOOBIS DALE, L. F Hississippi Power & Light Co BO/05/15. 2pp.
- BOOA:10109 Interim deficiency rept re carbon filters. Type NPP-Q: supplied by Farr Co. Vendor reported that test equipment used for qualifying filters was unreliable Filters returned for verification of quality & reliability MCGAUOHY, J.P. Mississippi Power & Light Co. BO/05/30 2pp.
- SOO6110150 Forwards final deficiency rept for PRD-B0/24 re Commip.Inc containment gas analysis sys & 800403 ltr to NRC MCGAUGHY, J P Mississippi Power & Light Co 80/05/30, 2pp
- --B006110166 Notifies NRC of defective Commission Inc containment gas analysis sys During testing. Pump K deadheaded for approx 20-s & pressure at pump outlet exceeded 150 psig Pump discharge bypass line to be fitted VARINGIE. C Commission. Delphi Bystems Div. B0/04/03. 4pp
- --8006i10i78 Final deficiency rept for PRD-80/24 re Comsip. Inc containment gas analysis sys Vendor proposed installation of 6ypass line on pump discharge to prevent overpressurization installation will be complete by 800831.

 * Hississippi Power & Light Co 80/03/30, ip.
- BO06110303 Interim deficiency rept re nonconformances associated w/ Computer Boiences Corp calibr svos Evaluation of representative sample of calibr equipment revealed no significant deficiencies Final rept provided by 800722 MCGAUGHY, J.P. Mississippi Power & Light Co. B0/05/30. 2pp

- 8006200024 Final Part 21 reptive mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch ters were mfg to A234WPB requirement investigations conducted & closed at 46 listed facilities SEAY. J. Chemtron Curp., Tube lurns biv 100/06/06 Jpp
- BOD6160103 Forwards interim deficiency rept to damaged Instrumentation cables under reactor presente vossel Final tept will be sent by BOD611

 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/09 ip
- --8006/60106 Interim deficiency rept to damaged instrumentation cable under reactor pressure vessel Approx 130 cables damaged during installation of control and drive hydraulic sys & neutron monitoring sys Caused by restricted working erea + Kississippi Power / light Co 80/06/09 tp
- B006180237 Forwards final deficiency rept re loose key in Bettie robot arm actuators installed on Henry Pratt butterfly valves Reportable under 1007R30 33(e) for Units 1 & 2 & 1007R21 for Unit 1 only MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/11 2pp
- --B0061B0251 Final deficiency rept re loose key in Bettis robot are actuator for Henry Pratt butterfly valves Operators will be reoriented if possible if reorientation not possible new keys of longer length will be installed # Mississippi Power & Light (o 100/06/11 Tpp
- 8006190877 Deficiency rept (PRD 80/26) re QE Type 88-12 switches Questions rationals that pafety function of breaker was to trip on signal from reactor protection eye Re evaluation will be conducted & final rept filed by 100710 MCGAUQHY, J.P. Mississippi Power & Light CO 80/06/12 2pp
- 8006180287 Forwards third interim deficiency mept me failure to provide qualified instrumentation in safety-related sys final mept will be submitted by 810110 MCOAUCHY. J.P. Mississippi Power & Light Co. 100/06/13 2pp
- ---8006190291 Third interim deficiency rept re failure to provide qualified instrumentation in safety-related sys Corrective actions in process Action plan will be completed by 800/11 # Mississippi Power & Light Co. 800/06/13 4pp
- 8006240384 Notifies that final tept & determination of potentially reportable deficiency, concerning failure of QF handswitch CR2740-US203E, will be provided by 800918 MCQAUGNY, J.P. Mississippi Power & Light Co. 80/06/18, 2pp
- 8006270284 Deficiency rept re failure of radiographs to meet ABME Code requirements Bample review of radiographs has been performed Vendor plans to make inquiry w/ABME code body & discuss w/NRC Final rept will be provided by 801020 MCGAUGHY-J P Mississippi Power & Light Co 80/06/20 2pp
- DOCKET 80-423 MILLBTONE NUCLEAR POHER BIATION, UNIT 3

 A Application/construction stage documents & correspondence
- BOOA230110 Advises BMR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NURRG-0577 readsquary of applicable support structures General operating reactor review procedure & acceptance criteria and EISENHUT, D O Division of Licensing HO/05/HO 13pp.
- H Caneral correspondence
- 8006170464 Advises of personnel change FJ Mroczka relieved JF Opeka as station superintendent on 800601 MRGCZKA,E J Northeast Utilities 80/06/02 1p
- Q Inspection reports. If Bulletine & correspondence
- 8006250173 Forwards IC Insp Rapt 50-423/80-02 on 800401-02 No noncompliance noted CARLEGURR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/14 2pp.
- --8006250176 IE Insp Rept 50-423/80-02 on 800401-02 No noncompliancy noted. Major areas inspected concrete placement, pressuriser rigging & installation, reactor vassel storage & previous insp findings MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch CERNE, A C, VARELA, A A Region 1, Philadelphia, Office of the Director, 80/05/07 7pp

- B006200037 Forwards IE Circuler 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- S Reportable occurrences, LERs & related correspondence
- 8006090469 Ack receipt of 800415 interim deficiency rept re guide tube support pin cracking Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/04 1p
- --8006090474 Interim deficiency rept re cracking of control rod guide tube support pins Cracking restricted to pins solution annealed below 1,800 F Cracking of tube support pins have potential for release of loose parts into upper core region COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/04/15 ip
- 8006250401 Ack receipt of 800508 final deficiency rept re component cooling water heat exchanger supports CARLSDN,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 IP

DOCKET 50-424 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006180377 Responds to NRC 800421 1tr requesting info re use of concrete masonry walls in Category 1 structures No masonry walls used in Category 1 structures No need to answer Questions 2-6 EHRESNERGER.N Georgia Power Co

I Financial information

- 8006170310 Forwards Annual Financial Repts 1979 WIDNER,W A Georgia Power Co 80/06/11 ip
- --8006170314 Annual Financial Rept 1979 * The Southern Co 80/03/10 43pp
- --8006170318 Annual Financial Rept 1979 * Georgia Power Co 80/02/28 38pp
- Q Inspection reports. IE Bulletins & correspondence
- 8006030581 Forwards IE Insp Repts 50-424/80-06 & 50-425/80-06 on 800331-0402 No noncompliance noted STDMR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/04/21 2pp
- ---8006030585 IE Insp Repts 50-424/80-06 & 50-425/80-06 on 80033i-0402 No noncompliance noted Major areas inspected environ protection, erosion & runoff control & const effects monitoring
 JENKING, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch CUNNINGHAM.A L Region 2, Atlanta, Office of the Director 80/04/18 5pp
- 8006130042 Forwards IE Insp Repts 50~424/80~08 ක 50~425/80~08 on 800415-17 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- ---8006130054 IE Insp Repts 50-424/80-08 & 50-425/80-08 on 800415-17 No noncompliance noted Major areas inspected const deficiency repts & IE bulletins & circulars RAUSCH, J K Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch HUNT: M D Region 2, Atlanta, Office of the Director 80/05/01 4pp
- 8006060498 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" ancl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08

- B006040226 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice B0-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07 200
- 8006300119 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director BO/05/13 200
- B006190135 Ack receipt of 1E Insp Repts 50-424/80-08 & 50-425/80-08 No proprietary info DUTTON, D Georgia Power Ca B0/Q6/05 1p
- 8006240279 Anticipates response to IE Bulletin 80-05 re vacuum condition resulting in damage to holdup tanks will be submitted by 800731 Util 616 not receive bulletin until 800606
 DUTTON, D Georgia Power Co 80/06/07 ip
- S. Reportable occurrences, LERs $\boldsymbol{\delta}$ related correspondence
- 8006040164 Ack receipt of 800502 ltr providing interim followup to 800131 rept re possible deficient pipe support designs Actions will be reviewed at mext insp BEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/12
- --8006060170 Interim followup to B00131 rept re possible pipe support design deficiency Pipe support review will take longer than three months Completion expected by June 1980. Current status of corrective actions includes review of 5.760 supports

 LEX.B L Bechtel Power Corp (subs of Bechtel Corp) 80/05/02

 3po
- --8006060204 Confirms 800129 telcon re possible pipe support design deficiency Written rept will be filed by 800201 covering nature of deficiency, investigative & evaluative actions taken Investigation should take 90 days

 LEX.B L Bechtel Power Corp (subs of Bechtel Corp) 80/01/29
- B006270337 Advises that potential discrepancies in 791121 final significant deficiency rept or embed plate assembly have been avaluated Corrective action noted is adequate & has been effected DUTTON.D Georgia Power Co 80/06/20 2pp
- DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing. 80/05/20 13pp
- .8006180379 Responds to NRC 800421 ltr requesting info re use of concrete masonry walls in Category 1 structures No masonry walls used in Category 1 structures. No need to answer Questions 2-4 EHRESNPERGER. W. Georgia Power Co. 80/06/12 lp
- I Financial information
- BOO6170310 Forwards Annual Financial Repts 1979 WIDNER, W A Georgia Power Co. BO/06/11 1p
- --8006170314 Annual Financial Rept 1979 * The Southern Co 80/03/10 43pp
- ~~8006170318 Annual Financial Rept 1979 * Oporgia Power Co 80/02/28 38pp
- Q Inspection reports. IE Bulletine & correspondence
- 800&030581 Forwards IE Insp Repts 50-424/80-06 \$ 50-425/80-06 on 800331-0402 No noncompliance noted STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/21 2pp

- ---8006030585 IE Insp Repts 50-424/80-06 & 50-425/80-06 on B00331-0402 No noncompliance moted Major areas inspected environ protection erosion & runoff control & const effects manitoring
 JERNINB: 0 R Region 2. Atlanta, Fuel Facility & Materials Bafety
 Branch CUNNINGMAM. A t. Region 2, Atlanta, Office of the Director 80/04/18 5pp
- 8006630042 Forwards IE Insp Repts 90-424/80-08 & 50-425/80-08 on 800455-17 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --800Ai30054 IE Insp Repts 50-424/80-08 & 50-425/80-08 on 800415-17 No noncompliance noted Major areas inspected const deficiency repts & IE bulletins & circulars RAUSCH.J K Region 2, Atlanta, Reactor Construction & Engineering Support Branch HUNT,M D Region 2, Atlanta, Office of the Director 80/05/01 4pp
- 8006060498 Forwards IE Bulletin 80-11. "Nasonry Hall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Bupport Loads" encl
 O'REILLY-J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006040226 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Hode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07 20s
- 8006300119 Forwards IE Circular BO-11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, BO/05/13 200
- 8006190135 Ack receipt of IE Insp Repts 50-424/80-08 & 50-425/80-08 No proprietary info DUTTON.D Osergia Power Co 80/06/05 1p
- 8006240279 Anticipates response to IE Bulletin 80-05 re vacuum condition resulting in damage to holdup tanks will be submitted by 800731 Util did not receive bulletin until 800606 BUTTON D Georgia Power Co 80/06/09 ip
- S Reportable occurrences, LERs & related correspondence
- 8005050154 Ack receipt of 800502 ltr providing interim followup to 800131 rept re possible deficient pips support designs Actions will be reviewed at next insp SEYFRIT. X V Region 4. Dailas. Office of the Director 80/05/12
- --9006060170 Interim followup to 800131 rept re possible pipe support design deficiency Pipe support review will take longer than three months Completion expected by June 1980 Current status of corrective actions includes review of 5.760 supports LEX.B L Bechtel Power Corp (subs of Bechtel Corp) 80/05/02 300
- --9006060204 Confirms B00129 betcon re possible pipe support design deficiency Written rept will be filed by B00201 covering nature of deficiency, investigative & evaluative actions taken Investigation should take 90 days

 LEX.B L. Bethtel Power Corp. (subs. of Bechtel Corp.) 80/01/29
- 800&270337 Advises that potential discrepancies in 791121 final significant deficiency rept re embed plate assembly have been evaluated Corrective action noted is adequate & has been effected
 DUTTON. D. Georgia Power Co. HO/O6/20 Pag.
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8006030425 Informs that revised physical security plan has been completed except for internal review Plan should be submitted in approx i with PROFIG.A E California, Univ of, Ganta Barbara 80/05/27 ip
- 8006230518 Forwards revised physical security plan for L-77 educational nuclear reactor Plan withheld (ref 100FR2 790)
 KROES,R J California, Univ of, Santa Barbara 80/06/18 ip

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- 8006230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing B0/05/20 13pp
- 8006090477 Bummary of 800430 meeting w/applicant in Bethesda,MD re near-term mfg license requirements from TMI-2 accidents BIRKEL,R A Licensing Branch 1 80/05/28 16pp
- 8006300316 Forwards reorganization chart for Dfc of Nuclear Reactor Regulation Facility licensing matters will be handled by R Birkel Transition being made w/min of disruption to ongoing activities TEDEGEO.R L. Assistant Director for Licensing 80/06/12 3pp
- O Adjudicatory correspondence
- BD06030145 Advises that status rept to progress of vendor application review will be submitted on B00731 Per B00506 ltm.NRC will respond to post-TMI Action Plan items in Jul 1980 Upon receipt applicant responses will be evaluated for SER suppl SOHINKI.S M Hearing Branch 3 B0/05/30 1p
- 8 Advisory Committee on Reactor Safeguards reports & correspondence
- 8005280076 Forwards MS Piesset 800416 ltr re suggestions & recommendations for floating nuclear plant core ladia design Specifica 800523 as compliance deadline & urges preparation for signature of executive director PLESETINS ACRS Advisory Committee on Reactor Safeguards 80/04/17 Ip
- --8005280079 Advises that review of vendor proposed core ladle design / j floating plant, was completed during 800410-12 meeting Design adequate but planned tests & analytical programs must firm present operation estimates prior to const PLESSET: N S ACRS - Advisory Committee on Reactor Safeguards 80/04/16 3pp
- BOOG180544 Responds to BOO416 recommendation that consultant be engaged re design of high temp melting furnaces & handling of high temp molten matis Contract w/Applied Science Associates. Inc implemented on BOO417 ROSS.D F Division of Systems Integration BO/06/04 2pp
- --8004180556 Suggests effort he made to establish acceptable frequercy for accident in which molten core reaches ocean & criteria for limiting accidental liquid releases Consultant should be engaged in design of high temp melting furnaces PLESSET.N S ACRS Advisory Committee on Reactor Safeguards 80/04/16 3pp
- BOOA180540 Confirms BOOA17 implementation of technical assistance contract w/Applied Science Associates. Inc. to perform core melt matis interaction evaluations Annual progress repts will be forwarded ROSS: D F Division of Systems Integration 80/06/04 is
- G Inspection reports, IE Bulletins & correspondence
- 9006060434 Forwards IE Bulletin BO-11, "Masonry Hail Design " No actice or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" entl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/08 is
- 8006050302 Forwards IE Bulietin BO-12. "Decay Heat Removal Bys Cperability " No written response required IE Info Notice BO-20. "Loss of Decay Heat Removal Capability at Davis-Desse Unit I While in Refueling Mode" encl D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/09 ip
- 8005300077 Forwards IE Circular 80-ii. "Emergency Diesel Generator Lusa Dil Cooler Failures " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 lp

ļ

- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 9006230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D © Division of Licensing 80/05/20 13pp
- 8006020338 Responds to NRC 800424 ltr re INRYCO tendon installations & related GA/QC activities Util has approved training procedures Following training of GC inspectors, INRYCO will resume installation Comments re procedures requested MILLS, L. H. Tennessee Valley Authority 80/05/21 2pp
- 8006030366 Forwards response to OD Parr 800325 supplemental request for add1 info re changes & studies proposed in Encl F of 791203 response to initial request Continued const justified MILLS, L M Tennessee Valley Authority 80/05/30 200pp
- 8006:103:5 Forwards study plan for monitoring water quality & equatic biological conditions in Guntersville reservoir, per Part III 7 of NPDES Permit AL0024635 EL-ASHRY, M T Tennessee Valley Authority 80/06/03 12pp.
- 8006120282 Responds to NRC 800424 ltr requesting info re INRYCO tendon installation operations & related QA/QC activities, INRYCO training satisfactorily completed & resumption of tendon cutoff receiving activities & storage planned MILLS,L M Tennessee Valley Authority. 80/06/05 1p
- 8006260049 Forwards request for add1 info re instrument & control sys for continuing review of application for OLs. YOUNGBLOOD, B. J. Licensing Branch 1 80/06/11. 11PP
- B006300310 Forwards reorganization chart for DFc of Nuclear Reactor Repulation Facility licensing matters will be handled by R Bournia. Transition being made w/min of disruption to ongoing activities
 TEDEBCO.R L Assistant Director for Licensing 80/06/12 2pp.
- 8006240405 Responds to NRC 800424 itr re INRYCO tendon installation operations & related GA/GC activities Util has approved, w/ corrections as noted, encl addl training procedures.
 MILLS, L M Tennessee Vallay Authority 80/06/18 3pp.
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for amergency response facilities defined in 790913 ltr Addl specific criberts for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 61pp
- 8006060274 Forwards addl info to training & qualification plan. Info withheld (ref 10CFR2 770) MILLS.L M Tennessee Vallay Authority 80/06/02 2pp
- Q Inspection reports, IE Bulletins & correspondence
- BOOSOSOT Forwards IE Bulletin 80-11, "Masonry Hall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/06
- 8004040267 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Bassa Unit 1 While in Refueling Mode" encl D
- 8005:20034 Forwards IE Circular 80-1:, "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required, D'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/05/13
- 8006120033 Ack receipt of 800515 ltr informing NRC of steps taker to correct violations noted in IE Insp Repts 50-438/80-04 & 50-439/80-04. MURPHY.C.E. Region 2: Atlanta, Reactor Construction & Engineering Support Branch. 80/05/22 2pp.

- --8006120037 Responds to NRC 800423 ltr re violations noted in IE Insp Repts 50-438/80-04 & 50-439/80-04 Corrective actions frequency of documented survaillance to ensure smalld openings an piping equipment increased to once per week MILL8.L M Tennessee Valley Authority 80/03/13 3pp
- --8006120039 Forwards IE Insp Repts 50-438/80-04 & 50-439/80-04 on B00318-21 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch B0/04/23 2pp
- --8004120043 Notice of violation from insp on 800318-21
 * Region 2, Atlanta, Office of the Director 80/0 BO/04/21 1o
- --8006120041 IE Insp Repts 50-438/80-04 & 50-439/80-04 on 800318-21 Noticempliance noted failure to follow procedure for capping & sealing during piping sys fabrication & to provide appropriate criteria in insp procedures

 HERDI. AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch COLEY, J L., KLEINSORGE, W P Region 2, Atlanta, Support Branch COLEY, J L , KLEINSORGE, W P Office of the Director 80/04/21 App Region 2, Atlanta,
- 8006230321 Ack receipt of 800602 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-438/80-06 & 50-439/80-06 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/09 2pp
- --8004230327 Responds to NRC 800505 ltr re violetions noted in IE Insp Repts 50-439/80-06 & 50-439/80-06 Corrective actions work release written to rework Conduit 1A3-6014-D to eliminate chance of misroute Cables reinstalled MILLS:L M Tennessee Valley Authority 80/04/02 3pp
- --8006230331 Forwards IE Insp Repts 50-438/80-06 & 50-439/80-06 on 800415-18 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/05 2pp
- ---8005230332 Notice of violation from insp on 800415-18.
 * Region P. Atlanta. Office of the Director 80/0
- ~~8006230336 IE Insp Repts 50-438/80-06 % 50-439/80-06 on 800415-18 206230336 IE Insp Repts 30-433/80-06 % 30-433/80-06 on Mu0413-18 Moncompliance noted failure to follow procedures on installation & insp of safety-related cables CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch IERRIMEATHER.II. GIBBONS,T D Region 2. Atlanta. Office of the Director 80/05/05 4pp
- 8006240260 Forwards resconse to It Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freore protection for refueling water storage tank at Sequeyah & Watts Dur is provided by redundant heaters & tank insulation MILLGL M Tennessee Volley Authority 80/06/09 Spp
- 8006270191 Ack receipt of 800919 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/80-05 & 50-439/80-05 MURPHY: C. Region 2. Atlanta, Reactor Construction & Engineering Support Granch 60/06/10 2pp
- --B006270197 Responds to NRC B00424 ltr re violation noted in IE Insp Repts 50-438/80-05 & 50-439/80-05 Corrective actions closer watch on matls storage insp will be undertaken Inspectors' training program will be established MILLS.L M Tennessee Valley Authority B0/05/19 3pp
- --8006270207 Forwards IE Insp Repts 50-438/80-05 & 50-439/80-05 on 800402-04 & notice of violation MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --8006270211 Notice of violation from insp on 800402-04
 * Region 2, Atlanta, Office of the Director 80/0 80/04/23 1p
- --8006270214 IE Insp Repts 50-438/80-05 & 50-439/80-05 on 800402-04
 Noncompliance noted failure to maintain proper storage of
 prestressing sys components & failure to maintain accurate
 quality records
 LENAHAN.J J Region 2, Atlanta, Office of the Director
 CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/04/23 7pp
- 5 Reportable occurrences, LERs ≯ related correspondence
- 8006)10263 Forwards first interim deficiency rept re welding of structural steel annulus floor framing MILLS.L M Tennessee Valley Authority 80/05/15 (p

- 800Ai10285 First interim deficiency rept re welding of structural steel annulus floor framing Records completed improperly will be invalidated & affected welds will be reinspected Inspectors will be reinstructed on completion of GC records * Tennetsee Valley Authority 80/05/15 1p
- 004060383 Forwards first interim deficiency rept re const QA audit deficiency
 MILLS, L. M. Tennessee Valley Authority 80/05/30 to
- -800.6060387 First interim deficiency rept to const GA audit deficiency GA audit revealed that three welders & all welder foremen were not included in GA training/re-training outlined in BO0206 ltr to NRC Personnel are being re-trained * 'Tennessee Valley Authority 80/05/30 19
- 006090334 Forwards RE 50-438/80-06-01 Tennessee Valley Authority 80/06/02 ip
- -8006090337 RD 50-438/80-06-01 improperly routed safety-related cables were found to be inspected & accepted by GC Caused by inspectors & electrical Craft foreman Tennessee Valley Authority 80/05/02 200
- 006090471 Forwards final deficiency rept re Rustin fire dampers MILLB.L M Tennessee Valley Authority 80/06/02 is
- -8006090476 Final deficiency rept re Ruskin fire dampers Closure spring detaches from mounting bracket on Ruskin vertical spring closure. IBD fire dampers Alternative fix of small metal clamp developed & snap-in strip installed to hold blade e Tennessee Valley Authority 80/06/02 ip
- 004110074 Forwards fourth interim deficiency rept re defective seat ring seal welds on Borg-Warner valves MILLS.L M Tennessee Valley Authority 80/06/03 ip
- -800.611.0079 Fourth interim deficiency mept to defective seat ring seal walds on Borg-Harner valves Util insp completed on representative sample of 93 valves Four valves failed liquid penetrant insp
 * Tennessee Valley Authority 80/06/03 ip
- 006110328 Forwards second interim deficiency rept re lack of internal purge on two welds in chemical addition & boron recovery sys Next rept will be submitted by 800723
 HILLS.L M Tennessee Valley Authority 80/06/03 ip
- -800&110333 Second interim deficiency rept we lack of internal purge on two welds in chemical addition & boron recovery sys. Welds made by welders FANN, FAOI. FANO & FANN investigated Unacceptable welds will be reworked & training implemented a Tennessee Valley Authority 80/08/03 2pp
- 00&i10139 Discusses deficiency rept re welding in waste disposal sys Forwards add1 lab data requested in 800511 telcon.in response to IE comments on revised final rept W/o encl MILLS.L M Tennessee Valley Authority 80/06/04 ip
- 006230488 Forwards add1 lab data in response to NRC 800511 telcon request re deficiencies in welding for waste disposal sys M/o enc!
 MILLS, L M. Tennessee Valley Authority 80/06/04 1p
- 1006170485 Forwards first interim deficient rept re defective fillet welds Next rept will be submitted by 800919 MILLE.L M Tennessee Valley Authority 80/06/06 1p
- -8006170489 First interim deficiency rept re deficient fillet welds Socket & flange fillet welds will be reinspected GA procedures have been revised & reissued to reflect ABME code requirements * Tennessee Valley Authority 80/06/06
- 3006200024 Final Part 21 rept re mixed heat of steel supplied by UB Steel from which 4-inch elbows & 2-inch tees were mfg to AZ34MPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J.L Chemtron Corp . Tube Turns Div 80/06/96 3pp
- 300A250227 Forwards second revised final deficiency rept re blown fuses in low voltage switchgear MILLS.L M Tennessee Valley Authority 80/06/20 ip
- --BOO6250230 Second revised final deficiency rept re blown fuses in low voltage switchgear To avoid possibility of fuse opening on innush currents.3-amp fuse will be replaced w/6-amp fuse Tennessee Valley Authority 80/06/20 ip

- DOCKET 50-439 RELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp
- 8006ii03iS Forwards study plan for monitoring water quality & aquatic biological conditions in Guntersville reservoir.per Part III 7 of NPDES Permit AL0024635 EL-ASHRY,M T Tennøssee Valley Authority 80/06/03 12pp
- B006260049 Forwards request for add1 info re instrument & control sys for continuing review of application for OLs YOUNGBLOOD, B J Licensing Branch 1 80/04/11 11PP
- 8006300310 Forwards reorganization chart for Ofc of Nuclear Reactor Regulation Facility licensing matters will be handled by R Bournia Tiansition being made w/min of disruption to ongoing activities TEDESCORL Assistant Director for Licensing 80/06/12 2pp
- 8006030366 Forwards response to OD Parr 800325 supplemental request for addl info re changes & studies proposed in Encl F of 791203 response to initial request Continued const justified MILLS. L M Tennessee Valley Authority 80/09/30 200pp
- F Security, medical, emergency & fire protection plans
- B005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT, D O Division of Operating Reactors B0/04/25 61pp
- 8008060274 Forwards addl info to training & qualification plan Info withheld (ref 100fR2 790) MILLS.L M Tennessee Valley Authority 80/06/02 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8006060157 Forwards IE Bulletin 80-ii, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006040267 Forwards IE Bulletin 80-12. "Decay Heat Removal 8ys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" enci 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/09
- B006120034 Forwards IE Circular 80-ii. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/05/13
- B006120033 Ack receipt of B00815 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-04 & 50-439/80-04 MNRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/22 2pp
- --8006120037 Responds to NRC 800423 ltr re violations noted in IE Insp Repts 50-438/80-04 & 50-439/80-04 Corrective actions frequency of documented surveillance to ensure scaled openings on piping aquipment increased to once per week MILLS,L M Tennessee Valley Authority 80/05/15. 3pp
- --8006120039 Forwards IE Insp Repts 50-438/80-04 & 50-439/80-04 on 800318-21 & notice of violation MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- ~-9006120043 Notice of violation from insp on 800318-21 * Region 2, Atlanta, Office of the Director 80/0 80/04/21 ip.

- --8006120041 IE Insp Repts 50-438/80-04 & 50-439/80-04 on 800318-21 206120041 IE Insp Repts 50-4,38/80-04 & 50-439/80-04 en BOU318-21
 Noncompliance noted failure to follow procedure for capping
 & sealing during piping sys fabrication & to provide
 Appropriate criteria in insp procedures
 HERDT, A.R. Region 2. Atlanta. Reactor Constitution & Engineering
 Support Branch COLEY. J. L. KLEINSORGE, W.P. Region 2. Atlanta.
 Office of the Director 80/04/21 App
- 8006230321 Ack receipt of 800602 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/80-06 & 50-439/80-06 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/09 2pp

- --8004230327 Responds to NRC BG0505 ltr re violations noted in IE Insp Repts 50-438/80-06 & 50-439/80-06 Corrective actions work release written to rework Conduit 1A3-6014-B to eliminate chance of misroute Cables reinstalled MILLB,L M Tennessee Valley Authority 80/06/02 3pp
- --8006230331 Forwards IE lasp Repts 50-438/80-06 & 50-439/80-06 on 800415-18 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/05 2pp
- -8006230332 Natice of violation from insp on 800415-18 Region 2, Atlanta, Office of the Director 80/0 80/05/05 10
- ---8006230336 IE Insp Repts 50-438/80-06 & 50-439/80-06 on 800415-18
 Noncompliance noted failure to follow procedures on instablation & insp of safety-related cables
 CUNLONTE Region 2. Atlanta, Reactor Construction & Engineering Support Branch MERRIMEATHER, N. GIBBONE, T.D. Region 2. Atlanta, Office of the Director 80/05/05 App
- 8006240260 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Bequoyah & Watts Bar is provided by redundant heaters & tank insulation MILLS.L M Tennessee Valley Authority 80/06/09 8pp
- 8006270191 Ack receipt of 800319 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-438/80-05 & 50-439/80-05 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/10 2pp
- --8006270197 Responds to NRC 800424 ltr re violation noted in IE Insp Repts 50-438/80-05 \$ 50-439/80-05 Corrective actions closer watch on matis storage insp will be undertaken Inspectors' training program will be established MILLB.L M Tennessee Valley Authority 80/05/19 3pp
- --8006270207 Forwards IE Insp Repts 50-438/80-05 & 50-439/80-05 on 800402-04 & notice of violation MVRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Brench 80/04/24 2pp
- --8006270211 Notice of violation from insp on 800402-04
 * Region 2, Atlanta, Office of the Director 80/0 80/04/23 1p
- --8006270214 IE Insp Repts 50-438/80-05 & 50-439/80-05 on 800402-04
 Noncompliance noted failure to maintain proper storage of prestressing sys components & failure to maintain accurate quality records
 LENAHAN.J J Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/23 7ρρ
- S Reportable occurrences, LERs & related correspondence
- 8006110263 Forwards first interim deficiency rept re welding of structural steel annulus floor framing MILLBLE M Tennessee Valley Authority 80/05/15 ig
- --8005110285 First interim deficiency rept re welding of structural steel annulus floor framing Records completed improperly will be invalidated to affected welds will be reinspected Inspectors will be reinstructed an completion of GC records * Tennessee Valley Authority 80/05/15 ip
- 8006060383 Forwards first interim deficiency rept re const QA audit deficiency MILLS.L M Tennessem Valley Authority 80/05/30 ip
- --8006060387 First interim deficiency rept re const GA audit deficiency GA audit revealed that three welders & all welder foremen were not included in GA training/re-training outlined in 800206 ltr to NRC Personnel are being re-trained * Tennessee Valley Authority 80/05/30 1p

- 8006090471 Forwards final deficiency rept re Ruskin fire dampers MILLS.L M Tennessee Vailey Authority 80/06/02 1p
- --B006090476 Final deficiency rept re Ruskin fire dampers Closure sp detaches from mounting bracket on Ruskin vertical spring closure, IBD fire dampers Alternative fix of small metal clamp developed & snap-in strip installed to hold blade s Tennessee Valley Authority 80/06/02 ip
- 8006110074 Forwards fourth interim deficiency rept re defective seat ring seal welds on Bory-Warner valves
 MILLS.L M Tennessee Valley Authority 80/06/03 ip.
- --8006i10079 Fourth intersm deficiency rept re defective seat ring so welds an Borg-Marner valves Util (nap completed on representative sample of 93 valves Four valves failed liquid penetrant insp * Tennasses Valley Authority 80/06/03 ip
- 8006110328 Forwards second interim deficiency rept re lack of interna purge on two welds in chemical addition & boron recovery sys Next rept will be submitted by 800723 MILLS,L M Tennessee Valley Authority 80/06/03 ip
- --8006110333 Second interim deficiency rept re lack of internal purge two welds in chemical addition & boron recovery sys Welds made by welders FANN, FADI, FANO & FAMN investigated Unacceptable welds will be reworked & training implemented * Tennessee Valley Authority 80/06/03 2pp
- 8006110138 Discusses deficiency rept re-welding in waste disposal sys Forwards addi lab data requested in 800511 telcon.in response to IE comments en revised final rept W/O encl MILLS.L M Tennessee Valley Authority 80/06/04 ip
- 8006230498 Forwards add1 iab data in response to NRC 800511 telcon request re deficiencies in welding for waste disposal sys W/o encl
 M/LLB,L M Tennessee Valley Authority 80/06/04, 1p
- 8006170483 Forwards first interim deficient rept re defective fillet welds Next rept will be submitted by 800919 MILLS,L M Tennessee Valley Authority 80/06/06 ip
- --8006170489 First interim deficiency rept re deficient fillet wolds. Socket & flange fillet wolds will be reinspected GA procedures have been revised & reissued to reflect ABME code requirements Tennesses Valley Authority 80/06/06 ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by UB Essel from which 4-inch elbows & 2-inch tees were mfg to A234WB requirement. Investigations conducted & closed at 46 listed facilities EEAY.JL Chemtron Corp., Tube Turns Div. 80/06/06. 3pp
- 8006250227 Forwards second revised final deficiency rept re blown fusc in low voltage switchgear MILLS.L M Tennessee Valley Authority. 80/04/20 ip
- --B006250230 Second revised final deficiency rept re blown fuses in lovoltage switchgear. To avoid possibility of fuse opening on incush current: G-amp fuse will be replaced w/6-amp fuse * Tennessee Valley Authority B0/06/20 ip
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1 A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0377 readequacy of applicable support structures Ceneral operating reactor review procedure & acceptance criteria encl EISENHUT.D & Division of Licensing 80/05/20 iSpp
- 8006250276 Notification of 800619 meeting w/wtil in Bathesda.MD to discuss facility OE application & schedule. HQUSTQN.D Licensing Branch 2 80/06/13 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 800627027B Forwards environ rept.Vols 1 \$ 2 DAVIDSON, D R Cleveland Electric Illuminating Co B0/06/20, 1p
- ---B0062702BO Environ rept.Vol 1
 * Cleveland Electric Illuminating Co 80/06/20 250pp

- ---8006270285 Environ rept. Vol 2
 * Cleveland Electric Illuminating Co 80/06/20 350pp
- I Financial information
- BO06270275 Forwards amend to application for OL.consisting of 1977 annual repts for Duquesne Light, Toledo Edison, Claveland Electric Illuminating Co.PA Power Co & OH Electric Co DAVIDSON, D R Cleveland Electric Illuminating Co B0/06/20 1 80/06/20 1p
- --800527029B Amend to application for OL, including annual repts for 5 utils and miscellaneous financial info
 # Cleveland Electric Illuminating Co 80/06/20 480pp

- 8006060314 Requests that deadline for requests for hearings be extended to 800709 re availability of transmission svc Extension will allow NRC & intervenor to work out language discord between FERC Opinion 84 & NRC 800513 order OCLDBERO, Cleveland, OH GOLDBERO, Cleveland, OH GOLDBERO, R CLEVELAND, OH GO
- 8005170958 Motion for mod of NRC 800513 order to require filing of transmission schedule per FERC 800505 order Requests hearing on 800513 order if NRC denies mod Certificate of Svc URBAN, J R Justice, Dapt of 80/06/09 13pp
- G Inspection reports, IE Bulletins & correspondence
- 8004240378 Responds to IE Bulletin 80-09 re hudramotor actuator deficiencies Vendors supplying valve actuators indicated that only Powers Regulatory Co supplied ITT General Model NH-90 hydramotor actuators Model AH-90 not supplied DAVIDSON.D R Cleveland Electric Illuminating Co 80/06/18 ip
- S Reportable occurrences, LERs & related correspondence
- BOOA030270 Part 21 rept re possible noncompliance of motor control ctrs to customer specs Util will be requested to remove units & return for wire mods & will be authorized to replace nonconforming blocks
 BERQUIET, B Cutler-Hammer, Inc 80/05/14 3pp
- 8006240092 Ack receipt of 800522 interim deficiency rept re pump failures on Comsip post-LOCA hydrogen analyzers Review of matter will be completed during future insp FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 ip

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8006230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures Ceneral operating reactor review procedure & acceptance criteria encl EISENHUT,D Q Division of Licensing 80/05/20 12pp
- 8006250276 Notification of 800619 meeting w/util in Bethesda.MD to discuss facility OL application & schedule HOUSTON,D Licensing Branch 2 80/06/13 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 8006270278 Forwards environ rept.Vols 1 & 2 DAVIDBON,D R Cleveland Electric Illuminating Co 80/06/20 ip
- --8006270280 Environ tept:Val 1 * Cleveland Electric Illuminating Co 80/06/20 250pp
- --8006270285 Environ rept.Vol 2
 * Cleveland Electric Illuminating Co 80/06/20 350pp
- I Financial information
- B006270295 Forwards amend to application for CL, consisting of 1979
 Annual repts for Duquesne Light. Toledo Edison, Cleveland
 Electric Illuminating Co. PA Power Co & OH Electric Co
 DAVIDSON, D R Cleveland Electric Illuminating Co B0/C6/20 1p

- ---8006270298 Amend to application for CL.including annual repts for 5 utils and miscellaneous financial info
 * Cleveland Electric Illuminating Co 80/06/20 480pp
- M Antitrust correspondence
- 8006060314 Requests that deadline for requests for hearings be extended to 800709 re availability of transmission svc Extension will allow NRC & intervenor to work out language discord between FERC Opinion 84 & NRC 800513 order GULDBERO,R Cleveland, OH GOLDBERO,R Goldberg,Fieldman & Letham,P C 80/04/02 2pp
- 8006170555 Motion for mod of NRC 800513 order to require filing of transmission schedule per FERC 800505 order Requests hearing on 800513 order if NRC denies mod Certificate of Svc URBAN, J.R. Justice, Dept of 80/04/09
- G Inspection reports, IE Bulletins & corrospondence
- 800624037B Responds to IE Bulletin 80-09 re hydramotor actuator deficiencies Vendors supplying valve actuators, indicated that only Powers Regulatory Co supplied ITT General Model NH-90 hydramotor actuators Model AH-90 not supplied DAVIDSON, D R Cleveland Electric Illuminating Co 80/06/iB 80/06/18 1p
- S Reportable occurrences, LERs & related correspondence
- 8006240092 Ack receipt of 800522 interim deficiency tept re pump failures on Comsip post-LOCA hydrogen analyters Review of matter will be completed during future insp FIORELILO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/10 ip

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISEMMUT,D 0 Division of Licensing 80/05/20 13pp
- BOOG18068B Responds to 791015 ltr.requesting use of certain ABME code cases in const of components for facility Gode Cases N-237, N-218 & N-288 are acceptable Use of code cases should be documented in FBAR YOUNGBLOOD, B J Licensing Branch 1 80/05/30 2pp
- Q Adjudicatory correspondence
- 8006040182 Forwards written remarks to be made part of 800323 briefing before Commission ra review of ASLAB seismic decisions ALAB-422 & ALAB-561 Requests copy of decision HEINHOLD,E H Affiliation Unknown 80/05/17 1p
- ~-8006040191 Urges that Commission grant New England coalition on Nuclear Pollution petition to review ASLAB decisions on selsmic design Requests review of Okrent comments & NRC quarterly bulletins supporting activities HEINHOLDIC H Affiliation Unknown 80/05/17 3pp
- 8006060477 Informs NRC that financial difficulties prohibit attendance at 800823 briefing re intervenor New England Coalition on Nuclear Pollution petition for review of ALAB-422 k ALAB-756; Forwards written remarks for inclusion in record HEINHOLD, E H Affiliation Unknown 80/05/17 4pp
- 8006110049 Advises that Chinnory will make major portion of New England Cualition on Nuclear Power presentation at Thursday briefing Operating equipment for viewgraphs necessary WEISS.E R Sheldon, Harmon & Weiss WEISS,E R New England Coalition on Nuclear Pollution 80/05/28 ip
- 8006140089 Proposes, on behalf of New England Coalition on Nuclear Pollution, that three listed documents be included in record of pending proceeding re soismic risks Forwards MA Inst of Technology rept, "Investigation of Mar Possible Earthquakes " WEISS, E R Sheldon, Harmon & Weiss 80/06/11 App
- --8006i6093 "Investigation of Max Possible Earthquakes," annual rept CHINKERY,M A Massachusetts Institute of Technology NRC-04-77-019 78/08/15 90pp

6160100 Order granting extension until 800625 for Commission to eview Director's 800211 decision denying petition remergency planning & Class 9 accidents, under 10CFR2 206 HILM.S.J. Office of the Secretary of the Commission 80/06/11 p.

&180406 Order granting extension until 800627 for Commission to lect whether to review ALAB-422 & ALAB-561 HILKS J Office of the Secretary of the Commission 80/05/12 p

623026: Response in opposition to New England Coalition on Nuclear oflution 800611 motion to reopen record & introduce new vidence Chinnery theory ignores geology for SSE purposes reges dismissal of petition for review W/Certificate of Syc 19NAN, T 9, RITSHER, J A Ropes & Oray 80/06/17 7pp

6300491 Response in opposition to New England Coalition on Nuclear Ollution 800611 ltr requesting reopening of record to enter hinnery articles & 800529 briefing transcript Admittance ould violate rules of evidence Certificate of Svc encl

General correspondence

6170107 Forwards minutes of Kensington,NH 800313 town meeting BODVIN, M Rogovin, Stern & Huge 80/05/12 ip

O06170183 Submits extract of Kensington NH 800313 town meeting minutes re syacuation of 10-50 mile radius around nuclear facilities License should not be granted until safe evacuation plan demonstrated EASTMAN.CR. GAVUTIS.S New Hampshire, State of 80/04/19 ip

6020459 Responds to encl 800418 ltr to President Carter expressing pposition to const of facilities NRC authority does not attend to planning for adequate electrical generating mpacity or for interceding in state & local decisions DVNQBLQDD, B. J. Licensing Branch 1 80/05/23 3pp

6300240 Responds to 791011 ltr to President Carter requesting halt f const until safe & timely evacuation plan is achieved NRC mergency planning review will include re-evaluation of xisting licensee & local & state govt emergency plans ENTON, H R Office of Nuclear Reactor Regulation. Director 9706/11 2pp

D04300251 Forwards SC Dunfey.RC Pevear.EF Parr & P Keenan 791011 ltr to President Carter requesting halt of const until safe & timely evacuation plan is achieved Seacoast area cannot be evacuated in event of serious accident SEAL.M M President of US & Executive Offices 79/10/19 5pp

Antitrust correspondence

\$260207 Advises that PSC of NH addl antitrust info will not be royided as stated in HK Shapar 800516 ltm to Atty General JTBERG, J Antitrust Division 80/06/24 ip

Inspection reports: IE Bulletins & correspondence

5060251 Forwards combined IE Insp Repts 50-443/80-01 & 50-444/80-01 m arrests of const workers on charges of conspiracy to folate state drug laws No concern necessary re quality of onst work A drug inquiry RIER, B H Region i, Philadelphia, Office of the Director 2/03/11 ip

5200030 Forwards IE Circular 80-13, "Grid Strap Damage in matinghouse Fuel Assemblies " No written response required SIER, B H Region 1, Philadelphia, Office of the Director D/05/28 1p

\$300276 Responds to IE Bulletin 80~05, "Vacuum Condition Resulting n pamage to Chemical Vol Control Sys Holdup Tanks " All anks except resin sluice & primary drain tanks either will nt experience or can withstand full vacuum conditions EVINCENTIS.J Public Service Co of New Hampshire 80/06/05 4pp

Reportable occurrences. LERs & related correspondence

\$020017 Part 21 rept re discrepancy in seismic design in containment noular area Cause unstated Details contained in util 71206 deficiency rept ARSTENS E United Engineers & Constructors, Inc. (subs. of author Co.) 80/05/13 3PP

800&i80372 Part 21 rept re util use of invalid seismic amplified response spectra Confirms RH Leonard 800530 telcon w/NO Reinmuth of revision to final rept date Short-term qudit & redesign of containment annular steel complete SARSTEN.O E United Engineers & Constructors, Inc (subs of Raytheon Co) 80/06/02 4pp

T Hearing transcripts on non-antitrust matters

BOO6260079 Transcript of 800527 afternoon public meeting in Hashington, DC resersmic issue Pp 1-82 Supporting documentation encl AHEARNE, J.F., GILINGKY, V., BRADFORD, P.A. Commission 80/05/29

DOCKET 50-444 BEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Bection 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D Q Division of Licensing 80/05/20 13pp

8006180688 Responds to 791015 ltr.requesting use of certain ASME code cases in const of components for facility Code Cases N-237. N-218 & N-288 are acceptable Use of code cases should be documented in FGAR YOUNGBLOOD.B J Licensing Branch 1 80/05/30 2pp

Q Adjudicatory correspondence

BOO6040182 Forwards written remarks to be made part of 800323 briefing before Commission re review of ASLAB seismic decisions ALAB-422 & ALAB-561 Requests copy of decision WEINHOLD, E H Affiliation Unknown 80/08/17 ip

--B004040191 Urges that Commission grant New England coalition on Nuclear Pollution petition to review ASLAB decisions on setsmic design Requests review of Okrent comments & NRC quarterly builetins supporting activities HEINHOLDLE H Affiliation Unknown 80/05/17 3pp.

BOO6060479 Informs NRC that financial difficulties prohibit attendance at BOO523 briefing re intervenor New England Coalition on Nuclear Pollution petition for review of ALAB-422 & ALAB-364 Forwards written remarks for inclusion in record WEINHOLD, E H Affiliation Unknown 80/05/17 App

BOO6110049 Advises that Chinnery will make major portion of New England Coalition on Nuclear Power presentation at Thursday briefing Operating equipment for viewgraphs necessary WEISS,E R Sheldon, Harmon & Weiss MEISS,E R New England Coalition on Nuclear Pollution BO/05/28 1p.

8006160087 Proposes on behalf of New England Coalition on Nuclear Pollution, that three listed documents be included in record of pending proceeding re seismic risks Forwards MA Inst of Technology rept. "Investigation of Max Possible Earthquakes " WEISS,E R Sheldon, Harmon & Weiss 80/06/11 App

---8006160093 "Investigation of Max Possible Earthquakes," annual rept CMINNERY,M A Massachusetts Institute of Technology NRC-04-77-019 78/08/15 90pp

8006160100 Order granting extension until 800625 for Commission to review Director's 800211 decision denying getition reemergency planning & Class 9 accidents, under 100FR2 206 CHILK S J Office of the Secretary of the Commission 80/06/11

BOO6180406 Order granting extension until BOO627 for Commission to elect whether to reviou ALAB-422 & ALAB-561
CHILK, S. J. Office of the Becretary of the Commission BO/06/12 io.

8006230261 Response in opposition to New England Coalition on Nuclear Pollution 800611 motion to reopen record & introduce new evidence Chinnery theory ignores geology for SSE purposes Urges dismissal of petition for review W/Certificate of Svc DIQNAN.T 0 , RITSHERJ A Ropes & Oray 80/06/17 7pp

8006300491 Response in opposition to New England Coalition on Nuclear Pollution 800611 ltr requesting reopening of record to enter Chinnery articles & 800529 briefing transcript Admittance would violate rules of evidence Certificate of Svc encl REIS.E J Hearing Branch 3 80/06/26 9pp.

H General correspondence

- 8005170107 Forwards minutes of Kensington NH 800313 town meeting ROGOVIN.H Rogovin.Stern & Huge 80/05/12 1p
- ---8006170183 Submits extract of Kensington.NH 800313 town meeting minutes re evacuation of 10-50 mile radius around nuclear facilities License should not be granted until safe evacuation plan demonstrated EASTMAN.C R . GAVUTIS, 5 New Hampshire, State of 80/04/18 ip
- 8006020459 Responds to encl 800418 ltr to President Carter expressing opposition to const of facilities NRC authority does not extend to planning for adequate electrical generating capacity or for interceding in state & local decisions YOUNGBLOOD, B J Licensing Branch 1 80/05/23 3pp
- BODA300240 Responds to 791011 ltr to President Carter requesting halt of const until safe & timely evacuation plan is achieved NRC emergency planning review will include re-evaluation of existing licensee & local & state govt emergency plans DENTON.H R Office of Nuclear Reactor Regulation, Director 80/04/11 2pp
- --800A300251 Forwards SC Dunfey.RC Pavear.EF Parr & P Keenan 791011 ltr to President Carter requesting halt of const until safe & timely evacuation plan is achieved Seacoast area cannot be evacuated in event of serious accident SEAL.M M President of US & Executive Offices 79/10/19 5pp

M Antitrust correspondence

8006260207 Advises that PSC of NH addi antitrust info will not be provided as stated in HK Shaper 800516 ltr to Atty General RUTBERG,J Antitrust Division 80/06/24 1p

G Inspection reports. IE Bulletins & correspondence

- 8006060251 Forwards combined IE Insp Repts 50-443/80-01 & 50-444/80-01 re arrests of const workers on charges of conspiracy to violate state drug laws No concern necessary re quality of const work & drug inquiry ORIER.8 H Region i, Philadelphia, Office of the Director 80/03/11. Ip
- 8006200030 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Evel Assemblies " No written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/09/28 19
- 8006300276 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys Holdup Tanks " All tanks except resin sluice & primary drain tanks either will not experience or can withstand full vacuum conditions DEVINCENTIS, J Public Service Co of New Hampshire 80/06/05 4pg

S Reportable occurrences. LERs & related correspondence

- 8006020019 Part 21 rept re discrepancy in seismic design in containment annular area. Cause unstated Details contained in util 791206 deficiency rept SARTEIN 9 E United Engineers & Constructors, Inc (subs of Raytheon Co).
- 8006180372 Part 21 rept re util use of invalid seismic amplified response spectra Confirms RH Leonard 800530 telcon w/M0 Reinmuth of revision to final rept date Short-term audit & redesign of containment annular steel complete SARBIEN.0 E United Engineers & Constructors, Inc. (subs. of Raytheon Co) 80/06/02 4pp

T Hearing transcripts on non-antitrust matters

DOLLER ED 415 00 0 0 0

10 %

8006260075 Transcript of B00529 afternoon public meeting in Washington, DC re seismic issue Pp 1-82 Supporting documentation encl.
AHEARNE, J F , GILINSKY, V , BRADFORD, F A Commission. 80/05/29

'nce

---10d i fu

- 800612008/ Summary of 800325 meeting w/util & Westinghouse in Bethesda.MD re instrumentation & control sys BURWELL.S B Licensing Branch 2 80/05/27 App
- 8006070484 Summary of 800423 meeting w/util in Bethesda,MD re reliability evaluation of auxiliary foodwater sys BURWELL,8 B Licensing Branch 2 80/05/30 App
- 8006120349 Forwards qualification test schedule & status for Class IE equipment to be supplied by vendor Submittal in response to action item per 800507 meeting re qualification programs & review, required to ensure timely issuance of OL ANDERSON, T.M. Westinghouse Electric Corp. 80/06/03 2pp
- 8006306018 Notifies that util has provided detailed design info re piping analysis of main steam line inside containment Action is taken in conformance w/NRC PM Operating Procedure 208, Revision i, "Submittal of Supplementary Detailed Data " BURWELL,S B Licensing Branch 2 80/06/06 ip
- 8006300020 Lists ltrs incorporating detailed electrical, instrumentation & control drawings re facility design Action is taken in conformance w/NRC PM Operating Procedure 208, Revision 1. "Bubmittal of Supplementary Detailed Data "BURWELL S B Licensing Branch 2 80/06/06 1p
- 8006260422 Notification of 800618 & 19 meetings w/util & ANL in Bethesda & Bilver Spring MD. respectively, to review electrical instrumentation & control drawing for conformance w/separation.redundancy & signal failure criteria BURWELL.S Licensing Branch 2 80/06/12 2pp
- 8006190458 Forwards electrical instrumentation & control drawings List of drawings & revision status encl Drawings available in Central Files only GARY,R J Texas Utilities Generating Co 80/06/13 2pp

F Becurity, medical, emergency & fire protection plans

- B005i303i7 Forwards clarification of NRC requirements for emergency response facilities defined in 7909i3 ltr Addl specific criteria for facilities under development EIBENHUT.D 0 Division of Operating Reactors B0/04/25 6ipp
- B006250325 Summary of B00513 meeting w/util in Bethesda.MD re fire protection criteria BURWELL.S B Licensing Branch 2 80/06/09 5pp

Q Adjudicatory correspondence

- 8006060255 Motion to compel applicants to supply 800410 position on contentions per ASLB 800319 order re prehearing conference schedule Urges postponement of 800430 prehearing conference pending receipt & review of position W/Certificate of 8vc ELLIG.J. Citizens Association for Sound Energy 80/04/21 App
- --8006060257 Corrects typographical emissions & errors made in intervenor 800410 position on contentions Table of contents encl ELLIS, J Citizens Association for Sound Energy 80/04/21 4pp
- --8006050261 Corrects typographical arrors made in intervenor 800411 motion for extension of time & 800410 motion to consider Contention B Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 80/04/21 2pp
- 8006060346 Motion in support of intervenor Contention 19 re GA/GC Present wording covers areas of concern re design, testing, managerial & administrative controls Proposes other version if present wording is not accepted Certificate of Svc encl. ELLIS.J Citizens Association for Sound Energy 80/05/12 10pp
- BOO6060347 Post-hearing conference memorandum submitting statement of position re impact of ALAB-590.wording of Citizens' Association for Bound Energy contentions & intervenors' proposed GA/GC contention Certificate of Svc encl REYNOLDS, N S . HORIN, W A Texas Utilities Generating Co REYNOLDS, N S . Debevoise & Liberman 80/05/12 17pp
- 8006090001 Position on Contention 4 A Intervenor supports present wording of contention & emphasizes necessity of including Contention 4 B special operating requirements in proceeding Certificate of Svc encl FGUKE, R L Citizens for Fair Utility Regulation 80/05/12 4pp

- 8006090005 Statement of position on ALAB-590 application to admissibility of intervenor contentions Opinion places intervenor under no obligation to explain validity of contentions Certificate of Svc enci OAY. O M Association of Community Organizations for Reform Nou-Texas GAY. O M West Texas Legal Services 80/05/12 8pp
- 8006090007 Statement of position re GA/GC contention Urges keeping contention broad at this stage in interest of justice & in compliance w/ALAB-590 Certificate of Svc sncl GAY. G M Association of Community Organizations for Reform Now-Texas GAY. G M West Texas Legal Services 80/05/12 3pp
- 8006020099 Forwards Commission 800516 memorandum & order ruling on certified question of litigability of combustible gas control issue ROTHSCHILD, M U Hearing Branch 1 80/05/30 ip
- B006020128 Forwards final version of NUREO-0660, "NRC Action Plan Developed as Result of TMI-2 Accident," Vols 1 & 2 W/o enci ROTHSCHILD,M U Hearing Branch 1 80/05/30 1p
- 8006190544 Order accepting Citizens for Fair Util Regulation Contentions 1,2A,2B,3A & 3B & Association of Community Organizations for Reform Now Contentions 1.3, - 11,14,15,20, 22,24,25 & 31 BOMERS,E S Atomic Safety and Licensing Board Panel 80/06/16

- 8006130243 Discovery rept for Mar 1980 No discovery requests initiated or received Certificate of Svc & change of address notice encl
 JOHN.D F Southwest Texas Electric Cooperative JOHN.D F
 McDermott, Will & Emery 80/04/16 5pp
- 8006060428 Corrects misstatement of fact in Public Utils Board of City of Brownsville.TX Mar-Apr 1980 discovery rept.Failure to participate in J Bruggeman deposition was due to counsel independent decision not to attend Certificate of Svc encl STAHL.D M Isham, Lincoln & Beale 80/05/01 4pp
- 8006120056 Motion for 800509 prehearing conference to apprise ASLE of status of settlement discussions Proposed order & Certificate of 8vc encil CYPHERT, S.B., DOPSOVIC, D.A., LUQUE, N. Justice, Dept of 80/05/05 50e
- 800605055 Forwards status rept Delivery arrangements made for 800512 KNDTTB.J B Debeypise & Liberman 80/05/09 ip
- --8006050561 Status rept re settlement negotiations' progress
 Discussions are continuing Urges ASLB to hold prehearing
 conference by 800514 & requests deferred of ruling on
 extension Certificate of Svc & supporting documents encl
 SAMPELS.M D Texas Utilities Co SAMPELS,M D. Worsham, Forsythe
 & Sampels, 80/09/09 28pp
- 8006060033 Forwards Houston Lighting & Power status of settlement rept, per ASLB 800410 order Affidavit not appropriate OREEN.D G Lowenstein.Newman,Reis,Axeirad & Toil 80/05/09. 2pp
- --8006060036 Status of settlement rept per ABLB 800410 order deferring trial briefs, final prehearing conference & svidentiary hearing Urges addl 30-day extension for continuance of negotiations due to complexity Certificate of Svc encl BARNETT, E.W. Houston Lighting & Power Co. 80/05/09 7pp
- 8006060492 Status rept re settlement discussions' progress Urges ABLB to convene pretrial conference to accommodate outstanding discovery, final trial preparation & resolution of remaining procedural matters Certificate of Svc encl.

 CYPHERT. 8 B. PARMENTER. F. DOPSOVIC. D. A. Justice, Dept of. 80/05/09 7pp.
- 8006110233 Forwards rept on status of settlement GREEN, D 0 Lowenstein, Newman, Reis, Axelrad & Toll 80/05/09 Zpp.
- BOO6180189 Rapt on settlement negotiations Buggests that conference be held to determine add1 time needed by applicant Trial should be preceded by pretrial conference to accommodate discovery & other matters, W/Certificate of Svc CYPHERTIS, B., PARMENTER, F., DDPSOVIC, D.A. Justice, Dept of. BO/05/09 9pp

- 8006230157 Settlement status rept by Public Utili Board of Brownsville.

 TX Proposes early trial schedule & 30-day extension to
 explore possibility of settlement Certificate of Syc encl
 SPIEOEL. G Brownsville. TX SPIEOEL. G Spiegel & McDiarmid
 80/05/09 6pp
- 8006240250 Status rept on settlement negotiations per ABLB 800410 order Requests 30-day extension in procedural dates to allow continuation of discussions Certificate of Svc enci STAHL, D M Central & South Mest Services, Inc STAHL, D M Isham, Lincoln & Beale 80/05/09 12pp
- 8006250193 Submits status rept on settlement negotations per ASLB 800410 order Joint ownership agreement will be completed by 801101 Supporting documentation & Certificate of Svc encl BURCHETTE,W H . RITTS.F R Texas-Louisiana Electric Cooperative, Inc BURCHETTE,W H Northcutt Ely 80/05/09 29pp
- 8006060541 Discovery mept for Apr 1980 Util counsel participated in depositions of NC Lerner & O Taylor, expert economic witnesses for NRC & DDT, respectively AHEARNE, C D Texas Utilities Co AHEARNE, C D Debayoise & Liberman 80/05/15 Spp
- 8004090175 Discovery rept for Apr 1960 Participated in NC Learner & G Taylor depositions Revolved NRC updated response to Houston Lighting & Power second set of interrogatories Inspected NRC documents designated by expert witness AHEARN.C D Texas Utilities Generating Co AHEARN.C.D Debevoise & Liberman 80/05/15 Spp
- 8006200142 Discovery rept for Apr 1980 Participated in QTC Taylor deposition Responded to Houston Lighting & Power motion to compel production of documents Undertook settlement discussions & trial preparation Certificate of Svc encl. CYPHERT.S B Justice.Dept of 80/05/19 5pp
- 8006170242 Discovery rept for Apr 1980 Attended continuation of NC Lerner deposition Responded to Houston Lighting & Power first set of Interrogatories Joined parties' motion for 30day extension Certificate of Svc encl CARNEY, J A Central & South West Corp 80/05/22 App
- 8006170004 Forwards corrected Page 3 to DOJ 800821 motion to establish trial & other procedural dates
 CYPHERT,S 8 Justice,Dept of 80/05/23 ip
- --8006170007 Corrected Page 3 to DDJ B00921 motion to establish trial & other procedural dates Centificate of Svc encl CYPHERT, 8 B. PARMENTER, F. DDPSOVIC, D. A. Justice, Dept of 80/05/21 App
- 8005120052 Reply in opposition to DOJ 800521 motion to establish trial & other procedural dates Request premature, ASLB should adhere to previous discretion that parties address schedule at 800610 prehearing conference Certificate of Svc encl KNOTTS, J. B. Texas Utilities Generating Co. KNOTTS, J. B. Debevoise & Liberman. 80/05/28 Spp
- 8006050272 Notice of appearance in proceeding Certificate of Byc encl. LEWIS.8 H Hearing Branch 2 80/06/03 4pp
- BOO6110162 Notifies parties that BH Lewis, appearing in proceeding on behalf of NRC, is nephew of G Spiegel of Spiegel & McDiarmid, representing Public Utils Board of City of Brownsville, TX No conflict of interest exists CHANANIA: F D Antitrust Division 80/06/06 ip
- 8006ii0302 Rept on settlement negotiations per ASLS 8005i3 order. Requests 30-day extension for procedural dates to resolve & marrow issues Frehearing conference should be held at end of extension Certificate of Svc encl SAMPELS:M D . KNOTTS.J H Texas Utilities Generating Co SAMPELS:M D . Worsham, Forsythe & Sampels 80/06/09 5pp
- 8006110352 Second sattlement status rept per ASLB 800513 order Urges add1 60 to 90-day extension to permit continued efforts. Complex areas re wheeling & access to do interconnections remain under continuing study certificate of Svc encl CHANANIA:F D Antitrust Division 80/06/07. 7pp.

- BOOA110357 Settlement status rept per ASLB 800513 order Urges establishment of trial date to complete outstanding ASLB discovery, to resolve ASLAB discovery & to expedite final trial preparation Certificate of Sov encl CYPHERT, S B Justice. Dept of 80/06/09 App
- 8006110364 Rept on settlement negotiations per ASLS 800513 order Urges add1 extension to entertain further substantial progress Expects to execute agreement w/Central & South West Corp & TX Utils Generating Co Certificate of Svc encl BARNETT, E W Houston Lighting & Power Co # Baker & Botts # Lowenstein, Newman, Reis, Azelrad & Toll 80/06/07 7pp.
- BOO6110371 Rept on settlement negotiations by Public Utils Board of City of Brownsviller TX.per ASLB BOD513 order Submitted draft of transmission agreement & rates to Central & Bouth Hest Corp No response received Certificate of Svc enci SPIECELO Teras. State of SPIECEL. G Spiegel & McDiarmid 80/10/2/99 6pp
- BOOA110375 Rept on settlement discussions per ABLB BOO513 order South West Co reached agreement w/Houston Lighting & Power & TX Utils Co Differences w/Public Utils Board of Brownsville.TX not yet resolved Certificate of Bvc encl STAHL, D M Central & South West Bervices, Inc STAHL, D M Isham, Lincoln & Beale BO/06/09 Bpp
- BOO6190454 Submits settlement negatiations status rept per AGLB 800513 order TX LA & TX Power & Light Co resolved differences in itr of intent Petition to intervene will be amended to reflect new position Certificate of Svc encl BURCHETTE, H H , RITTS, F H Northcutt Ely 80/06/09 5pp
- BOO6200167 Rept on settlement negotiations status South TX Electric Cooperative & Medina Electric Cooperative should be brought into settlement process due to readiness to address concerns re protection of certain interests Certificate of Bvc entl JOHN, D F , HUNTER, M Medinaelectric Cooperative, Inc JOHN, D F McDermott, Will & Emery 80/06/09 App
- 8006110266 Forwards settlement agreement executed 800609 BDUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 80/06/10
- --8006110282 Settlement agreement for all outstanding controversies re question whether Electric Reliability Council of TX should be interconnected w/Southwest Power Pool Certificate of Svc encl JORDAN, b D Houston Lighting & Power Co FARRINGTON, J 9 Dallas Power & Light Co MARGUARDT, W Texas Electric Service Co 80/06/09 19pp
- 8006190890 Order advising that further settlement negotiations status repts are to be filled by 800711, that another prehearing conference he held on 800714 & that discovery question be deferred until further developments Urges fair agreement BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/16 3pp

N Antitrust hearing transcripts

- 8006170743 Transcript of 800610 prehearing conference in Bethesda.MD Pp 832-890 Morning session * Atomic Safety and Licensing Board Panel 80/06/10 59pp
- B006230254 Proposed corrections to 800610 prehearing conference transcript Certificate of Svc encl CYPHERT. 8 B Justice. Dept of 80/06/16 5pp
- O Inspection reports. IE Bulletins & correspondence
- 8006300050 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/01 19
- 8006060169 Forwards notice of violation from insp during 791213-800402 IE Insp Repts 50-445/80-08 & 50-446/80-08 will be transmitted in near future SEIDLE-NC Region 4. Ballas. Reactor Construction & Engineering Support Branch 80/04/02 2pp
- --8006060178 Notice of violation from insp during period or 791213-800402. Noncompliance noted failure to report significant const deficiency.

 * Region 4, Dallas, Office of the Director 80/04/02 2pp

- 8006090140 Ack receipt of IE Insp Repts 50-445/80-07 to IE Investigation Repts 50-445/80-02 to 50-446/80-02 No proprietary info OARY.R J Fexas Utilities Generating Co 80/04/07 1p
- 8006120223 Forwards IE Insp Repts 90-445/80-08 & 50-446/80-08 during Mar 1980 & hotice of violation SEIDLE, N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/18 2pp
- --8006120227 Notice of violation from insp during Mar 1980 * Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/18 ip
- --8006120231 IE Insp Repts 50-445/80-08 & 50-446/80-08 during Mar 1980 Noncompliance noted failure to follow procedures for repair of damaged cable & failure to report significant const deficiency TAYLOR.R G , CROBSMAN, W A Region 4, Dallas, Office of the Director 80/04/16 1000
- 800619021B Forwards Mgt Meeting Repts 50-445/80-12 & 50-446/80-12 on 800408 No noncompliance noted SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/30 Spp
- --8006190226 Mgt Meeting Repts 50-445/80-12 & 50-446/80-12 on 800408 No noncompliance noted Areas discussed at meeting reportability & documentation of significant const deficiencies & other events of NRC interest not within reporting requirements CROSSMAN.W A., TAYLOR.R o., SEIDLE.W C. Region 4, Dallas, Office of the Director 80/04/29 App
- 8006190063 Advises that 1E Insp Repts 50-445/80-09 & 50-446/80-09 contain no proprietary info ORRY, R J Texas Utilities Generating Co 80/05/08 ip
- 8006040286 Forwards IE Suiletin 80-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/09
- 8006180118 Advises NRC that IE Insp Repts 50-445/80-08 & 50-446/80-08, dtd 800418.contain no proprietary info OARY,R J Texas Utilities Generating Co 80/05/13 ip
- 8006090580 Ack receipt of 800505 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-445/80-11 & 50-445/80-11 BEIDLE.W C Region 4, Dallas Reactor Construction & Engineering Support Branch 80/05/14 ip
- --B006090584 Responds to NRC 800409 ltr re violation noted in IE Insp Repts 50-445/80-11 % 50-446/80-11 Corrective actions bolts connecting spools to pump flange removed, precluding further deadweight loading on pump norile QARY,R J Texas Utilities Generating Co 80/05/05 3pp
- 8006300063 Forwards IE Circular 80-12. "Valve-Shaft-To-Actuator Key Hay Fall Out of Piace When Mounted Below Horizontal Axis " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/05/14
- 8004050110 Ack receipt of 800505 ltr informing NRC of steps taken to correct violation noted in IC insp Repts 50-445/80-09 & 50-445/80-09 BRQMN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/05/21 ip
- --8006080113 Responds to NRC 800407 ltr re violation noted in IE Insp Repts 50-445/80-09 % 50-446/80-09 Corrective actions conducted review of flow measuring instrumentation, water demand & recording procedure QARY.R J Texas Utilities Generating Co 80/05/05 3pp
- --8006050115 forwards IE insp Repts 50-445/80-07 & 50-446/80-09 on 800312-14 % notice of violation BROWN, 0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/04/07 2pp
- --8006050117 Notice of violation from insp on 800312-14
 * Region 4. Dallas, Office of the Director 80/03/31 1

- --8006050122 If Insp Rept= 50-445/80-09 & 50-445/80-09 on 800312-14 (Ioncompliance noted groundwater withdrawal rates above
 - limit BROWN,G D. Ragion 4. Dallas, fuel facility & Materials Safety Dianch WILBORN,l Region 4. Dallas, Office of the Director 80/03/31
- 8006190740 Advises that It Insp Repts 50-445/80-12 & 50-446/80-12 contain no proprietary info GARY.R J. Texas Utilities Generating Co. 80/05/21 ip
- 8006290217 Forwards IE Insp Ropts 50 449/80-13 & 50-446/80-19 on 800421-25 & notice of violation BEIDLE:NO Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/09/21 3pp
- --8006250219 Notice of violation from insp on 800421-25
 * Region 4, Dallas, Office of the Director 80/05/20 2pp
- --8006250221 IE Insp Repts 90-449/80-13 & 50-446/80-13 on 800421-25 Noncompliance noted failure to follow welding & insp procedures HALL.R C Region 4. Dallas. Reactor Construction & Engineering Support Branch (ROSSMAN, W A., OILBURT, D Region 4. Dallas, Office of the Director 80/05/20 /pp
- 8006120240 Ack receipt of 800514 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 90-445/80-08 & 50-446/80-08 BEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/05/82 ip
- --B006120245 Responds to NRC B00418 ltr ne violation noted in IE Insp Repts 50-449/80-08 & 50-446/80-08 Corrective actions cable was pulled back during investigation of damage to cable Jacket & will be replaced GRIY,R J Texas Utilities Concrating Co 80/05/14 3pp
- B006230115 Responds to IF Bulletin 80-05 ie vacuum condition resulting in damage to chemical vol holdup tanks Licensee review is not yet complete Thus far, all affected tanks are in NGBG scope of supply, except recycle holdup tanks QARY, R. J. Taras Utilities Generating Co. 80/05/27 ip
- 8 Reportable occurrences, LERs & related correspondence
- B006060570 Deficiency rept to apparent discrepancy in installation & insp requirements for Class 3 non-nuclear safety-related piping supports Formal rept should be submitted by B00715 OARY.R J Texas Utilities Cenerating Co
- 8006230156 Deficiency rept re weided control board connections updating 800321 rept Work will be completed by 800701 OARY R J Toxes Utilities Generating Co 80/05/02 ip
- BOO6240242 Supplemental deficiency rept re 1981-83 2300 MW installation piping min wall Engineering review & disposition of min wall violations at welds & base metal defects is continuing Anticipates submitting next progress rept by 901219.

 GARY.R J Texas Utilities Constanting Co 80/06/19 1p
- T Hearing transcripts on non-antitrest matters
- 8006120398 Rubmits proposed corrections to transcript of 800430 & 0501 prehearing conference held in Fort Worth, TX Certificate of 8vc encl REYNOLDS, N.S. Texas Utilities Generating Co. REYNOLDS, N.S. Debevoise & Liberman 60/06/10 17pp
- DOCKET 50-446 COMMINCHE PEAK STEAM FLLCTRIC STA . UNIT 2

 A Application/construction stage documents & correspondence
- EOO6230110 Advises BWR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures Owneral operating reactor review procedure & acceptance criteria encl EISENHUT, D O Division of Licensing 60/05/20, 13pp
- 8006120087 Summary of 800328 meeting w/util & Westinghouse in Bethasda. MD re instrumentation & control sys BURWELL. 8 B Licensing Branch & 80/05/27 App.
- 8006090484 Summary of 800423 meeting w/util in Bethesda, MD rereligibility evaluation of auxiliary feedwater sys BURWELL, B. B. Licensing Branch 2 80/05/30 App

- 8006120349 Forwards qualification test schedule & status for Class IE equipment to be supplied by vendor Bubmittal in response to action item per 800907 meeting re-qualification programs & review, required to ensure timety issuance of QL ANDERSON. T.M. Upstinghouse Electric Corp. 80/06/03 2pp
- 800A300018 Notifies that util has provided detailed design info repiping analysis of main steam line inside containment Action is taken in conformance w/NRC PM Operating Procedure 208, Revision 1. "Submittal of Supplementary Detailed Data" DURHELL, S.D. Licensing Branch 2. 80/06/06. 1p
- 8006300020 lists ltrs incorporating detailed electrical, instrumentation 8 control drawings re facility design Action is taken in conformace w/NRC PM Operating Procedure 200, Revision 1. "Submittal of Supplementary Detailed Data "BURWELL, S D Licensing Branch 2 80/06/06 ip
- B006260422 Notification of 800618 % 19 meetings w/util & ANL in Dethesda & Bilver Bpring MD: respectively, to review signtrical instrumentation & control drawing for conformance w/separation, redundancy & signal failure criteria BURNFLL, B Licensing Granth 2 80/06/12 2pp
- 8006190488 Forwards electrical instrumentation & control drawings List of drawings & revision status encl Drawings available in Central Files only GARY, R. J. Teras Utilities Generating Co. 80/06/13 Zpp
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development FIGENEUT, D © Division of Operating Reactors 80/04/25 61pp
- 8006250325 Bummary of 800513 meeting w/util in Betheeds.HD ra fire protection criteria BURNELLS B Licensing Branch 2 80/06/09 5pp
- Q Adjudicatory correspondence
- 8004060299 Motion to compel applicants to supply 800410 position on contentions per ABLB 800319 order re prehearing conference schedule Urges postponement of 800430 prehearing conference pending receipt & review of position W/Certificate of 8vc ELLIB.J Citizens Association for Bound Energy 80/04/21, 4pp.
- 8006060261 Corrects typographical errors made in intervenor 800411 motion for extension of time & 800410 motion to consider Contention & Centificate of Svc encl ELLIS.J Citizens Association for Sound Energy 80/04/21 2pp
- B006060346 Motion in support of intervenor Contention 19 re GA/QC Present wording covers areas of concern re design testing, managerial 3 administrative controls Proposes other version if present wording is not accepted Certificate of Svc encl. ELLIS.J Citizens Association for Bound Energy. B0/05/12 10pp
- HOOAGC347 Post-hearing conference memorandum submitting statement of position re impact of ALAB-590, wording of Citizens' Association for Sound Energy contentions & Intervenors' proposed GA/GC contention Certificate of Evc encl REYNOLDB, N B. HORIN, W A. Texas Utilities Generating Co
- 8006090001 Position on Contentian 4 A, Intervenor supports present wording of contention & emphasizes necessity of including Contention 4 B special operating requirements in proceeding Cortificate of Suc encl
 FOUKF, R L Citizens for Fair Utility Regulation 80/05/12. App
- 0006070008 Btatement of position on ALAB-590 application to admissibility of intervenor contentions Opinion places intervenor under no obligation to explain validity of contentions. Certificate of Svc and OAY. O M Association of Community Organizations for Reform Now-Taxas CAY. O, M Wost Texas Legal Services 80/05/12 Bp
- BOOGO90007 Statement of position re QA/QC contention. Urges keeping contention broad at this stage in interest of justice & In compliance w/ALAD=590 Certificate of Bvc encl QAY, O M Association of Community Organizations for Reform Now-Texas GAY, Q M Hest Texas Legal Services BO/O5/12. Spp.

- 8006020099 Forwards Commission 800516 memorandum & order ruling on certified question of litigability of combustible gas control issue ROTHSCHILD, M.U. Hearing Branch I 80/05/30 1p
- BOO602012B Forwards final version of NUREG-0660, "NRC Action Plan Developed as Result of TMI-2 Accident," Vols 1 & 2 H/o encl ROTHSCHILD,M U Hearing Branch 1 80/05/30 ip
- 8006190544 Order accepting Citizens for Fair Util Regulation Contentions 1,2A,2B,3A & 3B & Association of Community Organizations for Reform Now Contentions 1,3, - 11,14,15,20, 22,24,25 & 31 BOMERS,E S Atomic Safety and Licensing Board Panel 80/06/16

- BOO6130243 Discovery rept for Mar 1980 No discovery requests initiated or received Certificate of Svc & change of address notice encl JOHN, D F Southwest Texas Electric Cooperative JOHN, D F McDermott, Will & Emery 80/04/16 5pp
- BOO6060428 Corrects misstatement of fact in Public Utils Board of City of Brownsville.TX Mar-Apr 1980 discovery rept Failure to participate in J Bruggeman deposition was due to counsel independent decision not to attend Certificate of Svc ancl STAHL.D M Isham, Lincoln & Beale 80/05/01 6pp
- BOO6120056 Motion for BO0509 prehearing conference to apprise ASLB of status of settlement discussions Proposed order & Certificate of Svc anci CYPHERT, S B , DOPSOVIC, D A , LUGUE, N Justice, Dept of BO/05/05
- 8006050555 Forwards status rept Delivery arrangements made for 800512 KMOTTB, J B Dekevoise & Liberman 80/05/09 ip
- --BOQAO50361 Status rept re settlement negotiations' progress
 Discussions are continuing Urgas ASLB to hold prehearing
 conference by 800514 & requests deferral of ruling on
 extension Certificate of Svc & supporting documents and
 SAMPELS, H D Texas Utilities Co SAMPELS, H D Worsham, Forsythe
 & Sampels BO/05/09 2Spp
- 8006060033 Forwards Houston Lighting & Power status of settlement rept. per ABLB 800410 order Affidavit not appropriate OREEN.D 0 Lowenstein.Newman.Reis.Axelrad & Toll 80/05/09 2pp
- --8006060036 Status of settlement rept per ASLB 800410 order deferring trial briefs, final prehearing conference & evidentiary hearing Urges addl 30-day extension for continuance of negotiations due to complexity Certificate of Svc encl BARNETT, E W Houston Lighting & Power Co 80/05/09 7pp
- 8008080492 Status rept re settlement discussions' progress Urges ASLB to convene pretrial conference to accommodate outstanding discovery, final trial preparation & resolution of remaining pracedural matters. Certificate of Svc encl CYPHERTS B , FARMENTER, F , DDPSDVIC, D A Justice, Dept. of 80/05/09. 9pp
- BOO6110233 Forwards rept on status of settlement OREEN.D 0 Lowenstein, Newman, Reis, Axelrad & Toll 80/05/09 2pp
- SOCA180189 Rept on settlement negotiations Suggests that cohference be held to determine addl time needed by applicant Trial should be preceded by pretrial conference to accommodate discovery & other matters M/Certificate of Svc CYPHERT, S B, PARHENTER, F, DOPSOVIC, D A Justice, Dept of 80/05/09 9pp
- 8006230157 Settlement status rept by Public Utils Board of Brownsville, TX. Proposes early trial schedule & 30-day extension to explore possibility of settlement Certificate of Svc encl SPIECEL. O Brownsville, TX SPIECEL. Q Spiegel & McDiaraid 80/05/09 6pp
 - ment negotiations per ASLB 800410 n procedural dates to allow 'icate of Svc encl. ervices.Inc STAHL.D M Isham.
 - ttlement negutations per ASLB ment will be completed by Pertificate of Byc encl Louisiana Electric Cooperative, Inc 0/05/09 29pp

- BOO6060541 Discovery rept for Apr 1980 Util counsel participated in depositions of NC Lerner & G Taylor, expert economic witnesses for NRC & DOT, respectively AHEARNE, C D Teras Utilities Co AHEARNE, C D Debevoise & Liberman 80/05/15 5pp
- 8006090175 Discovery regt for Apr 1780 Participated in NC Learner & O Taylor depositions Reveived NRC updated response to Houston Lighting & Power second set of interrogatories Inspected NRC documents designated by expert witness AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debevoise & Liberman 80/05/15 Spp
- BOO6200142 Discovery rept for Apr 1980 Participated in QTC Taylor deposition Responded to Houston Lighting & Power motion to compel production of documents Undertook settlement discussions & trial preparation Certificate of Svc encl CYPHERT. B B Justice. Dept of BO/05/19 5pp
- 8006i60i63 Motion to establish trial & procedural dates Proposes 800609 for settlement repts.8006i0 for prehearing.8006i3 for witness lists & briefs.800627 for responding parties & 800701 for final prehearing conference W/Certificate of Svc CYPHERT.5 B , PARMENTER.F , DDPSOVIG.D A Justice.Dept of 80/05/21 6pp
- 8006170242 Discovery rept for Apr 1980 Attended continuation of NC Lerner deposition Responded to Houston Lighting & Power first set of interrogatories Joined parties' motion for 30day extension Certificate of Svc encl CARNEY, J A Central & South Nest Corp 80/05/22 6pp
- 8006170004 Forwards corrected Page 3 to DQJ 800521 motion to #stablish trial & other procedural dates
 CYPHERT, B B Justice, Dept of 80/05/23, 1p
- --8006170007 Corrected Page 3 to DDJ 800521 motion to establish trial & other procedural dates Certificate of Svc encl CYPHERT, 8 B . PARMENTER, F . DOPSOVIC, D A Justice, Dept of 80/05/21 4pp
- 8006120052 Reply in opposition to DGJ 800521 motion to establish trial & other procedural dates Request premature ABLD should adhere to previous discretion that parties address schedule at 800610 prehearing conference Certificate of 8vc encl KNOTTS-J B Texas Utilities Generating Co KNOTTS-J B, Debevoise & Liberman 80/05/28 5pp
- 8006050272 Notice of appearance in proceeding Certificate of Svc encl. LEWIS,S H Hearing Branch 2 80/06/03 4pp
- BOO6110162 Notifies parties that BH Lewis appearing in proceeding on behalf of NRC. is nephew of Q Spiegel of Spiegel & McDiarmid, representing Public Utils Board of City of Brownsville, TX, No conflict of interest exists CHANANIA, F D Antitrust Division BO/06/06 ip
- 8006110302 Rept on settlement negotiations per ABLB 800513 order. Requests 30-day extension for procedural dates to resolve & narrow issues Prehearing conference should be held at end of extension Certificate of Svc encl
 BAMPELS,M D. KNOTTS,J B. Texas Utilities Generating Co.
 BAMPELS,M D. Horsham, Forsythe & Sampels 80/06/09 5pp.
- 8006110352 Second settlement status rept per ASLB 800513 order Urges add1 60 to 90-day extension to permit continued efforts Complex areas re wheeling & access to do interconnections remain under continuing study Certificats of Evo encl CHANANIA.F D Antitrust Division 80/06/09 7pp
- 8006110357 Settlement status rept per ASLB 800513 order Urges establishment of trial date to complete outstanding ASLB discovery, to resolve ASLAB discovery & to expedite final trial preparation Certificate of Syc encl
- 8005110364 Rept on settlement negotiations per ASLB 800513 order. Urges add1 extension to entertain further substantial progress Expects to execute agreement w/Central & South West Corp & TX Utils Generating Co Centificate of Svc encl BARNETT.E W Houston Lighting & Power Co * Baker & Botts. * Lowenstein, Newman, Reis. Axelrad & Toll 80/06/09 7pp
- 8006110371 Rept on settlement negotiations by Public Utils Board of City of Brownsville.TX.per ABLB 800513 order Bubmitted draft of transmission agreement & rates to Central & South Hest Corp No response received Certificate of Svc encl. SPIECEL.G Texas, State of SPIECEL.G Spiegel & McDiarmid 80/06/09 6pp

- 8006110375 Rept on settlement discussions per ABLB 800513 order South West Co reached agreement w/Houston Lighting & Power & TX Utils Co Differences w/Public Utils Board of Brownsville, TX not yet resolved Certificate of Svc encl STAHL,D M Central & South West Services,Inc STAHL,D M Ishem, Lincoln & Beale 80/06/09 Spp
- 8006190454 Bubmits settlement negotiations status rept per ASLB 800513 order TX LA & TX Power & Light Co resolved differences in itr of intent Petition to intervene will be amended to reflect new position Cellificate of Svc encl BURCHETTE, W.H., RITTS, F.H. Northcutt Ely 80/06/09 Spp
- 8006200167 Rept on settlement negotiations status South TX Electric Cooperative & Medina Electric Cooperative should be brought into settlement process due to readinoss to address concerns re-protection of certain interests Certificate of Svc encl JOHN.D F, HUNTER:M Medinaelectric Cooperative.Inc JOHN.D F McDermott,Will & Emery 80/06/09 App
- 8006110266 Forwards settlement agreement, executed 800609
 BDUKNIGHT, J. A. Lowenstein, Newman, Reis, Axelrad & Toll 80/06/10
- --8006110282 Settlement agreement for all outstanding controversies re question whother Electric Reliability Council of TX should be interconnected w/Southwest Power Pool Certificate of Svc enci JORDAN, D.D. Houston Lighting & Power Co. FARRINGTON, J. B. Dallas Power & Light Co. MARQUARDT, W. Texas Electric Service Co. 80/706/09 19pp
- 8006190590 Order advising that further settlement negotiations status repts are to be filed by 800711 that another prehearing conference be held on 800714 & that discovery question be deferred until further developments Urges fair agreement BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/16
- N Antitrust hearing transcripts
- 8006170743 Transcript of 800610 prehearing conference in Bethesda.MD Pp 832-890 Morning session * Atomic Safety and Licensing Board Panel 80/06/10 59pp
- 8006230254 Proposed corrections to 800610 prehearing conference transcript Certificate of 8vc encl CYPHERT.8 8 Justice.Dept of 80/06/16 5pp
- O Inspection reports. IE Bulletins & correspondence
- 8006300050 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/01
- 8006060169 Forwards notice of violation from insp during 791213-800402 IE Insp Repts 50-445/80-08 & 50-446/80-08 will be transmitted in near future SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/02 2pp
- ---8006060178 Notice of violation from insp during period or 791213-800402 Noncompliance noted failure to report significant const deficiency Region 4, Dallas, Office of the Director 80/04/02 2pp
- 8006090140 Ack receipt of IE Insp Repts 90-445/80-07 & IE Investigation Repts 30-445/80-02 & 50-446/80-02 No proprietary info QARY.R, J. Texas Utilities Generating Co. 80/04/07 ip
- 8006120223 Forwards IC Insp Repts 30-445/80-08 & 50-446/80-08 during Mar 1980 & notice of violation SCIDLE:W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/18 2pp
 - --8006120227 Notice of violation from insp during Mar 1980 * Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/04/18 ip
 - --8006120231 IE Insp Repts 50-445/80-08 & 50-446/80-08 during Mar 1780
 Noncompliance noted failure to follow procedures for repair
 of damaged cable & failure to report significant const
 deficiency
 TAYLOR.R G. CROSSMAN.W A Region 4, Dallas, Office of the
 Director 80/04/16 10pp

- 8006190218 Forwards Mgt Meeting Repts 50-445/80-12 & 50-446/80-12 on BOO408 No noncompliance notes BEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch BO/04/30 2pp
- --8006190226 Mgt Meeting Repts 50-445/80-12 & 50-446/80-12 on 600408. No noncompliance noted Areas discussed at meeting reportability & documentation of significant const deficiencies & other events of NRC interest not within reporting requirements CROGEMAN. W A . TAYLOR.R G . SEIDLE.W C Region 4. Dallas, Office of the Director 80/04/27 4pp
- 8006190063 Advises that IE Insp Repts 50-445/80-09 & 50-446/80-09 contain no proprietary info GARY,R J Texas Utilities Generating Co 80/05/08 ip
- 8006040286 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Dperability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl BEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/09.
- 8006180118 Advises NRC that IE Insp Repts 50-445/80-08 & 50-446/80-08, dtd 800418, contain no proprietary info OARY,R J Texas Utilities Generating Co 80/05/13 1p
- 8004090580 Ack receipt of 800505 ltr informing NRC of steps taken to correct violation nated in IE Insp Repts 50-445/80-11 & 50-446/80-11 SEIDLE,W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/05/14 Ip
- --8006070584 Responds to NRC 800407 ltr re violation noted in IE Insp. Repts 50-445/80-11 & 50-446/80-11 Corrective actions bolts connecting spools to pump flange removed precluding further deadweight loading on pump noisle OARY, R J Texas Utilities Generating Co. 80/03/05 3pp.
- 8006300063 Forwards IE Circular 80-12, "Valve-Shaft-To-Actuator Key May Fall Out of Place then Mounted Selow Horizontal Axis " No written response required BEYFRITK V Region 4, Dallas, Office of the Director 80/05/14.
- 8006050110 Ack receipt of 800505 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-445/80-07 & 50-445/80-09.

 BROWN 0 D Region 4, Dallas, Fuel Facility & Materials Balety Branch 80/05/21 ip
- --8004050113 Responds to NRC 800407 ltr re violation noted in IE Insp Repts 50-445/80-09 t 80-446/80-09 Corrective actions conducted review of flow measuring instrumentation.water demand & recording procedure GARY:R J Texas Utilities Generating Co 80/05/05. 3pp
- --8004050115 Forwards IE Inep Repts 50-445/80-09 & 50-444/80-09 on 800312-14 & notice of violation. BROWN.0 D. Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/04/07 2pp.
- --8006030117 Notice of Violation from insp on 800312-14
 * Region 4, Dallas, Office of the Director 80/03
- --8006050122 IE Insp Repts 30-445/80-09 & 30-446/80-09 on 800312-14 Noncompliance noted groundwater withdrawal rates above BROWN, O D Region 4, Dallas, Fuel Facility & Materials Bafety Branch, WILBORN, L. Region 4, Dallas, Office of the Director 80/03/31 7pp.
- 8006190740 Advises that IE Insp Repts 50-445/80-12 & 50-446/80-12 contain no proprietary info OARY.R J Taxas Utilities Generating Co. 80/05/21. 1p
- 8006280217 Forwards IE Insp Repts 50-445/80-13 & 80-446/80-13 on 800421-25 & notice of violation SEIDLE.W C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- -8006250219 Notice of violation from insp on 800421-25.
 * Region 4: Dallas: Office of the Director 80/05. 80/05/20 2pp
- ---8006250221 IE Insp Repts 50-445/80-13 & 50-446/80-13 on 800421-25.
 Nancompliance noted failure to follow welding & insp rancompliance naces railing to rollow weiging & insp procedures HALL.R.E Region 4. Dallas. Resctor Construction & Engineering Support Branch CROBSMAN.W.A. GLBERT.L.D. Region 4. Dallas. Defice of the Director 80/03/20 7pp.

- 8006120240 Ack receipt of 800514 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-445/80-08 & 50-446/80-08 อบ-446/ฮบ-VB SEIDLE.H C Region 4. Dallas. Reactor Constiuction & Engineering Support Branch 80/05/22 ip
- --8004120245 Responds to NRC 800418 ltr re violation noted in IE Inap Repts 50-445/80-08 & 50-446/80-08 Corrective actions cable was pulled back during investigation of damage to cable jacket & will be replaced GARY.R J Texas Utilities Generating Co 80/05/14 3pp
- BOO6230115 Responds to IE Bulletin BO-O5 re vacuum condition resulting in damage to chemical vol holdup tanks Licensee review is not yet complete Thus far, all affected tanks are in NBSS scope of supply, except recycle holdup tanks

 CARY,R J Texas Utilities Generating Co BO/O5/27 ip
- S Reportable occurrences. LERs & related correspondence
- B006060570 Deficiency rept re apparent discrepancy in installation & insp requirements for Class 5 non-nuclear safety-related piping supports Formal rept should be submitted by 800715 GARY,R J Teras Utilities Generating Co 80/04/21 ip
- B006230156 Deficiency rept re welded control board connections, updating B00321 rept Work will be completed by B00701 GARY,R J Texas Utilities Generating Co 80/05/02 1p
- 8006240242 Supplemental deficiency rept re 1981-83 2300 MW installation piping min wall Engineering review & disposition of min wall violations at welds & base metal defects is continuing Anticipater submitting next progress rept by 801219 GARY.R J Texas Utilities Generating Co 80/06/19 ip
- T Hearing transcripts on non-antitrust matters
- 8004120398 Submits proposed corrections to transcript of 800430 & 0501 prehearing conference held in Fort Worth,TX Certificate of Svc encl REYNOLDS.N S Texas Utilities Cenerating Co REYNOLDS.N S Debevoise & Liberman 80/06/10
- DUCKET 50-448 DOUGLAS POINT NUCLEAR STATION. UNIT 1
- Q Adjudicatory correspondence
- 8006060509 Notice of withdrawal of application for early site review Load growth forecasts indicate little possibility of commencing const within validity of findings Requests order terminating proceeding Certificate of Svc encl TROMBRIDGE, OF Potomac Electric Power Co TROMBRIDGE, OF Shew, Pittman, Potts & Trowbridge 80/05/14 3pp TROWERIDGE, OF Shaw,
- 8006240381 Forwards PSC of MD Order 64338 closing Case 6603, PEPCO application for certificate of public convenience & necessity for const of two nuclear power plants, due to util 800602 withdrawal of application HAHKINS, R & Maryland, State of 80/06/17 2pp
- DOCKET 50-449 DOUGLAS FOINT NUCLEAR STATION, UNIT 2
- O Adjudicatory correspondence
- 8006060509 Notice of withdrawal of application for early site review Load growth forecasts indicate little possibility of commencing const within validity of findings Requests order terminating proceeding Certificate of Svc oncl TROMBRIDGE, G F Potomac Electric Power Co TROMBRIDGE, G F Potomac Electric Power Co TROMBRIDGE, G F Shaw, Pittman, Potts & Trowbridge B0/03/14 3pp
- 8006240381 Forwards PSC of MD Order 64338, closing Case 6603, PEPCO application for certificate of public convenience & necessity for const of two nuclear power plants, due to util 800602 withdrawal of application HAMKINS.R E. Maryland, State of 80/06/17 2pp
- DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp.

- G Adjudicatory correspondence
- 8006240311 Order granting extension until 800715 for applicant to respond to Citizens for Energy & Employment 800602 motion to compel withdrawal of application for licenses BOMERS.E S Atomic Safety and Licensing Board Panel 80/06/18 ip
- 8006240467 Forms os procedural rules in response to intervenor 800602 motion W/o encl REIS.E J Hearing Branch 3 (NRC 80/06/23 ip
- 8006260205 Response to Concorned Citizens for Employment & Energy 800602 metion to compol withdrawal of applications for CPs Urges referral to ASLB having jurisdiction over issue Notice of Appearance & Certificate of Byc encl REIS.E J Hearing Branch 3 80/06/23 9pp
- DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3
- A Application/construction stage documents & correspondence
- 8005230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT,D 0 Division of Licensing 80/05/20 13pp
- G Adjudicatory correspondence
- 8006240311 Order granting extension until 800715 for applicant to respond to Citizens for Energy & Employment 800602 motion to compel withdrawal of application for licenses BOHERS, E.S. Atomic Safety and Licensing Board Panel 80/06/18 ip
- 8006240467 Forwards procedural rules in response to intervenor 800602 motion W/o encl REIS.E J Hearing Branch 3 NRC 80/06/23 1p
- 8006260205 Response to Concerned Citizens for Employment & Energy 800602 motion to compel withdrawal of applications for CPs Urges referral to ASID having jurisdiction over issue Notice of appearance & Certificate of Svc encl REIS.C J Hearing Branch 3 80/06/23 9pp
- DOCKET 50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to moimplementation plan presented in Section 4 of NUREG-0377 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EIBENHUT, D O Division of Licensing 80/03/20 13pp
- 8006110040 Forwards Drawing 583F499 inadvertently omitted from Itam 7 of 800506 ltr NAUQHTON,W F Commonwealth Edison Co 80/06/03 ip
- 8006250145 Discusses reorganization of Dfc of Nuclear Reactor Regulation & advisos that mpt responsibilities re facility have been assigned to C Moon Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/12 80/06/12 11pp
- 8006230167 Requests addl info re auxiliary bldg design & containment bldg loads to assist EG%G in preparation of independent structural analysis YQUNGBLOOD, B J. Licensing Branch i 800/G6/16 3pp
- GOO6300453 Submits update of scheduled commerical svc dates for facilities, reflecting delays & scheduled OL fuel load dates Stresses importance of continued licensing process for Byron & Brajdwood PEOPLES,D L. Commonwealth Edison Co. BO/06/20 2pp
- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed GA Program for Nuclear Generating Stations "Revised Revision ii includes basis on which equivalent education requirements will be established PEOPLES,D L. Commonwealth Edison Co 80/06/23 1p
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 itr Addl specific criteria for facilities under development EIBENRUT, D. G. Division of Operating Reactors 80/04/25

- 8006160259 Forwards request for add1 info re 800324 safeguards contingency plan.constituting eighth set of Round 1 questions Encl withheld (ref 10CFR2 790) YOUNOBLOOD, 8 J Licensing Branch 1 80/06/02 2pp
- 8006160293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEDPLES,D L. Commonwealth Edison Co. 80/06/04 2pp
- --8006180347 Revision 1 to dra+t emergency plan * Commonwealth Edison Co 80/07/31 139pp
- 8006240490 Responds to NRC 800425.30.0501.07 ½ 20 ltrs requesting addlenger of response submittal date be extended to 800804 PEOPLES, D. Commonwealth Edison Co. 80/06/18 1p
- G Adjudicatory correspondence
- 8006060232 Supplemented statement of contentions alleging lack of technical qualifications to operate station Dose impacts of projected routine releases of radioactive matls should be re-evaluated Certificate of Svc oncl * DeKalb Area Alliance for Responsible Energy * Safe Energy for New Haven 80/05/07 24pp
- 8006020105 Answer to Dekalb Area Alliance for Responsible Energy & Sinnissippi Alliance for Environ supplemented contentions Recommends Contentions 7 & B. rewriting of Contentions 1.2 & 6 & deformal of Contentions 2a.3 & 4 W/Certificate of Svc KARMAN.M Hearing Branch 2 80/05/29 16pp
- H General correspondence
- 800&030307 Requests that ER Cross of Sargent & Lundy be added to distribution list
 NAUGHTON, W F Commonwealth Edison Co 80/05/22 1p
- G Inspection reports. IE Bullatins & correspondence
- 8006060325 Forwards IE Insp Repts 50-373/80-18, 50-374/80-11, 50-454/80-06, 80-445/80-06, 50-456/80-02 & 50-457/80-02 from meeting on 800328 No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/24 2np
- --8006060333 IE Insp Repts 50-373/80-18,50-374/80-11,50-454/80-06, 50-455/80-06,50-455/80-02 & 50-457/80-02 from meeting on 800328 Areas inspected status of three stations under const FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ,E R, BARRETT,P A, Region 3, Chicago, Office of the Director 80/04/14 4pp
- 8006170208 Forwards IE Insp Repts 50-454/80-05 & 50-455/80-05 on 800325-26 & notice of violation KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/25
- ---8006170213 Notice of violation from insp on 800325-26
 * Region 3, Chicago, Office of the Director 80/04/18 3pp
- --8006170219 IC Insp Repts 50-454/80-05 & 50-466/80-05 on 800325-26
 Noncompliance noted inadequate design drawing review & installation procedures
 YIN, I T. DANIELEON, D. H. Region G. Chicago, Office of the Director 80/04/18 App
- 8006020013 Forwards IE Insp Rept S0-454/80-07 on 800408-10 No noncompliance noted FIORFLLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006020816 IE Insp Rept 50-454/80-D7 on 800408-10 No nencompliance noted Major areas inspected RCPB & safety-related piping work activities, welding & procedures
 DANICLSON.D H Region 3, Chicago, Reactor Construction & Engineering Support Branch LEE, E W K Region 3, Chicago, Office of the Director 80/04/21 4pp
- 8006090497 Confirms 800519 discussion re 800530 meeting in Olen Ellyn, IL to discuss findings of util investigation into matl failure of containment post-tensioning sys anchor heads & remedial action to be taken KEPPLER, J & Region 3, Chicago, Office of the Director 80/05/22

- 8006170160 Revises response to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" Cover gasket replacement will be completed when cables to suitches are terminated PEOPLES D C. Commonwealth Edison Co. 80/05/30 Spp
- BOO6240535 Confirms 800613 meeting in Glen Ellyn, II to discuss findings of util investigation into math failure of containment post-tensioning sys anchor heads & remedial action KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/04 in
- BOO6230312 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-454/80-05 & 50-455/80-09 FIORELI, & Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/10 ip
- --8004230318 Responds to NRC 800425 ltr re violations noted in IE Insp Repts 50-454/80-05 & 50-455/80-05 Corrective actions safetyrelated hanger & snubber supplier forwarded revised installation instructions PEOPLES.D L. Commonwealth Edison Co. 80/05/27 10pp
- 8006260305 Ack receipt of 800521 itr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-454/79-18 & 50-457/79-18 & 50-457/79-18 FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/12 ip
- --8006260312 Responds to NRC 800126 ltr re violations noted in IE Insp Repts 50-45479-18 & 50-455/79-18 Corrective actions in depth analysis on concrete expansion anchor installations accomplished installation procedures revised & approved PCOPLES.D L Commonwealth Edison Co 80/05/21 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006020564 Ack receipt of 800515 interim deficiency rept re posttensioning anchorhead failure Requested extension until 800630 for submittal of final rept is acceptable FIDRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/23 ip
- DOCKET 50-455 BYRON STATION, URIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Settion 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and EISENHUT, D G Division of Licensing 80/08/20 iSpp
- 8006110040 Forwards Drawing 583F499 inadvertently unitted from Item 7 of 800506 ltr NAVGHTON.W F Commonwealth Edison Co 80/06/03 ip
- 8006250145 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re-facility have been assigned to C Moon Reorganization clearts smcl. TEDESCO.R L Assistant Director for Licensing 80/06/12 11pp
- 8006250167 Requests add1 info re auxiliary bldg design & containment bldg loads to assist E08G in preparation of independent structural analysis YOUNOBLOOD:B J Licensing Branch 1 80/06/16 3pp
- 8006300433 Submits update of scheduled commercial svc dates for facilities, reflecting delays & scheduled OL fuel load dates Stresses importance of continued licensing process for Buron & Braidwood PEOPLES, D. L. Commonwealth Edison Co. 80/06/20 2pp
- BOO6270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A, "Comm Ed GA Program for Nuclear Generating Stations" Revised Revision 11 includes basis on which equivalent education requirements will be established PEGPLES.D L. Commonwealth Edison Co. 80/06/23 1p
- F Security, medical, emergency & fire protection plans
- BOO5130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Add1 specific criteria for facilities under development EISENHUT.D G Division of Operating Reactors BO/04/25 61pp.

- 8006160259 Forwards request for add1 info re 800324 safeguards contingency plan.constituting eighth set of Round 1 questions Enc1 withheld (ref 100FR2 790) YOUNDELCOD, B J Licensing Branch 1 80/06/02 Rpp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES D. L. Commonwealth Edison Co. 80/06/04 2pp
- --8006180347 Revision I to draft emergency plan
 * Commonwealth Edison Co 80/07/31 139pp
- BD06240490 Responds to NRC 800425.30.0501.07 & 20 ltrs requesting addl info re guard training & qualification plans Requests that response submittal date be extended to 800804 PEDPLES, D. L. Commonwealth Edison Co. 80/06/18 1p
- Q Adjudicatory correspondence
- 8006060232 Supplemented statement of contentions alleging lack of technical qualifications to operate station Dose impacts of projected routine releases of radioactive matls should be re-evaluated Certificate of Svc encl * DeKalb Area Alliance for Responsible Energy * Safe Energy for New Haven 80/05/09 24pp
- H General correspondance
- BOO6030309 Requests that ER Cross of Sargent & Lundy be added to distribution list NAU0HTON:W F Commonwealth Edison Co BO/03/22 ip
- G Inspection reports. IE Bullatins & correspondence
- 8006060325 Forwards IE Insg Repts 50-373/80-18,50-374/80-11. 50-454/80-06,80-445/80-06,50-455/80-02 & 50-457/80-02 from asseting on 800328 Ny noncompliance noted KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/04/24
- --8006060333 IE Insp Repts 50-373/80-16.50-374/80-11.50-454/80-06. 50-455/80-06.50-436/80-02 & 50-457/80-02 from meeting on 800328 Areas inspected status of three stations Under const FIORELLIC Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/14 App
- 8006170208 Forwards IE Insp Repts 50-434/80-05 & 50-455/80-05 on 800325-26 & notice of violation KEPPLER, J O Region 3. Chicago, Office of the Director 80/04/25
- --8006170213 Notice of violation from insp on 800325-26 * Region 3, Chicago. Office of the Director 80/04/18 3pp
- --B006170219 lE Insp Repts 50-454/80-05 & 30-466/80-05 on 800325-26 Noncompliance noted inadequate design drawing review & installation procedures YIN.17 DANIELSON.D H Region G. Chicago, Office of the Director 80/04/18 6pp
- 800&070499 Confirms 800519 discussion re 800530 meeting in Olen Ellyn, IL to discuss findings of util investigation into met1 failure of containment post-tensioning sys anchor heads & remedial action to be taken KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/22 in
- 8006170160 Revises response to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EAIBO Limit Switches at Elevated Tamps "Cover gastet replacement will be completed when cables to switches are terminated PEOPLES,D L Commonwealth Edison Co 80/05/30 2pp
- BOO6240535 Confirms 800613 meeting in Olen Ellyn, Il to discuss findings of util investigation into mati failure of containment post-tansioning sys anchor heads & remedial action
 KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/06/04.

- 8006230312 Ack receipt of 800527 ltr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-454/80-05 & 50-455/80-05 FIORELLI, & Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/06/10 ip
- --8006230318 Respands to NRC 800425 ltr re violations noted in IE Insp Repts 50-454/80-05 & 50-455/80-05 Corrective actions safetyrelated hanger & snubber supplier forwarded revised installation instructions PEOPLES.D L Commonwealth Edison Co 80/05/27 10pp
- 8006260305 Ack receipt of 800521 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50~454/79-18 & 50~459/79-18 FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/12 ip
- --8006260312 Responds to NRC 800126 itr re violations noted in IE Insp Repts 50-454/79-18 & 50-455/79-18 Corrective actions in depth analysis on concrete expansion anchor installations accomplished Installation procedures revised & approved PEOPLES D L Commonwealth Edison Co 80/05/21 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006020364 Ack receipt of 800315 interim deficiency rept re posttensioning anchorhead failure Requested extension until 800630 for submittal of final rept is acceptable FIORELLIO Region 3. (hicago, Reactor Construction & Engineering Support Branch 80/05/23 ip
- DOCKET 50-456 BRAIDWOOD STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor revises procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 90/05/20 13pp
- 8006110040 Forwards Drawing 583F499 inadvertently omitted from Item 7 of 800506 ltr NAUGHTON.W F Commonwealth Edison Co 80/06/03 ip
- 8004250145 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mot responsibilities re facility have been assigned to C Moon Reorganization charts enci TEDEBCO.R L Assistant Director for Licensing 80/Q6/12 11pp
- 8006200167 Requests addl info re auxiliary bldg design & containment bldg loads to assist E0&O in preparation of independent structural analysis YOUNOBLOOD, BJ Licensing Branch 1 80/06/16 3pp
- 8006300433 Submits update of scheduled commercial svc dates for facilities, reflecting delays & scheduled OL fuel load dates Stresses importance of continued licensing process for Byron & Braidwood PEOPLES, D. L. Commonwealth Edison Co. 80/06/20, 2pp
- 800&270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations "Revised Revision 11 includes basis on which equivalent education requirements will be established PEOPLES.D L. Commonwealth Edison Co. 80/06/23 ip
- F. Becurity, medical, emergency & fire protection plans
- 8005i303i7 Forwards clarification of NRC requirements for emergency response facilities defined in 7909i3 itr Addl specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 dipp
- BOO6040019 Forwards seventh set of round one questions re 790818 training & requelification plan per review of application for GL Encl withheld (ref 10CFR2 790) YOUNGBLOOD, B J Licensing Branch 1 80/05/20 2pp
- 8006170855 Forwards sighth set of Round one questions re 800324 safeguards contingency plan Questions withheld (ref 100FR2 790) YOUNGBLOOD; B J. Licensing Branch 1 80/06/02, 2pp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES, D. L. Commonwealth Edison Co. 80/06/04 2pp

- --8006180347 Revision 1 to draft emergency plan * Commanwealth Edison Co 80/07/31 139pp
- BOO6240490 Responds to NRC BO0425.30.0501.07 & 20 ltrs requesting addline or guard training & qualification plams Requests that response submittal date be extended to 800804 PEOPLES.D L Commonwealth Edison Co 80/06/18 ip

H General correspondence

- 8006030309 Requests that ER Cross of Sargent & Lundy be added to distribution list NAUGHTON,N F Commonwealth Edison Co 80/09/22 1p
- Q Inspection reports, IE Bulletins & correspondence
- 8006060325 Forwards IE Insp Repts 50-373/80-16, 50-374/80-11, 50-454/80-06, 80-445/80-06, 50-456/80-02 & 50-457/80-02 from meeting on 800328 No noncompliance noted KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/24 200
- --8004040333 IE Insp Repts 50-373/80-18.50-374/80-11.50-454/80-04, 50-455/80-04, 50-455/80-04, 50-456/80-02 & 50-457/80-02 from meeting on 800328 Areas inspected status of three stations under const FIORELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/14 App
- B006170771 Forwards IE Insp Repts 50-456/80-03 & 50-457/80-03 on B00416-17 No noncompliance noted FIGRELLI.O Region 3. Chicago: Reactor Construction & Engineering Support Branch B0/05/06 Zpp
- ---8006170776 IE Insp Repts 30-456/80-03 & 50-457/80-03 on 800416-17 No noncompliance noted Major areas inspected review of records, cable tray hanger specs & action on previous insp findings HAYES,D W Region 3. Chicago, Office of the Director NAIDU,K R Region 3. Chicago, Roactor Construction & Engineering Support Branch 80/05/06 ópp
- 8006090044 Ack receipt of 800508 ltr informing NRC of steps taken to correct yielations noted in IE lnsp Repts 50-456/79-15 & 50-457/79-15 FIDRELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/21 ip
- --8006090047 Responds to NRC 800118 ltr re violations noted in IE Insp Repts 50-456/79-15 & 50-457/79-15 Corrective actions vendor long-term storage recommendations will be reviewed & filed for future ref PEOPLES.D L Commonwealth Edison Co 80/05/08 2pp
- 8006170160 Revises response to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model CAIBO Limit Switches at Elevated Temps "
 Cover pastet replacement will be completed when cables to switches are terminated.
 PEOPLES D L Commonwealth Edison Co 80/05/30 2pp

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

- A Application/construction stage documents & correspondence
- B006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adducacy of applicable support structures General operating reactor review procedure & acceptance criteria encl. EISENHUT.D. G Division of Licensing B0/05/20 13pp
- B006110040 Forwards Drawing SB3F499 inadvertently omitted from Item 7 of B00506 ltr NAUQHTON,W F Commonwealth Edison Co B0/06/03 lp
- 8006250145 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to C Moon Reorganization charts encl TEDESCORY : Assistant Director for Licensing 80/06/12. 11pp
- BOO6250167 Requests add1 info re muxiliary bldg design & containment bldg loads to assist EG&O in preparation of independent structural analysis. YOUNOBLOOD, B J Licensing Branch i BO/O6/16 3pp
- 8006300453 Submits update of scheduled commerical svc dates for facilities, reflecting delays & scheduled OL fuel load dates Stresses importance of continued licensing process for Byron & Braidwood PEOPLES, D L. Commonwealth Edison Co. 80/06/20. 2pp

- 8006270306 Forwards revised Revisions 11 & 12 consisting of Page 1-7 of CE-1-A. "Comm Ed GA Program for Nuclear Denerating Stations "Ravised Revision 11 includes basis on which equivalent education requirements will be established PEOPLES.D L. Commonwealth Edison Co. 80/06/23 1p
- F Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENKUT, D 0 Division of Operating Reactors 80/04/25 61pp
- 8006040019 Forwards seventh set of round one questions re 790818 training & requalification plan per review of application for OL Encl withheld (ref 100FR2 790) YOUNOBLOOD, B J Licensing Branch 1 80/05/20 2pp
- 8006170855 Forwards mighth set of Round one questions re 800324 safeguards contingency plan Questions withheld (ref 10CFRZ 790) YOUNGBLODD: I J Licensing Branch 1 80/06/02 2pp
- 8006180293 Forwards Revision 1 to draft emergency plan Emergency plan station annexes also encl PEOPLES, D.L. Commonwealth Edison Co. 80/06/04 2pp
- 8006240490 Responds to NRC 800425,30,0301,07 & 20 ltrs requesting addition from guard training & qualification plans Requests that response submittal date be extended to 800804 PEOPLES.D L. Commonwealth Edison Co. 80/06/18 1p

H General correspondence

- 8006030309 Requests that ER Cross of Sargent & Lundy be added to distribution list. NAUOHION W F Commonwealth Edison Co B0/05/22 ip
- G Inspection reports, IE Bulletins & correspondence
- 8006060325 Forwards IE Insp Repts 50-373/80-18, 50-374/80-11, 50-454/80-06, 80-445/80-06, 50-455/80-02 & 50-457/80-02 from meeting on 800328 No noncompliance noted.

 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/04/24
- --B006060333 IE Insp Repts 50-373/80-18,50-374/80-11,50-454/80-06, 50-455/80-06,50-456/80-02 & 50-457/80-02 from meeting on 800328, Areas inspected status of three stations under const FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/14 4pp
- BOOA170771 Forwards IE Insp Repts 50-456/80-03 & 50-457/80-03 on 800416-17 No noncompliance noted FIGRELLI.G Region 3. Chicago, Reactor Construction & Engineering Buyport Branch BO/05/06 2pp
- --8006170776 IE Insp Repts 30-456/80-03 & 50-457/80-03 on 800416-17 No noncompliance noted Major areas inspected review of records, cable tray hanger specs & action on previous insp findings HAYEB, D W Region 3, Chicago, Office of the Director NAIDU, K. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/06 6pp
- 800,6070044 Ack receipt of 800508 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/79-15 & 50-457/79-15 FiORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/05/21 ip
- --8005090047 Responds to NRC 800118 ltr re violations noted in IE Inap Repts 50-455/79-15 & 50-487/79-15 Corrective actions vander long-term storage recommendations will be reviewed & filed for future ref PEOPLES,D L Commenwealth Edison Co. 80/05/08 2pp.
- 8006170160 Revises response to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps "
 Cover gasket replacement will be completed when cables to switches are berminated.
 PEOPLEB, D L Commonwealth Edison Co 80/05/30 2pp,

- DOCKET 50-458 RIVER BEND STATIO & UNIT 1

 A Application/construction stage documents & correspondence
- BOO5230110 Advises BHR 5 PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUMEG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT, D O Division of Licensing BO/05/20 13pp
- 8006180321 Ack receipt of 800506 ltm re fraquency of testing for job cament alkali content After consideration of final 6-month ASTM C277 norbar bar test reptiNRC has no further questions SEIDLE.H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/03/27 ip
- --8005180329 Forwards Pittsburgh Testing Lab 800985 & 800985 repts for fine & coarse aggregates respectively, in response to NRC 791213 request Repts give 6-ronth results of ASTH C027 mortar bar test using high & low alkali job cement MEIGAND, U.G. Gulf States Utilities Co. 60/05/06 5pp
- 8006170371 Forwards "Proposed Widening of Existing Transmission Line Corridor River Bend Nuclear Power Station Units 1 & 2." preliminary case rept Requests expedited comments sinco util has been requested to suspend const
- --8005170375 "Proposed Midening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2." preliminary case rept Natl Register property descriptions & proposed namonandum of agreement encl
- 8006240616 Forwards "For Comment" edition of NUREO-0619 Requests review & comment N/o encl EIGENNUT.D 9 Division of Licensing 80/06/10 3pp

- R006200545 Discusses NRC antitrust review in response to 800418 ltr repassible Cajun Electric Power Cooperative.Inc antitrust violations w/respect to facility Comments will be considered when util applies for OL NICHOLSGN.P Utility Finance Branch 80/05/05 2pp
- E0061E0197 Forwards Atty General 800505 ltr furnishing addl antitrust info Ltr will be sent to Ofc of FR Petitions to intervene & requests for hearings may be filed by interested parties within 30 days after FR publication SALTIMAN, J Utility Finance Branch 80/05/19 1p
- --B004160215 Advises that review of info submitted for antitrust review provides no basis to conclude that Cajun Electric Power Cooperative. Inc participation would create situation inconsistent u/antitrust laws
 LITVACK.8 M Justice.Dept of 80/09/05 ip
- 8006;2013: Forwards Atty General 800505 ltr providing add1 antitrust advise rs CP application No antitrust hearing necessary for proposed amend to CP BALTZMAN.J Antitrust & Indemnity Group 80/05/21 2pp
- --B006120137 Advises that review of info submitted for antitrust review purposes, re-proposed amend to CP to allow Cajun Electric Power Cooperative. Inc & Sam Rayburn GET. Inc to become unit co-owners, provides no basis for antitrust hearing LITRACK. S H Justice. Dept of 80/05/05 1p

G Inspection reports, IE Bulletins & correspondence

- 8006300058 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/01
- 8008030218 Forwards IE Insp Rept 50-458/80-04 on 800331-0403 No noncompliance noted SEIDLE, W C Region 4. Dalles. Reactor Construction & Engineering Support Branch 80/04/16 2pp
- --8006030225 IE Insp Rept 50-458/80-04 on B00331-0403 No noncompliance noted Major areas inspected storage of safety-related equipment concrete placement & reinforcing steel installation CROSBMAN, M A . BEACH.A B . OBERG.C R Region 4. Dallas. Office of the Director B0/04/15 5pp

- B006040345 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys
 Operability "No written response required IE Info Notice
 B0-20, "Loss of Decay Heat Removal Capability at Davis-Besse
 Unit 1 While in Refueling Mode" encl
 SEYFRIT.K V Region 4. Dallas, Office of the Director B0/05/09
- B006300065 Forwards IE Circular 80-12, "Valve-Shaft-To-Actuator Key May Fall Out of Place When Mounted Below Horizontal Axis " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/05/14
- 8006070012 Ack receipt of 800305 & 0425 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-459/79-06 GEIDLC.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/05/22 ip
- --8006090015 Responds to NRC 800401 ltr re violations noted in IE Insp Rept 50-498/79-06 Corrective actions accept/reject critoria for potentially reactive aggregate w/low alkalar cement has been deleted WEIGAND.J O Gulf States Utilities Co 80/04/25 2pp
- 8006230100 Responds to IE Bulletin 80-02, "Inadequate GA for Nuclear Supplied Equipment" No matls or work have been provided by Marvin Engineering Co GE supplies reactor pressure vessels to internals under contract w/util DRAPER, EL Oulf States Utilities Co 80/05/23 ip
- S Reportable occurrences, LERs & related correspondence
- BDDAOAOSAS Advisos that potential deficiency re concrete "cold joint" does not appear to represent significant deficiency reportable under 10CFRSO 35(o) Results of final analysis will be forwarded within 30 days WEIOAND, J O Quif States Utilities Co BO/04/22 1p
- 800611026B Deficiency rept re diesel generator bldg concrete matl cold Joint Equipment failure did not represent breakdown in GA program Btructural analysis indicated unplanned const joint did not impair structural integrity or performance of matl DRAPER.E L. Gulf States Utilities Co. 80/05/22 1p

DOCKET 50-459 RIVER BEND STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8006230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enri EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006170371 Forwards "Proposed Widening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2." proliminary case rept Requests expedited comments since util has been requested to suspend const activities REGAN, W H Siting Analysis Branch 80/06/02 2pp
- --8006170375 "Proposed Midening of Existing Transmission Line Corridor, River Bend Nuclear Power Station, Units 1 & 2," preliminary case rept Natl Register property descriptions & proposed memorandum of agreement encl # Division of Engineering 80/06/02 40pp
- 8006240616 Forwards "For Comment" edition of NUREG-0619 Requests review & comment W/o encl EISEMPUT.D Q Division of Licensing 80/06/10 3pp
- Q Inspection reports: IE Bulletins & correspondence
- 8004300058 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required SEYFRIT,K V Region 4. Dallas, Office of the Director. 80/04/01
- 8006040345 Forwards IE Bullstin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Dassa Unit 1 While in Refueling Mode" encl SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/09.

- 8004306065 Forwards IE Circular 80-12. "Valve-Shaft-To-Actuator Key May Fall Out of Place When Mounted Below Horizontal Axis " No Written response required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/05/14
- 8006230100 Responds to IE Bulletin 80-02, "Inadequate QA for Nuclear Supplied Equipment" No matis or work have been provided by Marvin Engineering Co GE supplies reactor pressure vessels 3 internals under contract w/util DRAPER,E L Guif States Utilities Co 80/05/23 1p
- DOCKET 50-460 MPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- 800.603.0464 Suggests that clarification be added to Pago 54 of NUREG-0460, Vol 4, to reflect context in which cost estimates for ATMS mods are made Utils believe indirect costs were underrated Disputes value impact analysis RENDERGER, K.L. Washington Public Power Supply System 80/05/28
- 8006050358 Forwards response to NRC 800325 request for add1 info re sym sensitivity RENBERGER.D L. Washington Public Power Supply System 80/06/02
- 800&110278 Notifies that lab will be conducting addit moisture testing on low hydrogen electrades using technique required in AWS AS 5. Section 25 Electrade coating moisture testing results will be applied only to Units 1 & A RENBERGER, D.L. Washington Public Power Supply System 80/06/06
- F Security, medical, emergency & fire protection plans
- 8006270324 Forwards Amend 2 to "Fire Protection Evaluation "
 RENBERGER, D L Washington Public Power Supply System 80/06/11
- --8006270326 Amend 2 to "Fire Protection Evaluation"

 * Washington Public Power Supply System 80/05/31 App
- BOGA240404 Forwards drawings re location for near-site emergency ctr Requests immediate review & response so that site-specific design work can proceed & site preparation begin "Preconceptual Site Plan" available in Central Files only RENNERGER, D L Washington Public Power Supply System 80/06/16 600
- --8006240408 "Wind Rose for WPPS-2 for Apr 1974 to Mar 1975 at
 - * Washington Public Power Supply System 75/03/31 ip
- --BOOA240418 "Environ Programs Base Map Hanford Area "

 ** Washington Public Power Supply System 79/01/12 10
- O Inspection reports, IE Bulletins & correspondence
- BOOACA0134 Forwards IE Insp Repts 50-460/80-05 & 50-513/80-05 on 800331-0403 No noncompliance noted SPENCER.0 S Region 5. San Francisco: Reactor Construction & Engineering Support Branch BO/04/28 2pp
- ---BOO&O&O141 IE Insp Repts 50-460/80-05 & 50-513/80-05 on 800331-0403 No moncompliance noted Major areas inspected WKM valve flaw indications: pipe support & restraint sys & administrative controls for nonconforming conditions DODDS:RT Region 5, San Francisco: Reactor Construction & Engineering Support Branch NARBUT.PP, WAGNER,W Region 5, San Francisco, Office of the Director 80/04/24 opp

- 8006090402 Ack receipt of 800515 ltr informing NRC of steps taken to correct deviation noted in IE Insp Repts 80-460/80-04 & 50-513/80-04
 SPENCER 6 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/30 1p
- --8006070404 Responds to NRC 800415 ltr re deviation noted in IE Insp Repts 30-460/80-04 \$ 50-513/80-04 Corrective actions engineering evaluations determined that use of electrode is acceptable based on ASME III guidelines REMBERGER, D. L. Washington Public Power Supply System 80/05/15 200
- ---8006070409 Forwards IE Insp Repts S0-460/80-04 & 50-513/80-04 on Q00301-31 & notice of deviation SPENCER. 0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/04/15 2pp
- --8006090412 Notice of deviation from insp on 800301-31 * Region 5, San Francisco, Office of the Director #0/04/11 ip
- --8006090418 IE Insp Repts 50-460/80-04 & 50-513/80-04 on 800301-31 Noncompliance noted welding electrodes qualified under Spac SFA-5 1 tather than SFA-5 5 were used for welding pipe-to-steam generator RCPD welds TOTHLA D . HAYNES.R C Region 5. San Francisco. Office of the Director 80/04/11 7pp
- 8006090406 Ack receipt of 800507 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-460/80-01 & 50-513/80-01 SPENCER. S Region 5, 9an Francisco, Reactor Construction & Engineering Support Branch 80/05/30 1p
- --8004090414 Responds to NRC 800407 ltr re violations noted in IE Insp. Repts 50-460/80-01 & 50-513/80-01 Corrective actions temporary hanger & support procedure initiated & training session held on 800206 RENBERGER.D. L. Washington Public Power Supply System 80/05/07 400
- --8006090441 Forwards IE Insp Repts 50-460/80-01 & 50-513/80-01 on 800101-31 & notice of violation SPENCER.O S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/04/07 2pp
- --BODA070447 IE Insp Repts 50-440/80-01 & 50-513/80-01 on 800101-31
 Noncompliance noted failure to control temporary attackments
 to structural steel & Undersite welds on pipe supports
 HAYNES,R C Region 5, San Francisco, Reactor Construction &
 Engineering Support Branch TOTH A D Region 5, San Francisco
 Office of the Director 80/04/02 9pp
- S Reportable occurrences: LERs & related correspondence
- 8006020032 Part 21 rept re use of earlier revision of amplified response spectra in design of two safety-related tanks.

 Details in NRC 790521-25 GA program insp

 SARSTCN.0 E United Engineers & Constructors, Inc (subs of Raytheon Co) 80/03/13 4pp
- ---H006020085 Notice of deviation from insp on 790821-25 * Region 4, Dallas, Office of the Director 79/06/13, is
- BOOA050236 FNO-V-80-037 on BOO518, Mount St Halen erupted. Unit 2 has approx 1/8-inch of ash on ground some ash dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive matls in sys components underway BISHOP. TW Region 5, San Francisco, Office of the Director BO/05/19. 2pp
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 readequacy of applicable support structures. General operating reactor review procedure & acceptance criteria encl EISENHUT.D Q Division of Licensing 80/05/20 13pp
- 8006230028 Notification of 800624-26 meeting w/util in Clinton, IL to discuss forthcoming caseload forecast panel visit BUCKLEY, B Licensing Branch 3 80/06/09 4ps

- 6006260054 Forwards "For Cornent" edition of NUREG-0619 Comments should be forwarded by 800707 M/o encl EISENNUT.D G Division of Licensing 80/06/09 2pp
- F Becurity, medical, energency & fire protection plans
- B006300438 Requests extension of time for submittal of security guard training & qualification program until Dec 1780 Previously tendered security plan matl has been accepted for docketing HULLER.O E Illinois Power Co 80/06/19 ip
- Q Inspection reports, IE Bulletins & correspondence
- 8006200118 Forwards IE Insp Rept 50-461/80-04 on 800325-28 & notice of violation FIGRELLIG Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/04/25 2pp
- --800A200121 Notice of violation from insp on 800325-28 e Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 ip
- --800A200124 IE Insp Rept 50-4A1/80-04 on 800325-28 Noncompliance noted requirements not correctly translated into drawings & specs NAIDU.K., WARD.K., KNOP.R.C. Region 3, Chicago, Office of the Director 80/04/21 15pp
- 8006230145 Forwards IE Insp Rept 50-461/80-07 on 800422-24 & notice of violation FIGRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/09 2pp
- --8006230148 Notice of violation from insp on 800422-24
 * Region 3. Chicago, Office of the Director 80/05/09 2pp
- --8006230151 IE Insp Rept 50-461/80-07 on 800422-24 Noncompliance noted failure to properly store welding math.failure to verify conformance during insp & failure to conform w/procedures DANIELSON, D H Region 3. Chicago, Reactor Construction & Engineering Support Branch LEE,E W K Region 3. Chicago, Office of the Birector 80/03/09 opp
- B006230049 Forwards 1E Insp Rept 30-461/80-08 on B00414-30 & notice of violation FIORELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8006230054 Notice of violation from insp on 800414-30
 * Region 3. Chicago. Office of the Director 80/05/13 2pp
- ---800A2300A1 IE Insp Rept 50-4A1/80-08 on 800414-30 Noncompliance noted inadequate control of welding processes & inadequate control of nonconforming mati NNDP.R C . LIVERMORE.H H Region 3, Chicago, Diffice of the Director 80/05/13 8pp
- 8006250372 Act receipt of 800522 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-461/80-04.
 FIURELLI. 9 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/11 tp
- --8006250375 Responds to NRC 800425 ltr re violations noted in IE Insp Rept 50-461/80-04 Corrective actions Bargent & Lundy design drawing will be revised to identify 480-volt switchgear holes to be welded to ambedded angle iron GERSTNER.W C Illinois Power Co 80/05/22 2pp
- 8006300613 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-461/80-08 FIORELI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/17 ip
- --8006300616 Responds to NRC 800514 ltr re violations noted in IE Insp Rept 50-461/80-08 Corrective actions removed all scrap matl from designated reject/hold area & verified appropriate boundary markers OERSTNER.W C Illinois Power Co 80/06/06 ip

2

ndence

to modify 77 rm ating

- BOO6260064 Forwards "For Commont" edition of NUREG-0619 Comments should be forwarded by 800707 W/a encl EISENHUT, D.G. Division of Licensing 80/06/09 2pp
- F Security, medical, emergency & fire protection plans
- 800630043B Requests extension of time for submittal of security guard training & qualification program until Dec 1980 Previously tendered security plan matl has been accepted for docketing WULLER.6 E Illinois Power Co 80/06/19 1p
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006290133 Forwards "For Comment" edition of NUREC-0617 Describes technical issues, studies & analyses performed by GE Comments should be forwarded to NRC by 800707 W/o encl EIGENNUT,D & Division of Licensing 80/06/06 2pp
- 8006230151 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to C Moon Reorganization charts encl TEDESCO,R L Assistant Director for Licensing 80/06/12 11pp
- Q Adjudicatory correspondence
- BOO6190343 Responds to telcon & ltr requesting clarification of applicant responses to 13th set of interrogatories Explains use of citations & extent of answers Related correspondence BIDDLE.C T Baker & Botts BO/03/31 2pp
- 8006186013 Response to Houston Lighting & Power motion to compel production of documents from TX PIRO & C Hinderstein Motion is most due to Johnson 80042B itr informing of intention to produce documents in two was Related correspondence SCOTY.J Texas Public Interest Research Group 80/05/01 ip
- 8006060392 Interrogatories & requests for production of documents reconsolidated Contention 2 concerning effect of transmission lines on human health Marrack 800502 Itr to util & Certificate of 8vc enc!

 MARRACK.D Marrack.D RENFRD.W E Affiliation Unknown 80/05/03
- 8006120030 Response to JF Doherty 16th request for production of documents NEDD-10903-1; NEDD-10478; APED-5756; APED-5555; NEDD-10017; NEDD-20913A; NEDD-20939 & NEDD-24154 I & II are evailable for insp & copying Certificate of Bvc encl BIDDLE; C T, NEWMAN; J R Houston Lighting & Power Co BIDDLE; C T Baker & Botts 80/05/06 4pp
- 8006170286 Requests & interrogatories re financial qualifications including request for insp & copying.first set of interrogatories directed to applicant & request for documents directed to ARC W/Gertificate of Evc & article BAKER.D Affiliation Unknown 80/05/09 9pp
- 8006050085 Motion for protective order re public disclosure of vendor documents & info requested by JF Doherty Disclosure may impair vendor competitive position Certificate of Svc & groposed order encl
 BIDDLE.C.T., NEWMAN.J R Houston Lighting & Power Co BIDDLE.C T Bater & Botts 80/05/13 9pp
- 8006020190 Discusses implications of ALAB-590, requiring patitioners to intervene to state bases for each contention w/reasonable specificity Ruling shifts burden on applicant & NRC w/respect to contentions
 LAZO.R M. Atomic Safety and Licensing Board Panel 80/05/16 2pp
- B006090204 First set of interrogatories & requests for production of documents directed to UM Bishop Requests identification of expert witnesses & matls related to testimony Certificate of Svc encl
 BIDDLE.C T , NEWMAN, J R Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/05/17 Spp

- BOO6090215 First set of interrogatories & requests for production of documents directed to intervenor BL Baker Requests identification of expert witnesses & matls related to testimony Certificate of Svc encl Related correspondence BIDDLE, J G Houston Lighting & Power Co BIDDLE, J G Baker & Botts BO/05/17 Sep
- BOO6120061 First set of interrogatories & requests for production of documents directed to intervenor SA Doggett Requests identification of witnesses & matter related to planned expert testimony Certificate of Svc encl BIDDLE.C T . NEWMAN.J R Houston Lighting & Power Co BIDDLE.C T Reker & Botts 80/05/17 Spp
- 8006120064 First set of interrogatories & requests for production of documents directed to intervenors Framson Requests identification of witnesses & matis related to planned supert testimony Certificate of Svc encl BIDDLE.C T . NEWMAN.JR Houston Lighting & Power Co *BIDDLE.C T Baker & Botts 80/05/17 5pp
- 8006120068 First set of interrogatories & requests for production of documents directed to intervenor D Marrack Requests identification of witnesses & matls related to planned expert testimony Certificate of Svc encl.

 BIDDLE, C T , NEWMAN, J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/05/17 Spp
- SOG6120097 First set of interrogatories & requests for production of documents directed to intervenor FH Potthoff Requests identification of witnesses & matls related to planned expert testimony Certificate of Svc encl
 BIDDLE, C T , NEWMAN, J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts B0/05/17 Spp
- 8006060380 Response to Houston Lighting & Power first set of interrogatories & requests for production of documents Intervenor witnesses & testimony-related documents are unknown Certificate of Syc ancl Related correspondence DOGOSTI, 6 A Affiliation Unknown 80/05/19, 5pp
- BD06120417 Urges that applicant 800427 motion be granted to compel production of documents from TX PIRG & C Hinderstein, re three groups of documents not produced on 800515 Certificate of 8vc encl Related correspondence

 NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 80/05/20 4pp
- BOO6180196 Notice of BOO613 deposition at author ofc, directed to BL Baker to testify on behalf of utiline contentions admitted per ASLB BOO310 order Instructions & Certificate of Byc encl COPELAND, J & Houston Lighting & Power Co COPELAND, J & Baker & Botts 80/05/20 4pp
- --8006180200 Notice of 800611 deposition at author ofc, directed to JM Bishop to testify on behalf of util.re contentions admitted per ASLB 800310 order Instructions & Certificate of Svc enc!
 COPELAND, J G Houston Lighting & Power Co. COPELAND, J G Baker & Botts 80/05/20 4pp
- --8006180205 Notice of 800612 deposition at author ofc.directed to SA Doggett to testify on behalf of util.re contentions admitted per ASLS 800310 order Instructions & Cartificate of Bvc entl COPELAND.J G Houston Lighting & Power Co COPELAND,J Q Baker & Botts 80/05/20 4pp
- 8006020464 Order granting in part & denying in part applicant 800501 motion to confirm agreements on consolidation & to consolidate centain contentions Lead party must be appointed in 10 days to present widence.cross-examine & plead WOLFE.B J Atomic Safety and Licensing Board Panel 80/05/23 6pp
- 8006060463 Advises that authors do not share RM Lazo concerns that ALAB-370 eliminates bases requirement for contentions. ABLB is not free to determine whether petitioner has correctly relied on bases cited PARIS.O H, BECHIOEFER, C, SHON, FJ Atomic Sefety and Licensing Board Panel 80/05/27 2pp
- 8006160166 Notice requesting D Marrack to appear for 800620 deposition on behalf of utiliat author ofc.re contentions admitted by ASLB 800310 onder Instructions & Certificate of svc encl Related correspondence BIDDLE.C T Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/05/27 4pp

- --8006160170 Notice requesting R or H Fremson to appear for 800618 deposition on behalf of util at author ofc.re contentions admitted by ASLS 800310 order Instructions & Certificate of Svc encl BIDDLE.C 7 Houston Lighting & Power Co BIDDLE,C T Baker & Botts 80/05/27 4pp
- 800&190101 FOIA request for i8 documents specifically identified by accession number, docket numbers & prief description to aid in facility proceeding DOHERTY. J F Doherty. J F 80/05/28 4pp
- 8004090065 Order granting applicant 800429 motion to compel production of documents from intervenors C Hinderstein & TX PJRO redocuments not produced on 800515 Intervenors shall comply w/order by 800609 WOLFE,S J Atomic Safety and Licensing Board Panel 80/05/30 2pp
- ---B004070076 Express concerns re exemption of plants from environ impact consideration on catastrophic events WEINREB-KIMHM Affiliation Unknown B0/05/20 2pp
- --8006090083 Urges issuance of supplemental EIB re Class 9 accident potential Certificate of Svc encl SCHWARTZ.A R Texas. State of 80/05/22 4pp
- 8006170224 Order granting applicant 800429 motion to compel production of documents from intervenors C Hinderstein & TX PIRG rethree groups of documents not produced on 800515 Intervenors shall comply worder by 800609 HOLFE, S U Atomic Safety and Licensing Board Panel 80/05/30. 2pp.
- 8006110346 Response in opposition to applicant motion to compel addl documents from TX PIRO & C Hinderstein Financial terms between intervenors & witnesses are proprietary in mature. TX PIRO does not possess city water supply studies SCOTT.J Texas Public Interest Research Oroup 80/05/31 5pp
- 8006040115 Second partial response to JF Doherty twelfth set of interrogatories includes NUREO CR-0660 recommendations. IE field insps of GA program implementation & diesel generator events Affidavit & Certificate of Svc encl SOHINKI.S M Hearing Branch 3 80/06/02 18pp
- 8006110170 Motion to quash applicant 800427 motion to compel production of documents from C Hinderstein & TX PIRO No written contract or agreement w/Barion exists Other info requested is under third party control Certificate of Byc encl. HINDERSTEIN:C Affiliation Unknown 80/06/03 4pp
- B006190883 Statement of position re linkage of financial qualifications & safety ASLB 800310 order did not prevent intervenors from asserting linkage between financial qualifications & safety. Certificate of Svc encl Related correspondence BAKER.B Affiliation Unknown 80/06/03 4pp
- --8006190557 Response to applicant first set of interrogatories & request for production of documents Mitnesses as yet unknown Certificate of Svc encl Related correspondence, BAKCR B Affiliation Unknown, 80/06/03 2pp
- --8006170564 Second set of interrogatories & request for production of documents Requests identity of witnesses Certificate of Svc encl Related correspondence BAKER.B Affiliation Unknown 80/06/03 2pp
- 8006190569 First set of interrogatories re consolidated contentions
 Doggett 4 & Perrenod 1 Requests info re witnesses, financial
 estimates of const delays & estimate of date of commercial
 operation Certificate of Syc uncl Related correspondence
 DOGGETT. B A Doggett, B A 80/06/05 lipp
- B006160028 Forwards 800606 interrogatories & requests for production of documents
 JOHNSON-C Texas Public Interest Research Group 80/06/06 [p.
- ---B006160029 Interrogatories & requests for production of documents.
 Includes questions re computation of stress capabilities of reactor coolant boundary & length of time required for reactor scram
 JOHNSDN: G Texas Public Interest Research Group 80/06/06 2pp
- 8006180427 Recommends that ASLAB composition be changed to remove imbalance between lawyer & technical members & that unnecessary legalistic burdens, procedures & requirements be eliminated DEALE, V B Valentine B Deale 80/06/09, 4pp

- 8006130157 Advises of receipt of B Bater 800603 statement of position re linkage between financial qualifications & safety All parties involved should be consolidated on issue Requests that ASLD require appointment of single representative 80HINKI/S M Hearing Branch 3 80/06/11 2pp
- 8006170609 Motion for encl protective order & agreement re JF Doherty 800112 motion for subposes to produce GE "Read Rept" Photocopy privilege will be granted if shown that document is essential for evidentiary purposes M/Certificate of Svc BIDDLE.C T , NEWAN.J R Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/06/11 iSpp
- BOO6180346 Response to Blaker BO0611 motion to compel production of documents me applicant rate hike application & hearing. Motion is most due to availability of documents for insp & capying Certificate of Svc encl COPELAND.J O. NEMMAN.J R. Houston Lighting & Power Co COPELAND.J G. Baker & Botts BO/06/12 3pp
- --8005180394 Mation to compel production of documents re applicant rate hite application & hearing Requests access for indefinite period beyond discovery limit BAKER:B Affiliation Unknown 80/05/11 2pp
- 8006180395 Order denying as most TX PIRO 800531 response & C Minderstein 800603 motion, due to resolution of disputed items among applicant & intervenors ASLB 800530 order reproduction of documents is vacated WOLFE, S J Atomic Safety and Licensing Board Panel 80/06/12 2pp
- --8006180398 Advises that disputed items between applicant & intervenors
 TX PIRG & C Hinderstein.re ASLB 800530 order, have been
 resolved
 COPELAND, J © Baker & Botts. 80/06/11 2pp
- 8006190096 Responds to FOIA request for 18 documents identified by accession number docket numbers & brief description to aid in facility proceeding Forwards documents listed in App A Documents 6 & 14 unavailable N/o encis FELTON, J M Division of Rules and Records 80/06/13. 3pp
- 8006230433 Concurs w/NRC 800611 position re intervenor B Paker 800603 contention re linkage between financial qualification & safety Order consolidating such contentions & appointing single litigating party requested Certificate of 8 oc ancl RASKIN, D B Lowenstein, Neuman, Reis, Azelrad & Toll 80/06/17 App
- 8005240457 Motion to compel D Marrak answers to util 800517 interrogatories & requests for production of documents. Applicant must be notified of expert witnesses prior to 800709 Certificate of Syc encl Related correspondence COPELAND. J. & Houston Lighting & Power Co 80/06/19 App
- BOOG240464 Motion for issuance of subpoena directed to D Marrack for BOO620 deposition noticed to intervenor on BO0527 Certificate of Syc. draft subpoena & deposition schedule and Related correspondence COPELAND. J O Houston Lighting & Power Co 80/06/19 9pp
- 8006240307 Order electing not to review ALAB-590 upon Commission initiative JF Abserva dissents & would summarily reverse decision CHILK.8 J Office of the Secretary of the Commission 80/06/20 is
- 8006240341 Second set of interrogatories & requests for production of documents. Requests identification of documents supporting contentions & identity of persons consulted in preparing contentions Certificate of Svc encil HANCOCK, D. NEHMAN, J.R. Houston Lighting & Power Co. HANCOCK, D. Bater & Rotts. 80/06/20.
- 8006260211 Mamorandum & order denying as most D Marrack 800611 mption for protective order & rejecting applicant 800619 motion for Issuance of subpown Applicant may file such motion directed to D Marrack for taking 800708 deposition WOLFE.S J Atomic Sefety and Licensing Board Panel, 80/06/23 3pp
- 8006270327 Response to intervenor TX PIRQ minth set of interrogatories Includes info re future analysis of RCPB piping per ABME code & Ebasco & GE calculations Affidavit & Certificate of Svc enc!
 COPELAND, J Q . NEWMAN. J R Houston Lighting & Power Co COPELAND, J Q . Baker & Botts . 80706723 7pp

whop Interrogatories is, n of documents. still subj to

Power Co

- 8006300317 Response to B Baker second set of interrogatories & requests for production of documents re applicant financial qualifications Identifies H Dean as anticipated witness due to familiarity wifinancial integrity W/Certificate of Svc COPELAND. J C NEMMAN. J R Houston Lighting & Power Co COPELAND. J G Baker & Botts 80/06/24 5pp
- 8006300323 Response to JF Doherty eightsenth request for production of documents NEDO-31551, NEDO-24154, Vols 1 & 2.PSAR Figure 7 7-2, NEDO-21175-P-1 & NEDO-21175-P-2 are available for intp & copying Certificate of Svc encl BIDDLE, C T , NEWMAN, J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts B0/06/24 4pp
- 8006300334 Response in opposition to intervenor Marrack June 1980 motion to compel answers to interrogatories Interrogatories were not received until date of motion Interrogatories untimely per ASLB 791119 order Certificate of Svc encl CULP.R H . COPELAND.J G Houston Lighting & Power Co CULP.R H Lowenstein, Newman, Reis, Axelrad & Toll 80/06/24 App
- 8006300340 Motion to compel FH Potthoff to answer first set of interrogatories & requests for production of documents reexpert witnesses Experts' dopositions must be taken within time left for termination of discovery M/Certificate of Svc BIDDLE.C T , NEWMAN.J R Houston Lighting & Power Co BIDDLE.C T Baker & Botts 80/06/24 4pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8006180086 Forwards ACRS 800506 ltr to Chairman Abserts re near-tire CP applications YCUN081.000,8 J Licensing Branch 1 80/05/28 3pp

BOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

O Adjudicatory correspondence

- BO06020150 Discusses implications of ALAB-570, requiring patitioners to intervene to state bases for each contention w/reasonable specificity Ruling shifts burden on applicant & NRC w/ respect to contentions

 LAZO,R M Atomic Safety and Licensing Board Panel 80/05/16 Rp;
- BOOA190101 FOIA request for 18 documents specifically identified by accession number, docket numbers & brief description to aid in facility proceeding DOHERTY, J.F. Doherty, J.F. 80/05/28 4pp
- BOO6190096 Responds to FOIA request for 18 documents identified by accession number, docket numbers & brief description to aid in facility proceeding Forwards documents listed in App A Documents 6 & 14 unavailable U/a encls FELTON, J M Division of Rules and Records 80/06/13 3pp
- DOCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 800&230110 Advises BUR & PUR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing 80/05/20 13pp
- 80062503B7 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt licensing matters w/respect to facility have been assigned to D Scaletti Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/13 12pp
- O Adjudicatory correspondence
- BOO609016B Responds to ABLB BOO327 order requesting date of planned testimony re emergency planning issue Written testimony will be filed within 4-6 wks from receipt of NRC evaluation Related correspondence WRIGHT.F B Massachusetts, State of 80/05/02 2pp
- 8006110038 Notice of withdrawal from proceeding effective 800602 Certificate of Svc ent! LEWIS.S H Hearing Branch 2 80/06/03 3pp

DOCKETED ITEMS

H General correspondence

ŧ.

- 8006160065 Request mod of first page of distribution list Distribution list encl list encl HICKEY.W F Boston Edison Co 80/06/09 2pp
- O Advisory Committee on Reactor Bafoguards reports & correspondence
- BOO6200530 Forwards ACRS 1tr re near-term CP applications SCHWENCER.A Licensing Branch 3 BO/05/30 4pp
- --8006200536 Discusses ACRS 800501-03 meeting re review of near-term CPs
 Urges that NRC resources be made available for resolution
 of action plan items & policy questions
 PLESSETIR'S ACRS Advisory Committee on Reactor Bafeguards
 80/05/06 2pp
- Q Inspection reports, IE Bulletins & correspondence
- BOO6190332 Requests provision of personnel for field survey re plant breakwater review Low tide on BOO610 will allow insp of toe of structure Site visit necessary to recommend final approval of design 2 placement BIVINS.W S Hydrologic 2 Geotechnical Engineering Branch 80/05/28 200

DUCKET STN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- BOOA230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREO-0577 re adequary of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT, D G Division of Licensing BO/05/20 13pp
- BOO6250196 Reports that ASME Code Case N-71-9 re add1 matis for component supports fabricated by welding is conditionally approved for general use YOUNGBLOOD.8 J Licensing Branch i 80/06/13 ip
- F Security, medical, emergency & fire protection plans
- 8006190325 Discusses review of util 800827 ltr responding to questions re GA programs for fire protection Requests that util & CP holders be informed that responses are acceptable MAA85.W P Quality Assurance Branch 80706705 ip
- 8006230384 Confirms intention to submit security training & qualification plan by 810101 KOESTER.O L Kansas Gas & Electric Co 80/06/18 2pp
- G Adjudicatory correspondence
- 8006060239 Notice of withdrawal from proceeding.effective 800602 Certificate of Svc encl LEWIS.8 H Hearing Branch 2 80/06/05 3pp
- M Antitrust correspondence
- 8006230042 Ack receipt of 800506 ltr submitting antitrust info,per Reg Guide 9 3 MESSIER.M Utility Finance Branch G0/05/21 lp
- P Operating license stage documents & correspondence
- 8006200144 Forwards Const Technology Labs "WR Waugh Basemat Concrete
 Testing Program," supporting util contention that basemat
 concrete is uniform & of high quality w/actual in situ
 strength exceeding 5,000 psi
 KOESTER,O L. Kansas Gas & Electric Co 79/10/26 2pp
- --BOO6200147 "WR Waugh Basemat Concrete Testing Program "
 SHIDELER, J J , CAMPBELL, D H Construction Technology Laboratories
 (div of Portland Cement Assoc) 79/09/24 45pp
- Q Inspection reports. IE Bulletins & correspondence
- BOO6S00047 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Ohsite Supply " No written response required SEVFRITIK V Region 4, Dalias, Office of the Director 80/04/01

- 8006050523 Forwards IE Insp Rept 90-492/80-05 on 800317-20 & notice of violation SEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/04/11 2pp
- ---8006030525 Notice of violation from insp on 800317-20 * Region 4, Dallas, Office of the Director 80/04/08 2pp
- ---8006050528 IE Insp Rept 50-462/80-05 on 800317-20 Noncompliance noted failure to provide prompt & adequate corrective action CROSSIAN.W A. MARTIN.L E. OBERG.C R Region 4, Dallas. Office of the Director 80/04/08 Apr
- 8006060128 Forwards IE Insp Rept 50~482/80-07 on 800331~0403 No noncompliance noted SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/16 2pp
- --8004040131 IE Insp Rept 50-482/80-0/ on 800331-0403 No noncompliance noted Major areas inspected const deficiency Tepts, allegation re welding & const activity CROSSHAN, W A. CUERG, C R. Region 4, Dallas, Office of the Director 80/04/15 Spp
- 8006120356 Advises that IE Insp Rept 50-482/B0-06 does not contain proprietary info Forwarding 1tr 5 rept may be placed in PDR KOESTER.G L. Kansas Gas & Electric Co. 90/04/24 ip
- 8004040330 forwards IE Bulletin 80-12, "Decay Heat Removal 8ys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i Uhile in Refueling Mode" encl SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/05/09 10
- 8006300064 Forwards IE Circular 80-12, "Valve-Shaft-To-Actuator Key May Fall Out of Place When Mounted Below Herizontal Axis " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director. 80/05/14 io
- 8006090183 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-482/80-05 SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/05/22 1p
- --8006090188 Responds to NRC 800411 ltr re violations noted in IE Insp Rept 90-482/80-05 Corrective actions storage bldg has been stiffened seams caulked & drainage around bldg improved KOESTER, 9 L Kansas Gas & Electric Co 80/05/09 3pg
- 8006130171 Forwards IE Investigation Rept 50-482/80-10 on 800429-30 No nancompliance noted SEYFRIT, K V Region 4. Dallas, Office of the Director 80/05/29
- --8005/30178 IE Investigation Rept 50-482/80-10 on 800329-30 No noncompliance noted Major areas inspected allegations that supervisory & labor personnel involved in narcotics use at site
 HERR, B. K. DRISKILL, D. D. SEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/05/27 4pp
- 8006120312 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Tank damage due to vacuum conditions precluded by design provisions or suitable vent connections PETRICK,N A Standardized Nuclear Unit Power Plant System 800/06/06 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006180525 Potential deficiency rept re Rockbestos cable jacket extrusion defects Jacket defects do not affect environ qualification or ability of cable to perform intended function Defect does not constitute reportable deficiency KOESTER.G L Kanwas Gas & Electric Co 80/05/08 ip
- 8006250012 Deficiency rept re cracks in refueling pool floor adjacent to reactor cavity Ack failure to submit timely rept to NRC Cracks are being evaluated by Bechtel Problem does not appear to constitute reportable deficiency MOESTER, O. L. Kansas Gas & Electric Co. 80/05/14 2pp
- 8006250018 Forwards Bechtel 800508 suppl to final deficiency rept re Ruskin Mfg Co vertical fire dampers Mod proposed in 800215 final rept is unacceptable since Number 6 screws could become loose Ruskin has developed successful design mod PETRICK, N A Standardized Nuclear Unit Power Plant System 80/05/16 8pp

- 8005300461 Part 21 rept re pipe support sway struts w/loose bushings During seismic event.piping could be overstressed Struts have been reworked to correct defictiency MEYERS.B L Bachtel Corp 80/05/19 Spp
- 8006250374 Ack receipt of 800516 final deficiency mapt re Ruskin Mfg Co fire dampers CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch BO/06/02 1P
- BOO6120311 Interim deficiency rept re centrifugal charging pump operation following secondary side line rupture discussed in BO0508 belion Evaluation of transient described in Westinghouse BO0508 ltr will be provided pending completion PETRICK, N A Standardized Nuclear Unit Power Plant System BO/06/06 2pp
- 8006240200 Follows up 800508 notification of potential deficiency re linear indications in pipe spaol in essential svc water discharge line Evaluation determined matter not reportable XDESTER.Q L Kansas Qas & Electric Co
- 8006240204 Follows up 800508 notification of potential deficiency recolor coding of wires in asfety-related switchgear supplied by OE Evaluation determined matter not reportable KOESTER, O L Kansas Gas & Electric Ca 80/06/06 ip
- 8006250403 Ack receipt of 800506 final deficiency rapt re Bunker Ramo Corp electrical penetration assemblies CARLSON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/06 IP
- BOO6170492 Supplemental deficiency rept advising NRC that addl insp found penetration wire terminations w/insulation extending into terminal lug barrel & incorrectly sized lugs on wire module Hold on addl fabrication at Bunker Ramo established SEIKEN.S J Standardized Nuclear Unit Power Plant System 80/06. 80/06/12
- 8006170612 Supplements 800506 interim deficiency rept re quality & integrity of penetration wire terminations Addl terminations found w/insulation extending into or through terminal lug barrel Assessment of Bunter Ramp OA L mgt underway SEIKEN S J Standardized Nuclear Unit Power Plant System 80/06/12

DOCKET STN-50-483 CALLOHAY PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8006170260 Summerizes questions transmitted to Bechtel as result of 800410 meeting re util embed rept SCHNELL,D F Union Electric Co 80/04/24 3pp
- BOO6230110 Advises BUR & PUR applicants of NRC decision to modify implementation plan presented in Bettom 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENMUT.D Q Division of Licensing 80/05/20 13pp.
- BOO6090501 Confirms BO0519 discussion re BO0529 masting in Olen Ellyn, It to discuss resolution of embedded plate matter at site KEPPLER,J G Region 3, Chicago, Office of the Director BO/05/22
- 8006300314 Forwards reorganization thart for Ofc of Nuclear Reactor Regulation Facility licensing matters will be handled by R Start Transition being made w/min of disruption to ongoing TEDESCO.R L. Assistant Director for Licensing 60/06/12 2pp
- 8006230176 Reports that ASME Code Case N-71-9 re add1 mat1s for component supports fabricated by welding is conditionally approved for general use YOUNGHLOOD, B J Licensing Branch 1 80/06/13 1p
- F Security, medical, emergency & fire protection plans
- 8006190325 Discusses review of util 800527 ltr responding to questions re 9A programs for fire protection Requests that util & CP holders be informed that responses are acceptable MAASS. W.P. Quality Assurance Branch 80/06/05 ip

H General correspondence

- 8006020451 Responds to 800324 request for info re application to facility of NRC revisions in plant design 5 safety stds resulting from TMI-2 accident Revisions published in encl NUREOs 0578 & 0585 W/o encis YQUNQBLOOD, B J Licensing Branch 1 80/05/22 2pp
- 8006110240 Submits info re recent functional changes in util organizational structure BRYAN, J K Union Electric Co 80/06/04 ip
- G Inspection reports, IE Bulletins & correspondence
- 8006050506 Forwards IE Insp Rept 50-483/80-01 on 800107-09 No noncompliance notes of the property of the sector construction & Engineering Support Branch 80/04/23 2pp
- --8006050511 IE Insp Rept 50-483/80-01 on 800107-09 No noncompliance noted Major areas inspected GA program relating to control of design & procurement audit program & document control KNOP.R C , NESCOTT.H M , HANSEN.W Region 3: Chicago, Office of the Director 80/04/17 9pp
- 8006170196 Forwards IE Insp Rept 50-483/80-07 on 800311-14 & notice Violation
 ORELLIG Region 3. Chicago, Reactor Construction & Engineering
 Opport Branch 60/04/26 2pp of violation FIORELLI, G Support Branch
- --8006170197 Notice of violation from insp on 800311-14 * Region 3. Chicago, Office of the Director 80/0 E0/04/25 1p
- --B006170201 IE Insp Rept 50-483/80-07 on B00311-14 Noncompliance noted failure to establish procedure to control welding MESCOTT.H M , KNOP,R C Region 3, Chicago, Office of the Director B0/04/25 6pp
- 8006180410 Forwards IE Insp Rept 80~483/80-11 on 800329-27 No noncompliance noted FIURELLIG Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/04/29 Zpp
- ---8006180414 IE Insp Rept 50-483/80-11 on B00325-27 No noncompliance
 noted Major areas inspected safety-related structural
 concrete & soils work
 LANDSMAN.R B Region 3. Chicago, Office of the Director
 HAYES,D W Region 3. Chicago, Reactor Construction & Engineering
 Support Branch 80/04/25 4pp
- 8006170187 Forwards corrected copy of NRC 800426 ltr.transmitting IE Insp Rept 50-483/80-07 FIQRELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/02 ip
- --8006170195 Corrected copy of 800426 ltr forwarding IE Insp Rept 50-483/80-07 & notice of violation W/o encis FIDRELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/02 2pp
- 8006300067 Forwards IE Insp Rept 50-483/80-09 on 800423-24 & notice of violation
 FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/05/14 2pp
- --8004300070 Notice of violation from insp on 800423-24 # Region 3, Chicago, Office of the Director 80/0 80/05/19 in
- --8006300073 IE Insp Rept 50-483/80-07 on 800423-24 Noncompliance noted failure to implement design instructions shown in design drawings & inadequate insp program to provide timely verification of work per design requirements DANIELSON.D H. Region 3, Chicago. Reactor Construction & Engineering Support Branch YIN.I T. Region 3, Chicago. Office of the Director 80/05/12 6pp
- 8006:20312 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks Tank damage due to vacuum conditions precluded by design provisions or suitable vent connections
 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/06 2pp
- 8006230063 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-07 FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 ip

- --8006230069 Responds to NRC 800426 ltr re violations nated in IE Insp Rept 50-483/80-07 Corrective actions arranging meeting w/Bechtel & P-W Industries to resolve questions re welding procedures used for cable tray fittings BRYAN.J K Union Electric Co 80/05/28 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006250018 Forwards Bechtel 800308 suppl to final deficiency rept re Ruskin Mfg Co vertical fire dampers Mod proposed in 800215 final rept is unacceptable since Number & screws could become loose Ruskin has developed successful design mod PETRICK:N A Standardized Nuclear Unit Power Plant System 80/05/16 809
- 8004030001 Ack receipt of 800513 interim deficiency rept re improper preheat of heavy structural members prior to welding NRC will review final rept upon receipt FIORELLI-Q Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/22 1p
- 8006250394 Ack receipt of 800516 final deficiency rept re Ruskin Mfg Co fire dampers CARL80N.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/02 IP
- 8006120311 Interim deficiency rept re centrifugal charging pump operation following secondary side line rupture discussed in 800508 telcon Evaluation of transient described in Hastinghouse 800508 ltr will be provided pending completion PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 80/06/06 2pp
- 8006230403 Ack receipt of 800306 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies CARLBUNK T Region 1. Philadelphia: Reactor Construction & Engineering Support Branch 80/06/06 1P
- 8006170492 Supplemental deficiency rept advising NRC that addl insp found penetration wire terminations w/insulation extending into terminal lug barrel & incorrectly sized lugs on wire module Hold on addl fabrication at Bunker Ramo established SEIKEN.S J Standardized Nuclear Unit Power Plant System 80/06/12
- BOOA170612 Supplements 800506 interim deficiency rept re quality & integrity of penetration wire terminations. Additerminations found w/insulation extending into or through terminal lugbarrel Assessment of Sunter Ramo GA & mgt underway SEIKEN. B J Standardized Nuclear Unit Power Plant System. BO/06/12
- 8006240441 Interim deficiency rept re surface mounted plates Reinspection of surface mounted plates underway Final rept will be issued on 800708 BRYAN, J K Union Electric Co 80/06/16 ip
- U Congressional/Executive Correspondence
- 9006120520 Expresses concern over delays in NRC reviews of pending OL applications for facilities Failure to carry out reviews in timely manner is unacceptable Schedule for reviews should be developed \$\psi\$ implemented EAOLETON, T F , DANFORTH, J C , DDLE, R Senate, Covernmental Affairs, 80/05/16 4pp
- DOCKET BTN-50-405 STERLING POWER PROJECT NUCLEAR, UNIT 1

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing BO/05/20 13pp
- 8006180597 Comments on 800506 presentation to NRC Commissioners re status of SEP & description of difficulty as lack of aggression by licensees NRC has not provided guidelines Issues w/higher priorities have anisen WHITE.L D Rochester Gas & Electric Corp 80/06/12 3pp

- O Adjudicatory correspondence
- 8006110397 Requests confirmation of util decision re licensing of proposed facility Ltr prompted by 800331 ltr to editor in Times-Union newspaper in which JE Houston claimed project was cancelled TOMPKINS, B. A. Atomic Safety and Licensing Appeal Panel 80/05/06
- 8006060245 Request for extension until 800618 for parties, except NRC, to submit post-hearing memoranda re radon issue Record lengthy & intervenors have other commitments made prior to Feb 1980 Certificate of Suc encl
 KEPFORD, C Citizens for Safe Environment 80/05/20 4pp
- 8006060242 Correction to licensees' 800428 brief on disposition of alleged Deficiency 1 Certificate of Bvc encl BILBERG, J E Metropolitan Edison Co 80/05/20 5pp.
- 8006050547 Response to intervenors. York Committee for Safe Environ & Citizens for Safe Environ request for extension until 800518 to file proposed findings of fact in generic radon proceeding Many delays in proceeding are cause for concern CONNER. T B Philadelphia Electric Co 80/05/23 11pp
- B006020590 Order granting extension until 800618 for York Committee for Safe Environ & Citizens for Safe Environ to file proposed findings of fact & conclusions of law NRC findings due on 800703 & intervenors & applicants' responses on 800718.
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/05/28 2pp
- 8006060527 Order, CL1-80-23, affirming ABLAB decision, ALAB-502 Separate views of Commissioners Kennady & Hendrie, separate views of Commissioner Gilinsky & dissenting views of Chairman Ahearne encl
 CHILK.8 J Office of the Secretary of the Commission 80/05/27
- 8006110172 Advises that no clear basis exists for termination of proceeding due to Unconfirmed rapts of cancellation of project Applicant must plainly set forth intentions REIS.E.J. Hearing Branch 3 80/06/06 2pp
- 8006230377 Memorandum & order vacating for moothess ABLB 1977 initial decision which authorized issuance of CP Proceeding terminated, Director of Nuclear Reactor Regulation instructed to revoke outstanding CP BISHOP, C J Atomic Safety and Licensing Appeal Panel B0/06/17 5pp
- 8006260207 Memorandum & order advising that Sterling issue is no longer germane to consolidated proceedings where radon issue is being determined Ecology Action cause for late intervention must be filed by 800702
 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/23
 3pg
- G Inspection reports. IE Bulletins & correspondence
- 8006200032 Forwards IE Circular 80-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies " No written response required. ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/28 1p
- 8006120312 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol control sys holdup tanks. Tank damage due to vacuum conditions precluded by design provisions or suitable vent connections PETRICK, N A Blandardized Nuclear Unit Power Plant Bystem 80/04/06 2pp
- S Reportable occurrences, LERs & related correspondence
- 8005120311 Interim deficiency rept re centrifugal charging pump operation following secondary side line rupture discussed in 800508 telcon Evaluation of transient described in Hestinghouse 800508 itr will be provided pending completion PETRICK.N A. Standardized Nuclear Unit Power Plant System 80/05/06 2pp
- DOCKET BIN-50-486 CALLOWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8004030204 Requests Commission notification of any acceleration in facility const schedule CHILK-8 J. Office of the Secretary of the Commission 80/04/17 ip.

- 8006170260 Summerizes questions transmitted to Bechtel as result of 800410 meeting re-util embed rapt BCHNELL,D F Union Electric Co 80/04/24 Spp
- 8006230110 Advises BKR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures Coneral operating reactor review procedure & acceptance criteria encl EISENHUT, D Q Division of Licensing 80/05/20 13pp
- 8006300314 Forwards reorganization chart for Ofc of Nuclear Reactor Regulation Facility licensing matters will be handled by R Stark Transition being made w/min of disruption to engoing activities TEDESCO, R L Assistant Director for Licensing 80/06/12 2pp
- 8006250196 Reports that ASME Code Case N-71-9 re addit matls for component supports fabricated by welding is conditionally approved for general use YOUNOBLOOD.B J Licensing Branch 1 80/06/13 ip
- F Security, medical, emergency & fire protection plans
- 8006190325 Discusses review of util 800527 ltr responding to questions re GA programs for fire protection Requests that util & CP holders be informed that responses are acceptable HAASS.H P Quality Assurance Branch 80/06/03 ip
- H General correspondence
- 8006020451 Responds to 800324 request for info re application to facility of NRC revisions in plant design & safety stds resulting from THI-2 accident Revisions published in encl NREGO 879 & 0589 H/o encls YOUNOBLOOD, B J Licensing Branch 1 80/05/22 2pp
- 600Ail0240 Submits info we recent functional changes in util organizational structure BRYAN.J K Union Electric Go 80/06/04 ip
- Q Inspection reports: IE Dulletins & correspondence
- 8004120312 Responds to IE Bulletin 80-05 re varuum condition resulting in damege to chemical volt control sys holdup tents Tank damege due to vacuum conditions precluded by design provisions or suitable vant connections PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 80/06/06 2pp
- S Reportable occurrences, LERs & related correspondence
- 800525;0018 Forwards Bachtel 800508 suppl to final deficiency rept re Ruskin Mg Co vertical fire dampers Mod proposed in 800215 final rept is unacceptable since Number 6 screws could become loose Ruskin has developed successful design and PETRICK.N A Standardized Nuclear Unit Power Plant System 80705716 Spp
- 8006250394 Ack rereipt of 800916 final deficiency rept re Rustin Mfg Co fire dampers CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/02 1P
- 8006120311 Interim deficiency rept re tentrifugal cherging pump operation following secondary side line rupture discussed in 800508 belion Evaluation of transient described in Hestinghouse 800508 ltr will be provided pending completion PETRICK, N A Standardized Nuclear Unit Power Plant System 80706706 2pp
- 8006230403 Ack receipt of 800506 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80706706 iP
- 8006170492 Supplemental deficiency rept advising NRC that add1 insp found penetration wire terminations w/insulation extending into terminal lug barrel 2 incorrectly sized lugs on wire module Hold on add1 fabrication at Bunker Ramo established SEIKEN.S J Standardized Nuclear Unit Power Plant System 80/06/12 200
- 8006170612 Supplements 800506 interim deficiency rept re quality & integrity of penetration wire terminations. Add1 terminations found w/insulation extending into or through terminal lugbarrel Assessment of Bunker Ramo QA & mgt underway SEIKEN.8 J. Standardized Nuclear Unit Power Plant System 80/06/12

- 8006240441 Interim deficiency rept re surface mounted plates Reinspection of surface mounted plates underway Final rept will be issued on 800908 BRYAN.J K Union Electric Ca 80/06/16 1p
- U Congressional/Executive Correspondence
- 8006120520 Expresses concern over delays in NRC reviews of pending OL applications for facilities Failure to carry out reviews in timely manner is unacceptable Schedule for reviews should be developed & implemented EAOLETON, T.F., DANFORTH, J.C., DOLE, R. Senate, Governmental Affairs 80705716 4pp
- DUCKET STN-50-468 PERKINS NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC derision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support attructures General operating reactor review procedure & acceptance criteria enci EISENHUT, D Q Division of Licensing 80/09/20 13pp
- 8006250149 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to C Moon Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/12 tipp
- Q Adjudicatory correspondence
- 8006090014 Response in support of D Epringer petition to intervene Add1 info may be helpful in reaching proper decision Certificate of Box & supporting documentation enc!

 PFEFFERKORNIN Pfefferborn & Cooley, P A 80/05/09 4pp
- 8006120024 Response in apposition to D Springer 800415 petition to intervene Intervenor advanced grounds that have been previously rejected in 1976-77 petitions Petition untimely & unsupported by facts Certificate of Svc encl MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 80707709 dpp
- BOO6170237 Ack receipt of NRC 800905 response to BOO415 petition & ASLB BOO507 memorandum & order Urges that request for 60-day attension be considered Criticizes NRC bureaucratic attitude
 SPRINGER, D Affiliation Unknown 80/05/12 ip
- 8006190189 Affidavit in support of D Springer 800415 petition alleging that neither NRC or ASLB has fully considered potential for once-through cooling & tower cooling Supporting documentation. & Certificate of Byc encl
 SPRINGER. D Affiliation Unknown 80/05/21 15pp
- 8006200066 Forwards Pages 4.5 & 6 which were inadvertently omitted from Ethibit A of High Rock Lake Association 800521 affidavit
 SPRINCIR.D High Rock Lake Association 80/05/P3 ip
- --8006207071 Pages 4.5 & 5 for Exhibit A of High Rock Lake Association 800521 affidavit, SPRINCER.D High Rock Lake Association 78/11/16 4pp
- 8006020310 Order granting extension until 600612 for Commission to review ALAB-391
 CHILK 8 J Office of the Secretary of the Commission 80/03/29
- 8006060372 Order advising parties to file exceptions to ASLE 800222 partial initial decision. LBP-80-9 re alternate site issue, by 800623 Certificate of Svc encl 818HOP.C J Atomic Safety and Licensing Appeal Panel 80/05/30 500
- G006110342 Motion to reconsider ABLB 800222 decision or to reopen record due to reasons stated in D Springer affidavit Certificate of Byc encl PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/06/06 2pp
- 8006110297 Response in opposition to D Springer 800415 affidavit re 800415 petition requesting 60-day extension to file documents supporting allegations Adheres to 800509 position Certificate of 8vc encl MCOARRY. J M Duke Pawer Co MCGARRY. J M Debeyoise & Liberman 80706709, 4pp

- 8005180341 Motion for extension until 000825 or after to file exceptions to ASLB 800222 partial initial decision Awaited resolution of petition to reopen record based on D Springer affidavit may make appeal unnecessary M/Certificate of Scr PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/06/11 2pp
- 8006190642 Order declaring ASLB has jurisdiction to consider D Springer BOD415 petition to intervene Will not rule on merits until ABLAB decides jurisdiction question NRC must respond to petition t 800415 affidavit regardless of outcome BONERS.C S Atomic Safety and Licensing Board Panel 80/06/17
- 8006240143 Response in apposition to intervenors' 800611 motion for add1 time to file exceptions to ABLB 800222 partial initial decision re alternate site issue Motion is based on Springer affidavit which was opposed by util W/Certificate of Svc MCGARRY, J M Duke Power Co MCGARRY, J II Debevoise & Liberman 80/06/18 4pp
- 8006230248 Response in opposition to intervenors' B00611 motion for extension until B00825 to file exceptions to ASLB 790202 partial initial decision on site alternatives Certificate of Svc encl BARTH, C A Hearing Branch 3 80/06/19 8pp
- BO06240415 Memorandum & order, ALAB-597, extending time to file exceptions to ASLB BO0222 partial initial decision. LBP-80-07, until ASLB takes action on D Springer petition & intervenors' BO0606 motion & until ABLAB further order BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/06/20 10pp
- 8006290291 Response in apposition to intervenors' B00606 motion to reconsider or reopen record Applicant has already opposed D Springer petition & affidavit, on which intervenors' motion was based, as untimely & unsupported Certificate of Svc encl MCGARRY. J M. PORTER, W.L. Duke Power Co. 00/06/23 3pp
- 8006300496 Response in opposition to intervenors' 800606 motion to reconsider ASLB 800222 partial initial decision resite alternatives Motion untimely & reconsideration stds not mot Certificate of Svc encl
 BARTH.C A Mearing Branch 3 80/04/26 10pp
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8006090003 Forwards MS Plesset 800506 ltr to JF Ahearne re ncar-term CP applications
 YOUNGBLOOD, U Licensing Branch 1 80/05/28 2pp
- 8006070006 Discusses ACR8 review of near-term CPs Utils identified six policy Issues Interim position must be formulated to resolve issues PLFSERT,M 8 ACR9 - Advisory Committee on Reactor Safeguards 80709704 2pp
- Q Inspection reports, IE Bullstins & correspondence
- 9006060493 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IC Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- BOO4040355 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Resse Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07 200
- 8006300123 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube 01 Cooler Failures" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/05/13 200.
- 8006240228 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damaga to holdup tanks Lists vacuum conditions in low pressure & holdup tanks by tank name, sys, quantity/ unit. design pressure & protective measures
 DAIL, L C Duke Power Co 80/06/09 2pp

- DOCKET STN-50-489 PERKINS NUCLFAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PNR applicants of NRC decision to modify implementation plan presented in Section 4 of MUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/03/20 13pp
- 8006250149 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mot responsibilities re facility have been assigned to C Moon Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/12 11pp
- Q Adjudicatory correspondence
- 8004090014 Response in support of D Springer potition to intervene Addl info may be helpful in reaching proper decision Certificate of Svc & supporting documentation encl PFEFFERKORN, W Pfefferkorn & Cooley, P A 80/05/09 4pp
- 6006120024 Response in apposition to D Springer 600415 petition to intervene Intervenor advanced grounds that have been previously rejected in 1976-77 petitions Petition untimely & unsupported by facts Certificate of Svc encl MCGARRY. J M Duke Power Co MCGARRY. J M Debevoise & Liberman 80/05/09 6pp
- 8006170237 Ack receipt of NRC 800505 response to 800415 petition & ASLB 800507 memorandum & order Urges that request for 60-day attension be considered Criticires NRC bureaucratic attitude

 SPRINGER D Affiliation Unknown 80/05/12 1p
- 8006190189 Affidavit in support of D Egringer 800415 potition elleging that noither NRC or ASLB has fully considered potential for once-through coaling & tower cooling Supporting documentation & Certificate of Syc encl SPRINGER, D Affiliation Unknown 80/05/21 19pp
- 8006R00066 Forwards Pages 4.5 % 6 which were inadvertently emitted from Fhibit A of High Rock Lake Association 800521 affidavit SPRINGER.D High Rock Lake Association 80/05/23 ip
- ---G006200071 Pages 4,8 & 6 for Exhibit A of High Rock Lake Association 900521 affidavit GPRINGER,D High Rock Lake Association 78/11/16 App
- 8006020310 Order granting extension until 800612 for Commission to review ALAB-591
 CHILK, S. J. Office of the Secretary of the Commission 80/05/29
- 8006060572 Order advising parties to file exceptions to ASLR 800222 partial initial decision, LBP-80-9, re-alternate site issue, by 800623 Cortificate of Syc encl BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/05/30 Spp
- BOO6110342 Motion to reconsider ASLB 800222 decision or to reopen record due to reasons stated in D Springer affidavit Certificate of Syc and Preferkorn & Couley, P A 80/06/06 2pp
- 8006110297 Response in opposition to D Springer B00415 affidavit re B00415 petition requesting 60-day extension to file documents supporting allogations Adheres to B00509 position Certificate of Svc ancl MCGARRY, J M Buke Power Co MCGARRY, J M Debayoise & Liberman 80/06/09 4pp
- 8006180341 Motion for extension until 800825 or after to file exceptions to ASLB 800222 partial initial decision Awaited resolution of petition to reopen record based on D Springer affiliavit may make appeal unnecessary W/Certificate of Svc PFEFFERKORN,W Pfefferkorn & Cooley, P A 80/06/11 2pp
- 8006190642 Order declaring ASLB has jurisdiction to consider D Springer 800415 petition to intervene Will not rule on merits until ASLAB decides jurisdiction question NRC must respond to petition & 800415 affidavit regardless of outcome.

 BOWERS.E S Atomic Safety and Licensing Board Panel 80/06/17

- 8006240143 Response in opposition to intervenors' 800611 motion for add1 time to file exceptions to ASLB 800222 partial initial decision re alternate site issue Hotion is based on Springer affidavit which was opposed by util H/Certificate of Svc MCOARRY, J M Dabevoise & Liberman 80/06/18 4pp
- 800623024B Response in opposition to intervenors' 800611 motion for extension until 800825 to file exceptions to ASLB 790202 partial initial decision on site alternatives Certificate of Svc encl
 BARTH.C A Hearing Branch 3 80/06/19 Spp
- 8006240415 Memorandum & order.ALAB-597, extending time to file exceptions to ASLB 600222 partial initial decision. LBP-80-09, until ASLB takes action on D Springer petition & intervenors' 800606 motion & until ASLAB further order BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/06/20
- 8006280251 Response in opposition to intervenors' 800606 motion to reconsider or reopen record Applicant has already opposed D Byringer petition & affidavit, on which intervenors' motion was based, as untimely & unsupported Certificate of Bvc encl MCGARRY.J M., PORTER.H L Duke Power Co 80/06/23 3pp
- 800A300496 Response in opposition to intervenors' 800A0A motion to reconsider ABLB 800222 partial initial decision re-site alternatives Motion untimely & reconsideration stds not met Certificate of Svc encl BARTH.C A Hearing Branch 3 80/06/26 10pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B006070003 Forwards MS Plesset 800506 itr to JF Ahearne re near-term CP applications YOUN0BLOOD, B J Licensing Branch 1 80/05/28 2pp
- --800A09000A Discusses ACRS review of hear-term CPs Utils identified six policy issues Interim position must be formulated to resolve issues PLESSET.M S ACRS -- Advisory Committee on Reactor Bafeguards 80/08/04 200
- G Inspection reports, IE Bulletins & correspondence
- 8006060493 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 2pp
- 8006040355 Forwards IE Bulletin 80-12. "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20. "Loss of Dacay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" encl D
- 8006300123 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J. P Region 2, Atlanta, Office of the Director 80/05/13 200
- 8006240228 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Lists vacuum conditions in low pressure & holdup tanks by tank name.sys.quantity/unit design pressure & protective measures DAIL.L C Buke Power Co 80/06/09 2pp

DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT, D O Division of Licensing 80/05/20 13pp
- 8006250149 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to C Moon Reorganization charts and TEDEBCO,R L Assistant Diractor for Licensing 80/06/12 11pp

Q Adjudicatory correspondence

- 8006090014 Response in support of D Springer patition to intervene Addl info may be helpful in reaching proper decision Certificate of Svc & supporting documentation encl PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/05/09 4pp
- 8006120024 Response in opposition to D Springer 800415 petition to intervene Intervenor advanced grounds that have been previously rejected in 1776-77 petitions Petition untimely & unsupported by facts Certificate of Svc encl MCOARRY, J M Duke Power Co MCOARRY, J M Debevoise & Liberman 80/05/09 dpp
- 8006170237 Ack receipt of NRC 800505 response to 800415 patition & ASLB 800507 memorandum & order Urges that request for 60-6ay extension be considered Criticizes NRC bureaucratic attitude
 SPRINGER.D. Affiliation Unknown 80/05/12 1a
- 8006190189 Affidavit in support of D Springer 800415 petition alleging that neither NRC or ASLB has fully considered potential for once-through cooling & tower cooling Supporting documentation & Certificate of Svc enci
- B006200066 Forwards Pages 4.5 & 6 which were inadvertently omitted from Exhibit A of High Rock Lake Association 800521 affidavit SPRINGER.D High Rock Lake Association 80/05/23 ip
- B006020310 Order granting extension until 800612 for Commission to review ALAB-591 CHILK.S J Office of the Secretary of the Commission 80/05/29
- BOO6060572 Order advising parties to file exceptions to ASLB S00222 partial initial decision, LBD-80-9. The alternate site issue. by 800622 Certificate of Svc encl BISHOP, C J Atomic Bafety and Licensing Appeal Panel 80/05/30 for
- 8006110342 Motion to reconsider ASLB 800222 decision or to reopen record due to reasons stated in D Springer affidavit Centificate of Bvc snc1 | PFEFFERNORN.W Pfefferkorn & Cooley, P A 80/06/06 2pp
- 8006110297 Response in opposition to D Springer 800415 affidavit re 800415 petition requesting 60-day extension to file documents supporting allegations Adheres to 800307 position Certificate of Svc encl MCGARRY, J M Debevoise & Liberman 80/06/09 4pp
- 8006180341 Motion for extension until 800825 or after to file exceptions to ASLD 800222 partial initial decision Awaited resolution of petition to reopen record based on D Springer affidavit may make appeal unnecessary W/Certificate of Svc PFEFFERKORN.W Pfefferkorn & Cooley, P A 80/06/11 2pp
- 8006190642 Order declaring ABLB has jurisdiction to consider D Springer B00415 petition to intervene Will not rule on merits until ABLBB decides jurisdiction question NRC must respond to petition & 800415 affidavit regardless of outcome B0WERS, E B Atomic Safety and Licensing Board Panel 80/06/17
- 8005240143 Response in opposition to intervenors' 800511 motion for add1 time to file exceptions to ASLB 800222 partial initial decision re alternate site issue Motion is based on Springer affidavit which was opposed by util W/Certificate of Svc MCGARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman 80/06/18 4pp
- 800623024B Response in opposition to intervenors' 80061i motion for extension until 800825 to file exceptions to ASLB 790202 partial initial decision on site alternatives Certificate of 8vc encl
 BARTH, C A Hearing Branch 3 80/06/19 8pp
- 8006240415 Memorandum & order, ALAB-597, extending time to file exceptions to ABLB 800222 partial initial decision, LBP-80-09, whill ABLB takes action on D Springer petition & intervenors' 800606 motion & until ABLAB further order BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/06/20 100e

- 8006250251 Response in opposition to intervenors' 800606 motion to reconsider or reopen record Applicant has already opposed D Springer petition & affidavition which intervenors' motion was based as untimely & unsupported Certificate of Svc enci MCGARRY. J M . FORTER, W L. Duke Power Co 80/06/23 3pp
- 8006300496 Response in apposition to intervenors' 800606 motion to reconsider ASLB 800222 partial initial decision re-site alternatives Motion untimely & reconsideration stds not met Certificate of Svc encl BARTH, C A Hearing Branch 3 80/06/26 10pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8006090003 Forwards MS Plesset 800506 ltr to JF Ahearne re near-term CP applications YOUNDBLOOD, B J Licensing Branch 1 80/05/28 2pp
- --8006090006 Discusses ACRS review of near-term CPs Utils identified six policy issues Interim position must be formulated to resolve issues PLESSET, M S ACRS Advisory Committee on Reactor Safeguards 80/05/06 2pp
- Q Inspection reports, IE Bulletins & correspondence
- B006060493 Forwards IE Bulletin 80-ii, "Masonry Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006040355 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" and O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07 20p
- 8006300123 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 20p
- 8006240228 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Lists vacuum conditions in low pressure & holdup tanks by tank name, sys, quantity/ unit, design pressure & protective measures
 DAILL C Duke Power Co 80/06/09 2pp
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREQ-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp
- 8006300306 Forwards reorganization chart for Ofc of Nuclear Reactor Regulation Facility licensing matters will be handled by C Moon Transition being made w/min of disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing 80/06/12 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006060493 Forwards IE Bulletin 80-11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" anci O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08.
- 8006070142 Ack receipt of IE Insp Repts 50-491/80-05,50-492/80-05 & 50-493/80-05 No proprietary info DAIL.L C Duke Power Co 80/05/08 ip
- --8004070144 Forwards IE Insp Repts 50-491/80-05,50-492/80-05 & 50-493/80-05 on 800415-17 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/04/29 2pp
- --8006090147 Natice of violation from insp on 800415-17
 * Region 2. Atlanta. Office of the Director 80/04/29 1

- --8006090156 IE Insp Repts 50-491/80-05,50-492/80-05 & 50-493/80-05 on 800415-17 Noncompliance noted survey loop closure data & settlement monitoring on Unit 1 & auxiliary bldg not documented & performed as required CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch HARRISJ R Region 2, Atlanta, Office of the Director 80/04/29 4pp
- 8006040355 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Dperability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Bosse Unit I While in Refueling Mode" encl O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/09 260
- 8006300123 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 20a
- 8006240228 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Lists vacuum conditions in low pressure & holdup tanks by tank name, sys, quantity/ unit.design pressure & protective measures
 DAIL.L C Duke Power Co 80/06/09 2pp
- S Reportable occurrences. LERs & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J. L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- DOCKET STN-50-492 CHERCKEE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- 8006300306 Forwards reorganization chart for Off of Nuclear Reactor Regulation Facility licensing matters will be handled by C Moon Transition being made w/min of disruption to ongoing activities
 TEDESCO,R L. Assistant Director for Licensing 80/06/12, 2pp.
- Q Inspection reports, IE Bulletins & correspondence
- B006060493 Forwards IE Bulletin B0-ii. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" and Office of the Director B0/05/08
- 8006090142 Ack receipt of IE Insp Repts 50-491/80-05,50-492/80-05 & 50-493/80-05 No proprietary info DAIL, L C Duke Power Ca 80/05/08 ip
- --8006070144 Forwards IE Insp Repts 50-491/80-05,50-492/80-05 & 50-493/80-05 on 800415-17 & notice of violation MURPHY.C.E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/29 2pp
- --8006070147 Notice of violation from insp on 800415-17

 # Region 2, Atlanta, Office of the Director 80/04/27 ip
- ---B006070156 IE Insp Repts S0-491/B0-05.50-492/B0-05 & 50-493/B0-05 on B00415-17 Noncompliance noted survey loop closure data & settlement monitoring on Unit 1 & auxiliary bldg not dacumented & performed as required CONLON, T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARRIEJ R Region 2. Atlanta, Office of the Director B0/04/29 4pp
- 8006040355 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys
 Operability " No written response required IE Info Notice
 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse
 Unit I While in Refueling Mode" encl
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09

- 8006300123 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failutes" No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/05/13 2ac
- 8006240228 Forwards vesponse to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Lists vacuum conditions in low pressure & holdup tanks by tank name, sys, quantity/ unit-design pressure & protective measures
 DAIL.L. C. Duke Power Co. 80/06/09 2pp
- S Reportable occurrences, LERs & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A234MPB requirement Investigations conducted & closed at
 46 listed facilities
 SEAY.J L Chemtron Corp., Tube Turns DIV 80/06/06 3pp
- DOCKET STN-50-493 CHERCIKEE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan prosented in Section 4 of NVREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT. D G Division of Licensing 80/05/20 13pp
- 8006300306 Forwards reorganization chart for Dfc of Nuclear Reactor Regulation Facility licensing matters will be handled by C Moon Transition being made w/min of disruption to ongoing activities TEDESCOR L Assistant Director for Licensina 80/06/12 200
- G Inspection reports, IE Bulletins & correspondence
- 8006060493 Forwards IE Bulletin 80-11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Bupport Loads" and O'REILLY, J P Region 2, Atlanta. Office of the Director 80/05/08
- B00A090142 Act receipt of IE Insp Repts 50-491/80-05.50-492/80-05 & 50-493/80-05 No proprietary info DAIL-L C Dake Power Co B0/05/08 ip
- --8006090144 Forwards IE Insp Repts 30-491/80-05,50-492/80-05 & 50-493/ 80-05 on 800415-17 & notice of violation MWRPHY,C E Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch 80/04/29 2pp
- --8006090147 Notice of violation from insp on 800415-17 * Region 2. Atlanta, Office of the Director 80/04/29 ip
- --8006070156 IE Insp Repts 50-491/80-05.50-492/80-05 & 50-493/80-05 on 800413-17 Noncompliance noted survey loop closure data & settlement monitoring on Unit 1 & auxiliary bldg not documented & performed as required CONLON.T.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARRIS.J R. Region 2. Atlanta, Office of the Director 80/04/29 App
- 8004040395 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/09 2pp
- 8006300123 Forwards 1E Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Feilures " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13
- 800A240228 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Lists vacuum conditions in low pressure 5 holdup tanks by tank names sys.quantity/unit.dasign pressure & protective measures
 DAIL-L C Duke Power Co '80/06/07 2pp

- 8 Reportable occurrences, LERs 3 related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234KPB requirement Investigations conducted & closed at 46 listed facilities SEAY, J. L. Chembion Corp., Tube Turns Div 80/06/06 3pp
- DUCKET 50-496 MONTAGUE NUCLEAR POWER STATION. UNIT 1

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Soction 4 of NUREG-05/7 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure to acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- BO04040259 Advises that CAM 79-37 will be withheld from public disclosure per 10CFR2 790 Document is part of package sent by util on 791120 representing detailed technical audit of fuel design
 SCHMENCER.A Operating Reactors Branch 2 80/05/22 3pp
- 8006130158 Notification of 800718 mesting w/util in Bethesda.MD re soil/structure interaction study Meeting orginally scheduled for 800626 SELLG.D Licensing Branch 2 80/06/02 1p
- 8006190688 Notification of 800626 meeting w/util in Bethesda.MD to discuss soil/structure interaction study SELLS.D Licensing Branch 2 80/06/02 3pp
- F. Security, medical, emergency & fire protection plans
- 8005130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 ltr Addl specific criteria for facilities under development EISENHUT.D 0 Division of Operating Reactors 80/04/25 61pp
- G Adjudicatory correspondence
- 8006120070 Confirms & notifies of agreement for DE Swayze 800619-21 deposition, subj to ASLB granting of motion for discovery extension Place will be determined at later time COMAN.F E Baker & Botts 80/04/28 Jpp
- 8006120278 Confirms & notifies parties of L Sinkin 800618 deposition Rescheduling necessitated by involvement in other hearing Buggests 800617 for Buchorn deposition Related correspondence COWAN.F E Baker & Botts 80/05/05
- 8006060478 Motion to compel Citizens for Equitable Utils to provide further answers to first set of interrogatories Intervenor 800423 answers incomplete & sometimes irrelevant & unresponsive Certificate of Svc encl COWAN,F E, NEWMAN,J R, Houston Lighting & Power Co. COWAN,F E Daker & Botte 80/05/08 iipp

1

- 8006200127 Ack 800506 telcon re agreement for P Buchorn 800617 deposition in San Antonio.TX Sinkin deposition will be taken on 800618 ⊅ Swayze on 800619-21 COMAN,F E Baker ⊅ Botts 80/05/08 3pp
- BOO6110267 Confirms final arrangements for P Buchern, L Sinkin & D Bwayra depositions P Puchoin & L Sinkin depositions scheduled BOO61/ / 18. respectively, in Ban Antonio, TX & D Bwayra deposition scheduled BOO619 in Bay City, TX COWAN, F E Baker & Botts BO'05/20 3pp
- 8006190595 Submits supportive evidence for 800527 request that NRC convene public hearing on 800430 show cause order re violations noted in NRC investigation interveners should be able to present evidence re contentions Name and SINKIN. L Citizens Concerned About Nuclear Power: Inc. SINKIN, L Citizens for Equitable Utilities 80/05/28 13pp
- B006030139 Advises that NRC has received Houston Lighting & Power 800원23 ltrs in response to [E 800530 ltr re-order to show cause, notice of violation & notice of proposed imposition of civil penalties MCGURREN, H 및 Hearing Branch I 80/05/30 ip
- 8006110340 Discusses possible solutions to matter raised by P Buchorn at 800529 meeting concerning application for OL Suggests that P Buchorn submit list of specific documents for oxamination or duplication COWAN.F E Baker & Botts 80/06/02 3pp
- 8006180506 Response in opposition to Citizens Concerned About Nuclear Fower & Citizens for Equitable Utils request for hearing re IE 800430 order to show cause Petitioners failed to establish right to hearing Certificate of Svc encl CULP.R H . COMAN.F Houston Lighting & Power Co CULP.R H Lowenstein, Newman, Reis, Axelrad & Toll 80/06/13 13pp
- 8006260196 Motion to deny Citizens Concerned About Nuclear Power & Citizens for Equitable Utils' 800527 request for hearing re IE 800420 order to show cause why safety-related const activities should not be stopped Certificate of 8vc encl LIEBERMAN, J. BURNS, 8 0 Rulemaking > Enforcement Division 80/04/24 12pp
- --B006260198 Requests hearing on behalf of Matagorda County,TX citizens re NRC 800430 rept sent to Houston Lighting & Power H Scarlott 800504 article in Houston Post & Citizens of Matagorda County petition encl KEEN,N Affiliation Unknown 80/05/15 3pp
- --8006260200 Submits Bexar County.TX.2ist Senatorial district convention resolution, requesting hearing to provide public w/full infere arder to show cause based on util vialations ANDERSON,I H Affiliation Unknown 80/05/19 ip
- --8006260201 Requests hearing on behalf of Houston Gulf Coast Bldg Trade Council in Matagorda County, TX VAN HOY, O Affiliation Unknown 80/05/20 1p
- H General correspondence
- 8006060284 Opposes licensing of power plant Informs NRC that legal action will be taken to provent licensing DUNSTON.L Affiliation Unknown 80/06/01 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006180370 Forwards Amend 11 to FSAR, consisting primarily of responses to NRC 800318 request for add1 QA info
 OPREA, 0 W Houston Lighting & Power Co 80/06/18 3pp
- ---B004180373 Amend 11 to FBAR, consisting primarily of responses to NRC B00318 request for add1 GA info OPREAG W Houston Lighting & Power Co 80/06/12 96pp
- M Antitrust correspondence
- 8006130243 Discovery rept for Mar 1980 No discovery requests initiated or received Certificate of Svc & change of address notice enci
 JOHN.D F Southwest Texas Electric Cooperative JOHN.D F
 McDermott, Will & Emery 80/04/16 5pe
- 8006060428 Corrects misstatement of fact in Public Utils Board of City of Brownsville:TX Mar-Apr 1980 discovery rept Failure to participate in J Bruggeman deposition was due to counsel independent decision not to attend Certificate of Svc encl STAML.D M Isham, Lincoln & Beale 80/03/01 App

- R006120056 Motion for 800509 pishearing conference to apprise ASLB of status of settlement discussions Proposed order & Certificate of Svc encl CYPHERT.S B . DDPSOVIC, D A . LUGUE.N Justice, Dapt of BO/05/05 Spp
- 8006/20272 Discovery rept for April 1980 No discovery requests received or initiated Certificate of Svc encl MOOD, J C San Antonio, TX MOOD, J C Matthews, Newlin, Macfarlane & Barrett 80/05/05 4pp
- 8006060026 Advises that Public Utils Board of City of Brownsville.TX does not agree w/DM Stahl version or facts re Bruggeman deposition Labeling matter as misunderstanding considered as polite understatement PDFRIER.H R Spiegel & McDiarmid BO/05/07 ip
- 8004050555 Forwards status rept Delivery arrangements made for 800512 KNDTYS, J.B. Debevoise & Liberman 80/08/09 ip
- ~-800\(\delta\)0505\(\delta\)15 Status repl re settlement negotiations' progress
 Discussions are continuing Urges ASLB to hold prehearing
 conference by 800314 \(\delta\) requests deferral of ruling on
 extension Certificate of Svc & supporting documents encl
 8AMPELS, M D Texas Utilities Co SAMPELS, M D Horsham, Forsythe
 & Sampels 80/05/07 20pp
- 8006060033 Forwards Houston Lighting & Power status of settlement rept, per ASLB 800410 order Affidavit not appropriate GREEN, D. G. Lowenstein, Newman, Reis, Axelrad & Toll 80/05/09 2pp
- --B006060036 Status of settlement rept per ASLB 800410 order deferring trial briefs, final proheuring conference & evidentiary hearing Unges addl 30-day extension for continuance of negotiations due to complexity Contificate of Svc encl BARNETT.E W Houston Lighting & Power Co 80/05/09 7pp
- 8006060492 Status rept re settlement discussions' progress Urges ASLB to convene pretrial conference to accommodate outstanding discovery, final trial preparation 1 resolution of remaining procedural matters Certificate of Svc encl
 CYPHERT, 6 B . PARMENTER, F . DOPSOVIC, D A Justice Dept of 80705/09 79p
- 8006110233 Forwards rept on status of settlement OREEN, D G Lowenstein, Newman, Reis, Axelrad & Toll 80/05/09 2pr
- BOOA:BOI89 Rept on settlement negotiations Buggests that conference be held to determine add1 time needed by applicant Trial should be preceded by pretrial conference to accommodate discovery & other matters W/Certificate of Bvc CYPHERT,S B . PARMENTER.F. DOPSOVIG.D A Justice, Dept of BO/O5/09 9pp
- BOO6230197 Settlement status rept by Public Utils Board of Brownsville.

 TX Proposes early trial schedule & 30-day extension to
 explore possibility of settlement Certificate of Syc encl
 SPIECEL. G Brownsville.TX SPIECEL. G Briegel & McDiarmid
 BO/05/09 6pp
- B006240250 Status rept on settlement negotiations per ABLB 800410 order Requests 30-day extension in procedural dates to allow continuation of discussions Certificate of Syc encl BTAML, D M Central & Bouth Hest Services, Inc STAHL, D M Isham, Lincoln & Beale B0/05/09 12pp
- BOO6250173 Submits status rept on settlement negotations per ASLB BOO410 order Joint owner≼hip agraement will be completed by BOI101 Supporting documentation & Certificate of Byc encl BURCHETTE, H H , RITTS, F H Texas—Louisiana Electric Cooperative Inc, BURCHETTE, W H Northcutt Ely BO/05/07 29pp
- BOO6040541 Discovery rept for Apr 1980 Util counsel participated in depositions of NC Lerner & Q Taylor expert economic witnesses for NRC & DDT respectively AHEARNE, C D Texas Utilities Co AHEARNE, C D Debevoise & Liberman HO/O5/15 Spp
- 8006090175 Discovery rept for Apr 1980 Participated in NG Learner & Q Taylor depositions Reverved NRC updated response to Houston Lighting & Power second set of interrogatories Inspected NRC documents designated by expert witness AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debevoise & Liberman 80/09/15 Spp
- 8004200142 Discovery rept for Apr 1980 Participated in OTC Taylor deposition Responded to Houston Lighting & Power motion to compel production of documents Undertook settlement discussions & trial preparation Certificate of Svc encl CYPHERT. S B Justice. Dept of 80/05/19 5pp

- 8006060361 Discusses review of 800507 document re question of disconnecting facilities in event of interconnection in interstate commerce Commission should not agree prematurely to license conditions re federal jurisdiction exemption SPIEGEL. O Spiegel & McDiarmid 80/05/20 2pp
- 8006160163 Motion to establish trial & procedural dates Proposes 800609 for settlement repts,800610 for prehearing,800613 for witness lists & briefs,800627 for responding parties & 800701 for final prehearing conference M/Certificate of Bvc CYPHERT,8 B , PARHENTER.F , DOPSGVIC.D A Justice,Dept of 80/05/21 6pp
- 8006170242 Discovery rept for Apr 1980 Attended continuation of NC Lerner deposition Responded to Houston Lighting & Power first set of interrogatories Joined parties' motion for 30-day extension Certificate of Svc encl CARNEY, J A Central & South West Corp 80/05/22 6pp
- 3006170004 Forwards corrected Page 3 to DDJ 800521 motion to establish trial & other procedural dates CYPHERIS B Justice: Dept of 80/05/23 ip
- ---8004170007 Corrected Page 3 to DDJ 800521 motion to establish trial & other procedural dates Certificate of Bvc encl CYPHERT. S B , PARMENTER, F , DOPSOVIC. D A Justice, Dept of 80/05/21 4ps
- 8006120052 Reply in opposition to DOJ 800521 motion to establish trial & other procedural dates Request premature ASLB should adhere to previous discretion that parties address schedule at 800610 prehearing conference Certificate of Svc encl KNOTTS.J B Texas Utilities Generating Co KNOTTS.J.B Defevoise & Liberman 80/05/28 Spp
- 8006050272 Notice of appearance in proceeding Certificate of Bvc encl LEWIS:8 H Hearing Branch 2 80/06/03 4pp.
- 8006110076 Advises that San Antonio has neither received nor inititated discovery during May 1980 Certificate of Svc encl MOOD, J C. Matthews, Nowlin, Macfarlane & Barrett, 80/06/03 4pp
- BOO6110162 Notifies parties that SH Lawis, appearing in proceeding on behalf of NRC, is mephew of O Spiegel of Spiegel & McDiarmid, representing Public Utils Board of City of Brownsville, TX No conflict of interest exists CHANANIA, F. D Antitrust Division 80/06/06 ip.
- 8006110302 Rept on settlement negotiations per ASLE 800513 order Requests 30-day extension for procedural dates to resolve & narrow issues Prehearing conference should be held at end of extension Cartificate of Svc and SAMPELS: M.D. . KNDITS: J B Texas Utilities Generating Co SAMPELS: M.D. . WOSTAM, Forsythe & Sampels 80/06/09, 5pp
- 8006i10352 Second settlement status rept per ASLB 8005i3 order. Urges add1 60 to 90-day extension to permit continued afforts Complex areas re wheeling & access to dc interconnections remain under continuing study. Certificate of Svc encl. CHANANIA, F.D. Antitrust Division 80/06/09, 7pp
- BOO6110357 Settlement status rept per ASLB 800513 order Urges establishment of trial data to complete outstanding ASLB discovery to resolve ASLAB discovery to resolve ASLAB discovery to resolve ASLAB discovery to expedite final trial preparation Certificate of Bvc encl CYPHERT, S. B. Justice, Dept of 80/06/09, 6pp
- BOO6110364 Rept on settlement negotiations per ABLB 800513 order Urges additions of a stantial progress Expects to execute agreement w/Central & Bouth West Corp & TX Utils Generating Co. Gertificate of Byc encl BARNETT, E. W. Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll. 80/06/09. 7pp
- 8006110371 Rept on settlement negotiations by Public Utils Board of City of Brownsville.TX.per ABLB 800313 order. Bubmitted draft of transmission agreement & rates to Central & South Hest Corp. No response received Certificate of Syc encl. BPIEGEL.9. Texas, State of. SPIEGEL.0 Spiegel & McDiarmid B0/06/09. App.
- BOO6110373 Rept on settlement discussions per ASLB 800513 order. South West Co reached agreement w/Houston Lighting & Power & TX Utils Co. Differences w/Public Utils Board of Brownsville, TX not yet resolved. Certificate of Svc encl BTAHL, D. M. Central & Bouth West Services, Inc STAHL, D. M. Isham, Lincoln & Beele. 80/06/09 Spp.

- 8006190454 Submits settlement negatiations status rept per ASLB 800513 order TX LA & TX Power & Light Co resolved differences in itr of intent Petition to intervene will be amended to reflect new position Certificate of Svc encl BURCHETTE.W H , RITTS.F H Northcutt Ely 80/06/09 5pp
- 8006200167 Rept on settlement negatiations status South TX Electric Cooperative & Medina Electric Cooperative should be brought into settlement process due to readiness to address concerns re protection of certain interests Certificate of Bvc encl JOHN.D F , HUNTER, M Medinaelectric Cooperative.Inc JOHN.D F McDermott.Will & Emery 80/06/09 App
- BOO6110266 Forwards settlement agreement, executed 800609
 BOUKNIGHT, J A Lowenstein, Newman, Rais, Axelrad & Toll 80/06/10
- --B005110282 Settlement agreement for all outstanding controversies re question whether Electric Reliability Council of TX should be interconnected w/Southwest Power Pool Certificate of Svc encl JORDAN.D D Houston Lighting & Power Co FARRINGTON, J S Dallas Power & Light Co MAROUARDT, W Texas Electric Service Co B0/06/09 19pp
- 8006190890 Order advising that further settlement negotiations status repts are to be filed by 800711; that another prehearing conference be held do 800714 & that discovery question be deferred until further developments Urges fair agreement BISMOP.C J Atomic Safety and Licensing Appeal Panel 80/06/16 3pp
- N Antitrust hearing transcripts
- 8006170743 Transcript of 800610 prehearing conference in Bethesda, MD Pp 832-890 Morning session * Atomic Safety and Licensing Board Panel 80/06/10 59pp
- 8006230254 Proposed corrections to 800610 prehearing conference transcript Certificate of Svc encl CYPHERT, 8 B Justice, Dept of 80/06/16 5pp
- G Inspection reports, IE Bulletins & correspondence
- 8006300053 Forwards 1E Circular 80-05, "Emergency Diesel Generator Lubricating Oil Addition & Onsite Supply " No written response required 8EYFRIT, K V Region 4, Dallas, Office of the Director 80/04/01
- 8006130194 Forwards notice of violation from insp on 800301-31 IE Insp Repts 50-498/80-05 & 50-499/80-05 will be issued in near future SEIDLE.W.C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/04 2pp.
- ---B006130203 Notice of violation from insp on B00301-31 Noncompliance noted failure to provide timely reply to item of noncompliance & failure to provide timely notification of const deficiencies

 * Region 4, Dallas, Office of the Director 80/04/04 2pp
- 8006130069 Forwards IE Insp Repts 50-498/80-05 & 50-499/80-05 on 800301-31 8EIDEL. N.C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/25 2pp
- --8006130074 IE Insp Repts 50-498/80-05 & 50-499/80-05 on 800301-31 Noncompliance noted failure to provide timely reply to item of noncompliance & failure to provide timely notification of const deficiencies CROSSMAN. M. A. PHILLIPS. H. S. Region 4. Dallas. Office of the Director 80/04/24 Spp
- BO06040164 Discusses special investigation of const activities conducted 791110-800207 Areas inspected include allegations of harasament intimidation & lack of support of QC inspectors by QC mgt & assessment of QA/QC program STELLO.V Office of Inspection & Enforcement, Office of the Director 80/04/28 ip
- 8006070225 Forwards 1E Insp Rapts 50-498/80-07 & 50-499/80-07 on 800408-11 & notice of violation SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch. 80/04/30 2pp

1.

--8006090229 Notice of violation from insp on 800408-11.
* Region 4. Dallas. Office of the Director 80/04/24 ip

- --8004090234 IE Insp Repts 50-498/80-07 & 50-499/80-07 on 800408-11
 Noncompliance noted failure to follow procedure for storage
 of matl
 - or mass MUBACEK,W G , CROSSMAN,W A Region 4, Dellas, Office of the Director 80/04/24 4ρp
- 8006040289 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl SEYFRIT.K V Region 4. Dallas. Office of the Director 80/05/09
- 8006090017 Ack receipt of 800507 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-498/80-05 & 50-497/80-05 SEIDLE:N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/05/14 ip
- --8006090021 Responds to NRC 800404 ltr re violations noted in IE Insp Repts 50-498/80-03 % 50-499/80-05 Corrective actions applicable personnel have been reminded to provide timely replies & notification to NRC TURNER.E A Houston Lighting & Power Co 80/05/07 3pp
- 8006300062 Forwards IE Circular 80-12, "Valve-Shaft-To-Actuator Key May Fall Gut of Place When Mounted Below Horizontal Axis " No written response required SEYFRIT, X V Region 4, Dallas, Office of the Director 80/05/14
- 8006030018 Forwards payment of civil penalties in amount of \$100,000 in response to NRC 800430 notice Items of noncompliance are essentially substantiated Certificate of 8vc encl
 DPREA, O W Houston Lighting & Power Co 80/05/23 3pp
- 8006030023 Responds to 800430 show cause order Matters re Section III answered in reply to notice of violation Mgt is committed to become more involved in program & make GA/GC functions highly visible & independent Certificate of Svc encl
 OPREA. G W Houston Lighting & Power Co 80/05/23 App
- 8006030172 Responds to NRC 800430 ltr re violations noted in IE Insp. Repts 50-498/79-19 & 50-499/79-19 Corrective actions Brown & Root conducted mgt assessment of causes of perception of harassment Util increased involvement in GA/OC program OPRIA.G W Houston Lighting & Power Co 60/05/23 75pp
- 800620004B Forwards IC Circular 80-13, "Orid Strap Damage in Hestinghouse Fuel Assemblies " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/28
- 8006300578 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks "
 Two tanks will be augmented w/vacuum relief valves prior to plant operation Bys summary table encl
 TURNER, E A Houston Lighting & Power Co 80/06/02 3pp
- 8006160171 Bummary of 800530 meeting w/util in Bethesda, MD re util response to enforcement actions THORNBURG. H D Division of Reactor Construction Inspection 80/06/03 2pp
- 8006300636 Ack receipt of 800523 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/80-07 & 50-497/80-07 & SEIDEL, N C Region 4, Dallas, Reactor Construction & Engineering Support Branch
- --8006300644 Responds to NRC 800430 ltr re violations noted in IE Insp Repts 50-498/80-07 & 50-499/80-07 Corrective actions site mechanical GA instructed to perform survaillance of installed penetrations/sieeves on weekly basis TURNER.E A Houston Lighting & Power Co 80/05/23 2pp
- 9 Reportable occurrences, LERs & related correspondence
- 8006090571 Advises that potential deficiency re excessive hydrostatic pressure under essential cooling pend does not meet criteria of 10CFR55(s)
 TURNER.E A Houston Lighting & Power Co 80/04/25. 3pp
- B006180638 Notifies NRC that 800411 final Part 21 rept re unqualified motor operator for turbine driven auxiliary feedwater pump was also intended to satisfy 10CFR50 55(e) reporting requirements
 TURNER.E.A. Houston Lighting & Power Co. 80/05/07. 3pp

- 8006110314 Forwards final deficiency mept re safety injection syscontainment emergency sump piping design TURNER, E.A. Houston Lighting & Power Co. 80/05/30 ... 3pp
- ---8006i10322 Final deficiency rept re safety injection sys containment emergency sump piping design During routine review, discovered weld between sump liner & process pipe insurfficient Design corrected & procedures revised.

 * Houston Lighting & Power Co 80/05/30 3pp
- B006i10337 Interim deficiency rept re nonconforming backfill matl areas around Unit 2 power block Borings into structural backfill showed Unit 1 area in conformance Four areas within Unit 2 found potentially below GC criteria Boring diagram encl TURNER: E A Houston Lighting & Power Co 80/05/30 5pp
- 8006240292 Second interim deficiency rept re essential cooling water sys girth wold radiograph rejectable indications Deficiency will be addressed in util response to show cause order Next rept will be submitted 800912

 OPREAG W Houston Lighting & Power Co 80/05/13 3pp
- B006300435 Interim deficiency rept re seismic qualification of essential cooling water intake structure gantry crame & diesel generator fuel oil storage tank Preliminary findings show designs sufficiently conservative Mods not expected OPREA.O W Houston Lighting & Power Co 80/06/26 2pp
- V Operator Examinations
- 8006180095 Notification of 800717 meeting w/util in Bethesda,MD to discuss current requirements for operator qualification & licensing Meeting originally scheduled for 800625 SELLS,D E Licensing Branch 2 80/06/02 ip
- BOO618033? Notification of BO0625 meeting w/util in Bethesda.MD to discuss current requirements for operator qualification & licensing SELLS.D E Licensing Branch 2 80/06/02 3pp
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PKR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl. EISENHUT.D O Division of Licensing 80/05/20 13pp
- 8006060259 Advises that CAM 79-37 will be withheld from public disclosure per 10CFR2 790 Document is part of package sent by util on 791120 representing detailed technical audit of fuel design BCHMENCER. A Operating Reactors Branch 2 80/05/22. 3pp
- 8006130159 Notification of 800718 meeting w/util in Bethesda. MD resoil/structure interaction study Meeting orginally scheduled for 800626
 BELLS.D Licensing Branch 2 80/06/02 ip
- 800619068B Notification of 800626 meeting w/util in Bethesda.MD to discuss soil/structure interaction study SELLS:D Licensing Branch 2 80/06/02 3pp
- F Security, medical, emergency & fire protection plans
- BOOS130317 Forwards clarification of NRC requirements for emergency response facilities defined in 790913 itr Addi specific criteria for facilities under development EISENHUT, D G Division of Operating Reactors BO/04/25 6ipp
- BOO6050368 Responds to NRC 791121 ltr re upgraded emergency plans Util will defer submittal of upgraded plan until later date consistent w/project licensing schedule & development of NRC guidance
 MCQUIRE.W F Houston Lighting & Power Co 80/05/28 2pp
- 9 Adjudicatory correspondence
- 8006120070 Confirms & notifies of agreement for DE Swayze 800619-21 deposition, subj to ABLB granting of motion for discovery extension Place will be determined at later time COMAN.FE Baker & Botts 80/04/28 Spr

8006120278 Confirms & notifies parties of L Sinkin 800618 deposition Rescheduling necessitated by involvement in other hearing Suggests 800617 for Buchorn deposition Related corrascondence

Baker & Botts 80/05/05 3pp COUAN F F

- 800&060478 Notion to compel Citizens for Equitable Utils to provide further answers to first set of interrogatories Intervenor 800423 answers incomplete & sometimes irrelayant & unresponsive Certificate of Svc encl CONAN, F E, NEWMAN, J R Houston Lighting & Power Co CONAN, F E Baker & Botts 80/05/09 (1pp
- 8006200129 Ark 800506 telcon re agreement for P Suchorn 800617 deposition in San Antonio, TX Sinkin deposition will be taken on 800618 & Swayze on 800619-21 CGWAN, P E Bater & Botts 80/05/08 Jpp
- 8006110267 Confirms final arrangements for P Buchorn.L Sinkin & D Swayre depositions P Buchorn \$ L Sinkin depositions scheduled 800617 & 18 respectively, in San Antonio.TX & D Swayre deposition scheduled 800619 in Bay City.TX COMAN.F E Baker & Batts 80/05/20 3pp
- 8006190595 Submits supportive evidence for 800527 request that NRC convene public hearing on 800430 show cause order reviolations noted in NRC investigation Intervenors should be able to present evidence recontentions Memo encl BINKIN.L Citizens Concerned About Nuclear Power. Inc. Citizens For Equitable Utilities 80/05/28 13pp
- 8006030139 Advises that NRC has received Houston Lighting & Power 800523 ltrs in response to IE 800530 ltr re order to show cause, notice of violation & notice of proposed imposition of civil penalties MCOURREN.H J Hearing Branch 1 80/05/30 1p
- 8006110340 Discusses possible solutions to matter raised by P Buchorn at 800527 meeting concerning application for GL Suggests that P Buchorn submit list of specific documents for examination or duplication COMAN.F E Baker & Botts 80/06/02 3pp
- 8006180506 Response in opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utils request for hearing re IE 800430 order to show cause Petitioners failed to establish right to hearing Certificate of Byc encl CULP,R H . COHAN.F Houston Lighting & Power Co CULP,R H Lowenstein, Newman. Reis, Aisland & Toil 80706/13 13pp
- 8006260196 Motion to deny Citizens Concerned About Nuclear Power & Citizens for Equitable Utils' 800527 request for hearing re IE 800420 order to show cause why safety-related constactivities should not be stopped Certificate of Svc encl LIEBERAN, J. BURNS, S. G. Rulemaking & Enforcement Division 80/05/24 12pp
- --900A2A019B Requests hearing on behalf of Matagorda County, TX citizens re NRC 800A30 rept sent to Houston Lighting & Power H Scarlett 800504 acticle in Houston Post & Citizens of Matagorda County petition encl KEEN, N Affiliation Unknown 80/03/15 3pp
- --8006260200 Submits Bexar County, TX, 21st Benaturial district convention resolution.requesting hearing to provide public w/full infore order to show cause hased on util violations ANDERSON, I H Affiliation Unknown 80/05/19, 1p
- --8006260201 Requests hearing on behalf of Houston Gulf Coast Bidg Trade Council in Matagorda County.TX VAN HOY.O Affiliation Unknown 80/05/20 is
- H Canaral correspondence
- 8006060284 Deposes licensing of power plant informs NRC that legal action will be taken to prevent licensing DUNSTON, F., DUNSTON, L. Affiliation Unknown 80/06/01 1p
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- BOO6180370 Forwards Amend 11 to FBAR, consisting primarily of responses to NRC 800318 request for addl GA info OPREA, O W Houston Lighting & Power Co 80/06/18 3pp
- ---8006180373 Amend 11 to FBAR, consisting primarily of responses to NRC 800318 request for add1 QA info.

 OPREA-G H Houston Lighting & Power Co 80/06/12. 96pp

- M Antitrust coirespondence
- 8006130243 Discovery rept for Mar 1980 No discovery requests initiated on received Centificate of Svc & change of address notice enci unct JOHN, D F Southwest Taxas Electric Cooperative 80/04/16 Spp
- 8006060429 Corrects misstatement of fact in Public Utils Board of City of Brownsville, TX Mar-Apr 1980 discovery rept Failure to participate in J Bruggeman deposition was due to counsel independent decision not to attend Certificate of Syc encl STAHL.D N Isham, Lincoln & Beale 80/05/01 App
- B006120056 Motion for 800509 prehearing conference to apprise ASLB of status of settlement discussions Proposed order & Certificate of Svc ancl CYPHERT-S B , PARMENTER.F , WALLACE.R L Justice, Dept of 80/05/05
- ROO6120272 Discovery rept for April 1980 No discovery requests received or initiated Certificate of Svc encl WOOD, J C San Antonio. TX WOOD, J C Matthews, Nowlin, Macfarlane & Barrett 80/05/05 4pp
- 8006060026 Advises that Public Utils Board of City of Brownsville,TX does not agree w/DM Stahl version of facts re Bruggeman deposition Labeling matter as misunderstanding considered as polite understatemont POIRIER.M R Spiegel & McDiarmid 80/05/07 1p
- 8006030535 Forwards status rept Delivery arrangements made for 900512 KNOTTS, J B Debevoise & Liberman 80/05/09 tp
- --8006090361 Status rept re settlement negotiations' progress
 Discussions are continuing Orges ASLB to hold prehearing
 conference by 800914 & requests deferral of ruling on
 extension Certificate of Bvc & supporting documents encl
 SAMPELS,M D Texas Utilities Co 80/09/09 20pp
- 8006060033 Forwards Houston Lighting & Power status of settlement rept, per ABLD 800410 order Affidavit not appropriate GREEN, D & Lowenstein, Newman, Reis, Axelrad & Toll 80/05/07 2pp
- --8006060036 Status of settlement rept per ASLB 800410 order deferring trial briefs, final prehearing conference & evidentiary hearing Urges addl 30-day extension for continuance of negotiations due to complexity Certificate of Svc encl BARNETT, E W Houston Lighting & Power Co 80/03/09. 7pp
- 8006060492 Status rept re settlement discussions' progress Urges ASLB to convene pretrial conference to accommodate outstanding discovery final trial preparation & resolution of remaining procedural matters Certificate of Svc encl CYPHERT, S B . LUQUE, N . WALLACE. R Justics Dept of 80/05/09 9pp
- 8006110233 Forwards rept on status of settlement OREEN.D 0 Lowenstein.Neuman.Reis.Axelrad & Toll 80/05/09 2pp
- 8006:180:189 Rept on settlement negotiations Suggests that conference be held to determine add1 time needed by applicant Trial should be preceded by pretrial conference to accommodate discovery & other matters W/Certificate of Suc CYPHERT. S B , LUGUE. N , MALLACE. R Justice. Dept of 80/05/09 9pp
- 8006230157 Settlement status rapt by Public Utils Board of Brownsville. TX Proposed early trial schedule & 30-day extension to explore possibility of settlement Certificate of Svc encl. SPIE0EL.0 Brownsville.TX 80/05/09 6pp
- 8004240250 Status rept on sottlement negotiations per ASLB 600410 order Requests 30-day extension in procedural dates to allow continuation of discussions Certificate of Svc encl STAHL.D M Central & South West Services.Inc 80/05/09 i2pp
- 8006250193 Bubmits status rapt on settlement negotations per ABLB 800410 order Joint ownership agreement will be completed by 801101. Supporting documentation & Certificate of Byc enci. BURCHETTE.W H Texas-Louisiana Electric Cooperative, Inc. RITTS, F. H Northcutt Ely 80/05/09 29pp
- BOO40A0541 Discovery rept for Apr 1980 Util counsel participated in depositions of NC Lerner & 9 Taylor, expert economic witnesses for NRC & DOT, respectively AHEARN.C D Texas Utilities Co 80/08/15 3pp

- 8006090175 Discovery rept for Apr 1980 Participated in NC Learner & G Taylor depositions Received NRC updated response to Houston Lighting & Fower second set of interrogatories Inspected NRC documents designated by expert witness AHEARN.C D Texas Utilities Generating Co 80/05/15 5pp
- B006200142 Discovery lept for Apr 1980 Participated in GTC Taylor deposition Responded to Houston Lighting & Power motion to compel production of documents Undertook settlement discussions & trial preparation Certificate of Svc encl CYPHERT.S B Justice.Dept of 80/09/19 Spp
- B006060361 Discusses review of B00509 document re question of disconnecting facilities in event of interconnection in interstate commerce Commission should not agree prematurely to license conditions re federal jurisdiction exemption SPIECEL, G. Spiegel & McDiarmid B0/05/20 2pp
- 8006160163 Motion to establish trial % procedural dates Proposes 800607 for settlement repts. 800610 for pickearing. 800613 for ulthose lists % briefs. 800627 for iosponding parties % 800707 for final pickearing conterence W/Certificate of Syc CYPHERT. S B. WALLACE, R Justice, Dept of 80/05/21 6pp
- 8006170242 Discovery rept for Apr 1980 Attended continuation of NC Lerner deposition Responded to Houston Lighting & Fawer first set of interrogatories Joined parties' motion for 30day extension Centificate of Svc ancl CARNEY, J A Central & South Wast Corp 80/05/22 App
- --8005170007 Corrected Page 3 to DDJ 800521 motion to establish trial & other procedural dates Cortificate of Svc encl CYPHERT, S B . WALLACE, R Justice, Dept of 80/05/21 4pp
- QOO6120052 Reply in opposition to DGJ 800521 motion to establish trial 5 other procedural dates Request premoture ASLB should adhere to previous discretion that parties address schedule at 800610 prehearing conference Certificate of Svc encl
 KNOTYS, J R Texas Utilities Generating Co 80/05/28 5pp
- 8006050272 Notice of appearance in proceeding Certificate of Svc encl LEWIS, S.H. Hearing Branch 2 80/06/03 4pp
- 6006110076 Advises that San Antonio has neither received nor inititated discovery during May 1780 Certificate of Svc encl WCCD, J. C. Matthews, Nowlin, Macfarlane & Borrett 80/06/03 4pp
- BOOG110162 Notifies parties that BH Lewis, appearing in proceeding on behalf of NRC, is nephew of 0 Spiegel of Spiegel & McDiarmid, representing Public Utils Board of City of Brownsville, TX No conflict of interest exists CHANANIA,F D Antitrust Division 80/06/06 1p
- 8006110302 Rept on settlement negotiations per ASLB 800513 order Requests 30-day extension for procedural dates to resolve & narrow issues Prehearing conference should be held at end of extension Certificate of Svc encl SAMPELS,M D Texas Utilities Generating Co KNOTTS,J R Debevoise & Liberman 80/06/09 Spp
- GOO6110352 Second settlement status rept per ASLB BOO513 order Urges addl 60 to 90-day extension to permit continued efforts Complex areas re whoeling 5 access to do interconnections remain under continuing study Certificate of Svc encl CHANANIA.F D Antitrust Division BO/06/09 7pp
- 8006110387 Settlement status ropt per ASLB 600513 order Urges establishment of trial date to complete outstanding ASLB discovery. to resolve ASLAB discovery & to expedite final trial preparation Certificate of 8vc encl CYPHERT. S B Justice, Dept of 80/06/09 dpp
- 8006110364 Rept on settlement negotiations per ASLB 800513 order Urges add1 sttension to entertain further substantial progress Expects to execute agreement w/Central & South Mest Corp & TX Utils Cenerating Co Certificate of Byc encl BARNETT, E W Houston Lighting & Power Co 80/06/09 7pp
- 8006110371 Rept on settlement negotiations by Public Utils Board of City of Brownsville, TX, per ASLB 800513 order Submitted draft of transmission agreement & rates to Central & South West Corp No response received Certificate of Svc encl SPIEGEL, O Texas, State of 80/06/09 App

- 8006110375 Rept on settlement discussions per ABLB 800913 order South Mest Co reached agreement w/Houston Lighting & Power & TX Utils Co Differences w/Public Utils Board of Brownsyille, TX not yet resolved Certificato of Syc encl
 STANL.D M Central & South West Services, Inc 80/06/09 Opp
- 8006190454 Submits settlement negotiations status rept per ASLB 800513 order TY LA & TX Power & Light Co resolved differences in ltr of intent Petition to Intervene uill be amended to reflect new position Certificate of Svc enc.

 BURCHETTE.W H Northcutt Cly 80/06/09 Spp
- 8006200167 Rept on settlement negotiations status Bouth TX Electric Cooperative & Medipa Electric Cooperative should be brought into settlement process due to readiness to address conceins re-protection of certain interests Certificats of Evc enri JOHN.D F Medinaelectric Cooperative.Inc HUNTER.M McGinnis. Lochridge & Kilgore 80/06/09 App
- 8006110266 Forwards settlement agreement, executed 800609
 BOUKNIOHT, J.A. Lowenstein, Newman, Rois, Axelrad & Toll 80/06/10
- --8006110252 Settlement agreement for all outstanding controversies requestion whether Electric Reliability Council of TX should be interconnected w/Southwest Power Pool Certificate of Svc encl

 JDRDAN.D D Houston Lighting & Power Co SPENCE.M D Texas Power & Light Co MARRIS.B J Central & South West Corp 80/06/09
- 8006190570 Order advising that further settlement negotiations status repts are to be filled by 800711, that another prehoaring conference be held on 800714 & that discovery question be deferred until further developments Urges fair agreement BISKOP, C J Atomic Safety and Licensing Appeal Panel 80/06/16 3pp
- N Antitrust hearing transcripts
- 8006170743 Transcript of 800610 prehearing conference in Bethesda.MD Pp 832-890 Morning session # Atomic Safety and Licensing Board Panel 80/06/10 59pp
- B006230254 Proposed corrections to 800610 prehearing conference transcript Certificate of Svc enci CYPHERT, 8 B Justice.Dept of 80/04/16 5pp
- G Inspection reports. IE Dulletins & correspondence
- 8006300053 Forwards IE Circular 80-05, "Emergency Diesel Generator Lubricating Oll Addition & Onsite Supply," No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director. 80/04/01
- 8006130194 Forwards notice of violation from insp on 800301-31 IE Insp. Repts 50-498/80-05 & 50-499/80-05 will be issued in near future SEIDLE.W.C. Region 4. Pallas. Reactor Construction & Engineering Support Branch 80/04/04 2pp
- --8006130203 Notice of violation from insp on 800301-31 Noncompliance noted failure to provide timely reply to item of noncompliance & failure to provide timely notification of const deficiencies

 * Region 4. Dallas. Office of the Director 80/04/04 2pp
- 8006130069 Forwards IE Insp Repts 50-498/80-05 & 50-499/80-05 on 800301-01 SEIDELLW C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/25 20
- --B006130074 IE Insp Repts 50-498/80-05 & 50-499/80-05 on 800301-31 Noncompliance noted failure to provide timely reply to item of noncompliance & failure to provide timely notification of const deficiencies CROSEMAN.W A. PHILLIPS.H S. Region 4. Dallas. Office of the Director 80/04/24 5pp
- BO06040164 Discusses special investigation of const activities conducted 791110-B00207 Areas inspected include allegations of harassment Intimidation & lack of support of GC inspectors by GC mgt & assessment of GA/GC program STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/28 ip

- 8006090225 Forwards IE Insp Repts 50-498/80-07 & 50-499/80-07 on 800408-11 & notice of violation SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/30 2pp
- --8006070227 Notice of violation from insp on 800408-11
 Region 4. Dallas. Office of the Director 80/04/24 1p
- --8006090234 IE Insp Repts 50-498/80-07 % 50-499/80-07 on 800408-ii Noncompliance noted failure to follow procedure for storage of matl HUBACEK, W. G. CROSSMAN, W. A. Region 4: Dallas, Office of the Director 80/04/24 App
- 8006040289 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Dperability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 Meile in Refueling Mode" and SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/09 10.
- 8006090017 Ack receipt of 800507 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-499/80-03 & 50-499/80-03 SEIDLE, W.C. Region 4. Dallas. Reactor Construction & Engineering Support Branch
- --8006070021 Responds to NRC 800404 ltr re violations noted in IE Insp Repts 50-498/80-05 & 50-499/80-05 Corrective actions applicable personnel have been reminded to provide timely replies & notification to NRC TURNER, E A Houston Lighting & Power Co 80/05/07 3pp
- 8006300062 Forwards IE Circular 80-12. "Valve-Shaft-To-Actuator Key May Fall Gut of Place When Mounted Below Horizontal Axis " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/14 ip.
- 800&030018 Forwards payment of civil penalties in amount of \$100,000 in response to NRC 800430 notice Items of noncompliance are essentially substantiated Certificate of Syc enc1
 OPREA.Q.W Houston Lighting & Power Co 80/05/23 3pp
- B006030023 Responds to B00430 show cause order Hatters re Bection III answered in reply to notice of violation Mpt is committed to become more involved in program & make GA/GC functions highly visible & independent Certificate of Svc encl
 OPREA: G W Houston Lighting & Power Co 80/05/23 6pp
- 8004030172 Responds to NRC 800430 ltr re violations noted in IE Insp. Repts 50-498/79-19 & 50-499/79-19 Corrective actions Brown & Root conducted mgt assessment of causes of perception of harassment Util increased involvement in GA/GC program OPREA:0. II Houston Lighting & Power Co. 80/05/23, 75pp
- 8006200048 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies" No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director. 80/05/28 ip
- 8006300578 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "
 Two tanks will be augmented w/vacuum relief valves prior to plant operation Sys summary table enc!
 TURNER, E A Houston Lighting & Power Co 80/06/02 3pp
- 8006160171 Bummary of 800530 meeting w/util in Bethesda,MD re util response to enforcement actions THORNBURG,H D Division of Reactor Construction Inspection 80/06/03 2pp
- BOO6300696 Ack receipt of BOO523 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/80-07 & 50-499/80-07 BEIDEL, W C Region 4, Dallas, Reactor Construction & Engineering 40/06/09 ip

- 8006180638 Notifies NRC that 800411 final Part 21 rept re unqualified motor operator for turbine driven auxiliary feedwater pump was also intended to satisfy 10CFR50 55(e) reporting requirements
 TURNER-E A Houston Lighting & Power Co 80/05/07 3pp
- 8006110314 Forwards final deficiency rept re safety injection syscontainment emergency sump piping design TURNER, E.A. Houston Lighting & Power Co. 80/05/30 ... 3pp
- ---8006110322 Final deficiency rept re safety injection sys containment emergency sump piping design During routine review, discovered weld between swmp liner & process pipe insufficient Design corrected & procedures revised * Houston Lighting & Power Co 80/05/30 3pp
- 8006i10337 Interim deficiency rept re nonconforming backfill math areas around Unit 2 power block Borings into structural backfill showed Unit 1 area in conformance Four areas within Unit 2 found potentially below GC criteria Boring diagram encl TURNER, E A Houston Lighting & Power Co 80/05/30 Spp
- 8006240292 Second interim deficiency rept re essential cooling water sys girth weld radiograph rejectable indications Deficiency will be addressed in util response to show cause order Next rept will be submitted 800912

 OPREA.G N Houston Lighting & Power Co 80/06/13 3pp
- 8006300435 Interim deficiency rept re seismic qualification of essential cooling water intake structure gantry crane & diesel generator fuel oil storage tank Preliminary findings show designs sufficiently conservative Mods not expected OPREA: G W Houston Lighting & Power Co 80/06/26 2pp

V Operator Examinations

- 8006180075 Notification of 800717 meeting w/util in Bethesda.MD to discuss curent requirements for operator qualification & licensing Meeting originally scheduled for 800625 SELLS.D E Licensing Branch 2 80/06/02 ip
- 8006180339 Notification of 800625 meeting w/util in Bethesda, MD to discuss current requirements for operator qualification & licensing Branch 2 80/06/02 3pp.
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

 A Application/construction stage documents & correspondence
- BOO6230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D Q Division of Licensing BO/05/20 13pp

G Adjudicatory correspondence

- 8006200071 Pages 4.5 & 6 for Exhibit A of High Rock Lake Association 800521 affidavit SPRINGER.D High Rock Lake Association 78/11/16 App
- DOCKET 30-501 DAVIS-BESSE NUCLEAR POWER STATION. UNIT 3

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURRQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance oriteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp.

DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8004230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NURRO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT, D G Division of Licensing BD/05/20 13pp

- DOCKET SIN-50-508 MPPSB NUCLEAR PROJECT, UNIT 3
- A Application/constitution stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify Implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, DO Division of Licensing 80/05/20 13pp
- E300411027B Notifies that lab will be conducting additionisture testing on low hydrogen electrodes using technique required in AMS A5 5.Section 25 Electrode coating moisture testing results will be applied only to Units 1 & 4
 REMBERGER. D.L. Washington Public Power Supply System 80/06/06
- 8006250140 Discusses reorganization of Ofc of Nuclear Reactor Regulation & advises that mgt responsibilities re facility have been assigned to A Bournia Reorganization charts encl TEDESCO.R L Assistant Director for Licensing 80/06/12
- F Security, medical, emergency & fire protection plans
- ED06250195 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan
 TEDESCO, R T Assistant Director for Licensing 80/04/16 2p Assistant Director for Licensing 80/04/16 2pp
- S Reportable occurrences, LERs & related correspondence
- BO04050236 PNO-V-BO-037 on B00518, Mount St Helen erupted Unit 2 has approx 1/B-inch of ash on ground, some ash dust inside plant Filtration sus operability confirmed Monitoring to detect abrasive matl in sys components underway BISHOP.T W Region 5, San Francisco. Office of the Director B0/05/19 2pp
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria enci EISENHUT.D C Division of Licensing 80/05/20 13pp
- BOO6ii0278 Notifies that lab will be conducting add1 moisture testing on low hydrogen electrodes using technique required in AMS AS 5.Section 228 Electrode coating moisture testing results will be applied only to Units 1 & 4
 RENGERGER, D.L. Washington Public Power Supply System BO/06/06
- BO06250140 Discusses reorganization of Ofc of Nuclear Reactor * Regulation & advises that mgt responsibilities re facility have been assigned to A Bournia Reorganization charts encl TEDESCO,R L. Assistant Director for Licensing BO/06/12 i
- F Security, medical, emergency & fire protection plans
- BOO6250195 Approves request for topical manual approach for site emergency plan & denies request for late submittal of site emergency plan TEDESCORT Assistant Director for Licensing 80/06/14 2pp.
- S Reportable occurrences, LERs & related correspondence
- BOO6050236 PNO-V-80-037 on 800518 Mount St Helen erupted Unit 2 has approx 1/8-inch of ask on ground, some ask dust inside plant Filtration sys operability confirmed Monitoring to detect abrasive math in sys components underway BISHOP.T W Region 5. San Francisco, Office of the Director 2pp
- DECKET 50-513 WPPSS NUCLEAR PROJECT: UNIT 4
- A Application/construction stage documents & cornespondence
- BOOGR30110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures, General operating reactor review procedure 4 acceptance criteria encl EISENHUT.D 0 Division of Licensing 80/05/20 13pp

- 8006030464 Suggests that clarification be added to Page 54 of NUREQ-0460. Vol 4 to reflect context in which cost estimates for ATMS mode are made Utils believe indirect costs were under-rated Disputes value impact an
- 8004050359 Forwards response to NRC 800325 request for addl info re sus sensitivity
 RENBERGER.D L Washington Public Power Supply System 80/06/02
- 8006110278 Notifies that lab will be conducting addl moisture testing on low hydrogen electrodes using technique required in AMB AS 5. Section 25 Electrode coating moisture testing results will be applied only to Units i & 4 RENBERGER. D. L. Washington Public Power Supply System 80/06/06
- F Security, modical, emergency & fire protection plans
- 8006270324 Forwards Amend 2 to "Fire Protection Evaluation RENBERGER,D L Washington Public Power Supply System S 80/06/11
- --B004270326 Amend 2 to "Fire Protection Evaluation"

 * Washington Public Power Supply System 80/05/31 App
- 8006240404 Forwards drawings re location for near-site emergency ctr Requests immediate review & response so that site-specific design work can proceed & site preparation begin "Preconceptual Bite Plan" available in Central Files only RENBERGER, D. L. Washington Public Power Bupply System 80/06/14
- --8006240408 "Wind Rose for WPPS-2 for Apr 1974 to Mar 1975 at ft Level " Washington Public Power Supply System 75/03/31, 1p
- --8006240413 "Combined Plant Svcs & Emergency Coordination Facility Site Location 1,930 Meter Radius Exclusion Areas & Property Lines "
 - Washington Public Power Supply System 77/01/12 1p
- --8006240418 "Environ Programs Base Map Hanford Area "
 * Washington Public Power Supply System 79/01/12 ip
- @ Inspection reports, IE Bulletins & correspondence
- 8006060134 Forwards IE Insp Repts 50-460/80-05 & 50-513/80-03 on SDOGSI-0403 No moncompliance noted

 SPENCER,O B Region 5, Ban Francisco, Reactor Construction &
 Engineering Support Branch 80/04/28 2pp
- --8006060141 IE Insp Repts 50-460/80-05 & 50-513/80-05 on 800331-0403, No noncompliance noted Major areas inspects WiMM valve flaw indications, pipe support & restraint sys & administrative controls for noncomforming conditions

 DDDDS.R T Region 5, Sam Francisco, Reactor Construction & Engineering Support Branch NARBULP P, WAONER, W Region Francisco, Office of the Director GO/04/24 App Region 5, San
- BOO4090402 Ack receipt of BOO515 ltr informing NRC of steps taken to correct deviation noted in IE Imag Repts 50-460/80-04 & 50-513/80-04 SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch BO/05/30 ip
- ---B005090404 Responds to NRC 800415 ltr re deviation noted in IE Insp. Repts 50-460/80-04 & 50-513/80-04 Corrective actions:
 engineering evaluations determined that use of electrode is acceptable based on ABME III guidelines
 RENBERGER, D. L. Washington Public Power Supply System 80/05/15
- --8006090409 Forwards IE Insp Repts 50-460/80-04 & 50-513/80-04 on BOO301-31 & notice of deviation SPENCER, Q B Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/04/15 2pp
- --8006090412 Notice of deviation from insp on 800301-31 * Ragion 5, San Francisco, Office of the Director 80/04/11 ip.
- ---8006070418 IE insp Repts 50-460/80-04 & 50-519/80-04 on 800301-31 Noncompliance noted welding electrodes qualified under Spac SFA-5 i rather than SFA-5 5 were used for welding pipe-to-steam generator RCPB welds TOTH A D . HAYNES,R C Region 5, San Francisco, Office of the Director 80/04/11 7pp

DOCKETED ITEMS

- :090406 Ack receipt of 800507 itr informing NRC of steps taken to rrect violations noted in IE Insp Repts 50-460/80-01 & -513/80-01 **ERCER/9 S Region 5. San Francisco. Reactor Construction & igineering Support Branch 80/05/30 ip
- 106090414 Responds to hRC 800407 ltr re violations nated in IE Insp Ropts 50-460/80-01 & 50-513/80-01 Corrective actions tamporary hanger & support procedure initiated & training session held on 800206 RENBERGER, D. W. Washington Public Power Supply System 80/05/07
-)06690441 Forwards 1E insp Repts 50-460/80-01 & 50-513/80-01 on 800101-31 & netice of violation SPENCER.G S Region 5. San Francisco. Reactor Construction & Enginesing Support Branch 80/04/07 2pp
- 105070444 Notice of violation from insp on 800101-31 # Region 5. Ban Francisco, Office of the Director 2pp 80704702
- 204090447 IE Insp Repts 50-460/80-01 & 50-513/80-01 on 800101-31 Moncoapliance noted failure to centrol temporary attachments to structural stool & undersite welds on pips supports HAYNES.R C Region 5. San Francisco. Reactor Construction & Engineering Support Branch TOTH.A D Region 9, San Francisco. Office of the Director 80/04/02 9pp
- KET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1 Application/construction stage documents & correspondence
- 230110 Advises EUR & PWR applicants of NRC decision to modify relamentation plan presented in Section 4 of NUREG-0877 re lequedly of applicable support structures General operating eactor roview procedure & acceptance criteria encl (SENKUT.O & Division of Licensing 80/05/20 13pp
- iduudicatory correspondence
- olio235 Response to ABLB 800327 & Q403 orders & to FES. Buppl 1 Urgas re rigorous site alternative analyses prior to further carings Recommends that Subpart II of EPA be treated as intention in proceeding NRBET.1 K. Forelaus on Board 80/05/27 App
- \$110287 Request for deferral until 800715 to respond to incorvenors proless on Board 800527 contentions Proposed contentions on the contentions of the second secon
- 1260199 Order for 600/23 probedring conference to consider propriate issues for early site suitability hearing Grants tension until 600715 for NRC to respond to Forelaus on hard & LK Narbet 600927 [1]ing DNERB.E 8 Atomic Sefety and Licensing Board Panel 80/05/23 12
- \dvisory Committee on Reactor Bafaguards reports & corruspondence
- :200610 Forwards ACRS 800306 ltr to JF Absarms re near-term CP:plications entl for info 'MHENCER.A Licensing Branch 2 80/05/30 2pp
- 006200611 Discusses ACRS 241st meeting on 800501-03 to review status of applications for near-torm CPs PLESSET.KS & ACRS Advisory Committee on Reactor Safeguards 80705706 2pp
- (ET 50-515 PEBBLE SPRINGS MUCLEAR PLANT, UNIT 2 Application/construction stage documents & correspondence
- 5230110 Advises BUR & PUR applicants of NRC decision to modify aplementation plan presented in Section 4 of NUREO-0577 re sequacy of applicable support structures, General operating sactor review procedure & acceptance criteria enc! (SENHUT,D G Division of Licensing 80/05/20 13pp
- idjudicatory correspondence
- SiiO235 Response to ASLB 800327 & 0403 orders & to FEG, Suppl 1.Urges ore rigorous site alternative analyses prior to further earings Recommends that Subpart II of EPA be treated as ontention in proceeding ARBET.L K Forelaws on Board 80/05/27 4pp

- 8006110289 Request for deferral until 800715 to respond to intervenors Forelaws on Board 800527 contentions Proposed contentions on MRC alternative sits reanalysis need to be discussed w/perties Certificate of Sv. encl 80RDENICK.8 M Hearing Branch 4 80/06/10 5pp
- BO06260199 Order for B00723 prehearing conference to consider appropriate issues for early site suitability hearing Grants extension until 600715 for NRC to respond to Forelaws on Board & LK Marbet 800827 filing BONERS.E S Atomic Serbty and Licensing Board Panel 90/06/23 19
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- BOOA200610 Forwards ACRS 800505 it; to JF Ahearne re near-term CP applications encl for info SCHWENCER.A Licensing Branch 2 80/05/30 2pp
- --8006200611 Discusses ACRS 241st meeting on B008C1-03 to review status of applications for mear-term CPs PLESET, M S ACRS Advisory Committee on Reactor Safeguards B0/09/04 2pp
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1 A Application/construction stage documents & coursespondence
- BOO6230110 Advises BWR b PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adaquacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 80/03/20 13pp
- 8006180604 Advises that NRC overcharged util for review & processing CPs Controller authorized to forward refund MILLER, W.O. License Fee Management Branch 80/06/03 1p
- H General correspondence
- B006300425 Requests verification of address Related correspondence REVELEY.W T Hunton & Williams 80/06/12 ip
- G Inspection reports, IE Bulletine & currespondence
- G006200034 forwards IE Circular 80-13, "Grid Strap Damage in Mestinghouse Fuel Assemblies " No written response required GRICR, B H Region 1, Philadelphia, Office of the Director 80/03/28 1p
- 8005240500 Responds to IE Bulletin 79-03A, "Lungitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel " All Westinghouse-supplied pipe for use on NSSS is either of forged seamless or centrifugal cask const PLASKON,R E Long Island Lighting Co 90/05/20 1p
- BOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- BOO6230110 Advises MWR & PWR applicants of NRC decision to mndify implementation pian presented in Bertion 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENMUT.D O Division of Licensing 80/05/20 13pp
- BOO6180604 Advises that NRC overcharged util for review & processing CPs Controller authorized to forward refund MILLER, W.D. License fee Management Branch 80/06/03 1p
- H General correspondence
- 8006300425 Requests verification of address Related correspondence REVELEY.N T Hunton & Williams 80/06/12 1p
- O Inspection reports. IE Bulletins & correspondence
- B006200034 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required ORIER.B H Region 1, Philadelphia. Office of the Director 80/05/28 ip

- 2006240600 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME SA-312 Type 304 Stainless Stool " All Mostinghouse-supplied pipe for use on MSSS is either of forged seamless or contrifugal cask const
 PLASKON-R E Long Island Lighting Co 80/03/28 ip
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- BOO6230110 Advises BHR & PHR applicants or NRC decision to modify implementation plan presented in Section 4 of NURLO-05/7 readequacy of applicable support structures General operating reactor review procedure & acceptance critoria encl
- Q Adjudicatory correspondence
- 8006060396 Advises that AH Gutterman will no longer appear in proceedings on behalf of util SANGER.H S Tennessee Valley Authority 80/05/19 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006030498 Forwards IE Insp Repts 50-518/80-05.50-519/80-05.50-520/80-05 & 50-521/80-05 on 800128-0229 No mancompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/22 2pp
- --8006030511 IE Insp Repts 50-518/80-05, 50-519/80-05, 30-520/80-05 & 50-521/80-05 on 800128-0229 No noncompliance noted Major aroas inspected structural concrete, steel structures & reactor vessel installation CANIRELL, F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SIAN, W B Region 2. Atlanta, Office of the Director 80/04/22 App
- 8006060159 Forwards IC Bulletin 80 ti, "Massary Wall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/05/09
- 8006040247 Forwards IE Rulletin 80-12. "Decay Heat Renoval Sys Operability "No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY.J F Region 2. Atlanta, Office of the Director 80/09/09
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Gil Cooler Failures" No written response required G'REILLY, J. P. Region 2, Atlanta, Office of the Director 90/05/13
- 8006090496 Responds to 800121 itr which transmitted IE Sulletin 80-02 Investigations revealed that feedwater spargers or thermal sleeves mfg 8/or fabricated by Marvin Engineering Co have not been purchased 3/or have not been installed in plants MILLS,L M. Tonnessee Valley Authority 60/05/21 ip
- 8006180061 Ack receipt of 800507 itr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-518/80-04, 50-519/80-04 & 50-521/80-04 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8006180064 Forwards supplemental rusponse to IC Insp Rept 50-518/80-04 Investigating all applicable welds 80P-17 & 80P-34 being revised Clarification or requirements will prevent noncompliance through misinterpretation MILLS.L M Tennesse Valley Authority 80/05/07 2pp
- --8006180068 Ack receipt of 800407 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-04, 50-519/80-04, 50-521/80-04 Supplemental rept 50-517/50-04-07-560-04 2. due by 800509 MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/20 2pp
- ---80061800/2 Responds to NRC 800317 ltr re violations noted in IE Insp Repts 50-518/80-04,50-519/80-04,50-520/80-04 & 50-821/80-04 Corrective, actions joint stamped w/low stress stamps in piping mati adjacent to welds MILLS,L M Tennessee Valley Authority 80/04/09 2pp

- --800618007/ Forwards If Insp Repts 50-518/80-04, 50-519/80-04. 50-520/80-04 & 50-521/80-04 un 800219-22 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch BO/03/17 2pp
- --8006180093 Netice of violation from insp on 800219-22 80/03/11 10
- --8006180071 IE Insp Repts 50-518/80-04.50-517/80-04.50-520/80-04 & 50-521/80-04 on 800219-22 Noncompliance noted failure to follow procedure in weld joint identification HEPDT, A 9 Region 2, Atlanta, Reactor Construction & Engineering Support Branch BLARC. J. KLEINSCROE. W Region 2, Atlanta, Office of the Director 00/03/11 7pp
- S Reportable occurrences. LERs & related correspondence
- B00A060230 Forwards CTI-Nuclear S00503 Part 21 rept re potential failurn or McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in airstream in various air filtration sys

 KENYO
- 800A0991.30 PNO-11-80-090 on B00520, while in process of pouring Unit A-1 vent wall, crame brake failed & dropped four cubic yard concrete bucket Three employees where severely injured Licenses plans to issue press release HRIOHT, R W. CANTRELLES S. Region 2. Atlanta, Office of the Director 80/05/21 ip
- B006040230 Forwards second interim dericipncy rept to unid deficiencies on tractor pressure ressel shield well Final rept should be submitted by B00926
 MILLS.L N Tennessee Valley Authority B0/05/29 lp
- BOOAOAO4O1 Forwards final deficiency rept re unacreptable bending of walded stud unchors on enbedded plates
 MILLS,L M. Tennesuee Vailey Authority 80/06/02 up
- --800660413 Final deficiency :ept re unacceptable bending of welded itudenchurs on embedded plates Tosting program was initiated Bending of stude has no significant effect on atude capacity Lists guidelines for max bending of studenchors Tannesovs Valley Authority B0/04/02 3pp Tennesses Valley Authority
- BOObiloo's Forwards first interim deficiency rept re standby gas treatment sys charconi adsorber MILLS.L M Tennessee Valley Authority 80/06/04 ip
- ---8006110058 First interim deficiency rept re standby gas treatment sys charcoal adsorbers Charcoal retention screens teperating from framus due to improper or broken spot wolds Vendor, CTI-Nuclear, investigating problem Final rept by 800920 # Tonnessec Valley Authority 80/06/04 ip
- 6006120009 Forwards interim deficiency rept re steam tunnel embedment stiffener plate weld
 MILLS,L M Tennessee Valley Authority 80/06/04 ip
- ---B006120313 Interim deficiency rept re failure by Atlas dachino & Iron Works to implement QA procedures for steam tunnel embedment stiffener plato weld Stiffener plate NCR-10 welded per QA requirements & ald for Atlas QA program contracted

 * Tonnessee Valley Authority B0/06/04 ip
- BOO6200024 Final Part 21 rept re mixed heat of steel supplied by UB Steel from which 4-inch oldows \$ 2-inch tees were mfg to A234MPB requirement investigations conducted & closed at 46 listed facilities SEAY, J.L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006200432 Forwards final deficiency rept re defective McGrau-Edison tamp detection controllers in standby gas treatment sys MILLS,L M Tennessee Valley Authority 80/06/13 ip
- ---8006200494 Final deficiency rept re defective temp detection controller in standby gas treatment sys Electronic temp detection controller failed in svc Gaused by acid flux solder sealing controls Controllers to be replaced w/certified controllers * Tennesses Valley Authority 80/06/13 2pp

- 8006250275 Forwards final deficiency rept re incorrect root face on skewed caduald sleeves MILLS.L M Tennessee Valley Authority 80/06/19 1p
- --8006290281 Final deficiency rept re incorrect root face on skewed caduald sleaves Atlas Machine & Iron Works fabricated some representative structures using same welding process as sleaves Destructive pull tests performed satisfactorily a Tennessee Valley Authority 80/06/19 2pp
- 8006250256 Second interim deficiency rept re defects in Rosemount trip/calibr units Util & QE investigations re quantity of Model 1152 pressure transmitters shipped continuing Final rept uill be submitted by 800917 NILLS.L M Tennessee Valley Authority 80/06/20 ip
- DOCKET STM-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PHR applicants of NRC decision to modify implementation plan presented in Section 4 of NURRQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria and EISENHUT.D Q Division of Licensing 80/05/20 13pp
- Q Adjudicatory correspondence
- 8006060356 Advises that AM Outterman will no longer appear in proceedings on behalf of util SANGER.H S Tennessee Valley Authority 80/05/19 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8006030498 Forwards IE Insp Repts 50-518/80-05.50-519/80-05.50-520/ 80-05 t 50-521/80-05 on 800128-0229 No mancampliance noted MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/04/22 2pp
- --8006030511 IE Insp Repts 50-518/80-05,50-519/80-05,50-520/80-05 & 50-521/80-05 on 800128-0229 No noncompliance noted Major areas inspected structural concrete,steel structures & reactor vessel installation CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SHAN,H B. Region 2, Atlanta, Office of the Director 80/04/22 Spp
- 8006060159 Forwards IE Bulletin 80-11, "Masonry Hall Design " No action or written response required IE Info Notice 79-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 3pp
- 8006040227 Forwards IE Bulletin BO-12, "Decay Heat Removal Bys Operability " No written response required. IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/05/09 3pp.
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Luba Oil Cooler Failures " No written response required O'REILLY, J. F. Region 2, Atlanta, Office of the Director 80/05/13
- 8006090456 Responds to 800121 ltr which transmitted IE Bulletin 80-02 Investigations revealed that feedwater spargers or thermal sleeves mfg &/or fabricated by Hervin Engineering Co have not been purchased &/or have not been justalled in plants HILLS-L M Tennessee Valley Authority 80/05/21 ip.
- 8006180066 Ack receipt of 800507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-04, 50-519/80-04, 50-520/80-04 50-520/80-04 NRF8/Y.C.E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8006:80064 Forwards supplemental response to IE Insp Rept 50-588/80-04 Investigating all applicable welds BOP-17 & 60P-34 being revised Clarification of requirements will prevent noncompliance through misinterpretation RILLB.L M Tennessee Valley Authority 80/05/07 2pp

- --R00A18006B Act leceipt of 800409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-04, 30-519/80-04, 50-520/80-04 & 50-521/80-04 Supplemental rept due by 800509 MNRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/28 2pp
- ~-8006/80072 Responds to NRC 800317 ltr re violations noted in IE lnsp Repts 50-518/80-04,50-519/80-04,50-520/80-04 & 50-521/80-04 Corrective actions joint stamped w/low stress stamps in piping matl adjacent to welds MILLS,L M Tennessee Valley Authority 80/04/09 2pp
- --8006180077 Forwards IE Insp Repts 50-518/80-04,50-519/80-04, 50-520/80-04 & 50-921/80-04 on 800219-22 & notice of violation IRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/17 2pp
- --8006180083 Notice of violation from insp on 800219-22
 * Resign 2, Atlanta, Office of the Director 80/03/11 ip
- --B0061B0091 IE Insp Repts 90-518/80-04.50-519/80-04.50-520/80-04 & 50-521/80-04 on B00219-22 Noncompliance noted failure to follow procedure in weld joint identification HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch BLAKE. J. KLEINSORGE, W Region 2. Atlanta, Office of the Director B0/03/11 7pp
- S Reportable occurrences. LERs & related correspondence
- 8006060230 Forwards CTI-Nuclear 800503 Part 21 rept re potential failure of McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in airstream in various air filtration sys
 KENYON, M Tennessee Valley Authority 80/05/08 4pp
- 8006060401 Forwards final deficiency rept re unacceptable bending of welded stud anchors on embedded plates
 MILLS.L. M. Tennessee Valley Authority 80/06/02 ip
- --8006060413 Final deficiency rept re unacceptable bending of welded st anchors on embedded plates Testing program was initiated Bending of studs has no significant effect on stud capacity Lists guidelines for max bending of stud anchors * Tennessee Valiey Authority 80/06/02 3pp
- 8006110048 Forwards first interim deficiency rept re standby gas treatment sys charcoal adapter MILLS.L K Tennesser Valley Authority 80/06/04 ip
- --8006110059 First interim deficiency rept re standby gas treatment sycharcoal adsorbers Charcoal retention screens separating from frames due to improper or broken spot welds Vandor. CTI-Nuclear.investigating problem Final rept by 800820 * Tennessee Valley Authority 80/06/04 ip
- 8006120309 Forwards interim deficiency rept re steam tunnel embedment stiffener plate weld
 MILLB.L M Tennessee Valley Authority 80/06/04 ip
- --8006120313 Interim deficiency rept re failure by Atlas Machine & Iro Works to implement QA procedures for steam tunnel embedment stiffener plate weld Stiffener plate NCR-10 welded per QA requirements & aid for Atlas QA program contracted * Tennessee Valley Authority 80/06/04 ip
- 8006200024 Final Part 21 rept rs mixed heat of steel supplied by US Steel from which 4-inch albows & 2-inch tees were mfg to A234WPB requirement Investigations conducted & closed at 46 listed facilities SEAY,J L Chemtron Corp , Tube Turns Div 80/06/06 3pp ,
- 8006200432 Forwards final deficiency rept re defective McGraw-Edison temp detection controllers in standby gas treatment sys MILL8,L M Tennessee Valley Authority 80/06/13 1p
- ---8006200454 Final deficiency rept re defective temp detection control in standby gas treatment sys Electronic temp detection controller failed in svc Caused by acid flux solder sealing controls Controllers to be replaced w/certified controllers * Tennessee Vailey Authority 80/06/13 2pp
- 8006230278 Forwards final deficiency rept re incorrect root face on skewed cadweld sleeves MILLB.L M Tennessee Valley Authority 80/06/19 1p

- --800625028i Final deficiency rept re incorrect root face on skewed cadweld sleeves Atlas Machine & Iron Works fabricated some representative structures using same welding process as sleeves Destructive pull tests parformed satisfactorily * Tennessee Valley Authority 80/06/19 2pp
- 8006250256 Second interim deficiency rept re defects in Rosemount trip/calibr units Util & OE investigations re quantity of Model 1152 pressure transmitters shipped continuing Final rept will be submitted by 800917 MILLS
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp
- Q Adjudicatory correspondence
- 8006060356 Advises that AH Gutterman will no longer appear in proceedings on behalf of util SANGER, H S Tennessee Valley Authority 80/05/19, 3pp
- G Inspection reports: IE Bulletins & correspondence
- 8004030498 Forwards IE Insp Repts 50-519/80-05.50-519/80-05.50-520/ 80-05 & 30-521/80-05 on 800128-0229 No noncompliance noted MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/04/22 2pp
- ---B006030511 IE Insp Repts 30-518/80-05, 30-519/80-05, 50-520/80-05 & 50-521/80-05 on B00128-0229 No noncompliance noted Major areas inspected structural concrete, steel structures & reactor vessel installation CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SWAN, W B Region 2, Atlanta, Office of the Director B0/04/22 6pp
- 8006060157 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 77-28, "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006040267 Forwards IE Bulletin 80-12, "Decay Heat Removal Sys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/07
- 8006120034 Forwards IE Circular 80-ii, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- 8006090486 Responds to 800121 itr which transmitted IE Builetin 80-02 Investigations revealed that feedwater spargers or thermal sleeves mfg &/or fabricated by Marvin Engineering Co have not been purchased &/or have not been installed in plants MILLS,L M Tennesses Valley Authority 80/05/21. ip.
- 8006180061 Ack receipt of 800507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-519/80-04, 50-520/80-04 \$50-521/80-04 MXRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/21 2ps
- --8006180064 Forwards supplemental response to IE Insp Rept 50-518/80-04. Investigating all applicable welds 80F-17 & 50F-34 being revised Clarification of requirements will prevent noncompliance through misinterpretation MILLS.L. M Tennesses Valley Authority 80/05/07 2pp.
- --8006180068 Ack receipt of 800409 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/80-04, 50-519/80-04, 50-521/80-04 & 50-521/80-04 Supplemental rept due by 800509 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/28 2pp

- --B0061B0072 Responds to NRC B00317 ltr re violations noted in IE Insp Repts 50-51B/80-04.50-519/80-04.50-520/80-04 & 50-521/80-04 Corrective actions joint stamped w/low stress stamps in piping matl adjacent to welds MILLB,L M Tennessee Valley Authority B0/04/09 2pp
- --8006180077 Forwards IE lnsp Repts 50-518/80-04.50-519/80-04.
 50-520/80-04 & 50-521/80-04 on 800219-22 & notice of violation BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/17 2pp
- --B0061800B3 Notice of violation from insp on 800219-22
 * Region 2, Atlanta, Office of the Director 80/03/11 is
- --8006180091 IE Insp Repts 50-518/80-04, 50-519/80-04, 50-520/80-04 & 50-521/80-04 on 800219-22 Noncompliance noted failure to follow procedure in weld joint identification HERDT, A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAKE, J. KLEINSORGE, H Region 2, Atlanta, Office of the Director 80/03/11 7pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006040230 Forwards CTI-Nuclear 800503 Part 21 rept re potential failure of McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in airstream in various air filtration sys KENYON, M Tennessee Valley Authority. 80/05/08 4pp
- 8006060401 Forwards final deficiency rept re unacceptable bending of welded stud anchors on embedded plates
 MILLS.L. M Tennessee Valley Authority 80/06/02 1p
- --8006060413 Final deficiency rept re unacceptable bending of welded stud anchors on embedded plates Testing program was initiated Bending of studs has no significant effect on stud capacity. Lists guidelines for max bending of stud anchors * Tennessee Valley Authority 80/05/02 3pp
- 800611004B Forwards first interim deficiency rept re standby gas treatment sys charcoal adsorber MILLS, L. H. Tennessee Valley Authority 80/06/04 ip.
- --8006110058 First interim deficiency rept re standby gas treatment sys charcoal adsorbers Charcoal retention screens separating from frames due to improper or broken spot welds, Vendor, CTI-Nuclear, investigating problem Final rept by 800820 * Tennessee Valley Authority 80/06/04 ip,
- 8006120309 Forwards interim deficiency rept re steam tunnel embedment stiffener plate weld MILLS.L K Tennessee Valley Authority 80/06/04. ip.
- ---8006i203i3 Interim deficiency rept re failure by Atlas Machine & Iron Works to implement GA procedures for steam tunnel embedment stiffener plate weld Stiffener plate NCR-10 welded per GA requirements & aif for Atlas GA program contracted * Tennessee Valley Authority 80/06/04 ip.
- 8006200024 Final Part 21 rept re mixed heat of ateel supplied by US Btael from which 4-inch elbows & 2-inch tees were mfg to A234WE requirement Investigations conducted & closed at 46 listed facilities SEAY.J L. Chemtron Corp , Tube Turns Div 80/06/06. 3pp
- 8006200432 Forwards finel deficiency rept re defective McGraw-Edison temp detection controllers in standby gas treatment sys MILLS.L M Tennessee Valley Authority 80/06/13 ip.
- ---8006200484 Final deficiency rept re defective temp detection controller in standby gas treatment sys Electronic temp detection controller failed in svc Gaused by Acid flux solder sealing controls Controllers to be replaced w/certified controllers * Tennessee Valley Authority 80/06/i3 2pp
- 8006250256 Second interim deficiency rept re defects in Rosemount trip/ calibr units Util & OE investigations re quantity of Model 1152 pressure transmitters shipped continuing final rept will be submitted by 800917 MILL8/L M Tannessee Valley Authority 80/06/20 ip.

- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PWR applicants of NAC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance Criteria encl EISCHMUT.D G Division of Licensing 80/05/20 13pp
- G Adjudicatory correspondence
- 8006040356 Advises that AH Gutterman will no longer appear in proceedings on behalf of util SANGER. H S Tennessee Valley Authority 80/05/19 3pp
- G Inspection reports. IE Bulletins & correspondence
- 8004030498 Forwards 1E Insp Repto 50-518/80-05, 50-519/80-05, 50-520/80-05 & 50-521/80-05 on 800128-0229 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 30/04/22 2pp
- --8006030511 IE Insp Repts 50~518/80~05.50~519/80~05.50~520/80~05 & 50~521/80~05 on 800128~0229 No noncompliance noted Major areas inspected structural concrete, steel structures & reactor vessel installation GANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/22 App
- 8006060139 Forwards IE Builetin 60-11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Quarloading of Structural Elements Due to Pipe Bupport Loads" encl
 O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/08
- 8006040267 Forwards IE Bulletin 80-12, "Decay Heat Removal Bys Operability " No written response required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 Mille in Refueling Mode" encl 6/REILLY, J P Region 2, Atlanta, Office of the Director 80/05/09
- 8006;20034 Forwards IE Circular 80-11, "Emergency Diesel Concrator Lube Oil Cooler Failures" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 3bp
- .306.090456 Responds to 800121 itr which transmitted IE Bulletin 80-02 Investigations revealed that feedwater spargers or thermal slaves mfg &/or fabricated by Marvin Engineering Co have not been purchased &/or have not been installed in plants HILLS:I. H Tennessee Valley Authority 80/05/21 ip
- 8006180061 Act receipt of 800307 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-518/80-04. 50-519/80-04, 50-529/80-04 & 50-521/80-04 MURPHY, C C Region 2. Attanta. Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --B004iB0044 Forwards supplemental response to IE Inap Rept 50-318/B0-04 Investigating all applicable welds, 80P-17 & 80P-34 being revised Clarification of requirements will prevent nancompilance through misinterpretation MILLS.L. M. Tennessee Valley Authority 80/05/07 2pp
- --8006180068 Ack receipt of 800409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-918/80-04, 50-519/80-04, 80-520/80-04 & 50-521/80-04 Supplemental rept dum by 800509 HURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/28 2pp

- --B006180091 IE Insp Repts 50-518/80-04, 50-519/80-04, 50-520/80-04 & 50-521/80-04 on 800219-22 Noncompliance noted failure to follow procedure in weld joint identification HERDTIA R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/11 7pp
- 8 Reportable occurrences, LERs & related correspondence
- 8006060230 Forwards CTI-Nuclear 800503 Part 2t rept re potential failure of McGraw Edison device used in CTI-Nuclear electronic control carcuit for detecting high temps in airstream in various air filtration sys KENYUN.M Tennessee Valley Authority 80/05/08 4pp
- 8005050401 Forwards final deficiency rept re unacceptable bonding of walded stud anchors on embedded plates
 MILLS:L M Tennessee Valley Authority 80/06/02 1p
- --8006060413 Final deficiency rept re unacceptable bending of welded stud anchors on embedded plates Testing program was initiated Bending of studs has no significant effect on stud capacity Lists guidelines for max bending of stud anchors * Tennessee Valley Authority 80/06/02 3pp
- 8006110048 Forwards first interim deficiency tept re standby gas treatment sys charcoal adsorber MILLS.L M Tennessee Valley Authority 80/06/04 Ip
- --8006110058 First interim deficiency rept re standby gas treatment sys charcoal adsorbers Charcoal retention screens separating from frames due to improper or broken spot welds Vendor. CTI-Nuclear-investigating problem Final rept by 800820 * Tennessee Valley Authority 60/06/04 1p
- B0D6120309 Forwards interim deficiency rept re steam tunnel embedment stiffener plate weld MILLS:L M Tennessee Valley Authority 80/06/04 1p
- --B006i203i3 Interim deficiency rept re failure by Atlas Machine & Iron Works to implement GA procedures for steam tunnel ambadment stiffener plate weld Stiffener plate NCR-10 welded per GA requirements & aid for Atlas GA program contracted * Tennessee Vailey Authority 80/06/04 Ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities
 SEAY.J L. Chemtron Corp., Tube Turns Div. 80/06/06 3pp
- 8006200432 Forwards final deficiency rept re defective McGraw-Edison temp detection controllers in standby gas treatment sys MILLS.L M Tennessee Valley Authority 80/06/13 ip
- ---8006200454 Final deficiency rept re defective temp detection controller in standby gas treatment sys Electronic temp detection controller failed in svc Caused by acid flux solder sealing controls Controllers to be replaced w/certified controllers * Tennessee Vailey Authority 80/06/13 2pp
- 8006250256 Second interim deficiency rept re defects in Resembent trip/ calibr units Util & OE investigations re quantity of Model 1152 pressure transmitters shipped continuing Final rept will be submitted by 800917 MILLS.L M Tennessee Valley Authority 80/06/20 ip
- DOCKET STN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

 A Application/construction stage documents & correspondence
- 8006090143 Requests info re composition of open cooling sys Advises that Bkagit Tribes concorn about toxicity at diffusers have intensified BUBCH.R W Evergreen Legal Services 80/01/29 ip
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-057/ re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D & Division of Licensing 80/05/20 13pp

G. Adjudicatory correspondence

- 800o060297 Notion to dismiss application w/prejudice Applicants took no steps to pursue application despite opportunity given at 800122 conference to address pending geology & solomology issues Certificate of Svc encl LEED, R M Skagitonians Concerned About Nuclear Power LEED, R M Lead, R M 80/05/08 5pp
- R006060328 Forwards monthly status rept for May 1/80 consisting of util reply in apposition to infervenum, Skagitonians Concerned About Nuclear Puwer motion to Jismiss const application & JE Necca afridayst U/o encl.
 THO
- 8006180181 Reply in opposition to Skagitonians Concerned About Nuclear Power 800508 motion to dismiss application u/prejudice due to lack of diligent pursuit Applicants are engaged in extensive program to locate suitable site THOMSEN, FT Puget Sound Power & Light Co THOMSEN, FT Perkins, Core, Stone, Olsen & Williams 80/05/23 5pp
- 8006180185 Affidavit in support of applicants' reply objecting to Skagitonians Concerned About Murlear Power 800508 motion to dismiss application Explains applicants' efforts to locate suitable site Certificate of Sic encl MECCA, J. E. Puget Sound Power & Light Co. 80/05/23 6pp
- 8006030213 Submits second status rept re Skagit application & continuing review efforts by RRC / USGS No progress made re respective review functions Change in proposed site is being considered by applicants Updated info will be provided BLACK, R L Hearing Branch 1 80/05/30 2pp
- BOO6190447 Reply withdrawing DO0508 motion to dismiss application Applicant response to motion & Mecca affidavit provided detailed info re applicant BO0414 rept Progress rept must be filed by DO0601 by applicant Certificate of Bvc encl GENDLER.II W . LEED.R M . Skagftonians Concerned About Nuclear Power GENDLER.II W . Leed.R M . BO706704 . Spp.
- B006180411 Arcepts 800630 as date for submittal of NRC & applicants' repts continuing Apr-May responses to Paragraph 14 C of ABLB 800306 order
 DEALE, V B Atomic Safety and Licensing Board Panel B0/06/13 lp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B006170385 Forwards 800506 ltr from ACRS to Commissioner Ahearne re near-term CP applications for info & use SCHWENCER.A Licensing Branch 2 80/05/30 2pp
- DOCKET STN-50-929 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 A Application/construction stage documents & correspondence
- 8006070143 Requests info ie composition of open cooling sys Advises that Skagit Tribes concern about toxicity at diffusers have intensified BUSCH,R W Evergreen Legal Services 80/01/29 ip
- 8006230110 Advises DWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp

G Adjudicatory correspondence

- 8006060297 Motion to dismiss application w/prejudice Applicants took no steps to pursue application despite opportunity given at 800122 conference to address pending geology & seismology issues Certificate of Svc encl
 LEED.R M Skagitonians Concerned About Nuclear Power LEED.R M
 Leed.R M 80/05/08 5pp
- 8006060328 Forwards monthly status rept for May 1980 consisting of util reply in opposition to intervenor. Skagitonians Concerned About Nuclear Power motion to dismiss const application & JE Mecca affidavit W/o encis
 THOMSEN.F T Perkins, Coie, Stone, Disen & Williams 80/05/23
 3pp

- 8006180181 Reply in apposition to Skagitanians Concerned About Nuclear Power 800988 motion to dismiss application whyre judice due to lack of diligent pursuit Applicants are engaged in extensive program to locate suitable site THOMBEN.F T Puget Sound Power & Light Co THOMBEN.F T Perkins. Coie. Stone. Disen & Williams 80/05/23 Spp
- ---8004180185 Affidavit in support of applicants' reply objecting to Skagitonians Concerned About Nuclear Power 800508 motion to dismiss application Explains applicants' efforts to locate suitable site Certificate of Svc enci MECCA.J E Puget Sound Power & Light Co 80/05/23 App
- 8006030213 Submits second status rept re Skagit application & continuing review efforts by NRC 2 USGS No progress made re respective review functions Change in proposed site is being considered by applicants Updated info will be provided BLACK-P L Hearing Branch I 60/05/36 2pp
- B006190447 Reply withdrawing 800508 motion to dismiss application Applicant response to motion & Merca affidovit provided detailed into the applicant B00414 rept Progress rept must be filled by 800601 by applicant Certificate of Svc oncl GENDLER(II W. LEED,R.M. Skagitonians Concerned About Nuclear Power GENDLER(II W. Leed,R.M. 80/06/04 bpp
- 8006180411 Accepts 800630 as date for submittal of NRC & applicants' repts continuing Apr May responses to Paragraph 14 C of ASLB 800306 order

 DEALE, V B Atomic Safety and Licensing Board Panel 80/06/13 in
- DEALETA B MEDMIC SHARES BUG CICRUSTIS BOARD BUSING BOARD BOARD BOARD BOARD
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8006170385 Forwards 800506 ltr from ACRB to Commissioner Abserve re near-term CP applications for info 5 use 8CHMENUER:A Licensing Branch 2 80/05/30 2pp
- DOCKET BIN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BMR & PMR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT,D G Division of Licensing 80/05/20 13pp
- 8006240232 Advises that NRC & industry should develop improved procedures for expediting license applications Buggests meeting w/applicant & vendors for expeditious review of systemsign decisions
 EISENHUT.D 0 Division of Licensing 80/06/10 ip
- --8006240236 Notification of 800709-10 meeting w/util in Bethesda, MD to participate in review of ac power sys KERRIGAN.J Licensing Branch 2 80/06/10 1p
- 8006300185 Recommends that station application be accepted for docketing Application is about 90% complete & some sections of FEAR & environ rept are complete TEDESCO.R L. Assistant Director for Licensing 80/06/16 ip
- 8006230676 Forwards application for DL VAN BRUNTLE E Arizona Public Service Co 80/06/19 1p
- --8006230680 Application for DL * Arizona Public Service Co 80/06/19 260pp
- 8006230693 Forwards "TMI-2 Lessons Learned Implementation Rept " VAN BRUNT,E E Arizona Public Service Co 80/06/19 150pp
- C Utility Environmental Report (ER), amends & correspondence
- 8004230686 Forwards environ rept.Vols 1-4 VAN BRUNT.E E Arizona Public Service Co 80/06/19 1p
- --8006230692 Environ rept.Vol 1 of 4 * Arizona Public Service Co 80/06/19 300pp
- --8006230697 Environ rept, Vol 2 of 4

 * Arizona Public Service Co 80/06/19 500pp
- --8006230702 Environ rept.Vol 3 of 4 * Arizona Public Service Co 80/06/19 500pp

- --8006230705 Environ rept.Vol 4 of 4 * Arizona Public Service Co 80/06/19 500pp
- F Security, medical, emergency & fire protection plans
- 8006230691 Forwards emergency plan
 VAN BRUNT,E E Arizona Public Service Co 80/06/19 ip
- --8006230696 Emergency plan
 # Arizona Public Service Co 80/06/19 140pp
- Q Adjudicatory correspondence
- 8006260158 Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental environ statements on Class 9 accidents at Diablo Canyon, Rancho Seco & Palo Verde DENTON-M R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --B006260159 Responds to 791024 petition requesting preparation of supplemental EIS re impact of Class 9 accidents at facilities No special circumstances exist which would warrant reopening proceedings Request denied DENTION.H R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8006260161 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS on Class 9 accidents No special circumstances exist which would warrant recycling environ proceedings DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/19 17pp
- --8006260163 Notice of issuance of Director's decision per 2 204 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents DENTON.H R Dffice of Nuclear Reactor Regulation, Director 80/06/19 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8006230673 Chapter 1 of Palo Verde FSAR. "Introduction & General Discription of Plant " Includes Revision 1 • Arizona Public Service Co 80/03/31 150pp
- 8006230577 Chapter 2 of Palo Verde FSAR, "Site Characteristics "
 # Arizona Public Service Co 80/06/19 500pp
- 8006230683 Chapter 3 of Palo Verde FSAR, "Design of Structure, Components Equipment & Sys "
 • Arizona Public Service Co 80/06/19 600pp

8006230694 Forwards FSAR, Vols 1-10 VAN BRUNT, E E Arizona Public Service Co 80/06/19 ip

- 8006230688 Chapter 4 of Palo Verde FSAR, "Reactor "
 # Arizona Public Service Co 80/06/19 20pp
- .
- --8006230698 FSAR, Vals 1-10 Includes Revision I * Artiona Public Service Ca 80/03/31 310pp
- BO06230695 Chapter 5 of Palo Verde FSAR, "RCS & Connected Bys " + Arizona Public Service Co 80/06/19 60pp
- 8006230701 Chapter 6 of Palo Verde FSAR, "Engineered Safety Features "
 Arizona Public Service Co 80/06/19 300pp
- 8006230703 Chapter 7 of Palo Verde FSAR, "Instrumentation & Controls "
 * Arizona Public Service Co 80/06/19 140pp
- 8006230710 Chapter 8 of Palo Verde FSAR, "Electric Power" * Arizona Public Service Co 80/06/19 150pp
 - ziliary Sys "
 - Steam & Power Conversion
 - 15000
 - Radwaste Mgt "

- 8006230716 Chapter 12 of Palo Verde FSAR, "Radiation Protection " * Arizona Public Service Co 80/06/19 100pp
- B006230717 Chapter i3 of Palo Verde FSAR. "Conduct of Operations " * Arizona Public Service Co 80/06/19 60pp
- 8006230718 Chapter 14 of Palo Verde FSAR, "Initial Test Program" * Arizona Public Service Co 80/06/19 20pp
- 8006230720 Chapter 15 of Palo Verde FSAR, "Accident Analysis "
 * Arizona Public Service Co 80/06/19 40pp
- 8006230721 Chapter 16 of Palo Verde FSAR, "Tech Bpecs " * Arizona Public Service Co 80/06/19 130pp
- 8006230722 Chapter 17 of Palo Verde FSAR, "GA "
 * Arizona Public Service Co 60/06/19 30pp
- Q Inspection reports, IE Bulletins & correspondence
- 800A250187 Forwards IE Insp Repts 50-528/80-04,50-529/80-04 & 50-530/80-04 on B00201-28 No noncompliance noted SPENCER, O S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/02 2pp
- ---8006250192 IE Insp Repts 50-528/80-04,50-529/80-04 & 50-530/80-04 on 800201-28 No moncompliance noted Major areas inspected containment bldg concrete; polar crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement DUDDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch VORDERBRUGGEN Region 5, San Francisco, Office of the Director 80/05/01 App
- S Reportable occurrences, LERs & related correspondence
- 8006030351 Advises that commitment made in 800324 preliminary deficiency rept will not be met Info from qualification testing will not be available within 60 days, due to implementation difficulties Info finalized by 800801 VAN BRUNT, E E Arizona Public Service Co 80/05/23 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234MPB requirement Investigations conducted & closed at 46 listed facilities SEAY.J L Chemtron Corp . Tube Turns Div 80/06/06. 3pp
- T Hearing transcripts on non-antitrust matters
- 8006110308 Forwards 800508 sys review transcript re Class IE power sys Review held before Power Sys Review Board in Phoenix, AZ Pp 1-179. VAN BRUNT, E E Arizona Public Service Co 80/06/04 200pp
- DOCKET STN-50-927 PALO VERDE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp
- BOD6240232 Advises that NRC 5 industry should develop improved procedures for expediting license applications Suggests meeting w/applicant 5 vendors for expeditious review of sysdesign decisions
 EISENHUT, D © Division of Licensing 80/04/10 ip
- --8006240236 Notification of 800709-10 meeting w/util in Bethesda.MD to participate in review of ac power sys KERRIGAN.J Licensing Branch 2 80/06/10 ip
- 8006300185 Recommends that station application be accepted for docketing Application is about 90% complete & some sections of FSAR & environ rept are complete TEDESCO,R L Assistant Director for Licensing 80/06/16 1p
- 8006230676 Forwards application for CL.
 VAN BRUNT, E E Arizona Public Service Co 80/06/19 ip
- --8006230680 Application for DL * Arizona Public Service Co 80/06/19 260pp

- 8006230693 Forwards "TMI-2 Lessons Learned Implementation Rept " VAN BRUNT.E E Arizona Public Service Co 80/06/19 150pp
- C Utility Environmental Report (CR), amends & correspondence
- 8006230686 Forwards environ rept. Vols 1-4
 VAN BRUNT, E E Ariiona Public Service Co 80/06/17 1p
- --B006230692 Environ rept.Vol 1 of 4 + Arizona Public Service Co 80/06/19 300pp
- --8006230697 Environ rept. Vol 2 of 4 * Arizona Public Service Co 80/06/19 500pp
- --8006230702 Environ rept. Vol 3 of 4

 * Arttona Public Service Co 80/06/19 500pp
- --8006230705 Environ rept. Vol 4 of 4
 * Arizona Public Service Co 80/06/19 500pp
- F Security, medical, emergency & fire protection plans
- 8006230671 Forwards emergency plan
 VAN BRUNT, E. E. Arizona Public Service Co. 80/06/19 1p
- ---8006230696 Emergency plan
 * Arizona Public Service Co 80/06/19 140pp
- G Adjudicatory correspondence
- B006260158 Forwards Director's decision per 2 206 & FR notice in response to Friends of the Earth 791024 petition to require preparation of supplemental environ statements on Class 9 accidents at Diablo Canyon.Rancho Seco & Palo Verde DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/19 2pp
- --8006260159 Responds to 791024 petition requesting preparation of supplemental EIB re impact of Class 9 accidents at facilities No special circumstances exist which would warrant reopening proceedings Request denied DENTOR.H R Office of Nuclear Reactor Regulation. Director 80/06/19 2pp
- --B006260161 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIB on Class ? accidents No special circumstances exist which would warrant reopening environ proceedings DENTON, H R Defice of Nuclear Reactor Regulation, Director B0/06/19 17pp
- ---8006260169 Notice of issuance of Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/19 200
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8006230673 Chapter 1 of Palo Verde FSAR. "Introduction & General Description of Plant " Includes Revision 1 * Arizona Public Service Co 80/03/31 150pp
- 8006230677 Chapter 2 of Palo Verde FBAR. "Bite Characteristics "
 * Arizona Public Service Co 80/06/19 500pp
- 8006230683 Chapter 3 of Palo Verde FSAR, "Design of Structure, Components Equipment & Sys "
 * Arizona Public Service Co 80/06/19 600pp
- 8006230688 Chapter 4 of Palo Verde FSAR, "Reactor " * Arizona Public Service Co 80/06/19 20pp
- 8006230694 Forwards FBAR, Vols 1-10 VAN BRUNT, E Arizona Public Service Co 80/06/19 ip
- ~~8006230698 F8AR. Vols 1-10 Includes Revision 1 * Arizona Public Service Co 80/03/31 310pp
- 8006230695 Chapter 5 of Palo Verde FSAR, "RCS & Connected Sys "
 * Arizona Public Service Co 80/06/19 60pp

- 8006230701 Chapter 6 of Palo Verde FSAR. "Engineered Safety Features" * Arizona Public Service Co 80/06/19 300pp
- 8006230703 Chapter 7 of Palo Verde FSAR. "Instrumentation & Controls "
 * Artiona Public Service Co 80/06/19 140pp
- 8004230710 Chapter 8 of Paio Verde FSAR, "Electric Power" * Arizona Public Service Co 80/06/19 150pp
- 8004230711 Chapter 9 of Palo Verde FSAR, "Auxiliary Sys "
 4 Arizona Public Service Co 80/06/19 600pp
- 8006230713 Chapter 10 of Pain Verde FSAR. "Steam & Power Conversion Sys " * Arizona Public Service Co 80/06/19 150pp
- 8005230714 Chapter II of Palo Verde #SAR, "Radwaste Mgt"

 * Arizona Public Service Co 80/06/19 120pp
- 8006230716 Chapter 12 of Palo Verde FSAR, "Radiation Protection "
 * Arizona Public Service Co 80/06/19 100pp
- 8004230717 Chapter 13 of Palo Verde FSAR, "Conduct of Operations" * Arizona Public Service Co 80/06/19 60pp
- 8006230718 Chapter 14 of Palo Verde FSAR. "Initial Test Program" * Arizona Public Service Co 90/06/17 20pp
- 8006230720 Chapter 15 of Palo Verdo FSAR, "Accident Analysis" * Arizona Public Service Co 80/06/19 40pp
- 8006230721 Chapter 16 of Palo Verde FBAR, "Tech Specs " * Arizona Public Service Co 80/06/19 130pp
- 8006230722 Chapter 17 of Palo Verde FSAR, "GA" * Arizona Public Bervice Co 80/06/19 30pp
- G Inspection reports: IE Bulletine & correspondence
- 8006250187 Forwards IE Insp Repts 50-528/80-04,50-529/80-04 & 50-530/80-04 on 800201-28 No noncompilance noted SPENCER,0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch, 80/05/02 2pp
- --800A250192 IE Insp Repts 50-528/80-04,50-529/80-04 & 50-530/80-04 on 800201-28 No noncompliance noted Major areas inspected containment bldg concrete, polar crane support girders, reactor vessel supports & auxiliary bldg wall reinforcement DODDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch VORDERBRUGGEN Region 5, San Francisco, Office of the Director 80/05/01. 4pp
- B Reportable occurrences, LERs & related correspondence
- 8006030391 Advises that commitment made in 800324 preliminary deficiency rept will not be met Info from qualification testing will not be available within 60 days, due to implementation difficulties Info finalized by 800801 VAN BRUNT, E. & Arizona Public Service Co. 80/05/23 2pp
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch olbows & 2-inch tees were mfg to A234MPS requirement Investigations conducted & closed at 45 listed facilities SEAY, J.L. Chemtron Corp., Tube Turns Div. 80/06/06. 3pp.
- T Hearing transcripts on non-antitrust matters
- 8006110308 Forwards 800508 sys review transcript re Class IE power sys Review held before Power Sys Review Board in Phoenix.AZ Pp 1-179 VAN BRUNT, E Arizona Public Service Co 80/06/04 200pp.
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20. 13pp

- 8006240232 Advises that NRC & Industry should develop improved procedures for expediting license applications Suggests meeting w/applicant & vendors for expeditious review of systemsing decisions
 EISENHUT.D G DI/ision of Licensing 80/06/10 lp
- --B006240236 Notification of 900709-10 meeting w/util in Bethesda.MD to participate in review of ac power sys KERRIGAR, J. Licensing Branch 2 80/06/10 1p
- 8006300185 Recommends that station application be accepted for docketing Application is about 90% complete & summ sections of PSAR & environ mept are complete TEDESCO.R L. Assistant Director for Licensing 80/06/16 ip
- 8006230676 Forwards application for OL VAN BRUNT, E E Arizona Public Service Co 80/06/19 ip
- --8006230680 Application for OL * Arizona Public Service Co 80/06/19 260pp
- 8006230693 Forwards "TMI-2 Lessons Laarned Implementation Rept " VAN BRUNTLE E Arizona Public Service Co 80/06/19 150pp
- C Utility Environmental Report (ER), amends & correspondence
- 8006230686 Forwards environ rept. Vols 1-4 VAN BRUNT, E E Arizona Public Service Co 80/06/19 1p
- --8006230692 Environ rept, Vol 1 of 4 * Aritona Public Service Co 80/06/19 300pp
- --8006230697 Environ rept, Vol 2 of 4 * Arizona Public Service Co 80/06/19 500pp
- --8005230705 Environ rept.Vol 4 of 4
 * Arizona Public Service Co 80/05/19, 500pp
- F Security, medical, emergency & fire protection plans
- 8006230691 Forwards emergency plan
 VAN BRUNTLE E Arizona Public Service Co 80/06/19 ip
- Adjudicatory correspondence
- 8006260198 Forwards Director's Secision per 2 206 & FR notice in response to Friends of the Earth 791024 patition to require preparation of supplemental environ statements on Class 9 accidents at Diablo Canyon, Rancho Seco & Palo Verde DENTON, H R Gffice of Nuclear Reactor Regulation, Director 80/06/19 2pp
- --8005250157 Responds to 791024 petition requesting preparation of supplemental EIB re impact of Class 9 accidents at facilities No special circumstances exist which would warrant reopening proceedings. Request denied DENION. HR Office of Nuclear Reactor Regulation, Director 80/06/19, 2pp
- ~-8006260161 Director's decision per 2 206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIB on Class 9 accidents No special circumstances exist which would warrent reopening environ proceedings DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/19 17pp
- --B006260163 Notice of issuance of Director's decision per 2.206 denying Friends of the Earth 791024 petition to require preparation of supplemental EIS re Class 9 accidents.

 DENTON: HR Office of Nuclear Reactor Regulation, Director 80/06/19 2pp
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 8006230673 Chapter i of Palo Verde FSAR, "Introduction & General Description of Plant." Includes Revision i # Arizona Public Service Co 80/03/31 150pp

- BO06230677 Chapter 2 of Palo Verde FSAR. "Site Characteristics "

 * Arizona Public Service Co 80/06/19 500pp
- BO06230693 Chapter 3 of Palo Verde FSAR. "Design of Structure. Components.Equipment \$ Sys " * Arizona Public Service Co 80/06/19 600pp
- 8006230688 Chapter 4 of Palo Verde FSAR, 'Reactor "
 Anizona Public Service Co 80/06/19 20pp
- 8006230694 Forwards FSAR.Vols 1-10
 VAN BRUNT, E.E. Arizona Public Service to 80/06/19 1p
- --8006230698 FSAR, Vals 1-10 Includes Revision 1

 * Arizona Public Service Co 80/03/31 310pp
- 8006230695 Chapter 5 of Palo Verde FSAR, "RCS & Connected Sys "
 Anizona Public Service Co 80/06/19 60pp
- 8006230701 Chapter 6 of Palo Verde FSAR, "Engineered Safety Features"

 * Arizona Public Service Co 80/06/19 300pp
- 8006230703 Chapter 7 of Palo Verde FSAR. "Instrumentation & Controls "

 * Arizona Public Service Co 80/06/19 140pp
- 8006230710 Chapter 8 of Palo Verde FSAR, "Electric Power" * Arizona Public Service Co 80/06/19 150pp
- 8006230711 Chapter 9 of Palo Verde FSAR, "Auxiliary Sys" * Arizona Public Service Co 80/06/19 600pp
- 8006230713 Chapter 10 of Paio Verde FSAR, "Steam & Power Conversion Sys " * Arizona Public Service Co BO/06/19 150pp
- 8006230714 Chapter 11 of Palo Verde FSAR. "Radwaste Mgt " * Arizona Public Service Co 80/06/19 120pp
- 8006230716 Chapter 12 of Palo Verde F5AR, "Radiation Protection " * Arizona Public Service Co 80/06/19 100pp
- 8006230718 Chapter 14 of Palo Verde FSAR. "Initial Test Program " * Arizona Public Service Co 80/06/19 20pp
- 8006230720 Chapter 19 of Palo Verde FSAR: "Accident Analysis "
 # Arizona Public Service Co 80/06/19 40pp
- 8006230721 Chapter 16 of Palu Verde FSAR. "Tech Spacs "

 # Arizona Public Service Co 80/06/19 130pp
- 8006230722 Chapter 17 of Pale Verde FSAR. "GA "
 * Arizona Public Service Co 80/06/19 30pp
- G Inspection reports, IE Bulletins & carrespondence
- BOO62501B7 Forwards IE Insp Repts 50-528/80-04.30-529/80-04 & 50-530/80-04 on BOO201-28 No noncompliance noted BPENCER,9 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch BO/05/02 2pp
- --8006250:192 IE Imap Repts 50-528/80-04, 50-529/80-04 & 50-530/80-04 on 80020:1-28 No noncompliance noted Major areas inspected containment bidg concrete/polar crame support girders, reactor vessel supports & auxiliary bidg wall reinforcement DODDS:R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch VORDEREREVEOCEN Region 5. San Francisco, Office of the Director 80/05/01 4pp
- 8 Reportable occurrences. LERs & related correspondence
- 8006030351 Advises that commitment made in 800324 preliminary deficiency rept will not be met Info from qualification testing will not be available within 60 days due to implementation difficulties Info finalized by 800801 VAN BRUNT, E.E. Arizona Public Service Co. 80/05/23 2pp

8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch toos were mfg to A234KPB requirement investigations conducted & closed at 46 listed facilities SEAY.J L. Chemtron Corp., Tuby Turns Div 80/06/06 3pp

T Hearing transcripts on non-antitrust matters

GOO&11030B Forwards 80050B sys review transcript 1e Class IE power sys Review held before Power Sys Review Board in Phoenix.AZ Pp 1-179
VAN BRUNT.E E Artiona Public Service Co 80/06/04 200pp

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

B Utility Preliminary Safety Analysis Report, amends

8006110301 Confirms distribution of Amend 54 to PSAR Certificate of Svc encl COPELAND.R L Chergy, Dept of, Clinch River Breeder Reactor Plant 80706705 2pp

9006270205 Forwards Amend 55 to PSAR COPELAND, R L Energy, Dept of, Clinch River Breeder Reactor Plant 80/06/27 App

--8006270223 Amend 55 to PSAR

* Energy, Dept of, Clinch River Breeder Reactor Plant 80/06/27

DOCKET 90-538 MEMPHIS STATE UNIV RESEARCH REACTOR

G Adjudicatory correspondence

8006190501 Response in opposition to Zimmer Area Citizens 800515 proposed contentions Intervenors failed to demonstrate good cause under policy stated in Commission decision overruling ALAS-590 Celtificate of Svc oncl CONNERT B Cincinnati Gas & Electric Co WETTERHAHN, M J Conner, Moore & Corber 80/06/16 11pp

DOCKET SIN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

BOO6230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0977 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing BO/09/20 13pp

8006060592 Forwards evaluation of 800428 consolidated description of revised GA program & 800506 supplemental rept Revised GA program is acceptable YUU/R8LCGD.B J Licensing Branch 1 80/05/23 4pp

--B006060596 Bafety evaluation supporting revised QA program * Licensing Branch 1 80/05/23 5pp

800A090071 Forwards response to questions & comments presented at 800325 public meeting & 800A07 ltr Ofc of Nuclear Reactor Regulation 800A11 meeting discussed changes to 0A program Changes have been documented & are part of docketed file BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/23 7pp

--8006090073 QA program for facility * Sargent & Lundy, Inc 80/05/23 37pp

8006190286 Ack receipt of 800509 ltr informing NRC of proposed method for evaluating concrete surfaces which are inaccessible due to backfilling FIDRELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/28 ip

8006200613 Informs that proposed alternatives for design of quality records storage facility are acceptable Acceptable alternatives should be incorporated into GA program TEDESCO,R L Assistant Director for Licensing 80/06/03 App

G Adjudicatory correspondence

8006110424 Response to Save the Valley-Save Marble Hill 800423 motion to strike & objections to util bill of costs re Civil Action 78-1369 on appeal Urges assigning costs to State of KY & intervenor W/Cortificate of Svc Related correspondence V010T.H H Public Service Co of Indiana, Inc V016T.H H LeBoeuf, Lamb, Leiby & MacRae 80/04/29 3pp

8006050443 Forwards gladuated rescission of 770815 order STELLO, V Office of Inspection & Enforcement, Office of the Birector 80/05/19 1p

---8004050449 Graduated rescission of 790Bi9 order confirming that process prescribed in app affords reasonable assurance that safety-related activities will be conducted per requirements STELLO.V Office of Inspection & Enforcement. Office of the Director 80/05/15 App

H General correspondence

8005210113 Requests, as followup to 800313 itr, that safety-related work not be allowed until FBI investigation results are known FORD, W H Senate 80/04/17 2pp

8005210130 Ltrs from six citizens & associations requesting that CP not be issued until FBI investigation results are known & actod upon Urges that all const be stopped until facility is inspected by Save the Valley engineers OILL.M., SHELBOURN.J.L., HEPLER.W. Affiliation Unknown 80/04/30

8006090134 Advises of certain changes in PBC of IN senior mgt HA Barter elected chairman but will also serve as chief executive officer DV Menscer elected president but will serve as chief operating officer Related correspondence VDIOT.H H LeBoeuf, Lamb, Leiby & MacRae 80/05/02 2pp

8005210116 Mailgrams from 23 citizens requesting that CP should not be issued until FBI investigation results are known & acted upon Urges that all const be stopped until facility is inspected by Save the Valley engineers
OMEN.R F. BRAEMLER.T F. BENNETT.M Affiliation Unknown 80/05/05

800A090S85 Opposes facility based on inadequate demand for increased electrical generating capacity & public safety considerations Util motivated by tax-related incentives Preliminary tax incentive rept encl HAUGK.F Bave the Valley - Save Marble Hill 80/05/05 App

BOO6120463 Responds to BOO404 ltr re status of FBI investigation into alleged misconduct at facility Premeture release of findings could jeopardise future action of DBJ Ltr & plan will be attached to transcript of BOO325 meeting STELLON V Defice of Inspection & Enforcement, Office of the Director BO/05/23 ip

BOO6130184 Ack receipt of 800326 ltr enclosing M Hudgin statement & MA Cassaro prof vita Encls will be placed in 800325 meeting record & MA Cassaro vita will be considered in selection process for independent engineer STELLO, V Defice of Inspection & Enforcement, Office of the Director 80/05/23 Ip

--8006130187 Forwards M Hudgin statement presented at NRC 800325 meeting w/util in Madison. IN 8 MA Cassaro prof vita DATTILO.T M Dattilo. T M 80/03/26 7pp

8006170335 Ack receipt of 800326 1tr forwarding comments re 800325 meeting on resumption of const Comments will be carefully considered STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/23 1p

--8006170342 Forwards statement which was not completely presented at 800325 meeting re resumption of const Sassafras Audubon written statement also oncl M/O Sassafras Audubon statement HAUCK,F Save the Valley - Save Marble Hill 80/03/26 13pp

BOO&120141 Responds to 800411 ltr re DM McCarthy comments & questions about meeting in Madison.IN concerning facility Forwards NRC response DIRCKS.H J Office of the Executive Director for Operations 80/05/28 ip

- --8006120146 Act receipt of 800402 ltrs providing list of comments & questions for record of 800325 meeting refacility Comments & questions will be included in meeting record & considered in license deliberations
 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 lp.
- --8006120150 Requests review of DH McCarthy 1tr re 800325 meeting in Madison. IN re facility FORD. W H Senate. Commerce, Science & Transportation 80/04/11
- 8006170531 Notifies of formation of new div & author relocation to plant site BHIELDS:8 N Public Service Co of Indians, Inc. 80/06/09 ip
- Q Inspection reports. 1E Bulletine & correspondence
- 800A090032 Forwards IE Insp Repts 50-54A/80-11 & 50-547/80-11 on 800402-04 & 08-11 No honcompliance noted FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/04/25 Zpp
- --8006090056 IE Inap Repts 50-546/80-11 & 50-547/80-11 on B00402-04 & OB-11 No noncompliance noted Major areas inspected status review of IOCFR2; item & const verification Proceduras SPP-2 & SPP-5 HAWKING.F C Region 3. Chicago. Office of the Director HAYES,D W Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/21 Spp
- 8006020020 Forwards IE Insp Repts 50-546/80-14 & 50-547/80-14 on 860331-0403 No noncompliance noted FICRELLIO Region 3, Chicago, Office of the Director. 80/04/26 200
- --8005020024 IE Insp Repts 50-546/80-14 & 50-547/80-14 on B00331-0403 No noncompliance noted Major areas inspected safety-related pipting lagdous areas & storage warehouse DANIELEON.D H Region G. Chicago, Reactor Construction & Engineering Busport Branch CORDERD.Z.C Region G. Chicago, Office of the Director 80/04/21 Jpp
- 8006020059 Forwards IE Insp Repts 50-846/80-08 & 50-847/80-08 on 800227-29,0306 & [8-21 No noncompliance noted FIORELLI,O Region 3 Chicago Reactor Construction & Engineering Support Branch 80/04/26 2pg
- --B006020063 IE Insp Repts 50-546/80-08 & 50-547/80-08 on 800227-29,0306 & 18-21. No noncompliance noted Major areas inspected observation of work & review of quality records & procedures
 HAYES, D. H. Region 3, Chicago, Reactor Construction & Engineering Support Branch HAHKINS, F. C. HARRIS, J. R. Region 3, Chicago, Office of the Director 80/04/17 7pp.
- 8006020069 Forwards IE Insp Rests 50-546/80-12 & 50-547/80-12 on 800331 No noncompliance noted KEPPLER, J G. Region 3, Chicago, Office of the Director 80/04/26 2pp
- --8006020073 IE Insp Repts 50-546/80-12 & 50-547/80-12 on 800331 No noncompliance noted Major areas inspected meeting to discuss proposed restart program & resumption of receipt inspactivities FIORELLI, 9 Region 3. Chicago, Reactor Construction & Engineering Support Brench SCHWEIBINZ, E.R., HAYES, D.W. Region 3. Chicago, Office of the Director 80/04/23 2pp
- 800&190317 Forwards IE Insp Repts 50-546/80-15 & 50-547/80-15 on 800416-18 Ng noncompliance noted FIORELLI, 9 Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/04/29. 2pp.
- --B006190323 IE Insp Repts 50-546/80-15 & 50-547/80-15 on 800416-18. No noncompliance noted. Major areas inspected, licensee actions re insp of installed Category I structural steel & safety-related piping as part of const verification program NOMMLIN. J E. CORDERO, Z.C., WILLIAMS, G.C., Region 3, Chicago, Office of the Director 80/04/23, App.
- BOO6230166 Forwards IE Insp Repts 50-546/80-20 & 50-547/80-20 on 800401-30. No noncompliance noted. FIORELLI, O Region D. Chicago, Reactor Construction & Engineering Support Branch. 80/05/21. 2pp.
- ---8004230170 [E Insp Repts 50-546/80-20 & 50-547/80-20 on 800401-30. No nencompliance noted Major areas inspected const activities & storage & preservation of matl & equipment. WILLEMBS, C. C. HARRISON, J. J. Region 3: Chicago, Office of the Director 80/05/21. 4pp.

- 8006300175 Forwards IE Insp Repts 50-546/80-18 & 50-547/80-18 on 800507-08 No noncompliance noted FIGHELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8006300182 IE Insp Repts 30-546/80-18 & 30-547/80-18 on 800507-08 No noncompliance noted Major areas inspected licenses action relative to physical snsp & verification of in-place safety Category 1 piping & hangers
 CORDERO. 2 C Region 3. Chicago. Office of the Director DANIELSDN. D H Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/19 3pp
- 8006190696 Notifies Board of Clark County Commissioners, Jeffersonville, IR of 800606 meeting in Madison, IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agende entl W/o entl KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- ---8006190700 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident insep programs for nuclear power plants Tentative agenda encl Wo encl KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/29,
- --8005190703 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800605 meeting in Madison, IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda encl N/O sucl KEPPLER, J O Region 3. Chicago, Office of the Director 80/05/29
- --8006190706 Notifies Hanover Town Board Hanover, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident insp pragrams for nuclear power plants Tenatative agenda encl M/o encl KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/05/29
- --B006190713 Notification of 800606 meeting in Madison, IN to discuss NAC regulatory & resident insp programs for nuclear power plants Tentative agenda encl W/o encl MEPPLER, J Q Region 3, Chicago, Office of the Director 80/05/29
- ~-8006190719 Notifies New WA State Bank of 800606 meeting in Madison.IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda encl KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/29
- 8006230162 Responds to IE Bulletin B0-05 re vacuum condition resulting in damage to chemical vol holdup tanks Evaluation of protective measures against vacuum damage is ongoing Requests extension until 800709 SHIELDS/S W Public Bervice Co of Indiana, Inc 80/06/04 ip
- B006190296 Forwards IE Insp Repts 50-546/80-16 & 50-547/80-16 on 800422-25,0429-0502:06-09 & 14-16 No noncompliance noted FIORELLI,G Region 3. Chicago, Reactor Construction & Engineering Support Branch. B0/06/06 2p
- --8006190300 IE insp Repts 50-546/80-16 & 50-547/80-16 on 800422-25,0429-0502,06-09 & 14-16 No noncompliance noted Major areas inspected procedure revisions, quality records, observation of work & previous insp findings

 HAYES,D W Region 3. Chicago, Reactor Construction & Engineering Support Branch HAMKINS,F C , HARRIB,J R Region 3. Chicago, Office of the Director 80/06/02 6pp
- 8006260332 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/80-03 & 50-547/80-03. FIORELIA & Region 3. Chicago, Reactor Construction & Engineering Bupport Branch.
- --8006260356 Responds to NRC 800321 ltr re violations noted in IE Insp Repts 50-546/80-03 & 50-547/80-03 Corrective actions util is presently arranging for proper personnel assignment to assume deficiency rept responsibilities BHIELDS,8 W Public Service Co of Indiane, Inc 80/05/28 Spp.
- S. Reportable occurrences, LERs & related correspondence
- 8006200069 Interim Part 21 rept re operation of centrifugal charging pumps at min flow rate when RCS reaches pressuriter safety valve satpoint pressure during secondary sys high energy line rupture Westinghouse will analyze problem SHIELDS,S W Public Service Co. of Indiana, Inc. 80/06/02 3pp

- T Hearing transcripts on non-antitrust matters
- 8005210137 Forwards transcript of 800325 hearing in Madison, IN, containing few omissions & some inaccuracies due to absence of prof court reporter STELLO. Office of Inspection & Enforcement, Office of the Director 80/05/05 Ip
- --8005210177 Transcript of 800325 hearing in Madison, IN STELLO,V Office of Inspection & Enforcement, Office of the Director 80/03/25 230pp
- ---8005210187 Act receipt of NRC notice of 800411 meeting in Bethesda, MD re revised RA program Expresses concerns re safety-related questions not answered at Madison, IN meeting EYED, J.A. Sassafras Audubon Society 80/04/07 2pp
- --8005210202 Submits questions & comments presented at 800325 public meeting in Madison.IN
 EYED, J A Sassafras Audubon Society 80/04/30 5pp
- --8005210208 Forwards M Hudgins statement presented at 800325 meeting in Madison. IN w/prof qualifications
 DATTILO.T M Dattilo. T M 80/03/26 7pp
- ---B005210217 Compliments handling of 800325 meeting in Madison.IN F Hauck comments re safety matters encl HAUCK.F Save the Valley - Save Marble Hill 80/03/26 8pp
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- BO06230110 Advises BMR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREO-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EIBENHUT, D G Division of Licensing 80/05/20 13pp
- 8006060592 Forwards evaluation of 800428 consolidated description of revised QA program & 800506 supplemental rept Revised QA program is acceptable YOUNOBLOOD.B J Licensing Branch 1 80/05/23 App
- --8006060576 Safety evaluation supporting ravised QA program
 * Licensing Branch 1 80/05/23 5pp
- 8006090071 Forwards response to questions & comments presented at 800325 public meeting & 800407 ltr Ofc of Nuclear Reactor Regulation 800411 meeting discussed changes to QA program Changes have been documented & are part of docksted file STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 7pp
- --800609037 QA program for facility * Sargent & Lundy, Inc 80/05/23 37pp
- 8006190286 Ack receipt of 800909 ltr informing NRC of proposed method for evaluating concrete surfaces which are inaccessible due to backfilling FIRRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/28 ip
- 8006200613 Informs that proposed alternatives for design of quality records storage facility are acceptable Acceptable alternatives should be incorporated into GA program TEDESCO.R L. Assistant Director for Licensing 80/06/03 4pp

G Adjudicatory correspondence

- 8006110424 Response to Save the Valley-Bave Marble Hill 800423 motion to strike & objections to util bill of costs re Civil Action 78-1367 on appeal Urges assigning costs to State of KY & Intervenor W/Certificate of Svc Related correspondence VOIOT, H H Public Service Co of Indiana, Inc VOIOT, H H LeBosuf, Lemb Leiby & HacRae 80/04/27 3pp
- 8006090443 Forwards graduated rescission of 790815 order STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/18 1p
- --8006050449 Graduated rescission of 790815 order confirming that process prescribed in app affords reasonable assurance that safety-related activities will be conducted per requirements BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/15 App

- H General correspondence
- 8005210113 Requests, as followup to 800313 ltr.that safety-related work not be allowed until FBI investigation results are known FORD.N R Senate 80/04/17 2pp
- B005210130 Ltrs from six citizens b associations requesting that CP not be issued until FBI investigation results are known & acted upon Urges that all const be stopped until factlity is inspected by Save the Valley engineers GILL.M. SHELBOURN.J., HEPLER.W. Affiliation Unknown 80/04/30
- 8006090134 Advises of certain changes in PSC of IN senior ngt HA Barker elected chairman but will also serve as chief executive officer DV Menscer elected president but will serve as chief operating officer Related correspondence VOIGT, HH LeBoeuf, Lamb, Leiby & MacRae 80/05/02 2pp
- BOOS210116 Mailgrams from 23 citizens requesting that CP should not be issued until FBI investigation results are thoun & acted upon Urges that all const he stopped until facility is inspected by Bave the Valley engineers

 UNEN.R F. BRAEHLER.T F. BENNETT.M Affiliation Unknown 80/05/05
- B006090585 Opposes facility based on inadequate demand for increased electrical generating capacity & public safety considerations Util motivated by tax-related incentives Preliminary tax incentive rept enci HAUCK.F Save the Valley Save Marble Mill 80/05/05 4pp
- 8006120463 Responds to 800406 ltr re status of FBI investigation into alleged misconduct at facility Premature release of findings could jeopardize future action of BDJ tr & plan will be attached to transcript of 800329 meeting STELLO,V Office of Inspection & Enforcement, Office of the Birector 80/05/23 sp
- 8006130184 Ack receipt of 800326 ltr enclosing H Hudgin statement & MA Cassaro prof vita Encls will be placed in 800325 meeting record & MA Cassaro vita will be considered in selection process for independent engineer STELLO.V Office of Inspection & Enforcement, Office of the Director 80/05/23 ip
- --8006130187 Forwards M Hudgin statement presented at NRC 800325 meeting w/util in Madison, IN & MA Cassaro prof vita DATTILO, T M Dattilo, T M 80/03/26 7pp
- 8005170335 Ack receipt of 800325 ltr forwarding comments re 800325 meeting on resumption of const Comments will be carefully considered STELLD, V Office of Inspection & Enforcement, Office of the Director 80/05/23 lp
- --8006170342 Forwards statement which was not completely presented at 800325 meeting re-resumption of const Bassafras Audubon written statement also encl W/o Bassafras Audubon statement HAUCK,F Save the Valley Save Marble Hill 80/03/26 13pp
- 8005120141 Responds to 800411 ltr re DH McCarthy comments & questions about meeting in Madison.IN concerning facility Forwards NRC response DIRCKS.W J Office of the Executive Director for Operations 80/05/28 ip
- --8006120146 Ack receipt of 800402 ltrs providing list of comments & questions for record of 800325 meeting refacility Comments & questions will be included in meeting record & considered in license deliberations
 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/23 ip
- --B006120150 Requests review of DH McCarthy 1tr rs 800325 meeting in Madison, IN re facility FORD, WH Senate, Commerce, Boience & Transportation, B0/04/11 ip
- 8006170531 Notifies of formation of new div & author relocation to plant size
 BHIELDERS W Public Bervice Co of Indiana, Inc. 80/06/09 ip
- Q Inspection reports. IE Bulletins & correspondence
- BO06090052 Forwards IE Insp Repts 50-546/80-11 & 50-547/80-11 on B00402-04 & 08-11 No moncompliance noted FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch SO/04/25 2pp

DOCKETED ITEMS

- --8006090056 IE Insp Repts 50-546/80-11 & 50-547/80-11 on 800402-04 & 08-11 No noncompliance noted Major areas inspected status review of 10CFR21 item & const verification Procedures SPP-2 & SPP-5

 HARRINS-F C Region 3, Chicago, Office of the Director MAYES, D W Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 Spp
- 8006020020 Forwards IE Insp Repts 50-546/80-14 & 50-547/80-14 on 800331-0403 No noncompliance noted FIORELLI, G. Region 3. Chicago. Office of the Director 80/04/26 2pp
- --B006020024 IE Insp Repts 50-546/80-14 & 30-547/80-14 on 800331-0403 No noncompliance noted Major areas inspected safety-related piping laydown areas & storage warehouse DANIELSON,D H. Regton 3. Chicage, Reactor Construction & Engineering Support Branch CURDERO, Z.C. Region 3. Chicage, Office of the Director 80/04/21 3pp
- 8006020059 Forwards IE Insp Repts 50-546/60-08 & 50-547/80-08 on 800227-29,0306 & 18-21 No noncompliance noted FIGRELLIGE Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/26 2pp
- --8006020063 IE Insp Repts 50-546/80-06 & 50-547/80-08 on 800227-29,0306 & 18-21 No noncompliance hated Major areas inspected observation of work & review of quality records & procedures
 HAYES,D W. Region 3, Chicago, Reactor Construction & Engineering Support Branch HAMMINS,F C., HARRIS,J R. Region 3, Chicago.

 Office of the Director 80/04/17 7pp
- 8006020067 Forwards IE lasp Repts 50-546/80-12 & 50-547/80-12 on B00331 No noncompliance noted KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/04/26 2pp
- --8006020073 IE Insp Repts 50-946/R0-12 & 50-547/R0-12 on R00331 No noncompliance noted Major areas inspected meeting to discuss proposed restart program & resumption of receipt inspactivities

 FICRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch SCHWEIBINZ, E.R., HAYEB-D.W. Region 3. Chicago, Uffice of the Director BO/04/23 2pp
- BOOA170319 Forwards IE Insp Repts 50-546/80-15 & 50-547/80-15 on 800416-18 No noncompliance noted FIORELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/04/29 2pp
- ~~8006190323 IE Insp Repts 50-546/80-15 & 50-547/80-15 on 800416-18 No noncompliance noted Major areas inspected licenses actions re insp of installed Category I structural steel & safety-related piping as part of const verification program KONGLIN.J E. CORDERO.Z C. MILLIAMS.C. C. Region 3. Chicago. Office of the Director 80/04/23. App
- 8006250166 Forwards IE Insp Repts 50-546/80-20 & 50-547/80-20 on 800401-30 No noncompliance noted FIORELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8006250170 IE Insp Repts 50-546/80-20 & 50-547/80-20 on 800401-30 No noncompliance noted Major areas inspected const activities & storage & preservation of matl & equipment WILLIAMB.C. C. rARREDON.J. J. Region 3. Chicago, Office of the Director 80/05/21 App
- 8006300175 Forwards IE Insp Repts S0-546/80-18 & 50-547/80-18 on B00507-08 No noncompliance noted FIGRELLI-6. Region S. Chicago. Reactor Construction & Engineering Support Branch B0/05/21 2pp
- ~-8006300182 IE Imsp Repts 30-546/80-18 & 50-547/80-18 on 800507-08 No noncompliance noted Major areas inspected licenses action relative to physical imsp & verification of in-place safety Category 1 plping & hangers.

 CRRDERO, Z C. Region 3. Chicago. Office of the Director.

 DANIELBON, D H. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/05/19 3pp
- 8006190696 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison. IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda entl W/o encl.

 KEPFLER. J Q Region 3. Chicago. Office of the Director 80/05/29 is.

- --8006i90700 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident inspiprograms for nuclear power plants Fontative agenda enti M/o enci
 KEPPLER, G Region 3, Chicago, Office of the Director 80/05/29 ip
- ~~8006190703 Notifies Board of Clark County Commissioners, Jeffersonville, IN of 800606 meeting in Madison, IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda enci W/o encl KPPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- --B006190706 Notifies Hanover Town Board, Hanover, IN of B00606 meeting in Hadison, IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tenatative agenda encl W/o encl KEPPLER, J G Region 3, Chicago, Office of the Director B0/05/29
- --8006190713 Notification of 800606 meeting in Madison, IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda encl W/o encl KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/05/29 in
- ~~8006190719 Notifies New WA State Bank of 800606 meeting in Madison. IN to discuss NRC regulatory & resident insp programs for nuclear power plants Tentative agenda encl KEPPLER, J Q Region O, Chicago, Office of the Director 80/05/29 Jpp
- 8006230162 Responds to IE Bulletin 80-05 re vacuum condition resulting in damage to chemical vol holdup tanks Evaluation of protective measures against vacuum damage is ongoing Requests extension until 800709 SHIELD8.8 W
- 8006190296 Forwards IE Insp Repts 50-546/80-16 & 50-547/80-16 on 800422-25, 0429-0502, 06-09 & 14-16 No noncompliance noted FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --8006190300 IE Insp Repts 50-346/80-16 & 30-547/80-16 on 800422-25,0429-0502,06-09 & 14-16 No noncompliance noted Major areas inspected procedure revisions, quality records, observation of work & previous insp findings

 HAYES,D W. Region 3. Chicago: Reactor Construction & Engineering Support Branch HAMKINS,F C. HARRIS,J R. Region 3. Chicago.

 Office of the Director 80/06/02 App
- 8006260352 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/80-03 & 50-547/80-03 FIORELLI, 9 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/11 1p
- --B005260336 Responds to NRC B00321 itr re violations noted in IE Insp Repts 50-346/80-03 & 90-547/80-03 Corrective actions util is presently drranging for proper personnel assignment to assume deficiency rept responsibilities SHIELDS, S W Public Service Co of Indiana, Inc 80/05/28 App
- S Reportable occurrences. LERs & related correspondence
- 8006200069 Interim Part 21 rept re operation of centrifugal charging pumps at min flow rate when RCS reaches pressurizer safety valve setpoint pressure during secondary sys high energy line rupture Hestinghouse will analyze problem SHIELDS.S W Public Service Co of Indiana, Inc. 80/06/02 3pp
- T Hearing transcripts on non-antitrust matters
- 8005210137 Forwards transcript of 900325 hearing in Madison, IN. containing few omissions > some inaccuracies due to absence of prof court reporter STELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/05 1p
- ~~900521017/ Transcript of B00325 hearing in Madison,IN
 BTELLO,V Office of Inspection & Enforcement, Office of the
 Director 80/03/25 230pp
- ~-8005210187 Ack receipt of NRC notice of 800411 meeting in Bethesda. MD re revised GA program Expresses concerns re safety-related questions not answered at Hadison, IN meeting EYED. J A Seisafras Audubon Society 80/04/07 2pp

- --8005210202 Submits quostions & comments presented at 800325 public meeting in Madison.IN EYED.JA Sassafras Audubon Society 80/04/30 3pp
- ETED. J A Bassarras Auduban Bociety GU/04/30 Spp
- --8005210208 Forwards M Hudgins statement presented at 800325 meeting in Madison.IN w/prof qualifications
 DATTIC.T M Dattilo, T M 80/03/26 7pp
- ~-8005210217 Compliments handling of 800325 meeting in Madison, IN F Hauck comments re safety matters encl HAUCK.F Save the Valley - Save Marble Hill 80/03/26 Bpp
- DOCKET 50-548 FORT CALHOUN STATION, UNIT 2
 G Adjudicatory correspondence
- B006060456 Urges to hold further licensing proceeding in abeyance due to pending Westinghouse breach of contract action against util Present ltr constitutes semianmual status rept Related correspondence VOIOT.H H LeBoeuf, Lamb, Leiby & MacRae B0/05/05 ip
- H General correspondence
- 8006110086 Requests that MA Tebor be substituted for MR Paradis on svc list In future, all info should be sent to MA Tebor TEBOR.M A LeBoeuf, Lamb, Leiby & MacRae 80/05/28 ip
- DOCKET SO-549 GREENE COUNTY NUCLEAR POWER PLANT
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREQ-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT,D Q Division of Licensing 80/05/20 13pp
- O Adjudicatory correspondence
- 8006110020 Notice of withdrawal from proceeding effective 800602 Certificate of Svc encl LENIS:S H Hearing Branch 2 80/06/03 4pp
- DOCKET STN-90-959 PHIPPS BEND NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0377 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EIBENHUT, D Q Division of Licensing 80/03/20 13pp
- 8006060370 Forwards detailed description of tranverse fault beneath essential svc water spray pand one per 800502 & 07 telcons Fault is not judged capable per App A to 10CFR100 HILLS, L M Tennessee Valley Authority 80/06/03 App
- 8006240620 Forwards "For Comment" edition of NUREQ-0619 Requests review & comment W/o encl EIGENHUT.D Q Division of Licensing 80/06/10 3pp
- 9 Adjudicatory correspondence
- 8006040396 Advises that AM Gutterman will no longer appear in proceedings on behalf of util SANDER: H B Tennesses Valley Authority 80/09/19 3pp
- Q Inspection reports, IE Bulletins & carrespondence
- 8006050415 Forwards IE Insp Repts 50~553/80-06 & 50~554/80-05 on 900331-0403 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/23 2pp
- ---8006050420 IE Insp Repts 50-553/80-06 \$ 50-554/80-05 on 800331-0403 No noncompliance noted Major areas inspected concrete placement QA manual review & inspector followup items CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIGHT, R W. Region 2, Atlanta, Office of the Director 80/04/22 7pp

- 8006060197 Forwards (E Bulletin 80-11, 'Masonry Hall Design " No action or written response required IE Info Notice /9-28, "Overloading of Structural Elaments Due to Pipe Support Loads" encl O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8006040267 Forwards IE Bulletin 80-12. "Decay Heat Removal Bys Operability ' No wiltten response required IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Hode" encl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/09 Opp
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- 8006030602 Ack receipt of 800508 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-553/79-17 & 50-554/79-16 MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8006030604 Responds to NRC 800427 ltr re violation noted in IE Insp Repts 50-983/79-17 & 50-854/79-16 Corrective actions deposited weld metal in excess of limit will be removed MILLS:L M Tennessee Valley Authority 80/03/08 4pp
- ---8006030604 Ack receipt of 800331 ltr informing NRC of steps taken to correct violation nuted in IE lnsp Repts 50-553/79-17 & 50-554/79-14 MMRPHy C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/04/27 2pp
- --8006030608 Responds to NRC 800325 itr re violation noted in IE Insp Repts 50-553/79-17 & 30-554/79-16 Corrective actions excess weld metal deposits will be removed Add1 details re max weave usdth provided in Nanconformance Rept PSN-067 MILLS,L M Tennessee Vailey Authority 80/03/31 ip
- 8006070456 Responds to 800121 ltm which transmitted IE Bulletin 80-02 Investigations revealed that feedwater spargers or thermal sleeves mfg &/ar fabricated by Marvin Engineering Co have not been purchased &/or have not been installed in plants.
 MILLS, L. M. Tennessee Valley Authority 80/05/21 ip
- BOOG180567 Outlines BOO516 into of geologic faulting in Unit 1 spray pond Util may proceed w/fill concrete operations on Zone 20 & Fault 19 Addl faulting must be reported MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch BO/05/29 2pp
- 8006190466 Responds to NRC B00521 ltr re violation noted in IE Insp. Repts 50-953/80-07 & 50-954/80-06 Corrective actions: procedure for controlling submerged arc welding flux has been made available to craft personnel MILLS, L M Tennessee Valley Authority B0/06/12 3pp
- 8006250252 Forwards final response to notice of violation described in IE Insp Repts 50-553/80-08 \$ 50-554/80-07 Concrete cylinder breaks for samples representing safety-related structure placements made 800507-09 have been reviewed MILLS.L M Tennessee Valley Authority 80/06/19 3pp
- S Reportable occurrences. LERs & related correspondence
- 8006060230 Forwards CTI-Nuclear 800503 Part 21 rept re potential failure of McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in ainstream in various air filtration sys KENYON, M Tennessee Valley Authority 80/05/08 4pp
- 800808401 Forwards final deficiency rapt re unacceptable bending of welded stud anchors on embedded plates
 MILLS.L M Tennessee Valley Authority 80/06/02 ip
- --8005060413 Final deficiency rept re unacceptable bending of welded atud anchors on embedded plates Testing program was initiated.

 Bending of studs has no significant affect on stud capacity Lists guidelines for max bending of stud anchors # Tennessee Valley Authority 80/06/02. 3pp
- 800&110048 Forwards first interim deficiency rept re standby gas treatment sus charcosl adsorber MILLSAL M Tennesses Valley Authority 80/06/04 ip

- --800bi1005B First interim deficiency rept re standby gas treatment sys charcoal adsorbers Charcoal retention screens separating from frames due to improper or broken spot welds Vendor, CTI-Nuclear, investigating problem Final rept by 800820 e Tennessee Valley Authority 80/06/04 ip
- 8006120309 Forwards interim deficiency rept re steam tunnel embedment atiffener plate weld MILLS/L K Tennessee Valley Authority 80/06/04 ip
- --B006120313 Interim deficiency rept re failure by Atlas Machine & Iron Works to implement GA procedures for steam tunnel embedment stiffener plate weld Stiffener plate NCR-10 weided per GA requirements & aid for Atlas GA program contracted = Tennessee Valley Authority B0/06/04 ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch albows & 2-inch tees were mfg to A234MPB requirement investigations conducted & closed at 46 listed facilities
 SEAY, J. C. Chembron Corp., Tube Turns Div. 80/06/06. 3pp
- 8006200432 Forwards final deficiency rept re defective McGraw-Edison temp detection controllers in standby gas treatment sys MILLS.L M. Tennessee Valley Authority 80/06/13 ip
- --8006200434 Final deficiency rept re defective temp detection controller in standby gas treatment sys Electronic temp detection controller failed in svc Caused by acid flux solder smaling controls Controllers to be replaced w/certified controllers # Tennessee Valley Authority 80/06/13 2pp
- 8006250257 Forwards first interim deficiency rept re improper insprecards
 MILLS.L M Tennessee Valley Authority 80/06/19. ip.
- --8006250261 First interim deficiency rept re improper inep records Civil GC insp program being reviewed to determine changes necessary for compliance w/applicable requirements.

 * Tennessee Valley Authority 80/06/19 1p
- 8006250278 Forwards final deficiency rept re incorrect root face on stewed cadweld sleeves MILLS:L M Tennessee Valley Authority 80/06/19 ip
- --8006250281 Final deficiency rept re incorrect root face on skewed cadweld sleeves. Atlas Machine & Iron Works fabricated some representative structures using same welding process as sleeves Destructive pull tests performed satisfactorily # Tennessee Valley Authority 80/06/19 2pp
- 8006250256 Second interim deficiency rept re defects in Rosemount trip/ calibr units Util & GE investigations re quantity of Model 1152 pressure transmitters shipped continuing Final rept will be submitted by 800717 MILLS.L M Tennessee Valley Authority 80/06/20 ip
- DOCKET STN-50-554 PHIPPS SEND NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D C Division of Licensing 80/05/20 13pp
- 8006060370 Forwards detailed description of tranverse fault beneath essential svc water spray pond one ger 800502 & 09 telcons fault is not judged capable per App A to 10CFR100 HILLS,L M Tennessee Valley Authority 80706703 App
- 8006240620 Forwards "For Comment" edition of NUREG-0619 Requests review & comment W/o encl
 EISEMHUT.D O Division of Licensing 80/06/10 3pp
- Q Adjudicatory correspondence
- 8006060336 Advises that AH Gutterman will no longer appear in proceedings on behalf of util SANGER,H S Tennessee Valley Authority 80/05/19 3pp

- Q Inspection reports. IE Bulletins & correspondence
- 8006050415 Forwards IE Insp Repts 50-553/80-06 & 50-554/80-05 on 800331-0403 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/23 2pp
- --8006050420 IE Insp Repts 50-553/80-06 & 50-554/80-05 on 800331-0403 No noncompliance noted Major areas inspected concrete placements(A manua) review & inspector followup items CANTRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch WRIGHT,R W Region 2. Atlanta, Office of the Director 80/04/22 7pp
- B006060159 Forwards IE Bulletin 80-11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" encl
 O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/08
- 8006040267 Forwards IC Bulletin 80-12, "Decay Heat Removal Sys Operability " No written responso required IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Hode" encl O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/09
- 8006120034 Forwards IE Circular 80~11, "Emergency Diesel Generator Lube Oil Cooler Failures" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/13 3Dp
- B006030602 Ack receipt of 800508 ltr informing NRC of steps taten to correct violation noted in IE Insp Repts 50-553/79-17 & 50-554/79-16 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- ---8006030604 Responds to NRC 800429 ltr re violation noted in IE Insp Repts 50-953/79-17 & 50-554/79-16 Corrective actions deposited weld metal in excess of limit will be removed MILLS:L M Tennessee Valley Authority 80/05/08 4pp
- --8006030606 Ack receipt of B00331 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-553/79-17 & 50-554/79-16 HURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/04/29 2pp
- --8006030608 Responds to NRC 800325 itr re violation noted in IE Insp Repts 50-553/79-17 ½ 50-554/79-16 Corrective actions excess weld metal deposits will be removed Add1 details re max weave width provided in Nonconformance Rept PBN-067 MILLS,L M Tennessee Valley Authority 80/03/31 ip
- B006090496 Responds to 800121 ltr which transmitted IE Bulietin 80-02 Investigations revealed that feedwater spargers or thermal sleeves mfg &/or fdbricated by Marvin Engineering Co have not been purchased &/or have not been installed in plants MILLS,L M Tennessee Valley Authority 80/05/21 1p
- 8006:80567 Outlines 8005:6 insp of geologic faulting in Unit 1 spray pond Util may proceed w/fill concrete operations on Zone 20 & Fault 19 Add1 faulting must be reported MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 2pp
- 8006190466 Responds to NRC 800521 ltr re violation noted in IE Insp Repts 50-553/80-07 & 50-554/80-06 Corrective actions procedure for controlling submerged arc welding flux has been made available to craft personnel MILLS.L M Tennessee Valley Authority 80/06/12 3pp
- B006290292 Forwards final response to notice of violation described in IE Insp Repts B0-553/80-08 & 50-554/80-07 Concrete cylinder breaks for samples representing safety-related structure placements made 800507-09 have been reviewed MILLS.L M Tennessee Valley Authority 80/06/19 3pp
- S Reportable occurrences, LERs & related correspondence
- 8004040230 Forwards CTI-Nuclear 800503 Part 21 rept re potential failure of McGraw Edison device used in CTI-Nuclear electronic control circuit for detecting high temps in airstream in various air filtration sys KENYON, M Tennesses Valley Authority 80/05/08 4pp

- 8006060401 Forwards final deficiency rept re unacceptable bending of welded stud anchors on embedded plates
 MILLS,L M Tennessee Valley Authority 80/06/02 ip
- --80060604i3 Final deficiency cept re unacceptable bending of welded stud anchors on embedded plates Testing program was initiated Bending of studs has no significant effect on stud capacity Lists guidelines for max bending of stud anchors * Tennessee Valley Authority 80/06/02 3pp
- 8006110048 Forwards first interim deficiency rept re standby gas treatment sys charcoal adsorber MILLS.L M Tennessee Valley Authority 80/04/04 ip
- --8006110058 First interim deficiency rept re standby gas treatment sys charcoal adsorbers Charcoal retention screens separating from frames due to improper or broken spot wolds Vendor. CTI-Nuclear, investigating problem Final rept by 800820 * Tennessee Valley Authority 80/06/04 1p
- B006120309 Forwards interim deficiency rept re steam tunnel embedment stiffener plate weld MILLS, L.M. Tennessee Valley Authority B0/06/04 ip
- --8006120313 Interim deficiency rept re failure by Atlas Machine & Iron Horks to implement QA procedures for steam tunnel embedment stiffener plate weld Stiffener plate NCR-10 welded per QA requirements & aid for Atlas QA program contracted * Tennessee Valley Authority 80/06/04 ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch elbows & 2-inch tees were mfg to
 A234MPB requirement investigations conducted & closed at
 46 listed facilities
 SEAY.J L. Chemtron Corp., Tube Turns Div 80/06/06 3pp
- 8006200432 Forwards final deficiency rept re defective McGraw-Edison temp detection controllers in standby gas treatment sys MILLS, L M Tennessee Valley Authority 80/04/13 ip
- --8006200454 Final deficiency rept re defective temp detection controller in standby gas treatment sys Electronic temp detection controller failed in svc Caused by acid flux solder sealing controls Controllers to be replaced w/certified controllers * Tennessee Valley Authority 80/06/13 Rpp
- 8006250257 Forwards first interim deficiency rept re improper insprecards
 MILLS.L M Tennessee Valley Authority 80/06/19 ip
- --8006250261 First interim deficiency rept re improper insp records. Civil QC insp program being reviewed to determine changes necessary for compliance w/applicable requirements # Tennessee Valley Authority 80/06/17 ip
- 8006250281 Final deficiency rept re incorrect root face on skewed cadweld sleeves Atlas Machine & Iron Works fabricated some representative structures using same wolding process as sleeves Destructive pull tests performed satisfactorily * Tennessee Valley Authority 80/06/19 2pp
- 8006250256 Second interim deficiency rept re defects in Rosemount trip/calibr units Util & GE investigations re quantity of Model
 1152 pressure transmitters shipped continuing Final rept
 will be submitted by 800917
 MILLS.L M Tennessee Valley Authority 80/06/20 1p
- DUCKET BTN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT, D G Division of Licensing 80/05/20 13pp.
- 800630036B Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retardancy will be provided i yr subsequent to receipt of CP MUENCH.O W Public Service Co of Oklahoma 80/06/20 2pp
- F Security, medical, emergency & fire protection plans
- 8006300368 Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retardancy will be provided I yr subsequent to receipt of CP MUENCH.9 W Public Service Co of Oklahoma 80/06/20. 2pp

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8006200072 Forwards ACRS 800505 ltr to JF Absance re near-term CP applications SCHWENCER.A Licensing Branch 2 80/05/30 2pp
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8006230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NVREO-0577 readequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D 0 Division of Licensing 80/05/20 13pp
- 800630036B Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retardency will be provided 1 yr subsequent to receipt of CP MUENCH. 0 W Public Bervice Co of Oklahoma 80/06/20 2pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8006200072 Forwards ACRS 800506 ltr to JF Ahearne re mear-term CP applications SCHWENCER.A Licensing Branch 2 80/05/30 2pp
- DOCKET STN-50-561 B-SAR-205
- A Application/construction stage documents & correspondence
- 8006090098 Forwards add1 info re extended operation of LMBR core in Shippingport Power Station, per 800508 request Releases of radioactifyity continue to be below applicable stds as documented in annual environ repts
 RICKOVER, HO Energy, Dept of 80/05/21, 13pp
- ---B006090104 Forwards comments on extension of LWBR operations Proposed continuation might affect conclusions in areas of proposed augmented inservice insp program-reactor vessel irradiation & control rod drive mechanisms

 DENTON.H R Office of Nuclear Reactor Regulation, Director B0/04/30 6pp
- --800609011B Forwards ACRB conclusions re extended operation of LWBR core W/o encl FRALEY.R F ACRB - Advisory Committee on Reactor Safeguards 80/05/06 1p
- DUCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 80060202RO Summary of 800507 meeting re partial refund of CP fee Refund will be made using ASLAB average of d man-days HOLLOWAY.C J License Fee Managament Branch 80/05/19. ip
- 8006230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D O Division of Licensing. 80/05/20 13pp
- 8004040051 Notifies util that NRC will refund portion of sum paid in CP fees. Fees paid exceeded cost of processing & issuing MILLER.W O License Fee Management Branch 80/05/23 1p
- 8006240077 Informs that effective 800428.0fc of Nuclear Reactor Regulation was reorganized Mgt of all licensing matters w/respect to facility have been assigned to H Rood Reorganization chart encl TEDESCO.R t. Assistant Director for Licensing 80/06/13 10pp.
- E MRC Safety Evaluation Report (SER), supple & correspondence
- 8006300595 "Safety Evaluation re Const of Yellow Creek Nuclear Plant, Units 1 & 2." Suppl 1 * Office of Nuclear Reactor Regulation, Director NUREG-0347 Si 78/06/27 56p Available at NTIS \$6 00

G Adjudicatory correspondence

- 8006050356 Advises that AH Gutterman uill no longer appeal in proceedings on behalf of util SANGER, H E Tonnessee Valley Authority 80/05/19 3pp
- G Inspection reports. IE Bullatins & correspondence
- 8006050095 Forwards IE Insp Repts 50-566/80-05 & 50-567/80-06 on 800319-21 No noncompliance noted MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/08/11 2pp
- --8006050103 It Insp Repts 50-544/80-06 & 50-547/80-06 on 800319-21 No noncompliance intea Major areas inspected inspector following items. (OCFR50 35(e)) item, observation of safety-related work activities & warehouse insp CANTRELL F 5 Region 2. Atlanta. Reactor Construction & Engineering Support Dianch (NOMAS, M. Region 2. Atlanta, Dffice of the Director 80/04/11 3pp
- 8006040159 Forwards IE Bulletin 80-11, "Masonry Wall Design " No action or written response required IE Info Notice 79-26, "Overloading of Structural Elements Due to Pipe Support Loads" entl 0/REILLY, J. P. Region 2, Atlanta, Diffice of the Director 80/05/08
- 800&040267 Forwards IE Bulletin 80-12. "Decay Heat Removal Sys Decrability " No written response required IE Info Notice 80-20. "Loss or Decay Hoat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" entl O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/07 3pp
- 8006120034 Forwards IE Circular 80-11, "Emergency Diesel Generator Lube Uil Cooler Failuren" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/10 3pp
- 8004040232 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-03 & 50-567/80-03 MRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 2pp
- --8006040249 Responds to NRC 800228 ltr re violations noted in IE Insp. Repts 50-566/80-03 t 50-567/80-03 Corrective actions 800324 to 0421 submittals revised Re-evaluation of radiographs showed only seven welds will require reradiographing HILLS,L H Tennessee Valley Authority 80/04/28 2pp
- --B006040296 Responds to NRC 800228 ltr re violations noted in IE Insp Repts 50-556/80-03 & 50-567/80-03 Advises that revised response to 800409 ltr will be submitted by 800408 HILLS:L M Tennessee Valley Authority 80/04/21 ip
- 6006170740 Ack receipt of 800519 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-565/80-07 & 50-567/80-07 MMRPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Suggest Branch 80/06/02 2pp
- --8006170746 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-866/80-07 & 50-867/80-07 Corrective actions purge air blower filters & solenoid valve cleaned MILLS.L M Tennessee Valley Authority 80/05/19 3pp
- --8006170751 Forwards IE Insp Repts 50-566/80-07 & 50-567/80-07 on 800401-04 & notice of violation MURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/04/24 2pp
- --8004170757 Notice of violation from insp on 800401-04
 * Region 2. Atlanta, Office of the Director 80/04/23 ip
- --8006170768 IE Insp Repts 50-366/80-07 & 50-567/80-07 on 600401-04
 Noncompliance nated records on Pour Al-JI show recorded
 water contents incompatible w/recorded slump test data
 Records for Pour A-Pr unreadable
 CONLON.T E Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch HARRIS.J R Region 2, Atlanta, Office of the
 Director 80/04/23 5pp
- 8006240260 Forwards response to IE Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Sequoyah & Watts Bar is provided by redundant heaters & tank insulation MILLS, L M Tennessee Valley Authority 80/06/09 8pp

- 8006170540 Responds to IE insp Repts 50-566/80-03 & 50-567/80-03 re failure to establish adequate measures to control tadaography Radiography of wolds scheduled for completion bu 800701 MILLS.L II Tennusseo Valley Authority 80/06/10 1p
- 5 Reportable occurrences, LERs & related correspondence
- 600a050002 Forwards first interim deficiency rept re placement & compaction of concrete pour A2-Di MICLS.L Di Tennessoe Valley Authority 80/05/27 ip
- --0006050004 First interim deficiency rept re-placement & compaction of concrete pour A2-D1 Concrete placement is being evaluated for acceptability w/G-2 requirements Honeycomb increase determined not excessive
 # Tennessee Valley Authority 80/05/27 1p
- 8006110274 Forwards first interim deficiency rept re Const GA Audit YC-C-80-05 Next rept will be submitted by 800710 MILLS.L M Tennessec Valley Authority 80/05/27 1p
- --8006110284 First intorim deficiency rept le Const GA Audit YC-C-60-05 On 600422, pour not placed & compacted per const specs No GA insp personned Inspectors instructed in requirements of General Const Spec G-2 * Tennessee Vailey Authority 60/05/27 1p
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by UB Steel from which 4-inch elbows & 2-inch tees were mfg to AV34KPB requirement Investigations conducted & closed at A6 listed facilities SEAY.J L. Chemtron Corp., Tube Tuins Div 80/06/06 3pp
- 8006200375 Forwards final deficiency rept re defective concrete pour in auxiliary bldg MILLS.L M Tennessee Valley Authority 80/06/13 ip
- --8006200378 Final deficiency rept re failure of concrete pour A1-P3 to obtain initial set in normal time Apparently caused by abnormal amount of air voids Defective concrete replaced Outline drawings, 4RE0417-5R series.
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- GOO6020220 Summary of BOO507 meeting re partial refund of CP fee Refund will be made using ASLAB average of 6 man-days HOLLOWAY,C J License Fee Management Branch BO/05/19 1p
- G006230110 Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0977 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D G Division of Licensing 80/05/20 13pp
- BOO6060051 Notifies wtil that NRC will refund portion of sum paid in CP fees Fees paid exceeded cost of processing & issuing MILLER.W O License Fee Management Branch 80/05/23 ip
- 8006240077 Informs that effective 800428.Ofc of Nuclear Reactor Regulation was reorganized Mgt of all licensing matters w/respect to facility have been assigned to H Rood Reorganization chart encl TEDESGO.R L Assistant Director for Licensing 80/06/13 10pp
- E NRC Bafety Evaluation Report (BER), supple & correspondence
- 9006300595 "Safety Evaluation re Const of Yellow Creek Nuclear Plant, Units 1 & 2," Suppl 1 4 Office of Nuclear Reactor Regulation, Director NUREG-0347 Si 78/06/27 Sopp Available at NTIS \$6.00
- G Adjudicatory correspondence
- 8006060356 Advises that AH Gutterman will no longer appear in proceedings on behalf of util SANGER, H S Tennessee Valley Authority 80/05/19 3pp

G. Inspection reports. IE Bulletins & correspondence

- 8006050095 Forwards IE Insp Repts 50-566/80-06 & 50-567/80-06 on B00319-21 No noncompliance noted MURPHY, C.E. Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/04/11 2pp
- --8006050103 IE Insp. Repts 50-566/80-06 & 50-567/80~06 on 800319-21 Ng noncompliance noted Major areas inspected inspector followup itoms, 10CFR50 55(e) item, observation of safety-related work activities 2 warehouse insp. CANTRELL, F 5 Region 2, Atlanta, Reactor Construction & Engineering Support Dirench THOMAS, M. Region 2, Atlanta, Office of the Director 80/04/11 3pp.
- 8006060159 Forwards IF Bulletin 80 11. "Masonry Wall Design " No action or written response required IE Info Notice 79-28. "Overloading of Structural Elements Due to Pipe Support Loads" encl O'RETILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08 3bp
- BO06040267 Forwards IE Bulletin BO~12, "Decay Heat Removal Bys Gerability " No written response required IE Info Notice BO~20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" enc! O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/05/09 Goo
- 8006120034 Forwards IE Circular 60-11. "Emergency Diesel Generator Lube Dil Cooler Failures " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/13 300
- 8006040232 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IF lnsp Repts 50-566/80-03 & 50-567/80-03 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 2pp
- --8004040245 Responds to NRC 800228 ltr re violations noted in IE Insp Repts 50-964/80-03 & 50-967/80-03 Corrective actions 800324 & 0421 submittals revised Re-evaluation of radiographs showed only seven welds will require reradiographing MILLS,L M Tennessee Valley Authority 80/04/28 2pp
- ---8006040256 Responds to NRC 800228 ltr re violations noted in IE Insp Repts 50-566/80-03 & 50-566/480-03 Advises that revised response to 800409 ltr will be submitted by 800428 MILLS,L M Tennessee Valley Authority 80/04/21 ip
- 8006170740 Ack receipt of 800519 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-566/80-07 & 50-567/80-07 MMRPHY.C E Region 2. Atlanta Reactor Construction & Engineering Bupport Branch 80/06/02 2pp
- --8006170746 Responds to NRC 800424 ltr re violations noted in IE Insp Repts 50-566/80-07 & 90-967/80-07 Corrective actions purge air blower filters & solenoid valve cleaned MILLS:L M Tennessee Valley Authority 80/05/19 3pp
- --B006170751 Forwards IE Insp Repts 50-566/80-07 & 50-567/80-07 on B00401-04 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/04/24 2pp
- --8006170757 Natice of violation from insp on 800401-04
 * Region 2. Atlanta, Office of the Director 80/04/23 ip
- --8006170768 IE lasp Repts 50-566/80-07 & 30-567/80-07 on 800401-04 Noncompliance noted records on Pour Al-JI show recorded water contents incompatible w/recorded slump test data Records for Pour A-Pr unreadable CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J. R. Region 2. Atlanta, Office of the Director 80/04/23 5pp
- BOO6240260 Forwards response to IC Bulletin 80-05 re vacuum conditions resulting in damage to holdup tanks Freeze protection for refueling water storage tank at Bequoyah & Watts Bar is provided by redundant heaters & tank insulation MILLS.L M Tennessae Valley Authority 80/06/09 8pp
- 8006170540 Responds to IE lnsp Repts 50-566/80-03 & 50-567/80-03 re failure to establish adequate measures to control radiography Radiography of welds scheduled for completion by 800701 MILLE-L M Tennessee Valley Authority 80/06/10 ip

- S Reportable occurrences. LERs & related correspondence
- 8004050002 Forwards first interim deficiency rept re placement & compaction of concrete pour A2-D1 MILLS.L M Tennessee Valley Authority 80/05/27 ip
- ~-8006050004 First interim deficiency rept re placement & compaction of concrete pour A2-D1 Concrete placement is being evaluated for acceptability w/8-2 requirements Honeycomb increase determined not ercessive

 ⊀ Tennessee Valley Authority 80/05/27 ip
- 800A110274 Forwards first interim deficiency rept re Const QA Audit YC-C-80-05 Next tept will be submitted by 800710 MILLS.L M Tennessee Valley Authority 80/09/27 ip
- --8004110284 First interim deficiency rept re Const GA Audit VC-C-20-05
 On 800422.pour not placed & compacted por const specs No
 GA insp performed Inspectors instructed in requirements of
 General Const Spec G-2
 * Tennessee Valley Authority 80/05/27 ip
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows \$2-inch tees were mfg to A2344PB requirement Investigations conducted & closed at 46 listed facilities
 SEAY.J 4. Chemtron Corp , Tube Yurns Div 80/06/06 3pp

DOCKET STN-50-573 KO-RI. UNIT 2

- S Reportable occurrences, LERs & related correspondence
- 6006050236 PNO-V-60-037 on 800516. Mount St Helen erupted Unit 2 has appror 1/8-inch of ash on ground, some ash dust inside plant filtration sys operability confirmed Monitoring to detect abrasive matis in sys components underway RISHOP, T W Region 5. San Francisco. Office of the Director 60/05/19 2pp
- DDCKET BTN-50-574 FAQNAC NUCLEAR POWER PROJECT

 O Adjudicatory correspondence
- B004170792 Confirms T Rothschild 800418 telcon w/BZ Cowan Requests dates of pressure vessel, steam generator, control rod & coalant pump shipments re Westinghouse B00414 opposition to motion for stay pending appeal Certificate of Bvc encl B1CKNIT. C. Office of the General Counsel 80/04/22 4pp
- B006200569 Brief on appeal before US Court of Appeals.BC Circuit, from Commission B00506 orders Case must be remanded to examine US common defense & security under Atomic Energy Act. Nuclear Non-Proliferation Act & NEPA Centificate of Bvc snc1 CURTIS.C E Center for Law & Social Policy CURTIS.C E Natural Resources Defense Council CURTIS.C E Philippine Movement for Environmental Protection B0/06/10 79pp

DOCKET STN-50-591 ESSAR. EBASCO SERVICES

G Inspection reports. 1E Bulletins & correspondence

- 8006120034 Forwards IE Circular 80-11. "Emergency Diesel Generator Lube Oil Cooler Failures " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/13
- DOCKET BIN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

 8 Reportable occurrences, LERs & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US Steel from which 4-inch elbows & 2-inch tees were mfg to A234UPB requirement Investigations conducted & closed at 46 listed facilities
 SEAY.J L Chemtron Corp. Tube Yurns Div 80/06/06 3pp
- DOCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 5

 S Reportable occurrences, LERS & related correspondence
- 8006200024 Final Part 21 rept re mixed heat of steel supplied by US
 Steel from which 4-inch elbows \$ 2-inch tees were mfg to
 A234MPB requirement Investigations conducted & closed at
 46 listed facilities
 BEAY.J L Chemtron Corp , Tube Yurns Div 80/06/06 3pp

DOCKET STN-50-596 NEW HAVEN, UNIT 1

A Application/construction stage documents & correspondence

800.6230110 Advises BHR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREO-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT.D © Division of Licensing 80/05/20 13pp

@ Adjusticatory correspondence

8005110214 Order by State of NY Board on Electric Generation Siting & Environ denying application for rehearing Proceeding closed due to substantial uncertainty about facility ownership Related correspondence MADISGN, S.R. New York, State of 80/05/23 7pp

8006050274 Notice of withdrawal from proceeding Certificate of Svc anci LEWIB, S H Hearing Branch 2 80/06/04 9pp

DOCKET STN-50-597 NEW HAVEN, UNIT 2

A Application/construction stage documents & correspondence

80062301iO Advises BWR & PWR applicants of NRC decision to modify implementation plan presented in Section 4 of NUREG-0577 re adequacy of applicable support structures General operating reactor review procedure & acceptance criteria encl EISENHUT,D G Division of Licensing 80/05/20 13pp

O Adjudicatory correspondence

BOO6110214 Order by State of NY Board on Electric Generation Siting & Environ.denying application for rehearing Proceeding closed due to substantial uncertainty about facility ownership Related correspondence
MADISON, S.R. New York, State of BO/05/23 7pp

8006050274 Notice of withdrawal from proceeding Certificate of Svc enci LENIE:8 H Hearing Branch 2 80/06/04 5pp

DOCKET 50-599 CARROLL FACILITY I

O Adjudicatory correspondence

8006070047 Memorandum & order re intervenors' contentions Accepts State of IL Contentions 4 & 4(b).6 w/o Subparagraphs 6(a)-6(d).7 as modified & others Grants consolidation of certain contentions upon NRC motion HOLTON.R L., BRIGHT.O G., WOLF, J.F. Atomic Safety and Licensing Board Panel BO/05/30 iSpp

--8006090055 Statement of consolidated & modified contentions re Plum River fault terrestrial & aquatic scology. Stransky airport, socio-economic risis & roads at site Certificate of Box encl

* Atomic Safety and Licensing Board Panel. 80/05/30 10pp.

8006170560 Notice of appeal from ASLB 800530 order denying petition to intervene RUNYON, J. 9000L, E Affiliation Unknown 80/06/12 1p

--8006170570 Brief in form of pleading in support of appeal from ASLB B00530 order denying petition to intervene. Case law demonstrates that early site suitability & need for power are warranted as issues Certification of svc enci.

KEDNER-J L Citizens Against Nuclear Power RUNYON. J., GOODL. E Affiliation Unknown B0706/12 lipp

DOCKET 50-600 CARROLL FACILITY 11

9 Adjudicatory correspondence

8006090049 Memorandum & order re intervenors' contentions Accepts State of IL Contentions 4 & 4(b),6 u/o Subparagraphs 6(a)-6(d),7 as modified & others Grants consolidation of certain contentions upon NRC motion HOLTON,R L , BRIGHT,G O,, MOLF,J F Atomic Safety and Licensing Board Panel 80/05/30 19pp

- --8006090055 Statement of consolidated & modified contentions re Plum River fault turrestrial & aquatic ecology, Stransky airport, socio-economic risks & roads at site Certificate of Svc encl # Atomic Safety and Licensing Board Panel 80/05/30 10pp
- BOO6170560 Notice of appeal from ASLB BOO530 order denying petition to intervene KUNDER, J. L. Citizens Against Nuclear Power RUNYON, J., 9000L. E.

intervene KODNER.J L Citizens Against Nuclear Power RUNYON,J, 9000L,E Affiliation Unknown 80/06/12 1p

--BOOS:70570 Brief in form of pleading in support of appeal from ASLB BOO530 order denying petition to intervene Case law demonstrates that early site suitability & need for power are warranted as issues Certification of svc encl KODNER.J L Citizens Against Nuclear Power RUNYON, J. OGOOL, E Affiliation Unknown BO/OS/12 lipp

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

8004190237 Informs of recent organizational change in radiation safety program at BMI Lab HM Faust promoted to assistant group manager for nuclear svc. assuming mpt responsibility of all lab nuclear svc functions TDY.H L Battelle Memorial Institute, Pacific Northwest Laboratory 80/04/02 2pp

8006120438 Advises that major safeguards amend fee is required for review of physical protection plan submitted on 800522 WEISS,D Licensing Management Branch 80/06/02 1p

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

8006250056 Forwards AI-74-44, Suppl 3, "SNM Control Program for EBR-1 Decladding:" as application for amend to License SNM-21 Fee encl Program withheld (ref 10CFR2 790) REMLEY.M E Rockwell International Corp , Energy Systems Div 80/05/01 2pp

8006070041 Forwards IE Insp Rept 70-0025/80-04 on 800114-17 No noncompliance noted BOOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/05/05 2pp

--8006090046 IE Insp Rept 70-0025/80-04 on 800114-17 No noncompliance noted Major areas inspected safety committee activities, operations criticality safety radwaste mgt & followup to IE Bulletin 79-19

BOOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch METZLACH.N, COOLEY,W J Region 5, San Francisco. Office of the Director B0/05/02 Spp

8006030141 Forwards description of site environ around facility for use as increment of analysis in succeeding analyses of effect of natural phenomena upon Pu fabrication facilities
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/07

--8004030146 Recommends endorsement of encl description of site environ around facility as increment of analysis in succeeding analyses of effect of natural phenomena upon Pu fabrication facilities

AVER.JE : BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch 80/05/07 60pp

8006120432 Advises that major safeguards amend fee is required for review of physical protection plan submitted on 800519 WEISS, J D Licensing Management Branch 80/06/02 1p

B006170269 Partial response to FOIA request for documents re NRC insp of Atomics Intl & allegations of 8 Schecter Forwards documents listed in App A FELTON.J M Division of Rules and Records 80/06/03 2pp

--8006170274 Forwards IE Insp Rept 70-0025/79-10 on 791211-14 & notice of deviation BOOK,H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/04/21 2pp

- --8006170292 IE Insp Rept 70~0025/79~10 on 791207 & 11-14

 Noncompliance noted arithmetic calculations of filter
 efficiency of air cleaning sys were found to be in error in
 more than 50% of tests reviewed

 CDDLEY.W J. WDNG.K S. Region 5. San Francisco. Office of the
 Director BODK.H E. Region 5. San Francisco. Fuel Facility &
 Materials Safety Branch BO/04/21 15pp
- --8006170297 Responds to NRC 800421 ltr re deviation noted in IE Insp Rept 70-0025/79-10 Corrective actions written procedures for conducting DOP tests have been revised to clarify & simplify arithmetic manipulations REMLEY, ME Rockwell International Corp 80/05/13 ip
- ---B006170302 Ack receipt of 800513 ltr informing NRC of steps taken to correct deviation noted in IE Insp Rept 70-0025/79-10 BOOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 80/05/21 ip

DOCKET 70-0027 BABCOCK & WILCOX CO

- 8006230121 Bubmits addi info to 800330 ltr Evaluation of core storage facility has been reviewed & approved Nuclear safety calculation performed using KENO & 16-group Hansen-Roach cross section library w/specs of Section III CORDANIR A Babcock & Wilcox Co , Navai Nuclear Fuel Div 80/03/27 1p
- --8006230125 Application for amend to provide for proposed revisions to plant liquid effluent lines Changes reviewed & approved & involve piping revisions & liquid effluent U content measurement Fee & revised license pages encl. CORDANLR A Babcock & Wilcox Co , Naval Nuclear Fuel Div 80/03/25 10pp.
- 8006200132 Forwards certificate of assurance of vendor ability to cover costs of decommissioning all nuclear facilities

 JDRDAN.L V Babcock & Wilcox Co 80/03/28 3pp
- BOOA230072 Forwards certificate to company lenders that all restrictive covenants contained in note agreements have been met.as assurance of ability to cover decemmissioning costs JORDAN-L V Babcock & Wilcox Co 80/03/28 3pp
- BOD6230052 Application for amend to License SNM-42, requesting exception to 10CFR70 51 to delay completion of calculation of associated limit of error of MUF & fissile isotope for U contained in matl in process BOD401-04 W/o encl amend fee CORDANI.R A Babcock & Wilcox Co , Naval Nuclear Fuel Div. BO/03/31 in
- 8006180616 Advises that JP Eckert has been appointed div vice president, replacing JP Ewing who transferred to corporate ofcs in New Orleans, LA CORDANI, R A Bobcock & Wilcox Co , Naval Nuclear Fuel Div. 80/04/28 lp
- 8006040127 Submits review of 780621 license amend application, 780703 revision & 800130 & 0327 suppls Adequate safety is provided in const of addition to north end of Bay 4A & storage of complete power assemblies in addition CROW-W T , KETZLACH, N Uranium Fuel Licensing Branch. 80/04/29 3pp
- 8006180381 Requests 30-day time limit exception for shipment KAS-PCR-49 to complete all measurements of matt Total U analysis of semifinished samples will be performed when equipment available Forwards administrative amend fee W/o encl CORDANI: R A Rabcock & Wilcox Co . Naval Nuclear Fuel Div 80/05/01 ip
- 8004050399 Forwards IE Insp Rept 70-0027/80-06 on 800424-29 Cover sheat only encl Rept details withheld (ref 10CFR2 790), KENNA, W B Region 3: Chicago, Bafeguards Branch, 80/05/09 ip
- --8006050410 IE Insp Rept 70-0027/80-06 on 800424-29 No noncompliance noted Details withheld (ref 10CFR2 790) HIND.J.A Region 3. Chicago. Bafeguards Branch FINLEY, A G. PATTERSDN.J.P Region 3. Chicago. Office of the Director 80/05/07 1p
- 8006020551 Notifies vendor that License 9NM-42 is amended to authorize use of flowmaters & proportional automatic samplers to measure U content of liquid effluents as they are discharged from retention tanks to liquid waste treatment facility PAGE.R 9 Uranium Fuel Licensing Branch 80/05/20. ip

- ---8006020557 Safety evaluation of 800118 license amend application requesting authorization to use flowmeters & proportional automatic samplers to measure U content of liquid affluents. Controls & procedures are adequate to protect public safety. KETZLACH, N . CROW, W T Uranium Fuel Licensing Branch 80/05/20 200
- B006200595 Advises that review of manpower expenditures required for review of Amend 9 to License SNM-42 was less than submitted Ofc of Controller has been notified to send refund MILLER.W D License Fee Management Branch B0/05/27 ip
- 8006300048 Ack receipt of 800320 ltr assuring that B&W has sufficient capital to cover decommissioning costs
 PAGE.R O Uranium Recovery Licensing Branch 80/06/02 1p
- B006300280 Submits contract costs incurred & manhours expended in reviewing 800188 application for amend & B00325 revision to License SNM-422 KETZLACH N Uranium Recovery Licensing Branch 80/04/06 ip
- 8006300519 Ack receipt of 800521 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/79-18 G/REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/12
- ---B006300524 Responds to NRC 800506 ltr re violations noted in IE Insp Rept 70-0027/79-18 Corrective actions withheld (ref 10CFR2 790) ECKERT,J P Bebcock & Wilcox Co , Naval Nuclear Fuel Div 80/05/21 ip
- ---8006300532 Forwards IE Insp Rept 70-0027/79-18 on 791017-800109 & notice of violation Encis withheld (ref 10CFR2 790)
 D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/04 | Ip

DOCKET 70-0033 TEXAS INSTRUMENTS, INC.

- B006200149 Forwards Figures 3-1 & 5-2 of plan for protection of nuclear facilities & matls.inadvertently omitted from B00218 ltr Figures depict plant mgt structure & security organization. ELTIG.M Texas Instruments. Inc B0/04/08 3pp
- 8006200237 Forwards nonproprietary version of IE Insp Rept 70-0033/80-04 No noncompliance noted Details withheld (ref 100FR2 790) MARTIN.W O Region 1, Philadelphia, Safeguards Branch, 80/04/25
- --8006200257 Nonproprietary version of IE Insp Rept 70-0033/80-04 on B00318-21 No noncompliance noted Major areas inspected security plan & organization, physical barriers access controls, keys & locks Datails withheld (ref 10CFR2, 790) LADUN,R H Region I, Philadelphia, Office of the Director, DEVLIN,J W Region 1, Philadelphia, Bafeguards Branch 80/04/23, in
- 800&200520 Forwards IE Insp Rept 70-0033/80-05 on 800407-10. No noncompliance noted. Cover sheet only encl Rept withheld (ref 100FR2 790) MARTIN, W 0 Region 1, Philadelphia, Safeguards Branch 80/04/29.
- --B006200538 Nonproprietary version of IE Insp Rept 70-0033/80-05 on B00907-10 No noncompliance noted Hajor areas inspected: physical inventory reconciliation records & repts shipping & receiving Details withheld (ref 10CFR2 790)
 ZIBULSKY, H. COHEN, I Region 1. Philadelphia, Office of the Director JUYNER, J H Region 1. Philadelphia, Bafeguards Branch B0/04/23
- 8006050053 Ack receipt of 800417 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 70-0033/80-03 SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Bafsty Branch 80/04/30 ip
- --8006080078 Responds to NRC 800403 ltr re violations noted in IE Insp Rept 70-0033/80-03 Corrective actions personnel reinstructed to complete all record items for each occasion of respirator use SCHWENSFEIR:R Texas Instruments, Inc 80/04/17 2pp
- --B0060500B2 Forwards IE Insp Rept 70-0033/80-03 on B00312-14 & notice of violation
 SMITH.6 H Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch 80/04/03 2pp

- --8006050084 Notice of violation from insp on 800312-44

 * Region 1: Philadelphia: Office of the Director 80/04/02 In
- --8006050068 IE insp Rept 70-0033/80-03 on 800312-14 Noncompliance noted failure to maintain records on respirator assignments & leak tests KNAPP,P

tests
KNAPP.P Region 1. Philadelphia, Fuel Facility & Materials Safety
Branch CLEMONS,P Region 1. Philadelphia, Office of the
Director 80/04/02 Spp

800&300011 Forwards updated sections of HFIR project emergency plan W/o encl SCHWENSFEIR.R Texas Instruments, Inc 80/05/21 3pp

DOCKET 70-0036 COMBUSTION ENGINEERING, INC.

- 8006230056 Advises of completion of hydrologic & hydraulic analysis for Joachim Creek in Jefferson County.MO Kundred-yr frequency flood elevation determined to be about 435 5-ft msi Study will be available shortly after 800315 CORBIN.K D Army.Dept of Corps of Engineers 80/03/11 ip
- 8006190417 Forwards Form 10-K. Annual Rept 1979 M/o encl LICHTENBERGER Combustion Engineering, Inc. 80/04/11 ip
- 8006200112 Forwards final draft of Clark Diet: Engineers "Special Study for Joachim Creek, Jefferson County, MD " CORBIN, K D Army, Dept of, Corps of Engineers 80/04/18 ip
- --- 8005200117 Final draft of "Special Study for Jeachim Creek, Jefferson County. No "

 Clark Dietz Engineers 80/03/31 15pp
- 8005040083 Requests submittal of major safeguards amend fee re 800513 transmittal of physical protection plan Plan classified as requiring major amend to License SNM-33 WEISS,D License Fee Management Branch 80/05/20 ip
- DOCKET 70-0089 HASSACHUSETTS INST OF TECHNOLOGY
- 8006300270 Forwards table listing all licenses authorizing BNM, form, location, tupe of math authorized amounts & 800331 inventory Table withheld (ref 10CFR2 790)

 CLARK.L Massachusetts Institute of Technology 80/06/23 ip
- DOCKET 70-0095 MASSACHUSETTS INST OF TECHNOLOGY
- 9004300290 Forwards table listing all licenses authorizing BNM, form, location type of math authorized amounts & 800331 inventory
 Table withheld (ref 100FR2 790)
 CLARKIL Massachusetts Institute of Technology 80/06/23 ip
- DOCKET 70-0124 TELEDYNE ISOTOPES
- 8004300014 Forwards administrative fee for amend to License SNM-107 for exemption to criticality alarm requirement BLACK.8 A Teledyne Isotopes 80/05/20 ip
- DOCKET 70-0135 BABCOCK & WILCOX CO
- B006180344 Forwards revisions to Spec 1-3 & Table 5 0 of Spec 1-5 of License SNM-145 re operations organization changes AUSTIN-M A Babcock & Wilcox Co 80/03/20 15pp
- --8004180330 Forwards approved organizational change evaluation w/complete description Change will maintain & strengthen technical control support of product lines AUSTIN,M A Babcock & Milcox Co. 80703/20 14pp
- --8006180353 Forwards administrative amend fee re B&W 800320 ltr to RC Page concerning technical control dept reorganization AUSTIN.K A Babcock & Wilcox Co 80/03/20 1p
- 8006230103 Notification of current project being undertaken at Nuclear Matls & Mfg Div Project involves dismantling of blue bldg & pump shed In-transit placement of trailers w/burial matl, will be required to assure timely & efficient operation AUBTIN, M A Batcock & Wilcox Co , Nuclear Material Div 80/03/26

- 8005230072 Forwards certificate to company lenders that all restrictive covenants contained in note agreements have been met, as assurance of ability to cover decommissioning costs JORDAN:L V Babcock & Wilcox Co 80/03/28 Spp
- 8006230002 Requests amend of Tech Spec I 8 5 16 per encl revised page, re W Nixon 800328 telcon w/PJ Defilippi Amend will make contamination smear survey frequency consistent w/other applicable survey frequencies
 AUSTIN.M A Babcock & Wilcox Co 80/03/31 2pp
- 8006200554 Notifies of personnel change within B&W Effective 800401, CJ Baroch will replace JS Disems; as General Manager of Nuclear Matls & Mfg Div AUSTIN,M A Babcock & Wilcox Co , Nuclear Material Div 80/04/01
- 8004040124 Submits costs for review of 790814 & 27 applications to amend License SNM-145
 NIXON.W A Uranium Fuel Licensing Branch 80/04/03 ip
- 8006040045 Forwards IE Insp Repts 70-0135/80-07 & 70-0364/80-06 on B00204-29 No noncompliance noted MARTIN.W 0 Region 1. Philadelphia, Safeguards Branch 80/04/08
- --8004040270 IE Inso Reats 70-0135/80-07 & 70-0344/80-04 on 800204-29 No JOBONALZ/O LE INSP Repts /U-0139/80-0/ & /U-0304/80-06 on 80020/ noncompliance noted Major areas inspected mati control, physical security & health & industrial safety Portions withheld fref 10CFR2 790) JUNNER.J H Region 1, Philadelphia, Safeguards Branch KUSHNER.W L Region 1, Philadelphia, Office of the Director, 80/04/07 8pp
- 8006300590 Forwards application for amend of License BNM-145, revising Spec 1 D 5 to assure that employees on extended absences receive required monthly workplace meeting info AUSTIN: H A Babcock & Wilcor Co , Nuclear Material Div 80/04/16
- 9006300593 Application for amond of License GNM-145, revising Spec I B 3 to assure that employees on extended absences receive required monthly workplace meeting info * Babtock & Wilcox Co · Nuclear Material Div 80/04/16 2pp
- 8006170798 Informs that RV Carison will replace EM Benson as manager of PA operations AUSTIN,M R Babcock & Wilcox Co , Nuclear Material Div 80/05/01
- B006060185 Forwards corrected Page 2 for IE Insp Repts 70-0135/79-09 & 70-0364/79-10 Unresolved Item 70-364/78-04-03, mistakenly closed out, will be addressed in IE Insp Repts 70-0135/80-13 & 70-0364/80-12 Encl withheld (r
- 8006270172 Ack receipt of 800328 ltr informing NRC of steps taken to correct violation moked in IE Imap Rept 70-0135/80-04 ORIER.8 H Region 1. Philadelphia. Office of the Director 80/05/22 ip
- --8006270177 Responds to NRC 800305 itr re violations noted in IE Insp Rept 70-0135/80-04 Corrective actions all personally issued masks are being inspected annually by mask fit test chamber operator AUBTIN, M A Babcock & Wilcox Co , Nuclear Material Div. 80/03/28
- --8004270180 Forwards IE Insp Rept 70-0135/80-04 on 800123-25 & notice of violation

 BMITH G H Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch 80/03/05 2pp
- --8006270184 Notice of violation from insp on 800123-25
 * Region i, Philadelphia, Office of the Director , 80/02/25 2pp
- --800627018B IE Insp Rept 70-0135/80-04 on 800123-25 Noncompliance noted four personnel respirators were issued w/o being inspected or documented CLEMONS P. Region 1. Philadelphia. Office of the Director or socumentso
 CLEMONS.P Region 1. Philadelphia, Office of the Director
 CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials
 Safety Branch 80/02/25 7pp
- 8006230006 Advises that no add1 fee is required for review & approval of minor safety & environ amend MILLER:W O License Fee Management Branch 80/06/05 1p

- DOCKET 70-0143 NUCLEAR FUEL SERVICES. INC
- B006200558 Application for amend of License SNM-124 revising exception section of License Condition 2 9 of Amend MPP-1 to include scrap generated from cleanup & equipment mods.791213-B00121 & from cleanupt of U hexafivoride line.800121-0325 Fee encl HENSLEY.K D Nuclear Fuel Services. Inc (subs of Oetty Oil Co.) B0/04/14 4pp
- 800&190203 Forwards Revision 12 to fundamental nuclear matl control plan. Jan 1980 Changes are upgrading mods which do not decrease effectiveness of control plan Encls withheld (ref 10GFR2 790)
 MENSLEY.K D Nuclear Fuel Services, Inc (subs of Ostty Oil Co) 80/04/16 10
- 8004040256 Advises that 60-day extension requested on 800420 to complete procedure for evaluation of shipper/receiver differences is not granted Six months, is sufficient time for compliance Thirty-day extension acceptable KENNA, W B Region 2, Atlanta, Safeguards Branch 80/05/08 ip
- 8006120382 Requests amend of License SNM-124 Proprietary info withheld (ref 100FR2 790)
 HENBLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co)
 8D/03/09 ip
- 9006190350 Application for amend of License BNM-124 as described in encl Fee encl Encl describing amend request withheld (ref 10CFR2 790)
 HENBLEY/K D Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.)
 80/05/09 16
- 8006120391 Ack receipt of IE Insp Rept 70-0143/80~10 dtd 800424 No proprietary info MANSER.W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 80/05/12 1p
- 8006200329 Forwards IE Insp Rept 70-0143/80-10 on 800221-0418 No noncompliance noted Details withheld (ref 10CFR2 770) KENNA.W B Region 2, Atlanta, Safeguards Branch. 80/05/12 2pp
- --B096200338 IE Insp Rept 70-0143/80-10 on 800221-0418 No nencompliance noted Major areas inspected worker concerns, radiation protection, burial shipments & U holdup in diked areas Safeguards & security measures withheld (ref 10CFR2 790) LEE, T D , TODD, G A Region 2, Atlanta, Office of the Director GILLESPIE, F P Region 2, Atlanta, Safeguards Branch B0/04/24
- 8006070378 Advises that License SNM-124 is amended, modifying Conditions 14.17.30 & 32 adding Conditions 61-65, to assure that concentrations of radioactivity both inside & outside plant are as a low as reasonably achievable PAGE,R O Uranium Fuel Licensing Branch 80/05/15 3pp
- 8004190334 Forwards App B to 800509 fundemental nuclear mati control plan Changes are upgrading mods which do not decrease effectiveness of plan Encl withheld (ref 100FR2 790) HENBLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co.) 80/03/15 1p
- 8006160237 Forwards Supplemental IE Insp Rept 70-0143/80-12 on 800317-0424 No noncompliance noted KENNA.W B Region 2, Atlanta, Safeguards Branch 80/05/27 2pp
- --8006160242 Supplemental IE Insp Rept 70-0143/80-12 on 800317-0424 No noncompliance noted Major areas inspected program for nuclear math control & specific license conditions Details withheld (ref 100FR2 790) CLAY, E. L. OLLEBPIE, F. P. Region 2. Atlanta, Safeguards Branch 80/05/23 ip
- 8006170301 Revises License Condition 2 1 of Amend MPP-1 to License SNM-124, effective immediately Based on NRC review, revised Section 1 0 & new App 8 to fundamental nuclear math control plan are both acceptable PARTLCW.J 0 Material Control Licensing Branch 80/05/28 1p
- 8006120396 Forwards Revision 16 to fundamental nuclear math control plan dtd May 1980 Changes consist of upgrading mods Revision withheld (ref 10CFR2 790)
 HENSLEY,K D Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 80/06/02 ip
- 8006300D03 Forwards revisions to fundamental nuclear matl control plan Revisions withheld (ref 100FR2 790)
 HENGLEY,K D Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 80/06/02 1p

- 8006120306 Forwards response to NRC 800516 ltr re violations noted in IE Insp Rept 70-0143/80-12 Encl withheld (ref 10CFR2 790) MANBER: M C Nuclear Fuel Services, Inc (subs of Cetty Oil Co) 80/06/03 io
- 8006250032 Forwards IE Insp Rept 70-0143/80-16 on 800513-16 No nomcompliance noted KENNA.W B Region 2. Atlanta. Safeguards Branch 80/06/04 2pp
- ---8006250035 IE Insp Rept 70-0143/80-16 on 800513-16 No noncompliance noted Major areas inspected measurement control program Details withheld (ref 10CFR2 790)
 OILLESPIE.FP Region 2. Atlanta, Safeguards Branch BATES, J W Region 2. Atlanta, Office of the Director 80/06/03 ip
- 8006300283 Forwards request for add1 info in order to complete review of 800416 fundamental nuclear mat1 control plan. Section A 0 Enc1 withheld (ref 10CFR2 790) PARTLOW, J G Material Control Licensing Branch 80/06/10 1p
- 8006180387 Forwards response to NRC 800306 ltr stating evaluation & significant differences identified in IE Insp Rept 70-0143/79-49 Response withheld (ref 10CFR2 790) MANSER, W C Nuclear Fuel Services, Inc. (subs of Getty Dil Co.) 80/06/11 ip
- 8006:80428 Forwards bimonthly status rept for completing installation on add1 liquid storage capacity for waste water treatment facility
 MICHEL,C J Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.)
 80/06/ii 2pp
- BO061904B1 Application for amend to License BNH-124 Administrative amend fee encl W/o check Amend withheld (ref 10CFR2 790).
 HENBLEY, K D Nuclear Fuel Services, Inc (subs of Getty Dil Co).
 BO/06/13 ip
- BO06190579 Forwards proprietary version of June 1780 App C to fundamental nuclear matl control plan App consists of upgrading mods Info withheld (ref 100FR2 770) HENBLEY, K D Nuclear Fuel Services, Inc (subs of Getty 011 Co.). B0/06/13 1p
- 8006300583 Responds to appeal re denial of FOIA request for documents re licensing of NFS Erwin nuclear fuel facility Danies appeal re App 8 Documents 2.4 & 7 (ref FOIA Exemption 3) Grants appeal for App 8 Documents 1.3.5 & 6 CHILK.S J Office of the Secretary of the Commission, 80/06/16
- --8006300605 Nonproprietary memo recommending that facility license be modified to preclude possession of significant quantities of high enriched U Lists considerations in reviewing paper Info withheld (ref FOIA Exemption 3)
 THOMPSON, H L Commission 79/12/13 2pp
- ---8006300612 Nonproprietary memo recommending that facility be allowed to operate under NRC licensing control w/ID limit of 1% throughput NES must increase physical sacurity as proposed in 86CY-79-650 Info withheld (ref FOIA Exemption 3) AHEARNE, J. Commission 80/01/09 2pp.
- ---B006300629 Nonproprietary memo agreeing w/B00109 memo Commission position on facility Recommends that 1% throughput be considered ID limit goal, w/shutdown & inventory required at 1.5 or 2.0% Info withheld (red FOIA Exemption 3) HENDRIE, J.M. Commission 80/01/11. 1p
- ---B006300635 Concurs w/summary points in 800109 memo recommending Commission position on facility subj to listed requirements Commission decision should be rendered immediately. RENNEDY.R.T Commission. B0/01/15. ip
- 8006240391 Forwards matt balances for inventory period 791206-800507 for low enriched U.Encl withheld (ref 100FR2 790), HENGLEY, K.D. Nuclear Fuel Bervices, Inc. (subs. of Getty 611 Co.) 80/06/17. 1g
- 8006240403 Ack receipt of 1E Insp Rept 79-0143/80-15 No proprietary info MANSER, N. C Nuclear Fuel Bervices, Inc (subs of Oetty Oil Co), 80/06/17. ip
- 8006250235 Forwards Revision 14 to fundamental nuclear mati control plan Revision withheld (ref 10CFR2 790)
 HENBLEY, X D Nuclear Fuel Services, Inc (subs. of Getty Gil Co), 80/06/18 ip

DOCKET 70-0194 MASSACHUSETTS INST OF TECHNOLOGY

- 8006300290 Forwards table listing all licenses authorizing BNK form location type of math authorized amounts & 800331 inventory Yable withheld (ref 10CFR2 790) CLARK. L Massachusetts Institute of Technology 80/06/23 ip
- DOCKET 70-0267 NUCLEAR SCIENCE & TECHNOLOGY FACILITY AT SUNY
- 8006190677 Requests NRC action on 760714 application for revision of Licenses SNN-273 & SNM-723 HERRY,L Q New York, State Univ of, Buffalo (10/05/02 lp.
- --8006190679 Requests current status of 760816 application for revision of Licenses BNM-273 & SNM-723
 THOMAS.C C New York. State Univ of, Buffalo 79/07/14 ip
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 8006240198 Forwards revisions to Demonstration II-0 of License SNM-414. changing page numbers Pages were inadvertently misnumbered when originally submitted for review & approval AUSTIN.M A Babcock & Wilco. Co. Nuclear Material Div. 80/03/18
- 8006200156 Forwards change in organization & evaluation Change will strengthen technical control support of product lines. AUSTIN M A Babcock & Wilcox Co., Nuclear Material Div. 80/03/20
- 8006200584 Confirms 800313 & 24 telcons & formalizes 8&W understanding of Condition I3 of License SNK-414 re intended phasedown of Pu facility operations Data reduction requirement may be waived following review of first yr data AUSTIN.M A Babcock & Wilcox Go , Nuclear Material Div 80/03/25
- 8006200585 Notifies of intention to phase down Pu facility activities at site As a result, physical security upgrades required by applicable regulations will not be implemented AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div 80/03/26 to
- 8006230072 Forwards certificate to company lenders that all restrictive covenants contained in note agreements have been met, as assurance of ability to cover decommissioning costs JORDAN, L. V. Babcock & Wilcox Co. 80/03/28 3pp
- 8006200354 Notifies of personnel change within 8&W Effective 800401.CJ Baroch will replace JS Driewisz as General Hanager of Nuclear Hatls & Hig Div AUSTIN.M A Babcock & Wilcox Co., Nuclear Material Div 80/04/01
- 8006040:045 Forwards IE Insp Repts 70-0135/80-07 & 70-0364/80-06 on 800204-29 No moncompliance noted MARTIN.W 9 Region 1. Philadelphia, Safeguards Branch 80/04/08
- --8006040270 IE insp Repts 70-0138/80-07 & 70-0364/80-06 on 800204-29 No noncompliance noted Major areas inspected mat1 control, physical security & health & industrial safety Portions withheld (ref 10CFR2 790)
 JOYNER, J. H. Region 1, Philadelphia, Bafeguards Branch KUSHNER, W. L. Region 1, Philadelphia, Office of the Director 80/04/07 | Bpp
- 8006190421 Forwards addl info re mini-plan for storage/staging area at site.in response to NRC 800410 request Encl withheld (ref 100FRZ 790)
 AUSTIN-M A Babcock & Wilcov Co , Nuclear Material Div. 80/04/15 ib.
- 8006250111 Application for amend to License BNN-414 per W Buckhardt 800416 telcon w/PJ Defilippi Amend assures required training to all employees & does not decrease effectiveness of training program AUSTIN, M.A. Babcock & Wilcox Co. 80/04/16 Spp.
- 8006170798 Informs that RV Carlson will replace EM Benson as manager of PA operations
 AUSTIN.M.R Babcock & Wilcox Co., Nuclear Material Div 80/05/01
 ip

- 8006060185 Forwards corrected Page 2 for IE Insp Repts 70-0135/79-09 & 70-0364/79-10 Unresolved Item 70-364/78-04-03 mistakenly closed out-will be addressed in IE Insp Repts 70-0135/80-13 & 70-0364/80-12 Encl withheld (ref 10CFR2 790)
 MARTIN,W 0 Region 1. Philadelphia, Safeguards Branth 80/05/08
- 8006300023 Forwards revision to fundamental nuclear matl control plan Revision withheld (ref 10CFR2 790) AUSTIN.M A Babcock & Wilcox Co 80/05/28 ip
- 8006250148 Advises of refund following submittal of fee for OL Amends 6 & G MILLER,W O License Fee Management Branch 80/06/04 ip
- 8006260230 Advises of revision to Safaguards Amend MPP-1 to License SMM-414. effective immediately Adds new License Condition 2 1 2 Maste storage plan submitted by licensee acceptable PARTLOW JQ Material Control Licensing Branch 80/06/04 1p
- DOCKET 70-0371 UNITED NUCLEAR CORP
- 800606015B Forwards revised emergency plan & comments KIRK,W F United Nuclear Corp ,Naval Products Div 80/02/01 11pp
- --B006060160 Revised emergency plan * United Nuclear Corp .Naval Products Div 80/01/25 48pp
- 8006030026 Forwards IE Insp Rept 70-0371/80-03 on 800314-20 No noncompliance noted MARTIN.W G Region 1, Philadelphia, Safeguards Branch 80/04/16 in
- --8006030029 IE Insp Rept 70-0371/80-03 on 800314-20 No noncompliance noted Major areas inspected physical inventory procedures Details withheld (ref 10CFR2 790) JOYNER, J H Region 1, Philadelphia, Safeguards Branch COHEN, I , ZIBULBKY, H Region 1, Philadelphia, Office of the Director B0/04/14 3pp
- 8006180111 Forwards IE Insp Rept 70-0371/80-04 on 800402-03 No noncompliance noted 8MITH.9 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/29 2pp
- --8004180114 IE Insp Rept 70-0371/80-04 on 800402-03 No noncompliance noted Major areas inspected licensee program for packaging low level radwaste for transport & burial KINNEY.W W Region 1. Philadelphia. Office of the Director CROCKER.H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch BD/04/28 Spp
- 8006260239 Expresses concern re potential adverse impact on facility safeguards program of licensee decision to terminate recovery of high enriched U Excessive scrap not conducive to effective safeguards may accumulate PARTLOW.J O Material Control Licensing Branch 80/06/06 1p
- DOCKET 70-0398 COMMERCE, DEPT OF
- B006060405 Ack receipt of B00422 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0398/80-02. SMITH, O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch B0/05/07 ip
- ---B006060457 Responds to NRC 800327 ltr re violations noted in IE Insp Rept 70-0378/80-02 Corrective actions large quantity radioactive matls shipments have been terminated effective 800321 BELL.K E Commerce, Dept of, National Bureau of Standards 80/04/22 App
- --8006060464 Forwards IE Insp Rept 70-0398/80-02 on 800227-29 & notice of violation SMITH/O H Region i, Philadelphia, Fuel Facility & Materials Safety Brench 80/03/27 2pp
- --8006060469 Notice of violation from insp on 800227-27

 * Region 1, Philadelphia, Office of the Director 80/03/27. 1p
- --8004040472 IE Insp Rept 70-0398/80-02 on 800227-29 Noncompliance notes.

 GA program for shipping packages not submitted to NRC & approx 27 shipments of fissile radioactive matls made 790110-1210

 ROTH, J. Region 1, Philadelphia, Office of the Director CROCKER, H W. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/03/27 7pp

- 8006230067 Forwards physical security plan for protection of SNM of moderate & low strategic significance W/o encl HOBBS.T Q Commerce.Dept of National Bureau of Standards 80/05/14 ip
- DOCKET 70-0442 HEW, DEPT OF, FOOD & DRUG ADMINISTRATION
- 8006050655 Ack receipt of 800425 ltr informing NRC of corrective actions taken re IE insp of Licenses 19-07538-01,19-07538-03 & SNM-402 on 800310 CRUCKER,H W Region 1. Philadelphia. Office of the Director 80/05/08 1p
- --8006050661 Discusses IE insp of Licenses 19-07538-01,19-07538-03 & SNM-402 on 800310 & forwards notice of violation CROCKER.H W Region 1, Philadelphia, Office of the Director 80/04/02 2pp
- --800&050&65 Notice of violation re IE insp of License 19-07838-01 on B00310 Noncompliance noted failure of radiation safety committee to meet since 780831 # Region i. Philadelphia, Office of the Director 80/04/02 ip

DOCKET 70-0572 MONSANTO RESEARCH CORP

- 8006190213 Requests exemption from requirements of 10CFR73 47 Wishes to possess & present for shipment Pu w/isotopic concentration greater than 78% of Pu-238 w/o being subj to physical security provisions
 TAYLOR, R. R. Monsanto Research Corp. 80/03/12 ip
- --8006190219 Forwards check to cover fee for review of amend to License SNM-567 TAYLOR.R R Monsanto Research Corp 80/03/31 ip
- ---8006190227 Ack receipt of 800312 ltr re amend to License BNM-567 for exemption from 10CFR73 47 Amend five required Request being reviewed by licensing staff WEISB.D License Fee Management Branch 80/03/19 ip

DOCKET 70-0423 KENYON COLLEGE

8006130290 Informs that personnel whole body expoure monitoring not required during CY79
MILLER: F Kenyon College 80/05/02 1p

DOCKET 70-0487 UNION CARBIDE CORP

- 8004230021 Revised application for amend to permit U recovery from waste, Revision supersedes 791229 request in entirety VOTH.M H Union Carbide Corp 80/04/02 16pp.
- 800606003B Forwards IE Insp Rept 70-0687/80-02 on 800127-0201 SMITH: 0 H Region i, Philadelphia. Fuel Facility & Materials Safety Branch 80/04/18 Zpp
- --800606004i IE Insp Rept 70-0687/80-02 on 800i29-020i No noncompliance noted Major area inspected licensee program for packaging low level radwaste for transport & burial KINNEY,W W , KOTTAN,J J Region 1, Philadelphia, Office of the Director CRUCKER,H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/17 9pp
- 8006120090 Forwards combined IC Investigation Repts 50-054/80-01 27-0048/80-01,27-0039/80-01,30-05986/80-01 & 70-0687/80-01 NRC has proposed civil penalties to Union Carbids, Smith Kline & French Labs Respective states & DOT notified, ORIER,B H Region 1, Philadelphia, Office of the Director BO/04/18 2pp
- --8006120095 IE Combined Investigation Repts 50-054/80-01.27-0048/80-01. 27-0039/80-01.30-05986/80-01 % 70-0687/80-01 Union Carbide failed to mark bill of lading Smith Kline & French Labs failed to use proper packaging CROCKER,H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 44pp

- B004180417 Forwards Waste Packaging Insp Rept 80-03 on B00227-29 No noncompliance noted SMITH, G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/04/24 2pp
- --8006180624 Waste Packaging Insp Rept 80-03 on 800227-29 No noncompliance noted Major areas Inspected compliance of licensee-shipper vehicles w/NRC & DOT regulations including shipping paper & placanding requirements & radiation levels POTTER. J P. PEERY. W W. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/17 7pp
- 8006300682 Requests info to supplement 800402 application for amend to License SNM-639 to authorize mods to existing wasta handling process Info needed re waste form conversion process, process equipment & airborne efficients ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/22 200
- DOCKET 70-0698 WALTZ MILL SITE, WESTINGHOUSE ELECTRIC CORP
- BOO6200101 Forwards application for renewal of License SNM-770 DIPIAZZA,R P Westinghouse Electric Corp 80/04/01 32pp
- --B006200107 Application for renewal of License SNM-770
 * Westinghouse Electric Corp 80/04/01 144pp
- 8006160217 Forwards 1980 program for decommissioning of retired Westinghouse test reactor facilities.

 DIPIAZZA.R P Westinghouse Electric Corp 80/05/05 7pp.
- 8006300191 Confirms 800501 telcon & 800423 itr re release of retired Westinghouse test reactor PIF facilities under Licenso SIMM-770 Areas decontaminated to unrestricted limits will remain licensed areas until action taken by NRC KETZLACH.N Uranium Fuel Licensing Branch 80/06/05 ip.
- DDCKET 70-0734 GENERAL ATOMIC CO
- 8006200565 Requests meeting to discuss plans for upgrading physical protection of high enriched U Facility visit scheduled for wk of 800415 MOWRY, W R General Atomic Co (subs of Guif Dil Co) 80/04/07 Ann
- BOO6040050 Advises that License SNM-1507 is revoked & Condition 19 is added to SNM-676, authorizing possession of U-235 & transport of matl to & from authorized persons Shipper responsibility exempted between vendor facilities PAGE.R Q Uranium Fuel Licensing Branch BO/05/02, 2pp
- 8004090569 Notifies that License SNM-1507 has been revoked & Condition 19 added to License SNM-496, authorizing possession of U emriched in U-235 isotope PAGE.R Q Uranium Recovery Licensing Branch 80/05/02 2pp
- 8006170846 Forwards IE Insp Rept 70-0734/80-03 on 800428-0504.No noncompliance noted Rept withheld (ref 100FR2 790). NORDERHAUG, L. R. Region S. San Francisco, Bafeguards Branch. 80/06/06 2pp
- DOCKET 70-0754 VALLECITOS NUGLEAR CENTER, GENERAL ELECTRIC CO
- 8006190184 Responds to 800222 itr re iOCFR70 reviews & audits Vendor practice is to have closeout mesting w/responsible managers on last day of investigations Recommendations have no basis in regulation & should be withdrawn from statement MOSCHNER, R A General Electric Co , Nuclear Energy Products Div 80/03/10. 19
- 8006190093 Disapproves use of primary routing identified in 791226 ltr to NRC Route traverses heavily populated areas Acceptable alternative route is available Approved route and, Route withheld (ref 10CFR2 790).

 MCCORKLE. G W Physical Security Licensing Branch 80/04/07 2pp.
- B006200125 Forwards Pages B-1 & 8-2 to fundamental nuclear mati control plan Enci withheld (ref 10CFR2 790)

 * General Electric Co., Nuclear Energy Products Div 80/04/11 ip
- 8006200127 Forwards Pages 8-1 & 8-2 to fundamental nuclear mati control plan Encl withheld (ref 10CFR2 790)

 * General Electric Co , Nuclear Energy Products Div. 80/04/11 ip.

- 8005190424 Forwards request for route approval for shipment of irradiated reactor fuel W/o enci XIRKLAND, H W General Electric Co 80/04/14 1p
- 8005200046 Forwards "Seismic Evaluation of Vallecitos Site " HALLUM J. NEWMARK.N M N M Newmark Consulting Engineering Services NRC-03-78-150 80/04/14 ip
- --8006200050 "Seismic Evaluation of Vallecitos Site "
 NEWMARK, N M , HALL, H J N M Newmark Consulting Engineering
 Services NRC-03-78-150 80/04/14 6pp
- 8006040136 Notification of 800507 meeting w/Univ of IL & TERA Corp in Silver Spring.NO to discuss Part 2 of site seismicity re Verone fault BURKHARDT.N Advanced Fuel & Spent Fuel Licansing Branch 80/04/30
- 8006090050 Forwards IE Insp Rept 70-0754/80-02 on 800325 No noncompliance noted 800K.H E Region 5, San Francisco. Fuel Facility & Materials Safety Branch 80/04/30 2pp
- --8004090054 IE Insp Rept 70-0754/80-02 on 800325 No noncompliance noted Major areas inspected actions taken in response to IE Bulletin 79-19
 BUDK, H. E. Region 5, San Francisco, Fuel Facility & Materials BODK.H E Region 5, San Francisco, Fuel Facility & Materiale Safety Branch THOMAG.R D , COOLEY.W J Region 5, San Francisco, Office of the Director 80/04/30 App
- BOOA090349 Requests payment of major safeguards amend fee to 800509 physical protection plan for SNM of moderate strategic significance WEIBS, J D License Fee Management Branch 80/05/22 ip
- 8006300001 Denies 800414 & 0505 requests for approval of primary route for transport of spent reactor fuel due to passage through heavily populated areas Approves and B00305 supplemental route Encl route & related data withheld (ref 100FR2 790) MCGORKLE.O W Physical Security Licensing Branch 80/06/03 2pp
- DOCKET 70-0778 GENERAL ELECTRIC CO . NUCLEAR ENERGY PRODUCTS DIV
- 80062302B7 Forwards info requesting route approval for s irradiated reactor fuel per 10GFR73 Encl withheld (ref 10GFR2 790) CORRIER / M J. General Electric Co , Nuclear Energy Products Div 80/04/23 ip
- DOCKET 70-0785 STATE UNIV OF NEW YORK AT BUFFALO
- 8006190677 Requests NRC action on 760714 application for revision of Licenses SNM-273 & SNM-723 HENRY,L Q New York, State Univ of, Buffalo, 80/05/02 ip
- --8006190679 Requests current status of 760816 application for revision of Licenses 8NM-273 & 8NM-723 THOMAS.C C New York, State Univ of, Suffalo 78/07/14 ip
- DOCKET 70-0820 UNITED NUCLEAR CORP
- 8006180374 Forwards mods to License BNM-777, revising technical specialist degree requirements \$ inserting min scheduling requirements for svcs of consulting criticality safety specialist per RL Stevenson B00616 ltr.

 BOWERS, C E United Nuclear Corp , UNC Recovery Systems Div 800707374
- 8006230147 Forwards Revision 1 of Amend MPP-2 to License SNM-777 PARTLOW, J. Q. Material Control Licensing Branch. 80/03/28 1
- 8006230153 Revision 1 of Amend MPP-2 to License SNM-777. Incorporates revised pages of fundamental nuclear mati control plan & revised license conditions Revised nuclear control plan was forwarded in 800307 ltr ### Haterial Control Licensing Branch, 80/03/28 Spp.
- 6006190732 Amends License 8NM-777 to authorize waste processing operations as described in 800128 application Revised Page 188 encl Guantity of U-235 per cubic ft shell not exceed PAGE, R Q Uranium Fuel Licensing Branch 80/04/01 ip.

- --8006190735 Amend i3 to License SNM-777 consisting of revised Page 188 Lists effective pages to incorporate into amended license * United Nuclear Corp 80/04/01 1p
- 8006240231 Forwards revised Page 3, Section 200, to reflect changes in BO/C4/22 2pp
- 8006190083 Forwards IE Insp Rept 70-0820/80-03 on 800331-0402 No noncompliance noted , Philadelphia, Fuel Facility & Materials Safety Branch 80/04/27 2pp
- -8006190038 IE Insp Rept 70-0820/80-03 on 800331-0402 No mancompliance undividual in the kept /0-082/80-03 on Social-9422 we hancompilant noted Major areas inspected packaging of low level radwaste for transport & burial CROCKER.H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch Kinner, W W Region 1. Philadelphia. Office of the Director 80/04/28 7pp
- 8006250014 Advises of decommissioning plans Small quantity of scrap on hand will be reprocessed by 800701,followed by concentrated program of site decontamination Total SNM inventory should be below 5 kg by early Fall,1980 BOWERS.C E United Nuclear Corp , UNC Recovery Systems Div 80/04/29 1p
- 8006020045 Safety evaluation re United Nuclear Corp 790521 application for amend of administrative procedures United Nuclear should not use offsite safety specialists to exclusion of full-time safety officer on site STEVENSON, R.L., CROW, W.T. Uranium Fuel Licensing Branch 80/05/07
- B006240180 Forwards IE Insp Rept 70-0820/80-04 on 800407-11 No noncompliance noted MARTIN.W Q Region 1. Philadelphia, Safeguards Branch 80/05/07
- --B0062401BB IE Insp Rept 70-0820/B0-04 on 800407-11 No mancompliance OUASEMOURD IE insp Rept 70-0820/80-04 on BU040/-11 No moncomy noted Major areas inspected physical barriers access controls, response controls, central alarm & communication sys Details withheld (ref 10CFR2 790) DEVLIN, J W Region 1, Philadelphia, Safeguards Branch Li Region 1, Philadelphia, Office of the Director 80/05/01 LADUN, R H
- B006250153 Confirms B00514 telcon re B00527 meeting to present plans for decommissioning & interaction towards decommissioning List of topics for discussion encl OREGO,R J United Nuclear Corp , UNC Recovery Systems Div B0/05/14 3pp
- 8006300214 Responds to 800217 ltr re restrictions on commercial burist of radwastes & potential impact on lagoon cleanout schadule Buggests utilizing commercial radwaste disposal facilites, if DDE negotiations are unsuccessful, PAGE.R Q Uranium Fuel Licensing Branch 80/06/06 2pp
- DOCKET 70-0824 BABCOCK & WILCOX CO
- 8006250011 Forwards Lynchburg Research Ctr.Bldg C security plan Plan withhold (ref 100FR2 790)

 OLSEN.A.F. Babcock & Wilcox Co 80/03/20 1p
- 8006250208 Forwards Revision 11 to BAW-381. "Demonstration & Conditions for License SNM-778." adding impact absorbing mat1 to hot cell storage pool floor to insure limiting criterion not GLSEN, A, F Babcock & Wilcox Co 80/03/24 2pp
- --8006250211 "Demonstration & Conditions for License SNM-778," Revision 11 replacing Pages A-1 & A-2 re addition of impact absorbing matl to hot cell storage pool floor # Babcock & Wilcox Co BAM-381 Ri1 80/03/31 3pp
- B006200165 Forwards Amend 11.Revision 10 to BAW-381. "Demonstration & Conditions for License SNM-778." clarifying conditions under which fuel rod segments may be placed in irradiated commercial fuel assemblies
 OLSEN.A F Babcock & Wilcox Co. 80/03/25 2pp
- --8006200169 "Demonstration & Conditions for License SNM-778," Amend 1%-Revision 10, Pages A-35d & A-36 re fuel assemblies & hot cell Babcock & Wilcox Co BAN-381 RIO 80/03/31. 3pp

- --8006200172 "Demonstration & Conditions for License SNM-778," Amend O. Revision 6.Pages A-41 % A-42 re fuel rod dismantlement, shipment & disposal # Babcock & Wilcox Co BAW-381 R6 80/03/31 4pp
- 8006230072 forwards certificate to company lenders that all restrictive covenants contained in note agreements have been metias assurance of ability to cover decommissioning costs JCRDAN, L V Babcock & Wilcox Co 80/03/28 3pp
- 8006180162 Forwards revised replacement pages for DAK-301, "Demonstration & Conditions for License SNM-778," dtd 700531 & 781231 re renewal application OLSEN.AF Babcock & Wilcox Co 80/04/08 ip
- ---8006180165 Revised replacement Pages 3-32.3-32a.A-19 & A-20 for "Demonstration & Conditions for License SHM-778." 700531 * Babcock & Wilcox Co BAM-381 80/04/30 6pp
- --B0061B0169 Revised replacement Pages 3-17,3-18,3-27,A-28,3-19 & 3-20 for "Demonstration & Conditions for License SNM-778," 781231 renewal application * Babcock & Wilcox Co BAW-381 B0/04/30 Bpp
- 8006180378 Forwards revised pages for security personnel qualification training & equipment plan Pages withheld (ref 100FR2 790)
 OLSEN, A.F. Babcock & Wilcox Co. 80/04/30 ip
- 8006020041 Safety evaluation re B&W 800218 amend application & 800325 & 0408 suppls requesting const & use of temporary addition to Bldg J for storage of solid transuranium waste Recommends issuance of amend KETZLACH, N Uranium Fuel Licensing Branch 80/05/07 2pp
- 8006130269 Forwards License SNM-778 Apr 1980 rept for normal operating losses, matl unaccounted for & burnup of SNM LONG, K D Babcock & Wilcox Co 80/05/07 2pp
- 8006040087 Forwards replacement pages for renewal application to License SNM-778 CLSEN-A F Babcock & Wilcox Co 80/05/09 ip
- --8006040092 Replacement pages for renewal application to License SN4-778 * Babcock & Wilcox Co 80/05/31 App
- B006090159 Forwards replacement page for Section 1 & two add1 pages for Section 2 O of GA plan per NRC 800314 request OLSEN, A F Babcock & Wilcox Co 80/05/15 4pp
- 8006250156 Forwards Revision il to application for renewal of License SNM-778 DLSEN,A F Babcock & Wilcox Co 80/05/20 ip
- --8006250160 Revision 1: to application for renewal of License SNM-778.

 * Babcock & Wilcox Co 80/05/20 13pp
- 8006200600 Advises that review of manpower expenditures required for Amend 11 to License SNM-778 was less than submitted Ofc of Controller has been notified to send refund MILLER.W O License Fee Management Branch 80/05/27 ip
- 8006270067 Forwards BAW-3Bi, "Demonstration & Conditions for License 8NM-778 (Renewal Application)," Revision 12 DLSEN.A F Babcock & Wilcox Co 80/05/30 ip
- ---8006270071 "Demonstration & Conditions for License SNM-778 (Renewal Application)." Revision 12

 * Babcock & Wilcox Co BAW-381 R12 80/05/31 7pp
- 8006260244 Advises licenses of partial refund of fee accompanying 800218 application for amend to License 8NM-778 Manpower expenditures required to review application were less than anticipated MILLER, W.O. License Fee Management Branch 80/06/06 in
- 8006160122 Forwards rept for normal operating losses.matl unaccounted for & turnup of SNM
 LONG, K D Babcock & Wilcox Co 80/36/07 2pp
- 800A30021A Grants 800A13 request for extension until 800701 to complete final corrective action re two previously reported items of noncompliance KENNA.W B Region 2, Atlanta, Safeguards Branch 80/06/17 ip

DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP

- 8006020260 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Sys intended for use during emergencies to link all power plants & NRC Emergency Notification Sys hotline will also be used KEPPLER. J G Region 3, Chicago, Office of the Director 80/04/18 200
- DOCKET 70-0938 MASSACHUSETTS INST OF TECHNOLOGY
- B006300290 Forwards table listing all licenses authorizing SNM, form, location, type of math authorized amounts & 800331 inventory Table withheld (ref iOCFR2 790) CLARK, L. Massachusetts Institute of Technology 80/06/23 ip
- DOCKET 70-0984 PACIFIC NORTHWEST LAB
- BD06230019 Forwards responses to NRC questions re application for renewal of License SNM-942, decommissioning plan for laboured facilities & Revision 7 to renewal application OLEGEN, D & Bottelle Memorial Institute, Pacific Northwest Laboratory 80/03/27 ip
- ---8006230022 Provides assurance that lab will maintain sufficient financial resources to decontaminate & decommission lab-owned facilities at such time as action may be appropriate GLESEN, D E Battelle Memorial Institute, Pacific Northwest Laboratory 80/03/18 1p
- --8004230025 "Decommissioning of BNWL-Duned Facilities at Richland.WA"
 Response to NRC comments & questions re license remewal
 application enci
 # Battelle Memorial Institute, Pacific Northwest Laboratory
 80/03/27 18pp
- --8004230026 Revision 7 to application for renewal of License SNM-942 * Battelle Memorial Institute, Pacific Northwest Laboratory 80/03/19 48pp
- DOCKET 70-1007 GENERAL ELECTRIC CO
- 8006130006 Application to amend Certificate of Compliance 9019 for BU-7 package to increase mar bulk density of U oxide powder from 2 3 to 4 2 g/cc Amend fee encl KAPLAN.A L. General Electric Co , Nuclear Energy Products Div 80/05/15 2pp
- --B0D613000B Forwards Certificates of Compliance 901B & 9019, authorizing delivery of radioactive matl to carrier for transport in Models BU-6 & BU-7 Vendor authorized to use Models BU-6 & BU-7 under License SM-54 MACDONALD.C E Transportation Branch 74/08/06 ip
- --8006130012 Certificate of Compliance 9019, authorizing delivery of radioactive matl to carrier for transport in Models BU-6 & BU-7 Vendor authorized to use Models BU-6 & BU-7 under License SRN-54 MACDONALD, C.E. Transportation Branch, 74/08/06. 4pp
- ---8006130013 Application to amend License SNM-54 to authorize delivery of SNM to carrier for transport in Models 8U-6 & BU-7 TSCHAECHE: A N General Electric Co 74/05/24, 16pp
- --8006130015 "GE Model BU-7 U Shipping Container Criticality Safety Analysis " ARTIGAS,R , WILSON,B D General Electric Co NEDO-11277 74/02/28 9pp
- DOCKET 70-1100 COMBUSTION ENGINEERING. INC
- 8006170753 Forwards revised Page 3 1 of fundamental nuclear maticontrol plan per iOCFR70 32 & NRC 790706 1tr BDWIE,T B C-E Power Systems 80/03/19. 2pp
- BO06200151 Forwards definition of book record or book balance to be added to Chapters 5 & 6 of fundamental nuclear mat1 control plan.per B00125 request LICHTENBERGER.H C-E Fower Systems 80/04/02 App.
- BOO6190417 Forwards Form 10-K, Annual Rept 1979 W/o encl LICHTENBERGER Combustion Engineering, Inc. 80/04/11 ip

- 8006040142 Requests submittal of major safeguards amend fee re 800516 transmittal of physical protection plan Plan classified as requiring amend to License SNH-1057 WEISS, D License Fee Management Branch C 80/05/21 ip
- 8006300934 Adds License Condition 5 2 of Amend MPP-4 to License SNM-1067.permitting physical inventories of low-enriched U at intervals not enceding 210 days PARTLONIJ 9 Physical Security Licensing Branch 80/06/09 1p
- DOCKET 70-1113 GENERAL ELECTRIC CO
- BOO6200344 Forwards info re SAM II calibr in response to EJ McAlpine BOO318 request KAPLANA L General Electric Co , Nuclear Energy Products Div BO/03/20 4pp
- BOOA230045 Forwards revisions to fundamental nuclear mati control plan. Plan withheld (ref 10CFR2 790) KAPLAN.A L General Electric Co . Nuclear Energy Products Div 80/03/21 1p
- 800&1803&3 Forwards statistical summary of personnel monitoring during 1979 KAPLAN,A L. General Electric Co., Nuclear Energy Products Div. 80/03/28 2pp.
- 8006i60223 Forwards latest revisions to fundamental nuclear matl control plan Encl withheld (ref 10CFR2 790) KAPLAN, A L General Electric Co . Nuclear Energy Products Div. 80/04/10 ip
- 8006270369 Forwards revisions to fundamental nuclear matl control plan Revisions withheld (ref 100FR2 790) KAPLAN. A L General Electric Co , Nuclear Energy Products Div. BO/04/24 ip
- 8006020067 PND-II-80-083 criticality warning sys experienced false alarm & fuel mfg bldg was evacuated Licenses determined no abnormal radiotion levels existed Re-entry team verified that radiation levels were normal OILLESPIE.F P . KENNA. # 8 Region 2. Atlanta. Office of the Director 80/05/13 ip
- 8005270365 Forwards changes to fundamental nuclear matl control plan Changes withheld (ref 10CFR2 790) KAPLAN.A L. General Electric Co , Nuclear Energy Products Div 80/05/14 ip
- 8006090489 Ack receipt of itr reporting results of IE Insp Rept 70-1113/80-06 on 800421-25 Requests rept be withheld (raf 10CFR2 790) KAPLAN, A L General Electric Co., Nuclear Energy Products Div 80/05/20 ip
- B006040249 Requests submittal of major safeguards amend fee re 800516 transmittal of physical protection plan Plan classified as requiring major amend to License SNK-1097 WEISB, D. License Fee Management Branch B0/05/21. 1p
- 8006050418 PND-II-80-092 on 800520, release from pipe flange to work area of less than 1 kg U hexafluoride occurred Ten workers evacuated from area No detectable personnel exposures resulted CORYELL. G P , KENNA. W B Region 2, Atlanta, Office of the Director 80/05/22 1p
- 8006200431 Forwards add1 info for 800409 response to IE Insp Rept 70-1119/80-02 Info includes mat1 control & accounting procedures KAPLAN,A L. General Electric Co., Nuclear Energy Products Div, 80/06/13 7pp

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

()

- 8005200576 Forwards manual. "Physical Security Plan for Protection of SNM of Moderate Strategic Significance at Cheswick Site." for NRC approval.Fee encl Plan withheld (ref 10CFR2 790). B1PIAZZA.R P Westinghouse Electric Corp 80/03/11 ip
- 8006050514 Forwards IE Insp Rept 70-1143/80-04 on 800218-21.No noncompliance noted MARTIN, W Q Region 1, Philadelphia, Safeguards Branch 80/04/09. 2pp

- --8006050514 IE Insp Rept 70-1143/80-04 on 800218-21 No noncompliance noted Major areas inspected preshipment planning, shipping containers, seals 2 in-transit procedures Details withheld (ref 10CFR2 790)
 DEVLIN, U , LADUN, R , MADDEN, W Region 1, Philadelphia, Bafeguards Branch 80/04/07 1p
- B006050513 Forwards IE Insp Rept 70-1143/80-08 on B00326-27 No noncompliance noted MARTIN,N O Region I. Philadelphia, Safeguards Branch B0/04/16 200
- --800a050517 IE Insp Rept 70-i143/80-08 on 800326-27 No noncompliance noted Major areas inspected measurement & statistical controls & inventory difference & associated limit of error Datails withheld (ref (OCFR2 770) JOYNER, J H Region 1, Philadelphia, Safeguards Branch HOLODY, D J Region 1, Philadelphia, Office of the Director 80/04/14 1p
- B00A200120 Forwards Revision 4 to fundamental nuclear matt control plans for Pu fuels development tab Encl withheld (ref 10CFR2 790)
 DIP1ATZA,R P Westinghouse Electric Corp 80/04/18 1p
- 8006200592 Forwards Revision 1 to manual. "Physical Security Plan for Protection of SNM of Moderate Strategic Significance at Cheswick Site." for NRC approval Revision incorporates adminstrative corrections Encl withheld (ref 10CFR2 790) DIPIAZZA,R P Westinghouse Electric Corp 80/05/02 1p
- B006040140 Advises that negative air atmosphere is appropriate in ARD gloveboxes PFDL during present decontamination activities for final decommissioning of Pu fuel facility During operation, inert atmosphere was required ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/05 ip
- BOO6190139 Requests exemption from certain of 10CFR67 requirements for exclusion of residually contaminated waste from aggregate SNM quantity Math is in containers awaiting burial at authorized site Fee encl.

 DIPIAZZA, R P Westinghouse Electric Corp BO/05/12 1p
- B006R30304 Forwards application for Revision 6 to License SNM-1120 reducing quantities of radioactive matls authorized for possession at facility Fee encl DIPIAZZARR P Westinghouse Electric Corp 80/05/12 5pp
- --8006230308 Application for Revision 6 to License SNM-1120, reducing quantities of radioactive matls authorized for possession at facility
 DIPIAZZAR P Westinghouse Electric Corp 80/05/12 5pp
- 8006300120 Forwards IE Insp Rept 70-1143/80-06 on 800212,25 & 27-29 No noncompliance noted MARTIN,W © Region 1, Philadelphia, Safeguards Branch 80/05/12 25p
- ---8006300131 IE Insp Rept 70-1143/80-06 on 800212,25 & 27-27 No noncompliance noted Major areas inspected matl control & accounting.physical security & health & industrial safety Portions withheld (ref 10CFR2 790)
 KUBHNER.W.L. Region 1. Philadelphia, Office of the Director OYNER.J H Region 1. Philadelphia, Safeguards Branch 80/05/08
- B006120239 Advises that License SNM-1120 is amended Amend reduces possession limits (dentified in Attachment 1 of B00512 application ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/05/16
- B006300227 Revises License Condition 2 1 of License BNM-1120.permitting revised pages to "Fundamental Nuclear Matl Control Plan for Pu Fuels Development Lab "PARTLOW.JO Material Control Licensing Branch 80/05/22 ipp.
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP
- 8006250021 Application for amend to License SNM-1107, authorizing use of SNM in advanced waste treatment process per info described in encl Processing expected to begin in Juli 1980 W/o encl # Westinghouse Electric Corp 80/04/07 ip
- 8006300292 Forwards revised manual, "Fundamental Nuclear Matl Control Plan — Columbia Plant " Requests approval Manual withheld (ref 10CFR2 790) DIP16274.R.P Westinghouse Electric Corp , PWR Systems Div 80/05/01 ip

- 8006250050 Application for ameno to license SNM-1107,deleting requirement for gross beta analyses of environ air particulates DIPIACZALR P Westinghouse Electric Corp 80/05/14 3pp
- BOO6300037 Forwards site physical security plan for approval Fee encl Plan withheld (ref 100FR2 790) DIPIAZZA: R P Westinghouse Electric Corp b PWR Systems Div BO/05/15 ip
- BOO6050467 PNS-II-80-014 on BO0519, bomb threat was received by receptionist at facility Licensee conducted searching bomb was found Facility was not evacuated OILLIESPIE.F. CORYELL, 0 P Region 2, Atlanta, Office of the Director 80/05/20 in
- 8006180001 Ack receipt of 800429 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1151/80-06 STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/05/29 lp
- --8006180002 Responds to NRC 800408 ltr re violations noted in IE Insp. Rept 70-1151/80-06 Corrective actions instituted formal program to assure annual fish collection Samples will be obtained by 800601
 D'AMDRE,M Westinghouse Electric Corp 80/04/27 2pp
- --B006180003 Forwards IE lnsp Rept 70-1151/80-06 on 800225-28 & notice of violation STDMR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/04/08 2pp
- --8005180004 Notice of violation from insp on 800225-28
 * Region 2. Atlanta, Office of the Director 80/04/07 ip
- --B006180005 IE insp Rept 70-1151/80-06 on B00225-28 Noncompliance noted failure to obtain required fish samples
 JENKING, 0 R Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch MACARTHUR, T C Region 2, Atlanta, Office of the Director
 80/04/07 4pp
- 8006200004 Ack receipt of 800513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/80-10 KENNA W B, Region 2, Atlanta, Safeguards Branch 80/05/29 ip
- ---B006200007 Responds to NRC 800421 ltr re violations noted in IE Insp Rept 70-i151/80-10 Corrective actions withheld (ref 10CFR2 790) G0DDWIN.W L . D'AMORE, M Westinghouse Electric Corp 80/05/13
- --8004200010 Forwards IE Insp Rept 70-1151/80-10 on 800325-28 & natice of violation Natice of violation withheld (ref 10CFR2 790) KENNA.W D Region 2. Atlanta. Safeguards Branch 80/04/21 2pp
- --B006200015 IE Insp Rept 70-1151/B0-10 on B00325-28 Noncompliance noted failure to calibrate emission spectrometer w/stds traceable to natl sys of stds & failure to record results of control data exceeding limit Details withheld (ref 10CFR2 770) GILLESPIE,F P Region 2, Atlanta, Safeguards Branch BATES,J W. Region 2, Atlanta, Office of the Director B0/04/21. 1p

DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP

- BOOGO20260 Notifies that new telephone sys called Health Physics Network (HPN) has been installed at site Bys intended for use during emergencies to link all power plants & NRC Emergency Notification Bys hotline will also be used KEPPLER.J Q Region 3. Chicago. Office of the Director BO/04/18 2pp
- 8006230333 Forwards proposed changes to standby physical security plan Proposed changes strengthen access control & thus do not require prior license approval SHELLEY:W J Kerr-McOpe Corp 80/05/09 5pp
- 8006170352 Determined that reporting requirements of License Condition 6 1 are no longer necessary Amend MMP-3 to License SNM-1174 is revised effective immediately, to delete license condition PARTLOW.J G. Material Control & Accountability Development Branch 80/06/02 ip
- BOD6230207 Discusses review of math control & accounting requirements re License SNM-1174 Amend MPP-3, Condition 6 1 is deleted Monthly loss rept not required PARTLOW, J & Material Control Licensing Branch 80/06/02. 1p

- DOCKET 70-120) UF & CONVERSION FACILITY, BABCOCK & WILCOX CO
- BOO6230072 Forwards certificate to company lenders that all restrictive covenants contained in note agreements have been met, as assurance of ability to cover decommissioning costs JORDANIL V Babcock & Wilcox Co BO/03/28 3pp
- 8006170724 Forwards administrative amend license fee re revised MPP-2 Condition 6 5 for License SNM-1168, elempting plant from requirement to issue NRC-741 documents for shipment of empty containers to U pouder supplier W/o check ZEFF.D W Babcock & Wilcox Co 80/04/10 1p
- --BOO6170729 Requests amend to License SNM-1168, exempting plant from requirement to issue NRC-741 documents for shipment of mmpty containers to U powder supplier

 * Babcock & Wilcox Co BO/04/01 ip
- 8006230272 Application to amend License SNM-1168 re use of emission spectrometric technique for isotopic measurements Encls withheld (ref 10CFN2 790) ZEFF,D W Babcock & Wilcox Co 80/04/17 1p
- 6006230302 Application to amend License SNM-1168 re measurement of received fuel assemblies & control chanting for impurity analysis Encis withheld (ref 10CFR2 790)
 ZEFF, D.W. Babcock & Wilcox Co. 60/04/17 lp
- 8006250019 Forwards Revision O to fundamental nuclear math control plan & administrative licensing fee Encls withheld (ref iOCFR2 790) ZEFF,D W Babcock & Wilcox Co BO/05/01 1p
- BOO6240515 Forwards fee & revised spec pages re 800107 Amend Application 79-3 for License SNM-1168 ZEFF.D W Babcock & Wilcox Co 80/05/06 3pp
- --8006240518 Revision to 800109 Amend Application 79-3 for License SNM-1168 Areas addressed include levels of air effluent releases & liquid effluent releases & contamination survey frequency * Babcock & Wilcox Co 80/05/06 9pp
- 8006300683 Forwards physical security plan for review & approval. Includes request for exemption of liquid waste retention & disposal sys, addition of certain license conditions & exclusion of manual sections Plan withheld (ref 10CFR2 790) ZEFF.D.W Babcock & Wilcox Co 80/05/16 1P
- BOOA040135 Requests investigation into trend of abnormal oscillatory pattern in recent inventory difference review Should include reasons for trends, corrective actions & projected schedule for completion Results requested by BOI031 PARTLOW, J O Material Control Licensing Branch 80/05/20 ip
- 8006020592 Ack receipt of 800516 ltr which transmitted physical protection plan for SNM of low strategic significance Plan classified by safeguards licensing staff as requiring major amend to License SNM-1168 Safeguards amend fee required WEISB, D License Fee Management Branch 80/05/21 1P
- 8006250004 Application for amend to License SNM-1168 Revisions include action levels for air & liquid effluent releases, isolation criteria & contamination survey frequency ZEFF,DW Babcock & Wilcox Co 80/05/22 35pp
- 8006300666 Forwards application to amend License SNM-1168 re regulatory requirements for establishing & maintaining control limits. Administrative amend fee enci Application withheld (ref 10CFRZ 790)
 ZEFF.D W Babcock & Wilcox Co 80/05/22 lp

DOCKET 70-1252 EDLOW INTERNATIONAL CO

- B006300019 Requests 30-day extension for submittal of security plan, in order to prepare format compatible w/NRC regulations WRIGHT, D Ediow International Co 80/05/16 1p
- DOCKET 70-1257 MIXED DXIDE FABRICATION PLANT, EXXON NUCLEAR CO , INC.
- 8006250146 Lists four items not covered by current fundamental mati control plan Revisions will be submitted if necessary BCHNEIDER,R. A Exxon Nuclear Co., Inc. (subs. of Exxon Corp.), 80/03/25 2pp

- 8006200081 Forwards upgrading & clarifying revisions to 790430 application for renewal of License SIM-1227 ESTEY, HP Erron Nuclear Co , Inc (subs of Exxon Corp) 80/04/29 1p
- --B006200093 Revised pages to 790430 application for renewal of License BNM-1227 g. Erzon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/04/30
- 8006180565 Advises that no add1 safety 2 environ fee is required for Amend 23 to License SNM-1227 issued on BO0415 Manpawer expenditures required to review 771119 amend application exceeded max fee limit MILLER.H 0 License Fee Management Branch 80/05/01 1p
- 8006200616 Advises that License Condition 2 8 has been added to Amend MPP-2 to License SNM-1227 for sampling 5 measurement of U hexafluoride from foreign source PARTLOW, J G Licensing Management Branch B0/05/23 1o
- 8006070490 Requests payment of administrative amend fee re 800506 request for temporary exemptions from code requirements MEIBS.J.D. License Fee Management Branch 80/05/27 1p
- 8006300165 Revises License Condition 2 1 of Amend MPP-2 to License 8NM-1227 & deletes License Condition 5 2 License Condition 5 2 will be renumbered 5 1 PARTLOW. J G Division of Licensing 80/05/30 1p
- 8006120434 Advises that major safeguards amend fee is required for review of physical protection plan submitted on 800516 WEIBS.J D Licensing Management Branch 90/06/02 1p
- 8006190013 Advises that minor safeguards amend fee required for review of 80050B proposed procedures to perform receipt measurements of nine cylinders of U hesafluoride WEISS, J D Licensing Management Branch 80/06/02 ip
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- B006200140 Forwards "EIA re Renewal of Hatls License SNM-1265 for Receipt.Storage & Transfer of Spent Fuel at Morris Operation.GE Co "ROUSE.L C Fuel Process & Fab Branch (Pre 790727) 80/06/05
- --8006200145 "EIA re Renewal of Matls License SNM-1265 for Receipt, Storage & Transfer of Spent Fuel at Horris Operation, GE Co " * Office of Nuclear Material Safety & Safeguards 80/06/30 63pp
- 8005240202 Informs that GE general revenues & retained earnings as shown by 1979 annual reptrare sufficiently large that resources deamed necessary to decommission Morris facility will be available Board Resolution 9440, dtd 790427 encl. HDLFE/B General Electric Co 60/04/15 3pp
- 6006160220 Forwards table showing increased inventory of fuel DAMEON, D M General Electric Co . Nuclear Energy Products Div 80/05/01 2pp
- 8006170057 Forwards IE Insp Rept 70-1308/80-02 on 800321 & 26-27 No noncompliance noted DAVIS.A B Region 3, Chicago. Fuel Facility & Materials Safety Branch 80/05/02 2pp
- --8004170044 IE Insp Rept 70-1308/80-02 on 800321 & 26-27 No noncompliance noted Major areas inspected organization, fuel storage & handling, facility changes & mods, surveillance testing & internal exposure control FECKIC C Region 3, Chicago, Diffice of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/04/30 4pp
- 8006060332 Opposes relicensing of facility due to radioactive emissions from plant, close proximity & undus risks to public health & safety

 HALSH,P J Affiliation Unknown. 80/05/05 2pp
- 8006170263 Forwards QA input to SER re vendor application to renew License SNM-1265 ODRDON.L L Advanced Fuel & Spent Fuel Licensing Branch 80/05/14 8pp
- 8006110293 Forwards GE 800516 ltr to NRC re Licensa BNM-1265 Related Correspondence RUONEY. M A Mayer, Brown & Platt 80/05/22 ip

- --8006110298 Notifies that physical security plan for License 9NM-1269 changed Requests encl to ltr be withheld (ref 10CFR2 790) DAWSON, D.M. General Electric Co. 80/05/16 2pp
- B006130123 Notification of B00610 meeting w/GE in Silver Spring,MD re B00123 license amend request & vendor plans for possible expansion of pool pump room CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch 80/05/30
- 8006070304 Order ruling on BL Rorem.R Rorem.K Storey & E Guigley contentions Wording of contentions as accepted by ASLB encl GOODHOPE, A C Atomic Safety and Licensing Board Panel 60/06/04 25mp
- B006070307 Order denying E Walsh B00403 petition to intervene as matter of right & discretion Contention is not litigable Petitioner failed to establish good cause for late intervention ODODHOPE.A C Atomic Bafety and Licensing Board Panel B0/06/04
- 8006090320 Order establishing discovery schedule Requests must be served by 800630, objections by 800711 & answers to requests w/o objections by 800718 ABL will establish dates for summary disposition during or after discovery GODDHOPE, A C Atomic Safety and Licensing Board Panel 80/06/04
- 8006090244 Forwards Jun 1980 EIA re renewal of Matls License 8NM-1265 for receipt storage & transfer of spent fuel ROTHSCHILD,M U Hearing Branch 1 80/06/05 ip
- --8006090246 EIA re renewal of Matls License SNM-1265 for receipt, stores & transfer of spent fuel * Office of Nuclear Material Safety & Safeguards 60/06/05 ii/On
- 6005180333 Motion for extension until 800730 or 30 days after receipt of NRC safety evaluation to complete first round of discovery Requests win 14-day extension for objections & answers after final filing of requests WCertificate of 8vc BEKULER, 8 N Illinois, State of 80/05/12 7pp
- 8006180109 Motion for reconsideration of ASLB 800604 order ruling on contentions Urges denial of Contention 1(b)(vii) & clarification of whether parties are consolidated recombined contentions Certificate of 8vc encl ROTHSCHILD, M U Hearing Branch 1 80/06/16 12pp
- 8006240148 Memorandum in opposition to State of IL motion for add1 time for preparation of discovery requests Urges State of IL to devote efforts to preparation of requests by 800630 Schedule should not be abandoned Certificate of Svc encl SZWAJKOWSKI.R , RODNEY.M A General Electric Co SZWAJKOWSKI.R Mayer, Brown & Platt 80/06/18. Spp
- B006240321 Notice of filing of motion for reconsideration & memorandum in support SEKULER, S N Illinois, State of 80/06/20 1p
- --B006240587 Motion to reconsider ASLB B00604 ruling on parties' contentions & to admit State of IL Contentions 1(a),9 & 11(a-h)

 SEKULER,8 N , SCOTT,W J Illinois, State of B0/06/20 ip
- --8006240592 Memorandum in support of motion for reconsideration of ASLB 800604 ruling on parties' contentions Urges admission of State of IL Contentions (4a).7 & it(a-h) to conform w/NRC interim policy on EIS Certificate of Svc encl SEKULER.8 N . SCOTT.W J Illinois, State of 80/06/20 Bpp
- 8006260254 Order extending discovery requests until 800715, objections to requests until 800804, answers to discovery until 800804, & parties opinions re further discovery until filing of SER QUODHOPE, A C Atomic Safety and Licensing Board Panel 80/06/23 2ab
- 8006260203 Response supporting in part State of IL 800612 motion for add1 time. Urges revision of ASLB 800604 order re discovery schedule to adopt NRC dates which will relieve burden & will take into account EIA & SER delays W/Certificate of 95 vc ROTHSCHILD, M U Hearing Branch 1 80/04/24 8pp
- 8006260423 "EIA Re Renewal of License SNM-1265 for Receipt, Storage & Transfer of Spent Fuel"
 # Office of Nuclear Material Safety & Safeguards. NUREG-0675 80/06/30 104pp

DOCKET 70-1314 NASA, LANGLEY RESEARCH CENTER

8006i10089 Application for amend of License SNM-1288 authorizing storage of licensed matt at Bldg 1254 & Bldg 1247D CHURCH.J D National Aeronautics & Space Admin 80/06/04 ip

DECKET 70-1319 U.S. NUCLEAR, INC.

- 8006230224 Forwards IE Insp Rept 70-1319/80-02 on 800327 No noncompliance noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/04/29 1p
- --8006230230 IE Insp Rept 70-1319/80-02 on 800327 No noncompliance noted Major areas inspected lung count results raduaste shipments & removal of radiation/radioactive matl caution signs QIBSON.A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch DAVIS.J H Region 2. Atlanta. Office of the Director 80/04/28 3pp

DOCKET 70-1359 IRT CORP

- 8004200159 Requests 45-day license extension to allow timely submission of renewal application followed by amend covering new facility Fee encl
 MERTZ.R L. IRT Corp BO/04/11 2pp
- 8006120440 Advises that major sefeguards amend fee is required for review of physical protection plan submitted on 800516 MEIBS.D Licensing Management Brench 80/06/02 ip

DOCKET 70-1510 NUCLEAR ASSURANCE CORP

8005120430 "GA Manual " SCHUTT.P F , JOHNSON.C R , WEBSTER.D A Nuclear Assurance Corp 80/03/15 200pp

DOCKET 70-1621 CONOVER & ASSOCIATES, INC

- B006160020 Forwards Endorsements 39 & 40 to ANI Policy NF-226 & Endorsements 33 & 34 to MAELU Policy MF-87 BARNETT, J E Conover & Associates, Inc. Insurance 80/06/09 5pp
- DOCKET 70-1729 FUEL REC & STOR STA , ALLIED GENERAL NUCLEAR BERVICES
- BOO6060435 Requests copy of study made for Allied General Nuclear Byos by H Ragsdale re spent nuclear fuel storage at facility, info re hearings on facility & rept by Div of Fuel Cycle & Matl Bafety re geological fault Certificate of Syc encl THOMAB,R Environmentalists, Inc. 80/05/19 2pp
- 8006260189 Clarifies NRC 790221 ltr re away from reactor spent fuel storage facility DDE & QAO should be contacted for documents listed in attachment Remaining documents available in PDR ENOELHARDT.TF Deputy Executive Legal Director 80/06/20 2pp

DOCKET 70-1812 GENERAL ATOMIC CO

- 8006049050 Advises that License SNM-1507 is revoked & Condition 19 is added to SNM-696, authorizing possession of U-235 & transport of math to & from authorized persons Shipper responsibility exempted between vendor facilities
 PAGE, R O Uranium Fuel Licensing Branch 80/05/02 2pp
- BOOA090369 Notifies that License SNM-1507 has been revoked & Condition 19 added to License SNM-696, authorizing possession of U enriched in U-235 isotope PAGE:R G Uranium Recovery Licensing Branch 80/05/02 2pp

DOCKET 70-1966 TENNESSEE VALLEY AUTHORITY

8006180232 Application for renewal of License SNM-1526, authorizing possession of byproduct, source & SNM per 10CFR71 Updated list of util corporate organization encl MILLS.L M Tennessee Valley Authority 80/03/18 3pp

DOCKET 70-1992 MT AUBURN HOSP CAMBRIDGE, MA

8006060072 Discusses lE insp of Licenses 20-12063-02 & BMM-1544 on 800424 No noncompliance noted Major areas inspected interviewed personnel & discussed plans for future use of nuclear pacemakers CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/08 ip

DOCKET 70-2131 EDLOW INTERNATIONAL CO

8006300560 Transcript of 770321 briefing in Hashington,DC re Edlow Intl Co application to export SNM to India Pp 1-42 e Commission 77/03/21 42pp

DOCKET 70-2260 ST JOSEPH HOSP STAMFORD, CT

- B006270021 Ack receipt of 800524 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 06-06992-02 & SNM-1567 on 800407 CROCKER.H W Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/06 ip
- --8006270025 Responds to NRC 800505 ltr re violations noted in IE insp of Licenses 06-06922-02 & BNM-1567 on 800407 Corrective actions posted caution sign in room containing cosium source & instructed personnel to monitor hands w/OM meter BISTER DANIEL M St Joseph Hosp Stamford.CT 80/05/24. ip.
- --8006270029 Discusses IE insp of License 06-06922-02 & 8NM-1967 on 800407 & forwards notice of violation CROCKER,H W Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/05 2pp
- ---8006270032 Notice of violation from insp on 800407 Noncompliance noted failure to post storage room where Cs-137 brachytherapy sources are stored w Region i. Philadelphia. Office of the Director. 80/05/05 ip.

DOCKET 70-2474 HOLY NAME HOSP TEANECK, NJ

8006300624 IE Insp Findings & Licensee Ack #t# 800527 of Licenses BNN-1722 & 27-033B2-01 Insp findings no noncompliance noted BTEARUS.C J Region 1, Philadelphia, Office of the Director, BO/05/27 ip

DOCKET 70-2495 EDLOW INTERNATIONAL CO

B006300560 Transcript of 770321 briefing in Mashington.DC re Edlow Intl Co application to export SNM to India Pp 1-42 * Commission 77/03/21 42pp

DOCKET 70-2486 ST ELIZABETH HOSP MEDICAL CENTER LAFAYETTE, IN

BOO6040246 IE Insp Findings & Licensee Ack dtd 800421 of License SNM-1742 Insp findings no items of moncompliance or unsafe conditions found REICHHOLD.WP Region 3, Chicago, Office of the Director 80/04/21

DOCKET 70-2523 GENERAL ATOMIC CO

- 800A040280 Recommends that Commission authorize denial of QA Corequest for license to export 24.4 kg U-235 contained in 26.2 kg U, to Iran No agreement for cooperation exists between US & Iran BHEALJ R Office of International Programs, Director BECY-80-247. 80/05/13 3pp
- --8006040252 Application by GA Co for license to export 21 7 kg U. containing 20 2 kg U-235. to Iran.
 MOWRY, W R General Atomic Co (subs of Gulf Oil Co.) 77/02/11
- --8004040262 Forwards amend to 770211 application for license to export fuel elements to Iron Requests issuance of license to export 24 4 kg U-235, contained in 26 2 kg U End use statement uncl MONRY, W R General Atomic Co (subs. of Quif Oil Co), 78/07/18 3pp

DOCKET 70-2542 WESTINGHOUSE ELECTRIC CO.

8005120452 Requests amend to export license, extending expiration date to 811231 DAHLSTRUM.C Q Westinghouse Electric Corp 80/05/22

8006090152 Amend 4 to import license for Westinghouse, extending expiration date from 801231 to 811231 PETERSON-H R Assistant Director for Export/Import & International Safeguards 800/06/02 ip

DOCKET 70-2609 COMMONWEALTH EDISON CO

900A200555 Application for amend of Licenses ENK-1802 & SNM-1803 extending expiration dates to 810A30 & 82033; respectively PEOPLES, D L Commonwealth Edison Co 80/04/03 2pp

8006240274 Application for amend to Licenses SNM-1802 & SNM-1803, extending expiration dates to 810630 & 820331, respectively PEOPLES, D. L. Commonwealth Edison Co. 80/04/03 . 2pp

DOCKET 70-2619 BLOOMINGTON HOSP BLOOMINGTON, IN

8006250605 Discusses IE insp of Licenses 13-10408-01, i3-10408-02 & 8MM-174& & forwards notice of violation DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/06/02 2pp.

--8006250608 Notice of violation from insp on 800514 Noncompliance noted failurs to conduct quarterly meetings of medical isotope committee Review of records showed that Co-57 ref source was not assayed before daily use # Region 3, Chicago, Office of the Director 80/06/02 2pp

DOCKET 70-2623 MCOUIRE SPENT FUEL POOL, DUKE POWER CO

8006030074 Forwards resolution opposing movement of spent nuclear fuel or waste over roads through Lincoln County,NC Board raeffirmed on 800408 that spent nuclear fuel or waste should be bransported on interstate highways.

HOUSER,F M Affiliation Unknown 80/04/17. 3pp

8006240594 Forwards Lincoln County.NC Board of County Commissioners 791001 & 800408 resolutions affirming position that spent nuclear fuel should be transported from Ocones to McQuire on interstate highways. HOUSER.F M North Carolina, State of 80/04/17 3pp

BOO6200065 Advises that util will submit revision to spent fuel transportation plan incorporating regulatory requirements not met in 800408 plan & noted in DJ Kasun 800424 affidavit Lists changes to be made.

PARKER: H O Duke Power Co 80/04/28 2pp

8005230577 Advises that util is to submit proposed findings of fact by 800519; non-NRC parties by 800529 & NRC by 800609.

MCGARRY, J M Debevoise & Liberman 80/04/30 ip

BOO6180210 Responds to appeal re partial denial of FDIA request for route info re spent fuel shipments from Chalt River to SC Appeal is denied Info withheld (ref FDIA Examption 4 & 10GFR2.770) Office of the Executive Director for Operations DIRCKS, W J 80/05/09 200

8006060R69 Forwards applicant proposed findings of fact & conclusions of law in form of initial decision MCGARRY.J M Debevoise & Liberman 80/05/19, 1p

---8006060281 Submittal of proposed findings of fact & conclusions of law in form of initial decision HCGARRY, J M Duke Power Co. 80/05/19 ip

---B004040284 Proposes initial decision containing findings of fact & conclusions of law.approving amend to authorize storage of Ocones agent fuel at McGuire Environ radiological monitoring program shall be maintained W.Certificate of Svc MCGARRY.J M Duke Power Co 80/05/19 88pp.

8006110246 Proposed findings of fact & conclusions of law toward initial decision Alleges that NRC has not been concerned w/local views & that ASLB can cure matter per President Carter 800212 address to Congress Affireation of svc enci RILEYIL L. Carolina Environmental Study Group 80/05/28 20 80/05/28 20pg. 8006110176 Motion for extension until 800617 to file proposed findings of fact & conclusions of law due to other assignments & complex nature of case Certificate of Svc enc!
KETCHEN.E G Hearing Branch 4 80/06/06 4pp

8006160126 Order granting extension until 800617 for NRC to file proposed findings of fact & conclusions of law MILLER.M E Atomic Safety and Licensing Board Panel 80/06/09 lp

8006170423 Response in opposition to NRDC 800529 proposed findings of fact & conclusions of law in form of initial decision requesting denial of license amend Maintains that contentions have been resolved Certificate of Svc encl MCGARRY. J M Duke Power Co MCGARRY. J 1 Debevoise & Liberman 80/06/13 17pp

B006180517 Response in apposition to Carolina Environ Study Group B00929 proposed elements of fact & conclusions of law toward initial decision No good reason presented for not approving application re spent fuel shipment W/Certificate of Svc MCGARRY, J M Duke Power Co B0/06/13 21pp

8006180538 Forwards 800603 FR notice announcing NRC amend to physical protection regulation of irradiated reactor fuel during transit Fulfills NRC committment made at 800428-29 hearings MODEFLING.R K Hearing Branch 4 80/06/13 13pe

8006190593 Forwards proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to & storage at KETCHEN, E 0 Hearing Branch 4 80/06/17 ip

--8006190606 Proposed findings of fact & conclusions of law in form of initial decision approving license amend to authorize Oconee spent fuel transportation to & storage at McGoire Proposed transcript corrections & Centificate of Svc encl KETCHEN.E O Hearing Branch 4 80/06/17 195pp

DOCKET 70-2805 NIBSHO-IWAI AMERICAN CORP

8006020165 Application by Nissho-Iwai American Corp to amend license to export U to Japan changing quantity to 39 284 kg U-235. contained in 42 105 kg U YAMANA: K Nissho-Iwai American Corp 80/05/07 ip

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

8004250340 Application for amend of License BNM-1823 extending expiration date to earlier of 811102 or conversion to DL FLYNN.J D Cincinnati Gas & Electric Co 80/04/10 ip

DOCKET 70-2885 COMMONWEALTH EDISON

8006200555 Application for amend of Licenses SNM-1802 & BNM-1833 extending expiration dates to 810630 & 820331.respectively PEOPLES.D L Commonwealth Edison Co 80/04/03 2pp

8006240274 Application for amend to Licenses SNM-1802 & SNM-1833, extending expiration dates to 810630 & 820331, respectively FEOPLES.D i. Commonwealth Edison Co 80/04/03 2pp

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

BOD6200587 Requests placement on list to receive DES for SNM license for proposed Westinghouse nuclear fuel fabrication plant near Prattville.AL DANIELEON:L J National Wildlife Federation 80/03/25 ip.

8006200591 Notifies that addl distribution of environ rept to federal, state & local officials has been completed per instructions provided in NRC 800227 ltr Addresses will be placed on environ rept distribution list for future amends
DIPIAZZA,R F Westinghouse Electric Corp 80/03/25 ip

BOOG180584 Forwards NRC notice of hearing & NRC rules & regulations, 10GFR2 Documents concern proposed facility W/o encis NIXON,W A Uranium Fuel Licensing Branch 80/03/28, 1p

8006250327 Opposes proposed Westinghouse fuel peliet plant Companies should build plants in sparsely populated areas such as NV & UT Email group of people should not subj entire area to potential catastrophe.

VASSER: E Affiliation Unknown 80/03/28 2pp

- B006240587 Requests that 16 listed questions be addressed in NRC EIS for facility including effect on economic social & ecological environ of central AL ALLRED.W H Affiliation Unknown B0/04/02 App
- 8006160146 Comments on DES Suggests inclusion of additeffects re channelization of AL River, radioactive releases into underground areas, use of Pu & noise from transportation W/ Certificate of Svc Certificate of Svc ARDNOV, Affiliation Unknown MCPHILLIPS, J Affiliation Unknown 80/04/03 3pp
- --800&1&0150 Motion for two-month extension to make comments on scope of DES Statements during 800327 meeting confused parties redeadlines Certificate of Svc entl
 ANDNOV.R Affiliation Unknown MCPHILLIPS.J Affiliation ARDNOV.R Affiliat Unknown 80/04/03 200
- 8006180174 Protests chemical & radioactive pollutants & wastes discharged into air & AL River from Westinghouse Power Bys NRC decision to award EIS contract to ORNL will not result impartial study DE LISSOVGY, J Affiliation Unknown 80/04/03 2pp
- 8006180371 Protests NRC decision to contract performance of AL Nuclear Fuel Fabrication Plant EIS w/ORNL & manner in which 800327 stoping meeting was posted \$1:0 of advertisement & selection of typeface made legal notice unreadable DELISSOVOY. G Affiliation Unknown 80/04/03 2pp
- 8006250162 Forwards questions & statement handout distributed by Bafe Energy Alliance antinuclear group & used by many speaking at 800328 scoping meeting in Prattville. AL Newspaper article re meeting also encl Transcript expected CELLIER. F Westinghouse Electric Corp. PMR Systems Div 80/04/07
- BOOG190744 Advises of extension until BOOG14 to file request for hearing re issuance of SNM license to facility Extension is necessary for public review of environ rept FR notice encl PAGE.R Q Uranium Fuel Licensing Branch 80/04/08 3pp
- --8004190745 Notice of extension of apportunity to file request for hearing re issuance of SNM license for facility PAGE.R G Uranium Fuel Licensing Branch 80/04/03 2pp
- 8006180570 Requests info re whether any plants or animals listed as andangered species may be present in vicinity of proposed plant Plant will convert tow-enriched U hexafluoride into U dioxide for fabrication into ceramic fuel pellets GHUM. E Y Uranium Fuel Licensing Branch 80/04/09 2pp
- 8006190407 Comments on envison rept for nuclear fuel fabrication plant im Autauga County.AL Environ statement should identify aquifier tapped by Prattville wells & should assess impacts of water demand on Prattville sys & on aquifier MENARD.H W Interior.Dept of Geological Survey 80/04/14 ip
- 8006200550 Expresses concern re environ impact of proposed nuclear rod mfg plant near Prattville.AL River is major part of recreation in area BTEINWINDER.J Affiliation Unknown 80/04/16 1p
- 8006170324 Requests that second public scoping hearing re environ rept for proposed fuel fabrication facility be held in near future Hearing should be held due to unavailability of rept prior to first hearing in Prattville, AL ALLRED. D L Affiliation Unknown 80/04/21 2pp
- 800A190328 Ack receipt of NRc 800409 request for info re endangered & threatened species in site area Request has been forwarded to Jackson area ofc for review Interior, Dept of, Fish & Wildlife Service 80/04/23 BLACK, K E
- 8004030057 Forwards NRC environ review schedule for proposed fuel fabrication plant in response to request NRC anticipates issuing DES by 800818 & FES by 810224 CRUM.W T Uranium Fuel Licensing Branch 80/05/20 2pp
- 8006300034 Forwards comments & questions re environ rept for proposed fuel fabrication plant Requests response by 800710 SHUM, E Y Uranium Recovery Licensing Branch 80/06/03 12pp

DOCKET 70-2910 TENNESSEE VALUEY AUTHORITY

- 8006250053 Application for amend to License SNM-1861, reflecting personnel & div changes within util % making Unit 1 % 2 applications identical MILLS.L M Tennessee Valley Authority 80/05/13 5pp
- DOCKET 70-2920 ALARAMA POWER CO.
- 8006250142 Forwards signed copy of Amend 6 to Indemnity Agreement B-81 CLAYTON:F L Alabama Power Co 80/03/27 2pp
- DOCKET 70-2928 TENNESSEE VALLEY AUTHORITY
- 8006250062 Forwards application for license to receive.possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility MILLS.L M Tennessee Valley Authority 80/05/13 2pp
- --8006250065 Application for license to receive, possess & store assembled fuel assemblies & up to 100 loose fuel rods at facility * Tennessee Valley Authority 80/05/13 20pp

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER **CERTAIN CONDITIONS**

- DOCKET 71-0015 CHICAGO BRIDGE & IRON CO
- BOO6130032 Requests certificate of approval from 780615 submittal of QA program for radioactive matl shipping packages MCCORMAC, J B Chicago Bridge & Iron Co 80/05/27 ip
- 8006180603 Responds to 800528 ltr re GA program by forwarding NRC 790629 ltr & approval of GA program W/o encl MACDONALD.C E Transportation Branch 80/06/03 ip
- DECKET 71-0102 SOURCE PROD & EQUIP CO . INC
- 8006200586 Discusses status of Source Production & Equipment Co 780623 application for GA program for Type B packages Requests explanation of what is unacceptable in application & which points of regulation apply to program
 PARKER, R A Parker, R A 80/05/30 2pp
- DOCKET 71-0108 MISSOURI, UNIV OF
- BOO6230174 Forwards request for add1 info re research reactor facility GA program submitted w/780627 ltr Includes questions re GA responsibilities of each organizational element in App I & requirements for position of reactor manager MACDONALD,C E Transportation Branch B0/06/04 4pp
- DOCKET 71-0135 BABCOCK & WILCOX CO.
- 8006040094 Forwards Revision 9 to PA operations 0A policy & procedures manual re NRC 800314 request for add1 info 7able referencing each comment to applicable paragraph in manual enci AUSTIN.M A Babcock & Wilcox Co 80/05/16 Spp
- ---8004040056 PA operations GA policy & procedures manual.Revision 9, CARLSON.R V Babcock & Milcor Co 80/04/30 87pp
- 8006090174 Forwards GA program approval for radioactive matl package MACDONALD: C E Transportation Branch 80/05/27 ip
- --8004090177 GA program approval for radioactive mati package 0135. MACDONALD, C E Transportation Branch, 80/05/27 ip
- DOCKET 71-0164 MASSACHUSETTS INSTITUTE OF TECHNOLOGY
- 8006270055 Forwards request for addl info re 780630 GA program in order to satisfy 190FR71. App E requirements Response due within 60 days MACDONALD, C.E. Transportation Branch 80/06/12, 4pp.

DOCKET 71-0145 NAVY, DEPT OF

- 8006300620 Forwards revised GA program for industrial radiography in response to NRC 790813 ltr QRDVES.K L. Navy.Dept of Naval Nuclear Power Unit 80/02/28 1p
- --8006300622 Forwards revised QA program for industrial radiography Code requirements & sample program forwarded in NRC 790813 ltr ware used to revise program GLENN.T D Navy.Dept of 80/02/07 ip

--8006300626 Revised QA program for industrial radiography QLENN:T D Mavy.Dept of 80/02/07 4pp

DOCKET 71-0173 BATTELLE-PACIFIC NORTHWEST LABS

- BOOA2002BB Forwards revised GA program description incorporating addless in the second of the FUOUAY. J Battelle Memorial Institute: Pacific Northwest Laboratory 80/05/16 ip
- --8006200292 QA program for shipping packages of radioactive matls, Revision 2 * Battelle Memorial Institute, Pacific Northwest Laboratory 80/05/16 13pp

DOCKET 71-0195 FBF. INC

- 800520095 Forwards GA program approval for radioactive matl package MACDONALD.C E Transportation Branch 80/04/22 1p
- --8006200100 GA program approval for radioactive matl package 0185, Revision O MACDUNALD:C E Transportation Branch 80/04/22 ip

DOCKET 71-0230 BABCOCK & WILCOX CO

- 80060\$0159 Forwards replacement page for Section i & two addl pages for Section 2 O of GA plan,per NRC 800314 request OLSEN,A F Babcock & Wilcox Co B0/05/15 4pp
- 8006120226 Forwards GA program approval for radioactive mati package MACDONALD.C E Transportation Branch 80/05/27 1p
- --8006120234 QA program approval for radioactive matl package 0230r Revision O MACDOMALD.C E Transportation Branch 80/05/27 ip

DOCKET 71-0384 NEW ENGLAND NUCLEAR CORP

- BOGG120405 Forwards request for add1 info re NRC review of BOO415 GA program Lines identifying reporting responsibilities should be shown in Figure 1-1 Statement should be provided re indoctrination & training program HACDUNALD.CE Transportation Branch 80/05/21 3pp
- 8005230257 Forwards revised QA program for facility Requests that review of program be given priority status
 DEMARIA.E New England Nuclear Corp 80/05/05 1p
- --B006230260 Revised GA program for facility DEMARIA,E New England Nuclear Corp TSC-1 80/04/15 2ipp.

- ---8006020579 QA program for receipt use & transfer of radioactive matl shipping packages by USS CAMMPUS * Navy, Dept of 80/04/03 6pp
- 8004070022 Forwards GA program approval for radioactive matl package MACDONALD,C E Transportation Branch 80/05/27 1p
- --8006090024 GA program approval for radioactive matl package 0388, Revision 0
 MACDDNALD.C E Transportation Granch 80/05/2/ 1p

DOCKET 71-0389 GEORGIA, UNIV OF

- B006050454 Forwards matl on GA program for shipping container for 1 ci Am-241 smaled source to be used for analysis of mineral samples Requests notification of add1 required info MUSE, L A Georgia. Univ of. 80/05/12 2ipp
- BD06250197 Forwards request for addl info to complete review of QA program MACDDNALD.C E Transportation Branch 80/06/06 2pp
- DOCKET 71-0390 COMMERCE, DEPT OF, NATIONAL BUREAU OF STANDARDS
- 8006170094 Forwards proposed GA program for procurement,maint,repair & use of transportation packages for radioactive matls PEVEY.L E. Commerco, Dept of. National Bureau of Standards 80/05/30 lp
- --8006170106 Progosed QA program for procurement maint, repair & use of transportation packages for radioactive matis
 * Commerce, Dept of, National Bureau of Standards 80/05/30 7pp
- 8006300611 Forwards QA program approval for radioactive mat1 package MACDONALD.C E Transportation Branch 80/06/12 ip
- --8006300618 GA program approval for radioactive matl package 0390, Revision O MACDONALD C E Transportation Branch 80/06/12 ip

DOCKET 71-0391 NAVY, DEPT OF

- 8006300574 Forwards QA program description
 OROVES,K L. Navy, Dept of, Navai Nuclear Power Unit 80/06/10 ip
- ~~8006300690 Forwards QA program ZIMBOR.R E Navy.Dept of, Naval Facilities Engineering Command 80/05/21 1p
- --B0063G0608 GA program for Licenses 39-08478-03 & 39-08478-04 ZIMBDR,R E Navy, Dept of, Burgau of Medicine & Burgery 80/05/20 3aa

DOCKET 71-4888 MODEL SENTINEL-25A, B. C. CS. D. E. F. TELEDYNE ENGERY

- 8006250[3] Notifies of expiration of Certificate of Compliance 4988 for Models Sentinel-25A, LCG-25A; Sentinel-25B, LCG-25B; Sentinel-25C, LCG-25C; Sentinel-25C, -25C, & -25F To continue Using package, should request renowal MACDONALD, C.E. Transportation Branch 80/06/11 ip
- DOCKET 71-4984 MODEL RA-2, EXXON NUCLEAR CO . INC
- 8006060002 Ack receipt of 800402 ltr requesting amend to Certificate of Compliance 4986 to permit shipment of test trains to Ontario, Canada WEISB,D License Fee Management Branch 80/05/01 ip
- ~-8006060005 Requests amend to Certificate of Compliance 4986 to permit shipment of nuclear fuel test trains to site in Deep River. Ontario. Canada Forwards drawings & data demonstrating safety of Class I shipments * Battelle Memorial Institute. Pacific Northwest Laboratory. 80/04/02 iopp
- ~~B0060A0008 "Test Train Arrangement " Sheet 1 of 17 * Battelle Memorial Institute, Pacific Northwest Laboratory Energy, Dept of 80/03/28 ip

- ___8006060010 "Test Train Arrangement" Sheet 2 of 17

 * Battelle Memorial Institute, Pacific Northwest Laboratory *
 Energy,Dept of 80/03/28 1p
- __ADOADAODI4 "Thermal Hudraulics & Matls Test Bundim Assemblies Side A " Debugged of 1

 * Battelle Memorial Institute, Pacific Northwest Laboratory
 Energy, Dept of 79/12/18 ip
- ___B006060020 "Thermal Hudraulic & Matls Test Bundle Assemblies, Side 1 " Sheet i of i

 * Battelle Memorial Institute, Pacific Northwest Laboratory
 Energy, Dept of 80/01/17 ip

- —-8006060025 "Shipping Container for Test Bundle" Sheet 1 of 1 # Battelle Memorial Institute, Pacific Northwest Laboratory Energy, Dept of 80/04/07 1p
- DOCKET 71-5026 MODEL BC-48-220, ATCOR, INC
- ⊕006020565 Requests registration as user of Model BC~48-220 MANRY,M Georgia Power Co B0/04/30 ip
- BO06050541 Requests registration as user of Models 6144, QE-1600,PB-1, BC-48-220,LL-50-100 & LL-28-4
 MARRY,M Georgia Power Co 80/04/30 ip
- ⇔OO6230167 Advises util of registration as user of Models B-2,GE-1600, CNB-4-45,CNB-14-190,LL-50-100 & LL-2B-4 MACDONALD,C E Transportation Branch 80/06/03 2pp
- DOCKET 71-5071 MODEL URIPS-P-1, NAVY, DEPT OF
- ⊖**CO6300126 Notifies of expiration of Certificate of Compliance 5071 for Model URIPS-P-1 To continue using package, should request renewal of existing certificate of compliance MACDONALD, C E Transportation Branch 80/06/11 ip
- DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC.
- ED06120183 Requests amend to Certificate of Compliance 5364 allowing shipment of large quantities of Co-60 Fee encl W/o encl SMEDIRA.C Neutron Products. Inc. 89/05/12 jp
- BIO 06090416 Forwards Revision 3 to Certificate of Compliance 5364 for Model NPI-67-0442 MACDONALD:C E Transportation Branch 80/05/23 2pp
- --- 9004090421 Certificate of Compliance 5364.Revision 3.for Model NPI-47-0442 MACDONALD.C E Transportation Branch 80/03/23 3pp
- DOCKET 71-5450 MODEL RCC-1,-2,-3, WESTINGHOUSE ELECTRIC CORP.
- ED05120001 Requests that Certificate of Compliance 5450 be revised to include RCC-4-type shipping package List of requested changes in certificate & rept on fresh fuel shipping container test encl
 DIPIAZZA,R P Westinghouse Electric Corp 80/04/02 8pp
- -- 8005120006 "Fuel Assembly Shipping Container Internals Support Frame & Details
 - # Westinghouse Electric Corp , Nuclear Energy Systems 80/03/10
- - Westinghouse Electric Corp., Nuclear Energy Systems 80/04/01
 10

- --8005120014 "XL Fuel Assembly Shipping Container Cover & Base Weldment Details " Sheet 1 of 1 Westinghouse Electric Corp , Nuclear Energy Systems 80/04/01
- --8005120018 "XL Fuel Assembly Shipping Container/Internals " Sheet 1 of 2 * Westinghouse Electric Corp. 80/04/01 1p.
- 8006130043 Notifies of intention to use Model RCC-1.2 & 3 YUNDT.C P Portland General Electric Co 80/05/23 2pp
- DOCKET 71-9407 MODEL GE T-2, GENERAL ELECTRIC CO
- 8006060438 Forwards Certificate of Compliance 5607 for shipping package Model GE T-2 DGE evaluation of SAR & upgraded "T-2 Shipping Package SAR ROSS, D M Energy, Dept of 80/05/07 1p
- --8004040442 Certificate of Compliance 5607 for shipping package Model GE T-2 DDE evaluation of T-2 shipping container enci MATTMUELLER,F C Energy, Dept of 80/02/27 Bpp
- --8006060446 Upgraded "T-2 Shipping Package SAR " Shipping cask container drawings encl
 PETRY.8 F E I du Pant de Nemours & Co , Inc BO/04/30 450pp.
- DOCKET 71-5794 MODEL 181341, PICKER CORPORATION
- 8006040189 Forwards leak rate tests to upgrade matls licenses PENGOV.C A Picker Corp 80/04/28 3pp
- DOCKET 71-5930 HODEL SNAP 21, NAVY, DEPT OF
- BO06300134 Notifies of expiration of Certificate of Compliance 5830 for Model SNAP-21 To continue using package, should request renewal of existing certificate of compliance MACDUNALD.C E Transportation Branch 80/06/11 ip
- DOCKET 71-5862 MODEL SENTINEL-100F, TELEDYNE ENERGY BYSTEMS
- BO0625010i Notifies of expiration of Certificate of Cempliance 5862 for Model Buntinel-100F To continue using package, should request renewal of existing certificate of compliance.

 MACDONALD, C. Transportation Branch 80/06/11 ip
- 8006300630 Forwards fee for renewal of three certificates of compliance Requests renewal of current revision of Certificate of Compliance 5862 for 5-yr period ending MCGREW, J W Teledyne Emergy Bystems BO/04/13 ip
- DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO
- BD06300336 Advises that vendor is reanalyzing shielded shipping containers to confirm that calculational methods will accurately predict container response to accidents Personnel shortage impedia CUNNINGHAM, G € eding progress E General Electric Co 80/05/30 2pp
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CD
- BOD4120453 Forwards comparative data re welded Mastelloy C-276 & Type 316L stainless steel Data is submitted as supplement info for mod of Certificate of Compliance 5939, Priority review requested TRAVIS.W H Energy, Dept of 80/05/14 2pp
- 8006060612 Forwards Revision 4 to Certificate of Compliance 5737 for MAGDUNALD.C E Transportation Branch 80/05/22 2pp
- --8006060616 Certificate of Compliance 5939, Revision 4, for Model OE-1500 MACDDNALD, C.E. Transportation Branch 80/05/22 3pp
- 8006230032 Forwards Revision 5 to Certificate of Compliance 5939 for MACDONALD,C E Transportation Branch 80/06/06 2pp

~~8006230037 Certificate of Compliance 5937 Revision 5 for Model 0E-1500 MACDONALD.C E Transportation Branch 80/06/06 3pp

DOCKET 71-8940 MODEL EX-16-10, BATTELLE COLUMBUS LABORATORIES

8006290134 Notifies of expiration of Certificate of Compliance 5940 for Model EX-16-10 To continue using package, should request renewal of existing certificate of compliance HACDDNALD.C E Transportation Branch 80/06/11 ip

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

8005210456 Requests renewal of Certificate of Compliance 5942 for Model 700 shipping container Forwards drawings & package description Consolidated application for certification & renewal fee encl Drawings available in Central Files only CUNNINGHAM.G E General Electric Co 80/03/18 56pp

~-8005210460 "Shipping Cask Basket " * General Electric Co 70/02/26

~-8005210461 "Transfer Dolly Details " # General Electric Co 49/05/21 1p

--8005210465 "Cask Extension * General Electric Co 71/07/08 10

--8005210469 "700 Fuel Shipping Cask " * General Electric Co 72/03/09 ip

~-8005210472 "700 Bhipping Catk" * General Electric Co 72/03/06 ip

--Bu05210475 "Protective Jacket 700 Series Cask "

© General Electric Co 72/03/06 ip

~-8005210477 "Fuel Shipping Cask Extension 700 Series "
General Electric Co 64/01/30 ip

~-8005210481 "Base 702 Series Cask " * General Electric Co 72/03/06 ip

8005230064 Notification of registration as user of Model GE-700 in macDDNALD, C E Transportation Branch 60/06/06 19

DOCKET 71-5957 MODEL BMI-1, ENERGY, DEPT OF

8006090592 Requests that address be removed from list of shipping package addresses Research reactor has been shut down since Jun 1978, No use for Model BHI-1 package foreseen. VOIOT.A F Ames Laboratory. Energy & Mineral Resources Res. Institute 80/05/12 ip

DOCKET 71-5975 MODEL 5975, SCHLUMBERGER WELL SERVICEB

BOO6250027 Notifies of expiration of Certificate of Compliance 3975 for Model 3975 To continue using package, should request renewal of existing certificate of compliance MACDONALD.C E Transportation Branch 80/06/09 ip

DOCKET 71-5980 MODEL GE-600. GENERAL ELECTRIC CO

8006270037 Informs that before applying for competent authority certificate, amend to Gertificate of Compliance 3780 necessary Design: contents & operating conditions of package must be same in competent authority certificate.

MACDUNALD.C E Transportation Branch. 80/06/13 ip

DOCKET 71-6058 MODEL B3-1. NUCLEAR ENGINEERING CO

BOO6170077 Notification of registration as user of Models Super Tiger. Paduch Tiger, 6679, Poly Tiger, B-3, B-2 & 6272 in response to request
MACDGNALD, C E Transportation Branch 80/05/19 200

SOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

8008020499 Requests registration as user of Model CNS 15-1808 MANRY, M Georgia Power Co 80/04/30 1p

8006050541 Requests registration as user of Models 6144. GE-1600, pg-1, 9C-4B-220, LL-50-100 & LL-2B-4 MANRY, M Georgia Power Co 80/04/30 1p

BOO6170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, 6679, Poly Tiger, 8-3,8-2 & 6272 in response to request MACDONALD, C E Transportation Branch 80/05/13 2pp

8006090554 Requests registration as user of Model 6144/B HURRAY.Y D Toledo Edison Co 80/05/19 1p

8006120195 Requests registration as user of Model CNSI 15-1600 shipping cask

QERBIG.R H Neutron Products. Inc. 80/05/19 ip

8006230147 Advises util of registration as user of Models B-2.9E-1600, CNS-4-45.CNS-14-170.LL-S0-100 \$ LL-28-4 MACDONALD.C E Transportation Sranch 80/06/03 2pp

8006300007 Notifies of registration as user of Models CNBI-14-195-H & B-2 MAGDONALD,C E Transportation Branch 80/06/16 1p

DOCKET 71-6206 MODEL B. BARCOCK & WILCOX CO.

8008250118 Notification of registration as user of Model B MACDONALD, C.E. Transportation Granch 80/06/06 1p

DOCKET 71-6272 MODEL POLY PANTHER, TELEDYNE ENERGY BYSTEMS

8006170077 Notification of registration as user of Models Buper Tiger. Paduch Tiger, 6679, Poly Tiger, B-3, B-2 & 6272 in response to

MACDONALD, C E Transportation Branch 80/05/13 2pp

DOCKET 71-6275 MODEL LL-28-4, CHEM-NUCLEAR SYSTEMS, INC

9006020518 Requests registration as user of Model LL~28~4 MANRY,M Georgia Power Co 80/04/30 tp

8006050541 Requests registration as user of Models 6144, QE-1600,PB-1. BC-48-220.LL-50-100 & LL-28-4 MANRY.M Georgia Power Co 80/04/30 lp

8005040076 Requests termination of Certificate of Compliance 5275 Costs involved to refurbish package exceed what could be realized in income

CORBETT, J S Chem-Nuclear Systems, Inc 80/05/09 1p.

BOO6230167 Advises Util of registration as user of Models B-2.0E-1600. CNB-4-45.CNB-14-190.LL-50-100 & LL-2B-4 MACDONALD.C E Transportation Branch BO/06/03 2pp

DUCKET 71-6375 MODEL PO-1, CHEM-NUCLEAR SYSTEMS, INC.

HOO6050541 Requests registration as user of Models 6144, QE-1600,PB-1. BC-4B-220.LL-50-100 & LL-28-4 MANRY.M Georgia Power Co 80/04/30 1p

BOO6190146 Requests that period of 180 days be allowed to respond to NRC 800402 itr re referenced package.

CORBETTLU S Chem-Nuclear Bystems. Inc. 80/05/26. 1p

8006230167 Advises util of registration as user of Models B-2.QE-1600.* CNB-4-45.CNB-14-190.LL-50-100 & LL-28-4. MACDONALD.C E Transportation Branch 80/06/03 2pp

8006250125 Notification of registration as user of Model CNS 4~45 MACDONALD, C E Transportation Branch 80/06/06 ip

- DUCKET 71-6387 MODEL 60, BATTELLE MEMORIAL INSTITUTE
- BOO6270004 Forwards "HEDL Model 60 Unitradiated Fissionable Mati Shipping Container SAR for Packaging (SARP) " Rept contains info for consolidated application for renewal of certificate of compliance Renewal fee encl FUOUAY, J J Battelle Memorial Institute, Pacific Northwest Laboratory 80/06/02 2pp
- DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8006020415 Responds to NRC 800227 ltr re Certificate of Compliance 6400.Revision 8 Forwards rept from contractor.Hestinghouse Hanford Co Container noted in rept is only loaded SuperTiger delivered to carrier since 780228

 FITZSIMMONS.T Energy.Dept of 80/05/07 13pp
- 8006060168 Forwards addi info & drawings per NRC 800329 request re parkaging covered by Certificate of Compliance 6400 JEFFERSON,R M Sandia Laboratories 80/05/08 4pp
- --800&0&0172 "Super Tiger Assembly " Sheet 1 of 9

 * Nuclear Engineering Co . Inc , (subs of Teledyne, Inc)
 76/12/14 19
- --8006060173 "Super Tiger Assembly Details " Sheet 2 of 9 * Nuclear Engineering Co , Inc , (subs of Teledyne, Inc) 76/12/14 19
- --BOOGOADIB1 "Lid Assembly & Details " Sheet 4 of 9 * Nuclear Engineering Co . Inc . (subs of Teledyne, Inc) 76/12/14 19
- --8006060186 "Exterior Bhell Details " Sheet 6 of 9

 * Nuclear Engineering Co , Inc , (subs of Teledyne, Inc)
 75/12/14 19
- --8006060190 "Aluminum Cover" Sheet 8 of 9

 * Nuclear Engineering Co , Inc , (subs of Teledyne, Inc)
 76/12/14 1p
- ---8006060191 "Super Tiger Details " Sheet 9 of 9

 * Nuclear Engineering Co , Inc , (subs of Teledyne, Inc)
 76/12/14 ip
- 800604006B Responds to NRC 800227 itr re Model 6400 shipping package Lab has never owned package Three shipments made in package since 78022B EMBMILER.TR Battelle Memorial Institute, Columbus Laboratories 80/05/13 ip
- 8006170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, 6679, Poly Tiger, 3-3.8-2 & 6272 in response to request

 MACDUNALD, C E Transportation Branch 80/05/13 2pp
- 9006120199 Responds to B00229 ltr transmitting Certificate of Compliance 6400.Revision 8 Advises that Nuclear Engineering Co owns two SUPER TIGER shipping packages & rents to registered users
 BAER.T B Nuclear Engineering Co , Inc , (subs of Teledyne, Inc.) 80/05/16 ip
- 8004i70057 Forwards insp results on container Lab owns one super Tiger, Serial Number WO 4300 Lab has not used any other Model 4400 packaging since 780228 CHIN:S Lawrence Livermore Laboratory 80/05/19 3pp
- 8006300136 Forwards 0C Spec 85-21 67 for approval Spec used to inspect shipping container Model 6400 PADDOCK, K M 3M Co., Minnesota Mining & Mfg Co. 80/04/03 5pp.

- DOCKET 71-6553 MODEL PADUCAN TIGER, ENERGY, DEPT OF
- 800617D077 Notification of registration as user of Models Super Tiger, Paduch Tiger, 6679, Poly Tiger, 8-3, 8-2 & 6272 in response to request MACDONALD, C.E. Transportation Branch 80/05/13 208
- DOCKET 71-6591 MODEL 51032-1 & 1A, EXXON NUCLEAR CO , INC.
- --8006300623 Revised pages for Rovision 1 to consolidated license application for Models 51032-1 & 1a * Exxon Nuclear Co , inc (subs of Exxon Corp.) XN-52-01 80706730 74pp
- --8006300627 "U Oxide Fuel Rod Inner Shipping Container "
 * Exxon Nuclear Co , Inc. (subs. of Exxon Corp.) XN-301,901
 80/06/30 Ip
- --8006300628 "Rod Packaging Method for Use W/Shipping Container Model 51032-1" * Exton Nuclear Co., Inc. (subs. of Exxon Corp.), XN-601.825 D/M 80/06/30 ip
- DOCKET 71-6601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC.
- 8006020483 Requests registration as user of Model LL-50-1001 MANRY, M Georgia Power Co 60/04/30 1p
- 8006050541 Requests registration as user of Hodels 6144. QE-1600.PB-1, BC-48-220.LL-50-100 & LL-28-4 MANRY, M Georgia Power Co 80/04/30 ip
- 8006170212 Notifies of registration as user of Model LL-50-100. MACDDNALD, C E Transportation Branch 80/06/03 ip.
- 8006230167 Advises util of registration as user of Models 8-2.0E-1600. CNS-4-45.GNS-14-190.LL-30-100 & LL-28-4 MACDDNALD.C E Transportation Branch 80/06/03 2pp
- DOCKET 71-6639 MODEL MH-1A, ARMY DEPT OF
- 8004020529 Responds to NRC 800404 ltr re Hodel MH-1A packaging. Consultant will answer NRC questions by 800901 & will arrange meeting as soon as authorization to proceed is obtained from Sandia Lab CRAMFORD, H.L. Ridihalgh, Eggers & Associates 80/09/02 ip.
- DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO
- 8006170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, 6679, Poly Tiger, B-3, B-2 & 6272 in response to request MACDONALD, C E Transportation Branch 80/05/13 2pp.
- DOCKET 71-6697 MODEL 8500 PKG, GENERAL ELECTRIC CO
- GOO6300483 Requests registration as user of Model GS00 FITZSIMMONS, T Energy, Dept of BO/06/05 ip
- DOCKET 71-6698 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC
- 8006160157 Application for amend to Certificate of Compliance 6698. Revision 9, for Model NFS-4, revising removable impact limiters & protection for valves & altering configuration of bottom end of Cask NAC-1 Drawings & safety enalysis encl MIEDEMANN, L. W. JOHNSON, C. R. Nuclear Assurance Corp. 80/05/21
- ---8006160161 "Shipping Cask Spent Fuel, NFS-4 & NAC-1 " Sheet 1 of 5 WIEDEMANN, L W Nuclear Assurance Corp 80/05/08 ip

- --8006160172 "Shipping Cask Spent Fuel,NFS-4 & NAC-1" Sheet 2 of 5 WIEDEMANN,L W Nuclear Assurance Corp 80/05/08 1p
- --8006160176 "Shipping Cask Spent Fuel.NFS-4 & NAC-1" Bheet 3 of 5 WIEDEMANN, L W Nuclear Assurance Corp 80/05/08 ip
- --8006160179 "Shipping Cask Spent Fuel.NFS-4 & NAC-1" "Sheet 4 of 5 WIEDEMANN.L W Nuclear Assurance Corp 80/05/08 ip
- --8006160184 "Shipping Cask -- Spent Fuel, NFS-4 & NAC-1 " Sheet S of 5 WIEDEMANN, L W Nuclear Assurance Corp 80/05/08 ip
- --8005160187 "Safety Analysis of Modified NAC-1 Spent Fuel Shipping Cask" * Nuclear Assurance Corp NAC-E-801 80/05/16 500pp

DOCKET 71-6717 MODEL 6717 B

- BO06300027 Requests approval to use Model 6717-B.if approval not already granted Model 6717-B is used for air shipments throughout US & transportation of siposure devices in darkroom trucy vehicles BBT competency certificate encl CUTHEERTSON.T Peabody Testing/X-Ray Engineering Co 80/05/08 4pp
- --8006300031 Requests payment of fee re 800508 request for amend to Certificate of Compliance 6717 WEISS.D License Fee Management Branch 80/05/22 ip
- 8006i10032 Requests registration as user of Gamma Industries Model 6717-8 & Technical Operations Model 715 OAMBLE.O C Nuclear Energy Service. Inc 80/06/04 ip
- 800&300039 Notification of registration as user of Model &717-8 in response to 800508 request MACDGNALD,C E Transportation Branch 80/06/96 ip

DOCKET 71-6744 MODEL POLY TIGER, NUCLEAR ENGINEERING CO

- 8006170077 Notification of registration as user of Models Super Tiger, Paduch Tiger, 6679, Poly Figer, B-3, B-2 & 6272 in response to request MACODNALD, C E Transportation Branch 80/05/13 2pp
- DOCKET 71-4771 HODEL SN-1, NUCLEAR ENGINEERING CD
- 8006250063 Notifies of expiration of Certificate of Compliance 6771 for Model BN-1 MACDDNALD.C E Transportation Branch 80/06/06 is
- DOCKET 71-6786 MODEL URIPS-88, NAVY, DEPT OF
- 8006200503 Notifies of expiration of Certificate of Compliance 6786 for 15dels URIPS-88 to continue using package, renawal should be requested MACDONALD, C E Transportation Branch 80/06/11 ip
- DOCKET 71-9001 MODEL 1F-300, GENERAL ELECTRIC CO
- 8004050067 Requests amend to Certificate of Compliance 9001, Revision 9, for IF-300 spent fuel shipping cask Forwards Revision 2A for insertion into NEDO-10084-2, "Consolidated SAR for IF-300 Shipping Cask." Vols 1 & 2 Fee encl DAMSON.D M General Electric Co 80/05/12 2pp
- ---8004060074 Forwards Revision 2A for "Consolidated BAR for IF-300 Shipping Cask," Vol 1 Revision incorporates high pressure fuel rod accident analysis for dry casks shipping mode " General Electric Co NEDO-10084-2 VI 80/04/30 9pp
- --8006060078 Forwards Revision 2A for "Consolidated SAR for IF-300 Shipping Cask," Vol 2 Revision incorporates high pressure fuel rod accident analysis for fry cask shipping mode # General Electric Co NEDO-10084-2 V2 80/04/30 53pp
- 8006040030 Ack receipt of 800422 ltr informing NRC of steps taken to correct deviations noted in 9A Program Insp Repts 97900382/80-01 to 71-9001/80-01 POTAPGVS.U Region 4, Dalias, Vendor Inspection Branch 80/05/13

- --8006040032 Responds to NRC 800324 ltr re deviations noted in QA Program
 Imag Repts 99900392/80-01 % 71-9001/80-01 Corrective
 actions fabrication records for PRV valves requested from
 supplier
 HOOMMISSEN.J E General Electric Co 80/04/22 5pp
- --8004040035 Forwards GA Program Insp Repts 99900382/80-01 & 71-9001/80-01 on 800225-29 & notice of deviation PDTAPOUS,U Region 4, Dallas, Vendor Inspection Branch 200
- --8006040037 Notice of deviation from insp on 800225-29
 * Region 4, Dallas, Vendor Inspection Branch 80/03/20 2pp
- --8006040039 GA Program Insp Repts 979003B2/80-01 & 71-9001/80-01 on 800225-29 Noncompliance noted six categories of records not on file.Cask 301 not hydrostatically tested to 600 psig WHITESELL.D E Region 4. Dallas, Vendor Inspection Branch ODEGARDEN,R H . CONMAY.J T Region 4. Dallas, Office of the Director 80/03/20 8pp

DOCKET 71-9007 MODEL. 520. ARGUNNE NATIONAL LABORATORY

- 8005070013 Forwards drawings in support of application for renewal of Centificate of Compliance 9007 for Model 520 Iriditron exposure device Drawings available in Central Files only SANTORO.M P Automation Industries, Inc 80/03/24 ip
- --8005070015 "Head Assembly Iriditron Model 520 " Sheet 1 of 1 * Automation Industries, Inc 70/12/21 ip
- --8005070023 "Shield & Sleeve Assembly Model 520" Sheet i of i * Automation Industries, Inc 70/12/21 ip
- --8005070029 "'8' Tube Model 520 " Sheet 1 of 1 * Automation Industries, Inc 70/12/21 1p
- --B005070032 "Shield Casting Model 520 " Sheet 1 of 1 Automation Industries, Inc 70/12/21 1p
- 80060605 Forwards Revision 2 to Certificate of Compliance 9007 for Model 520
 MACDONALD,C E Transportation Branch 80/05/23 2pp
- --B006060609 Certificate of Compliance 9007 Revision 2, for Model 520 MACDONALD C & Transportation Branch 80/05/23 2pp
- 8006250122 Notification of registration as user of Model 520 MACDDNALD.C E Transportation Branch 80/06/06 ip
- DOCKET 71-9009 MODEL FL 10-1. GENERAL ELECTRIC CO
- 8006130062 Requests amend to Certificate of Compliance 9009, Revision 7. revising dimensions of alternate inner container constructed of 300 series stainless steel pipe permit tubing or pipe w/outside diameter tolerance of 0 031 inches
 AUSTIN.M A Babcock & Wilcor Co , Nuclear Material Div 80/05/14 is
- --8006130064 Forwards check in payment for 800514 amend request to Certificate of Compliance 9009.Revision 7 AUSTIN.M A Babcock & Wilcox Co , Nuclear Material Div 80/05/14
- DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC
- 800422025 Requests that Certifificate of Compliance 9010 be revised to provide option for method of capping off neutron shields appared to take Certificate available in Central Files only Fee encl
 HILLIAB.C E NL Industries NL Nuclear Div 80/02/21 2pp
- --8004220262 "NLI 1/2 Cask # Trailer Ceneral Arrangement "Sheet 1 of 2 * NL Industries, Inc 80/02/15 ip
- ---8004220270 "NLI 1/2 Cask & Trailer General Arrangement "Sheet 2 of 2 * NL Industries, Inc 80/02/15 1p
- --8004220277 "NLI 1/2 Spent Fuel Cask Details, Configuration B "Sheet J of 4 * NL Industries, Inc. 80/02/15 in

DOCKET 71-9011 MODEL F-MEH-GO-00004. TRANSPORTATION, DEPT OF

80060401B9 Forwards leak rate tests to upgrade matls licenses PENGDV.C A Picker Corp 80/04/28 3pp

DOCKET 71-9015 MODEL TN-8, TRANSNUCLEAR, INC.

80050B0533 Requests renewal of Certificates of Compliance 9015 for Model TN-B packaging & 9016 for Model TN-P packaging Forwards "TN-B & TN-P SAR" Vols 1 & 2, Revision B GULDMANN.K Transnuclear, Inc 80/04/07 2pp

~-8005080537 "TN-8 & TN-9 SAR " Six oversize drawings encl * Transnuclear, Inc 80/04/08 250pp

DOCKET 71-9016 MODEL TN-9 / TRANSNUCLEAR, INC.

80050B0533 Requests renewal of Certificates of Compliance 9015 for Model IN-8 packaging & 9016 for Model IN-9 packaging Forwards "TN-8 & TN-9 SAR" Vols 1 & 2, Revision 8 OBLDMANN.K Transnuclear, Inc 80/04/09 2pp

--8005090537 "TN-8 & TN-9 SAR " Six oversize drawings encl * Transnuclear, Inc. 80/04/08 250pp

DOCKET 71-9018 MODEL BU-6, GENERAL ELECTRIC CO

8006130006 Application to amend Certificate of Compliance 9019 for BU-7 package to increase max bulk density of U oxide powder from 2 3 to 4 2 g/cc Amend fee encl KAPLAN.A L General Electric Co , Nuclear Energy Products Div 80/05/15 2pp

--8006130008 Forwards Certificates of Compliance 9018 & 7019, authorizing delivery of radioactive matl to cerrier for transport in Models BU-6 & BU-7 Vendor authorized to use Models BU-6 & BU-7 under License SMM-54 Transportation Branch 74/08/06 is MACDONALD.C F

--8006130012 Certificate of Compliance 9019, authorizing delivery of radioactive mati to carrier for transport in Models BU-6 & BU-7 Vendor authorized to use Models BU-6 & BU-7 under License SMM-54 MACDONALD.C E Transportation Branch 74/08/06 4pp

--8006130013 Application to amend License SNM-54, to authorize delivery of SNM to carrier for transport in Models BU-6 & BU-7 TBCHAECHE, A N General Electric Co 74/05/24 16pp

--8006130015 "GE Model BU-7 U Shipping Container Criticality Bafety Analysis "
ARTIGAS,R , WILSON, B D General Electric Co NEDQ-11277
74/02/28 9pp

DOCKET 71-9019 MODEL 8U-7, GENERAL ELECTRIC CO

800Ai30006 Application to amend Certificate of Compliance 9019 for BU-7 package to increase max bulk density of U oxide powder from 2 3 to 4 2 g/cc Amend fee encl KAPLAN, A L General Electric Co , Nuclear Energy Products Div 80/05/15 2pp

--8006130008 Forwards Certificates of Compliance 9018 & 9019, authorizing delivery of radioactive matl to carrier for transport in Models BU-6 & BU-7 Vendor authorized to use Models BU-6 & BU-6 MODENALD.C E Transportation Branch 74/08/06 19

--8006130012 Certificate of Compliance 9019, authorizing delivery of radioactive mat1 to carrier for transport in Models 80-6 & 80-7 Vendor authorized to use Models 80-6 & 80-7 under Licanse SMM-54 MACDONALD.C E Transportation Branch 74/08/06. 4pp

--8006130013 Application to amend License SNM-54, to authorize delivery of SNM to cerrier for transport in Models BU-6 & BU-7.
TBCHAECHE, A N General Electric Co 74/05/24 16pp.

--8006130015 "GE Model BU-7 U Shipping Container Criticality Bafety Analysis "
ARTIGAS,R , WILSON, B D General Electric Co. NEDO-11277 74/02/28

DOCKET 71-9023 MODEL NL1-10/24. NL INDUSTRIES, INC

8006180595 Recommends issuance of IAEA Certificate of Competent Authority for NL Industries Model NLI-10/24 as Type B(M) package in response to licensee 800207 request MACDOMALD, C E Transportation Branch 80/06/03 1p.

DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.

8006270041 Notification of registration as user of Model 650 MACDONALD, C E Transportation Branch 80/06/09 1p

DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.

BO06040061 Requests continued registration as user of Model 715 matl DAGGUDAL Requests continued registration of the shipping package

GONWAY,W F Capital X-Ray Service 80/05/12 ip

BOO6120142 Requests renewal of Certificate of Compliance 9039 for Technical Operations Model 715 shipping package DALLINGER, J.F. General Dynamics Corp., Electric Boat Div. 80/05/15.

8006110449 Advises that Model 715, authorized by Certificate of Compliance 9039, meets IAEA requirements for Type B(u) packages MACDONALD, C. E Transportation Branch 80/05/27 1p

BO06240111 Requests registration as user of Tech/Dps Model 715. HEBS.C R High Steel Structures, Inc. B0/05/29 1p.

BOO6170200 Notifies of registration as user of Model 715 MACDONALD,C E Transportation Branch BO/06/03 1p

8006|10032 Requests registration as user of Camma Industries Model 6717-8 & Technical Operations Model 715 GAMBLE,O C Nuclear Energy Service, Inc. 80/06/04 1p

8006300108 Notification of registration as user of Model 715 in response to request MACDONALD.C E Transportation Branch 80/06/16 1p.

DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO.

8005290066 Requests renewal of Certificate Df Compliance 9044 for Model 1600 shipping cask Oversize revised cask drawings in support of application & renewal fee onc! W/o renewal fee CUNNINOHAM.G E General Electric Co 80/04/09. 16pp

--B005270070 "Bpacer & Plug "
* General Electric Co 77/0B/03 ip

--8005290075 "Spec Control Drawing Model 1600 Seal." Sheet i * General Electric Co 80/04/17 ip

--8005290083 "Lifting Device Cover & Lock Assembly." * General Electric Co 69/03/3: 1p

--8005290087 "Redundant Ear "
* General Electric Co 79/10/10 ip

---B005290091 "Model 1600 Jacket Tie-Down Yoke," Sheet 1.
* General Electric Co 79/10/10 1p

---8005290095 "Model 1600 Transport Container Assembly "

* General Electric Co 79/10/11 to

--8005270100 "Base, Model 1600 Cask " * General Electric Co 79/10/10 1p

--8005290105 "Shielding Liner 26-Inch Diameter Lead, Model 1600 "
* General Electric Co 79/10/10 ip

--8005290111 "Tacket,Model 1600." * General Electric Co 77/10/10 1p

--8005270115 "Neutron Shielding Liner" * General Electric Co 79/05/10 1p

```
--8005270120 "Hodel 1600 Shipping Catk "
* General Electric Co 79/10/10 ip
   -9005290123 "Model 1600 Cast W/Redundant Suspension Ears "
# General Electric Co 79/10/10 1p
8006020569 Requests registration as user of Model GE-1600 MANRY, M Georgia Power Co 80/04/30. ip
800605054% Requests registration as user of Models 6144, QE-1600.PB-%, BC-48-220.LL-50-100 & LL-28-4 MANRY.M Qeorgia Power Co 80/04/30 ip
8006120464 Forwards ltr & analysis that should have been included w/
800409 renewal request for Cartificate of Compliance 9044
CUNNINGHAM.O E General Electric Co 80/05/07 1p
--B006120480 Application to amend License SNM-760, to increase allowable loading of fistie matl to 1200 g CUNNINGHAM Q E General Electric Co , Nuclear Energy Products Div. 73/07/03 10pp.
8006230167 Advises util of registration as user of Models B-2.GE-1600,
CNS-4-45,CNS-14-190.LL-50-100 & LL-28-4
MACDONALD.C E Transportation Branch 80/06/03 2pp
DOCKET 71-9045 HODEL QE-1000, GENERAL ELECTRIC CO
B006030034 Requests renewal of Certificate of Compliance 7045 for QC Model 1000 shipping container Revised consolidated application k oversize drawings encl CUMNINGKAH-9 E General Electric Co B0/04/21 15pp
 ~~8006030037 "Jacket,1.000 Series Cask "
* General Electric Co 69/03/26 ip
 Canaral Electric Co
                                                    69/03/26 1p
~-8006030044 "Base 1,000 Series Cask "
# General Electric Co 69/03/26 1p
~~8006030048 "Shipping Assembly.1,000 Series Cask "
* General Electric Co 69/03/26 ip
DOCKET 71-9046 MODEL GE-1100, GENERAL ELECTRIC CD.
B005270337 Requests renewal of Certificate of Compliance 9046 for Model 1100 shipping container. Revised consolidated application supporting request & oversized drawings encl CURNINGHAM. 0 E General Electric Co 80/04/22 13pp.
--8005270342 "Jacket.1100 Series Cask " * General Electric Co. 69/03/20
--8005270345 "Shipping Cask Assembly "
# General Electric Co. 69/03/20
---8005270348 "Cask, 1100 Series Cask "
* General Electric Co 69/03/20 ip.
 --8005270351 "Base, 100 Series Cask "

+ General Electric Co 69/03/20 1p
DOCKET 71-9050 MODEL GE-900, GENERAL FLECTRIC CO.
$606030019 Requests renewal of Certificate of Compliance 9050 for QE
   Medal 900 shipping container.Forwards revised consolidated application oversize drawings & renewal fee CONNINGHAM, O & General Electric Co 80/04/18 i3pp
--8006030022 "Jacket Assembly 700 Series Cask."

* General Electric Co 49/03/20, ip
--B006030025 "Base - 400,900 & 1,400 Series Cask "

# General Electric Co B0/02/22 1p
```

--8006030031 "Bhipping Assembly.900 Series Gask "
* General Electric Co 69/03/20 ip

```
8004040067 "Base - 400,900,1400 Series Cask "
* General Electric Co 80/02/22 16
---8004040070 "Jacket Assembly - 1400 Series Cask "

* General Electric Co 69/03/29 1p
--8006040072 "Shipping Assembly - 1400 Series Cask"
* Oeneral Electric Co 69/03/29 ip
--8006040075 "Bhipping Cask Assembly 1.000 Ci Co-60 - 1400 Series Cast "
* Budd Co 69/01/07 ip
DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF
8006040175 Advises that vendor will ship 3 mCi Cm-244 sealed sources under general license VERNIG-P Q Kevex Corp Analytical Instrument Div 80/04/29 1p
8006170110 Notifies of registration as user of Model N-55
MACDONALD,C E Transportation Branch 80/06/03 ip
 DOCKET 71-9071 MODEL AP-101, CHEM-NUCLEAR BYS, INC.
8006130044 Forwards "Amend to ANEFCO, Inc BAR, Cask AP-101, Section 6
Criticality & Section 7 Operating Procedures " Rept
completes petition to amend Certificate of Compliance 9071
to include spent fuel assemblies as contents
MURPHY, J D Anefco, Inc 80/05/16 3pp
--8006130045 "Amend to ANEFCO.Inc SAR.Cask AP~101.Section 6 Criticality & Section 7 Operating Procedures "

* Anefco.Inc 80/05/15 98pp
DOCKET 71-9073 MODEL DH-142, NUCLEAR PACKAGING, INC
8006120149 Advises of address change effective 790321
DODSON,D Nuclear Packaging, Inc 80/05/12 ip
DOCKET 71-9079 MODEL HN-100 BERIES 2, HITTMAN NUCLEAR & DEVELOPMENT
8005070261 Requests that Certificate of Compliance 9079 for Model HN-100 be amended to cover use of nonstructural appurtenances Forwards Drawing CO01-4-9119 Revision E. Sheets 1 to 7 Amend Fee forwarded in 791219 Itr Drawings in Central Files MALLORY. C W. Hittman Nuclear & Development Corp (subs. Hittman Corp.) 80/03/17 3pp
--8005070268 "Assembly Transportation Shield Model HN-100 Series-2 "
       Sheet 1 of 7 ** Hittman Nuclear & Development Corp (subs. Hittman Corp.)
--B005070274 "Weldment & Details Cask Body, HN 100-2 Transportation Shield" Bheet 2 of 7 # Hittman Nuclear & Development Corp (subs. Hittman Curp.), B0/03/17 ip
  --8005070284 "Weldment & Details Cask Body,HN-100-2 Transportation
Bhield " Bheet 3 of 7
* Hittman Nuclear & Development Corp (subs Hittman Corp )
80/03/17 1p
--8005070294 "Weldment & Details Primary Lid.HN-100-2 Transportation
Shield" Sheet 4 of 7
* Hittman Nuclear & Development Corp (subs Hittman Corp )
--8005070303 "Weldment & Details Primary Lid.HN-100-2 Transportation
Bhield " Sheet 5 of 7

# Hittman Nuclear & Development Corp (subs Hittman Corp )
--8005070316 "Weldment & Details Secondary Lid, HN-100-2 Transportation
Shield" Sheet 6 of 7
* Hittman Nuclear & Development Corp (subs Hittman Corp.), 3
60/03/17 1p
```

DOCKET 71-9051 MODEL GE-1400, GENERAL ELECTRIC CO

- --8005070319 "Optional Cask Appurtenances HN-100 Series-2 " Sheet 7 of 7 * Hittman Nuclear & Development Corp (subs Hittman Corp) 80/03/17 1p
- 8006050433 Requests amend to Certificate of Compliance 9079, revising drawings to show critical features of cask which are part of safety analysis Amend fee encl MALLORY, G W Hittman Nuclear & Development Corp (subs Hittman Corp) 80/05/20 3pp
- ---8006050437 "Assembly Transportation Shield, HN-100 Series-2 " Sheet 1 of 1 4 Hittman Nuclear & Development Corp (subs. Hittman Corp.) 80/05/14 10
- --BOQ6050439 "Weldment.Cask Body Transportation Shield.HN-100 Series 2 "
 Sheet 1 of 1
 4 Hittman Nuclear & Development Corp (subs Hittman Corp)
 80/05/13 ip
- --8096050441 "Option Cask Appurtenances Transportation Shield.HN-100 Series-2 " Sheet 1 of 1 * Hittman Nuclear & Development Corp (subs Hittman Corp) 80/09/13 ip.
- 8006060276 Forwards Revision 5 to Certificate of Compliance 9079 for Model HN-100 Series 2 thipping package MACDONALD.C E Transportation Branch 80/05/23 2pp
- --800.60.60.282 Certificate of Compliance 9079. Revision 5. for Model HN-100 Baries 2 shipping package MACDONALD. C E Transportation Branch 80/05/23 3pp
- DOCKET 71-9081 MODEL CN81-1600, CHEM-NUCLEAR SYSTEMS, INC
- 8006020495 Requests registration as user of Model CNSI-1600 MURRAY.7 D Toledo Edison Co 80/05/06 ip
- 8006170214 Notifies of registration as user of Model CNS-1600 MACDONALD, C E Transportation Branch 80/06/03 19
- DOCKET 71-9086 MODEL HN-100 SERIES 1, HITTMAN NUCLEAR & DEVELOPMENT
- BOO51201B1 Requests that Certificate of Compliance 9086 for Model HN-100 Series 1 be amended to cover use of nonstructural appurtenances Forwards Drawing COO1-5-7120, Sheet 1 & list of requested changes in Certificate of Compliance 9086 MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 80/03/17 Spp
- DOCKET 71-9089 MODEL NH-100 8, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8005070560 Requests that Certificate of Compliance 9089 for Model HN-1008 package be amended to cover use of nonstructural appurtenances Forwards Drawing COO1-5-9721. Revision 1.8 heet 1 & list of requested changes Drawing in Central Files only MALLORY, C W Hittman Nuclear & Development Corp (subs. Hittman Corp) 80/03/17 Spp
- --BG05070564 "Optional Cask Appurtenances HN-1005," Sheet 1 Of 1
 4 Hittman Nuclear & Development Corp (subs Hittman Corp)
 B0/03/18 1p
- DOCKET 71-9091 MODEL 30 A) GENERAL ELECTRIC CO
- 8006160172 Requests registration as user of Model 30 A SHELLEY, W J Kerr-McGee Corp 80/03/28 1p
- DUCKET 71-9093 MODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 8006250031 Notifies of expiration of Certificate of Compliance 9093 for Models MW-3000, Bentinel-3 5 Sentinel-8 To continue using package, should request renewal of existing certificate of compliance MACDONALD, C.E. Transportation Branch 80/06/06 ip

- DOCKET 71-9094 MODEL CNSI-14-195-H. CHEM-NUCLEAR BYSTEMS, INC
- BO05270516 Forwards consolidation of application & BAR for Model 14-175-H shipping cask, superseding refs in 790406 certificate of compliance, Revision 3 Includes Revision A-F to Drawing 1-189-101 Amend fee encl CORBETT, J S Chem-Nuclear Systems, Inc 80/03/31 5pp
- --8005270522 Informs of refund resulting from everpayment of minor amend fee for Certificate of Compliance 9094 JACKSON, 6 License Fee Management Branch 80/04/17 ip
- --8005270525 "SAR for MOdel 14-195-H Shipping Cask" * Chem-Nuclear Systems, Inc. 80/03/31 111pp
- --8005270528 "Transport Cask 14-195-H." Revision A-F * Chem-Nuclear Systems. Inc 80/03/31 1p
- 8004030152 Forwards oversize Drawings 1-189-101 & 1-298-101,per B00509 telcom between D Odegaarten & B Svinis * Chem-Nuclear Systems, Inc B0/05/09 1p
- ---8006030161 "Transport Cask 14-195-H * Chem-Nuclear Systems, Inc. 80/03/28 ip
- --8006030164 "Transport Cask 21-300 "
 # Chem-Nuclear Systems, Inc 89/03/26 ip
- BOO6120192 Requests registration as user of Model CNBI-14-195-H MURRAY,T D Toledo Edison Co BO/05/14 ip
- 8006030033 Forwards Revision 4 to Certificate of Compliance 9094 for Model CNSI 14-195-H MACDONALD,C E Transportation Branch 80/05/20 3pp
- --8006030035 Certificate of Compliance 9094.Revision 4.for Model CNSI 14-195-H MACDONALD.C E Transportation Branch 80/05/20 Rpp
- 8006170815 Forwards Certificate of Compliance 9094, Revision 5, for Model CNS 14-195-H Supersedes Revision 4, dtd 800590 Constitutes authority to use package for shipment of radioactive metl & for package to be shipped per code requirements MACDONALD, C E Transportation Branch 80/05/29 Gpp.
- --B006170817 Certificate of Compliance 9094 Revision 5 for Hodel CN8 14-195-H MACDDNALD, C E Transportation Branch 80/05/29 2pp
- 8006300007 Notifies of registration as user of Models CNSI-14-195-H & 8-2 MACQDONALD.C E Transportation Branch 80/06/16. ip
- DOCKET 71-9096 MODEL. CNBI-21-300, CHEM-NUCLEAR SYSTEMS, INC.
- BO05130121 Forwards consolidated application & SAR for renswal of certificate of compliance for Model 21-300 Supersedes all refs in Certificate of Compliance 9096. Revision 2 CORBETT, J B Chem-Nuclear Bystems, Inc. B0/04/14 6pp
- 8006030152 Forwards oversize Drawings 1-189-101 & 1-298-101.per 800509 telton between D Udegsarten & 8 Syinis * Chem-Nuclear Systems, Inc. 80/05/09 1p
- --8006030161 "Transport Cask 14-195-H " # Chem-Nuclear Systems, Inc 80/03/28 ip
- ---8006030164 "Transport Cask 21-300 "

 * Chem-Nuclear Systems, Inc 80/03/26 ip
- 8006020582 Forwards Revision 3 to Certificate of Compliance 9096 for Model CHSI 21-300 MACDUNALD, C. E. Transportation Branch 80/05/20 3pp
- ---80060205B5 Certificate of Compliance 9096:Revision 3:for Model CNSI 21-300 MACDUNALD.C.E Transportation Branch. 80/05/20. Rpp
- 8006170174 Authorites extension of Certificate of Compliance 7096; Revision 2 until 800731 Extension will provide orderly transition to implement gasket seal changes required by Revision 3 of certificate, 4td 800520 MACDONALD.C.E. Transportation Branch, 80/05/29 2pp.

DOCKET 71-9103 MODEL NL1-6502

- BOO6180210 Responds to appeal repartial denial of FOIA request for route info respent fuel shipments from Chaik River to Ontario Canada Appeal is denied Info withheld (ref FOIA Exemption 4 to 100FR2 790)
 DIRCKS, H J Office of the Esscutive Director for Operations BO/05/09 2pp
- --8006180223 Certificate of Compliance 9103 Revision 1.for radioactive math shipping package Model N.1-6502
 MACDONALD C E Transportation Branch 78/05/03 4pp
- DOCKET 71-9111 MODEL CN6-80A, CHEM-NUCLEAR, INC
- 8006040060 Notifies that facility will use Chem Nuclear Inc Model CNS 6-80-2 radioactive shipping cask for delivery of matls to carrier FAY.C W Wisconsin Electric Power Co 80/05/14 ip
- 8004170207 Notifies of registration as user of Model CNA-80A MACDONALD.C E Transportation Branch 80/04/03 ip
- DOCKET 71-9113 MODEL 7-100, CHEM-NUCLEAR SYSTEMS, INC.
- 8006040071 Requests registration as user of Hodel CN9-7-100 matte shipping package FRANCO.F.F Omaha Public Power District 80/05/08 ip
- B00A230315 Forwards revision bringing Certificate of Compliance 9113 in line w/Certificate 90B0.issued for same package. Upgrades matl from A-36 to A-516.Grade 70.providing larger positive safety margin Bupportive drawings encl HANBEN.L J Nuclear Packaging. Inc 80/05/09 29pp
- --8006250319 "Transportation Shield Model 7-100. Tupe A. * Sheet 1 of 2 * Nuclear Packaging. Inc 78/05/01 ip
- --9005250322 "Transportation Shield, Model 7-100, Type A." Sheet 2 of 2 * Nuclear Packaging, Inc 80/05/14. ip
- 8006170203 Notifies of registration as user of Model 7-100, MACDDNALD.C E Transportation Branch 80/06/03 ip
- DOCKET 71-9132 MODEL T-3. NUCLEAR PACKAGING, INC
- 8006060429 Forwards Revision 0 to Certificate of Compliance 9132 for Model T-3 & safety evaluation MACDUNALD, C.E. Transportation Branch 80/05/21 ip.
- --8006060433 Cartificate of Compliance 9132 Revision O.for Model T-3 MACDONALD.C E Transportation Branch 80/05/21 App.
- --8006050437 Bafety evaluation approving Model T-3 cask MACDDNALD, C E Transportation Branch, 80/05/21 11pp
- DOCKET 71-9195 MODEL CENTURY, DAMMA INDUSTRIES
- B006030067 Forwards request for add1 info re 790824 application, as amended 800227, requesting approval to deliver Century model packaging to carrier for transport Add1 info should be submitted in form of revised pages to original BAR MACDONALD.C E Transportation Branch 80/05/16 2pp

- DOCKET 71-9138 MODEL 78-D-1458, NAVY, DEPT OF
- 8006200606 Advises that request for info re container approval is being prepared & will be forwarded by 800630 MCKNIGHT,T R Navy.Dept of 80/05/28 ip
- DOCKET 71-9141 MODEL 900 TYPE B. TECHNICAL OPERATIONS, INC.
- B006090407 Forwards Revision 0 to Certificate of Compliance 9141 for Model 900 Type 8 & safety evaluation MACDONALD, C E Transportation Branch 80/05/20 1p
- --8006090410 Certificate of Compliance 9141, Revision O.for Model 900 Type B MACDONALD.C E Transportation Branch 80/05/20 2pp
- ---B006090413 Bafety evaluation approving Model 900 Type B packaging MACDUNALD.C E Transportation Branch 80/05/20 2pp
- 8004070486 Advises that Model 900 authorized by Certificate of Compilance 9141, meets requirements for Type 8(U) packages MACDDNALD, C E Transportation Branch 80/05/20 1p
- DOCKET 71-9853 MODEL ORNL BNL NBS UN FUEL CONTAINER, ENERGY,
- 9006040088 Forwards as-built DRNL drawings for shipping containers, per NRC request TRAVIS, H.H. Energy, Dept of 80/05/05 1p
- ~-8006040095 "Unirradiated Fuel Element Shipping Container Details." asbuilt, Sheet 2 of 2 * Union Cerbide Corp. 79/03/31 ip
- ~-800&040099 "Unirradiated Fuel Element Shipping Container Assembly," asbuilt Sheet 1 of 1 * Union Carbide Corp 80/02/06 1p
- --8006040102 "Unirradiated Fuel Element Shipping Container Details," asbuilt Sheet 2 of 2 * Union Carbide Corp 80/02/06 ip
- --8006040105 "Unirradiated Fuel Element Shipping Container Assembly," astwilt Sheet 1 of 1 * Union Carbide Corp. 80/02/06 ip
- --8006040107 "Unirradiated Fuel Element Shipping Container Details," asbuilt Sheet 2 of 2 * Union Carbide Corp 80/02/06 ip
- ---8006040109 "Unirradiated Fuel Element Shipping Container-Assembly," as--built Bheet 1 of 1 * Union Carbide Corp 80/02/06 1p
- BOO&O&O421 Forwards Revision 1 to Certificate of Compliance 9853 for Models ORNL-UNL-NBS unirradiated fuel shipping container shipping sackages MACDDNALD, C E Transportation Branch 80/05/22, 2pp
- --8006060425 Certificate of Compliance 9853.Revision 1.for Models ORNK-BNL-NBS unitradiated fuel shipping container shipping packages MACDONALD.C E Transportation Branch 80/05/22 3pp

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS 8003100176 Transcript of 800305 briefing on assessment of cleanup at TMI Pp 1~65 * Commission 80/03/05 45pp ~-B003100181 Forwards "Evaluation of Cleanup Activities at TMI," rept of special task force formed on B00219 Lists actions to be taken in order to restore forward motion to cleanup process DIRCMS.W J Office of the Executive Director for Operations B0/02/29. 2pp 8008270078 Forwards notice of 800809 & 27 meetings of Advisory Screening Committee for Lawyer Members Requests 800425 FR publication HGYLE.J C ACRS - Advisory Committee on Reactor Safeguards 80/04/23 ip ~-B005270581 Notice of B00509 & 27 meetings of Advisory Ecreening Committee for Lawyer Members HOYLE.J C Office of the Secretary of the Commission 80/04/23 8006060215 Transcript of 800515 public meeting in Bethesda, MD re withholding of NRC spent fuel route info from public disclosure Pp 1-34 # Commission 80/05/15 35pp. 8006120407 Transcript of 800528 afternoon Affirmation Bassion 80-25 re 8ECY-A-80-74 in Washington DC. Pp 1-3 # Commission 80/05/28. 3pp 8006120422 Transcript of 800515 briefing in Bathesda, MD re upgrade of operations ctr Pp 1-73. Morning session # Commission 80/05/15 73pp. 8006120427 Forwards notice of Commission meetings during wk of 800517 for publication in 800517 FR CHILK-S J Office of the Secretary of the Commission 80/05/15 --800&120431 Notice of Commission meetings during wk of 800517 to discuss mgt-organization & internal personnel matters
TWEED:R M Office of the Secretary of the Commission. 80/05/14 800&130009 Transcript of 800&00 public meeting in Washington,DC to discuss action plan policy statement, Pp 1-23 * Commission 80/06/06 23pp 8004i30079 Forwards notice of Commission meetings during wk of 800505 for publication in 800504 FR.
CHILK-S J Office of the Secretary of the Commission 80/05/01 --8006130084 Notice of Commission 800505,06 & 07 meetings in Washington, BC re revised Philippine opinion, affirmation items & const resumption at Marble Hill.

THEED,R M Office of the Secretary of the Commission 80/04/27 8005130087 Forwards notice of availability of draft safety guide for

public comment CHILK, S.J. Office of the Secretary of the Commission 80/05/06

--- B006130091 Notice of availability of draft safety guide for public

comment. MINDONE,R B, Office of Standards Development, Director 80/04/29

```
8006130100 Forwards notice of Commission meetings during wt of 800505 for publication in 800508 FR CHILK, S J Office of the Secretary of the Commission 80/05/06
   --B006130103 Notice of Commission B00512 meeting in Hashington, DC re
meeting w/Harrisburg-Middletown area citizen groups re TMI--2
cleanup
           cleanup
MAGEE.W Office of the Secretary of the Commission 80/05/05
 8006160167 Informs that Commission approved proposed ltr to McDonough re retransfer of medium enriched U to South Africa, subj to listed mod CHILK, S J Office of the Secretary of the Commission 80/06/03
 8006170800 Transcript of 800515 Affirmation Session 80-22 in Bethesda.
MD Pp 1-4 Afternoon session Draft FR notice encl
* Commission 80/05/15 16pp
 8006170809 Transcript of B00516 discussion of SECY-80-230 in Washington, DC Pp 1-30 Morning session + Commission 80/05/16 31pp
 8006180125 Transcript of 800830 Affirmation Session 80-06 in Washington DC Pp 1-2  
* Commission 80/05/30 3pp
 ---800A160132 SECY-80-1826
          DOINGTO DELT-DU-LOZE
Recommends approval of encl revised draft order Encl PA
Bradford separate statement to be appended to order.
BICKWIT,L. Office of the General Counsel 80/03/29. 9pp.
---B00618013B Responds to B00324 ltr to J Ahearne re problems of evacuating large populations in short period of time Program of upgrading emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant DENTON, HR Diffice of Nuclear Reactor Regulation, Director B000429 208
                                   Չրր
 --8006180149 Elaborates on concerns expressed in 800102 ltr re need for practical evacuation plans around nuclear power sites Problems of evacuating large populations is short time have been underestimated Requests open hearings on issues HOLF: B Affiliation Unknown 80/03/24 2pp
 BOO61B0146 Transcript of 770331 Commission briefing on South Africa in Washington, DC Pp 1-9. Afternoon session * Commission 77/03/31 10pp
8006180176 Transcript of 800512 Affirmation Session 80-21 in Washington, DC. Pp 1-6 Afternoon session.

* Commission 80/05/12 7pp
 8006180628 Transcript of 800604 public meeting in Washington,DC to discuss action plan,Pp 1-45.

* Commission, 80/06/04 46pp
B006180635 Transcript of B00606 meeting re site characteristics in Washington, DC Pp 1-27
* Commission. B0/06/06 28pp.
800619004B Transcript of B00605 Affirmation Bession 80-27 in Washington, DC, Pp 1-3 * Commission 80/06/05 4pp
8006200343 Transcript of 800523 open Affirmation Session 80-24 in Washington DC re SECY-A-80-4A & SECY-B0-202 Pp 1-3 * Commission 80/05/23 4pp
```

- --8006200348 SECY-80-202 006200349 SECY-80-202
 Discusses role of NRC in waste confidence proceeding
 Recommends issuance of proposed memorandum & order.Draft
 memorandum & order encl
 BICKHITL Office of the General Counsel 80/04/24 4pp
- 8006200528 Transcript of 800612 public meeting in Washington.DC to discuss progress status & plans of Nuclear Safety Analysis Ctr.Pp 1-84 Viewgraphs encl * Commission 80/06/12 120pp
- 8006230278 Forwards IAEA draft safety guide notice of availability for public comment for FR publication at earliest possible date CHILK.S J. Office of the Secretary of the Commission. 80/06/04
- --8006230281 Notice of availability of IAEA draft safety guide for public SMITH, R O Office of Standards Development, Director 80/06/02
- 8006240201 Forwards Bunshine FR notice of Commission meetings during wk of 800519, for 800521 FR publication CHILK,S J Office of the Secretary of the Commission 80/05/19
- --- 8006240206 Sunshine FR notice of Commission meetings during wk of MAGEE.W Office of the Secretary of the Commission 80/05/15
- 8006240211 Forwards Sunshine FR notice of Commission meetings during wk of 800526, for 800604 FR publication CHILK.B J Office of the Secretary of the Commission 80/06/02
- --8006240213 Bunshine FR notice of Commission meetings during wk of 800526 to discuss Indian Point revised order THEED:R M Office of the Secretary of the Commission 80/05/30
- 8006240223 Forwards Sunshine FR notice of Commission meetings during wk of 800526 for 800527 FR publication CHILK.S J Office of the Secretary of the Commission 80/05/22
- 9008240225 Sunshine FR notice of Commission meetings during wk of 800524 TWEED, R M Office of the Secretary of the Commission 80/05/21
- 8006240623 Forwards FR notice of Commission meetings during wk of 800609.for publication on 800606 CHILK.S. J. Office of the Secretary of the Commission 80/06/04
- --8006240426 FR natice of Commission meetings during wk of 800609, for publication on 800606
 THEED,R M. Office of the Secretary of the Commission 80/06/03.
- 8006240630 Forwards notice of Commission meetings during wks of 800519 & 0526 for 800528 FR publication CHILK-B J Office of the Secretary of the Commission 80/05/23
- --8006240436 Sunshine FR notice of Commission meetings during wks of BOO519 & 0526 to discuss mpt-organization & internal personnel metters & review ALAB-502 TWEED:R.M. Office of the Secretary of the Commission 80/05/22
- BOO6250025 Transcript of BOO612 discussion & vote on affirmation item in Hashington.DC Pp 1-15. Braft orders & separate views of Commissioner Bradford enc! * Commission BO/06/12. G5pp
- --8006250030 SECY-B0-271A Forwards draft revision to TMI action plan statement of policy reflecting changes made as result of 800606 Commission meeting, mods to language & minor editorial BICKWIT.L. Office of the General Counsel 80/06/11. [1pp
- 8008230199 Forwards notice of issuance of appointment of performance review board for Benior Executive Svc for earliest possible FR publication CHILK. B. J. Office of the Becretary of the Commission. 80/05/15.

- -8006250204 Notice of issuance of appointment of performance review board for Senior Executive Svc for three-yr term, effective 800901 DIRCKS, & J Office of the Executive Director for Operations
- 8006250313 Forwards notice of Commission metings during wk of 800905 for publication in 800906 FR CHILK, S. J. Office of the Secretary of the Commission 80/09/02
- --B006250320 Notice of Commission 800508 meeting in Washington,DC rs mgt. organization,internal personnel & action plan TWEED,R M Office of the Secretary of the Commission 80/05/01
- B0062503B4 Forwards notice of Commission 800506 meeting in Washington, DC for publication in 800508 FR CHILK-B J Office of the Secretary of the Commission 80/05/06
- ---8006250398 Notice of Commission 800506 meeting in Washington, DC to discuss Phillipine export & SEP MAGEE, W. Office of the Secretary of the Commission 80/05/01
- 8006250376 Forwards Sunshine FR notice of Commission meeting during wk of 800602, for publication on 800603 CHILK.8 J Office of the Secretary of the Commission 80/05/30
- --8008250377 Sunshine FR natice of Commission meeting during wk of 800602 THEED,R M Office of the Secretary of the Commission 80/05/29
- 8006260011 Forwards notice of Commission meetings during wk of 800905 for publication in 800512 FR
 CHILK.8 J Office of the Sacretary of the Commission 80/05/08
- ---8006260016 Notice of Commission meetings during wk of 800506 in Washington,DC re Phillipine export TMEED,R M Office of the Secretary of the Commission 80/05/67
- B006260021 Forwards notice of Commission meetings during wk of B00512 for publication in B00513 FR CHILK.8 J Office of the Secretary of the Commission B0/05/09
- ~-8006260028 Notice of Commission 800512.13 & 15 meetings in Washington. BC tr THI-2 cleanup.Tarapur export licenses.operations ctr upgrade & protection of routing info MAGEC.W Office of the Secretary of the Commission 80/05/08
- 8006260061 Forwards FR notice of 800527.0606 & 09 closed meetings of Advisory Screening Committee for Lawyer Vacancies on ASLAP, for publication on earliest possible date CHILK.8 J Office of the Secretary of the Commission 80/05/19
- --8006260072 FR notice of 800527.0606 & 09 closed meetings of Adylsary Reresning Committee for Lawyer Vacancies on ASLAP. HOYLE, J C Office of the Bacretary of the Commission 80/05/19
- 8006260071 Transcript of Commission 800618 public meeting in Washington.DC re final rulemaking on emergency preparedness Pp 1-90 * Commission 80/06/18 108pp
- 8006300544 Transcript of 770406 meeting in Washington, DC re development of availuation program Prepared from tape recording Pp 1-55 * Commission 77/04/06. 55pp
- 8006300560 Transcript of 770321 briefing in Washington,DC re Edlow Intl Co application to export SNM to India Pp i-42 * Commission 77/03/21. 42pp

- ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- 8002150066 Discusses review of draft NUREG-0660 during 800110-12 meeting Comprehensiveness dilutes items important to safety & subsequent termination of licensing moratorium Safety improvements should be developed PLESBET.H S ACRS Advisory Committee on Reactor Safeguards 80/01/15 25p
- 8005230071 Forwards notice of ACRS Ad Hoc Subcommitte on Class 9 Accidents 800509 meeting Requests 800424 FR publication CHILK.S J. Office of the Secretary of the Commission 80/04/21
- --8005230082 Notice of ACRS Ad Hoc Subcommittee on Class 9 Accidents 800509 meeting in Chicago, IL Meeting originally scheduled to be held 800506 in Washington D C HOYLE, J C ACRS - Advisory Committee on Reactor Safeguards 80/04/21 3pp
- B005230107 Forwards change notice for ACRS Subcommittee on Reactor Fuel S00427 meeting Requests 800425 FR publication CHILK.S J Office of the Becretary of the Commission B0/04/22 is
- --8005230116 Notice of ACRB Subcommittee on Reactor Fuel 800427 meeting change Portions of meeting may be closed MOVLE. J C ACRB Advisory Committee on Reactor Safeguards 80/04/22 ip
- 8005230247 Forwards notice of ACRS 800519-20 & 28-29 meetings w/German Reactor Safety Committee & French Groupe Permanent-Reactor, respectively Requests 800501 FR publication CHILK-B U Office of the Secretary of the Commission 80/04/25
- --8005230253 Notice of ACRB 800519-20 & 28-27 meetings w/German Reactor Safety Committee & French Groupe Permanent-Reactor, respectively HOVES OF ACRB - Advisory Committee on Reactor Bafeguards
- B005230274 Forwards notice of ACRS Subcommittee on Regulatory Activities 800430 meeting Requests 800418 FR publication CHILK.8 U Office of the Secretary of the Commission 80/04/15
- --8005230280 Notice of ACRS Subcommittee on Regulatory Activities 800430 meeting HOVLErJ C ACRS Advisory Committee on Reactor Safeguards 80/04/14 2pp
- B0052303B3 Forwards notice of ACRS Subcommittee on Metal Components 800424 meeting schedule & location change Requests 800421 FR publication CHILK-S J Office of the Secretary of the Commission. B0/04/16.
- --8003230387 Natice of change of location & date of ACRS Subcommittee on Metal Components 800424 meeting Meeting will run only 1 day, rather than 2 & will be held at Museum of Science & Energy, rather than ORNL.

 HOYLE, 0 ACRS Advisory Committee on Reactor Safeguards 30/04/16 1p.
- B005230394 Forwards change notice of ACRB Bubcommittee on Reliability Probabilistic Assessment B00430 meeting Requests B00425 FR publication CHILK-B J Office of the Secretary of the Commission 80/04/22
- ---8005230398 Notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 800430 meeting change, Portions of meeting may be closed HOYCE, J C ACRS - Advisory Committee on Reactor Safeguards 80/04/22 1p
- 8005230560 Forwards notice of AGRB Subcommittees on Site Evaluation & Reactor Radiological Effects joint 800521 & 22 meeting. Requests 800506 FR publication CHILK.S J Office of the Secretary of the Commission 80/04/29 is
- --80052305&& Notice of ACRB Subcommittees on Site Evaluation & Reactor Radiological Effects joint 800521 & 22 meeting. HOYLE, J C. ACRS Advisory Committee on Reactor Safeguards. 80/04/29 2pp.

- 8005270043 Forwards notice of ACRB Subcommittee on Reactor Radiological Effects 800423 meeting to be published on 800408 CHRLK-S J Diffice of the Secretary of the Commission 80/04/03 to
- --8003270080 Notice of ACRS Subcommittee on Reactor Radiological Effect 800423 meeting in Hashington DC to review nuclear power plant radiological protection programs HDYLE J C ACRS - Advisory Committee on Reactor Safeguards 80/04/02 2pp
- 8005270053 Forwards notice of ACRS Subcommittee on Reliability & Probabilistic Assessment 800430 meeting, to be published on 800415 CHILK, S. J. Office of the Secretary of the Commission 80/04/10
- --8005270659 Notice of ACRE Subcommittee on Reliability & Probabilistic
 Assessment 800430 meeting re need to develop quantitative
 safety goals for nuclear power plants
 HGYLEJ C ACRE Advisory Committee on Reactor Safeguarde
 80/04/09 2pp
- B005270230 Forwards notice of ACRS 800501-03 meeting Requests 800429 FR publication CHILK, B J Office of the Secretary of the Commission B0/04/24 in
- --8005270236 Notice of ACRS 800501-03 meeting re-miscellaneous matters of ACRS activities HOVLE, J C ACRS Advisory Committee on Reactor Bafeguards 80704723 App
- 8005280084 Forwards notice of ACR8 Subcommittee on Concrete & Concrete Structures 800422-23 meeting to be published on 800407 CHILK, 8 J Office of the Secretary of the Commission. 80/04/02 in
- --8005280090 Notice of ACRS Subcommittee on Concrete & Concrete Structures 800422-23 meeting re review of user needs in structural engineering HOYLE,J C ACRS - Advisory Committee on Reactor Bafeguards 80/04/01 2pp
- 8005050495 Discusses ACR8 800501-03 meeting ACR8 strongly recommends assignment of specific identification numbers to proposed reg guides prior to submittal for ACR8 review Concurrence reached on Revision 1. Reg Quide 1.144
 PLESSETIM 9 ACR8 Advisory Committee on Reactor Safeguards 80/05/06 2pp
- 8006090064 Transcript of ACRS Joint Subcommittees on Site Evaluation & Reactor Radiological Effects 800522 meeting Listing of visugraphs & description of atmospheric dispersion research program and ACRS Advisory Committee on Reactor Safaguards. 80/05/22.
- 8006070127 Transcript of ACRB Subcommittee on Regulatory Activities 800604 meeting in Hashington DC Pp 1—128 # ACRS — Advisory Committee on Reactor Sefequerds 80/06/04. 1880b.
- 8006090130 Transcript of ACRS Subcommittee on Reactor Safety Research 800603 meeting in Washington, DC Pp 1-24, # ACRS - Advisory Committee on Reactor Bafeguards. 80/06/03 25pp
- 8006090132 Transcript of ACRB Bubcommittee on Extreme External Phenomena 800604 meeting in Washington, DC, Pp. 1-298 # ACRS - Advisory Committee on Reactor Safeguards 80/06/04
- 8006090139 Transcript of ACRS Subcommittee on Extreme External Phenomena 800604 meeting in Washington, DC Pp 299-414.

 * ACRS ~ Advisory Committee on Reactor Safeguards 80/06/04
- 8006120293 Discusses comparative suitability of LWRs for electric paus generation. Next generation of nuclear plants will need to load-follow. EPLER.E.P. Epier, E.P. 80/04/01, 9pp
- 8006120295 Discusses feasibility of designing containment that can withstand core melt Bldg could be designed based on present info. Design should be inexpensive CATTON. I ACRS Advisory Committee on Reactor Bafeguards 80/04/25. Rpp

- 8005120296 Summarizes ACRS Subcommittee on Concrete Structures meeting ZUDANS, Z Franklin Institute/Franklin Research Center 80/04/25
- 8006120298 Comments on ACR8 Bubcommittee on Natural Circulation 800424 meeting Overconservation prevents developing new technology LIENHARD, J H Kentucky, Univ of 80/04/29 4pp
- BOOGS120299 Comments on NUREQ-0467 NUREQ should be issued as guide only & industry invited to originate own implementation details In alternative, NUREQ should be made part of action plan ZUDANS: Z Franklin Institute/Franklin Research Center 80/04/30
- 9006130029 Bummary of ACRS Site Evaluation Subcommittee 800422 meeting in Mashington: DC re proposed emergency planning rule ACRS Advisory Committee on Reactor Safeguards 80/05/16 13pp
- 8006130046 Summary of AGRS Subcommittee on Reactor Safety Research 800409 meeting in Washington.DC re FYS1 & FYS2 research
- BOUNDY MEETING MEETING
- BOO6:30052 Summary of ACRS Reactor Radiological Effects Subcommittee BOO423 specting in Washington.DC re radiological safety evaluation program for operating plants a ACRS Advisory Committee on Reactor Safeguards BO/05/16 9pp
- 8006130055 Summary of ACRS B&W Mater Reactor, Subcommittee 800408 maeting in Washington, DC re B&W reactor sensitivity to feedwater transients ACRS Advisory Committee on Reactor Safeguards 80/04/17 15pp
- 8005130058 Summary of ACRS Subcommittee on Regulatory Activities 800409 meeting in Washington DC re regulatory guides & stds a ACRS Advisory Committee on Reactor Safeguards 80/05/01 15pp
- 8006160059 Discusses draft final rules 10CFR50 & 70 on emergency planning. NRC-FEMA approach should be developed & implemented to secourage state & local agencies to incorporate federal afforts into their emergency planning PLESSET.M B. ACRS Advisory Committee on Reactor Safeguards 80/06/11 200
- 800.616.0046 Discusses proposed position on seismic scram NRC does not have position for or against seismic scram Recommends that NRC initiate modest study of effects of seismic scram on various accident or transient scenarios PLEBSETIM S ACRS Advisory Committee on Reactor Safeguards. 80/06/11 ip.
- 8006160072 Discusses seismic qualification of PHR auxiliary feedwater sys. Recommends that NRC apply add1 manpower to complete review of affected plants. Utils should perform independent reviews on same time scale.

 PLESBET.M.8 AGRS Advisory Committee on Reactor Safeguards 80/06/10. ip.
- BOO5160075 Responds to BOO401 request for add1 info re ACRS comments in BOO311 ltr concerning near-term OL items from Draft 3 of NRC Action Plan Appraisal of merit of referenced proposals will be possible only after deliberate study. PLESEET, M. S. ACRS Advisory Committee on Reactor Bafeguards BO/02/10 2pp
- B006160101 Comments on NUREO-0667, "Transient Response of B&H-Designed Reactors," Expresses concern that recommendations in rept show continuation of NRC trend toward less flexibility in resolution of safety issues.

 PLESBET, M S ACRS Advisory Committee on Reactor Bafeguards
 80/06/10 20-20-2pp
- BOO6160111 Discusses factoring of quantitative estimates into seismic safety evaluation. AGRS wishes to develop rationale for including estimates in decision-making process Requests update re NRC efforts to develop rationale PLESETTH 8. ACRS Advisory Committee on Reactor Safeguards 80/06/10.
- 8006160182 Comments on 800424 ad hoc Shete meeting on natural controlled comments on bounds as not onest meeting on natural circulation, Bemiscale should be encouraged to solve heat loss problem on friority 1 basis LOFT instrumentation group seems to be isolated & tends to be unimaginative CATTON.1 ACRS - Advisory Committee on Reactor Safeguards 80/05/03 Ip

- 8006160189 Comments on ECCS & Natural Circulation Subcommittee B00325-26 meetings Semiscale should be used soon for series of scaping experiments to determine amount of noncondensible gas nacessary to degrade reflux boiling mode CATTON. I. ACRS - Advisory Committee on Reactor Safeguards B0/05/08. 2pp
- 8006160195 Discusses 800411-12 UBA/Hest Germany melt research progrem review & info exchange meeting R Denning conclusions in support of Regovin rept include uncertainties in excess of boundary conditions

 GATION: I ACRS Advisory Committee on Reactor Safeguards CATTON, I ACRS - Advisory Committee on Reactor Safeguards 80/06/10 4pp
- 8006160203 Discusses ACRS Subcommittee on Concrete & Concrete Structures 800422-23 meeting Adequate provisions for integrating results of related research efforts by industry sponsored groups & govt organizations not apparent PICKEL,T W Union Carbide Corp 80/05/16 2pp
- 8006160204 Transcript of 242nd ACRS meeting on 800605 in Washington, BC Pp 1-254 * ACRS - Advisory Committee on Reactor Bafeguards 80/06/05
- 8006160209 Transcript of 242nd ACRS open session on 800606 in Washington. DC Pp 255-269

 * ACRS Advisory Committee on Reactor Safeguards 80/06/06
- 8006170287 Requests brief. written status rept re overall effort by Ofc of Nuclear Reactor Regulation in area of peliet-clad interaction Should include discussion of whether fuel failures would be increased by extending fuel burnup limits LIBARKIN.N W ACRS Advisory Committee on Reactor Bafeguards 79/07/27 ip.
- 800&170338 Summary of combined ACRS ECCS/Reactor Fuel Subcommittee 800214 meeting in Mashington.DC re effects of externally mounted thermocouples on LOFT fuel rods ACRS Advisory Committee on Reactor Safeguards 80/04/30
- 6006170343 Bummary of ACRS Subcommittee on ATMS 800125 meeting in Washington,DC re-proposed resolution of ATMS * ACRS ~ Advisory Committee on Reactor Safeguards 80/04/12 23pp
- 8006170346 Summary of ACRS Subcommittee on Metal Components 800123-24 meeting in Washington DC re status of steam generator oblems
 ACRS - Advisory Committee on Reactor Bafaguards 80/03/21. 21pp
- 8006180629 Comments on 800424 natural circulation meeting re use of LOFT/8EMISCALE facilities in future research activities More specific statements should be made on purpose of tests & of instrumentation & programs used.

 ACOSTA, A J Affiliation Unknown 80/04/29 ip
- 8006190190 Notice of change of location of ACRS Ad Hoc Subcommittee on TMI.Unit 2 Accident Action Plan 800401-02 meetings Meetings will be held in Room P-i18.Phillips Bldg.Bethesde.HD HOYLE,J C ACRS Advisory Committee on Reactor Safeguards. 80/03/19. ip
- 8006190195 Notice of rescheduling of ACRS Subcommittee on Metal Components meeting Meeting will be held on 800424 at American Museum of Science & Technology. Oak Ridge. TN HOYLE, J. C. ACRS Advisory Committee on Reactor Safeguards. 80/04/16 1p
- 8006170200 Notice of ACRS Procedures & Administration 800430 meeting in Hashington.DC.
 HDYLE, J C. ACRS Advisory Committee on Reactor Safeguards.
 80/04/14 1p.
- 800A190209 Notice of ACRS Subcommittee on Metal Components 800424-25 meetings in Washington, DC to review heavy section steel technology HOYLE, J C ACRS Advisory Committee on Reactor Safeguards. 80/04/02 3pp
- 8006190215 Notice of ACRS Ad Hoc Subcommittee on Natural Circulation of Feed & Bleed Heat Removal 800424 meeting in Washington, DC HOYLE, U.C. ACRS Advisory Committee on Reactor Safeguards. 80/04/02 3pp
- 8006190221 Notice of ACRS Subcommittee on ECCS 800326 in Weshington DC HOYLE, J C. ACRS Advisory Committee on Reactor Safeguards. 80/03/05 2pp

- 8006190667 Summary of ACRS Waste Mgt Bubcommittee 791031 meeting in Mashington.DC re objectives.goals & priorities of NRC waste mgt & fuel cycle research programs # ACRS - Advisory Committee on Reactor Safeguards 79/12/10 18pp
- --8006190668 Discusses Waste Mgt Subcommittee 791031 meeting Forwards revised key to project classification matrices encl w/791022 memo ARESENAULT.F J Division of Safeguards 79/11/04 4pp
- 8006200039 Nutice of ACRS Ad Hoc Subcommittee on TMI Unit 2 Accident Action Plan 800401-02 meeting in Washington, DC to continue consideration of Draft 3 of NURE9-0660 HDYLE, J C Office of the Becretary of the Commission
- 8006200153 Summary of ACRS TMI-2 Accident Bulletins & Orders
 Subcommittee 800304 meeting in Washington.DC
 * ACRS Advisory Committee on Reactor Safeguards 80/04/22 13pp
- 8006200619 Notice of ACRS Subcommittee on ATWS 800326 meeting in Washington.DC
 HOYLE, J C Office of the Secretary of the Commission 80/03/05
- 8006230015 Notice of proposed meetings of ACRS subcommittees, working groups & full committees from 800325-0504
 HOYLE, J C Office of the Secretary of the Commission 80/03/14
- 8006230018 Notice of ACRS Subcommittee on Site Evaluation 800422 meeting in Washington, DC to review 10CFRS0 & NUREG-0654 HDYLE, J C Office of the Secretary of the Commission, 80/04/01 Saa
- 8006230023 Notice of ACRS Subcommittee on Reactor Safety Research B00409 meeting in Washington, DC to review Ofc of Nuclear Regulatory Research response to ACRS recommendations to Congress re NURED-0687 HDYLE, J C Office of the Secretary of the Commission B0/03/20
- 8006230027 Notice of ACRE Subcommittee on B&W Water Reactors 800408 meeting in Mashington.DC to complete review of NRC study to determine whether const should be halted on certain B&W plants.
 HDYLE.J C Office of the Secretary of the Commission 80/03/18
- 8006230053 Notice of ACRS Subcommittee on Regulatory Activities 800407 meeting in Washington.DC HOYLE, J C Office of the Secretary of the Commission 80/03/20 2pp
- 8006230058 Notice of ACRS Subcommittee on Power & Electrical Sys 800409 meeting in Washington, DC to discuss nuclear data link HDYLE, J C. Office of the Secretary of the Commission 80/03/20
- BOO6230066 Notice of ACRS Ad Hoc Bubcommittee on TMI, Unit 2 Accident Implications BO0409 meeting in Washington, DC HDYLE, J C Office of the Secretary of the Commission. B0/03/20
- BOOA230079 Notice of ACRS Subcommittee on Concrete & Concrete Structures BOO325-26 meetings in Washington, DC to review user needs in structural engineering HOYLEJJ C Office of the Becretary of the Commission BO/03/05 2no
- 8005230084 Notice of change of date of ACRB Subcommittee on ECCB meeting Meeting rescheduled to 800325 HDYLE, J C Office of the Secretary of the Commission 80/03/14 ip
- 8006230229 Notice of ACRB Subcommittee on Reactor Fuel 800429 mesting in Washington,DC to discuss NRC research program on reactor fuels for ACRB annual repts to NRC & Congress.
 HQYLE,J C Office of the Secretary of the Commission 80/94/09 Gpp
- 8006230234 Natice of rescheduling of date of ACRS Ad Hoc Subcommittee on Naturel Circulation Heat Removal meeting to 800316 Title of subcommittee changed to ACRS Ad Hoc Subcommittee on Naturel Circulation & Feed & Bleed Heat Removal HDYLE, J C. Office of the Secretary of the Commission 80/03/14

- 8006240327 Notice of ACRS Subcommittee on Safeguards & Security 800626 meeting in Washington DC to review pertinent portions of NRC research program re spent fuel storage pobl consequence estimates from sabotage & plant security HOYLE J C Office of the Secretary of the Commission 80/06/05
- BOOA240520 Notice of ACRS Subcommittee on ECCS BOO624-25 meeting in Mashington. DC to review research programs to LOCAs & transients & LOFT HOYLE, J C Office of the Secretary of the Commission 80/06/04
- BOOA240588 Notice of ACRS Subcommittee on Metal Components 800617-18 maeting in Washington DC to review pertinent portions of NRC research program HOYLE, J C Office of the Secretary of the Commission 80/05/23
- BOO6240599 Notice of ACRS Subcommittee on Regulatory Activities 800604 open meeting in Hashington, DC to discuss proposed Reg Quide 1 23. Revision 1 & revisions to 10CFR00 & 55 HOVLE, J C Office of the Secretary of the Commission BO/05/16
- 800.6240.603 Notice of ACRS Subcommittee on Extreme External Phenomena B00.604 meeting in Washington.DC to discuss criteria for saismic design of safe shutdown & heat removal synseismic scram & research budget 30me closed sessions may be needed HOYLE.J C Office of the Secretary of the Commission 80/05/16.
- 8004240408 Notice of ACRB Subcommittee on Reactor Bafety Research 800603 meeting in Mashington, DC to review pertinent portions of FY82 research budget, Some sessions may be closed to explore matters involving proprietary info.

 MOYLE, J C Office of the Secretary of the Commission 80/05/14.
- 8006250087 Notice of ACRS Subcommittees on Waste Mgt & Fuel Cycle 800626-27 meeting in Washington, DC to discuss pertinent portions of NRC research program HOYLE, J C Office of the Secretary of the Commission 80/04/05 3pp.
- 8006250091 Notice of preliminary schedule of proposed meetings of ACR9 subcommittees & working groups, taking into account addl & postponed/camcelled meetings since 800425 publication. HQYLE, J C Office of the Secretary of the Commission 80/05/12, opp.
- 8006250147 Notice of ACRS Subcommittee on LERs 800422 meeting in Washington.DC HDYLE, J C. Office of the Secretary of the Commission 80/04/01. 3pp
- 8006250351 Summary of ACRS Ad Hoc TMI-2 Accident Implications Subcommittee 800305 meeting in Washington, DC * ACRS - Advisory Committee on Reactor Bafeguards 80/04/22 28pp
- 8004250371 Summary of 239th AGRS meeting on 800304-08 in Hashington, DC Items considered include NUREO-0460, proposed plans for implementation of NRC bulletins & orders resulting from YMI-2 accident & floating nuclear plant core ladle design PLESSET. N AGRS Advisory Committee on Reactor Safeguards, 80/03/24. 2pp.
- 8006250374 Discusses glan for extended operation of light water breader reactor Based on 241st meeting on 800501-03 w/Westinghouse, util DDE & NRC, ACRB believes operation of reactor core to 24,000 EFPH is acceptable.
 PLEBERT.M.S. ACRB Advisory Committee on Reactor Safeguards.
 80/05/06. ip
- 8006260082 Notification of ACRS Subcommittee on B&W Water Reactors 800429 meeting in Washington, DC to review NUMEG-0667 HOYLE, J C. Office of the Secretary of the Commission. SHIELDS, W C Office of the General Counsel. 80/04/09. 3pg.
- 8006260327 Forwards FR notice ACRS Subcommittee on Advanced Reactors 800615 meeting for publication on 800327 CHILK, B. J. Office of the Secretary of the Commission, 80/05/23, ip.

- --8008260364 FR notice of ACRS Subcommittee on Advanced Reactors 800815 meeting in Heshington. DC HOYLE, J C Office of the Secretary of the Commission 80/05/23
- 8006270005 Notification of ACRS Bubcommittee on Regulatory Activities 800430 meeting in Mashington,DC to hear comments on Reg Ouides 1.144 & 1 XXX HOYLE,U C Office of the Secretary of the Commission 80/04/14
- 8008270355 Tentative schedule for ACRS Subcommittee on B&W Water Reacturs 800408 meeting # ACRB - Advisory Committee on Reactur Safeguards 80/04/08 1p
- 8008270338 Schedule & outline for discussion at 241st ACRS meeting on 800801-03 in Washington.DC ACRS Advisory Committee on Reactor Safeguards 80/04/23 5pp
- BO06270377 Transcript of ACRS Subcommittee on Metal Components 800418 meeting in Washington, DC, Pp 285-463. Morning session Related matl & visugraphs encl.

 __ACRS Advisory Committee on Reactor Bafeguards 80/06/18
- 80062703Bi Transcript of ACRS Subcommittee on Advanced Reactors 8006i3 meeting in Washington, BC Pp 1-205 Related matls & vieugraphs entl ACRS - Advisory Committee on Reactor Safeguards - 80/06/13
- 8006300010 Submits status of near-term CP applications discussed at 241st ACRS meeting on 800301-03 Supports recommendation by representative that interim approach to major policy issues should be developed PLESSET.M S ACRS Advisory Committee on Reactor Safeguards 80/05/06 2np
- 8006300116 First draft of "Physics of Reactor Meltdown Accident " COHEN.B L Pittsburgh, Univ of. 80/03/24. 29pp
- BO06300312 Notification of ACRS Subcommittee on Reliability & Probabilistic Assessment 800430 meeting in Washington.DC to continue evaluation of need to develop quantitative safety goals for plants Segregation determination encl. 80/04/09.
- 8006300318 Notification of ACRS Ad Hoc Subcommittee on Class 9
 Accidents 800509 meeting in Chicago, IL Segregation
 determination encl
 HOYLE, J C Office of the Secretary of the Commission. SHILEDS, W C
 Office of the Owner
- 8006300324 Notification of ACRS 800519-20 & 28-29 meetings w/German Reactor Safety Committee & French Oroupe Permanent-Reactor in Obrigheim, Germany & Fontenay-Aux-Roses, France to discuss reactor safety & practice. W/segregation determination HOYLE, J C Office of the Secretary of the Commission. SHIELD, W C Office of the General Counsel 80/04/25. 3pp
- 8006300327 Notification of ACRE Subcommittee on Reactor Operations 800520 meeting in Washington,DC to review NRC research grograms Eggregation determination enci. HOYLE,J G Office of the Secretary of the Commission SHIELDS,W C Office of the General Counsel 80/04/29 3pp
- 8006300548 Notification of change of ACRS Subcommittee on Reliability & Probability Assessment 800430 meeting. Portions of meeting re NRC budget may be closed to public W/ determination made per Federal Advisory Gommittee Act HOYLE.J C Office of the Secretary of the Commission. SHIELDS.W M Office of the Censral Counsel 80/04/22. 2pp

- BOO6300661 Bummary of 241st ACRB meeting on 800410-12 in Hashington, DC Items considered include review of NUREQ-0660, discussion of ATMS w/representatives of nuclear power industry & discussion of effect on ACRS of 1980 Reorganization Plan 1 PLESSET, M S ACRB Advisory Committee on Reactor Bafeguards. 80/04/22 Зер
- COMMISSION NRC COMMISSIONERS
- 8001040696 Commissioner Kennedy's correspondence for May-Dec 1979 KENNEDY, R T Commission 79/12/18 110pp
- B004160186 Requests comments on proposed rulemaking concerning disposal of raduastes produced by nuclear facilities Comments due by B00418 FR notice encl AHEARNE, J.F. Commission 80/03/12 lp
- --8004160190 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by BOO415 FR notice encl AHEARNE, J F Commission 80/03/12 2pp
- --9004160193 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AMEARNE, J F Commission 80/03/12 2pp
- --8004160196 Requests comments on proposed rulemaking concerning disposed of raduastes produced by nuclear facilities Comments due by B00415 FR notice enci AMEARNE.J F Commission 80/03/12 2pp
- --8004160200 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415.FR notice ancl.
 AMEARNE, J.F. Commission. 80/03/12 2pp
- ---8004160202 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl
 AHEARNE, J F Commission 80/03/12 2pp
- --8004i60203 Requests comments on proposed rulemaking concerning disposal of radwastes produced by nuclear facilities Comments due by 8004i5 FR notice encl.

 AHEARNE, J F Commission 80/03/12 2pp
- -8004160206 Requests comments on proposed rulemaking concerning disposed of radwastes produced by nuclear facilities Comments due by 800415 FR notice encl AHEARNE. J F Commission 80/03/12 2pp
- --8004i6ORi2 Requests comments on proposed rulemaking concerning disposa of radwastes produced by nuclear facilities Comments due by 8004i5.FR notice encl AHEARNE.JF. Commission 80/03/12 2pp
- ---B004i602i5 Requests comments on proposed rulemaking concerning dispass of radwastes produced by nuclear facilities Comments due by B00415.FR notice enci AHEARNE, J.F. Commission 80/03/12. 2pp
- ---8004160220 Requests comments on proposed rulemaking concerning dispose of redwastes produced by nuclear facilities. Comments due by 800415 FR notice encl AHEARNE, J. F. Commission 80/03/12 5pp
- 8004180211 Responds to 800128 ltr re NRC emphasis on emergency planning for nuclear accidents NRC & FEMA cooperate in developing emergency planning rules & related state guidance, AMEARNE, J. F. Commission 80/03/18 jp.
- 8005200503 Discusses reasons why Commission does not support H R 5923 re requiring Secretary of Energy or Secretary of Defense to notify state legislature about proposed const of state radwasts storage facility.

 AHEARNE, J F Commission 80/04/28 2pp.

- --8005200512 Requests comments on encl H R 5923 re requiring Secretary of Energy or Secretary of Defense to notify State legislature about proposed const of state raduaste storage facility
 STAGGERS.H D House of Rep. Interst & Foreign Commerce 77/11/28 4pp
- 8005280455 Responds to 800207 ltr re reactor control sys failures which could result in accident sequences not previously anticipated Commission recognizes need for add1 deliberate investigation of control sys failures & consequent effects AHEARNE.JF Commission 80/05/14 2pp
- --8005280473 Discusses status of actions re high energy line break w/ consequential control sys failure Forwards interim criteria to be considered in realted followup reviews Supporting tables ehol CMECK.P S Division of Operating Reactors 79/12/19 17pp
- 8006020156 Comments on draft bill. "To Establish Nuclear Safety Oversight Committer " Recommends that accompanying ltr be sent to Congress clarifying that committee will not influence decisions or actions before Commission AHEARNE, J F Commission 80/05/01 iipp
- 800.6030586 Comments on Draft 3 of NUREQ-0660, "NRC Action Plans Developed as Result of TMI-2 Accident " Insufficient attention given to both general & special policy questions which require consideration in connection w/near-term OLs PLEBSET:M 8 ACRS Advisory Committee on Reactor Safeguards 80/04/17 5pp
- 8006090020 Responds to request for data comparing population densities near reactor sites abroad w/US figures Info is sketchy & imprecise Comparisons should serve immediate purposes Six foreign countries involved have higher densities than US, HANRAHAN,E J Office of Standards Development, Director B0/04/21
- 8004090110 Ack receipt of 800312 ltr re NRC policy on differing prof opinions Outlines characteristics of proposed NRC policy that match intent of recipient comments AHEARNE.JF Commission 80/04/27, ip
- ~~8006090113 Comments on NRC proposed policy on differing prof opinions Policy should be immediately implemented VON HIPPEL,F., RAVEN-HANSEN,P. American Association for the Advancement of Science 80/03/12 2pp.
- B006110393 Weekly info rept for wk ending B00516. REHM.T A Office of the Executive Director for Operations B0/05/21 32pp
- 8006120059 Weekly info rept for wk ending 800523 REHH.T A Office of the Executive Director for Operations 80/05/29 35pp
- 8006120065 Comments on amends to Reorganization Plan 1 of 1980 Congress should not disapprove amended plan Ultimate agency authority to interpret & apply plan resides w/Commission. Add1 clarification needed to prevent conflict for NRC AHEARNE, J F Commission 80/05/14 2pp
- ~~8006120071 Comments on amends to Reorganization Plan 1 of 1980; Congress should not disapprove amended plan Addl clarification needed to prevent conflict for NRC Separate comments by Chairman Ahearne encl
 AREARNE, J F Commission. 80/05/14 4pp.
- 8006120100 Comments on H R 4939 authorizing Ofc of Science & Technology to serve as federal focal point for encouraging technological risk comparisons Bill addresses desirable objective. Proposed approach would be useful AHEARNE, J F Commission 80/05/14, ip
- --8004120107 Requests comments on encl H R. 4939 authorizing Ofc of Science & Technology to serve as federal focal point for encouraging technological risk comparisons RITTER:D House of Rep : Science & Technology 80/03/24. 10pp.
- GOO6120201 Declines invitation to speak at Fourth ANS Topical Meeting on Technology of Controlled Nuclear Fusion on B01014 HENDRIE; J. M. Commission B0/05/02, 1p
- ~-B006120207 Extends invitation to speak at Fourth ANB Topical Meeting on Technology of Controlled Nuclear Fusion on B01014 TENNEY,F H Princeton Univ. 80/04/03 ip

- BOO6120213 Responds to BO0403 itr re project to compile fact sheets dealing w/low level waste Project is excellent & would be useful Offers NRC assistance HENDRIE.J M Commission BO/05/02 lp
- ---B006120219 Requests NRC assistance in compilation of fast-fact sheet re low level waste
 MARTY,R Ewedish Hosp Medical Center Seattle,WA 80/04/03 1p
- BOO6120260 Requests assistance in obtaining Congressional approval of FYBO supplemental budget OMB BOO407 cutting of NRC travel & transportation funds would severely limit ability of NRC to carry out required functions

 AHEARNE, J F Commission 80/05/13 1p
- 800&1202&4 Ack receipt of Oatlinburg II workshop proceedings & capies of recent speeches Discussions at Gatlinburg are step forward HENDRIE, J M Commission 80/05/02 1p
- --B006120266 Forwards Gatlinburg II workshop proceedings & recent speeches Workshop brought together approx 40 representatives of nuclear enterprise & public regulatory bodies W/o encls WEINDERGAM Dak Ridge Univs B0/04/25 Ip
- 8006130002 Declines invitation to attend 12th Annual Natl Conference on Radiation Control on 800318-22 in Louisville, KY Prior commitments preclude attendance HENDRIE, J M Commission 80/04/30 ip
- --B006i30003 Extends invitation to attend 12th Annual Natl Conference on Radiation Control on B005i8-22 in Louisville. KY LACKER, D.K. Conference of Radiation Control Program Directors, Inc. B0/04/15 ip
- 8006i30023 Responds to 800404 ltr RB Minogue, Director, Dfc of Stds Development will be NRC representative to Radiation Policy Council My Dircks, Director, Ofc of Nuclear Matl Safety & Bafeguards will be alternate AHEARNE, J F Commission 80/05/12. ip.
- --8006130027 Requests appointment of NRC representative to Radiation Policy Council Executive order establishing council encl COSTLE, D.M. President of US & Executive Offices 80/04/04 15pp
- --8006/30031 Requests appointment of NRC representative in anticipation of executive order establishing Radiation Policy Gouncil.
 COSTLE.D.M. Environmental Protection Agency 79/11/30 1p
- BOGGISO180 Comments on H.R 6570 re providing federal assistance to states for development of waste burial grounds Section 4(h) should be amended to permit use of federal facilities by states committed to establishment of disposal facility. AHEARNE, J F Commission 80/05/29 4pp
- --8006130191 Requests views on ancl H R 6570, re providing federal assistance to states for development of waste burial grounds STAGGERS.H.O House of Rep., Interst & Foreign Commerce 80/03/21, 11pp.
- 8006130197 Bubmits quarterly rept to Congress on number of full-time employees hired & promoted 791001-1231, No actions reported re promoting NRC equal employment opportunity W/o encl. AHEARNE, J F Commission. BO/03/28 ip
- ---BODAi30200 Submits quarterly rept to Congress on number of full-time employees hired & promoted 791001-1231 No actions reported re-promoting NRC equal employment opportunity W/o encl AMERANNE.J F. Commission BO/05/28. ip
- --BD06130205 Provides Subcommittee on Environ, Energy & Natural Resources \(\text{\subseteq}\) quarterly rept to Congress on number of full-time \(\text{smployees}\) hired \(\text{\text{\$p\$ romoted}}\) \(\text{\$T91001-1281}\) No actions reported \(\text{re promoting}\) NRC \(\text{square}\) amployment opportunity \(\text{\$H\$} / \text{o encl}\). \(\text{AMEARNE.} \(\text{\$J\$} \) \(\text{Commission}\) \(\text{\$900528}\) \(\text{\$1\$} \)
- --8006130207 Provides Bubcommittee on Nuclear Regulation w/quarterly rept to Congress on number of full-time amployees hired & promoted 791001-1231 No actions reported re promoting NRC equal employment opportunity W/A enci AHEARNE, J F Commission. 80/05/28 ip
- --8006130213 Provides Subcommittee on Energy & Environ w/quarterly rept to Congress on number of full-time employees hired & promoted 791001-1231. No actions reported re promoting NRC equal employment opportunity H/o entl AHEARNE, J F Commission. 80/05/28. ip

- --8006130215 Provides Subcommittee on Energy & Power w/quarterly rept to Congress on mumber of full-time employees hired & promoted 791001-1231 No actions reported re promoting NRC equal employment opportunity M/o encl A
- 8005130385 Responds to 800304 itr re proposed relocation of NRC Region 4 ofc to Fort Worth, TX 05A Regional Administrator bases relocation recommendation on Executive Order 12072 NRC unable to reverse decision AMEARNE, J. F. Commission 80/05/19 ip
- --8006i30387 Confirms 800304 beloom to relocation of NRC Region 4 ofc to Fort Worth, TX JM Hendrie 7907i1 ltr advised that Arlington, TX lease would be renegotiated QSA 800215 ltr notified that ofc would be moved Prompt examination of matter requested FROST, M House of Rep 80/03/04 2pp
- 8006180074 Weekly info rept for whending 800530 REHMIT A Office of the Executive Director for Operations 80/06/05 27pp
- 8006200574 Responds to 800522 request to clarify statements made during 800415 Commission meeting re environ qualification of safety-related electrical equipment-Forwards NRC 800523 memorandum & order.Certificate of 8vc encl DIRCKB, H J Office of the Executive Director for Operations 8070523 4pp
- 8006230112 Atk receipt of 800523 ltm & outlines for media training programs Info is being forwarded to training personnel for discussion.

 HENDRIE: J M Commission. 80/06/02. 1p.
- --8006230117 Forwards format for 1-day workshops on public speaking used in media training programs CRUTCHFIELD.C Media Communications, Inc. 80/05/23 5pp
- 8006230119 Responds to 800429 ltr & encl re thermodynamics & basis of nuclear industry NRC & predecessor have never claimed that nuclear science is perfect Refutes contention re thermodynamic theory.

 HENDRIE, J M Commission. 80/05/22 2pp.
- -8008230123 Forwards rept re thermodynamics. Nuclear industry is not based on true, precise, next-to-perfect science as was believed prior to THI W/o encl CLARK-R W Affiliation Unknown 80/04/29. 1p
- 800623012B Responds to Citizens for NRC in Silver Spring MD 800507 request for meeting w/Commission re relocation in Silver Spring Decision on where to relocate has not yet been made by Congress AMEARNE, J. F. Commission. 80/05/21 ip
- ~~8006230131 Requests on behalf of Citizens for NRC in Silver Spring MD, meeting w/NRC to facilitate NRC relocation to Silver Spring. FREEDMAN, 8 Affiliation Unknown 80/05/07 1p
- 8006230137 Advises of nomination of JB Martin to serve as alternate for future meetings of State Planning Council on Radwaste Mgt Expresses appreciation for support of NRC participation on Council as nonyoting observer.

 AMEARNE, J. F. Commission 80/05/20 ip
- 8006230206 Urges, on behalf of UCS, reconsideration of Commission new policy to permit licensees to challenge need for new TMI-related safety requirements intervenors should be given same rights per case law WEISS, E. R. Sheldon, Harmon & Weiss. 80/06/09. 3pp
- 8006240537 Urgss, on behalf of New England Coalition on Nuclear Pollution, reconsideration of Commission 800609 policy statement for CL requirements. Giving action plan force of regulations violates due process JORDAN, W.S. Sheldon, Harmon & Weiss 80/06/13 4pp
- 8006240601 Heekly info rept for wt ending 800606.
 REHHIJT A Office of the Executive Director for Operations 80/06/11. 32pp
- 8006250303 Ack receipt of 800508 ltr re dangers of nuclear power Ltr is being forwarded to headquarters in Maxhington, DC. HANCHETT.J. 9. Region 5. San Francisco. Office of the Director 80/05/27.
- --8006250305 Expresses apposition to use of nuclear power Profit is being put sheed of safety AOUIRE.A. Affiliation Unknown 80/05/08 Rpp.

- 8006260152 Responds to 800414 ltr forwarding KY 800213 House Resolution 57 requesting federal technical & financial assistance for Maxay Flats decommissioning NRC not authorized to provide funds for such purpose AHEARNE.J F Commission 80/06/09 1p
- --8006260155 Forwards 800213 House Resolution 57 requesting federal technical & financial assistance for Maxey Flats decommissioning BELL, 5 Kentucky, State of 80/04/14. Spp
- 8006300531 Forwards latest draft policy statement re licensing decisions & specific guidance for near-term OL cases Three Commissioners are in agreement w/approach Afternoon meeting will assess further comments AHEARNE.J F Commission 80/06/06 10pp
- B006300614 Responds to B00409 request for info re NRC federal woman's program Forwards plan for monitoring & evaluating progress on NRC affirmative action plan for FY80 & "Equal Employment Opportunity Plan FY80"

 AHEARNE, J F Commission 80/05/21 ip.
- ~-8006300617 "Equal Employment Opportunity Plan FYBO " Plan for monitoring & evaluating progress on NRC affirmative action plan for FYBO encl
 TUCKER,E E Office of Equal Employment Opportunity DIRCKS, H J
 Office of the Executive Director for Operations AHEARNE, J F
 Commission 80/05/02 71pp
- 8006300665 Responds to FDIA request for official communications from JM Hendrie to Congress during tenure as Chairman & Commissioner of NRC. All correspondence is available in FDR Forwards documents listed in App A FELTON. J M Division of Rules and Records 80/06/23, 2ipp

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- 8006020519 "Publication of Regulatory & Technical Documents Prepared by NRC Contractors, Including Repts Prepared Under or Per Interagency Agreements "

 Division of Technical Information & Document Control NRC-10-80-662 NRC APP 3202 78/01/25 35pp.
- --8006020526 "Contactor Organizational Conflicts of Interest," IOCFR20-1 54 effective rule Rule avoids, eliminates or neutralities contractor organizational conflicts of interests CHILK B J Office of the Secretary of the Commission. NRC-10-80-662 79/03/27 12pp
- 800&030039 Notification of contract execution, Mod 12 to "Evaluation of Soil Behavior Under Earthquake Loading Conditions" Contractor: Shannon & Wilson, Inc & Agbabian Associates WOLLETT, S A Research Contracts Branch, FIN 8-3015 NRC-04-76-200 79/11/01 is
- --8006030042 Mod 12.changing completion date from 791031 to 800531.te
 "Evaluation of Soil Behavior Under Earthquake Loading
 Conditions "
 MORTON K V Research Contracts Branch MILLER, R P Shannon &
 Wilson, Inc FIN B-3015 NRC-04-74-200 79/11/01 ip
- 8006030046 Notification of contract execution:Mod 4 to "Licensee Performance Evaluation " Contractor Teknekron Inc BAISDEN.L. Research Contracts Branch FIN B-122B NRG-05-78-302 80/05/12 ip
- --8006030049 Mod 4,modifying statement of work & extending period of performance w/add1 funding to "Licensee Performance Evaluation "
 MORTON, K V Research Contracts Branch COHEN, S Teknekron, Inc. FIN B-1228 NRC-05-78-302 80/05/12 3pp
- B006030052 Notification of contract execution, Mod 3 to "Radioactive Matl Transportation." Contractor Univ of Denver FLYNN, M Administrative Contracts Branch. NRC-04-78-361. B0/05/16
- --8006030055 Mod 3. extending period of performance for seven add1 month to "Radioective Mati Transportation."

 HATTIA, M J. Administrative Contracts Branch DAVIG, P L. Denver, Univ of, NRC-06-78-361 80/05/16 ip
- 8004030526 Notification of contract execution, Mod 9 to "Document Control Bys." Contractor TERA Advanced Bycs Corp.
 LEBD.C.D Administrative Centracts Branch NRC-10-78-580 80/05/22. 1p

- --8006050529 Mod 9.extending period of performance.to "Document Control Bys" HATTIA.M J Administrative Contracts Branch FELTON.R W TERA Corp NRC-10-78-580 80/05/22 1p
- BOO606060 Notification of contract execution. Mod 5 to "Electrostatic Copying Svcs " Contractor Literature Research Co CELEMAN. R Administrative Contracts Branch NRC-10-79-361 BO/09/20 19
- --8004060077 Med 5, obligating add1 funds, to "Electrostatic Copying Svcs " MATTIA, M J Administrative Contracts Branch NRC-10-79-361
- 8006060491 Notification of contract execution Mod 4 to "Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US " Contractor Roundout Associates. Inc SMITH, P A Technical Assistance Contracts Branch NRC-03-78-154 80/05/21 ip
- --8004040495 Mod 4,modifying Article 1 re description of work,to "Seismic Zoning Map for Siting Nuclear Electric Power Generating Facilities in Eastern US" * Rondout Associates DOUGHERTY,D.J Technical Assistance Contracts Branch NRC-03-78-154 80/05/21 ip
- 8006060594 Notification of contract execution Mod 2 to "Keypunching & Verifying Svcs " Contractor Small Business Administration Subcontractor Intl Business Bvcs. Inc HIGOTNS.E. Administrative Contracts Branch NRC-10-79-393
- --8006060601 Mod 2, increasing total amount obigated under contract, to "Keypunching & Verifying Sycs "
 MATTIA.M J Administrative Contracts Branch NRC-10-79-393
 79/11/20 1p
- 8006070429 Notification of contract execution, "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries," awarded to Franklin Inst MEDROM, L. A. K. Administrative Contracts Branch FIN 8-1648 NRC-08-80-338 60/05/28 1p
- --8006090432 Contract "Study of US Nuclear Health & Bafety Info Dissemination to Foreign Countries," awarded to Franklin Inst RFF RB-01P-80-338 encl MATTIA,M J Administrative Contracts Branch FIN B-1648, NRC-08-80-338 80/05/28 35pp
- --BOO4090436 SECY-78-365
 Requests Commission views on results of studies & recommendations re health & safety considerations in NRC reactor licensing & nuclear assistance programs Recommends Commission approve encl analysis
 SHEA.J.R. Office of International Programs. Director 78/07/03
- ---8006090437 "NRC Staff Analysis of Health & Bafety Considerations in Reactor Exports & Assistance Programs " * Commission 78/06/28 35pp.
- 8006090452 Notification of contract execution, Mod 5 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located Within SC " Contractor State of SC BAISDEN, L Research Contracts Branch FIN B-5112 NRC-05-77-106 77/05/01 ip
- --8006090459 Mod 5, deabligating funds at contract classout to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commmission Licensed Activities Within BC & Belected by Commission "MORTON.K V. Research Contracts Branch FIN B-5112 NRC-07-77-106 77/05/01 1p.
- 8006120409 Responds to FOIA request for NRC-03-80-137 between NRC & Ruman Design Group, underlying request for proposal & related correspondence Forwards documents listed in app. W/o encis FEL-TON, J K Division of Rules and Records. NRC-03-80-137 80/06/10 2pp
- 8006120413 Notification of contract execution, Mod 6 to "Modeling Tornado Dynamics " Contractor Aeronautical Research Associates of Princeton WGLLETT, 8 A Research Contracts Branch FIN 8-5795, NRC-04-76-218 80/03/31 ip

- ---B006120415 Mod 6.adding cost averrun.to "Modeling Tornado Dynamics"
 MORTON.K V Research Contracts Branch KRATZ, L A Aeronautical
 Research Associates of Princeton FUB B-5795 NRC-04-76-218
 B0/03/31 10
- 8006130005 Notification of contract execution "Site Characterization Test Programs," awarded to Golder Associates CULEMAN,R H Administrative Contracts Branch FIN B-6950-0 NRC-02-80-056 80/06/09 ip.
- --B006130007 Contract "Site Characterization Test Program," awarded to Golder Associates * Golder Associates MATTIA, N J Administrative Contracts Branch FIN-6950-0 NRC-02-B0-056 B0/06/07 54pp.
- 800&130234 Notification of contract execution.Mod 1 to "Vol Reduction Techniques in Low Level Radwaste Mgt " Contractor Teknekron. Inc SMITH, P A Administrative Contracts Branch. FIN B-6413-9 NRC-02-79-024 80/05/20 1p
- 8006130241 Notification of contract execution. Hod 1 to "Bys Analysis of Bhallow Land Burial " Contractor Science Applications. Inc BHITH.P A Administrative Contracts Branch FIN 8-6428-9 NRC-02-79-032 80/03/08 1p
- 8006130244 Natification of contract execution, Mod 3 to "EIB for Low Level Waste Regulation " Contractor Dames & Moore SMITH,P A Administrative Contracts Branch, NRC-02-79-025 80/09/23 ip
- --B006130280 Mod 3,deleting P Lohaus & substituting G Roles,to "EIS for Low Level Waste Regulation " * Dames & Moore DDUGHERTY, D J Branch NRC-02-79-025 80/03/23 ip
- 8006160224 Notification of contract execution. Mod 5 to "Keypunching & Verification " Contractor: Small Business Administration Subcontractor Intl Business Svcs. Inc HIGGINS.E J. Administrative Contracts Branch NRC-10-77-071 883-4-0-8-C-655 80/08/31, ip.
- ---BOD6160227 Mod 5.increasing funds.to "Keypunching & Verification."

 * Small Business Administration. MATTIA.K J. Technical
 Assistance Contracts Branch NRC-10-77-071 BB3-4-0-8-C-655.
 B0/08/31 1p
- 8006170732 RFP RB-0IP-80-338, "Study of US Nuclear Health & Bafety Info Dissemination to Foreign Countries." NRC manual (Form NRC-489) re publication of technical documents by NRC contractors & App A.contract provisions.encl STOVER.J R. Franklin Institute/Franklin Research Center NRC-08-80-338 79/11/14. 152pp.
- 8006180081 Notification of contract execution, Mod 1 to "Subscription to Energy Daily." Contractor: Energy Daily. Inc. FLYNN, M.J. Administrative Contracts Branch NRC-10-80-666. BO/00/30 ip
- --8006180087 Mad i,adding four subscriptions to "Subscription to Energy Deily." TERRELL, J. E., Energy Deily, Inc. MATTIA, M. J. Administrative Contracts Branch NRC-10-80-666 80/05/30 2pp
- BOOGIBO343 Natification of contract execution "Cost of Underground Tests: " awarded to American Mine Bycs: Inc. COLEMAN.R. Administrative Contracts Branch FIN 8-6949-0 NRC-02-80-055 BO/06/09. ip
- ---B006iB0349 Contract: "Cost of Underground Tests," awarded to American Mine Bycs, Inc. MCDUOALL, A. J. American Mine Bervices, Inc. MATTIA, N. J. Administrative Contracts Branch. FIN B-6949-0 NRC-02-80-055. B0/06/09. 40cs
- 8006180582 Notification of contract execution Mod 2 to "Extension of Skyshine II" Contractor Radiation Research Associates PEARLMAN, J. Purchasing Baction. NRC-03-79-159. 80/06/04 lp.
- --BOO6180587 Mod 2.extending period of performance, to "Extension of Bkyshine II." BCHAEFFER.N M Radiation Research Associates. MATTIA.M J Administrative Contracts Branch. NRC-03-79-159. 80/06/04. 1p
- BOO6190100 Natification of contract execution. "Licensing Technical Assistance," awarded to Science Applications. Inc EDGEWORTH,P J Technical Assistance Contracts Branch NRC-02-80-035 BO/05/23 ip

- --8006190104 Contract "Licensing Technical Assistance," awarded to Beience Applications Inc FINDLEY, D E Science Applications, Inc DDUGHERTY, D J Techni Assistance Contracts Branch NRC-02-80-035 80/05/23 24pp
- 8004190109 Authorizes expenditure of funds obligated under contract & directs performance of encl Task Order 1 Science Applications Inc countersigned on 800428 MRC-04-80-178 80/04/11

- BOO6190244 Notification of contract execution.Mod 3 to "Study of Broplet Hydrodynamics Important in LOCA Reflood "Contractor State Univ of NY HAGEY, H Research Contracts Branch FIN 8-6211, NRC-04-78-194 BO/05/29 ip
- -8006170252 Mod 3.adding funds.to "Study of Droplet Hydrodynamics Important in LGCA Reflood " PARR:R & New York-State Univ of, (Albany) MORTON.K V, Research Contracts Branch FIN B-6211 NRC-04-78-194 80/05, 4PP B0/05/29
- BOOA190261 Notification of contract execution, Mod 3 to "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors & Impact on Rates " Contractor New England Conference of Public Util Commissioners GUSTAVE, P Research Contracts Branch FIN 8-10180 NRC-01-79-008 80/04/20 ip
- ----8006190267 Mod 3.adding no cost extension to "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors Honoract on Rates "
 POTE, D R. New England Conference of Public Utility Commissioners
 HORTON, K V Research Contracts Branch. FIN B-10180 80/04/30.
- 8006190272 Notification of contract execution, Mod 4 to "Btudy of Ragional Tectonics & Seismicity for NE " Contractor: Univ of NE.

JACDBB: A Research Contracts Branch. FIN 8-5774 NRC-04-76-315 80/05/28. ip

- --8006190274 Mod 4,adding funds & scope for 5th yr of 3-yr contract to "8tudy of Regional Tectonics & Beismicity for NE" | WRIGHTR.H Nebrasks: Univ of, MORTON.K Y Research Contracts Branch FIN 8-5774 NRC-04-76-315 80/05/28. 4PP
- 8006190862 Kod 1, adding addresses to distribution list for monthly repts to "Vol Reduction Techniques in Low Level Radwaste Mgt."

 * Teanetron: Inc. DQUGHERTY, D. J. Division of Contracts
 NRG-02-79-024. 80/05/20 299
- 8006200002 Notification of contract execution "Conversion Programming, Implementation & Documentation of NRC Automated Personnel Sys," awarded to Rehab Group. Inc \$1902186; Administrative Contracts Branch, NRC-10-80-390, 80/05/20 ig
- ---8006200003 Contract "Conversion, Programming, Implementation & Documentation of NRC Automated Personnel Bys." awarded to Rehat Group, Inc. 4 Rehat Group, Inc. COLLINS.F.H Administrative Contracts Brench NRC-10-80-390.
- --8006200005 "Automatic Data Processing Btds Automated Bys Documentation Handbook," App 0903 # Office of Administration. 79/10/24 91pp.
- BOO6200073 Notification of contract execution.Mod 1 to "Determination of Tornado Wind Speed From Tornadic Bounds " Contractor, Univ of MB HAGEY, H. Research Contracts Branch FIN B-6278. NRC-04-78-241. BO/04/02 ip.
- -8006200078 Mod 1,adding 1-yr no-cost extension,to "Determination of Tornado Wind Speed From Tornadic Sounds." BANAGE.J H., MORTON.K V. Mississippi. Univ of, SAM.J Researc Contracts Branch. FIN B-6278 NRC-04-78-241. 80/06/02 2pp.
- 8006200086 Notification of contract execution "Purchase & Installation of Six Teleprinters," awarded to Extel Corp/Warner Associates, Inc. COLEMAN, R W Administrative Contracts Branch, NRC-10-80-492 80/06/04, 1p
- --8006200093 Contract, "Purchase & Installation of Six Teleprinters," awarded to Extel Gorp/Manner Associates, Inc COPFEV.E.C. Extel Corp. /Harner Associates, Inc Adainistrative Contracts Branch NRC-10-80-692 80/06/04, 48pp

- 8006200134 Notification of contract execution Mod 1 to "GETR ACRS & Hearing Appearance" Contractor DB Slemmons PERLMAN, J Purchasing Section NRC-03-79-170 80/06/04 ip
- --8005200137 Mod 1, extending pariod of performance, to "GETR ACRS & Hearing Appearance "
 SLEMMONS D B Simmons, D B MATTIA, M J Administrative
 Contracts Branch NRC-03-79-170 80/06/04 ip
- 8005230004 Notification of contract execution Mod 4 to "Economic Consulting Svcs in Connection W/Stanislaus Nuclear Unit," Contractor P Outmann GLAGOLA, A F Technical Assistance Contracts Branch FIN 8-6521 NRC-03-79-113 80/03/30 ip
- --B0062300B3 Mad 4.madifying period of performance & increasing cailing amount, to "Economic Consulting Svcs in Connection W/Btanislaus Nuclear Unit" GUTMANN.P M. Gutman, Peter DOUGHERTY, D. J. Technical Assistance Contracts Branch FIN 8-6521 NRC-03-79-113 80/03/30 1p
- 8006230034 Notification of contract execution. Mod 5 to "Gonduct Special Inquiry Into Incident at TMI-2" Contractor Regovin. Stern & Huge MORTON: K V Research Contracts Branch NRC-10-79-659 B0/06/04
- --8006230036 Mod 5, adding funds & extending period of performance, to "Conduct 8pecial Inquiry Into Incident at TMI-2" ROBOVIN,M Rogovin, Stern & Huge BICKWIT,L. Research Contract Branch. NRC-02-79-657 80/06/04 ip Research Contracts
- 8006230035 Notification of contract execution "Licensing Assistance/ Bocioeconomic Impacts Evaluation," awarded to Denver Research Inst EDGEWORTH.P.J Technical Assistance Contracts Branch NRC-02-80-032-03 80/05/29. 1p
- --8006230040 Contract "Licensing Assistance/Socioenconomic Impacts Evaluation," awarded to Denver Research Inst DAVIS, P. L. Denver: Univ. of.
 DDUGHERTY, D. J. Technical Assistance Contracts Branch 80/05/29 12pp

- 8006230037 Notification of contract execution, Mod 2 to "Bynthesis of Physical Security & Matl Control & Accounting Assessment Results " Contractor Science Applications Inc FOSTER, J M Technical Assistance Contracts Branch FIN 8-6412-9 NRC-02-79-029 80/06/04. 1p
- --B006230041 Mod 2.re-establishing delivery dates specified in contract & modifying period of performance, to "Synthesis of Physical Security & Mati Control & Accounting Assessment Results "TREVINO.T Ecience Applications, Inc DOUGHERTY.D J Technical Assistance Contracts Branch FIN 8-6412-9, NRC-02-79-029
- 8006230044 Notification of contract execution, Mod 1 to "Technical Presentation & Consultation in Connection W/Bagtram & Patram " Contractor Stanford Research Inst. EDGEMORTH:P J Technical Assistance Contracts Granch FIN 8-6124-0 NRC-02-80~051 80/05/23 ip
- --8006230048 Mod i, decreasing funds, to "Technical Presentation & Consultation in Connection W/Sagtram & Patram "
 RIBERA, J.R. Stanford Research Institute DOUGHERTY, D.J.
 Technical Assistance Contracts Branch FIN 8-6124-0,
 NRC-02-80-051 80/05/23 ip
- 8006230120 Notification of contract execution, Mod 3 to "Survey of Current State Radiological Emergency Response Capabilities for Transportation Related Incidents " Contractor IN Univ QUSTAVE,R P Research Contracts Branch. FIN 8-10708 NRC-01-78-013 80/06/04 ip
- ----3006230124 Mod 3, changing time for submission of final rept to read 21 months after effective date of contract to "Burvey of Current State Radiological Emergency Response Capabilities for Transportation Related Incidents "RYAN, J W Indiana Univ MORTON, K. V. Research Contracts Branch FIN 8-10708 NRC-01-78-013 80/06/04 ip
- 8006230129 Notification of contract execution, Mod 5 to "Properties of Reactor Matl at Constant True Strain Rates " Contractor Univ of FL JACOBS, A Research Contracts Branch FIN B-5948 NRC-04-77-039 80/06/11 ip

- --B006230133 Mod 5, extending contract through 800630 at no add1 cost, to "Properties of Reactor Mat1 at Constant True Strain Rates "RANDAZZO, A F Florida, Univ of, Qainesvilla MDRTON, K V Research Contracts Branch FIN B-5948 NRC-04-77-039 80/06/11 2pp
- 8006230150 Notification of contract execution, Mod 1 to "Thermal Conductivity of Disordered Minerals & of Rocks in High Lavel Haste Regositories " Contractor Cornell Univ HA0EV,H A Research Contracts Branch FIN B-6626 NRC-04-78-261 80/05/10 1p
- --8006230164 Mod i,adding no-cost extension for one addi year, to
 "Conductivity of Disordered Minerals & of Rocks in High
 Level Haste Repositories "
 RODERS T R Cornell Univ MORTON, K V Research Contracts Branch
 FIN B-4626 NRC-04-78-261 80/05/10 2pp
- B006230170 Notification of contract execution, Mod 1 to "Stenographic Reporting Svcs (LOT 1) " Contractor Intl Verbatim Reporters Inc Inc HEDROW, L A K Administrative Contracts Branch FIN B-1311 NRC-17-80-448 B0/06/11 1p
- --8006230178 Mod 1, terminating contract effective 800502 to,
 "Stanographic Reporting Svcs (LOT 1)"

 * International Verbatim Reporters, Inc MATTIA,M J
 Administrative Contracts Branch FIN B-1311 NRC-17-80-448
 80/06/11 1p
- B006230194 Notification of contract execution, Mod 1 to "Core Melt Matls Interactions Evaluations " Contractor Applied Science Associates, Inc FOSTER, J M Technical Assistance Contracts Branch FIN 8-6823 NRC-03-80-104 80/06/04 1p
- --8006230200 Mod 1, changing Article V overhead/general administrative rates to, "Coro Melt Matis Interactions Evaluations " 8MANSON.D 0 Applied Science Associates, Inc DDUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6823 NRC-03-80-104 80/06/04 1p
- 8008240241 Notification of contract execution "Devalopment of Model State Emergency Response Program for Transportation Related Radiological Incidents " Contractor EPA Municipal Environ Research Lab QUSTAVE, R P Research Contracts Branch FIN B-10730 NRC-01-80-020 80/06/02 1p
- --8006240246 Contract "Development of Model State Emergency Response Program for Transportation Related Radiological Incidents," awarded to EPA Municipal Environ Research Lab # Environmental Protection Agency MORTON.K V Research Contracts Branch FIN 8-10730 NRC-01-80-020 80/06/02 App
- B006240R36 Forwards State of QA second quarterly rept re transportation surveillance program Requests comments.

 JANICEK, M Office of State Programs, Director NRC-06-78-362
 B0/06/03 2pp
- --8006240262 Forwards second quarterly progress rept. Jan-Mar 1980, re transportation surveillance INGRAM, W D Georgia, State of NRC-06-78-362 80/05/13 34pp
- 8006240645 Notification of contract execution.Mod 2 to "Career Counseling " Contractor Binder.Elster.Mendelson & Wheeler. Int Int WIGOINS.E J Administrative Contracts Branch NRC-10-79-387 80706/02 ip.
- --8006240649 Mod 2, changing place of performance & amount of govt obligation, to "Career Counsaling "
 MENDELSON, I N Binder, Elster, Mendelson & Wheeler, Inc
 MATTIA: M J Administrative Contracts Branch NRC-10~79-387
 80/06/02 ip
- 8006280029 Notification of contract execution. Mod 2 to "Meteorological Consulting Byc " Contractor US Dept of Commerce Environ Research Labs GLACOLAIA F. Technical Assistance Contracts Branch FIN 8-6600, NRC-03-79-132 80/01/21, ip.
- --8006250034 Mod 2,modifying scope of work & increasing financial abligation.to "Medeorological Consulting Syc "HEBS.H N Commerce.Dept of DOUGHERTY.D J Technical Assistance Contracts Branch FIN 8-6600, 80/01/21 ip

- 8006250033 Notification of contract execution, Mod 6 to "Flood Protection" Contractor US Army Coastal Engineering Research GLAGOLA: A F Technical Assistance Contracts Branck FIN 8-5975 NRC-03-77-006 80/06/03 1p
- ~-8006250038 Mod 6.replacing LO Hulman w/WS Bivens as NRC cognitant engineer.to "Flood Protection " * Army Dept of DDUGHERTY,D J Technical Assistance Contracts Branch FIN B-5975 NRC-03-77-006 B0/06/03 1p
- 8006250040 Notification of contract execution, Mod 8 to "Document Control Bys " LEBO,C D Administrative Contracts Branch NRC-10~78-580 80/06/12 ip
- ~-8004250042 Mod 8, ordering option yr three, to "Document Control Sys " FELTON:R W TERA Corp MATTIA:M J Administrative Contracts Branch NRC-10-78-580 80/06/12 24pp
- 8006250041 Notification of contract execution "Environ Monitoring Program W/State of WI" Contractor State of WI BAIBDENL Research Contracts Branch FIN B-5114 NRC-05-80-275 80/01/01 1p
- --8006250045 Contract "Environ Monitoring Program W/Btata of WI."
 awarded to Btate of WI
 PERCY.D E Wisconsin, State of MORTON.K V Research Contracts
 Branch FIN B-3114 NRC-05-80-275 B0/01/01 14pp
- BOO6280049 Notification of contract execution, Mod 1 to "Economic Assistance re Antifrust Hearings for South TX Antifrust & Commanche Peak Antifrust Proceedings " Contractor Transcomm, Inc GLAGOLA: A F Technical Assistance Contracts Branch FIN B-6593 NRC-03-80-129 80/05/27 1p
- ---B006250059 Mod i, adding Task 6 % extending performance period to 800930.to "Economic Assistance re Antitrust Hearings for Bouth TX Antitrust & Commanche Peak Antitrust Proceedings "D0U0HERTY,D J Division of Contracts LERNER,N C Transcomm, Inc FIN 8-6593 NRC-03-80-129 80/05/27 1p.
- 8006250061 Notification of contract execution, Mod 9 to "Analysis of Hypothetical Accidents Resulting From Core Meltdown," Contractor Battelle Columbus Labs MORTON, K V Research Contracts Branch, FIN A-4067 NRC-04-78-293
- --8006290064 Mod 7.to include addl work including probabilistic uncertainty analysis to "Analysis of Hypothetical Accidents Resulting From Cope Meltdown"
 LUKZ.F J Battelle Hemorial Institute, Columbus Laboratories, NORTON,K V Division of Contracts FIN A-4067 NRC-04-76-273 79/11/01 6pp
- 8006250086 Notification of contract execution, Mod 2 to "Tearing Stability Analysis for LHR Piping " Contractor HA Univ OLAOCLA,A F Technical Assistance Contracts Branch FIN 8-657: NRC-03-79-134 80/04/29 ip
- --800A250090 Mod 2.modifying description of work,govt matl & consideration.to "Tearing Stability Analysis for LWR Piping "
 LEAHEY, H 8 Washington Univ DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-6571 NRC-03-79-134 80/04/29 2pp
- BOO6250206 Notification of contract execution Mod 6 to "Maint of Data General Corp C/330 Computers & Associated Peripherals " Contractor Data Consultants Inc MEDROWL A K Administrative Contracts Branch NRC-10-77-176 BO/06/02 ip
- --800A250210 Mod & changing Items 1.17 & 33. adding Items 4BA-Fracting forth current sys configurations increasing total amount of contract & revising pricing schedule to "Maint of Data General Corp C/330 Computers & Associated Perigherals."
 CASPERB.R H. Data Consultants. Inc MATTIA.M J Administrative Contracts Branch NRC-10-77-196 80/06/02 9pp
- 8006250222 Notification of contact execution, Mod 1 to "Bubscriptions to Nucleonics Wk" Contactor McGraw-Hill, Inc FLYNN, M J Administrative Contracts Branch NRC-10-80-665 80/06/04 1p. .
- --8006250225 Mod 1,adding four subscriptions, to "Subscriptions to Nucleonis Wk " CDLINE,P McGraw-Hill Publications Co MATTIA,M J. Administrative Contracts Branch NRC-10-80-465 80/04/06 2pp.

- 8006250293 Notification of contract execution, Mod 5 to "Electrostatic Copying Svcs " Contractor Potomac Research, Inc FLYNN-M J Administrative Contracts Branch NRC-17-77-152 80/06/10 ip
- --8006230295 Hod 3.relocating Xeror machines to Room 155 in Matomic Bldg. to "Electrostatic Copying Sycs" BAIN: E L Potomac Research. Inc MATTIA.M J Administrative Contracts Branch NRC-17-77-152 80/06/10 ip
- B006250330 Mod i.correcting typographical errors, to "Bys Analysis of Bhallow Land Burial" TREVIND. T Science Applications. Inc DOUGHERTY, D J Technical Assistance Contracts Branch FIN B-642B-9 NRC-02-79-032 B0/05/08 2pp
- 8006270010 Responds to FDIA request for NRC-03-80-117 & winning technical proposal Forwards requested documents FELTON, J M Division of Rules and Records 80/06/20 1g
- ---8006270014 Contract "Study of Requirements for Operator Licensing," awarded to Analysis & Technology, Inc HOODS, N. L. Analysis & Technology, Inc Of Contracts 80/05/12 23pp
- 8006270386 Notification of contract execution "Alternative Processes for TMI-2 Kr-85 Removal." awarded to Science Applications, Inc HAOAN.T.F Administrative Contracts Branch FIN 8-1582 NRC-19-80-472 B0/05/28 1p
- --800A270391 Contract "Alternative Processes for TMI-2 Kr-85 Removal."

 awarded to Science Applications, Inc
 FINDLEY,D E Science Applications, Inc MATTIA,M J

 Administrative Contracts Branch FIN B-1582 NRC-19-80-472

 B0/05/28 124ss
- 8006300338 Notification of contract execution, Mod 2 to "Engineering Assistance Related to Hearings for South TX Antitrust & Commanche Peak Antitrust Proceedings " Contractor RH Beck & Associates
 GLAGOLA: A Technical Assistance Contracts Branch FIN 8-6523
 NRC-03-80-120 80/06/10 ip
- --8006300343 Mod 2 modifying scope of work & period of performance & increasing funds to "Engineering Assistance Related to Hearings for South TX Antitrust & Commanche Peak Antitrust Proceedings"

 * Bechtel Corp DOUGHERTY.D J Division of Contracts FIN B-6323 NRC-03-80-120 80/06/10 2pp
- BOO6300345 Notification of contract execution, Mod 9 to "Review of Environ Impacts of High Level Radwaste Mgt " Contractor. Taknekron: Inc BHITH, P A Technical Assistance Contracts Branch FIN 8-4134-9 NRC-02-77-165 BO/06/13 ip.
- --BOOAGOO555 Mod 9, changing completion date of Bubtask 2 to BOO701, to "Review of Environ Impacts of High Level Radwaste Mgt "COMEN, 8 Teknekron, Inc BOUGHERY, D J Technical Assistance Contracts Branch, FIN B-6136-9 NRC-02-77-165, 80/06/13 1p
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 7903140178 R Sha has been appointed radiation safety officer for all matters relating to License 37-13129-02 W/encI resume detailing R Sha's qualifications.
 KIM-8.M Radiation Management Corp. 98793 79/02/23 4pp
- 7903270178 Discusses IE Insp 30-13219/79-01 on 790111 of License 19-17039-01 No noncospilance noted Major areas inspected radiation safety & compliance w/NRC rules & regulations MCCLINTOCK.R O Region i, Philadelphia, Office of the Director 79/01/25 2pp
- 8005050138 PNO-II-80-049 Sefe Energy Alliance is planning forum on 800327 at part outside plant gate Group has demonstrated peacefully before at plant MARTIN.R. Region 2, Atlanta, Office of the Director 80/03/28 ip.
- 8006020111 Responds to FOIA request for NL Industries amended application,including route into Request pertains to records to be received at future date FOIA is not applicable FELTON.J M. Division of Rules and Records 80/05/27 ip
- 8008020113 FOIA request for Ni. Industries amended application, including routé info REBNIKOFF, M Sierra Club 80/05/11 ip

- 8006040445 FOIA request for records concerning Hittman Nuclear & Development Corp.RAD Bvcs.Inc & Radiation Mgt Corp & issues of weekly info repts to date
 BUTTON.W H Radiological Controls 80/05/05 2pp
- 8006120165 Responds to FOIA request for SECY-78-137 Document is available in DC PQR
 FELTON, J M Division of Rules and Records NRC 80/06/03 1p
- BOD6120167 FOIA request for SECY-78-137
 JOHNSON, C Texas Public Interest Research Group 80/05/07 1p
- 8006120169 Responds to FOIA request for documents between R Martin & V Stello, summaries of conversations, logs for incoming or outgoing telcons & all R Martin travel claims since 800401 No documents exist pertaining to request FELTON, J M Division of Rules and Records 80/06/03 1p
- 8006120174 FOIA request for documents between R Martin & V Stello, summaries of conversations, logs for incoming or outgoing telcons & all R Martin travel claims since 800401 FIDELL, E R LeBoeuf, Lamb, Leiby & MacRae 80/05/23 2pp
- 8006120176 Partial response to FOIA request for documents re rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors Forwards documents listed in App A W/o encls FELTON.J M Division of Rules and Records 80/06/03 2pp
- 8006120180 FOIA request for documents re rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors BALTER:N S Affiliation Unknown 80/05/14 ip
- 8006120186 F01A request for TVA 76012B environ info rept.TVA responses to NRC comments on Edgemont U Mill Jul 1976 environ info rept & engineering analysis of mill facility decommissioning & long-term tailings stabilization REID.A B Black Hills Alliance 80/05/12 3pp
- 8006120401 Responds to Westchester County Board of Legislators FOIA requests for documents re N Lighlman grant proposal NRC has no record of receiving proposal from N Lighlman FELTON:J M Division of Rules and Records 80/06/10 1p
- 8006120403 FOIA request for N Lighlman grant proposal & supporting documentation AUDIN, L Weschester County, NY 80/05/16 1p
- B006120407 Responds to FOIA request for NRC-03-80-137 between NRC & Human Design Group, underlying request for proposal & related correspondence Forwards documents listed in app W/o encls FELTON-J M Division of Rules and Records NRC-03-80-137 80/06/10 2pp
- 8006120412 FOIA request for NRC-03-80-137 between NRC & Human Design Oraup, underlying request for proposal & related correspondence FIDELL: ER LeBosuf, Lamb, Leiby & MacRae 80/05/21 ip
- 8006120316 Responds to FOIA 800507 request for license applications & licenses issued to Pharmaco-Nuclear Forwards App A documents Documents 20:53 & 104 partially withheld home telephone numbers (ref FOIA Exemption 6) M/o encis FELTON.J.M Division of Rules and Records 80/06/05 10pp
- 800&120518 FOIA request for license applications & licenses issued to Pharmaco-Nuclear MCDONALD.D D Nuclear Pharmacy. Inc. DDM 580-7 80/05/07 ip
- 8006120521 Final response to FOIA requests for various documents listed & specifically identified by accession & rept numbers, author, number of pages & brief description FELTON J M Division of Rules and Records 80/06/06 3pp
- 8005130144 Discusses Ofc of General Counsel legislative proposal for changing civil penalty authority.Problems remain rerationale for increasing civil penalty limits Provides argumants supporting increased limits MURRAY,JP Rulemaking & Enforcement Division 78/12/21 2pp
- --8006130145 Comments on paper recommending changes in NRC civil penalty authority Lists weaknesses in arguments supporting various positions advanced in paper Submits comments justifying bases for civil penalty increases MURRAY, J P Rulemaking & Enforcement Division 77/12/15 6pp

- ---8006130148 Comments on final draft of Commission paper recommending higher civil penalty authority Recommends that Executive Legal Director not concur w/paper unless arguments are substantiated MURRAY.J P Rulemaking & Enforcement Division 78/01/30 5pp
- --800&130191 Forwards final draft of Commission paper recommending substantial increase in NRC penalty authority Requests review & comments JP Murray draft memo encl CONVER.S Office of Inspection & Enforcement, Office of the Director 78/01/19 20pp
- --8006130152 Forwards suggestions re proposed Commission paper concerning NRC civil penalty authority MURRAY, J P Rulemaking & Enforcement Division 78/02/06 4pp
- ---8006130194 Informs that NRC has draft proposal for civil penalties legislation modified to remove 30-day limitation & w/ supporting arguments Requests meeting to discuss procedure for levying penalties List of civil penalty cases encl HENDRIE, J M Commission 79/02/26. 19pp
- 8006130207 Responds to FOIA request for eight categories of personnel info re Hispanic employment Forwards documents listed in app NRC has no accession or promotion info for Hispanics for 1977 Hispanic recruitment program is underway FELTON, J M Division of Rules and Records 80/05/30 62pp
- 8006130212 FOIA request for eight categories of personnel info re Hispanic employment MONTOYA:D F National Image:Inc. 80/03/27 2pp
- 8006170282 FOIA request for documents re NRC insp of Atomics Intl & allegations of 8 Schecter.
 MILLER, T Affiliation Unknown NRC 80/05/08 4pp
- BOOA170287 Requests brief, written status rept re overall effort by Ofr of Nuclear Reactor Regulation in area of pellet-clad interaction Should include discussion of whether fuel failures would be increased by extending fuel burnup limits LIBARKIN, M W ACRB Advisory Committee on Reactor Safeguards 79/07/27 ip.
- 8006170791 Partial response to FOIA request for 22 categories of documents re facility. Forwards App A & B documents Portions of App A documents & names of individuals exposed to radiation withheld (ref FOIA Exemptions 4 & 6) W/o encls FELTON. J M Division of Rules and Records 80/06/11 5pp
- B006170797 F0IA request for 22 categories of documents re facility QIVEL.M. Affiliation Unknown B0/05/15 2pp
- 8006170811 Responds to FOIA request for list of Region 4 employees, including grades & dept 5/or ofcs. Forwards requested list. W/o encl
 W/o encl
 FELTON.J M Division of Rules and Records 80/06/02 lp.
- 8006170813 FOIA request for list of Region 4 employses, including grades & dept &/or ofcs
 DAVIS,E.P. General Services Life Insurance Co. 80/04/08 1p
- 8006180016 Responds to FOIA request for records re Hittman Nuclear & Development Corp, RAD Evcs, Inc & Radiation Mgt Corp & Matle article entitled, "Oft of IC, Items of Interest" from weekly info repts Forwards documents listed in App A FELTON, J.M. Division of Rules and Records 80/05/23 48pp
- --8006180110 Matl/Byproduct License 19-17039-01 for Hittman Nuclear & Development Corp. authorizing possession & receipt of packages containing solid waste byproduct, source & ENM, except in Agreement Btates Draft encl
 BABSIN.N Radioisotopes Licensing Branch (Pre 790501) 78/07/05
- --8004180115 Forwards addendum to 771117 licensing info re Model 8-6408, Am-241 sources for use in smoke detectors Info should be incorporated into original submission for evaluation FEINSTEIN.H W Hittman Nuclear & Development Corp (subs Hittman Corp) NB78-014 78/04/24. 4pp
- --8006180119 Bubmits correction to 770819 ltr re SNM specified under Requested Change Item 6. b FEINSTEIN.H W. Hittman Nuclear & Development Corp. (subs Hittman Corp.). 77/09/02 ip.

- --8006180129 Application for amend of 760526 application for matl byproduct license changing Items 6 b & 7 re radweste shipment packaging, receipt & possession Related documentation encl FEINSTEIN, H W Hittman Nuclear & Development Corp (subs Hittman Corp) 88396 77/08/19 16pp
- --G006180135 Requests extension until 770530 to forward application for byproduct matl license, in response to Commission requirements for addl info FEINSTEIN, H Hittman Nuclear & Davelopment Corp (subs Hittman Corp), 77086-N 77/04/21 1p
- --8006180137 Notifies that unless add1 info re application for hyproduct mat1 license is received within 30 days, application will be
 - Radioisotopes Licensing Branch (Pre 790501) 77/04/05 1a
- --8006:80141 Responds to 760924 ltr re application for license to receive radwaste Requests addl info re recipients of matl & transurantc wastes, quantities of matl. amount of time spent in training & driver training program description BASSIN.N Radioisotopes Licensing Branch (Pre 770501) FCRL NB 82062 76/12/09 2pp
- --8004180145 Notifies that unless add1 info re application for byproduct mat1 license is received within 30 days, application will be BASSIN.N Radioisotopes Licensing Branch (Pre 790501) 76/09/29
- ---800Ai80152 Forwards add1 info in response to NRC 760617 request for info concerning 760826 application for mat1 byproduct license Info should allow NRC to proceed w/issuance of license iscense FEINBTEIN,H W. Hittman Nuclear & Devalopment Corp. (subs. Hittman Corp.). 76452-N. 76/09/24, App.
- --B0061B01B2 Responds to 760514 application for hyproduct matl license Requests addi info re quantity of matl recipient & specific training & instruction BABSIN.N Radioisotopes Licensing Branch (Pre 790501) FCRL NB 76/06/17
- --800Ai80i92 Forwards application for suproduct mati license Fee encl FEINSTEIN.H W Hittman Nuclear & Development Corp (subs Hittman Corp) 820A2 76/08/26 ip
- --8004180193 Application for hyproduct/matl license, authorizing J Darrin to use, possess & supervise use of 2,000 Ci radioactive matl w/atomic numbers 1-98,500 lb any source matl & 200 g SNM TUITE, P T Hittman Nuclear & Development Corp (subs Hittman Corp). 82062 76/05/14. 6pp
- --8006180198 "Radsafe Program." * Hittman Nuclear & Development Corp. (subs Hittman Corp.) 82062 74/05/14. 27pp
- --8006180203 Amends Matl/Byproduct License 37-17010-01 for RAD Bycs. Inc per 741203 application Amend 1 removes condition authorizing licenses to store packages containing waste byproduct matl BARSIN.N Radioisotopes Licensing Branch (Pre 790501) 77/02/08
- --8006180206 Matl/Byproduct License 37-17010-01 for RAD Sycs, Inc. authorizing receipt & possession of 10,000 Cf byproduct matl w/atomic numbers 1-83 & 10 Cf Am-241 BELL,J M Radioisotopes Licensing Branch (Pre 790501) 76/09/21
- ---8006180227 Application for amend of Matl/Byproduct License 37-17010-01.
 deleting Item 2 re storage in bldg at Route 18 & Eastwood
 Drive.Big Beaver Township.Beaver Falls.FA RAD Svcs. Inc is
 looking for naw bldg to carry out licensed operations
 HABER.D.R Rad Bervices. Inc 65246 76/12/03 2pp
- --8006180234 Responds to NRC 760617 request for addi info re burial site Forwards info for inclusion in waste disposal license application Consists of corrected section, "Radiation Detection Instrumentation," & radiation training program HABER, D. R. Rad Bervices, Inc. 76/07/30 2pp
- --8006180241 Corrected section, "Radiation Detection Instrumentation," radiation safety training program & corrected instructions to personnel re packaged radwaste # Rad Services, Inc 76/07/30 33pp

- ---B006180245 Responds to 760426 application for math/byproduct license Requests clarification of inclusion of Am-241 in application-refs to calibr svc & length of training program BASSIN.N Redicisotopss Licensing Branch (Pre 790501) 76/06/17
- --BOOA180252 Forwards application for matl/byproduct license fee HABER, D.R. Rad Services. Inc. 71740 '76/04/24 ip
- ---8006180263 Application for mati/byproduct license authorizing possession of 100 Ci byproduct raduaste, transport & disposal of 10.000 Ci raduaste & possession of 10 Ci Am-241 in sealed sources Supporting documentation encl GARY. O R Rad Services, Inc 71740 76/04/26 87pp
- ---7902140223 Mat1/Byproduct License 37-13129-03 for Radiation Management Corp authorizing use of Ni-63 foils in Perkin-Elmer gas Chromatographs for sample analysis BASSIN-N Radioisotopes Licensing Branch (Pre 790501) 79/01/22
- --800618026B Forwards application for mati/byproduct license KIM.8 M Radiation Management Corp 97983 78/12/26
- --8006180272 Application for typroduct/matl license,authorizing possession & use of Ni-63 deposited on gold or platinum foil contained in detector cell KIH.S.M Radiation Hanagement Corp 97983 78/12/27 3pp
- ---8006180276 Amends Matl/Buproduct License 37-13129-02 per 791026 ltr Amend 3 changes Condition 7 to authorize possession & use of licensed matl described in Items 6,7 & 8 in accordance w/commitments.

 QUINN,P R Radioisotopes Licensing Branch (Pre 770501) 80/02/19
- --8006180279 Amends Matl/Byproduct License 37-13129-02 per 790223 ltr Amend 1 changes Condition 7 to authorize possession & use of licensed matl described in Items 6,7 & 8 in accordance w/conmitments Redicisatores Licensing Branch (Pre 790501), 79/04/09 ip
- --8004180283 Mat1/Byproduct License 37-13129-02 for Radiation Mgt Corp authorizing receipt, possession & transport of 2,000 Ci byproduct mat1 w/atomic numbers 1-84 inclusive, 2,000 kg source mat1.50 g U-23 & 150 g Pu. BABSIN,N Radioisotopes Licensing Branch (Pre 790501) 78/11/13.
- --8006180286 Forwards payment of fee for 791026 request for amend to Byproduct/Mat1 License 37-13129-02 KIM:B M Rediation Management Corp 79/11/14 ip
- ---BOOA:BO2BB Responds to 791026 request for amend to Byproduct/Matl License 37-13129-02 Requests amend fee.Application will be processed upon receipt of fee JACKBON:Q License Fee Management Branch 79/11/05 ip
- --800618029R Responds to NRC request for amend fee for 790223 request re Byproduct/Matl License 37-13129-02, Fee encl. KIM.B M Radiation Management Corp 79/03/12 ip
- ---800.6180.274 Responds to 7702.23 request for amend to Byproduct/Matl License 37-13129-02 Requests amend fee Application will be processed upon receipt of fee. JACKSON.0 License Fee Management Branch 79/03/06 ip
- --8006180900 Application for amend to Matl/Byproduct License 37-13127-02, changing SUP for commercial waste disposal by eliminating limit of storage drums,
 KIM.B M Radiation Management Corp NRC 01692, 79/10/26 ip.
- --8006180307 Forwards two amend applications & supplemental info reflecting new addresses on Licenses 37-13129-01 & 37-13129-02. KIM, B.M. Radiation Management Corp. 00182 79/05/25 1p
- Amended to incorporate suggestions contained in NRC 780304 ltr. Lists procedure revisions Forwards SDP KIM, 8 M. Radiation Management Corp. 78/09/22 28pp.
- --8006180336 Requests add1 info re 780504 application for license to receive prepackaged waste.Lists comments re 80P for commercial waste disposal BASSIN:N Radioisotopes Licensing Branch (Pre 790501). 78/07/12

218 T

- ---8006180342 Forwards application for license to collect prepackaged licensed radwaste Application fee encl
 KIH.8 M Radiation Management Corp 94440 78/05/04 ip
- --8006180348 Application for matl/byproduct license authorizing JB Davis to use & supervise use of 2,000 Ci,any byproduct matl w/atomic numbers 1-84.2,000 kg source matl & 200 g SNM SDP encl KIM, 8 M Radiation Management Corp 94440 78/05/04 22pp
- 8006180210 Responds to appeal re partial denial of FDIA request for route info re spent fuel shipments from Chalk River to Unterio.Canada Appeal is denied Info withheld (ref FDIA Exemption 4 & IOCFR2 770) Exemption DIRCKS N J D Office of the Executive Director for Operations
- ---8006180219 Responds to City Environ Commission 800229 request for info re Ci content of spent fuel shipments from Chalk River research reactors & for NUREQ-0170 Shipments may range in Ci content from 1 4 million to 9 1 million Ci BURNETT.R F Division of Safeguards 80/03/21 1p
- --8006180236 Forwards summary of 800416 meeting between NRC & NY State Energy Ofc re transportation of spent nuclear fuel Requests to be kept informed of NRC progress re proposed changes to spent fuel transportation safeguard requirements SPATH.J P New York, State of 80/04/30 6pp
- 8006180216 Appeals partial denial of FOIA request for route info of proposed spent fuel shipments from Chalk River, Ontario to EC RESNIKOFF.M Sierra Club 80/04/28 2pp
- 8006180308 FOIA request for info re mineral recovery or reprocessing operation conducted on premises of 9200 Latty Avenue. Bt
 Louis. MO.
 HIRZY, J W Affiliation Unknown 80/02/25 3pp
- 8006180313 Responds to FOIA request for info re mineral recovery or reprocessing operation conducted on premises of 9200 Latty Avenue:8t Louis:NO Items 7-10 & 15-18 are not DOE responsibilities & have been referred to NRC RAMBEY,R W Energy,Dept of 80/03/12 2pp
- 800619006B FOLA request for info re Coalition for Non-Nuclear World, member organizations &/or natl or intl nuclear protests held during 800325-0430 Affiliation Unknown 80/05/21 1p WARNOCK, D
- 8006190072 Partial response to FOIA request for info re Coalition for Non-Nuclear World, member organizations &/or natl or intl nuclear protests held during 800325-0430 Forwards documents in app NRC does not maintain files on organizations FELTON.J M Division of Rules and Records. 80/06/13 2pp
- --8006190080 Discusses WTTQ-TV news rept re 800426 nuclear protest in Washington, DC Raily is not end of anti-nuclear demonstrations. Next scheduled rally will be at Pentagon * Affiliation Unknown, NRC-00154 80/05/21, lp
- 8006190114 Responds to FOIA request for winning technical proposal in response to RFF-RD-EDO-80-502, "Btudy & Review of Issues Concerning Equal Employment Opportunity at NRC " Forwards nonproprietary version of proposal W/o encl.

 FELTON.J M Division of Rules and Records. 80/04/11 1p
- 8006190115 Supplements 781130 response to FOIA request for info re proposed nuclear fuel facilities in Pacific region. Forwards Documents 1 & 2 in App A Document 3 partially withheld & Document 4 withheld (ref FOIA Exemption 1) FELTON. J. M Division of Rules and Records NRDC/TBC/79-45 80/06/13 2pp
- --8006190118 Requests statement of NRC licensing criteria applying to storage of foreign spent fuel in UB or possessions Statement will be forwarded to State Dapt re interagency study on US foreign policy re foreign spent fuel storage SMEA.T.R Office of International Programs, Director 78/04/27
- ---8006190125 Responds to 780725 ltr re storage technologies & potential Pacific basin sites for spent fuel storage.NRC will provide technical expertise to respond to foreign govt requests for assessments of site suitability & storage technology.

 ODSSIGN.L.V Office of the Executive Director for Operations qqE

- --B006190129 Nonproprietary discussion of use of Pacific basin islands as interim spont fuel storage ctr Proposed independent spent fuel storage installation is expected to be of passive dry above-ground, smaled, steel & concrete cask design SMEALJR Office of International Programs, Director 7B/07/20 in
- 8006190116 Responds to FOIA request for winning proposal in response to RFP RS-NRR-80-102. "Energetic Thermal Interactions. Recriticality & HTOR Accident & Transient Coolant Flow "Forwards document W/o encl FELTON.J M Division of Rules and Records 80/04/17 ip
- 8006190237 Responds to FOIA request for list of equipment environmentally qualified by environ testing labs No documents available RH Vollmer 800530 mamo forwarding mamorandum & order re environ qualification encl FELTON.J M Division of Rules and Records 80/06/12 1p
- --B006190255 Forwards NRC 800528 memorandum & order re fire protection for electrical cables & environ qualification of electrical components
 VQLMER.R H Division of Engineering 80/05/30 19
- 8006190248 FGIA request for list of equipment environmentally qualified by environ testing labs KNUTH.D F KMC Inc 80/03/12 1p
- 8006200060 Responds to FOIA request for L Pitkin 1971-72 study of radiation levels in areas near active & inactive U mills & 1979 study, under NRC contract, re radiation levels in Shiprock,NM Deposit is required byfore request processed FELTON, J M Division of Rules and Records 80/06/03 2pp
- 8006200064 FOIA request for L Pitkin 1971-72 study of radiation levels in areas near active & inactive U mills & 1979 study/survey, under NRC contract, re radiation levels in Shiprock, NM area METTLER, E. R. DNA - People's Legal Services, Inc. 80/05/05 ip
- BOO6230047 Responds to FOIA request for seven categories of NRC distribution lists Forwards lists W/o encls FELTON.J.M Division of Rules and Records BO/06/16 1p
- 8006230050 FDIA request for seven categories of NRC distribution lists WIEDENHORN, J T Nucleonics Weeks, pub of McGraw Hill, Inc 80/05/29 Ip
- 8006230057 Responds to FOIA request for documents prepared for compliance w/NRC regulations re physical protection of irradiated reactor fuel in transit Documents listed in App A withheld (ref FOIA Exemption 4 & 10CFR2 790) FELTON, J M Division of Rules and Records 80/06/16 3pp
- BOO6230059 FOIA request for documents prepared for compliance w/NRC regulations re physical protection of irradiated reactor fuel in transit REYNOLDS, W. American Friends Service Committee BO/09/21 Rpp
- 8006230073 Responds to FOIA request for five categories of documents pertaining to specific companies in MY & 6D Forwards documents listed in App A Portions of Document 4 withheld social security numbers (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 80/06/17 3pp
- 8004230074 FDIA request for five categories of documents pertaining to specific companies in WY & 8D REID: A B Affiliation Unknown 90/05/12 2pp
- 80062300Bi Responds to FOIA request (sent to Dept of State) for info re nuclear fuel facilities in Pacific region Document responsive to request was released to NRDC on 800613 (FOIA-78-322. Document 2) FELTON. J M Division of Rules and Records NRDC/YBC/78-47 80/06/17 ip
- BO04230084 Forwards NRDC 781113 & 27 FOIA requests for info re proposed facilities in Pacific region Requests response Dept of State 800228 ltr encl CROAK.C State.Dept of 80/03/10 Spp
- 8006230089 Responds to FOIA request for SECY-75-429 Forwards document W/o encl FELTON,J K Division of Rules and Records 80/06/16 ip
- 8006230094 FOIA request for SECY-75-429 FIDELL, E R LeBosuf, Lamb, Leiby & MacRae 80/05/15 1p

- 8004230101 FOIA request for Edgement V mill decommissioning documents originating after Oct 1979 FOIA request REID.A B Affiliation Unknown 80/05/12 3pp
- 8006230106 Responds to FOIA request for documents re proposed nuclear reactors to be located near Gyaema. Morea SECY-80-185 & License XR-0133 are available in PDR FELTON.J M Division of Rules and Records 80/04/17 ip
- 8006230107 FOIA request for documents re proposed nuclear reactors to be located near Gyaema.Korea FOOTE.V B Center for Development Policy 80/05/21 19
- 8006240644 Responds to FOIA request for documents re cost benefit analysis of 800507 order & list of incidents in first paragraph of Section 1 of order No cost benefit analysis was performed Forwards list of incidents & exposures
 FELTON.J M Division of Rules and Records 80/06/19 4pp
- 8006240647 FOIA request for documents re cost benefit anelysis of B00507 order & list of incidents in first paragraph of Section 1 of order HUBBARD.L.B American Association of Physicists in Medicine B0/05/27 1p
- B006240650 Add1 response to FOIA request for documents re proposed nuclear reactors located near Gyzemai Korea, Forwards OH McCorkle 790322 memo BECY-79-141 is also suby to request & is available in PDR FELTON-J M Division of Rules and Records 80/06/20 ip
- --8006240453 Discusses review of application for license to export reactors to Korea No physical security concerns apparent Requests that Executive Branch provide info re Korean sys of accounting & control & status of safeguards implementation MCCORKLE, G W Physical Security Licensing Branch 79/03/22 1
- 8006270010 Responds to FOIA request for NRC-03-60-117 & winning technical proposal, Forwards requested documents FELTON, J M Division of Rules and Records 80/06/20 1p.
- --8006270014 Contract "Study of Requirements for Operator Licensing," awarded to Analysis & Technology, Inc WOODS, N L Analysis & Technology, Inc DOUGHERTY, D J Division of Contracts 80/05/12 23pp
- --8006270017 Response to RFP R8-NRR-80-117, "Btudy of Requirements for Operator Licensing." Describes technical approach, tasks, potential difficulties & solutions, power plant & training site selection & NRC operator licensing procedures.

 * Analysis & Technology, Inc R8-NRR-80-117 80/05/12 74pp
- 8006270012 FOIA request for NRC-03-80-117 & winning technical proposal NGCELLA:8 J Advanced Technology, Inc. 80/05/22. 1p.
- 8006270414 Responds to FOIA request for documents re Rockwell Intl Energy Bys Group use of radioactive matls Forwards documents in Apps A-D. Info partially withheld names & social security numbers (ref FOIA Exemption 6). Wo encis FELTON, J M Division of Rules and Records 80/06/20 9pp
- B006270415 FOIA request for documents re Rockwell Intl Energy Bys Group handling & use of radioactive matls
 TROY.M Affiliation Unknown 80/03/06 2pp
- 8006270416 Responds to FOIA request for documents re transportation of BNM Forwards JM Hendrie 780428 ltr to Z Brezinski FELTON, J M. Division of Rules and Records, 80/06/20 1p
- --B006270418 Forwards NRC 780428 ltr.in response to NRC request for assistance re FOIA request REGER.8 8 President of US & Executive Offices B0/05/21 1p
- --B006270419 Discusses possible use of military airfield for high enriched U shipments Guestion has been referred to Executive Branch for consideration NRC responsibility is to regulate commercial export & import of privately owned BNM HENDRIE, J M Commission 78/04/28. 20p
- 8006270417 FOIA request for documents re transportation of 8NM HANSELL.D Illinois: State of 79/01/24 2pp
- BOOA300022 Responds to FOIA request for documents listing nuclear plant locations, list of accidents at each location & radiation leaks & results Forwards App A documents Remainder of request does not meet specificity requirement FELTON, J M Division of Rules and Records BO/06/19 App.

- 8006300024 FOIA request for documents listing nuclear plant locations, list of accidents at each location, results of environ impacts, radiation leaks & results & list of radwaste depots ROBEY.J Affiliation Unknown 80/05/23 2pp
- BOOA300231 Forwards announcement re ACRS BOO40B technical meeting in Washington, DC to continue review of NRC study on whether equipment changes should be made on BM plants Announcement will be sent to news media on BOO325 W/o encl KAMMERER.C Office of Congressional Affairs 80/03/25 1p
- --800A300239 Forwards announcement re NRC appointment of BJ Snyder as program menager of facility cleanup operations W/o enc1
 KAMMERER, C Office of Congressional Affairs 80/03/25 ip
- ---B006300245 Forwards announcement re NRC publication of notice of availability for public comment of draft environ assessment concerning decontamination of facility reactor bldg atmosphere H/o encl KAMMERER, C Office of Congressional Affairs 80/03/26 ip
- --8006300254 Forwards announcement re ACRB 800407 meeting in Washington.
 DC to discuss implications of facility incident in relation
 to applications for CPs Announcement will be mailed to news
 media on 800326 W/o enci
 KAMMERER, C Office of Congressional Affairs 80/03/26 1p
- --8006300321 Forwards announcement to NRC issuance for public comment of Addendum 2 to draft rept. "Environ Assessment for Decontamination TMI-2 Reactor Bldg Amoshpere" W/o encl KAMMERER, C Office of Congressional Affairs 80/04/02 ip
- --8006300326 Forwards announcement re V Stello confirmation that IE has Heatmen, former facility control room operator W/o encl KAMMERER, C Office of Congressional Affairs 80/04/17
- --8006300337 Forwards announcement, w/attached NRC determination, that facility incident did not constitute extraordinary nuclear occurrence as defined by Price-Anderton Act & Commission regulations H/G and KAMMERER, C Office of Congressional Affairs 80/04/17 ip
- ---8006300345 Forwards announcement re NRC approval of util plans to make manned entry into facility containment bldg M/o encl
 KAMMERER, C. Office of Congressional Affairs 80/04/22 ip
- --8006300367 Forwards announcement re NASLB 800513 prehearing conference in Harrisburg.PA concerning proposed restart of facility
 - KAMMERER, C Office of Congressional Affairs 80/05/01. 1p
- --8006300445 Forwards announcement re extension until 800516 for public comment on draft environ assessment for decontamination of reactor bidg atmosphere. M/o encl
 KAMMERER, C Office of Congressional Affairs 80/05/08 ip
- 8006300535 Addi response to FOIA request for rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/04/17 2pp
- --8006300539 Comments on SECY-80-131, "Accident Considerations Under NEPA." Agrees wirecommendations in paper Commission should approve recommendation to initiate new approach wiongoing NEPA reviews

 HANRAHAN,E J Office of Policy Evaluations 80/03/14 in
 - 10546 Staff requirement memo re 800416 open meeting in Washington, o discuss SECY-80-131, "Accident Considerations Under ." Commission requested that personnel consider methods vning plants in early const stage ..." Bo/04/24
 - Jest for records pertaining to firm Joket.RI.NRC is unable to

 - ords re NUMANCO in Pawtucket.RI es, amends, suppls, correspondence trols 80/06/07 ip

- BOO6300569 Responds to appeal of partial denial of FOIA request for NL Industries most recent approved spent fuel route plan Appeal is denied info partially withheld surface transportation routes (ref FOIA Exemption 4 & 10CFR2 790) DIRCKS,W J Office of the Executive Director for Operations BO/06/18 1p
- 8006300876 Appeals partial denial of FOIA request for NL Industries most recent approved spent fuel route plan RESNIKOFF:M Sierra Club 80/05/12 ip
- 8006300582 Responds to FDIA request for NUREG-0646 & NUREG-0648 Forwards documents W/o encis
 FELTON, J M Division of Rules and Records 80/06/20 1p
- 8006300583 Responds to appeal re denial of FOIA request for documents re licensing of NFS Erwin nuclear fuel facility Denies appeal re App B Documents 2.4 & 7 (ref FOIA Exemption 3) Grants appeal for App B Documents 1.3,5 & 6 CHILK,8 J Office of the Secretary of the Commission 80/06/16
- --B00630060B Nonproprietary memo recommending that facility license be modified to preclude possession of significant quantities of high enriched U Lists considerations in reviewing paper Info withheld (ref FOIA Exemption 3) THOMPSDN:H L Commission 79/12/13 2pp
- -8006300612 Nonproprietary memo recommending that facility be allowed to operate under NRC licensing control w/ID limit of 1% throughput NES must increase physical security as proposed in SECY-79-630 Info withheld (nef FOIA Exemption 3) AHEARNE, J Commission BO/O1/09 2pp
- -8004300629 Nonproprietary mamo agreeing w/800109 memo re Commission position on facility Recommends that 1% throughput be considered ID limit goal, w/shutdown & inventory required at 1 % or 2 0% Info withheld (ref FOIA Exemption 3) HENDRIE.J M Commission 80/01/11 ip
- --800630635 Concurs w/summary points in 800109 memo recommending Commission position on facility, sub, to listed requirements Commission decision should be rendered immediately KENNEDY, R Y Commission 80/01/15 1p
- BO06300586 FOIA request for NUREO-0646 & NUREQ-0648 BANNER, A P Affiliation Unknown 80/06/02, 1p
- 8006300588 Add1 response to FOIA request for all NRC records re Coalition for Non-Nuclear World, member organizations %/or natl & intl protests held during 800325-0430 Forwards documents listed in App A Leaflet announcing protest encl FELTON, J M Division of Rules and Records 80/06/18 App
- --8006300592 Announcement 39 re Coalition for Non-Nuclear World 800428 possible demonstration at DDE Forrestal Bidg in Washington, DC & NRC N Street bidg Demonstrators should be treated in manner

 J Office of the Executive Director for Operations
 ip courteous manner DIRCKB.W J Off 80/04/22 1p
- --8006300576 "Civil Disobedience Action Training Handbook, March from DOE to Blockade Pentagon, 800428 "

 * Coalition for a Non-Nuclear World 80/04/28 32pp
- 8006300601 Responds to FOIA request for mailing list, "NRC Distribution Category Code #CL-State Legislation & Activities Rept "Forwards mailing list H/a enci FELTON.J M Division of Rules and Records 80/06/23 ip
- 8006300603 FOIA request for mailing list, "NRC Distribution Category Code #CL-State Legislation & Activities Rept " FORSTER,J Affiliation Unknown 80/06/09 1p
- BOO6300607 Responds to FQIA request for info re-medical-psychic projects NRC has no records partaining to request FELTON:J M Division of Rules and Records, 80/06/23 ip.
- 8006300609 FOIA request for info re medical-psychic projects.

 BEMIS, J M Affiliation Unknown 80/05/10 ip
- 8006300665 Responds to FDIA request for official communications from JM Hendris to Congress during tenure as Chairman & Commissioner of NRC All correspondence is available in PDR Forwards documents listed in App A FELTON

- BOO6300670 FOIA request for official communications from JM Hendrie to Congress during tenure as Chairman & Commissioner of NRC WEISS,E R Sheldon, Harmon & Weiss 80/05/28 ip
- 8006300672 Responds to 800603 followup FDIA request for Documents 16 & 17 omitted from NRC 800523 response to FOIA request for six categories of documents re CPC Forwards documents Four add1 documents are available in PDR W/o encis FELTON. J M Division of Rules and Records 80/06/23 1p

GEN TEC IS GENERIC TECHNICAL ISSUES

- 8006020170 Summary of 800514 meeting w/Sandia Natl Labs in Bethesda, MD re effectiveness of fault tree analysis in revealing sys interactions Sandia Labs will rescope program proposal for immediate demonstration of Phase I effectiveness ANGELO, J Ceneric Issues Branch 80/05/20 3pp
- BOO6020198 Summary of 800409-10 second technical meeting in Bethesda, MD, to discuss Task A-11.Revision 3, "Reactor Vessel Matis Toughness," Apr 1980 Meeting notice, agenda, list of attendees & supporting data encl JOHNSQN.R E Generic Issues Branch BO/05/09 50pp
- --8006020208 Discusses need for test & commercial reactor irradiations & analysis of existing radiation embrittlement data Reactor irradiations essential Bubmits embrittlement predictions Requests views re radiation damage program philosophy MARSTON,T U Electric Power Research Institute 80/03/18 7pp
- 8006030286 Forwards comments on NUREO-0460,Vol 4,re ATWS for LWRs Committee on Reactor Licensing & Safety disagrees w/proposed resolution based on design requirements GIBBS,D C. Atomic Industrial Forum 80/05/27 12pp
- 8006070057 Forwards "For Comment" edition of NUREO-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PNR Steam Generator & Reactor Coolant Pump Bupports," & notice of issuance & availability W/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/10 1p
- BOO6:10319 Forwards NEDE-24822-P. "Mark II Improved Chugging Methodology," as part of Task A 16 of Mark II containment program Prompt review requested Rept withheld (ref 10CFR2 790) BUCHHULZ,R H General Electric Co MFN 109-80 80/06/06 1p
- BOO6120156 Provides Subcommittee on Energy & Power w/NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking," for comment W/o encl FR notice encl DENTON, H R Office of Nuclear Reactor Regulation, Director BO/05/22 ip
- --8006120160 Notice of issuance & availability of NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking" EISENRUT, D. O. Division of Licensing 80/04/17 4pp
- 8006120164 Provides Subcommittee on Energy & Environ w/NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking," for comment W/o encl FR notice encl DENTON.H R. Office of Nuclear Reactor Regulation, Director 80/05/22 10
- 8006120170 Provides Subcommittee on Energy & Environ w/NUREG-0617. "BWR Feedwater Notice & control Rod Drive Return-Line Notice Cracking," for comment M/o enci FR notice enci DENTON, H & Office of Nuclear Reactor Regulation, Director BO/05/22 ip
- 8006120171 Provides Bubcommittee on Energy & Environ w/NUREO-0619, "BWR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking," for comment W/o encl FR notice encl DENTON.H'R Office of Nuclear Reactor Regulation, Director 80/05/22 1p
- BOO6160129 Provides Subcommittee on Nuclear Regulation w/NUREG-0577, "Potential for Low Fracture Toughness & Lameliar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " W/o encl
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director RO/08/16 in
- 8006230013 Requests that each project manager use Attachment 1 to determine whether assigned licensees submitted data in response to May 1977 memo re pressure vessel beltline mati surveillance
 EISENHUT.D 0 Division of Licensing 80/05/19 2pp

- 8006300188 Discusses implementation of revised SRP 5 4 7.providing revised cooling sys requirements & risk assessment recovered plant beat removal capability NGVAK.T M Reactor Systems Branch 78/06/08 3pp
- ~~8006300201 Discusses proposed implementation of revised cooling sys requirements & risk assessment re overall plant heat removal capability MATTSON.R J Division of Systems Safety STELLO.V Division of Operating Reactors 78/01/19 Spp

1%E INSPECTION AND ENFORCEMENT

- 800505013B PNO-I1-80-049 Safe Energy Alliance is planning forum on 800329 at part outside plant gate Group has demonstrated peacefully before at plant MARIIN.R Region 2. Atlanta. Dffice of the Director 80/03/28 ip
- BOO6020034 PNO-I-80-075 on BOO508, Mclean Trucking Co truck, carrying two Ohmart density gauge source holders containing Cs-137, exparienced load shift which twisted trailer body off frame Radioactive matl leakage not detectable ROTH, J. CROCKER, H.W., BMITH, G.H. Region 1, Philadelphia, Office of the Director 80/05/09 ip
- BOO6020061 PNG-III-80-086 Region 3 informed that personnel whole body film badge reading was 8,570 millinems during BOO210-0307 No explanation for exposure since individual was not working w/radiation PAPERIELLO, C J . DAVIS,A B Region 3, Chicago, Office of the Director 80/05/09 ip
- B006050126 PNO-II-B0-071 on B00520, small crack developed in pipe carrying hydrogen sulfide in heavy water, extraction process area Crack increased & chemical emergency declared on B00521 Leak temporarily self-sealed Repairs in process GIBBON, 6 T. JENKINS, 6 R. Region 2, Atlanta, Office of the Director B0/05/21, ip
- 8006060115 PNO-III-80-096. on 800516, informed that 10-mCi Cs-137 source in gauge source head was stolen, Licensee put 24 painted gauge source heads on pallets outside door of factory bldg to dry Employee returned & found I gauge missing PAPERIELLO, C J. DAVIS, A B Region 3, Chicago, Office of the Director 80/03/19 ip
- 8004040453 PND-III-80-097: on 800522.NRC plans to meet w/nonlicensee workers exposed to radiation from radiography activities of former licensee.American X-Ray & Insp.Inc License suspended 800228 & revoked 800519
 RRENIAHRKI,D J. DAVIS.A B Region G. Chicago, Office of the Director 80/05/21 2pp
- 8006090530 EN-80-018 on 800519, order revoking License 21-15455-01 was issued Action based on provisions of order to show cause & 800228 order suspending license. No response filed BROCKETT, T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/05/19 ip
- 8006090536 EN-80-007A on 800523, order imposing civil panalties issued, based on alleged noncompliance re math false statements in license renewal & application & failure to perform surveys.

 Licensee 800407 response inadequate BROCKETT, T., THOMPSON, D. Office of Inspection & Enforcement, Office of the Director, 80/05/23, 1p
- BOOLO90550 PNO-I-80-080 on BOO519.NRC was informed that Apr film badge issued to one radiographer showed dose of four rems Licensee conducting investigation OLENN.J E., EMITH.Q.H. Region 1. Philadelphia. Office of the Director. BO/05/19 ip
- 8006120005 PNC-I-80-079 on 800501, I-125 seed apparently ruptured while being implanted for interstitial treatment of cancer Mechanical difficulties encountered w/delivery sys Thyroid monitoring & urinalysis account for 250 mCi GLENN, U.E. SMITH, Q.H. Region i, Philadelphia, Office of the Director 80/05/19 ip

PUBLIC DOCUMENT ROOM MISCELLANEOUS

20952 Advises of 800313 or 20 meeting requested by J Nicholson of ranced Mechanical Technology, Inc to discuss future ition for rulemaking RY, J J Transportation & Product Standards Branch 80/02/27

)20249 Discusses interim procedures for research & stds ordination Ofc of Nuclear Regulatory Research safety needs solicies are underway Needs, comments & communications uld be transmitted to Div of Safety Technology ITON.HR Office of Nuclear Reactor Regulation, Director (05/23) 2pp

)20322 Forwards two tables of water levels measured in Great Marsh ar Cowles Bog during B00407-09 & 0416-0501 TSDN,L R Interior, Dept of, Geological Survey 80/05/23 4pp

020344 Informs that priorities for nuclear units scheduled for mmercial operation in 1982-85 period will be completed three was in response to 800507 itr Data sufficient to rify priority analysis will be supplied INER.R E Energy.Dept of 80/05/23 ip

020346 Comments on HR Denton 800328 ltr re qualification of reactor erators requirement for engineering degree should be more scific & spec of credit hr requirements should be more evative 7,D W Ohio State Univ 80/05/21 2pp

020594 Ack receipt of 800330 to R Dayoung Forwards rough guide to lative toxicity of various radionuclides included in App B 10CFR20, "Concentrations in Air & Water Above Natural ckground"
68, D F Division of Bystems Integration 80/05/14 9pp

04020414 Ack receipt of NRC 800103 ltr & 800121 telcon w/J8 Baegli Expresses interest in short-lived typically reactor-derived agents for potential use as radiological weapons Request originally sent to DDE DEMENT. J DeMent Laboratories 80/03/30 ip

090399 Industry, education, govt radiation machine registration plication NT.B.Q Affiliation Unknown 80/06/03 2pp

110050 Forwards specimen of std property insurance policy for erating power reactors including endorsements & claration page Policy form used for all insured, however, dividual coverage may be subject to conditions RDEB

:120004 Notification of 800327 meeting w/INPO in Bethesda.MD to scuss exchange on human factors program ELAND.R. Division of Human Factors Safety 80/05/23 2pp

120120 Responds to 800423 ltr re Ft. Willman concerns about impacts land uses at nuclear plant sites in State of IL Amount of remland involved is small fraction of total farmland

remiant invariant will be recutive Director for Operations 1/05/21 Rpp

06120122 Forwards FL Willman itr concerning impacts on land uses at nuclear plant sites in State of IL. RAIL88ACK.T House of Rep. 80/04/23 2pp

120157 Forwards comments on RW Clark paper. "Thermodynamics & sign of Heat Engines." forwarded by 800427 ltr Concerns - t applicable to nuclear reactor regulation since based on lealists models rather than actual properties of matls 10NITZ.R J Office of Nuclear Regulatory Research, Director 1703/27 App

NO6120138 Forwards "Thermodynamics & Design of Heat Engines " Nuclear industry is not based on true, precise, next to perfect

science CLARK,R W Affiliation Unknown 80/04/29 ip

106120161 "Thermodynamics & Design of Heat Engines " CLARK,R W Affiliation Unknown 80/04/29 36pp

x120272 Requests info re Atomic Energy Act of 1994, including any mendatory law & financial responsibility requirements of xclear facilities/such as insurance requirements or amounts insurance permissable WE,H.D Bayly, Martin & Fay Inc. 80/06/03 ip

8006(30182 Notification of 800610 mesting w/Nuclear Voice Control re demonstration on solid state voice talk-out capability into valve.check gauge,flow meter.dial.light & high/low temp Human Factors Engineering Branch 80/05/30 2pp JOYCE, J

8006130313 Forwards extract of Town of Kensington 800313 meeting re Article 18 of 1780 Town Warrant Evacuation for town feasible within time frame during which radioactive plume might cover town RDGDVIN.M Rogovin.Stern & Huge 80/05/12 1p

8006170631 Notifies that facility form modified to reflect change re definitions of insured shipment & insp suspension condition Amendatory Endorsements NE-30 & NE-51 encl QVATTROCCHI, J American Nuclear Insurers 80/06/13 6pp

BOO6180275 Returns license application for expert of thorium to Ciechoslavakia w/o action because matl no longer requires specific NRC export license FR notice of rulemaking, amending NRC 106FR110 23 regulations encl M/o encl HEMBY.E O Office of International Programs, Director 60/06/05

8006180580 Provides status of TMI Bulletins & Orders Task Force work Discusses MCAP-9600.LOCA analysis.auxiliary feedwater upgrade & plant procedural audits RDS3.D TMI-2 Bulletins & Ordera 79/11/03 3pp

BOO620063 Advises of inability to participate in Working Group 3 of Coordinating Committee on Mill Tailings due to limited travel funds Recommends rescheduling of mill tailings & waste mpt meetings to facilitate attendance MARTIN.J B Urenium Recovery Licensing Branch BO/05/07 2pp

BOO6230046 Bummary of BO0529 meeting w/Inst for Nuclear Power Operations re exchange of technical info IRELAND.R Division of Human Factors Safety 80/06/10 App

BO06240460 Forwards "Test Rept AGS21678/TR.Revision A.Booklet 174." & Catalog NP-1.per NRC B00514 & 16 requests Response to IE Info Notice B0-11 will be forwarded soon Test rept & catalog withheld (ref 10CFR2.790)
BROWN.W M Automatic Switch Co IEIN-80-11 B0/06/19 1P

BOO6250089 Notification of BOO617 meeting w/util group in Bethesda.MD to discuss IE Bulletin BO-11.masonry wall design JORDAN.E.L. Division of Reactor Operations Inspections IEB-80-11 BO/66/10 2pp

80062503i1 Bubmits trip report of third meeting of Nuclear Waste Mgt Process Review Forum on 800407-09 Supportive documentation encl COMELLA.P A Site Designation Standards Branch 80/05/23 20pp

8006300641 Calls special attention to certain procedures of revised manual chapter concerning radioactive contamination clearance Emphasizes need to establish representative monitoring grid BILES,M & Atomic Energy Commission 73/01/15 17pp

NRC NUCLEAR REGULATORY COMMISSION, GENERAL

BOO6160180 Notifies that current financial disclosure statements for senior NRC officials have been released to PDR per Ethics in Govt Act.

* Office of the Secretary of the Commission 80/05/27 ip

8006300527 Informs that confidential statement of employment & financial interests has been reviewed Exemption from provisions of 100FRO 733-21 must be granted in order to allow work on licensing matters involving Westinghouse VOLLMER.R H Division of Engineering 80/06/11 ip

NUREG NUREO REPORTS AND RELATED CORRESPONDENCE

8006020436 Comments on NUREG-0634 some criteria excessive More important requirements should be tested on prototype basis before implementation on grand expensive scale Also.NRC/FEMA should develop model emergency plan for states & towns COUNSIL.W O Northeast Utilities 80/05/14 7pp

8006020537 NUREG/CR-0808 DMADEWSJ/ NURKEJ/CR-UBOH "Un Corresion Adequacy of 2 1/4 Cr-imo Steel for LMFBR Steem Ceneration Sye Syc " ZIMA,Q.E Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2111. PNL-2795. BO/O5/31 70pp Available at NTIB

- 8006020543 NUREG/CR-1495
 "Photoglastic Studies of Damping, Crack Propagation & Crack
 Arrest in Polymers & 4340 Steel "
 IRWIN, G R. BARKER, D B. SANFORD, R J Maryland, Univ of FIN
 A-9026 80/05/31 275pp Available at NTIS
- 8006020548 Comments on NUREG-0654 requirement for mechanical maint person on shift is of questionable value Requirement for two or three maint people on call would be preferable PARKER.W O Duke Power Co 80/05/13 4pp
- BOO6020555 Comments on NUREG-0654 document should be amended to follow outdoor warning sys re max sound level received by individuals Examples of rept refs encl
 BERG.R E Affiliation Unknown BO/05/01 11pp
- 8006030286 Forwards comments on NUREO-0460,Vol 4.re ATMS for LWRs Committee on Reactor Licensing & Safety disagrees w/proposed resolution based on design requirements G1885,D C Atomic Industrial Forum 80/05/27 12pp
- 8006030296 Forwards util 800513 comments on NUREQ-0654/FEMA-REP-1.
 "Criteria for Preparation & Evaluation of Radiological
 Emergency Response Plans & Preparedness in Support of
 Nuclear Plants" submitted in response to 800213 FR notice
 JURGENSEN.R W American Electric Power Co , Inc 80/05/20 15pp
- BOO6030393 Comments on proposed NUREO-0654, submitted by County of Orange, CA. Offic of Emergency Sycs Requirement for lay terminology inconsistent w/requirement for brevity TURNER, E B Affiliation Unknown PC-21 1 BO/05/27 3pp
- 8006030586 Comments on Draft 3 of NUREO-0660, "NRC Action Plans Developed as Result of TMI-2 Accident " Insufficient attention given to both general & special policy questions which require consideration in connection w/near-term OLs PLESSET.M S ACRS - Advisory Committee on Reactor Safeguards 80/04/17. Spp
- 8004030576 Comments on NUREQ-0440, Vol 4.ATWB resolution defined by Vol 3 is satisfactory for majority of plants in operation & under const BCHWDERER, F Westinghouse Operating Plants Gwners Group BLNRC 80-17 80/04/07 3pp
- --8006030613 Recommends manually initiated 86 gpm standby liquid control sys as solution to ATMB issue Basic approach should be to improve reliability of reactor scram sys JENS.W H Detroit Edison Co 80/04/03 4pp
- 8006040081 NUREO/CR-1392
 "Evaluating Strength & Ductility of Irradiated Zircaloy
 Task 5," quarterly progress rept, Apr-June 1979
 LOHRY, L. M., MARKHORYH, A. J., PERRIN, J. S. Battelle Memorial Institute,
 Columbus Laboratories FIN A-4068 BMI-2049 80/05/31 45pp
 Available at 0PD.
- 8006040086 NUREO/CR-1321
 "Final Rept Phase 1 Sys Interaction Methodology
 Applications Program."
 BOYD, C J , CRAMOND, W R , HATCH, S W Sandia Laboratories FIN
 A-1113 SAND 80-0384 80/04/30 211pp Available at GPO
- BOO4040098 NUREO/CR-0849 V4

 "Safeguards Matl Control & Accounting Program," Vol 4, quarterly rept Jul-Bept 1979

 DUNN, D R Lawrence Livermore Laboratory FIN A-0115

 UCRL-52715-79-4 80/05/31 24pp, Available at GPO
- 8006040101 NUREG-0660 V1 "NRC Action Plan Developed as Result of TMI-2 Accident," Vol 1 * Commission 80/05/31 350pp Available at GPO
- 800A040322 Forwards comments on Vol 4 of draft NUREG-0460, "ATWS for LWRs." W/o enc1 LQEWENBTEIN,W Electric Power Research Institute 80/05/27 ip
- 8006050427 Comments on proposed rule 10CFR50 evaluation criteria do not adequately address issue of Class 9 event Requests available info that deals w/specific problem of protecting infants
 GARRETT, E. G. Affiliation Unknown 80/04/01 Bpp.
- 8006060287 Forwards partial B&W response to NUREO-0578, Section 2.1 9
 Info documents that B&W program for inadequate core cooling
 provides for development of operator guidelines H/o encl
 CAFRA,R.A TMI-2 Bulletins & Orders 797/11/13 2pp

- BOOACACY2 Forwards Analysis Group recommendations in draft App VIII to NUMED-OA11. "Generic Evaluation of Feedwater Transients & Small Break LOCAs in Westinghouse Designed Operating Plants"
 ROSITOCZY, Z R THI-2 Bulletins & Orders. 79/12/07 1Opp
- 8006060524 Requests info re encl draft request for addl info required to complete evaluation of responses for power operated relief valve/safety valve actuation & reactor trip frequency CAPRA, R TMI-2 Bulletins & Orders 77/09/24 3pp
- BOO6060554 Discusses options for enforcing compliance w/NUREG-0578 requirement to LDFT pretest prediction of L3-1 ROSS,D Division of Project Management 79/11/05 App
- 8006090105 Comments on draft NUREO-0554 definition of "critical load" should be changed Differences between hoist drive motors should be explained GLAZIER.R E Affiliation Unknown 80/04/25 9pp
- 8004090119 NUREG-75/087 03 9 6

 SRP proposed Revision 2 to Section 3 9 6. "Inservice Testing of Pumps & Valves"

 # Office of Nuclear Reactor Regulation, Director PBRP-3 9 6 R2

 80/04/05 10pp
- BOOA090446 NUREO/CR-1452
 "Further Testing of Pocket-Bird Electronic Dosimeters"
 FOX,R A , HOOKER,C D , HOOAN,B T Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN B-21278 PNL-3364 80/04/3
- 8006090502 NUREO/CR-1462
 "Mechanistic Considerations Used in Development of PRDFIT
 PGI Fatlure Model "
 PANKASKIE,P J. Battelle Memorial Institute, Pacific Northwest
 Laboratory FIN B-2171-0 PNL-3386 80/05/31 80pp Available at
 NTIS
- BOOA090514 NUREO/CR-0641
 "SOURCE Convoy Ambush Simulation Code"
 BTINNEL, K G Sandia Laboratories FIN A-1173 GAND78-9034
 79/01/31 30pp Available at NTIS
- 9006090522 NUREC-0484 Ri
 "Mathodology for Combining Dynamic Responses "
 MATTUR R Division of Systems Integration 80/05/31 34pp
 Available at NTIS
- 8006110249 Provides review of NUREO/CR-1280, "Power Plant Staffing" & agress w/many recommendations Urges NIC work w/Inst for Nuclear Power Operations on new requirements HECCA, J E Puget Sound Power & Light Co. PLN-228 80/06/03 3pp.
- 8006110255 Requests extension to 800630 for response to NUREO/CR-12BQ, "Power Plant Staffing" published in 800424 FR Delay caused by numerous local union replies received & anticipated PILLARD,C H International Brotherhood of Electrical Workers 80/06/06 ip
- B006110366 Advises that Section 3 2 of NUREG/CR-1280 not completely true Personnel performing maint on UB Navy facilities not always nuclear trained but are normally tender or repair support personnel MILLER, L C Affiliation Unknown 80/06/04 6pp
- 8006120196 Provides Bubcommittee on Energy & Power w/NUREO--0619, "BWR Faedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking," for comment W/o encl FR notice encl. DENTON-HR Office of Nuclear Reactor Regulation, Director 80/05/22 ip.
- --8006120160 Notice of issuance & availability of NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return-Line Nozzle Cracking."
 EISENNUT.D 0 Division of Licensing 80/04/17 4pp
- 8006120189 Forwards formal comments on proposed NUREG-0684 FEMA-REP-1. NRC & FEMA have failed to recognize diversity of state & local goves Provision for assignments of responsibility should be identified as guidance, not for concurrence THOMAS, L. M. South Carolina, State of 80/05/16. Spp
- 8006120164 Provides Bubcommittee on Energy & Environ w/NUREG-0619: "BWR Feedwater Nazzle & Control Rod Drive Return-Line Nazzle Cracking:" for comment W/a encl FR notice encl. DENTON.H.R Défice of Nucleer Reactor Regulation, Director. 80/03/22. 1p.

8006120170 Provides Subcommittee on Energy & Environ w/NUREG-0619, "BWR Feedwater Nozzle & control Rod Drive Return-Line Nozzle Cracking," for comment W/o enci FR notice encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/22 ip

8005:20171 Provides Subcommittee on Energy & Environ w/NUREG-0619, "BWR Faedwater Noisle & Control Rod Drive Return-Line Noisle Cracking," for comment W/o encl FR notice encl DENTON.H R Diffice of Nuclear Reactor Regulation, Director 80/05/22

BOO6120269 Comments on Vol 4 of NUREO-0460 Vol 3 requirements provide adequate resolution of ATMS for most plants NRC concerns do not justify addl requirements contained in Vol 4 SCHMOERER, F. Standardized Nuclear Unit Power Plant Bystem Зрр

BOOA120277 Comments on NUREG-0667 NUREG should be issued as guide only & industry invited to originate own implementation details In alternative, NUREG should be made part of action plan ZUDANS, Z Franklin Institute/Franklin Research Center 80/04/30

BOO6120355 Informs that Commission paper is being prepared re proposed resolution of ATMS generic issue contained in NUREO-0440 ZECH, 9 Q. Technical Support Branch 80/05/15 ip

BOO6120469 NUREO/CR-1135
"Econometric Study of Electricity Demand by Mfg Industries "
CHANO-H B , CHERN-H S Oak Ridge National Laboratory, FIN B-0190-8
DRNL-NUREO/IM-3 80/05/31 63pp

8006120476 NUREG/CR-1422

Apalzu470 NOREW/UR142Z
**Analytic Rebalance Technique for Pressure Calculation in
Two —Phase Flow Sys **
MIAGLC C., BHAH,V L., KRAZINSKI,J L. Argonne National Laboratory
FIN-A-2045 ANL-CT-80-19 80/04/30 28pp

BOOA130057 Forwards notice of 800509 release of NUREC-0090, Vol 2, Number 4, consisting of 19th AO rept to Congress CHILK.S J. Office of the Secretary of the Commission 80/05/09

--8006130061 Notice of release of NUREO-0070, Vol 2, Number 4, Consisting of 19th AO rept to Congress
CHILK:8 J Office of the Secretary of the Commission 80/05/08

BOO6130070 Forwards notice of issuance & availability of NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." for publication in earliest possible FR CHILK, S J Office of the Secretary of the Commission BO/05/15

--8004130071 Notice of issuance & availability of NUREQ-0617. "BHR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking " Comments should be forwarded by 800707 EISENHUT, D Q Division of Licensing 80/04/17 3pp

8006160015 Submits comments on NUREO/CR-1280 re power plant staffing Lack of knowledge of civilian power industry shown by document. Hajor differences not shown in operation of Navy plant compared to civilian nuclear plant RHODES,F T Kansas Gas & Electric Co 80/06/07 4pp

BOO4140076 Responds to BO0401 request for add1 info re ACRS comments in BOO311 ltr concerning near-term UL items from Draft 3 of NRC Action Plan Appraisal of merit of referenced proposals will be possible only after deliberate study PLESBET M B ACRS - Advisory Committee on Reactor Safeguards 80/06/10 **2**00

8006160101 Comments on NUREQ-0667, "Transient Response of B&W-Designed Reactors " Expresses concern that recommendations in rept show continuation of NRC trend toward less flexibility in resolution of safety issues.

PLESSET.M 9 ACRS — Advisory Committee on Reactor Safeguards 80/06/10, 2pp.

BOO6160141 NUREO/CR-1287

"Independent Verification Testing Analyses of Alternatives for Conducting Independent Verification Testing of Environmentally Qualified Bafety-Related Equipment "BUNZON,L L Sandia Laboratories FIN 8-3097 BAND78-241180/05/31, 416pp Available at NTI8 BAND78-2411

8006160148 NUREC-0380 V4 NO5
"Program Bummary Rept." Vol 4, Number 5
* Office of Management and Program Analysis 80/05/23 100pp

8006160167 Comments on NUREG-0654 suggests some specific requirement for protecting transient population be included in regional emergency preparedness program DARLEY, V O Transportation, Dept of 80/05/07 4pp

BOO6170164 NUREO/CR-1120 V2
"Seismic Bafety Margins Research Program (Phase I),"
Progress Rept 6
BAILEY, B , SMITH, P D , CHOU, C K Lawrence Livermon
FIN A-0126 80/04/15 110pp Available at NTIS Lawrence Livermore Laboratory

8006170627 Responds to NUREO-0460. "ATWS for LWRs " Several inadvertent startups of HPCI sys at Peach Bottom will show higher impact when factored into EPRI value-impact analysis KEMPER.J B Philadelphia Electric Co 80/06/10 3pp

BOO6200054 NUREO-0694 Draft NUREO-0694, "TMI-Related Requirements for New OLs " * Commission 80/06/18 34pp

8006200227 Comments on proposed rule 10CFR50 properly organized early warning sys should address & include emergency broadcast sys ME Bureau of Civil Emergency Preparedness will develop plan compatible w/federal guidelines
MCORAIL.8 J Federal Emergency Management Agency 80/04/01 4pp

BOO6200518 NUREO/CR-1239

"MABFLD Computer Code to Calculate Mass Flow Rates in Thermal Hydraulic Test Facility"

WHITE, M D Oak Ridge National Laboratory FIN 8-025

DRNL/NUREO/TM-2 BO/05/31 34pp Available at NTIS

8006200524 NUREO/CR-i017
"Vulnerability Analysis of Mixed-Oxide Plant"
EASTER.K W. MALTERMANN.H A Monsanto Co ML
7pp Available at NTIS MLM-2691 80/05/08

8006200531 NUREO/CR-1305 DOSDOD31 NUREO/CR-1303 "Heavy-Section Steel Technology Program, Quarterly Progress Rept for Oct-Dec 1979 " WHITMAN O D. BRYAN,R H. Oak Ridge National Laboratory F: GRNL/NUREO/TM-3 80/05/31 105pp Available at NTIB

8004200532 NUREQ/CR~1021 OVORMODIZE NUMEW/CR~1021
"Models Beletted for Calculation of Doses, Health Effects &
Economic Costs Due to Accidental Redionuclide Releases
From Nuclear Power Plants "
STRENDE, D.L Battelle Memorial Institute, Pacific Northwest
Laboratory PNL-3108 80/05/31 189pp Available at NTIS

8006200535 NUREQ/CR-1397 JOAZO0535 NOREO/CR-1397
"Risk Methodology for Geologic Disposal of Radwoste Small
Sample Sensitivity Analysis Techniques for Computer
Models WApplication to Risk Assessment "
IMAN.R.L. CONOVER, U.J. CAMPBELL. J.E. Bandia Laboratori
A-1192 80/03/31 14ipp Available at NTIS Sandia Laboratories

8006200542 NUREQ/CR~1430 DESCOUNT NUMBER OF THE TRANSPORT OF THE STATE OF THE STAT 99pp Available at NTIS

8006200543 Comments on NUREQ-0662 & Addenda 1 & 2 reactor bldg atmosphere & Kr-85 should be released to atmosphere as soon as possible HEDEMAN.W N Environmental Protection Agency 80/04/11 3pp

8006200546 NUREG/CR-1368 "Development of Checklist for Evaluating Meint,Test & Calibr Procedures Used in Nuclear Power Plants "
BRUNE, R L, WEINSTEIN,M Sandia Laboratories FIN A8AN080-7053 80/05/31 200pp Available at NTIS FIN A-0252

800620054B "Capital Recovery of Nuclear Plant Decommissioning Costs " EWERS, B. J. Northern States Power Co. 80/03/31 100pp

8006200556 Forwards updated status of activities for B&W operating plants re bulletin evaluations, compliance w/long-term requirements of NRC 1979 orders & implementation of NUREG-0578 items TMI-2 Bulleting & Orders 79/10/29 10pp. CAPRA, R. A.

8006200563 NURFQ/CR-1389 uoazousos NuRED/CK-1989
"Estimating Mater Equivalent Snow Depth from Related
Meteorological Variables,"
STEVAERT.L.T , LEDUC.S K : STROMMEN.N D Commerce, Dept of, National
"Oceanographic & Atmospheric Adminstration. FIN B-1080 E0/05/31
48pp Available at NTIS

8006200583 HUREG/CR-1429
"Setemic Review Table "
SUBUDHI,M, REICH,M, KUPLIK,B Brookhaven National Laboratory FIN
A-3326 80/05/31 200pp Available at NTIS 8006260286 NUREG/CR-1114 206220286 NUREG/CH-1114 "Physical Protection of Nuclear Facilities," quarterly progress rept for Jul-Sept 1979 CHAPMAN.L D Sandia Laboratories FIN A-1060 SAND79-2060 79/12/31 26pp Available at NTIS 26pp 8006200588 NUREO/CR-1276
"User's Manual for LADTAP II - Computer Program for Calculating Radiation Exposure to Man from Routine Release of Nuclear Reactor Liquid Effluents "
91MPSGN,D B , MCGILL,B L Dak Ridge National Laboratory FIN A-9100 GRNL/NUREG/TDMC 80/05/31 325pp Available at NTIG 8006260421 NUREQ/CR-1078 "Investigation of Distribution & Entrainment of Emergency Control Ctr Hater Injected Into Upper Pienum" BARATHAN, D. RICHTER, H. J., WALLIS, G. B. Dartmouth College FIN A-4070 60/01/31 67pp 8006260424 NUREG-0435 Vi NO4
"Research Results Utilization," status summary rept, data as of 791015 6006200593 NUREQ/CR-1390 Probability Estimates of Temp Extremes for Contiguous US "
Probability Estimates of Temp Extremes for Contiguous US "
NICODEMUSM L. GUTTMAN.N B Commerce. Dept of. National Oceanographic
& Atmospheric Adminstration FIN 9-1028 B0/05/31 BOpp
Available at NTIS Office of Nuclear Regulatory Research, Director 79/10/15 85p 8006270002 NUREG/CR-1231 DOBZYCOUR NUMBER (R-123)
"Remote Sensing for Detection & Monitoring of Salt Stress on Vegetation Evaluation & Ouidelines," final rept Sept 1976 - Mar 1977
Mar 1977
Mar 1979
SHIPLEY, B. L., PAHWA, S. B., THOMPSON, M. D. INTERA Environmental Consultants, Inc. FIN 8-6205 80/03/31 108pp Available at 8006200597 NUREG-0674 "Security Personnel Training & Qualification Criteria" FLOYD, W. Office of Nuclear Material Bafety & Safeguards Ki Division of Safeguards 80/05/31 24pp Available at NTIS KERS. D 108pp Available at NTI 8006200598 NUREO/CR-1237
"Best-Estimate LCCA Radiation Signature "
BONZON, L Sandia Laboratories LURIE:N A IRT Corp FIN
A-1051-9 SAND79-2143 80/01/31 175pp Available at NTIS 8004270003 NUREG-0468 DO62740003 NUREO-0668
Draft "Staff Review of Radioecological Assessment of Hyhl
Nuclear Power Plant, Analysis of Rept Prepared by Univ of
Heidelberg, West Germany "
BRANAGAN,E F, CONCEL,F J, CARDILE,F P Division of Systems
Integration 80/06/30 128pp 800620060B NUREQ/CR-1154 V1 NO2 TBUR Blowdown Emergency Core Cooling," fourteenth quarterly progress rept Apr-June 1979
OALYARDI,D L Deneral Electric Co NRC-04-76-215 GEAP-21304-14
79/08/31 30pp Available at NTIS 8004270015 NUREG/CR-1080 "Quarterly Technical Progress Rept on Hater Reactor Gafety Programs Sponsored by NRC Div of Reactor Gafety Reasearch, Jul-Sept 1979"
YBARRONDO.L J Idaho Mational Engineering Laboratory FR 1979 " |L.J. Idaho National Engineering Laboratory FIN A-4038 | 79/10/31 44pp Available at NTIS 8006230011 NUREQ/CR-1343 206430011 NOMEWORKH-1342 "Qualification Testing Evaluation Program.LHR Safety Research.Quarterly Rept Apr-June 1979 " BONZGN.L L , CLOUGH.R L , OILLEN.K T Sandia Laboratories FIN A-1051-0 SANDBO-0276 80/04/30 42pp Available at GPO 8006270019 NUREQ/CR-1138 NOLLYOUIT NORMEYLE-1135 "Diffusion & Exhalation of Radon from U Tailings " SILKER: N B . HEABLER: P O Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2269 PNL-3207 79/10/31 103pp Available at NTIB 8006240099 NUREO/CP-0011 DO6240079 NURED/CP-0011 Errata sheet for Page 45 of NUREO/CP-0011, "Proceedings of Morkshops on Proposed Rulemaking on Emergency Planning for Nuclear Power Plants " # Division of Siting, Health & Safeguards Standards 80/05/21 800A270022 NUREQ/CR-1077 NO6270022 NUREO/CR-1077
"Frecharacterization Rept for Instrumented Nuclear Fuel
Assembly IFA-513 "
BRADLEY.E R., CUNNINGHAM.M E., DANIEL.J L. Battelle Memorial
Institute. Pacific Northwest Laboratory FIN 8-2043 PNL-3156
79/11/30 97pp Available at NTIS. 8006250171 NUREO/CR-0672 V1
"Summary of Technology, Safety & Costs of Decommissioning Ref
BUR Power Station." Vol 1.main rept
DAK.R D. HOLTER.O M. KENNEDY, W. E. Battelle Memorial Institute.
Pacific Northwest Laboratory 80/06/13 18ap 8006270026 NUREG-03R2
"Ninth Annual Decupational Radiation Exposure Rept.1976 "
Office of Management and Program Analysis 77/10/31 42pp
Available at NTTA 800424003B NUREQ/CR-058B "Analysis of Fuel Relocation for NRC/PNL Halden Assemblies
IFA-431, IFA-432, & IFA-913, " interim rept
WILLIFORD, R E. MONR, C L. LANNING, D Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-2707 80/04/30 83pp Available 8004270031 NUREO/CR-1091
"HIOR Safety Studies for Div of Reactor Safety Research
Quarterly Progress Rept.Apr-June 1979 "
BALL, B J , CLEVELAND. J C , CONKLIN, J C Oat Ridge Natic
Laboratory FIN B-0122 GRNL/NUREO/TM-3 79/11/30 2
Available at NT19 Oat Ridge National 3 79/11/30 26pp BOO6240041 NUREG/CR-1229
"Bibliography of Repts on Research Sponsored by NRC Ofc of Nuclear Regulatory Research, Jan-June 1979 "
BUCHANAN, J R Clak Ridge National Laboratory FIN 8-0126
DRNL/NUREG/NSIC 80/02/29, 121pp 8006270035 NUREO/CR-1154 VI NO2 NOBATIOUS NUMBER ER 1194 VI NUM "BNR Bloudous Emergency Core Cooling Fourteenth Quarterly Progress Rept. Apr-June 1979 " GALYARDT, D L General Electric Co NRC-04-76-215 GEAP-21304-14 79/08/31 22pp 8006260043 NUREO/CR-1412
"Bys for Continuous Measurement of Airborne Rn-222
Concentration & Working Level "
MOMENIAM H. ZIELEN, A J. MIRANDA, J. E. Argonne National Laboratory
FIN A-2207 ANL/E8-88 60/04/30 44pp Available at NTIS 8006270038 NUREG/CR-1217 "Central VA Regional Beismic Network Crustal Velocity Btructure in Central & Southwestern VA " BOLLINGER.G A , CHAPMAN.M C , MOGRE, T P Virginia Tech NRC-04-77-134 80/01/31 201pp Available at OPO 8006260045 NUREG/CR-1283

"Accounting Sys for SNM Control "

KORSTAD,P A Battelle Memorial Institute, Pacific Northwest
Laboratory FIN B-20149 PNL-3265 80/06/30 75pp Avai Available at 8006270044 NUREG/CR-1158 "Tonsile Properties of Irradiated & Unirradiated Welds of A533 Steel Plate & A508 Forgings." WILLIAMS, J.A. Hanford Engineering Development Laboratory D-0119 HEDL-THE 79-51 BO/01/31 38pp Available at 0PU 8006260048 NUREO/CR-1264 "Measurement of Aerosol Deposition Rates in Turbulent GIESEKE, JA, LEE, KW, GOLDENBERG, MA Battelle Memorial Institute, Columbus Laboratories FIN A-4078 BMI-2041 80/01/31 33pp Available at NTIS 800A270045 NUREQ/CR-1331 UNAX/OUGS NUMBER/CR-1331 "Data Summaries of LERs of Control Rods & Drive Mechanisms at US Commercial Nuclear Power Plants." Jan 1972-Apr 1978 HUBBLE,W H , MILLER.C F EO&O Idaho, Inc FIN A-6276 E00 80/02/27 412pp Available at NTIS

8006260053 NUREO/CR-0849 VI

"Safeguards Mat Control & Accounting Program," quarterly rept.Oct-Dec 1978
DUNN, D. R. MAIMONI.A Lawrence Livermore Laboratory FIN A-0115
UCRL-52715-79-1 B0/06/30 B3pp Available at NTIS.

E00-EA-5079

8006270060 NUREG-0256 "Methods for Accountability of Mixed Oxide " * Commission NRC-13 77/04/30 84pp Available at NTIS

8006270065 NUREG/CR-1111 "Bovelopment of Fabrication Procedure for HRBT Fuel Simulator Based on Use of Cold-Pressed Boron Nitride Preforms

Preforms " W . JACOBB.P T . CLARK.D L Gak Ridge National DRNL/NUREG/TM-3 80/03/31 149pp Available Available at NTIB

8006270073 NUREO/CR-1354
"Microprocessor Base6 Underwater Data Acquisition Sys "
HOHELL.0 L Florida, Univ of, Qainesville UFL/COEL/TR/038
BO/03/31 122pp

8006270097 NUREO-0307

"Review & Assessment of Research Relevant to Design Assects of Nuclear Power Plant Piping Sus." final rept

P Division of Reactor Safety Research MAXEY.W A . EIBER.R J
Battelle Mamorial Institute. Columbus Laboratories AT(49-24)-0293

NRC-5 77/07/31 475pp Available at NTIS

BOO627026B Comments on proposed actions for resolution of ATMS in NUREG-0460, Vol 4. NRC should initiate rulemaking to determine need for & form of any licensing requirements for ATMS Supports AIF positions presented in IC Globs 800527 ltr OWEN. W H Duke Power Co 80/06/20 3pp

8006270344 NuREO/CR-1263
"Compilation of State Laws & Regulations on Transportation of Radioactive Matls "
BAILEY.J . JEFFRIES: C Federal-State Reports, Inc 80/01/31 200pp

8006270349 NURFQ/CR~1369

Procedures Evaluation Checklist for Maint, Test & Calibr Procedures "
MEINSTEIN.K , BRUNE, R. L. Human Performance Technologies, Inc.
Bandia Laboratories FIN A-0252 SAND80-7054 80/05/31 2

8006270362 NUREO/CR-0829
"Measurement Control Program for Nuclear Matl Accounting "
BROUNS,R J. ROBERTS,F P., MERRILL, J.A. Battelle Memorial Institute.
Pacific Northwest Laboratory. FIN 8-20149 PNL-3021 80/06/30
70pp Available at NTIS

8006270398 NUREO/CR-0930 V2
"Puncture of Shielded Radioactive Matl Shipping Containers
Static & Dynamic Tests of Laminated Plates "
LANDER, A , ARTHUR, D F Lawrence Livermore Laboratory F
A-0127-8 UCRL/52638 80/04/30 43pp Available at NTIS

8006270401 NUREO/CR-1446
"Preparation of Working Ref Matls U Dioxide"
HANDLR L , SPRAKTES, F W., BALDWIN, J M Allied Chemical Corp. FIN
A-60338 80/05/31. 46pp Available at NTIS

BOO6270420 NUREO/CR-1143

"Considerations in Small Scale Modeling of Fool Swell in BWR Containments"

HUBER, P W, SONIN.A A. ANDERSON, W G Massachusetts Institute of Technology FIN 8-6167 79/11/30 86pp /

B0Q6300027 NUREG-0442

D08300027 NURED-0442
"Technical Rept on Operating Experience w/BWR Offgas Bys "
"Technical Rept on Operating Experience w/BWR Offgas Bys "
LO.R. Environmental Evaluation Branch GRIMES,B Assistant
Director for Systems Engineering (Pre 791030) EISENHUT.D Division
of Operating Reactors 78/04/30 37pp Available at NTIS

BOOGSOOGS NUREO/CR-1120
"Seismic Safety Margins Research Program (Phase I),"
quarterly Progress Rest 5.771015.
BAILEY,R D. SMITH,P.D., CHOU,C K Lawrence Livermore Laboratory
FIN A-0126 BO/01/31 87pp Available at NTIS

BOOA300069 NUREO/CR-1243
"Methods to Assess Impacts on Hudson River Striped Bass Rept for Periad Oct 1977-Sept 1979."
BARNTHOUSE, L. W. CHRISTENSEN, B. W. KIRK, B. L. Oak Ridge National Laboratory FIN B-0165 ORNL/NUREO/TM-0 80/05/31 37pp Available at NTIS

8006300071 NUREG/CR-1072

"Advanced Two-Phase Flow Instrumentation Program Quarterly
Progress Rept for Apr-June 1979 "
TURNADE, K G. DAVIS.C E. Cak Ridge National Laboratory. FIN 8-0401.
ORNL/NUREO/TM-3. 79/11/30. 26pp Available at NTIS

8004300085 NUREG/CR-1242

JOSSICOUS NUREO/CR-1242
"Methods to Assess Impacts on Hudson River Whits Perch Rept for Period Oct 1978-Bapt 1979 "
BANNTHOUSE:L W , KIRK. B L., KUMAR. K D Dak Ridge Mational Laboratory FIN 8-0423 ORNL/NUREO/TM-3 80/05/31 44pp Available at NTIS

0SE0-03RUN 16000E9008 ovosyodyn Nuked-0320 "Interior Intrusion Alarm Sys " PRELL:J A Safeguards Standards Branch 78/02/28 45pp Available

9004300102 NUREG-0282

006300102 NUREG-0282
"Some Aspects of Fuel Motion in Unprotected Transient
Overpower Accident in LKFBRs "
Division of Project Management JOHNSON,M B ; ERDMAN,C A
Virginia, Univ of AT(49-24)-0158 77/06/30 26pp Available at
NTIS

8006300122 NUREG-0303 "Evaluation Behavior of Waterlogged Fuel Rod Failures in SEIGEL, B Reactor Systems Branch 78/03/31 26pp Available at

8006300127 NUREG/CR-1206
"Critical Pathways of Radionuclides to Man from AgroEcosys:" annual progress rapt for Oct-Sept 1979
SMITH,M H. ALBERTBI, J. ADRIANO,D C. Savannah River Ecology
Laboratory FIN B-4124 79/01/31 38pp Available at NTIS

8006300130 NUREO-0286
"Study of Reactivity Effect of Bubble Collapse in Molten
Liquid Metal Cooled Reactors"
Division of Project Management SHEAKS.O J. MUNNO.F J
Maryland. Univ of AT(49-24)-0186 77/08/31 62pp Ava
NTIB Available at

BOO630019B NUREO/CR-1315

"Feasibility of Field Evaluation of Physical Protection
Procedures" ROVOS/31 74pp Available at NTIB

8006300247 NUREO-0668
"Summary of NRC Review of 'Radioecological Assessment of Wyhl Nuclear Power Plant,' Rept by Univ of Heidelburg, West rmany " Office of Nuclear Reactor Regulation, Director 80/06/30 15pp

8006300250 Advises that B&W LOFT pretest calculations required by Section 2 1 9 of NUREO-0578 are scheduled to begin 791115 CAPRA.R A TMI-2 Bulletins & Orders 79/10/17 2pp

8006300256 NUREC-0668

06300256 NREG-046B
"Staff Raview of 'Radioscological Assessment of Huhl Nuclear
Power Plant,' Analysis of Rept Prepared by Univ of
Heidelberg:West Germany: " draft rept
BRANAGAN.E F, COMOEL,F J , CARDILE,F P Assistant Director for
Environmental Technology 80/06/30 175pp.

8006300298 ORNL/DEPA-4
"Stds & Guidelines Pertinent to Development of
Decommissioning Criteria for Sites Contaminated H/
Radioactive Matl "
DICKSON,H W Oak Ridge National Laboratory UC-70 78/08/31

8006300497 Notice of availability of proposed revision to SRP Section 3 9 6, "Inservice Testing of Pumps & Valves," & addition of App A to SRP Section 3 9 6. "Leak Testing of Pressure Isolation Valves " Comments requested by 800801.

MATTSON,R J. Division of Safety Technology 80/04/18 2pp

8006300506 NUREG/CR-1363 VI
"Data Bummaries of LERs of Valves at UB Commercial Nuclear Power Plants," Vol 1 main rept. Jan 1976-Dec 1978
HUBBLE,N H EG&G Idaho, Inc MILLER, C F EG&G, Inc FIN A-6276
EGG-EA-5123 80/06/30 165pp. Available at NTIB

--8006300514 NUREO/CR-1363 V2
"Data summaries of LERs of Valves at UB Commercial Nuclear Power Plants," Vol 2.Apps A-N, Jan 1976-Dec 1978 HUBBLE,W H EG& Idaho, Inc MILLER,C EQ&G, Inc FIN A-EQC-EA-5125 80/06/30 312pp Available at NTIS FIN A-6276

---8004300520 NURE9/CR-1343 V2 Q-Y
"Data Summaries of LERs of Valves at U8 Commercial Nuclear
Power Plants," Vol 3:Apps Q-Y:Jan 1976-Dec 1978
HUBBLE,W H E0&Q Ideho:Inc MILLER,C E0&Q, Inc. FIN AE00-EA-5125 80/06/30 447pp Available at NTIS Inc. FIN A-6276

CORRESPONDENCE WITH OTHER ORGANIZATIONS

ORG

8006030098 Concurs w/800324 drafts of FR notices re cleanup stds for inactive U processing sites Also concurs w/recommendation for immediate issuance of interim cleanup stds MARTIN. J B Division of Waste Management WM-80-131 80/04/02 in

B006040093 ANL/RAS/LWR 80-2 "Transient Critical Heat Flux & Blowdown Heat Transfer Studies" LEUNG, J C Argonne National Laboratory LEUNG, J C Northwestern Univ B0/04/30 482pp

8006050027 Discusses proposed atd re-rules for const for reactor coolant pump motor frames when used as intervening elements in ASKE support load paths BROWN.E J Director's Office N551 7-80-1 80/05/22 ip

BOO6050424 Summarizes info submitted to NRC in response to IE Bulletin 79-17 re pipe cracks in stagnant borated water sys at PWR plants BROWN.E J Director's Office IEB-79-17 80/05/22 ip

8006130073 Forwards notice of availability of IAEA draft safety guide for public comment for earliest possible publication in FR CHILK.S J Office of the Secretary of the Commission 80/05/15

--8006130075 Notice of availability of draft IAEA safety guide for public comment Comments received by 800701 will be useful for evaluation prior to next discussion MINGOUE, R B Office of Standards Davelopment, Director 80/05/12 200

8006160214 DDE/NE-0003/1
"LHRs," Vol 1 of 7, preliminary safety & environ info document for nonproliferation alternative sys assessment program
* Energy, Dept of 80/01/31 200pp Available at NTIS \$9 50

--8006160218 DDE/NE-0003/2

"Heavy-Water Reactors," Vol 2 of 7, preliminary & environ info document for nonproliferation alternative systems assessment program & Energy, Dept. of 60/01/31 150pp Available at NTIS \$7 25

--8006160221 DDE/NE-0003/3
"Light-Water Breeder Reactors," Vol 3 of 7, preliminary safety & environ info document for nonproliferation alternative sys assessment program # Energy, Dept of 80/01/31 170pp Available at NTIS \$9 00

---8006160222 DDE/NE-0003/4

"High-Temp Oas-Cooled Reactors," Vol 4 of 7 preliminary safety & environ info document for nonproliferation alternative sys assessment program

* Energy, Dept of 80/01/31 200pp. Available at NTIS \$9 50

--8006160226 DDE/NE-0003/5

"Qas-Cooled Fast Reactors." Vol 5 of 7.preliminary safety & environ info document for nonproliferation alternative sys assessment program
Energy.Dept of 80/01/31 120pp Available at NTIS \$6 50

--B006160228 DDE/NE-0003/6

"LMFBR," Vol 6 of 7, preliminary safety & environ info document for nonproliferation alternative sys assessment program

Energy, Dept of 80/01/31 120pp Available at NTIS \$6 50

---8006160230 DGE/NE-0003/7
"Fuel-Cycle Facilities," Vol 7 of 7.preliminary safety & environ info document for nonproliferation alternative sys assessment program # Energy, Dept of. 80/01/31 150pp Available at NTIB \$8 000

8006160239 Advises of formation of Bafety Data Integration Oroup to identify responsibility & cognizant managers in coordination concept similar to SECY-80-35A Hopes to reduce industry uncertainty described in TMI Action Plan MATTSON,R J Division of Safety Technology 80/05/28 2pp

--8006160235 Requests recommendations re min set of plant status/safety parameters & unique characteristics which should be available for display, display capability & whether reactor yendor should be included AIF 800423 ltr encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/05

--8006160236 Ferwards recommendations on reactor plant data display, evaluation & related activities developed by AIF Subcommittee on Safety Parameter Integration per 800502 ltr to H Denton HUNELL, B H Atomic Industrial Forum 80/05/20 16pp

8006170709 Hemorandum & order on UCS 771104 petition for remedial relief re fire protection of electrical cables & environ qualification of electrical components Reaffirms Commission 780413 decision re possible shutdown of operating reactors CHILK.S J Office of the Secretary of the Commission CLI-B0-21 80/05/23 26pp

8006200123 Advises that IE Circular 80-0B, "BMR Tech Spec Inconsistency "Ractor Protection Sys Response Time," was sent to listed utils on 800418 CARROLL, D.E. Region 3, Chicago, Office of the Director 80/04/25

8006230108 Forwards atd order for DDE work, "Utilization of Atmospheric Release Advisory Capability (ARAC) " RYAN,R O Office of State Programs, Director 80/06/06 ip

--8006230136 8td order for DOE work: "Utilization of Atmospheric Release Advisory Capability (ARAC):" issued to LLL RYAN.R O Office of State Programs. Director FIN A-0351-9 BO-BO-009 80/06/06 ip

8006230046 Notification of 800611 meeting w/DRNL in Bethesda, MD to discuss thermal hydraulic test facility test results of bundle uncovery & recovery testing & upflow film boiling test HUAND, T.L. Core Performance Branch

8006300341 Forwards draft functional requirements for proposed safety monitor console techincal support ctr.emergancy offsite factity & nuclear data link.as discussed in 800520 meeting MATTSON.R J Division of Safety Technology, 80/06/09. 31pp

PR PROPOSED RULE

7710310452 Comments on proposed rules 10CFR70 & 73 application of safeguards upgrade rule would have visibly adverse impact upon research programs conducted by nonpower reactors.

HOBSON, T.W. California, Univ. of, Los Angeles, 79/09/28 2pp

8005080228 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 40 & 70endorses Util Waste Mgt Oroup & EEI comments Greatest
concern w/proposed rules is potential for lack of
consistency between info presented & dacistons made,
BARTLETT, J W Affiliation Unknown 80/03/05. 7pp

8005130510 Calls attention to BC Court of Appeals decision re NRC role in proposed rulemaking on radwaste storage & disposal NRC reliance on other parties re development of adequate record, rejected HANSELL.D Illinois, State of 80/04/09 2pp.

8005220614 Comments on proposed rules 10CFR2, 30, 40, 50, 51, 70 & 110 questions effectiveness of uniform procedures designed to ensure consideration of onviron values & concerns OILMARTIN, D J Reilly & Like. 80/05/01 6pp.

B003220680 Comments on proposed rules 10CFR19,30.40,50,70.71 & 150 phone number & address should be listed on NRC Form 3 to provide confidentiality w/o fear of reprisal for amployees supplying NRC w/info.

LEWIS,M I Affiliation Unknown 80/04/19 3pp

BD05280706 Comments on proposed rules iOCFR19,30,40,50,70,71 & 150.rule will encourage workers to give info on antitrust, safety & security matters which is irrelevant & breeches confidentiality of proprietary matters HEGRAW, R E Bio-Dynamics, Inc (subs. of Boehringer Manheim Corp). 80/04/21, 1p

8005280231 Comments on proposed rules 10CFR19, 30, 40, 50, 70, 71 & 150 questions need for proposed regulations re-protection of amplayees who provide info DURHAM, J W Portland General Electric Co 80/05/09 Gpp

8005280885 Forwards comments on proposed rules 10CFR2,30,40,50,51,70 & 110 CEQ 800320 ltr & Environ Law Inst 800404 rept. "NRC Environ Analysis of Nuclear Accidents Is it Adequate." enci. SHEAJ F Council on Environmental Quality. 80/03/25. ip

- B003300283 Comments on proposed rules 10CFR20 & 50 10CFR50 72(a 6) should be clarified to permit plant operation pursuant to Tech Specs w/o requiring that repts be sent to NRC COUNSIL,W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/08/02 2pp
- 8004020004 Discusses 800418 comments by C McClure of Bechtel Corp re proposed rule 1007R72 Standardized structural design basis is reasonable approach Related wording should be clarified MINOQUE,R B Office of Standards Development, Director 80/05/07
- 800602006B Comments on proposed rule 10CFR19 objectives of holding mesting w/licensee representatives during NRC insp cannot be met w/o free & frank discussion Licensees may be hesitant to speak freely w/third party present
 BUMPTER.J R Houston Lighting & Power Co 80/05/09 4pp
- 8006020091 Comments on proposed rule 10CFR19 should clarify that right of NRC to inspect licensee matis activities. Facilities, premises & records does not extend to NRC invitees PEOPLES.D Commonwealth Edison Co. 80/05/05
- 8006020325 Order granting extension until 800707 to file statements of position, 800905 for cross-statements & 801006 for suggestions on scope of further rulemating proceedings restorage & disposal of radwaste MILLER.M E Atomic Safety and Licensing Board Panel 80/05/29
- 8005020477 Memorandum & order establishing working group to address NRDC & CA Energy Commission 800214 & 20 motions re proposed rulemaking on storage & disposal of radwaste Denies requests for Commission action contained in same motions

 CMILKS J Office of the Secretary of the Commission 80/05/28 Ann.
- 8006020340 Comments on proposed rule 100FR40, supports deletion of source mati medicinals from general license for small quantities of source mati when medicinals are carinogenic & no longer recognited as useful by medical community GREENBERG, R B Affiliation Unknown 80/05/02 1p
- 8006030050 Comments on proposed rule 10CFR50 outlines questions re evacuation plans for local govts within ten miles of power plants HOUCHIN-S Affiliation Unknown 80/04/14 ip
- 8008030071 Comments on proposed rule 10CFR19 requirements seam directed toward radiological working conditions but no such conditions exist during const or LWA phases of nuclear gower plant Serious confusion could result KOCH.L.J. Illinois Power Co. U-0140 80/05/12 2pp.
- 8006030077 Comments on proposed Trule 10CFR61: tenth objective should be added to define de minimus concentration of radioactive matl Some low level radwaste would present no undue hazard disposed of in landfill HOFFMAN.D P. Consumers Power Co 80/05/05 3pp
- 8006030092 Comments on proposed rule 10CFR50.vulnerability of nuclear power industry is increasing. Utils are more dependent upon politics to less upon good mgt to safety measures Politicizing process will doom nuclear development RORABACHER, J. A. Affiliation Unknown 80/02/18 Spp.
- B006030076 Comments on proposed rules 100FR19.30,40,50.70,71 & 150 objects to NRC involvement in antitrust actions or general safety conditions Business & industry are checked, investigated & inspected by more than enough agencies BETZLER,M.F. Jones & Laughlin Steel Corp (subs of LTV Co) B0/03/25 ip
- 8006030102 Comments on proposed rules 10CFR19,30,40,50:70.71 & 150-duplication of existing regulation not in best interests of taxpayer & runs counter to elimination of wasteful practices in govt. Regulation should be withdrawn SOMERB: C E United Nuclear Corp., UNC Recovery Bystems Div 80/03/31 2pp
- 8006030127 Comments on proposed rules iOCFR19,30,40,50,70,71 & 150.NRC should stick to attempting to protect individuals who legitimately notify NRC of radiation problems before expanding responsibility.

 HUBBARD, L B Cook County Hosp Chicago, IL 80/03/31 1p
- 800&030130 Comments on proposed rule 10CFR&1 regulations should state requirements that would provide reasonable assurance of low level watte confirmment Reg guides to provide guidence would therefore be unnecessary PARKER.N.O. Duke Power Co. 80/04/14 Spp

- BOO6040003 Forwards comments on proposed rule 10CFR19 proposed rule unnecessary & will not achieve intended objective NRC has not demonstrated need for rule Legitimate interest std is too broad & subj to unintended abuse REARNEY, J Edison Electric Institute BO/05/12 13pp
- BOO60400007 Comments on proposed rules 10CFR2,30,40,50,51,70 & 110 util currently reviewing proposed amends re environ protection for damestic licensing & related regulatory functions Comments to be submitted by BOO51& MILLS.L M Tennessee Valley Authority 80/04/30 1p
- 8006040012 Comments on proposed rules 100FR19.30,40.50,70.71 & 150 on behalf of MS Gas & Electric Supplementary info for proposed regulation fails to follow statutory language & Dapt of Labor regulations
 BILBERG, J E Shaw. Pittman. Potts & Trowbridge 80/05/05 4pp
- 8008030080 Order granting extension until 800707 for States of MN.WI.SC & others to file statements of position until 800905 to file cross-statements & until 801006 to file suggestions renature & scope of further proceedings
 MILLER.M E Atomic Safety and Liconsing Board Panel 80/05/29
- 8006050427 Comments on proposed rule 10CFR50 evaluation criteria do not adequately address issue of Class 9 event Requests available info that deals w/specific problem of protecting infants
 OARRETTLE O Affiliation Unknown 80/04/01 Spp
- 8006050447 Motion by CA Agencies for 60-day extension or until 800731 for scheduling first phase of proposed rulemaking proceeding re-storage & disposal of radwaste Proposes alternative individual extension if first phase is not extended URBAN.M., GREW.P. California, State of 80/05/20 3pp
- --8006050453 Confirms CA Energy Commission 800220 ltr expressing concerns re-procedures used in proposed rulemaking proceeding re-storage & disposal of radwaste Urges personal attention Certificate of Svc encl VARANINI.E E California, State of 80/05/13 7pp
- 8006050458 Reply taking no position on State of MN request for 60-day extension of procedural dates re proposed rulemaking on storage & disposal of radowste Opposes alternative relief re individual extension Certificate of Bvc encl KNOTTS, J B Atomic Industrial Forum KNOTTS, J B Debevoise & Liberman 80/05/15 7pp
- 8008000465 Response taking no position on States of MN.HI.IL.MO.HI.LA.
 CH.VT & BC motions for extension of schedule for first phase
 of proposed rulemaking proceeding re storage & disposal of
 radwasts Opposes individual extension M/Certificate of Svc
 BROWN.O.F., COLEMAN.L R. MCGOVERN.K S Energy.Dept of 80/05/21
 7pp
- 8006050487 Resourse in support of State of MN motion for extension of schedule dates for first phase of proposed rulemaking proceeding re storage & disposal of radwaste HANSELL, D Ilinois, State of HANSELL, D Hawaii, State of 80/05/14, ip
- BOO6090494 Notice of change of name & answer in opposition to States of MN & WI motions for extension of schedule dates for first phase of proposed rulemaking proceeding re storage & disposel of radwaste Certificate of Svc encl BAUSER:M A. Edison Electric Institute BAUBER:M.A. Lowenstein:Newman:Reis.Azeirad & Toll 80/05/16 9pp
- 8004050543 Comments on proposed rule 100FR20 only rationale on which NRC should mandate QA program is to ensure programs are capable of demonstrating compliance w/regulatory stds & provide measure of effectiveness SLASECK, L A Affiliation Unknown 80/04/17 3pp
- BOO6060116 Comments on proposed rules 10CFR20 & 50 if all NRC reporting requirements could be streamlined & addressed in one document, implementation would be easier & current confusion would be eliminated.

 WHITAKER, H B South Carolina Electric & Gas Co 80/05/08 2pp
- BOOA060119 Comments on proposed rules 10CFR20 & 50 supports proposal w/reservations re unnecessary duplication of reporting requirements Bome type of integration should be instituted between existing requirements MILLS.L M Tennesses Vailey Authority. BO/05/06. 2pp

- BOD6060138 Comments on proposed rule 10CFR19 refs to worker representatives & contractors should be clarified Licensee should be advised of invitees prior to meeting Present sys is workable & preferable to change FLYNN, J D Cincinnati Gas & Electric Co 80/05/09 2pp
- 8006060145 Comments on proposed rules 10CFR2,30,40,50,51,70 & 110 has reservations re alternatives & independent EIB Critical element of NEPA process is lost if NRC limits licensing function to approval or denial of applications
 HEDEMAN.W N Environmental Protection Agency 80/05/05 2pp
- BOOA050150 Comments on proposed rule 10CFR19 concurs w/concept of cadifying meeting procedures Regulations should not be modified to invite individuals w/o licensee prior agreement DIPIAZIA: R P Hestinghouse Electric Corp. WRD-LA-119 80/05/ 80/05/12
- 8004040154 Comments on proposed rules 10CFR19,30,40,50,70,71 & 150 proposal should be abandoned unless significant evidence is advanced re-protection of employees who provide info HUGAN, J P General Atomic Co (subs of Gulf Uil Co) 80/05/08
- 8006040167 Comments on proposed rule 10CFR20 prefers option re unspecified lab because operation would be free of cyclic federal govt budget & manpower constraints Major concern is credibility of certifying lab. BLABACK
- 800&040393 Response in support of State of MN motion for extension of proceeding schedule re first phase of proposed rulemaking on radwaste storage & disposal. Certificate of Svc encl LOWERRE, R W Texas. State of 80/05/21 5pp.
- 8006090007 Comments on proposed rule 10CFR19 interested parties & consultants should not take part in discussion of tentative findings but be included in meeting at end of insp to review insp findings

 AVRUTIKAR F Affiliation Unknown 512-80 80/05/09 ip
- 8006090010 Comments on proposed rule 10CFR20 independent certification lab under contract to NBS would be viable working relationship Recommends caution in any changes of ANSI Std WHEELER, R V , LANDAUER, R 8 Affiliation Unknown. 80/05/08 1p
- 8006070060 Comments on proposed rule 10CFR19, on behalf on Puget Bound Power & Light Co & IA Electric Light & Power Co. Proposal is acceptable if amended to recognize right of parties to oppose outsiders' attendance at meetings
 BAUBER: M A Lowenstein, Neuman, Reis, Axelrad & Toli 80/05/12 4pp.
- 8006090061 Comments on proposed rule 10CFR31 supports regulation review of alternative sites for nuclear power plants Local residents must have voice in matter JONES.C. Affiliation Unknown 80/05/14 ip
- 8006090075 Comments on proposed rule 10CFR170; objects to blank check approach to license fee assessments GA program separate from application for approval of shipping package is of no benefit BCHENDEL, K.R. Wyoming Mineral Corp. REP-80-241. 80/04/29 2pp
- 8006090087 Comments on proposed rule 10CFR19 no objections to mgt & NRC inspectors having meetings during or following insp.
 Inspectors should not be permitted to invite outside guests
 SIECK,P E Ohmart Corp 80/05/16 2pp
- 8006090092 Comments on proposed rule 10CFR73 fact that vital area access shall be positively controlled precludes need for serially numbered badges w/authorization codes. Criteria for authorization should be satisfied prior to sitering area UHRIG,R E Florida Power & Light Co L-80-134. 80/05/15 ip
- 8006090096 Comments on proposed rule 10CFR20 new regulations should include some techniques for introducing rational changes MCCLINTOCK, J.T. Affiliation Unknown, 80/09/15 2pp
- 8004070101 Comments on proposed rule 10CFR20 public does not have proper protection in event of severe accident when existing monitors cannot measure amount of radiation released WARREN, 8 K Affiliation Unknown, 80/05/14, 1p.
- 800609010B Comments on proposed rule 10CFR19 inspectors should not be permitted to invite outside gueste due to possibility of physical security plans & facility procedures being discussed in public forum KNUTH, D F KMC, Inc. 80/05/27. 4pp

- 8006090114 Comments on proposed rule 10CFR19 supports continuation of having informal conferences between applicants licensees & inspectors Introduction of third parties could change conference to adversary proceeding HOWELL.S H Atomic Industrial Forum 80/05/27 2pp
- 8006090531 Comments on proposed rule 10CFR73 existing regulations property implemented provide high degree of assurance against industrial sabotage by insider BRYAN.J K Union Electric Go 80705/15 ip
- 8006070987 Comments on proposed rule 10CFR20 radiation sources should be chosen to closely match radiation received by worker Processor should only be required to pass those categories of radiation for which legal records are provided BEER.J L Consumers Power Co 80/05/20 ip
- 8006i10060 Commants on proposed rules 10CFR50 & 51 schedule of initial phase of waste confidence rulemaking proceeding should be extended 60 days Concurs w/States of WI & MN motions to enable participants to review documents filed by DOE VANCE.R L Virginia. State of 80/05/27 9pp
- 8006110087 Forwards notice of withdrawal of appearance & substitution of counsel re proposed rulemaking on storage & disposal of nuclear waste Certificate of Svc encl SANGER. H S Tennessee Valley Authority 80/05/28 7pp.
- 8006110164 Response in support of State of MN motion for extension of schedule dates of first phase proceeding re-proposed rulemaking on radwaste storage & disposal Certificate of Svc MACARTOR, J. D. Delaware, State of 80/05/20, Spp.
- 8006110224 Notices of appearance in proceeding Certificate of Svc encl. BIBHOP,L.L. JORDAN,W.S. New England Coalition on Nuclear Pollution BIBHOP,L.L., Sheldon, Harmon & Weise 80/05/29 7pp
- BOO6110406 Memorandum in support of State of MN motion for 60-day extension of schedule dates re proposed rulemaking on radwaste storage & disposal NRC delay of core bibliography filing was not anticipated W/Certificate of Svc.
 MUCHNICKI.E D., BROWNIH J Ohio, State of. 80/05/14 10pp
- 8006110454 Comments on proposed rule 10CFR20 on behalf of TX Utils Cenerating Co consideration of possible accidents, different from those previously evaluated heads limiting language to control litigation & speedup amend processing. REYNOLDS:N 8 Debevoise & Liberman 60/05/27 8pp
- BOO6110465 Comments on proposed rules 10CFR2 & 50 NRC has developed two-pronged practice that frustrates public participation & is inconsistent w/Gongressional intent Utils are encouraged to wait until OL review for post-hoc approval of mods WEISB.E.R Union of Concerned Ecientists WEISB.E.R, Natural Resources Defense Council, WEISB.E.R, Sheldon, Harmon & Weiss GO/05/23 lipp.
- 8006110466 Comments on proposed rule 10CFR20 dosimetry processor certification should be performed by non-NRC regulated lab Private nonprofit lab or govt lab operated by NBB would minimize further govt expansion.

 KIRK.W.F. United Nuclear Corp., Naval Products Div NIS-80-5-35 80/05/21.
- 8006:10471 Comments on proposed rule 10CFR73 balance is needed between operational necessity & administrative burden of validating need for access each time entry is afforded Util believes physical security plan provides balance'
 CAMILL.W.J. Consolidated Edison Co. of New York 80/05/23 2pp
- BOO6110475 Comments on proposed rule 10CFR20 following areas should be addressed x-rays, radiographic work, hot cells radiopharmacy & nuclear steam generator stations Baseline calibr sources should be established. OA is prime raquisite BRICHT, R. M. Florida Power Corp. 80/05/20, 2pp.
- 8006110477 Comments on proposed rules 10CFR20 & 50 operators will be distracted from prime directive of plant operation to insure host of events are reported to NRC operations ctr Unly events requiring immediate actions should be reported, HUNTER.R.B Indiana & Michigan Electric Co IEIN-80-06 80/04/29
- 8006i1048i Comments on proposed rule iOCFR20 reg guide should be developed rather than rule or regulation Reg guide would give small "in house" sycs flexibility needed & hold line on large vendors. HOLEMAN, O R Yale Univ 80/05/23 2pp

- BOO6:10487 Comments on proposed rule 10CFR19 rule needs clarification, narrowing language to specify when informal meetings can be held, extent of participation by parties outside NRC & licensee & requirements for add1 participants HOFFMAN, D P Consumers Power Co. 80/05/19 ip
- 800&i10488 Comments on proposed rule 10CFR&O definition of disposal should mean emplacement w/o intent to retrieve for any reason Other editorial changes suggested for clarity Emphasis should be on site characteristics OUIST.A S Affiliation Unknown 80/05/21 2pp
- BOO6110492 Comments on proposed rule 10CFR19 practical difficuties could arise re untrained participants in inspeceetings Clarification of participant qualifications & concurrence of other party will facilitate resolution of insp findings HORNBERGER.K D Affiliation Unknown 80/05/13 ip
- 8006120008 Forwards comments on proposed rules 10CFR2,30,40,50,51,70 & 110 SCOT,W J Illinois, State of 80/05/22 1p
- --BOO6120019 Comments on proposed rules 10CFR 2,30,40,50,51,70 & 110 NRC should make worst case analyses to make reasoned choices among alternatives Class 9 accidents must be investigated & analysed for specific sites SCOTT.N J Illinois, State of BO/05/22 3pp
- 8006120013 Comments on proposed rules 10CFR19.30,40,50,70,71 & 150 provisions imposing civil penalties on licensees for actions of contractors or subcontractors should be clarified or deleted Hod needed to protect amplayer.

 GIBES.D C Atomic Industrial Forum 80/05/21 2pp
- BOO6120104 Comments on proposed rules 10CFR2.30.40.50.51.70.110 rule does not identify procedures for identification evaluation & protection of historical or archaeological properties affected by NRC licensing Responsibility is neglected DINEAUIE.D F Affiliation Unknown 80/04/07 1p
- 8006120113 Comments on proposed rules 10CFR2.30, 40, 50, 51, 70, 110 NRC need not eraggerate CEG regulations NRC patterns have used practical interpretations to require enough info in EIS to make decisions
 MILLS.L M Tennesses Valley Authority 80/05/19 2pp
- 8005120125 Comments on proposed rules 10CFR2,30,40,50,70 & 110 added costs of evaluating alternative sites not cost effective Major adverse environ impacts normally identified using raconnelissance-level info PEOPLES,D L. Commonwealth Edison Co. 80/04/30 7pp
- 8006120177 Comments on proposed rules 10CFR2.30,50,51,70 & 110 convoluted sentences, technical jargon & references to obscure documents make rule impossible for general public to comprehend Agencies should use writers to communicate FORD,C K Affiliation Unknown 80/04/29 ip
- BOO6120191 Comments on proposed rules 10CFR2:30,40:50,51,70 & 110 wording of 10CFR51 22(b)(11) should be revised to read no significant changes Editorial change would eliminate some confusion & parallel wording proposed for 10CFR51 22(b)(9) BCHENDEL.K R Wyoming Mineral Corp REP-80-291 80/05/21 1p
- 8006120208 Comments on proposed rule 10CFR20 NRC should certify lab w/centinual monitoring by NBB SPELL,W H Louisiane, State of. 80/05/17 1p
- 9006120216 Comments on proposed rule 10CFR20 combining proposed roles of MBB & branch lab within NBS would gain benefit of long standing continuous operation over contracted lab MINANS.L F Gregon, State of 80/05/22 2pp
- BOO5/20217 Comments on proposed rule iOCFR20 corrective measures are needed Supports proposed rule within reasonable cost limits Some add cost justified Should cost become excessive, other personnel exposure measurement should be considered DAVIS, W W Bectman Instruments, Inc. 80/05/15 lp.
- 8006120221 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 supports comments & suggestions offered by PJ Walley of MS Dept of Natural Resources States should be made full partners in activities of site characterization MONTGOMERY,0 V House of Rep , Armed Services 80/04/08 1p
- --8006i20202 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 consultation process should give state stronger, more formalized rule in activities of site characterization, MALLEY, P. J. Hississippi. State of 80/03/09 2pp

- --8006120246 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 NRC & states should have opportunity to consult in & review site characterization studies to help insure that adequate data & safeguards are obtained OREEN, J W Mississippi, State of, 80/03/03 2pp
- 8006120228 Comments on proposed rule 10CFR73 better safeguards lie in areas of sound personnel acreening, good mgt & trustworthy employees Proposed amend would be costly to administer & would create unnecessary burdens on plant operations RIVELLO, J Long Island Lighting Co 80/05/13 2pp
- 8006120235 Comments on proposed rules 10CFR2 & 50. significant hazard needs defined specificity NRC should not accept change even within regulation that may increase probability of accident Regulations need strengthening WASSERBACH, A E Affiliation Unknown 80/Q5/21 ip
- 8006120277 Comments on proposed rule 10CFR32 on behalf of Ionization Smoke Detector Info Bureau Present labeling practices adequate Labeling requirement should be deleted Compliance period should be extended to one yr HARRIS.K BRK Electronics 90/01/18 2pp
- 8006120456 Requests 30-day extension on behalf of Association of American Railroads for comments on proposed rule 10CFR70 GARDNER, R S Affiliation Unknown. 80/05/06, 1p.
- 8006120495 Comments on proposed rules 10CFR2, 30, 40, 50, 51, 70 & 115 on behalf of Boston Edison Co.C-E.FL Power & Light Co.Houston Lighting & Power Co.Northern IN Public 8vc Co.Portland General Electric Co & Puget Sound Power & Light Co. Co. QRAY, FS Loonsy, Nichels, Johnson & Hayes, 80/05/02 App
- B006:30047 Forwards advance notice of proposed rulemaking redevelopment of technical criteria for regulating geologic disposal of high level radwaste, for publication in 8005:3 FR CHILK, BJ Office of the Secretary of the Commission 80/05/06.
- --8006130051 Advance notice of proposed rulemaking re technical criteria for regulating geologic disposal of high level radwaste Comments due by 800714 CHILK, 8. J. Office of the Secretary of the Commission 80/05/05 80c
- 8006130066 Forwards notice of 10CFR50 amend, requiring periodic updating of FBAR: for publication in 800509 FR.
 CHILK: 8, J Office of the Secretary of the Commission 60/05/06 ip
- --B00613006B Notice of amend to 10CFR50 requiring periodic updating of FBAR CHILK,S J. Office of the Secretary of the Commission B0/05/01
- 8006130072 Forwards notice of extension of comment period on advance notice of rulemaking on certification of personnel dosimetry processors until 800627 for publication in 800809 FR.
 HOYLE, J. C. Office of the Secretary of the Commission 80/05/08
- BOO6160059 Discusses draft final rules 10CFR5O & 70 on emergency planning.NRC-FEMA approach should be developed & implemented to encourage state & local agencies to incorporate federal efforts into their emergency planning PLESSET.M B. ACRB Advisory Committee on Reactor Safeguards BO/O6/11. 2pp
- 8006160152 Forwards official svc list & 800528 memorandum & order to all participants Participants may serve two copies of filings w/NRC.
 CHILK: S J. Office of the Becretary of the Commission 80/05/28
- --8006160160 Order forming working group to advise Commission readequacy of record in instant proceeding. Group will prepare questions to be asked of participants & witnesses by presiding officer or Commission Certificate of Svc encl. CHILK, S. J. Office of the Secretary of the Commission 90/05/28.

- 8006170231 Comments on proposed rule 10CFR32 distributing Am-241 & daughter isotopes to general public is grossly negligent & highly irresponsible Regulations are extremely weak in attempting to inform consumer
 TONE, M M Lehigh-Porono Committee of Concern 80/01/10 2pp
- 8006170240 Comments on proposed rule 10CFR32 more definition needed remarking of external surface of smake detectors Marking name of radionuclide & quantity would be of little value to average person
 MODRE, P Square D Cp , Electromagnetic Industries 80/01/11 2pp

- 8006170246 Comments on proposed rule 10CFRS1 alternate sources of energy should be proposed in addition to alternative sites Negative aspects should be communicated to public in addition to positive points professed by utils PEAVER,R,C New Hampshire, State of 80/05/27 2pp
- 8006170247 Certifies svc of notices of appearances in proposed rulemaking proceeding on storage & disposal of redwaste on 800830
 - 800530 JORDAN.₩ 5 , BISHOP,L L. New England Coalition on Nuclear Pollution JORDAN.₩ 5 , Natural Resources Defense Council 80/05/30 5pp
- 8006170277 Comments on proposed rule 10CFR50 recent legislation in CA requires upgrading of state nuclear emergency planning & capability Legislation is being supported by technical assessment study of accident consequences
 VOLD, E California, State of 80/03/31 3pp
- 8006170331 Notice of appearances in proposed rulemaking proceeding restorage & disposal of radwaste AM Gutterman appearance withdrawn

BURGER, J F , BUSTION, D R Tennessee Valley Authority 80/05/28

- 8006170336 Notice of appearance in proposed rulemaking proceeding restorage & disposal of radwasts
 JORDAN.W 8 New England Coalition on Nuclear Pollution JORDAN.W
 Natural Resources Defense Council JORDAN.W S Christa-Maria JORDAN, M. S
- 8006170340 Notice of appearance in proposed rulemaking proceeding re storage & disposel of radwaste BISHOP.L L. New England Coalition on Nuclear Pollution BISHOP.L L., BISHOP.L L. Natural Resources Defense Council 80/05/29 1p
- BOO6170345 Memorandum in support of States of MN & WI motions for extension of proposed rulemaking proceeding deadlines re storage & disposal of radwaste Suggests 800731 for statements of position Certificate of Svc encl GRIFFIN.W , DIAMOND,M J Vermont, State of, 80/05/16 9pp
- 8004170715 Motion for 60-day extension of first phase schedule of proposed rulemaking proceeding re storage & disposal of radwaste Requests extension until 800731 to file statement of position if motion is not granted M/Certificate of Byc OLSON, J.F., SENECHAL, M.E., Minnesota, State of 80/05/08 14pp
- 8006170777 "Physical Protection of Irradiated Reactor Fuel in Transit."
 10CFR73 effective amends to interim final rule Summarizes
 public comments received gives Commission responses & sets
 forth interim amended rule in final form
 CHILK, B J. Office of the Secretary of the Commission 80/05/27
- 8006170778 Comments on proposed rule 10CFR32 decision not to include info re disposal of radioactive detectors is unacceptable Disposal instructions necessary to avoid accumulation of isotopes in landfill areas NRC should recall ion detectors MALTERS.E Environmental Policy Institute 80/01/13 ip
- 8006170781 Comments on proposed rule 100FR32 concern for inadequacy of marking on smoke detectors may be valid for devices sold retail, Class of product sont to professional fire protection specialists should not be included BTOCKHAMER, B Walter Kidde & Co., Inc., Fenuel, Inc. 80/01/14
- B006170786 Comments proposed rule 10CFR32 ionizing detectors are not necessary Photoelectric can do job w/o bringing harmful radiation into homes NRC has no rules or regulations re disposal of devices Pollution & Environmental Problems, Inc 80/01/10 12pp
- BOO6170B14 Comments on proposed rules 10CFR2 & 90 proposed rule would be improvement in general.Rule allows for some predictability of NRC decisions NRC should set forth examples of significant hazards STEPTOE.P Commonwealth Edison Co STEPTOE.P Isham, Lincoln & Beale 80/05/27 2pp.

- 8006170847 Paper entitled, "Legal & Financial Aspects of Decommissioning," presented at AIF Conference on Environ Regulation of the Nuclear Industry in San Francisco.CA on 800518-21
 - Debevoise & Liberman 80/05/21 19pp
- 8006170863 Comments on proposed rule 10CFR32 rule is important & should be made final Rule should be strengthaned to require disposal instructions printed on outside of container LOCHSTET, N A Affiliation Unknown 80/01/11
- B00617096B Paper entitled. "Util View of Decommissioning." presented at Conference on Environ Regulation of Nuclear Industry A New Decade in San Fransisco.CA on 800518-21
 BLACKMON,D B Duke Power Co 80/05/21 10pp
- BOO6170870 Comments on proposed rules 10CFR2 & 50 wording should be changed to limit current broad criteria for significant hazards consideration
 HDFFMAN, D P Consumers Power Co DPH-66-80, 80/05/27 1p
- 8006170873 Requests consideration of enci State of MN 800217 ltr re development of amergency evacuation plans for fixed nuclear accidents

BOSCHWITZ, R Senate. 80/04/02 1p

- BOO6170874 Comments on proposed rule 10CFR32 amends are strongly supported Group has suggested similar changes since 1977 Package should have provision posted on label that would keep detector away from children JOHNSON,B League of Women Voters of Rockford,IL BO/01/12 12pp
- 8006180025 Comments on proposed rule 10CFRSO NUREO-0634 appears to have been developed w/o consideration for local problems Most damaging is method of write-off at natl level of dollar costs by eleverly worded statement SLONE, S B. Alabama, State of 80/04/01 Spp
- 8006180090 Comments on proposed rule 10CFR19 rule language is excessively broad re timing of conferences & clase of persons to whom invitations might be extended Conference invitations must be limited to authorized representatives UHRIG.R.E Florida Power & Light Co L-80-146 80/05/09.
- 8005:80183 Comments on proposed rule 100FR20 Alternative 4 is very attractive NBS.in particular, would be ideal candidate since engineering stds are high & believable KIM.J J Harper-Grace Hosps Detroit.MI 80/05/20, ip
- 8005:80407 Forwards LA Cote 8003:2 comments on proposed rule 10CFR50 Properly organized early warning sys should address & include emergency broadcast sys Mods to present sys & associated electronic equipment would be more efficient MCGRAIL.8 J Federal Emergency Management Agency 80/04/01 App
- 8006200227 Comments on proposed rule iOCFR50 properly organized early warning sys should address & include emergency broadcast sys ME Bureau of Civil Emergency Preparedness will develop plan compatible w/federal guidelines MCGRAIL, S.J. Federal Emergency Management Agency. 80/04/01, 4pp
- B006200548 "Capital Recovery of Nuclear Plant Decommissioning Costs " EMERS, B J , BERGLUND, R. H Northern States Power Co. 80/03/31
- 8006R30342 "Rules of Practice for Domestic Licensing Proceedings," iOCFR2.764 proposed rulemaking Lists three options being considered for amend.
 CHILK, S. J. Office of the Secretary of the Commission 80/05/16
- BOO6230349 Comments on proposed rule 10CFR140 opposes NRC view that public health & safety have been protected by AEC allowable limits of ionizing radiation Proposes to do everything possible to stop farce of ALARA CRUMLEY.J J Affiliation Unknown 79/12/07 ip
- BOOA230355 Comments on proposed rule 10CFR140 NRC has grossly underestimated intelligence of public & insulted dignity of people aware of constitutional rights Opposes reopening of TMI MILLER, L.C. Affiliation Unknown, 79/07/31 10PP
- 8006240099 NUREQ/CP-0011 NOSZ40079 NUREG/CP-UDI1 Errata sheat for Page 45 of NUREG/CP-UDI1: "Proceedings of Horkshops on Proposed Rulemaking on Emergency Flanning for Nuclear Power Plants "
 # Division of Siting, Health & Safeguards Standards 80/05/21

- 8006240104 Comments on proposed rules 10CFR2, 30, 40, 50, 51, 70 & 110 objects strenuously to categorical esclusion for well logging from requirements for EIA & EIS Exclusion unwise & Unsupportable HONEY, D. HEH, Dept. 6. US Public Health Service 80/06/06 200
- 8006240138 Comments on proposed rule 10CFR20 concept of adding internal & external doses long overdus More than one way exists to achieve radiation protection Decision should be left to prof HEGST,W F Galifornia, Univ. of
- 8006240190 Comments on proposed rule 100FR20 matls re certification of personnel dosimetry processors have been distributed to governmental agencies for review & comment Review scheduled to close on 800266
 WHITEHEAD, M Alasta: State of 80/04/30 3pp
- 8006230077 "Fire Protection Program for Nuclear Power Plants Operating Prior to 790101," 10CFR50 proposed rule Amend would require cartain min provisions for fire protection in operating nuclear power plants
 CHILK, 8 J Office of the Becretary of the Commission 80/05/21
- 8006250171 NUREO/CR-0672 V1
 "Summary of Technology, Safety & Costs of Decommissioning Ref
 BUR Power Station: "Vol 1:main rept
 DAN: H D; HOLTER; O M. . KENNEDY, W E Battelle Memorial Institute,
 Pacific Northwest Laboratory 80/06/13. 18pp
- 8006280317 "Specific Domestic Licenses to Mfg or Transfer Certain Items Containing Byproduct Hatl," 10CFR32 final rule, Amends regulations providing new requirements for labeling gas & aerosol detectors, including smoke detectors DIRCKS, W J Office of the Executive Director for Operations 80/05/27 24pp.
- --8006250323 Value impact statement re amend to 10CFR32 to provide new requirements for labeling gas & aerosol detectors * Office of the Executive Director for Operations 80/04/23 1300
- B006250344 Forwards notice of amend of 10CFR35 for publication in BC0514 FR.
 CHILK: B J Office of the Secretary of the Commission B0/05/08 is
- --8006250348 Notice of amend of iOCFR35 requiring licensess to keep records of misadministrations of radioactive math report sems to NRC referring physician & patient & submit quarterly repts to NRC Effective on 801110 CHILK, S J Office of the Secretary of the Commission, 80/05/07 lbps
- 8006230346 "Utilization of Excess & Disposal of Surplus Personal Property," ACE menual, App 5170 * Atomic Energy Commission 63/09/20 19pp
- BOO6250347 Comments on proposed rules 10CFR19.3D.40.80.70.71 & 150-addition of Paragraph o strengthened ability of employers of transient workers to obtain records for employees Addi info necessary in order to have accura
- 8006250350 Comments on proposed rule 10CFR20 insp capability should be modified to provide adequate safety stds Provision for viable standardized description of health characteristics of population before operation of facility should be developed BERTELL, R Ministry of Concern for Public Health 80/05/21 3pp
- 8006260071 Transcript of Commission 800618 public meeting in Washington,DC re final rulemaking on emergency preparadness Pp 1-90 Commission, 80/06/18 108pp
- 8006260170 Forwards FR notice of proposed rule for fire protection program for nuclear power plants operating prior to Jan 1979, for publication on 800320 CHILK/S J. Office of the Secretary of the Commission. 80/05/22
- ---8005260173 FR notice of proposed rule for fire protection program for nuclear power plants operating prior to Jan 1979, for publication on 800329 CMIK.S J Office of the Secretary of the Commission 80/05/21 450p

- 8006270030 Forwards comments on proposed rule 10CFR51 Summary of Nati Environ Studies Project rept. Subcommittee on Emergency Planning & Siting Policy comments & Subcommittee on Environ Repts comments encl WALEKE.C Atomic Industrial Forum 80/06/11 15pp
- --8006270033 AIF/NESP-018
 "Alternative Biting Requirements & Practices for Nuclear Power Plants," prepared for AIF, Natl Environ Studies Project
 Pages & Monre B0/06/30 200n
- 8006270163 Forwards statement of interim policy, on accident considerations under NEPA, for publication in FR Statement discusses Commission position re including considerations for future EIS DENTON, HR Office of Nuclear Reactor Regulation, Director 80706706 13pp
- 8006300278 CRNL/DEPA-4
 "Stds & Quidelines Pertinent to Development of
 Decommissioning Criteria for Sites Contaminated W/
 Radioactive Matl "
 DICKBUN,H W Oak Ridge National Laboratory UC-70 78/09/31
- 8006300353 Memo to recipients of proposed rules iOCFR19,30,40,50,70,71 & 150 Advises that Comment 30 was miscoded & should be removed from file * Docketing & Bervices Branch 80/06/10 ip
- 8005300487 "Deletion of Ref to Panama Canal Zone; Minor Amends," 100FR95 & 140 final rule, Minor amends reflect provisions of Panama Canal Treaty of 1977 & recently enacted Panama Canal Defense Act of 1979 DIRCKS, HJ Office of the Executive Director for Operations 80/05/22 Spp
- BOO6300B04 Comments on proposed rule iOCFR91.exclusionary safety std for acceptable site should be standoff distance & population criteria Only reconnaissance level info is necessary to evaluate site against new criteria

 LENTSCH.J. W Portland General Electric Co 80/06/04 4pp
- 8006300511 Comments on proposed rule 10CFR51.submitted on behalf of Midddle Bouth Utils Bys endorses AIF comments Application of proposed rules to existing inventoried or banked sites is not clear PATTER80N.J D Middle Bouth Bervices. Inc. 80/06/06 3pp
- PRM PETITION FOR RULEMAKING
- 8006050482 Comments in opposition to petitions for rulemaking 50-25 & 50-25A No legislative history cited in support of contention * LeBosuf, Lamb, Leiby & MacRae 80/04/04 Spp
- 8006:20281 Comments on petition for rulemaking 50-26.petition should be discarded Radiation from direct hit of five magaton bomb would spread farther & faster them from nuclear plant ELD,M.E. Idaho, Univ. of. 80/02/25. Ip
- BOO61202B5 Comments on patition for rulemaking 50-26 Attack on US by five magaton weapons would render issue re const of nuclear facilities inconsequential Patition would cause further energy cost increases & const delays

 LOVE.E Affiliation Unknown BO/03/03 1p
- 8006120287 Comments on petition for rulemaking 50-26, petition is overreaction due to concern about possible radiation from power plant rather than from five megaton nuclear explosion PEYERSON.R J Affiliation Unknown 80/03/05 ip
- BOO6120271 Comments on petition for rulemaking 50-26 petition should be denied due to reliance on erroneous assumptions Hezard stems primarily from weapon, not from plant No method exists to fully protect nuclear generating station from such attack QILMAN,D W San Diego Gas & Electric Co 60/03/07 2pp.
- 8006120372 Comments on petition for rulemaking 50-28 challenges, recommendations & suggestions in petition are valid Urgas serious consideration before finalizing proposed emergency planning regulations
 BYRNE, J. P. Colorado, State of 80/05/12 2pp
- 8006120426 Comments on petition for rulemaking 50-28 supports petition & urges fair & impartial hearing
 HUNTER, R B Indiana & Michigan Electric Co. 80/04/24. ip

- 8006120436 Comments on petition for rulemaking 50-28 on behalf author & listed utils portion of rule requiring 10-minute notification of those within 10-mile radius of plant after incident detection should be subj of separate rulemaking KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/02/14 2pp
- --B006120441 Petition for rulemaking to amend App & of 10CFR50 Fiftmenminute period for warning all those in 10-mile radius is arbitrary & unjustified Issue should be subj of separate rulemaking Memorandum of support encl KNUTH.DF Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 80/02/14 13pp
- BOO6130094 Forwards notice of issuance of quarterly summary rept of patitions for rulemaking pending final action CHILK.S J Office of the Secretary of the Commission 80/05/06 to
- --8006130098 Notice of issuance of quarterly summary rept of petitions for rulemaking pending final action FELTON, J M Division of Rules and Records 80/05/05 2pp
- 8006170133 Forwards Duke Power Co.TX Utils Generating Co & WPPSS petition for rulemaking 50~28 MCGARRY.J N Debevoise & Liberman 80/03/12 tp
- --800617014! Patition for rulemaking 50-28, urging deferral of final interim emergency response planning regulations Urges redrating 5 republishing of proposed regulations to parmit public comments on issues raised in encl statument MCGARRY, J M Duke Power Co MCGARRY, J M Texas Utilities Generating Co MCGARRY, J M Washington Public Power Supply System 80/03/12 2pp
- --8006170157 Statement in support of petition for rulemaking 50-28 Recent events must be factored into proposed rule Urges NUREO-0854/FEMA-RRP-1 be sued only for guidance Requests add1 time for implementation MCGARRY, J M Duke Power Co Generating Co MCGARRY, J M Texas Utilities Generating Co MCGARRY, J M Washington Public Power Supply System 80/03/12 27p
- SOO6170136 Forwards WK Watson B0010B ltr & S00106 pstition to change wording of 10CFR50.Paragraph 13 to require protection against attack by nuclear weapons

 JACKSON.H M Sanate. Energy & Natural Resources 80/02/07 3pp
- --8006170149 Petition for rulemaking 50-26 to change wording of 10CFR90, Paragraph 13 to require protection against attack by nuclear weapons Supporting documentation encl HATSON, W.K. Affiliation Unknown 80/01/06 10pp
- 8006170812 Forwards 800520 notice of denial of petition for rulemaking 2-7 CHILK,8 J Office of the Secretary of the Commission 80/05/20 ip
- --8006/708/8 Notice of denial of petition for rulemaking 2-7 Consequences of proposed rule change permitting late intervention in NRC proceeding on basis of recent arrival in plant vicinity would not be conductive to orderly hearing CHILK, S J Office of the Secretary of the Commission 80/05/20 Ann
- 8006170828 Comments on petition for rulemaking 90-28 capital costs should be borne by ratepayer Federal funds should pay cost of emergency plan maint & personnel training JOKES.0 L. Virginia, State of 80/04/04 2pp
- BOO6200006 Comments on petitions for rulemaking 50-25 & 50-25A proceeding being requested in alternative to determination to be made by ABLB in CP extension HAMSELL.D Illinois. State of BD/04/04 4pp
- BOO6240281 Comments on patitions for rulemaking 50-25 & 25A.reserves right to supplement patition after ASLB determination in Bailly Nuclear Power Plant CP extension proceedings, reinterpretation of 10CFR30 35 Certificate fo 8vc encl. HANSELL.D , SCOTT,W / Illinois, State of 80/04/04 4pp.
- 8006260134 Forwards FR notice of denial of W Eddleman petition for rulemaking 2-7.for publication on earliest possible date CHILK.S J Office of the Secretary of the Commission 80/05/21
- ~~8006250137 FR notice of denial of W Eddleman petition for rulemaking 2-7 requesting amend of 10CFR52 to define what constitutes good cause for late filed petition to intervene CHILK.S J Office of the Secretary of the Commission. 80/05/20 600

- 8006300321 Notice of publication of Foster Wheeler Energy Corp petition for rulemaking PRM-71-8 Requests that persons licensed pursuant to IOCFR34 for industrial radiography be exampt from approval in order to deliver licensed mati to carrier CHILK.S J Office of the Secretary of the Commission 80/06/04 300
- 8006300868 Forwards comments on setition for rulemaking 20-6A
 "Estimation of Somatic Risks & Stds of ICRP" encl
 BERTELL, R Ministry of Concern for Public Health 79/12/14 ip
- --BOO6300585 "Estimation of Somatic Risks & Stds of ICRP," presented at sith Intl Congress of Radiation Research SCHMITZ-FEUERHA, MUSCHOL, E., BATJER, K. Breman, Univ. of, 2013(1)
- PROJ PROJECTS PREDOCKET LICENSING
- B006110056 Forwards list of files designated by NRC & State of CA Dapt of Water Resources for production from PG&E warehouse DEUKMEJIAN, 0 , HORN, H. C California, State of 80/05/23 2pp
- B006190573 Notice of substitution of JC Morrissey by MH Furbush as counsel for applicant Certificate of Svc encl MEISS:R L Pacific Gas & Electric Co B0/06/05 App
- 8006200150 Motion to dismiss appeal Agreement has been reached due to successful settlement negotiations RA Rizzi declaration encl RIZZI,R A., BARRY,D N. Southern California Edison Go, RIZZI,R, A Gibson, Dunn & Crutcher 80/05/06. 3pp
- 8006200572 Forwards "Post-Test Analysis of LOFT Loss-of Coolant Experiment L2-3 " KAUFMAN.N C E0&0 Idaho,Inc 80/03/26 3pp.
- BOO6250374 Discusses plan for extended operation of light water broader reactor Based on 241st meeting on BO0501-03 w/Westinghouse: util:DDE & NRC, ACRB believes operation of reactor core to 24,000 EFPH is acceptable PLESET.M B ACRB Advisory Committee on Reactor Safeguards. BO/05/06 ip.
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- BOO61203B3 Part 21 rept re Rosemount Model 1152 transmitter output between four & 20 mA occuring w/input pressures over or under calibr range. Caused by unique conditions in transmitter sitectronics Users should conduct analyses WARD, R A Rosemount, Inc. 80/03/14 5pp.
- 8006180356 Part 21 rept re possibility of stem nuts or extensions becoming loose after continuous rotation during opening & closing of volve Caused by vibration due to play between internal & external splines

 WHEATON, W R Borg-Warner Corp. 80/05/23 ip
- BOO61B0399 Part 21 rept re Rosemount Model 1152 pressure transmitters Defect is ambiguous output when over or underpressured Forwards Rosemount rept OE will inform affected utils & advise of proper corrective actions BHERNIODD.0 0 General Electric Co , Nuclear Energy Products Div MEN-10B-80 80/06/02 7pp
- 8006200084 Part 21 rept re two liner indications on outside surface of ARME Section III, Class II fitting, supplied by Capitol No defects found in other elbows tested Customer responsibility to specify type of evaluation required PALLOB, N O Harsco Corp., Capitol Manufacturing Co Div 80/06/02 3nn
- 8006200632 Supplement to 800314 Part 21 rept re potential deficient Model 1152 pressure transmitter embiguous output Causes & potential safety hazards more fully clarified for NRC review as potential deficiency Licensee awaiting review WARD,R A Rosemount, Inc 80/03/28, 5pp

- QA999 GUALITY ASSURANCE INSPECTACHS
- 8006030155 Ack receipt of 800509 ltm informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 97900214/80-01
 - POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/05/19
- --B006030162 Responds to NRC B00416 ltr re deviations noted in GA Program
 Insp Rept 99900214/B0-01 Corrective actions will implement
 program outlins for persons whose activities affect nuclear
 products quality
 DDLSON.T C Anderson-Greenwood & Co B0/05/09 2pp
- --8006030163 Forwards GA Insp Rept 99900214/80-01 on 800303-05 & notice of deviation POTAPOVS, U Region 4, Dalles, Vendor Inspection Branch 80/04/16
- --9006030165 Notice of deviation from insp on 800303-05, # Region 4. Dallas. Vendor Inspection Branch 80/04/15 ip
- --R006030167 QA Program Insp Rept 97900214/80-01 on 800303-05
 Noncompliance noted no evidence that QA director had
 prepared & approved required training guides, no procedures
 developed which specified stds to control visual exams.
 HMITEBELL,D E , KELLEY,W D Region 4, Dallas, Vendor Inspection
 Branch 80/04/13 10pp
- 8006040001 Ack receipt of 800428 ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 9900100780-01 POTAPOVS.V Region 4, Dallas, Vendor Inspection Branch B0/05/14
- --8006040004 Responds to NRC 800403 ltr re deviations noted in GA Program Insp Rept 99900100/80-01 Corrective actions tool & gage insp/calibr record completed for new Wilson Rockwell hardness tester ORGOME.K Limitorque Corp 80/04/28, 5pp
- --B006040003 Forwards GA Program Insp Rept 99900100/80-01 on B00318-20 & notice of deviation PDTAPDV8, U Region 4. Dallas, Vendor Inspection Branch, 80/04/03
- --8006040008 Notice of deviation from insp on 800318-20
 * Region 4: Dallas, Vendor Inspection Branch. 80/04/01 2pp
- --8006040010 QA Program Insp Rept 99900100/80-01 on 800318-20
 Noncompliance noted failure to maintain calibr card for
 Rockwell hardness tester & to include employee-owned
 measuring tool on calibr list
 HUNNICUTI,K M. OLLER, E Region 4, Dallas, Vendor Inspection
 Branch 80/04/01 11gp
- BOO6060208 Act receipt of BO0425 itr informing NRC of steps taken to correct violation noted in GA Program Insp Rept 97900057/79-02
 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/05/12.
- --8006060213 Responds to NRC ltr re violation noted in GA Program Insp Rept 99900057/79-02. Corrective actions: stiffening brace design complete Design sent to customer & GC dept. Fabrication of sample to be used for vibration testing. NIEHAUS:P W William Powell Co. 80/04/25 ip
- 8005060215 Ack receipt of 800128 & 0429 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9790022779-04.
 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/05/13.
- ---80060&0222 Responds to NRC 800414 itr requesting addl info re deviation noted in GA Program Insp Rept 99700325/79-04. Corrective actions; procurement files will be updated to include listing

- --8006060229 Responds to NRC 791228 ltr re deviation noted in GA Program
 Insp Rept 99900323/79-04 Corrective actions table of
 contents corrected & procedure introduced to revise table
 when manual is changed.
 BARKER,N R 0(1bert/Commonwealth Cos 80/01/28 3pp
- --8006060234 Forwards QA Program Insp Rept 99900525/79-04 on 791126-29 & notice of deviation POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 79/12/28
- --8006060237 Notice of deviation from insp on 791126-29 * Region 4, Dallas, Office of the Director 79/12/21 2pp
- --800404040 GA Program Insp Rept 99900525/79-04 on 791124-29
 Noncompliance noted failure to annotate table of contents in
 GA manual to include GAI/GA(F) ii 94 Procurement for pipe
 rupture restraints not controlled by written order
 HALE,C 0, FOX,D F Region 4, Dallas, Vendor Inspection Branch
 ANDERSON,D G Region 4, Dallas, Office of the Director 79/12/21
- 8006090094 Ack receipt of 800507 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900002/80-01 POTAPOV6.U Region 4. Dallas. Vendor Inspection Branch 80/05/07 is
- --8006090103 Responds to NRC 800328 ltr re deviation noted in GA Program Insp Rept 99900002/80-01. Corrective actions, tag indicating deviation notice number was immediately placed w/rods in question.

 LICHTENBERGER, H C-E Power Systems NGA 80-004 80/04/14 2pp
- ---B00A090109 Forwards GA Program Insp Rept 99900002/80-01 on B00310-14 & notice of deviation.
 POTAPOVE, U Region 4, Dallas, Vendor Inspection Branch 80/03/28
- ---8006090115 Natice of deviation from insp on 800310-14
 * Region 4, Dalles, Office of the Director 80/03/26 ip
- --B006090122 QA Program Insp Rept 99900002/B0-01 on 800310-14
 Noncompliance noted fuel rods not properly identified
 MCNEILL N. M., WHITESELL, D. E. Region 4, Dallas, Vendor Inspection
 Branch B0/03/28 1p.
- 8006090138 Ack receipt of 800425 ltr informing NRC of steps taken to correct violation & deviation noted in GA Program Inap Rept 99909710/80-01.
 PGTAPOVG.U. Region 4. Dallas, Vendor Inspection Branch 80/05/07 in
- --8006090149 Responds to NRC B00328 ltr rs violation & deviation noted in GA Program Insp Rept 97900710/B0-01. Corrective actions GC data sheet flow modified to provide GC inspector w/access to production package in work area JACKSON.R W. National Valve & Mfg. Co B0/04/25 3pp
- --8006070133 Forwards QA Program Insp Rept 99900710/80-01 on 800310-13 & notices of violation & deviation. POTAPOV8, U Region 4, Dallas, Office of the Director 80/03/28 2pp.
- --8006090163 Notice of violation from insp on 800310-13 # Region 4. Dailas. Office of the Director 80/03/25 ip
- --8006090167 Notice of deviation from insp on 800310-13, * Region 4: Dallas, Office of the Director. 80/03/25 2pp
- --8006090173 GA Program Insp Rept 999000710/80-01 on 800310-13
 Noncompliance noted failure to comply w/required posting of
 Energy Reorganization Act of 1974 & procedures & failure to
 record NCN number on GC deta sheet
 ROBERDS, H. M. Region 4, Dellas, Vendor Inspection Branch
 80/03/25, 7pe
- BOO6120254 Forwards response to BOO410 notice of noncompliance licensee denies noncompliance, but prefers not to pursue expensive & time-consuming proceedings Payment for total amount of Items 2 & 3 civil penalties encl
 GUILBERT, D E Babcock & Wilcox Co. BO/05/20 19pp
- 8006120467 Ack receipt of 800509 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700225/80-01.
 POTAPOVS,U. Region 4. Dallas, Vendor Inspection Branch. 80/05/22 is.

- --8006120472 Responds to NRC 800403 ltr re deviation noted in QA Program Insp Rept 99900228/80-01 Corrective actions periodic audits scheduled to confirm requirement implementation CALDER, W Foxboro Corp 80/05/09 4pp
- ---8006120475 Forwards GA Program Insp Rept 99900225/80-01 on 800317-21 & notice of deviation POTAPOVS.U Region 4. Dalles. Vendor Inspection Branch
- ---8006120478 Notice of deviation from insp on 800317-21 * Region 4, Dallas, Office of the Director 80/04 80/04/01
- --8006120483 GA Program Insp Rept 99900225/80-01 on 800317-21 Noncompliance noted maint checklist identifying preventive maint, personnel performing & date of accomplishment not attached to tool folder POSTER, W.E., HUNNICUTT, D.M. Region 4, Dallas, Vendor Inspection Врр 80/04/01
- BOO6120517 Advises that NRC has completed investigation of collection, evaluation & reporting of info available to B&W before TMT-2 accident B&W failed to report safety info in timely manner Notices of noncompliance & civil penalties encl W/o encl. BTELLO,V Office of Inspection & Enforcement, Office of the Director BO/04/10. 3pp
- 8005160116 Ack receipt of 800519 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900400/80-01 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/05/29
- **8006160119 Responds to NRC 800416 ltr re deviation noted in QA Program Insp Rept 99700400/80-01 Corrective actions developed forms to gather statistical data necessary for correction of scope of illegible records problem QUILBERT, D E Babcock & Wilcox Co 80/05/19 App
- -8006(60131 Forwards GA Program Insp Rept 99900400/80-01 on 800311-14 & notice of deviation.
 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/04/16
- --8006160134 Notice of deviation from insp on 800311-14
 * Region 4, Dallas, Office of the Director 80/04/15
- -8006160138 QA Program Insp Rept 99900400/80-01 on E00311-14
 Noncompliance noted failure to retain QA audit checklists QA
 records not legible Audit procedures do not contain ANSI
 requirements
 HALE.C. J. JOHNSON, J. M. FOX, D. F. Region 4, Dallas, Vendor
 Inspection Branch 80/04/15 3ipp.
- 8006180278 Forwards GA Program Insp Rept 99900304/80-01 on 800428-0502 No noncompliance noted POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/05/12
- --B006180303 GA Program Insp Rept 99900304/80-01 on 800428-0502 No noncompliance noted Major areas inspected mgt meeting & implementation of 10CF850. App B.mfg process control.control of nonconformances & corrective actions & audits BROWN.R.L., WHITEBELL.D E Region 4, Dallas, Vendor Inspection Branch 80/05/09 Bpp
- 8006190349 Ack receipt of 800204 & 790824 ltrs informing NRC of steps taken to correct deviations noted in GA Program Inap Rept 97900216/79-01 NRC agrees w/proposed corrective action commitment made at 800307 meeting PDTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/03/20
- --8006170356 Responds to NRC 791231 ltr re deviations noted in GA Program Insp Rept 99700216/79-01 Forwards attachments outlining corrective actions M/o attachments KAT2.L Tubeco, Inc 90/02/04 ip
- --B006190362 Ack receipt of 790824 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900216/79-01 Forwards discussion of deviation notices for which vendor has supplied unsatisfactory corrective actions, SEYFRIT, K V Region 4, Dallas, Office of the Director 79/12/31
- --B006170370 Responds to NRC 790618 ltr re deviations noted in GA Program
 Insp Rept 99700216/79-01 Corrective actions addl GA
 personnel will be hired extensive personnel training will
 be conducted & dept heads will review NRC rept
 GOLDSMITH.W Tubeco, Inc 79/08/24 ip

- -8006190374 Forwards GA Program Insp Rept 99900216/79-01 on 790212-16 & notice of deviation

 BEYFRIT, K V Region 4, Dallas, Office of the Director 79/06/18
- --8006190376 Notice of deviation from insp on 790212-16 * Region 4. Dallas, Office of the Director 79/06 79/06/18 1300
- --8006190382 GA Program Insp Rept 99900216/79-01 on 790212-16
 Noncompliance noted maint of liquid penetrant exam records & performance of weld repairs inconsistent w/code requirements No external audits by qualified auditors BARNEB, I. ELLERSHAWL E., KUNNICUTT, D.M. Region 4, Dallas, Vendor Inspection Branch 79/06/18 32pp
- 8006200133 Forwards &A Program Insp Rept 99700308/80-01 on 800305-07 No noncompliance noted POTAPOUS,U Region 4. Dellas, Vendor Inspection Branch 80/04/ii
- --8006200135 GA Program Insp Rept 99900308/R0-01 on 800305-07. No noncompliance noted Major areas inspected implementation of 100FR80. App ID by applicable codes & stds review of two deficiency repts & vendor corrective action & activities WHITESELL, D E , KELLEY, W D Region 4, Dallas, Vendor Inspection Branch 80/03/31 14pp
- 8006200138 Act receipt of 800522 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900507/80-01 PDTAPOVS,U. Region 4. Dalles, Vendor Inspection Branch 80/05/29
- -9004200139 Responds to NRC 800417 ltr re deviation noted in GA Program Insp Rept 99900507/80-01 Corrective actions drawings identified in insp will be sent out for comments by 800401 Mechanical dept 8td MAS-4 will be revised & reissued 800430 MCFARLAND.J E Sargent & Lundy. Inc 80/05/22 3pp
- --8006200143 Forwards GA Program Insp Rept 99900507/80-01 on 800324-28 & notice of deviation POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/04/17
- ---8006200146 Notice of deviation from insp on 800324-28 * Region 4, Dallas, Office of the Director 80/04. 80/04/16
- ---8006200148 GA Program Insp Rept 99900507/80-01 on 800324-28

 Noncompliance noted failure to obtain interface comments on design drawings & failure of mechanical dept procedures resys design reviews to meet procedural requirements COSTELLO, J.R., HALE: C.J. Region 4, Dallas, Vendor Inspection Branch 80/04/16 7pp
- 8006230212 Ack receipt of 800513 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99700371/80-01 POTAPOVS, U Region 4. Dellas, Vendor Inspection Branch 80/05/20
- --8006230214 Responds to NRC 800416 ltr re deviation noted in GA Program Insp Rept 97900371/80-01 Corrective actions records may be removed from files only by or in presence of personnel on authorized list ROBERTS, G. W
- --8006230216 Forwards GA Program Insp Rept 97900371/80-01 on 800331-0403 & notice of deviation.
 POTAPOVB,U Region 4, Dallas, Vendor Inspection Branch. 80/04/16
- ---8006230219 Notice of deviation from insp on 800331-0403.
 * Region 4. Dallas. Office of the Director 80/04/15 ip
- ---8006R302R3 QA Program Insp Rept 99900371/80-01 on 800331-0403
 Noncompliance noted std operating procedure does not require
 records removed from storage to be checked out w/QA or
 provide for method maintaining control of records,
 WHITBELL,D.E. KELLEY,W.D. Region 4. Dallas, Vendor Inspection
 Branch 80/04/15, 12pp
- 8006230233 Forwards OA Program Insp Rept 99900650/80-01 on 800324-26.No noncompliance noted. POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch. BO/04/11.

- ---8006230238 GA Program Insp Rept 97900650/80-01 on 800324-26 No noncompliance noted Major areas inspected implementation of Topical Rept FCTPN-78 & followup action or previous insp
 - HALE,C J , BROWN.R L Region 4, Dallas, Vendor Inspection Branch BQ/04/07 3pp
- 8006240054 Ack receipt of 800505 ltr informing NRC of steps taken to correct violation & deviation noted in GA Program Insp Rept 99700703/80-01 Region 4, Dallas, Vendor Inspection Branch 80/05/27
- --800624005B Responds to NRC 80032B ltr re violation & deviation noted in GA Program Insp Rept 99900703/80-01 Corrective actions written procedure for compliance w/10CFR21 is being prepared & will be implemented by 800531 PROCHAZKA, D.R. RTE-Delta Corp. 80/05/05 3pp
- --8006240065 Forwards QA Program Insp Rept 99900703/80-01 on 800219-21 & notices of violation & deviation PDTAPDVS.U Region 4, Dallas, Vendor Inspection Branch 80/03/28
- --8006240070 Notice of violation from insp on 800219-21 * Region 4. Dallas, Office of the Director 80/03
- --8006240073 Notice of deviation from insp on 800219-21
 * Region 4, Dallas, Office of the Director 80/03
- -8006246080 QA Program Insp Rept 99900703/80-01 on 800219-21
 Noncompliance noted practices not consistent w/10CFR21 21,
 10CFR30.App B.Criterion 5 & GA manual.Revision E
 HUNNICUTIO H. FORTER, W.E. Region 4, Dallas, Vendor Inspection
 Branch 80/03/26 10pp
- 8006240097 Ack receipt of 800515 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900005/80~01 Region 4, Dallas, Vendor Inspection Branch 80/05/29
- --8006240101 Responds to NRC 800416 ltr re deviation noted in GA Program Insp Rept 99900005/80-01 Corrective actions appropriate GC personnel responsible for implementation of procedure reinstructed as to requirements MOORE.J 8 Westinghouse Electric Corp 80/05/15 3pp
- --8006240103 Forwards GA Program Insp Rept 99900005/80-01 on 800324-28 & notice of deviation POTAPDV8:U Region 4. Dallas: Vendor Inspection Branch 80/04/16
- --8006240105 Notice of deviation from insp on 800324-28
 * Region 4, Dallas, Office of the Director 80/04 80/04/15 16
- -8006240107 GA Program Insp Rept 97900005/80-01 on 800324-28, Noncompliance noted failure to note operational status on WHITESELL, D E , MCNEILL, W M Region 4, Dallas, Vendor Inspection Branch 80/04/15 App
- BOO6240110 Ack receipt of BOO529 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900403/80-02 Region 4. Dalles, Vendor Inspection Branch 80/06/04
- --8006240114 Responds to NRC 800502 ltr re deviation noted in GA Program
 Insp Rept 99700403/80-02 Corrective actions new review has
 been made & revised review rept of GA manual was issued BARNARD, J. General Electric Co 80/05/29 App
- --8006240119 Forwards GA Program Insp Rept 99900403/80-02 on 800331-0411 & notice of deviation.
 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/05/02
- ---8006240122 Notice of deviation from insp on 800331-041: * Region 4, Dallas, Office of the Director 80/05/0
- --B006240124 GA Program Insp Rept 99900403/B0-02 on 800331-0411 Noncompliance noted: failure to evaluate GA manual for description on how suppliers are selected & qualified COSTELLO, J R. ANDERBON.D Q. HALE.C J Region 4. Dallas: Vendor Inspection Branch. B0/05/01 29pp

- B006240141 Ack receipt of 800529 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900378/80-01 Region 4. Dallas, Vendor Inspection Branch 80/06/05 POTAPOVS, U
- ~~B006240146 Responds to NRC 800429 ltr re deviation noted in QA Program Insp Rept 97900378/80-01 Corrective actions in process of documenting procedures in areas of ongineering changes & design review, matir review board & calibr SMANBON, N E Acme-Cleveland Co . Namco Controls Div BO/05/29
- -8006240153 Forwards GA Program Insp Rept 99900378/80-01 on 800211-14 & notice of deviation POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch
- --8006240155 Notice of deviation from insp on 800211-14
 * Region 4, Dallas, Office of the Director 80/04 80/04/29
- -8006240172 GA Program Insp Rept 99900378/80-01 on 800211-14
 Noncomplience noted failure to compile & implement written
 procedures in areas where activities affect quality
 AOEE.JR, HUNICUTT,D M Region 4, Dallas, Vendor Inspection
 Branch 80/04/29 App
- 8006240586 Requests add1 info re organizational changes discussed in 800516 ltr Info needed to demonstrate that changes will not result in less effective QA program MAASS,N P Quality Assurance Branch 80/06/09 lp
- 8006250097 Ack receipt of 800519 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900711/80-01 POTAPOVS, U Region 4: Dallas: Vendor Inspection Branch 80/06/05
- --8006250110 Responds to NRC 800417 ltr re deviation noted in GA Program Insp Rept 99900711/80-01 Corrective actions consultants engaged to review program, OA manager implementing checklist & procedures for quality activities MODRE,P D Leckenby Co 80/05/19 5pp
- 8006250114 Forwards GA Program Insp Rept 99900711/80-01 on 800317-20 & notice of deviation POTAPDV8.U Region 4. Dallas, Vendor Inspection Branch 80/04/17
- --8006250119 Notice of deviation from insp on 800317-20
 * Region 4, Dallas, Office of the Director 80/04 BO/04/14
- 8006280126 GA Program Insp Rept 99700711/80-01 on 800317-20
 Noncompliance noted weld passes not recorded welding w/o
 approved procedure GA manual not submitted for approval &
 weld wire travel speeds not documented
 WHITESELL. D E , HUNTER V H Region 4, Dallas, Vendor Inspection
 Branch 80/04/14 9pp
- 8006250113 Ack receipt of 800513 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900047/80-01 Region 4: Dallas. Vendor Inspection Branch 80/06/05 POTAPOVB, U
- --8006290117 Responds to NRC 800401 ltr re deviation noted in GA Program
 Insp Rept 99900047/80-01 Corrective actions GA manual
 revised, maintaining segregation of electrodes in oven, flux
 mail revisued fur wetness or svidence of foreign mail
 MILLER, T D Westinghouse Electric Corp TDM-80-051 80/05/13
- ---B006250121 Forwards GA Program Insp Rept 99900047/80-01 on 800310-14 to notice of deviation POTAPOVB,U Region 4, Dallas, Vendor Inspection Branch 80/04/01
- --8006250123 Notice of deviation from insp on 800310-1 * Region 4. Dallas, Office of the Director 80/0
- --8006250127 GA Program Insp Rept 99900047/80-01 on 800310-14
 Noncompliance noted welding math not segregated in holding
 oven absence of GA program requirements & instructions not
 provided to heat breatment svc vendor
 HUNNICUIT.D M : ELLERSHAW, L E : BARNES, I Region 4, Dalias, Vendor
 Inspection Branch, 80/03/31 16pp

- 8006300143 Ack receipt of 800313 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900287/80-01
- POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/05/05
- --8006300147 Responds to NRC 800314 ltr re deviation noted in OA Program Insp Rept 99700287/80-01 Corrective actions matl discrepancy rept recorded on shop traveler matl rept written reporting unpactaging of values w/o proper use of shop traveler BUCKNER, S.P. TRW. Inc., TRW Mission Mfg Co Div 80/05/13 2pp
- --8006300153 Forwards QA Program Insp Rept 99900287/80-01 on 800225-28 & notice of deviation POTAPDV8.U Region 4. Dallas. Vendor Inspection Branch 80/03/14
- --8006300157 Notice of deviation from insp on 800225-28
 * Region 4, Dallas, Office of the Director 80/03/13 3pp
- --8006300172 GA Program Insp Rept 99900207/80-01 on 800225-28
 Noncompliance noted mati discrepancy rept number not
 recorded on shop traveler mati discrepancy rept
 dispositioned by GC representative
 HUNNICUTT,D M , BARNES, I Region 4, Dallas, Vendor Inspection
 Branch 80/03/13 8pp

REGOD REGULATORY GUIDES

- 8006030489 Recommends that draft Reg Ouide 1 97.Revision 2 be issued after TMI-2 action plan requirements are settled Guide should include ANB stds
 SHERMODD, G G General Electric Co MFN-106-80 80/05/30 2pp
- 800609004B Comments on proposed Reg Ouide B. 14.Revision 2 albedo neutron sys usually requires close body contact at all times during usersizable error can occur if close body contact is not maintained Reg guide fails to support albedo desimetry PEOPLES.D L. Commonwealth Edison Co. 80/05/15 2pp
- B006090067 Comments on proposed Reg Quide 5 40 physical protection for matl well described. Info re security for protection plans, info on proposed shipments & routes should be provided WAITER T Affiliation Unknown 80/05/17 ip
- 8006090125 Comments on proposed Reg Guide 8 14 Revision 2 clause should be written into guide re need for absolute quality of rem instruments COPELAND.R L. Energy, Dept of 80/05/23 Zpp
- 8006120144 Comments on proposed Revision 2 to Reg Guide B 14 words should be added to Paragraphs C 1 b & c to clearly indicate neutron dosimetry is not necessary when doses are expected to exceed iio mrem/quarter Calculated estimates better HDFFMAN,D P Consumers Power Co 80/05/22 1p
- BOOG130001 Reg Guide 1.84 Revision 16, "Design & Fabrication Gode Case Acceptability ABME Section III Div 1 # Office of Standards Development, Director BO/05/31 10pp
- 8006130105 Forwards notice of issuance & availability of Reg Guide i 84.Revision 16 CHILK.S.J Office of the Secretary of the Commission 80/05/15
- BOO6170361 Comments on proposed Revision 2 to Reg Quide i 136 requirement to increase embed insp will result in increased costs w/o any justification COUNSIL.N G Northeast Utilities BO/01/05. 4pp
- BOO6170801 Forwards notice of issuance & availability of Reg Quide 5 6 CHILK, B J Office of the Becretary of the Commission BO/05/01
- --8004170807 Notice of issuance & availability of Reg Guide 5 & MINOGUE, R 8 Office of Standards Development, Director. 80/04/29
- 8006190333 Comments on draft Reg Guide 1 XX recommends that meter wells be included in introduction as acceptable sys for dewatering CAHN,A L Bechtel Carp. 79/11/28 ip
- 8006200104 Forwards comments on proposed Revision 2 to Reg Guide 8 14, "Personnel Neutron Dosimeters " Until questions re albedo nautron dosimeters & sys answered, such refs should be deleted from guide
 PEOPLES, D. L. Commonwealth Eduson Co 80/05/15. 2pp

- 8006200642 Forwards notice of issuance & availability of Reg Guide 5 7. Revision 1. for FR publication CHILK.B.J. Office of the Secretary of the Commission 80/06/02
- ---8006200645 Notice of issuance & availability of Reg Guide 5 7, Revision
 1. Requests comments
 MINOGUE, R B Office of Standards Development, Director 80/05/28
- 8006230172 Advises that review of draft Revision 2 to Reg Guide 6 4 is complete Agrees that revision is necessary KERR, G W Assistant Director for State Agreements Programs 80/06/09 ip
- 8006240174 Fowards notice of issuance & availability of proposed Revision 1 to Reg Quide 8 12, "Criticality Accident Alarm Sys" CHILK.S J Office of the Secretary of the Commission 80/06/02
- --8006240197 Notice of issuance & availability of proposed Revision 1 to Reg Guide 8 12, "Criticality Accident Alarm Sys " Comments requested on draft reg guide revision & value/impact statement QULLER-K R Division of Siting. Health & Safeguards Standards 80/05/27 2pp
- 8004240314 Notice of issuance & availability of draft reg guide, "Instructions Concerning Risk From Occupational Radiation Exposure" OCLLER.K R Division of Siting, Health & Safeguards Standards 80/05/20.
- --8005240317 "For Comment" issue of draft Reg Quide 8 XX "Instruction Concerning Risk From Occupational Radiation Exposure " Draft value/impact statement encl e Office of Standards Development, Director 80/05/31 34pp
- 8006240579 Notice of ACRS Subcommittee on Regulatory Activities 800604 open meeting in Washington, DC to discuss proposed Reg Guide 1 23, Revision 1 & revisions to 10CFR50 & 55 HOYLE, J C Office of the Secretary of the Commission BD/05/16
- 8006250337 Comments on proposed Reg Quide B 14 Primary function of personnel dosimetry is not measurement by dose control Notes for 800423 meeting in Ann Arbor, MI enci * Tennessee Valley Authority 80/04/23 bp
- 8006250369 Forwards FR notice of issuance & availability of Reg Guide 5 14, Revision 1, for publication on earliest possible date CHILK, S J Office of the Secretary of the Commission 80/05/22
- --B006280373 FR notice of issuance & availability of Reg Ouide 5 14.
 Revision I Comments being taken
 MINOSUE.R B Office of Standards Development, Director 80/05/19
 200
- 8006260005 Forwards notice of issuance & availability of Reg Guide 4 14, Revision 1.

 CHILK, S. J. Diffice of the Secretary of the Commission 80/05/09 in
- BOOGSO018B Discusses implementation of revised SRP 5 4 7 providing revised cooling sys requirements & risk assessment recoverall plant heat removal capability
 NOVAKIT M Reactor Systems Branch 78/06/08 3pp
- --8006300201 Discusses proposed implementation of revised cooling sys requirements & risk assessment re overall plant heat removal capability. MATTEON R. J Division of Systems Safety STELLO.V Division of Operating Reactors 78/01/19 Spp

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 800&020138 "Stress Analysis of Instrumentation Bupport Structures & Ctr Fuel Module Upper Core Support Structure Mods." Revision 1.LOFT program BLANDFORD.R K E0&0. Inc LTR 1111-62 80/03/25 25pp
- 8D06020141 "Analysis of Transient Load Measuring Sys," LOFT program GDDD,R,R, MEACHUM,TR EG&O, Inc. LTR LO-87-80-13 80/03/17, 85ep.

- 8006020144 "LOFT Fuel Bundle Structural Response to Mechanical Loads During Subcooled LOCE." Revision 1 MARTINELL.) 8 E080, Inc. LTR 1111-65 80/04/02 160pp
- BOO6020184 "Special LOFT Features for Improved Monitoring & Survival of LOCA Transients," technical R&D interim rept GDORTICK,L D , LEACH, L P E08.9 [daho, Inc LO-87-80-130 80/01/0749ns
- BOOA020189 "Mati Control & Accounting Effectiveness Evaluation Davelopment," progress rept for Mar 1980 POGOIGLA J Lawrence Livermore Laboratory FIN A-0115 MC 80-03-03-LR 80/05/19 7pp
- BOO6020481 "Experimental Data Rept for Heater Rod Test Series 9-TC." experimental data BARNWID J . SOLBRIG, C W . SELCHO, H S E0&O Idaho, Inc LTR 20-69 80/01/09 59pp
- 8006020503 "Beismic Analysis of LOFT FP3 TE Cooled Encl Box," analysis rept FINICLE, D P EG&O Idaho, Inc LO-87-79-129 80/02/28 9pp.
- 8006020539 "Electrical Instrumentation & Control Features of Proposed HPCI & ESAP Mods," informal rept.
 MAYB, S E E060, Inc E00-EA-5150 80/05/31 15pp
- BOO6020546 "WRRD Monthly Rept for Mar 1980." YBARRONDO:L J EQ&G: Inc YBR-59-80 B0/04/30 100pp
- 8006020552 "Inventory of Two-Phase Critical Flow Experiment Data Base," preliminary assessment rept. HALL.D 0 E000, Inc E00-CAAP-5140 80/04/30. 43pp
- 8006020561 "Experimental Data Rept for Transient Flow Calibr Facility Tests IA101:IA102 & IA103 " MARTINELL.J B E080: Inc LO-00-8--114. 80/03/10 108pp
- 8006020568 "Feasibility Transient Test of Correlation Type Transit Time Flowmeter in LTBF Blowdown Facility," experimental data BAKER.A O EGG, Inc LTR-141-11B. 80/02/26 91PP
- 8006120193 Offers no comments on Jan. 1980 monthly progress rept for NRC contract FIN 8-0279 SCARAND, R. A Uranium Recovery Licensing Branch FIN 8-0279. 80/03/24 ip
- 8006120247 "BWR Refill-Reflood Program Progress," monthly ltr for Apr 1980 BURNETTE, O W. General Electric Co NRC-04-79-184 80/04/30 41pp
- BOO6130360 "Physical Protection of Nuclear Facilities," informal progress rept for Mar 1980. CHAPMAN, L D Sandia Laboratories FIN A-1060 80/05/15 Gpp
- 8006130383 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Apr 1980 ZITTEL.HE Gak Ridge National Laboratory, FIN B-0279 ORNL/ED/E18-128. 80/04/30. 6pp
- B006130390 "Nonfastructive Examination Evaluation Support, ^amonthly progress rept for Apr 1980
 SMITH.J.H Dak Ridge National Laboratory FIN B-0233
 GRNL/RCD/NEES-8 80/05/08 3pp
- 8006130393 "LHR In-Plant Measurement Program Rept." informal monthly progress rept for Apr 1980
 MANDLER, J H EQ&O: Inc. FIN A-6075, 80/05/15 Spp
- BOO6160174 "Program for Standardized Analysis of Fuel Shipping Containers," quarterly rept for BOO101-0331. HHITESIDES:0.E. MESTFALL:R.H. Oak Ridge National Laboratory. FIN B-0172. ORML/CBD/INF-80 80/05/01 Spp
- 8006170330 "Physical Protection of Nuclear Facilities," monthly progress rept for Apr 1980 CHAPMAN, L. D. Sandia Laboratories FIN A-1060. 80/06/02 Epp
- 8006170705 "Experimental Evaluation of Ventilation Sys Components During Large Pressure Pulses," informal monthly progress rept for Apr 1980 GREGORY,W 8 Los Alamos Scientific Laboratory. FIN A-7028 80/05/20, 3pp.

- 800617070B "Characterization of Radionuclide Contamination Throughout LWR Power Stations." informal monthly progress rept,800411 ROBERT80N,D E Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2279 80/04/11
- 8006170716 "Impact of Decontamination on LWR Radwaste Treatment Sys & Decontamination as Precursor to Decommissioning," informal monthly progress rept for Apr 1980
 PERRIDOL D Battelle Memorfal Institute, Pacific Northwest
 Laboratory FIN B-2303 80/05/15 3pp
- 8006170721 "BHR Blowdown/Emergency Control Ctr Program Progress."
 monthly ltr for Apr 1980
 BURNETTE, G W General Electric Co NRC-04~76-215 80/05/12 13pp
- 8006180026 "Data Comparison of FLECHT-SEASET Boiloff Test 35557. Using RELAP4/MOD7." comparison rept UDBEN.D M E0&0 Idaho.inc FIN A-6037 E0G-CAAP-5152 80/05/31
- 8006180038 "Reactivity Initiated Accident Test Series, Test RIA 1-4," quick look rept HARTINGON, A R , EL-GENK, M.S , FUKUDA, B K EG&G Idaho, Inc FIN A-6041 EGG-TFBP-5146 80/05/31 53pp
- BOO6180097 "Quick Look Rept for Semiscale Mod-3 Small Break Tests S-83-P1.8-83P-P2 & S-88-P7." BINOMAN.8 E , FAUBLE,T J , HEWITT,J R E0&0 Idaho,Inc FIN A-6038 E0Q-BEMI-5137 BO/04/30 48pp
- 8006180261 "Rept on New BWR Feedwater Nozzle/Sparger Design by GE." informal rept SUBUDHI.M., REICH.M. Brookhaven National Laboratory FIN A-3122 BNL-NUREO-26299 79/12/31 25pp
- 8006180267 "Bafeguards for Proliferation Resistant Fuel Cycles," informal monthly itr repts for Nov 1979 through Apr 1980 CALDHELL, J J Brookhaven National Laboratory FIN A-3221 80/06/04 16pp
- 8006180306 "Test Prediction for Samiscale Mod-3 Small Break Tests 8-88-P3 & 8-88-P4 " FIREMAN, C. P. E0&0 Idaho, Inc. FIN A-6038 E00-8EMI-5139 60/04/30
- 8006180540 "FLECHT SEASET," monthly status rept for Apr 1980 MASSIE:H W Westinghouse Electric Corp. NRC-04-77-127 80/04/30
- B006190045 "Environ Statements Project." monthly progress rept for Apr 1980 ZITTEL.H E Oak Ridge National Laboratory FIN 8-0001 ORNL-ED/EIS-129 80/04/30, 5pp
- 8006190060 "Forecasting Electricity Demand by State & by Util Svc Area:" progress rept for Apr 1980 CHERN.W S. Dak Ridge National Laboratory FIN 8-0190-8 DRNL/ED/EAB-BO/ 80/05/11 3pp
- BOO6190070 "Effect of Dispersed Condensed Phase on Rayleigh-Taylor Instability of Gas-Liquid Interface." informal rept MOGIYNSKI.JR : QINSBERG, T Brookhaven National Laboratory FIN A-3024. BNL-NUREG-27581 BO/03/31 41pp
- 8006i90079 "Annual Rept on TRAC Independent Assessment at BNL," informal rept SAMA,P, ROHATOI,U S., NEYMOTIN,L Brookhaven National Laboratory FIN A-3024 BNL-WUREG-27580 B0/01/31 40pp
- 8006190685 "Code Development & Analytis Program Parametric Btudy on Cladding Surface Rewet," technical rept TBALC. EO&O Idaho,Inc FIR A-6278. EGG-CDAP-5149 80/04/30
- 8006200014 Paper entitled, "Gorrelation of Local Heat Flux from Inclined Vol-Heated Pools in Bubbly Flow," to be presented at 19th Natl Heat Transfer Conference OREENE, O A, ABUAF, N, JONES, WC Brookhaven National Laboratory BNL-NUREG-27561 80/06/18 9pp
- 8006200017 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Bypass Lines & Pipes in BWR Piping Sys." progress rept for 800428-0523 YEAGER: L. Daedaleam Associates, Inc NRC-04-78-242 80/06/04 1380

- B006200018 "Biocide Byproducts in Aquatic Environs," quarterly rapt for Jan-Mar 1980 BEAN,R 8 Battelle Memorial Institute, Pacific Northwest Laboratory B0/03/31 3pp
- 8006200021 "Safeguards Analysis for Byproduct Matls & Small Quantities of BNM," monthly progress rept for Apr CHESTER.R D . KANAK.K K . RANDOLPH.M L Dak Ridge National Laboratory FIN B-6108 DRNL/HASRD-79 80/05/15 6pp
- 8006200022 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects," monthly highlights for Apr BARI,R A Brookhaven National Laboratory FIN A-3000 80/05/09
- 8006200023 "Assessment of Radiation Doses Resulting from Releases of Rn-222 & Ra-226 from U Mining & Milling Activities," monthly progress rept for Apr TRAVIS.C C . MCDOWELL-BOYER. WATSON, A P Oak Ridge National Laboratory FIN 8-0281 ORNL/HASRD-80 80/05/15 4pp
- 8006200025 "Thermal Hydraulic LMFBR Safety Experiments," Apr monthly highlight ltr GINBBERG.T Brookhaven National Laboratory FIN A-3024 80/04/30 App.
- 8006200026 "HTGR Safety Program," monthly highlights ltr for Apr 8ASTRE, C Brookhaven National Laboratory FIN A-3016 80/05/09 500
- B006200027 "Evaluation of LWR Residual Heat Removal Under Accident Conditions Technical Assistance Reactor Projects," monthly highlights for Apr. BARI.R A Brockhaven National Laboratory FIN A-3315 80/05/09
- 8006200031 "RAMONA Code Mod & Evaluation," "IRT & RETRAN Code Mod & Evaluation" & "Bimulator Model Evaluation," Apr monthly highlight ltr.
 LEVINE,M M Brookhaven National Laboratory FIN A-3014 80/04/30
- 8006200041 "IFA-430 Fission Product Measurement Bys Description & Scoping Yest Results, Thermal Fuels Behavior Program." preliminary rept APPELMANS, A D , DAOBJARTSSON, B EQ&Q, Inc FIN A-6014 EGG/TFBP-5026 79/12/31, 43pp
- 8006230096 "Div of Reactor Bafety Research GRNL Programs." Apr 1980 monthly highlights MYNATT.F.R Oak Ridge National Laboratory 80/05/10. 34pp
- 8006250201 Paper entitled, "Analysis of Passive Ex-Vessel Core Retention Device During Postulated Core Helt Event " PRATT.W T. OASBER, R D Brookhaven National Laboratory BNL-NUREG-27594 80/06/18 Bpp.
- 8006250338 "Bandia Core Melt & Separate Effects Program Progress." monthly ltr for May 1780 BERMAN, M Sandia Laboratories 80/06/02 12PP
- 8006250342 "Integration of Nondestructive Examination & Fracture Mechanics," monthly rept for Apr 1980 BECKER,F L Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2289 80/05/27 19pp.
- 8006250345 "Evaluation of Docket Files of Terminated Licen's" monthly progress rept for Apr 1980 MCLORAY, C.F. DICKERSON, H W Oak Ridge National Laboratory. FIN A-9085-7 ORNL/HABRD-77 B0/04/30 14pp.
- 8006250349 "Impact of Decontamination on LWR Radwaste Sys & Decontamination as Pracursor to Decommissioning," informal monthly progress rept for May 1980 PERRISON. D Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2303 80/06/03 3pp
- 8006250352 "Long Level Activation Products in Reactor Matis," informal monthly progress rept for Apr 1980 EVANS, J C Battella Memorial Institute. Pacific Northwest Laboratory FIN 8-2296 80/05/05 App.
- 8006250365 RIL-070
 Research Info Ltr 70 submits results of first Dfc of Nuclear
 Regulatory Research sponsored independent assessment of LOCA
 code, RELAP-4/MOD6
 BUDNITZ,R, J Office of Nuclear Regulatory Research, Director
 80/05/22 23ps

- 8006240015 "LOCA Test Series Test TC-1," test results rept YACKLE.T R . WATERMAN, M E . MACDONALD, P E EQ&Q, Inc FIN A-6041 EQQ-TFBP-5068 80/05/31 118pp
- 8006260020 "Scaling Criteria & Assessment of Semiscale Mod-3 Scaling for Small Break Loss of Coolant Transients "
 LARBON.T K . ANDERSON.J L . SHIMECK.D J E0&0, Inc FIN A-6038 E0G-SEMI-5121. 80703/12 188pp
- 8006260025 "Inventory of High Level Nuclear Wastes in US Govt High Level Waste, Existing Commercial High Level Waste, Existing Commercial Spent Fuel & Projections of Commercial Spent Fuel " MAJUMDAR, D., INDUSI, J.P. Brookheven National Laboratory FIN A-3158, BNL-NUREG-27817 80/04/30 157pp
- 8006260031 "Fuel Code Assessment Data Sample Rept "
 CHAMBERS,R., HAMPTON,N L., LAATS,E.T E0&G, Inc FIN A-6046
 E0G-CAAP-\$114 80/02/27 40pp
- 8006260035 "Data Comparison of FLECHT-SEASET Reflood Test 31504 Using RELAP4/MOD6 & RELAP4/MOD7 GODEN.D H EG&G. Inc FIN A-6039 EGG-CAAP-5162, B0/05/31, 43pp
- 8006260037 "Guick-Look Rept on LOFT Nuclear Experiment L6-5 " REEDER, D.L. EG&G, Inc. FIN A-6048. EGG-LOFT-5165. 80/06/30,
- 8006260039 "Test Prediction for Semiscale Mod-3 Test 8-88-4 Small Break Test Series " STEINER,U L. SNIDER,D M EG&O, Inc FIN A-603B EGG-SEMI-5047 79/10/31 62pp
- 8006260042 "Semiscale Small Break Driftice Calibr Tests." CDZIUDL,J M., BLAKELEY,J E. EQ&O. Inc FIN A-6038 EQG-SEMI-5090 80/01/31 29pp
- 8006260046 "Core Reflood Dynamics Code FLOOD4," interim rept. SHUKMAY.R W EG&G, Inc FIN A-6038. EGG-SEMI-5038 79/10/31
- 8006260425 "BWR Refill Reflood Program." tenth monthly rept May 1780 BURNETTE. G W General Electric Co NRC-04-79-184 80/05/31 15pp.
- 8006270078 "Monitoring for Compliance w/Decommissioning Criteria," task progress rept.
 DICKSON,H W. LANTZ,P.M., HOLDMAY.C F. Dak Ridge National Laboratory FIN A-9085-7 ORNL/MASRD-78 80/05/31 77pp
- BO06300171 "TRAC Accessment & Model Development," monthly highlights for Apr 1980

 BAHAJP Brookhaven National Laboratory FIN A-3215 80/04/30 600
- 8006300183 "Analysis of Hypothetical Accidents Resulting in Core Meltdown:" progress rept for May 1980 DENNING,R B . CYBULSKIS.P . BAYBUTT,P Battelle Memorial Institute. Columbus Laboratories FIN A-4067 80/06/13 9pp
- 8006300189 "Steam Generator Tube Rupture Lodine Transport Mechanisms," progress rept for May 1980 DENNING,R S. Battslie Hemorial Institute, Columbus Laboratories, NRC-04-76-293 80/06/13. 4pp
- 8006300204 "Nuclear Power Plant Design Concepts for Sabotage Protection," Informal progress rept. Oct-Dec 1979. ERICERON.D M Sandia Laboratories FIN A-1210 80/01/25 14pp
- 8006300211 "Muclear Power Plant Dasign Concepts for Sabotage Protection," informal progress rept, Jan-Mar 1980 ERICSON, D.M. Sandia Laboratories. FIN A-1210 80/06/02 7pp
- 8006300215 "LWR Thermal Hydraulic Development Program," monthly highlights for Apr 1980 ABUAF.N. Brookhaven National Laboratory. FIN A-3045 80/04/30
- 8006300218 "Nuclear Power Plant Design Concepts for Sabotage Protection," informal progress rept. Jul-Sept 1979 ERICSON, D.H. Sandia Laboratories. FIN A-1210 79/10/25 10pp
- 8006300234 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for Apr 1980. BULLISCHECK.T, VAN RODYEN.D Brockhayen National Laboratory FIN A-3208 80/05/19 7pp

8006300298 "Stds & Guidelines Pertinent to Development of Decommissioning Criteria for Sites Contaminated W/ Radioactive Matl " DICKSON: H W Oak Ridge National Laboratory KORNL/DEPA-4 UC-70 56рр

8006300301 "Evaluation of PBF LOFT Lead Rod Test Results Concerning Surface Thermocouple Perturbation Effects," internal technical rept CARBONEAU, M L . TOLMAN,E L. EG&Q Idaho,Inc FIN A-6048 LO-00-79-10B 80/02/28 122pp

8006300455 "US Std Problem 10 Preliminary Rept," comparison rept DUBBE,C A . LACHANCE, J L EGSO Idaho, Inc FIR A-6048B EEQ-CAAP-5134 80/04/30 72pp

8004300500 "Monitoring for Compliance W/Decommissioning Criteria." DICKSON: H W , LANTZ: P M , HOLGWAY, C F Oak Ridge National Laboratory FIN A-9085-7 ORNL/HARRD-78 80/05/31 7pp

8006300578 "Noise Diagnostics for Safety Assessment Continuous On-Line Reactor Surveillence Sys," foreign travel rept SHEENEY.F J Gak Ridge National Laboratory FIN B-0191 ORNL/FIR-843 80/05/27 15pp

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8006200572 Forwards "Post-Test Analysis of LOFT Loss-of Coolant Experiment L2-3 "
KAUFMAN N C EG&O Idaho, Inc 80/03/26 3pp

SECY POSITION PAPERS BEFORE THE COMMISSION

SOCACOURSE SECVATUROSA

006020391 SECY-77-03BA
Submits analysis of need for further protection of
Category II & III math in transit Recommends approval of
Alternative 2 re amend of current NRC regulations. NRC should
prepare alternative for publication in FR
DIRCKSIH J. Office of Nuclear Material Safety & Safeguards
79/10/23 28pp

outswards bety--M-142
Recommends Commission approval of FR publication of public comment amend to 10CFR73 re physical protection of Category II & III math Table categorizing nuclear math encl BMITH-CV Office of Nuclear Material Safety & Safeguards 78/03/09, 14pp

-8004020530 Discusses SECY-77-798.NRC & intl physical protection stds Commission approves general NRC approach & recommends development of appropriate rules Matl related to BECY-78-142 CHILK:S J Office of the Secretary of the Commission 77/06/30

8004030118 BECY-77-283A

DUGGIOTH SECT-77-283A

Recomment amends to iOCFR73 to provide attempthemed physical protection against radiological sabotage & theft of strategic BNM Proposed rule, draft press raizase & EIA enci.

SMITH.C.V Dffice of Nuclear Material Safety & Safeguards MINQUE,R B Office of Standards Development, Director 77/06/17.

--B004030120 Comments on 770401 paper re amends to 10CFR73 to provide strengthened physical protection against radiological sabotage & theft of strategic BNM Neither EIA nor statement of considerations is fully explanatory BTRAUSS.P L Office of the General Counsel 77/06/07 5pp

8006040284 Forwards and use statement for GA Co 770211 application for license to export research reactor fuels to Iran MOHRY.H R Ownerel Atomic Go (subs of Gulf Di) Co) 77/03/02

--B004040258 Forwards Form NRC-7. Justification Analysis, in support of 770211 application for license to export fuel elements to Iran Insertion af new fuel will permit continued operation of reactor for research purposes.

MORRY, W R General Atomic Co (subs. of Guif Cil Co) 77/02/11.

--8006040264 Application by GA Co for license to export 24 4 kg U-235, contained in 26 2 kg U. to Iran NRC draft ltr to GA Co encl HOWRY, W R General Atomic Co (subs of Guif Dil Co) IEL-938 78/07/18 2pp

8006060215 Transcript of B00515 public meeting in Bethesda, MD rewithholding of NRC spent fuel coute info from public disclosure Pp 1-34 * Commission* B0/05/15 35pp

800.6090427 Notification of contract execution "Study of US Nuclear Health & Bafety Info Dissemination to Foreign Countries," awarded to Franklin Inst HEDROM.1. A K. Administrative Contracts Branch FIN B-1648 NRC-08-80-338 80/05/28 1p

--8006090432 Contract "Study of US Nuclear Health & Safety Info Dissemination to Foreign Countries," awarded to Franklin Inst RFP RB-DIF-80-338 encl MATTIA,M J Administrative Contracts Branch FIN 9-1648 NRC-08-80-338 60/05/28 56pp

~~B00A09043A SECY-78~3A5

006990426 SECY-78-369
Requests Commission views on results of studies & recommendations re health & safety Considerations in NRC reactor licensing & nuclear assistance programs Recommends Commission approve encl analysis, SHEA.J R. Office of International Programs, Director 78/07/03

--8006090437 "NRC Staff Analysis of Health & Safety Considerations in Reactor Exports & Assistance Programs " * Commission 78/06/28 55pp

8006120057 Weekly info rept for wk ending 800523 REHM.T A Office of the Executive Director for Operations 80/05/29 35pp

8006120165 Responds to FOIA request for SECY-78-137 Document is available in DC PDR.
FELTON, J M Division of Rules and Records NRC 80/06/03

8006120167 FOIA request for SECY-78-137
JOHNSON C Texas Public Interest Research Group 80/05/07 in

JUNIZUSAN SECT-80-238
Forwards Executive Branch views on proposed exports of fuel & components to India & recommends preparation of order & cover ltr to President noting that applicable export criteria have not been met

SHEA-J R Office of International Programs, Director 80/05/09

--8006120361 Application by Edlow Intl Co to export 487 3 kg U-239, to India Govt of India 780911 ltr to DOE encl. * Edlow International Co 78/09/20 3pp.

-BOO6120365 Confirms 800111 teleph re expedited issuance of license t export traversing in-core probe to India No spare probes available for scheduled replacement at Tarapur Atomic Power Station.Unit 1 WILSON.B D General Electric Co 80/01/11 1p

8006120407 Transcript of 800528 afternoon Affirmation Session 80-25 re 8ECY-A-80-74 in Washington DC Pp 1-3 * Commission 80/05/28 3pp

8006120422 Transcript of 800315 briefing in Bathesda.MD re upgrade of operations ctr Pp 1-73 Morning session & Cummission. 80/05/15 73pp

B00A120425 SECV-80-235

006120425 RECY-80-235
Recommends issuance of license to Reuter Stokes.Inc to export two ionization chambers to Venezuela.License request forwarded for Commission review because proposed export is destined for country w/o previous authorization BHEA.J R Dffice of International Programs, Director 80/05/07

--8006120430 Submits Executive Branch views re application by Reuter Stokes, Inc for license to export two ionization chambers to Venezuela, Recommends that license be issued NOSENZO, L. V. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/04/16. 3pp

8006120468 SECY-80-2388

JOALSONGO SECTION-2388
Recommends that Commission consolidate Applications
XCOM-0376, XCOM-0381 & XCOM-0395 w/applications listed in
SECY-80-238, for revisus purposes Also recommends that
Commission hote receipt of GE request to amend XCOM-0240
SHEA, J. R. Office of International Programs, Director 80/05/15

- --8006120473 Submits Executive Branch views re application by Byron Jackson Pump Div for license to export components & parts to India Recommends that license be issued NOSENZO, L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/05/13 2pp
- --B006120477 Submits Executive Branch views re application by Carpenter Technology Corp for license to export 160 Zircalog-4 channels to India Recommends that license be issued NOSENZO.L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/05/13 2pp
- ---8006:20482 Submits Executive Branch views re application by Pacific Pumps. Inc for license to export parts & components to India Recommends that license be issued NOSENTU.L V State.Dept of. Bureau of Oceans & Internat
- --8006120485 Responds to question re safety significance of pending export of Tarapur components If licensing action on pending applications continues to be withheld, impact would be more adverte than any single export treated in isolation SHEA.JR Office of International Programs, Director 80/05/08 80/05/08

8006160207 SECY-80-263
Requests review of encl Westinghouse applications for license to export two power reactors to Taiwan SHEA,J R Office of International Programs, Director 80/05/22

8006170809 Transcript of 800516 discussion of SECY-80-230 in Washington, DC Pp 1-30 Morning session * Commission 80/05/16 31pp

8004180117 SECY-80-219

D04180117 SECY-80-219
Suggests procedures for increased Commission involvement in major decisions of Ofc of Nuclear Reactor Regulation. Ofc of Nuclear Hatl Safety & Safeguards & IE Recommends meeting to discuss options set forth in paper BICKWIT, L. Office of the General Counsel BO/04/27 9pp

- ---8006180123 Discusses 791226 request by Chairman Ahearns for views on increased Commission involvement in significant regulatory actions Proposal might lead to increased opportunities to run afoul of separation of function restrictions BHAPAR.H K Office of the Executive Legal Director 80/01/18
- ~-BOOÁIBOI31 Discusses 791226 memo from Chairman Ahearns re direct Commission involvement in licensing decisions Commission can participate to greater degree in decisionmaking, Max benefit would arise if Commission participates in hearing process DIRCKB.W J. Office of Nuclear Material Safety & Safeguards BO/OZ/21 18pp
- ---8006180142 Transcript of 800515 discussion of SECY-80-219 re Commission review procedures in Bethesda.MD Pp 1-48 Afternoon session # Commission. 80/05/15 49pp

8005180125 Transcript of 800530 Affirmation Session 80-06 in Washington DC Pp 1-2 * Commission 80/05/30 3pp

--8006180132 SECY-80-182E Recommends approval of encl revised draft order Encl PA Bradford separate statement to be appended to order BICKWIT.L Office of the General Counsel 80/05/29 9pp

- --8006180138 Responds to 800324 itr to J Ahearne re problems of evacuating large populations in short period of time. Program of upgrading emergency planning is being carried out by NRC teams who visit each site of operating nuclear plant DENTON.H R Office of Nuclear Reactor Regulation. Director 80/04/29 2pp.
- --8006180149 Elaborates on concerns expressed in 800102 ltr re need for practical evacuation plans around nuclear power sites Problems of evacuating large populations is short time have been underestimated Requests open hearings on issues WOLF.B Affiliation Unknown 80/03/24 2pp

8006190127 SECY-80-169

JOA190127 SECY-80-149
Recommends approval of outline of ACRB participation in rulemaking Perticipation broken down into initiation of rulemaking, rule development rulemaking hearings & effect of delegation of rulemaking powers to Ofc of Stds Development BICKWIT, L. Offic's of the General Counsel 80/03/31 App

- --8006170130 Ack receipt of 800109 ltr re ACRS participation in rulemaking re storage & disposal of radwaste Requests 60-day comment period PLESSET.M S ACRS -- Advisory Committee on Reactor Safeguard: rioc S ACRS - Advisory Committee on Reactor Safeguards ip 80/01/15
- --B004190133 Proposes ACRS enter proceeding re storage & disposal of radwaste as commenter & adviser after statements & cross-statements filed by parties AHEARNE.J F Commission B0/01/09 1p
- 8006200343 Transcript of 800523 open Affirmation Bess'on 80-24 in Washington DC re SECY-A-80-4A & SECY-80-202 Pp 1-3 a Commission 80/05/23 4pp

--8004200348 SECY-80-202

DOAZOUGHB SECY-80-202 Discusses role of NRC in waste confidence proceeding Recommends issuance of proposed memorandum & order Draft memorandum & order enci BICKNITY.L Office of the General Counsel PA/04/24 App

8006230089 Responds to FOIA request for SECY-75-429 Forwards document W/o encl FELTON.J M Division of Rules and Records 80/06/16 in

8006250025 Transcript of 800612 discussion & vote on affirmation item in Mashington DC Pp 1-15 Draft orders & separate views of Commissioner Bradford encl * Commission 80/06/12 35pp

--B006250030 SECY-B0-271A

Towards draft revision to TMI action plan statement of policy reflecting changes made as result of 800606 Commission meeting mode to language & minor editorial BICKWIT.L Office of the General Counsel, 80/06/ii iipp

8006300535 Add1 response to FOIA request for rule banning environ impact rept analysis of possible risks in event of major accidents at nuclear reactors Forwards documents listed in FELTON, J.M. Division of Rules and Records 80/06/17 2pp

--8006300546 Staff requirement memo re 800416 open meeting in Hashington, DC to discuss SECY-80-131, "Accident Considerations Under NEPA" Commission requested that personnel consider methods of screening plants in early const stage CHILK,8 J Office of the Secretary of the Commission 80/04/24

8006300575 SECY-80-214

JDA3009/5 SECY-80-214
Requests Commission approval to publish advanced notice ^*
proposed rulemaking on Tech Specs New Tech Specs sys.
Congressional ltr & preliminary value-impact statement encl
DENTON-H R Office of Nuclear Reactor Regulation, Director,
80/04/28 35pp

STATE PROG STATE PROGRAMS

8006020003 Discusses personal evaluation of U mill training course ODRDON,C Office of State Programs, Director 80/05/13 2pp

8000020006 Forwards "Preliminary Study on Disposal of Low Level Radwaste Generated in IL " KERR.O W Office of State Programs, Director 80/05/14 1p.

--8006020009 "Preliminary Study on Disposal of Low Level Radweste Generated in IL." * Illinois: State of 80/04/14 41pp

8006020012 Notification of 800720-22 meeting in Seattle,WA to discuss continuing ed credit limit on technical meetings
LUBENAU,J O Office of State Programs, Director, 80/05/14 ip

8006020026 Forwards economic data re generation of electric power, requested by State of NC Public Utils Commission 800428 ltr. RYAN, 0 Office of State Programs, Director 80/05/16. 3pp

8004020224 Forwards draft matl for review prior to 800403-04

--8006020225 TTC-0123 NGOUVED 110-0123
"Contribution to Emergency Response Planning Guidance
Document," draft for comment
MCGLURE, J D Sandia Laboratories, 80/05/16 47pp

- 8004030143 Responds to 800428 ltr to Benetor Nelson re tailing at United Nuclear Church Rock Facility U mill operations in NM are licensed by State of NM KERR.OW. Office of State Programs. Director 80/03/14 lp
- 8006030215 Responds to NRC 800222 ltr re review of program during Jan 1980 Ran on air transportation has been included on SNM licenses authorizing Pu-Be sealed sources BABBLP D Kentuciy, State of 80/04/18 4gp
- 800&040158 Forwards several documents in response to 800411 itr from City of Portland, OR re-safe mgt of bazardous matls W/o documents RYAN, RO Office of State Programs, Director. 80/05/16. ip
- --BO06040160 Requests into re NRC responsibilities, authorities & programs for safe mgt of hatardous matis City of Portland, DR is preparing emergency response & other preventive plans to insure public protection from hazardous matis accidents ROBISON, R W Oregon, State of BO/04/11 2pp
- 800&050499 Requests confirmation of telex advising of escalation of costs associated w/radiological emergency response operations courses KERRO M Office of State Programs. Director. 80/04/07. ip.
- --BOO&050502 Requests add1 funding to cover escalating costs associated w/radiological emergency response operations courtes.

 OILPIN-J Federal Emergency Management Agency 80/04/04 ip.
- 8006050531 Advises that WB Mencrer has been appointed regional state liaison officer for Region 3 Responsibilities include coordination of communications between NRC & state & local goves in regulation of licensed nuclear metis & facilities KEPPLER.J Q Region 3. Chicago. Office of the Director 80/05/22 2pp
- 800505050 Notification of Tast Force on Emergency Planning for Transportation Accidents Involving Radioactive Matls 800503-04 maeting to work draft sections into first guidance document.

 MCCARTHY.E. Office of State Programs, Director. 80/05/15 2pp
- 8006070023 Forwards updated list of NRC resident inspectors to all state lisison officers of Agreement & Nonagreement States.

 WEISSBERG.8 Office of State Programs, Director. 80/05/21 7pp.
- 8006090430 Confirms discussion following NRC review of state radiation control program Program is adequate to protect public health & safety & is compatible to/NRC program Comments & recommendations encl
 KERR.G.W Assistant Director for State Agreements Programs
 80/05/13 5pp
- --8006090445 Confirms comments re NRC review of state radiation control program Program is adequate to protect public health & safety & is compatible w/NRC program KERR.0 W Assistant Director for State Agreements Programs 80/05/13.
- 8006090506 Advises that HB Mencrer has been appointed regional state liaison officer for Region 3 Responsibilities include coordination of communications between NRC & state & local govts in regulatory matters

 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/05/22
- BOCA070518 Advises that WB Mencier has been appointed regional state liaison officer for Region 3. Responsibilities include coordination of communications between NRC & state & local govts in regulatory matters.

 KEPPLER.J.G. Region 3. Chicago. Office of the Director. BO/05/22
- 8005090523 Confirms that WB Menczer has been appointed regional liaison officer for Region S. Responsibilities include coordination of communications between NRC & state & local govts w/interests in licensed nuclear matls & facilities KEPPLER, J O Region 3. Chicago, Office of the Director 80/05/22 2pp.
- 8006090527 Notifies that MB Mencrer has been appointed regional state limison officer for Region 3.Responsibilities include coordination of communications between NRC & state & local govts winterests in licensed nuclear matis & facilities KEPPLER.J. O Region 3. Chicago. Office of the Director 80/05/22

- 800511040D Advises that WB Mencrer has been appointed regional state lideton officer for Region 3 Responsibilities include coordination of communications between NRC & state & local govts in regulatory matters KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/05/22 200
- 8006110404 Confirms discussion following NRC review of state radiation control program Program is adequate to protect public health & safety & is compatible w/NRC program Remaining vacancy should be filled as soon as possible KERR,O M Assistant Director for State Agreements Programs 80/05/16 2pp
- 8006120066 Advises that WB Menczer has been appointed regional state limison officer for Region 3 Responsibilities include coordination of communications between NRC & state & local govts in regulatory matters

 KEPPLER.J O Region 3. Chicago. Office of the Director. 80/05/22
 200
- 8006120408 Advises that WB Menczer has been appointed regional state liaison officer for NRC Region 3 Responsibilities include coordination of communications between NRC & state & local govts re regulation of NRC licensed metls & facilities KEPPLER.J G Region 3. Chicago: Office of the Director 80/05/22
- 8006120512 Confirms comments made at conclusion of state radiation control program review Program is adequate to protect public health & safety & is compatible w/NRC program Effort should be made to reduce number of overdue insps
 KERR, O W. Assistant Director for State Agreements Programs, 80/09/16 2pp
- 8006130342 Forwards IN State Highway Commission 1979 annual rept of personnel exposure in response to NRC 800129 request Respondent followed 1978 rept format. ELKIN.B L., CMENS.P L. Indians. State of 80/04/29. 2pp
- 8006180236 Forwards summary of 800416 meeting between NRC & NY State Energy Ofc rs transportation of spent nuclear fuel Requests to be tept informed of NRC progress re proposed changes to spent fuel transportation safeguard requirements BPATH.J P New York, State of 80/04/30. App.
- 80D6200051 Ack receipt of 800523 ltr re concerns about future role of Ofc of State Programs. Views will be considered in any reorganization which may affect Ofc of State Programs DIRCKS/W J Office of the Executive Director for Operations 80/05/28 1p
- --8006200061 Commends Ofc of State Programs for being most helpful, cooperative & responsive to state needs & concerns.

 HARRIBON, D W Kentucky, State of. 80/05/23 ip.
- 8006200206 Forwards 8,2358 & 800515 committee rept on bill. Bill is presently awaiting consideration by Senate.Page 8,Section 7(a) of bill contains ref to State of 80.W/o encls WEI89BERO.S. Office of State Programs, Director 80/06/04 1p
- B006200578 Forwards proceedings of 800220-21 meeting on low level radwaste Proposes to send copy to state & federal representatives & industrial participants to solicit recommendations.

 RYAN, R. G. Office of State Programs: Director. 80/05/23 1p
- BO06230003 Ack receipt of BO0512 ltr & State of SC Joint Legislative Committee on Energy rept State & local govts have responded to new emphasis on emergency planning broad by NRC & FEMA in generally cooperative & affirmative way, NUREO-0070 encl RYAN, R O Office of State Programs, Director 80/06/10 3pp
- 8006230075 Responds to request for comments re LA State Univ proposed method of low level waste disposal Exempt concentration requires clarification, Proposed method of disposal is not acceptable Forwards NUREO-0656. W/o encl KERR.O.W Assistant Director for State Agreements Programs 80/06/09.
- BOO6230137 Advises of nomination of JB Martin to serve as alternate for future meetings of State Planning Council on Radwaste Mpt Expresses appreciation for support of NRC participation on Council as nonvoting observer.

 AHEARNE, J. F. Commission 80/08/20. 1p
- 800623016B Informs of inability to review preliminary draft license impact analysis due to preparation of radiological assessment & tailings mgt evaluation NM Environ Improvement Div appears to be in compliance w/requirements MILLER, H J Uranium Recovery Licensing Branch 80/05/23 ip.

1

- BOO6230177 Recommends that individuals & corresponding agreement states listed in encl receive copy of MILDOS code & preliminary user guide for records W/o encl KERR.9 W Assistant Director for State Agreements Programs BO
- 8006230187 Forwards 800421 State of NM radiation protection regulations H/o encl KERR.C M Assistant Director for State Agraements Programs 80/06/09 ip
- B006230192 Advises that review of draft Revision 2 to Reg Guide & 4 is complete Agrees that revision is necessary

 KERR, O W Assistant Director for State Agreements Programs

 80/06/09 Ip
- 8006240106 Notifies that State of CO requests NRC assistance in evaluating significance of tritium contamination resulting from handling of foils by licensee Info requested on controls on removable contamination on source mounts KERR.G W Office of State Programs, Director 80/06/11 1p
- 8006240R15 Discusses State of NM request for assistance in review of Exxon & Mobil in situ projects Documentation of NRC corrective actions re WY Minerals in situ project required by 800611 KERR, G W Assistant Director for State Agreements Programs, 80/06/09 1p
- 8006240256 Forwards State of QA second quarterly rept re transportation surveillance program Requests comments
 JANICEK.M Office of State Programs, Director NRC-06-78-362
 80/06/03 2pp
- --8006240262 Forwards second quarterly progress rept, Jan-Mar 1980, re transportation surveillance INGRAM, W D Georgia, State of NRC-06-78-362, 80/05/13 34pp
- 8006240641 Advises that TX Time, Inc has agreed to cease distribution & repair of tritium backlit watches until license has been amended LUBENAU, J O Office of State Programs, Director 80/06/11 Ip
- 8006240643 Responds to 800206 ltr requesting technical assistance in testing low level radioactive liquid wastes for structural integrity Recommendations limiting risk assessment for tanks & rapid cleanup operation encl N/o encl
 KERR. G W Office of State Programs. Director 80/06/11 ip
- BO06250008 Discusses NRC 800118 & 0201 ltrs re leaking C-252 sources from Isotope Products Lab Ack receipt of 800229 ltr reporting investigation being made by Los Angeles County Health Dept Rept re C-252 sources encl, KERR.O W Assistant Director for State Agreements Programs 80/06/03 ip
- ~~8006250009 Forwards Washington Univ rept re leaking C-232 sources received from Isotope Products Lab Rept & sources sent to Isotope Products Lab METZGER, J Office of Inspection & Enforcement, Office of the Director 80/05/21. App
- 8006250014 Comments on NRC paper re emergency preparedness at facilities licensed by NMSS Early state input into development of criteria for preparation of emergency plan is desirable KERR: 9 W Assistant Director for State Agreements Programs 80/06/09. ip
- BOO6250115 Requests Region 3 rapt on investigation of licensee in Rosemont, NM, mounting rejected military gun sights containing radioactive metl on civilian handguns State of TX Radiation Control Branch requests list of persons who received sights KERR.G W Office of State Programs, Director BO/06/11 1p
- 8006230339 Summary of Task Force on Emergency Planning for Transportation Accidents Involving Radioactive Matls 800603-04 meeting in Washington, DC to provide extensive comments on draft sections written independently by Task Force members MCCARTHY, E Office of State Programs, Director 80/06/13 2pp
- 8006260065 Requests that Covernor Riley consider appointing new individual to replace L Priester NRC/state listson program set up to improve federal & state cooperation RYAN.R C. Office of State Programs, Director 80/06/05 1p

- 8006260132 Comments on State of NM Radiation Protection Regulation 3-800, requiring specific license for transportation of nuclear waste on highways Any license issued by State of NM should not conflict w/Sections 73 37 & 73 72 of 10CFR73 KERR.9 W Assistant Director for State Agreements Programs 80/06/07
- 8004260218 Forwards list of all NRC radioactive math licenses issued to persons in Commonwealth of MA in response to 800520 request List is current as of 800602 W/o anch ASSHLEY, EC Assistant Director for State Agreements Programs 80/06/09 ip
- 8006260219 Forwards "Interagency Task Force on Health Effects of lonizing Radiation - Rept of Work Group on Science," in response to request M/o encl SCHNEIDER, K N Office of State Programs, Director, 80/06/09 1p
- 8006300015 Discusses accompaniment of FL inspectors during 791217-18 insp of Scott Luminous. Inc in St Petersburg. FL Noncompliance noted air sampling program is inadequate & no records of daily radiation level surveys
 ASHLEY.FC C Assistant Director for State Agreements Programs 80/06/04 4pp
- 8006300044 Advises CA Dept of Health Svcs, Radiologic Health Section that CA company may be distributing imported tritium gun sights w/o proper licenses Requests assistance in determining whether company possesses radioactive matls KERR, G W Assistant Director for State Agreements Programs 80/06/09 ip
- B006300350 Ack receipt of 800211 assessment of State of CO law & regulations in conformance w/1978 UMTRCA Setting of equivalent stds & preparation of written environ analyses noted as major problem areas KERR.9 W Assistant Director for State Agraements Programs 80/06/09 2pp
- 8006300449 Forwards TVA 800213 rept re Camma Industries 791228 shipment of radioactive matl to TVA, Muscle Shoals, AL Requests results of any action taken by State of LA KERR, 6 W Assistant Director for State Agreements Programs 80/06/03 ip
- --B006300457 Bubmits rept re Gamma Industries 791228 shipment of radioactive matl to TVA. Muscle Shoals. AL, in response to NRC B00205 request Details of noncompliance provided Shipment received on B00116 MAXMELL. R B Tehnessee Valley Authority B0/02/13 5pp
- 8006300537 Confirms discussion w/A Bimanis re review of state radiation control program for wk of 800714-18 Review will include field evaluations of state inspectors on 800714 KERR.O W Office of State Programs, Director 80/06/11 1p
- 8006300540 Forwards summary of NRC insp-enforcement activities re transportation of nuclear waste for Mar-Apr 1980 Next rept will cover May-June 1980; w/quarterly repts thereafter KERR, G. M. Assistant Director for State Agreements Programs 80/06/03 1p
- --8006300549 Forwards summary of insp-enforcement activities re transportation of nuclear wasts for Mar-Apr 1980 Rept should be forwarded to States of SC.WA & NV Next rept will cover May-June 1980.w/quarterly repts thereafter SNIEZEK,J H Division of Fuel Facility & Materials Bafety B0/05/28 5pp
- BOO6300542 Responds to BOO812 ltr re request for technical assistance on Exxon Corp L-BAR in situ leach pilot project. No significant assistance available to perform meaningful review Techn project license & assessment similar KERR, G W Office of State Programs, Director BO/06/11 ip
- BOO6300580 Forwards add1 NRC requirements resulting from investigations of TMI-2 that are required of utils w/CPs before issuance of OL Descriptions & schedules will be available in NUREG-0660. MINNERG W Division of Safety Technology 80/06/19 50pp
- 8006300647 Forwards Proposal Evaluation Panel rept for RFP RB-OBP-304, "Safety Aspects of Industrial Radiography for State Ragulatory Personnel." Recommends that written clarification be requested of two bidders in competitive range KERR.G W Office of State Programs, Director. SA/ECA 80/06/03 Bpp
- 8006300678 Forwards list of median staff salaries for Agreement States per request DDDA-R J Assistant Director for State Agreements Programs 80/06/23 2pp

- 8006300680 Forwards annotated list of current licensing guides.

 licensing guides & refs available to license review & inspguide for teletherapy W/o encl
 LUBENAU.J D Assistant Director for State Agreements Programs
 80/06/23 1p
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8006020010 Notification of 800521 meeting w/GE to discuss fuel mechanical design & reload licensing Proposed agenda encl IPPOLITO,T A Operating Reactors Branch 2 80/05/19 3pp
- BOO6020127 Summary of BOO505 meeting w/EPRI to discuss considerations of significant transients, frequencies of transients & testing frequencies of electrical portions of scram Bys Includes EPRI analyses.NRC comments & list of attendees THADANI,A C Generic Issues Branch BO/O5/20 25pp
- 8006020267 Forwards proprietary responses to Guestians M020 28 & M020 46 re NEDE-21051, "Mark II Dynamic Forcing Function Info Rept " Response withheld (ref 10CFR2 790) BUCHHOLZ, R H General Electric Co RHB 040-80 80/05/29 2pp
- 80D6020268 Discusses 800417 meeting between representatives of Turbine Oenerator Disc Integrity Task Force & MRC ne task force position on Category A units scheduled for insp STIEDE.W L. Commonwealth Edison Co. 80/05/27 1p
- 8006020270 Forwards update to Round 2 question responses re NEDE/NEDG-21061. "Mark II Dynamic Forcing Function Info Rept." BUCHHOLZ,R H General Electric Co RHB 041-80 80/05/29 75pp
- BOO6030308 Advises of forthcoming visit to Dute Power Co on 800610 retests conducted by Bouthwest Research Inst per methods stated in 800805 ltr
 HALL, RE Brookhayen National Laboratory. 80/05/22 is
- 8006040120 Forwards request for add1 info re proposed 800401 Revision 4 to util topical rept.TVA-TR75-1A. "GA Program Description" HAA85.WP Quality Assurance Branch. 80/05/20 5pp
- 8006040223 Forwards responses to NRC 800124 ltm re Barton Lot Number 2 transmitters Info required to complete review of Westinghouse MCAP-74101 rept Proprietary info withheld (ref 100FR2 790) Affidavit encl ANDERSON, T M Hestinghouse Electric Corp NB-TMA-2248 80/05/21 1900
- 8006060207 Requests that BG-TGP-1, Section 3, "Design Control," be revised to meet enci position statement re record retention requirements of ANSI N45 2 9 Suggests inclusion of flow chart that identifies each step of design process HAASB, N P Quality Assurance Branch 80/05/14 2pp
- 8006060296 Discusses review of TMI-2 Bulletins 5 Orders Task Force rept on Hastinghouse plants Several recommendations will not be included in final version; including accelerated NRC review of conservatism in LUGA calculations. ROSB; D TMI-2 Bulletins & Orders 79/12/04, 5pp
- 8305050300 Nonproprietary varsion of memo discussing long-term effect of setpoint mode made by B&W NSSS licensees in response to IE Bulletin 79-058; "Nuclear Accident at TMI-Suppl." Accurate assessment cannot yet be made.

 ISRAEL.S.L TMI-2 Bulletins & Orders IEB-79-058 80/06/03 2pp
- BOOA060372 Notifies NRC of early completion of two planned records storage action items Cantral Records Ctr at Boyers, PA now satisfies single atte storage requirements ANDERSON, T M Heatinghouse Electric Corp. N8-TMA-2249 80/05/27
- 800&060517 Discusses forthcoming generic safety evaluation for input to Bys Group re proposed operator action guidelines for early pump trip Draft evaluation should be available for final mgt review by 791031 RDSZTOCZY. Z. R TM1-2 Bulletine & Orders 1EB-79-05C, 79/09/27 ip
- B006060524 Requests info re encl draft request for addl info required to complete evaluation of responses for power operated relief valve/safety valve actuation & reactor trip frequency CAPRA, R TMI-2 Bulletins & Orders. 79/09/24 3pp.

- 8006060613 Forwards munthly rept on licensing case reviews for NRC Matls Engineering Branch HIDRIO,R D Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2172 80/05/15 5pp
- 8006070146 Accepts NEDD-10705-3 Amend 3: "High Pressure Core Spray Sys Power Supply Unit:" qualification test results of high pressure core spray diesel generator for described generator PARR. D D Light Water Reactors Branch 3 80/04/07 2pp
- 8006090434 Notification of 800625 mgt meeting w/EPRI in Gilver Spring, MD Requests suggested items for agenda by 800528 LARKINS.J T Program Coordination Branch 80/05/23 2pp
- --8006090439 Summary of 600326 mgt meeting w/EPRI in Dethesda.MD to Joint reactor safety research programs Discussed possibility of modifying LOFT facility to get better understanding of reactor parameters

 LARKINS.J T Program Coordination Branch 60/05/20 3pp
- BOO611027R Submits suppl to 800222 ltr re organizational changes to be incorporated in NUBCO Nuclear Engineering & Operations Group effective 800401 & GA Program Topical Rept Nu-GA-1 COUNSIL,N G Northeast Utilities GA-3834 80/06/06 5pp
- --8006110281 "Organizational Relationship Between NUSCO Personnel Having Quality Related Functions " * Northeast Utilities 60/06/06 ip
- --800&110276 "Organizational Relationship Between NUSCO & NUPOC Fersonnel Having Quality Related Functions " * Northeast Utilities 80/04/06 1p
- 8006i103i9 Forwards NEDE-24822-P. "Mark II Improved Chugging Methodology," as part of Task A 16 of Mark II containment program Prompt review requested Rapt withheld (ref 10CFR2 790). BUCHHOLZ:R H General Electric Co MFN 109-80 80/06/06 1g
- 8006120390 Forwards assessment of BAH-1564, "Integrated Control Sys Reliability Analysis " Integrated control sys has relatively low failure rate, however aspects of plant control sys should be investigated for improvement SATTERFIELD,R M Instrumentation & Control Systems Branch, 80/05/09
- ---8006120394 Topical rept evaluation of DAW-1564, "Integrated Control Eys Reliability Analysis" Approves recommendations Broader study should be performed * Instrumentation & Control Systems Branch 80/05/09 6pp
- B006130320 Forwards solution to NRC benchwork Problems 1.323A & 4 for WECAN response spectrum analysis Description of WECAN pipe & elsow elements & post-processor COMSPC entl ANDERSON, T H Hestinghouse Riectric Corp NB-TMA-2250 80/05/29
- 8006160127 Advises that results of pretest prediction of HDR test V 31 will be incorporated into rept showing comparisons w/actual test results Multiflex model used for calculations Topical rept describing improvements will be submitted ANDERSON. T M Westinghouse Electric Corp , PWR Systems Div NE-TMA-2233 B0/05/29. 2pp
- BOOA170103 Forwards auxiliary feedwater sys revised Addl Short-Torm Recommendation 2.reducing 72-h endurance test for auxiliary feedwater test pump to 48-h Westinghouse & C-E licensees should be notified MATTHEWS.P R TMI-2 Bulletins & Orders 79/12/03 3pp
- 8006170398 Forwards nonproprietary version of MCAP-9726, "Westinghouse Technical Support Complex " Application for withholding proprietary into & affidevit encl Proprietary version withhold (ref 10CFR2 790)
 ANDERSON, T M Westinghouse Electric Corp NS-TMA-2261 80/06/13 13pp.
- --8006170360 WCAP-9726

 "Mostinghouse Technical Support Complex." nonproprietary
 version Proprietary version withheld (ref 10CFR2 790)

 GENNARD, D V , LITTLE, J L , LUCE, W L Westinghouse Electric Corp
 N8-TMA-2261 80/06/30 100pp
- 8006170535 Notifies that review of GA program topical rept complete No addl changes beyond Revision 3 pages transmitted on 790814 & 800125 required to make document current Requests approval of Revision 3 PERRY, JA Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/06/12 ip

ŀ

- 8006170666 Discusses insp plan & preparations re guide tube support pins from two or more domestic plants Ultrasonic insp demonstrated to be viable insp technique on support pins ANDERSON.T M Westinghouse Electric Corp., PWR Systems Div NS-TMA-2254 80/06/10 2pp
- BOO6170745 Discusses fire resistance upgrade measures outlined in Westinghouse BOO502 ltr re underground record storage facility Records ctr is acceptable for either temporary or permanent storage of duplicated/nonduplicated records HAABS.W P Guality Assurance Branch BO/06/02 2pp
- 8006170830 Discurses B&W allegation of possible conflict of interest in Instrumentation & Control Sys Branch review of BAM-1564 Info reveals that reviewers were not involved in rept preparation white employed w/B&W SATERFIELD.R M Electric, Instrumentation & Control Systems Branch 7011101
- ---8006170833 Discusses B&W allegation re possible conflict of interest during Instrumentation & Control Sys Branch review of BAW-1364 Matter will be investigated by R Satterfield No further action required CAPRA.R A TMI-2 Bulletins & Orders 79/10/26 ip
- 8006170839 Notification of 790718 & 19 meetings w/B&W & B&W owners group in Bethesda,MD to discuss small break LOCA analysis CAPRA,R A TMI-2 Bulletins & Orders 79/07/17 ip
- --8006170843 Provides items for discussion during 790719 meeting w/B&H auners group subcommittee for TMT-2 issues CAPRA:R A TMT-2 Bulletins & Orders 79/07/16 3pp
- 8006170876 Forwards summary of status & potential problems for C-E plants Meeting will be held 791024 to discuss issues KANE.N TMI-2 Bulletins & Orders. 79/10/23 4pp
- 8006180993 Forwards updated status of activities re B&W.Westinghouse & BWR plants Review of emergency procedure guidelines for small break LOCA must be completed by 791031
 KANE.W TM1-2 Bulletins & Orders 79/10/17 22pp
- B006190235 Responds to request for NRC review of Topical Rept BJNPQ-101, "Performance & Safety Features of Byron Jackson Primary Reactor Coolant Pump for LNRs." Rept acceptable for referencing in std or custom plant design applications DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/21 2pp
- BOO6200103 Notification 800512 meeting w/BNL & CRNL BNL will describe EPIPE computer program for pipe stress analysis Discussion will cover program capabilities & access STEPHENS,R M Mechanical Engineering Branch, 80/06/02 2pp
- 8006200549 Provides questions & comments for consideration in review of IE Bulletins 79-05C & 79-06C ROSB.D F TMI-2 Bulletins & Orders IEB-79-05C 79/09/13 9pp
- BOO6200556 Forwards updated status of activities for B&W operating plants re bulletin evaluations, compliance w/long-term requirements of NRC 1979 orders & implementation of NRC6-0578 items
 CAPRA,R A TMI-Z Bulletins & Orders 79/10/23 10pp
- 8006230242 Requests add1 info to substantiate appointment of C Dick as GA Manager for San Francisco Power Div in light of BQ-TOP-1 re qualification requirements for key mgt positions in quality groups

 HAASS.W P Guality Assurance Branch 80/06/05 1p.
- 8006240424 Forwards proprietary info responding to questions on XN-NF-512, "XN-3 Critical Power Correlation" Affidavit encl Proprietary version withheld (ref 10CFR2.790) URSLEY, 9 F Exxon Nuclear Co . Inc (subs of Exxon Corp) 0FO 100 80 80/06/18 11pp
- BOO6250100 Forwards proprietary & nonproprietary responses to NRC BO0125 request re XN-NF-79-6(p), "Exxon Nuclear Analysis of Fower Distribution Measurement Uncertainty for Westinghouse PWRs " Proprietary to Central Files only (ref 10CFR2 790) OW8LEY.0 F Exxon Nuclear Co , Inc. (subs of Exxon Corp) oFO 080 80 80/04/15 4pp
- --8006250105 XN-NF-79-6(NP)

 Nonproprietary version of Amend 1 to XN-NF-79-6(NP),

 "Exxon Nuclear Analysis of Power Distribution Measurement

 Uncertainty for Westinghouse PWRs "

 HDLM.J S , JAECH, J L , BUSSELMAN.O J, Exxon Nuclear Co , Inc

 (subs of Exxon Corp) 80/04/18 14pp

- BO06250356 Notification of B00617 meeting w/GE in Bathesda,MD to discuss ECCS model review LAUBENN Reactor Systems Branch B0/06/12 2pp
- 8006250357 Notification of 800616 meeting w/C-E in Bethesda.MD to discuss proposed core exit thermocouple sys LANIK.G Instrumentation & Control Systems Branch 80/06/11 2po
- 8006260081 Forwards NEDO-24257, "Generic Info for Barrier Fuel Demonstration Bundle Licensing," & GE 800515 transmittal ltr IPPOLITO,T A Operating Reactors Branch 2 80/06/10 Ip
- ---9005250084 Forwards NEDO-24259, "Opnoric Info for Barrier Fuel Demonstration Bundle Licensing "Requests completion of NRC review by mid-sept 1980 Summary of 800325 meeting w/NRC rebarrier fuels program encl ENGEL, R. E. Opnoral Electric Co. MFN-099-80 80/05/15 18pp
- --800626008B NEDD-24259
 "Generic Info for Barrier Fuel Demonstration Bundle
 Licensing"
 * General Electric Co NEDD-24259 80/05/31 27pp
- 8006300250 Advises that B&W LDFT pretest calculations required by Section 2 1 9 of NUREG-0578 are scheduled to begin 791115 CAPRA.R A TMI-2 Bulletins & Orders 79/10/17 2pp
- BO063D0415 Advises that no plants currently reference CENPD-177-P, "CEDNBR ~ Computer Gode for Transient Thermal Margin Analysis of Reactor Core," in support of DL Requests rept be withdrawn from NRC review & proprietary copies returned SCHERER.A E C-E Power Systems LD-80-034 80/06/23. ip
- BO06300443 Responds to B00225 ltr re mode to NEDE-20944-P, "BWR/4 & BWR/5 Fuel Design " Proposed changes can be included in approved version of both proprietary & nonproprietary repts MILLER, J. R Standardization & Special Projects Branch 80/06/18 ip
- BOOGSOD454 Ack receipt of NRC BOO523 ltr indicating containment of proprietary info in Topical Rept DNS-RSS-O01-P Requests prior notice of NRC intent to supply consultants w/Dow info or transmit info to other govt agencies KANUCH.B.K Dow Chemical Co. BO/06/19 1p

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8005130512 Forwards "Ocatechnical Design Data. Proposed Tailing Disposal Facility Expansion. Down Minding Co.Ford. WA" & drawing for assessment according to state request for tech assistance KERR. 0 W Office of State Programs. Director 16202. 80/04/28
- --8005130516 "Geotechnical Design Data Proposed Tailing Disposal Facility Expansion, Dawn Mining Co. Ford, WA " * Golder Associates. 16202 79/11/02 51pp.
- ---8005130517 "Tailings Disposal Project Contract 1.Excavation Stockpile Location & Details " * NUS Corp 16202 79/11/05 1p.
- --8005130322 "Tailings Disposal Project Contract 2.Liner Installation Plan & Sections." * NUS Corp 16202 79/11/06 lp
- 8006020562 Notifies that U Recovery Licensing Branch has completed review of proposed Martin-Trost Associates U ore upgrader project Applicant has postponed project indefinitely MILLER.H J Uranium Recovery Licensing Branch 80/05/07 ip
- BOO6020570 Forwards responses to questions & comments re Hansen Project tailings disposal, par discussion at 800417 meeting One oversized map encl
 THOMPSON,M A Cyprus Mines Corp 80-20 17-652 80/05/12. 45pp.
- 8006030024 Notifies of completion of U Recovery Licensing Branch review of Cotter Corp application for State of CD radioactive matl license to operate Schwartzwalder sorter ROTHFLEISCH.JE Uranium Recovery Licensing Branch 80/05/12 2pp
- 8006030030 Notifies of completion of U Recovery Licensing Branch review of project in response to owner request State 800208 ltr transferred tailings licensing authority to NRC. MILLERIH J Uranium Recovery Licensing Branch 80/05/08 ip

- BOC4030045 Notifies of completion of evaluation of Site B tailings area Guner BOO(3) Itr & State of CO BOO219 Itr indicate that site is not considered viable for tailings disposal ROTHFLEISCH.J E Uranium Recovery Licensing Branth BO/03/25 is
- 800.6030143 Responds to 800428 ltr to Senator Nelson re tailing at United Nuclear Church Rock Facility U mill operations in NN are licensed by State of NM KERR. 6 W Office of State Programs, Director 80/05/14 ip
- 8006040173 Supports Cotter Corp disposal procedures for contaminated wastes at Canon City U mill tailings impoundment Irregular shaped pieces should not be placed at site w/o precautions so liner is not penetrated NELSON.J. D Colorado State Univ 16238 80/04/21 ip
- 8006040179 Forwards summary of UDAD runs based on Hansen Project meterology & emission sources Results indicate exposures usil 1 be well below current stds
 THOMPSQN,D Cyprus Mines Corp 16244 80/04/28 3pp
- 8006040181 Forwards notes of 800220 oral presentation by appelants & intervenors of administrative appeal re vendor project Record is being reviewed for espected middle May decision W/o notes.

 PETERSON.R M Agriculture.Dept of, Forest Service 16237
- BOCACHOIGS Forwards proposed mods to criteria for cleanup of Ric Puerco United Nuclear Corp has not been able to clean Th-23O from arroyo in nine months High levels could be avoided by averaging greater areas BUNL.TE New Mexico, State of 1624O 80/04/23 4pp
- BOOA050207 Bubmits trip rept re BO0409 insp of ore sorter facility site & 800410 maeting on contents of amended radioactive matis license application
 ROTHFLEISCH. J Uranium Recovery Licensing Branch 80/05/07 App
- 8006060136 Forwards "Geohydrologic Investigation of Tailings Disposal. Rhode Ranth Prospect.McMullen County.TX." Rept prepared to answer questions raised by NRC re hydrologic aspects of returning tailings to mined-out pits
 DAVIS.O R Amecanda Co. Amecanda Copper Co Div 16298 80/04/28
- --8006060140 Advises of application for waiver of requirement to transfer land ownership to federal govt at proposed Rhade Ranch U mining site. Attempts to purchase surface from owners have been unsuccessful Gamma survey data encl DAVIS,0 D Anaconda Co . Anaconda Copper Co Div 16298 80/04/23 6pp
- --8006060147 "Omohydrologic Investigation of Tailings Disposal.Rhode Ranch Prospect McMullen County.TX " Oversize drawings encl * Ed L Reed & Associates, Inc. 16298 80/04/30 100pp
- BOO6090026 Forwards summary of JE Rothfleisch BOO507 visit to Cotter Corp Schwartzwalder Dre Borter Project to provide recommendations on technical content of amended license application & environ rept Technical assistance complete BCARANO,R A Urenium Recovery Licensing Branch BO/05/12 1p
- 8006090129 Responds to T Buhl 800423 ltr requesting review of proposed revisions to cleanup criteria established w/Church Rock dam failure Due to lack of available resources, requested review totalical assistance cannot be provided SCARANO, R A Uranium Recovery Licensing Branch 80/05/16 ip.
- 8006090133 Responds to 800416 ltr requesting NRC review of Union Carbids proposal to operate Pond 3 at Uravan site after const of Phase II-A berm Final results & conclusion of dam taffety review contained in SER transmitted in 800521 ltr BCARANG, R A Uranium Recovery Licensing Branch 80/05/19 ip
- GOO6090551 Requests that radiological impact info re Union Carbide Corp Uravan,CD U mill be made available to public Description of extent of info & estimate of schedule & format for release also requested HAZLE:A J Colorado, State of 16356, BO/05/07 1p.
- GOO6120077 Confirms suggestion that BOO409-10 conference be held cd/CD Dept of Health & Cotter Gorp in Denver.CO re amend of radioactive matis license application Schedule will be open panding further advice MCGRATH.E J HcOrath, E J 15948 80/03/26 ip
- 8006:20154 Discusses application for license to operate ore buying station at same time site is proposed for mill HAZLE.A.J. Colorado, State of 16357. 80/05/13. 2pp.

- 8006120284 Forwards "Groundwater Discharge Plan. Dec 1979 "
 BDHM.R E Gulf Dil Corp , Gulf Mineral Resources Co 16436
 80/04/11 1p
- --8006120287 "Groundwater Discharge Plan.Dec 1979 "

 * Gulf Gil Corp , Gulf Mineral Resources Co 16436 79/12/31
 250pp
- 8006160225 Forwards "Hansen Project Groundwater Investigation Proposed Tailings Disposal Area," in response to Action Items 2 & 3 discussed at 800417 meeting BURANEK,D W A Wahler & Associates, Inc 16485 80/05/29 1p
- --8006160229 "Hansen Project Groundwater Investigation Proposed Tailings Disposal Area " # W A Wahler & Associates, Inc 16485 80/05/31 372p
- BOO4170366 Forwards responses to questions & comments discussed at BOO417 meeting Info includes characterization of landslide potential for three cell option & evaluation of use of underdrains Oversize drawings encl THOMPSON, to A Cyprus Mines Corp 16484 BO/05/27 56pp
- 8006200009 Submits conclusions re review of Rickano Corp application for use of Lyons.KS salt mine for retrievable storage of low level radwaste If project continues, environ assessment should be prepared GMITH.R D Low Level Waste Licensing Branch 80/05/30 6pp
- --8006200011 "Health & Assessment, Lyans, KS Low Level Waste Facility, Care Salt Mine" " Commission 80/05/31 47pp
- ---B006200013 Submits trip rept of B00319-20 visit to Topeka, KS re NRC review of Rickano Corp application for use of Lyons, KS salt mine for retrievable storage of low level radwaste Application deficient NRC will provide environ assessment SMITH: R D Low Level Waste Licensing Branch 80/03/28 49pp
- 8006230160 Advises that Cotter Corp proposal to dispose of contaminated trash in Cannon City U mill tailings impoundment, is accepteble plan that has no adverse impact on impoundment CD State Dept of Health notified RDTHFLEISCH, J Uranium Racovery Licenting Branch 80/05/20 ip
- 8006230168 Informs of inability to review preliminary draft license impact analysis due to preparation of radiological assessment & tailings mgt evaluation NM Environ Improvement Div appears to be in compliance w/requirements. MILLER:H J Uranium Recovery Licensing Branch 80/05/23 ip
- 8004240243 Responds to CD Dept of Health 800317 & 0415 ltrs retechnical assistance for Cyprus Mines Corp Hansen project & Pioneer Uravan San Miguel project Clarifies scope of assistance MILLER.H J Uranium Recovery Licensing Branch 80/05/22 2pp
- 800625034: Informs that Ofc of Waste Mgt has withdrawn from formal involvement in Homestake Mining Co Pitch Project due to unavailability of necessary manpower ROTHFLEISCH. J. Uranium Recovery Licensing Branch. 80/06/09.
- 8006250378 Discusses 800319~20 site visit w/State of OR representatives in Portland, OR & McDermitt, NV re NRC technical assistance for review of Placer Amex proposed U mill & proposed & alternative sites
 LINEHAN, J J Uranium Recovery Licensing Branch 80/05/27 4pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8006020572 Requests change to export license application for Zircaloy-4 fuel channels Quantity should read "150 fuel channels" instead of "160 " Correct figure appears in cover ltr BRISTOL.D C Carpenter Technology Corp 80/05/13 ip.
- 8004030051 License for CERAC, Inc to export 11 kg thorium oxide, containing 9 67 kg thorium to Italy PETERSON, M. R. Assistant Director for Export/Import & International Safeguards 80/05/23 2pp
- 8006030056 Executive Branch position re Westinghouse applications for license to export 904 micrograms Cf-252 to Spain License should be granted MOBENZO, L. V. State, Dept of, Eureau of Oceans & Internatl Environ & Scientific Affairs. 80/05/16 29p

- 8006030059 Forwards applications for license to export 7 667 kg U, containing 0 073 kg U-235 & 103 259 kg U.containing 96 34 kg U-235 to France W/o latter application MATSON, V Transnuclear, Inc 80/05/14 1p
- --8006030063 Application by Transnuclear, Inc for license to export 7 667 kg U.containing 0 073 kg U-235, to France MATSON, V Transnuclear, Inc 80-116/01 TNP 3 80/05/14 1p
- 8006030061 Executive Branch position re Rockwell Intl application for license to export specially-designed valve to India License should not be granted NDSENIOL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/16 2pp
- 8006030070 Application by Rockwell Intl Corp for license to export
 Rockwell-Edward globe stop valve to India
 OFSANIK, N J Rockwell International Corp 1822 FE 80/05/14 3pp.
- B00603007& License for Transnuclear, Inc to export 20 090 kg U, containing 18 707 kg U-235, to The Netherlands SHEA, J R Assistant Director for Export/Import & International Safeguards NUK-227 UEB/EU 80/05/21 2pp
- 8006030084 License for Transnuclear, Inc to export 113 182 kg U, containing 105 597 kg U-235, to Belgium BHEA, J M Assistant Director for Export/Import & International Bafeguards NUK 249 VES/EU/ 80/05/21 2pp
- 8006030116 Executive Branch position re Rockwell Intl Corp application for license to export one complete ultrasonic into sys to Argentina Ltrs of assurance encl License should be granted NOSENZOL V State.Dept of, Bureau of Oceans & Internati Environ & Scientific Affaire 80/05/20 2pp
- BOO4030157 Application by Integrated Photomatrix.Inc for license to import two pulse fission chambers from Great Britain GREEN,A R Interpace Corp BO/04/30 2pp
- 8006030230 Ltr of assurance re Transnuclear. Inc application to export 602 7 kg U-235, contained in 17.990 kg U & 0 034 kg U-235, contained in 1 kg U. to The Netherlands

 OUPPEL.M European Communities, Commission of 80/05/16 lp
- 8006030238 Ltr of assurance re Transnuclear, Inc application to export 370 94 kg U-235, contained in 10,449 kg U & 0 0355 kg U-235, contained in 1 kg U, to Switzerland GOPPEL,M European Communities. Commission of 80/05/16 ip
- 8006040087 Application to amend License XR-119, changing ultimate consignee address of Korea Electric Co. South Korea RODI, J P Westinghouse Electric Corp., PWR Systems Div TFG/NRC-4776 80/05/14 ip
- 800&04010& Advises that vendor correspondence & application to export two power reactors to Taiwan does constitute utilization facility MODRE,R N Office of International Programs, Director 80/05/21
- 8006040254 Forwards end use statement for GA Co 770211 application for license to export research reactor fuels to Iran MOMRY.W R General Atomic Co (subs of Gulf Gil Co) 77/03/02
- --8006040258 Forwards Form NRC-7, Justification Analysis, in support of 770211 application for license to export fuel elements to Iran Insertion of new fuel will permit continued operation of reactor for research purposes MOMRY, W R General Atomic Co (subs of Gulf Dil Co) 77/02/11
- --8006040264 Application by GA Co for license to export 24 4 kg U-235, contained in 26 2 kg U, to Iran NRC draft ltr to OA Co encl MONRY, W R General Atomic Co (subs. of Gulf Dil Co) IEL-938 78/07/18 2pp
- 8004050480 Executive Branch position re QE application for license to export neutron detectors to Finland Ltr of assurance encl License should be granted NOSENIGL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/19 Spp
- 8006030532 Executive Branch position re Edlow Intl application for license to export 192,326 kg U. contained in U oxide, to Federal Republic of Germany License should be granted Ltr of assurance encl NOSENIO,L V State.Dept of 80/05/09 3pp

- BO06060079 Executive Branch position re Pacific Pumps.Inc application for license to export components & parts.especially designed for Tarapur reactors, to India License should be granted NOSENZO.L V State.Dept of BO/05/13 2pp
- 8004040083 Executive Branch position re Byron Jackson Pump Div application for license to export various components & parts for Tarapur plants to India License should be granted NOSENZOL V State, Dept of 80/05/13 2pp
- 8006060087 Executive Branch position re Carpenter Technology Corp application for license to export 160 Zircaloy-4 fuel channels to India License should be granted NOSENZOL V State, Dept of 80/03/13 2pp
- 8006060201 Executive Branch position re Westinghouse application for license to export 1,917 kg U-235, contained in 73,173 kg U, to Spain Ltr of assurance encl License should be granted NOSENZO.E. V State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/21 3pp
- BOOGOGOZO3 Executive Branch position re Westinghouse application for license to export 2,452 kg U-235, contained in BB,636 kg U, to Spain Ltr of assurance enct License should be granted NOSENZO, L V State, Dept of, Bureau of Oceans & Internati Fnutron & Scientific Affairs 80/05/21 Spp
- 8004090035 Forwards request for Amend 1 to export license consisting of Radium-Chemic.Ltd 800506 & 12 ltrs re NUKEM statements concerning tritium order HOLM, W M Radium Chemical Co., Inc. 80/05/20 3pp
- 800809003B Application by OE for Amend 1 to export license extending expiration date to 810701 WILEON, B D General Electric Co 80/05/12 1p
- 8006090080 Executive Branch position re Westinghouse application for amend to license increasing amount of nuclear matl authorized by 87 kg U-255, contained in 2.774 kg U, for export to Spain Ltr of assurance encl License should be granted NOSENZO, L V State, Dept. of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/21 3pp
- BOO6090112 License for Edlow Intl Co to export 119,242 kg natural U, contained in 140.616 kg U-306.to West Germany PETERBON,M R Assistant Director for Export/Import & International Safeguards URG-5 80/05/30. 2pr
- 8006090116 License for Westinghouse to export 2,874 kg U-235.contained in 82,926 kg U.to Yugoslavia
 PETERSON, N R Assistant Director for Export/Import & International Bafeguards ZESX-11007 ARS 80/04/02 2pp
- 8006090120 Notifies that License X8NM-1657 may be issued same an matter changed circumstances from issuance of License X8NM-1604 WRIGHT, B L. Office of International Programs, Director 80/04/05
- 9004090121 License for Metal Bellows Corp to export air cooler hoses, oil cooler hoses & thermal barrier hoses to Belgium PETERSON, M R Assistant Director for Export/Import & International Safeguards 14825/026/827 8D/05/30 ip
- 8006090141 License for Carpenter Technology Corp to export 160 Zircalog-4 fuel channels to Hest Germany PETERSON, M. R. Assistant Director for Export/Import & International Safeguards. JOB 14051 80/05/30 ip
- BOO6090159 Amend 1 to import license for Westinghouse,changing ultimate consignee address PETERBON,M.R Assistant Director for Export/Import & International Safeguards. TEG/NRC-860A 80/05/28 ip
- 8006090161 Amond 1 to export license for GA Co.adding one fission counter, Model WL-6976 & extending expiration data from 800701 to 810701 PETERSON, M R Assistant Director for Export/Import & International Safaguards. IEL-1085 80/05/28 1p
- 8004090177 Application by Westinghouse for license to export fission chamber w/5 04 g U.contained in 5 43 g U-235, to Pakistan End use statement encl POCHAL, W F. Westinghouse Electric Corp ZE-60180 80/05/15 4pp
- 8006070184 License for Westinghouse to export 452 micrograms Cf-252, contained in two sealed sources, to Spain PETERSON, M. A *** stant Director for Export/Import & International Bafeguards ICS-8386 60/05/28 2pp.

- 8006090192 License for Wastinghouse to export 452 micrograms Cf-252, contained in two sealed sources, to Spain PETERBON, M.R. Assistant Director for Export/Import & International Safeguards ICS-8387 80/05/28 2pp
- 8006090194 License for Transmutlear. Inc to export 370 9755 kg U-239. contained in 10.500 kg U. to Switzerland PETERSON, M R Assistant Director for Export/Import & International Safeguards RBU324 80-092/1 80/05/28 2pp
- 8006090189 License for Transnuclear, Inc to export 602 734 kg U-235, contained in 17,791 kg U.to The Netherlands PETERSON M R Assistant Director for Export/Import & International Safeguards RBU323 80-091/1 80/05/28 2pp
- 8006090424 Executive Branch position re Westinghouse application for amend to license, increasing amount of nuclear matl authorized by 89 kg U-235, contained in 2.774 kg U, for export to Spain Ltr of assurance enti License should be granted NGSENZO, L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/05/21 Spp
- 8006090504 Application by GE for license to export 38 U oxide fuel rod segments to Canada WILEON, B Qeneral Electric Co BDW 80056 80/05/23 1p
- 8006090517 Advises that export license XSNK-1676 may be issued since no matl changes have been made since issuance of XSNM-1333 WRIGHT,B L Office of International Programs, Director 80/05/21
- 8006090538 Advises that export License XSNK-1658 may be issued since no matl changes have been made since issuance of XSNK-1604.

 WRIGHT, B L Office of International Programs, Director. 80/06/05
- 8006090566 Expresses disappointment re delay in issuing license for export of nuclear components to India EECKHOUT, A Reuter-Stokes, Inc. 80/05/05 ip
- 8006110437 Advises that no mat1 changed circumstances associated w/ License XBNM-1636 from those existing at time of issuance of XBNM-1636 License may be issued. WRIGHT.B L Office of International Programs, Director. 80/05/22
- 8006120078 Executive Branch position re Metal Bellows Core applications for licenses to export metal hose & assemblies to Epain Licenses should be granted NGENIOL V State.Dept.of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/28. 2pp.
- 8006120111 Forwards addendum to application for license to export 160 Zircaloy-4 BWR fuel channels to West Germany BRISTOL, D C Carpenter Technology Corp 80/05/12 ip.
- --8006:201:15 Application by Carpenter Technology Corp for addendum to license to export 160 Zircalog-4 BMR fuel channels to West Cermany, # Carpenter Technology Corp. 80/05/12 2pp
- 8006120155 Discusses request for amend to XBNM-1343 Fevorable response to amend expected due to approval by President Carter of fuel sale to Tarapur reactor Amend request will be resubstited due to June 1950 expiration EECKHQUT, A Reuter-Stokes, Inc. 80/05/12 ip.
- 8006120202 Ltr of assurance re QE 800130 application for license to export replacement parts to Finland.

 * Finland 80/05/16, 1p
- B006120204 Advises that circumstances associated w/License XBNM-1675 are seme/as those existing at time of issuance of XBNM-1529.

 License may be issued.

 WRIGHT, B L. Office of International Programs, Director 80/05/21
- 8006120211 Advises that circumstances associated w/License X8NM-1650 are same as those existing at time of issuance of X8NM-1636 License may be issued.

 WRIGHT, B L Diffice of International Programs, Director. 80/05/22
- 8006120247 Ltr of assurance re Japan Atomic Power Co application for license to export 1,002 kg U-235 contained in 36,730 kg Uto Japan MIYABAYASHI,M. Japan, 80/05/14, 1p

- 8006120252 Requests amend of license to export Taiwan Units 5 & 6 to Taiwan, adding Units 7 & 8 HE8B.R J Westinghouse Electric Corp 105-0121 80/04/23 Spp
- --8006120258 Requests license to export Taiwan Units 5 & 6 to Taiwan HERSCH,M M Westinghouse Electric Corp ICS-2612 76/01/07 2pp
- 8006120273 Requests amend of license to export components to Philippines, adding fission chamber NDNRY, W R General Atomic Co (subs of Gulf Dil Co) 696-1177 80/087373 2pp
- 8006120360 SECY-80-238 OO6120360 BECY-BO-238
 Forwards Executive Branch views on proposed exports of fuel & components to India & recommends preparation of order & cover ltr to President noting that applicable export criteria have not been met SHEA, J R Office of International Programs, Director 80/05/09
- ---B006120361 Application by Edlow Intl Co to export 487 3 kg U-239,to India Govt of India 780911 1tr to DOE encl * Edlow International Co 78/09/20 3pp
- ---8006120365 Confirms 800iil telcon re expedited issuance of license to expert traversing in-core probe to India No spare probes available for scheduled replacement at Tarapur Atomic Power Station, Unit 1

 WILSON, B D General Electric Co 80/01/11 ip
- 8006120364 Application by Matheson Gas Products for license to export one Size 3 cylinder containing 500 liters chemically pure deuterium m Matheson Qas Products 101-84512 80/05/21 1p
- 8006120397 Bubmits application for license to export 1,100 lb depleted U, for use as shielding in medical cancer therapy equipment, to Canada * Nuclear Metals, Inc 1-201-7 80/05/27 ip
- 8006120420 Forwards license application to export 103,258 kg U. containing 96.34 kg U-235 to West Germany MATSON, V Transnuclear. Inc 80/05/14 1p
- --8006120424 Application by Transnuclear, Inc for license to export 103 25B kg U.containing 96 34 kg U-235, to West Germany Ltr of assurance encl MATSON, V Transnuclear, Inc 80-115/01 NUK32 80/05/14 2pp
- 8004120425 SECY-80-235 DOA120425 SECY-BO-235
 Recommends issuance of license to Reuter Stokes.Inc to export two ionization chambers to Venezuola License request forwarded for Commission review because proposed export is destined for country w/o previous authorization SHEA.J R Office of International Programs, Director 80/05/07
- --8006120430 Submits Executive Branch views re application by Reuter Stokes,Inc for license to export two ionization chambers to Venezuela Recommends that license be issued NOBENZO,L V State,Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 90/04/16 3pp
- 8006120439 Withdraws application for export license HERSCH, M M. Westinghouse Electric Corp. 108-0333 80/05/23 ip
- 8006120442 Forwards license application to export slightly enriched U dioxide powder.compressed into fuel pellets, to Brazil HERBCH.M N Westinghouse Electric Corp IC8-0289 80/05/13 ip
- --8006120446 Application by Westinghouse for license to export slightly enriched U dioxide powder, compressed fuel pellets, to Brazil HERSCH, M. M. Westinghouse Electric Corp ICS-0289 80/05/13 ip
- B006120445 Requests cancellation of B00329 application for license to export BNM to Canada
 JUHNSON:N R Eberline Instrument Corp E1-917752 80/05/23 ip
- 8006120448 Hithdraws application for license to export R5 research reactor components to India. ECKHOUT, A Reuter-Stokes, Inc. 80/05/22 1p
- BOOG120449 Forwards license application to export 36,400 kg contaminated sintering boats to Sweden.
 HERBCH.M M Westinghouse Electric Corp. ICS-0292, 80/05/14 ip

- --8006120450 Application by Westinghouse for license to export 36,400 kg contaminated scrap molybdenum sintering boats, to Swaden HERSCH, M M Westinghouse Electric Corp ICS-0292 80/05/13 1p
- 9006120468 BECY-BD-2388

 Recommends that Commission consolidate Applications
 XCDM-0376.XCDM-0381 & XCDM-0395 w/applications listed in
 SECY-BD-238.for review purposes Also recommends that
 Commission note receipt of GE request to amend XCDM-0240
 SHEA.J R Office of International Programs, Director 80/05/15
 360
- --8006120473 Submits Executive Branch views re application by Byron Jackson Punp Dly for license to export components & parts to India Recommends that license be issued NOSENZO.L V Stabe, Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs SO/05/13 2pp
- --8006120477 Submits Executive Branch views re application by Carpenter Technology Corp for license to export 160 Zircaloy-4 channels to India Recommends that license be issued NOSEMZO.L V State. Dept of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/13 2pp
- ~-8006120482 Submits Executive Branch views re application by Pacific Pumps, Inc for license to export parts & components to India Recommends that license be issued NDSENZO,L V State, Dept of, Sureau of Oceans & Internati Environ & Scientific Affairs 80/05/13 3pp
- --B006120485 Responds to question re safety significance of pending export of Tarapur components If licensing action on pending applications continues to be withheld, impact would be more adverse than any single export treated in isolation BHEALJR Diffice of International Programs, Director B0/05/06
- 8006120487 Requests extension of expart license from 800731 to 801231 Possibility exists that order for Union Electric will not be completed by 800731 due to 2-3 month delivery backlog at primary cable supplier.Faleflex EECKHOUT, A Reuter-Stokes, Inc. 80/05/22 1p
- 8006120497 Forwards corrected end use statement for 800523 license application Requests that quantities of mation license be adjusted to read 21,044 7 kg U,containing 704 997 kg U-235 MATEON. V Transnuclear, Inc. 80/05/29 2pp
- --8006120500 Forwards application for license to export 21.045 kg U. containing 705 01 kg U-235 to Switzerland MATSON, V Transnuclear, Inc. 80/05/23. ip,
- --8006120502 Application by Transnuclear, Inc for license to export 21,044 7 kg U.containing 704 997 kg U-235, to Buitzerland * Transnuclear, Inc RBU 331 80-120 80/05/23 2pp.
- BOO6120305 Ltr of assurance re Marabeni America Corp application for license to export 148 kg+ U-235, contained in 5,458 kg U, to Japan, MIYABAYASHI,M Japan, 80/05/14 ip,
- 8006120507 Executive Branch position re Transnuclear, Inc application for license to export 1,234 kg U-235,contained in 30,746 kg U & 127,224 kg natural U to West Germany Ltr of assurance encl NGSENZO, L. V State, Dept of
- 8006120532 Submits application to amend license, increasing quantity of matl for export to 4,182 kg U-235, contained in 158,012 kg U. & extending expiration date to 811231.

 BAHLSTROM.C O Westinghouse Electric Corp. 80/05/19 ip
- 8006130026 Discusses application by Nuclear Metals. Inc for license to export 500 kg depleted U to Canada, Matl will be used for non-nuclear application License issued w/o normal 15-day waiting period PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. 80/05/28 ip.
- ---8006i30028 License for Nuclear Metals, Inc to export 500 kg depleted U. as solid metallic pieces to Canada. PETERSON-N.R. Assistant Director for Export/Import & International Bafeguards. 80/05/28 2pp
- 8006130030 Forwards application for license to export up to 20,000 lb per yr depleted U metal castings in discrete piecas up to 2 ft max dimension & individual piece weights up to 1,000 lb. for S-yr period to United Kingdom Requests quick response OCHER, D. A. Nuclear Metals, Inc. 80/05/21 lp

- --8006130033 Application by Nuclear Metals, Inc. for license to export up to 20,000 lb per yr depleted U metal castings in discrete pleces up to 2 ft max dimension & individual piece weights up to 1,000 lb.for 3-yr period.to United Kingdom GILMAN, A R Nuclear Metals, Inc. 80/05/22 lp
- B006130041 Requests approval to re-export 3 3 mg Cf-252 source to Democratic Republic of Germany, in response to license condition
 HARMON D Ediow International Co 80/05/27 ip
- 8006130048 Forwards itr from Teledyne Hah Chang Albany requesting cancellation of application XCOM-0103 to export Zircaloy tube shells to Argentina.
 PETERSON M R Assistant Director for Export/Import & International Safaguerds 80/05/28 lp
- 8006:30049 Requests Executive Branch position re Westinghouse application for license to export 3 fission chambers to Patistan W/o encl 800319 application PETERSON M R Assistant Director for Export/Import & International Safeguards 80/05/30 ip
- 8006130185 Executive Branch position re Teledyne Isotopes application for amend to export license extending expiration data for 2 yrs & limiting amount of tritium gas to 2,000 Ci.
 License thould be amended
 NOSENZO,L V State.Dept of 80/05/12 2pp
- 8006130236 Ltr of assurance re Transnuclear.Inc application to export 370 94 kg U-235, contained in 10,449 kg U & 0 0355 kg U-235, contained in 1 kg U, to Switzerland.
 MULLER.R E Switzerland 691 513 NOX 80/05/06 ip
- 8006160162 Informs that Commission approved issuance of license to export low enriched U to Yugoslavia CHILK, S J Office of the Secretary of the Commission 80/06/02 to
- 8006160173 Forwards Radium Chemical Co 800520 ltr transmitting addl info re amend request to License XB-1012 to export tritium to Switzerland W/o encl PETERSON M R Assistant Director for Export/Import & International Safeguards 80/05/30 ip
- 8006i60178 Notifies that Westinghouse withdrew export license application on 800923 PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/02 ip
- BOOGGGOODS Forwards Executive Branch responses re five export license applications for Spain requiring Commission action. Requests expeditious review H/o encl
 SHEA, J R Office of International Programs, Director. 80/06/02.
- 8006160199 Informs that Eberline Instrument Corp withdrew export license application on 800519 PETERBON.M R Assistant Director for Export/Import & International Bafaguards 80/05/30. ip
- 8006160207 SECY-80-263
 Requests review of encl Westinghouse applications for license to export two power reactors to Taiwan
 SHEA.JR Office of International Programs, Director. 80/05/22
- BOO6170095 Executive Branch position re Westinghouse application for amend to license increasing amount of authorized nuclear math by 635 kg U-235 contained in 17,600 kg U, for export to Spain License should be granted NOSENZOL V State.Dept of Bursau of Oceans & Internati Environ & Scientific Affairs. 60/05/21 Spp
- 8006170110 Executive Branch position re DOE application for license to export 7 3 kg U-235, contained in 245 kg U, to Canada Ltr of assurance encl. License should be granted NDSCNZOL. V State, Dept of, Bureau of Oceans & Internati Environ, & Scientific Affairs 80/05/14 3pp
- 8006170120 Executive Branch position re Nissho-Iwai American Corpapplication for license to export 145 685 kg U-235 contained in 7.587.75 kg U, to Japan Ltr of assurance encl License should be granted NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl, Environ & Scientific Affairs, 80/05/20 3pp

- 8006170225 Forwards DDE ltr requesting amend to License XSNM-163? to increase quantities to be exported Amend request should be considered w/800110 application W/o encl PETERSON M R Assistant Director for Export/Import & International Bafeguerds 80/06/02 1p
- 8006170382 Executive Branch position re Westinghouse application for license to export NSSS to Korea License should be limited to 10 yes & expiration date should coincide w/US-Korea agreement for cooperation

 HELFRICH, O F State, Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/05/27 1p
- 8005170388 License for Metal Beliows Corp to export flexible metal bose w/assemblies specially designed for nuclear reactors, to
- Spain PETERSON, H R R Assistant Director for Export/Import & International A14900 80/06/02 ip 19 Safeguarde
- 8006170737 Forwards 800502 ltr from Reuter-Stokes requesting cancellation of Export License Application XBMN-1308 H/o encl
 PETERSON, H R Assistant Director for Export/Import & Inter
- --R Assistant Director for Export/Import & International
 B0/05/30 ip Safeguards
- 8005170747 License for Nuclear Motals, Inc to export 27,300 kg depleted U.as metal castings, to United Kingdom PETERSON, H R Assistant Director for Export/Import & International Safeguards 80/06/09 2pp
- 8005170752 Forwards.for review.pending license application & proposed license for export of 27,300 tg depleted U to United Kingdom over 3-ur period Application no longer requires Commissioner review M/o encls PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/05/28 ip
- 8006170773 Requests Executive Branch position re Reuter-Stokes application for amend to license to extend expiration date to 801231 PETERSON, M R Assistant Director for Export/Import & International Conference of the Exp PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/04/03 ip
- 8006170783 Forwards application for license to export 7,587 75 kg U, enriched to 1 92%, to Japan Executive Branch position & proposed license no longer require Commissioner review H/o enci PETERBON.M.R Assistant Director for Export/Import & International Safeguards 80/03/23 ip Safeguards
- 8006170821 Forwards application by Nuclear Metals. Inc to renew license to export 65.000 lbs depleted U to Canada QCMER. D Nuclear Metals. Inc 80/05/22 lp
- --8006170826 Application by Nuclear Metals, Inc to renew license to export 65,000 lbs depleted U to Canada * Nuclear Metals, Inc 76/11/29 ip
- 8006170823 Requests Amends G & 1 to Licenses XCOM-0222 & XCOM-0274, respectively, increasing values & changing expiration dates to 811231 & 810630, respectively BRUSH-P N Hoke, Inc. 80703722 1p.
- 8006170845 Forwards application for license for minor nuclear export Requests assistance in securing required ltr of assurance, W/o encl
- PRICEBON, M R Assistant Director for Export/Import & International Safeguards. 80/05/23 ip
- 8006170B50 Forwards DRO Intl.Inc end use statement re application for I(cense Statement should be considered w/application submitted 791204
- PETERSON, M R Assistant Director for Export/Import & Interritional Safeguards 80/05/23 is
- 8006170834 Forwards application by Wastinghouse for license to export SMM to Brasil, W/o encl PETERSON M.R Assistant Director for Export/Import & International Sefeguards 80/05/23. ip
- 8006170858 Forwards application by Transnuclear, Inc for license to export SNM to West Germany W/o encl FETERSON, M. R. Assistant Director for Export/Import & International Safeguerds, 80/08723 p.
- 8006170862 Requests amend to export license, extending expiration to 810101. HARMON, D. Eslow International Co 80/06/02 1p.

- B006170864 Forwards application by Isotope Products Labs for license to export Cf-292 to Saudi Arabia W/o encl PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/23 ip
- 8006170867 Forwards application for license for minor nuclear export Requests assistance in socuring required ltr of assurance PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/05/23 ip
- 8006180066 License for Maruteni America Corp to export 148 kg U-235, contained in 5.458 kg U.to Japan PETERSON M R Assistant Director for Export/Import & International Safeguards ZH01318W 80/06/10 Zpp
- 8006180071 Amend 4 to GE export license, extending expiration date to 839/01 PETERBON,M R Assistant Director for Export/Import & International Bafeguards 89/06/10 1p
- BOO6180130 License for Self-Powered Lighting Ltd to export 450,000 Ci tritium in dispersed form only, incorporated into sealed light sources as optical instruments, to Albania, Bulgaria, Czechosiavakia, East Germony, Hungary & Mongolia PETERSON, N R Assistant Director for Export/Import & International Safeguards, 80/05/28 2pp
- B006180204 Amend 1 to Hoke Inc export license extending expiration date to 830630 & increasing total value of items PETERSON. H R Assistant Director for Export/Import & International Safeguards HNL-101 B0/06/09 ip
- 8006180214 Amend 3 to Hake Inc export license, extending expiration date to 831231 & increasing total value of items PETERBON H R Assistant Director for Export/Import & International Safeguards 1151A.C.C.10878 80/06/07. ip.
- B006180218 Application by Union Carbide Corp for license to export 5 010 kg deuterium contained in six cylinders, to Japan BALALIB, C G Union Carbide Corp 80-7840/7853 80/05/27 ip
- 8006180221 License for QE to export 1,002 kg U-235, contained in 36,730 kg U-to Japan
 PETERBON.H R Assistant Director for Export/Import & International
 Bafeguards BDW 80017 80/06/10 2pp
- 8006180225 License for Nissho-Iwai American Corp to export 145 685 kg U-235, contained in 7,587 75 U, to Japan PETERSON, M R Assistant Director for Export/Import & International Safaguards HHM-0157 BO/06/10 2pp
- 8006180287 Forwards Ediow Intl Co 800602 mailgram requesting that expiration date on export License X8-1005 be extended from 800801 to 810101 M/o encl PETERBON.M R Office of International Programs. Director 80/06/05
- 8006180270 Requests Executive Branch position re Edipw Intl Co 800927 request for amend to Liconse XB-1091 to allow Radiochemical Centre to re-export 3 3 mg Cf-252 to East Germany for medical purposes. PETERSON, M R Office of International Programs, Director 80/06/05
- 8006180583 Advises that proposed license to export 7,587 75 kg U.
 enriched to 1.920% to Japan no longer requires Commissioner
 review. Unless notified that further analysis is required.
 license will be issued.
 PETERSON M R Assistant Director for Export/Import & International
 Bafeguards 80/05/23. ip
- 8006:180570 Requests assistance in obtaining necessary ltr of assurance re application for license to export single reloads of low enriched U fuel, PETERBONM R Assistant Director for Export/Import & International Safeguards 80/06/03 ip.
- 8006180591 Advises that proposed license to export 33.660 kg U, enriched to 3 8%, to Sweden, no longer requires Commissioner review Unless notified that further analysis is required, license will be issued PETERSON, M R Assistant Director for Export/Import & Interna Bafeguards 80/05/23 ip Assistant Director for Export/Import & International
- 8006180593 Advises that Eberline Instrument Corp requests withdrawal of export license application per 800523 ltr PETERSON M R Assistant Director for Export/Import & International Bafeguards 80/05/30 ip.

- 8006180597 Requests Executive Branch position re Rockwell Intl application for license to export steel valves to India PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/06/03 ip
- d006190021 Forwards application by Aldrich Chemical Co. Inc for license to export deuterium oxide to India Requests info re status of 800429 application for license to export to Argentina EDELBTEIN.B Aldrich Chemical Co.
- --8006190025 Application by Aldrich Chemical Co.Inc for license to export 1 kg douberium.contained in 5 kg deuterium oxide to India EDELBTEIN.B Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 9/80 80/05/27 ip
- BOO6190026 Application by Mitsuf & Co.(USA). Inc for license to export Zircalog-2 tube shells to Japan MONDEN.T Mitsuf & Co., Ltd 136156 80/05/29 2pp
- 8006190067 Ltr of assurance re Transnuclear. Inc application to export 0,073 kg U-235, contained in 7 667 kg U-to France MARCHAL, J European Communities, Commission of B0/06/04 ip
- 8006190107 Application be Teledyne Precision-Cincinnati for license to export one resistance butt welder w/magnetically activated upset force sys to Argentina KROBER, R C Teledyne Precision Cincinnati 970018 80/05/29
- B006190160 Requests current status of B00317 application for license to export waste gas mgt treatment sys to South Africa Requests written response & description of pending problem areas by B00613 MURPHY, W J Helix Technology Corp , Process Systems Div 80/05/27
- 8006190224 Notifies that license issued without customary 15-day waiting period due to urgent used for deuterium gas PETERBON,M R Assistant Director for Export/Import & International Safaguards 80/06/11 ip
- --8006190231 License for Union Carbide Corp to export 30,000 liters dauterium gas & 0 005 microcuries tritium to Japan PETERSON, M R Assistant Director for Export/Import & International 8afeguards 80-7840-7853 80/06/11 2pp
- 8006190639 Petition to intervene & request for hearing re FR 790228 notice of export of two nuclear reactors to South Korea Pertinent data must be made available for public insp & export deferred until hearing is held M/related documents ASHER, TR Center for Development Policy ASHER, TR Asher, TR, PC 80/06/13. 35pr.
- 8006200001 License for Exxon Nuclear Co.Inc to export 1.010 kg U-235.contained in 33.660 kg U, to Sweden PETERSON,M R. Assistant Director for Export/Import & International Safaguards 80/06/04 2pp
- 8006200130 Forwards request for change or elternate route for spent fuel shipment. Encl withheld (ref 10CFR2 790) STUKENBROEKER. 9 NL Industries, NL Nuclear Div 16352 80/05/08
- 8006200207 Requests Executive Branch position re Westinghouse request for amend to application for export license, increasing quantity of matl from 150,091 kg U, containing 3,992 kg U-235 to 158,012 kg U, containing 4,182 kg U-235 PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/06/03 1p
- 800620026B Requests cancellation of application for export to Chile JOHNSON: N B Eberline Instrument Corp EI-917747 80/05/19 1
- BOO6200276 Ack receipt of H Bengelsdorf 791220 ltr requesting license to export Pu to Bwitzerland, Quantities reflected in Items 17.18.19.20 & 21 should be changed to reflect 2 5 kg Pu.92% fissile & 16 0 kg natural U. MCDDNQUQH, M D Energy, Dept of BO/05/22 lp.
- 8006200561 Notifies that License XBNM-1655 may be issued since no mattachanged circumstances existing at issuance of License XBNM-1636
 WRIGHT, B L Office of International Programs, Director 80/06/17

- 8006200581 Forwards 800522 application & proposed license for export of 34,500 kg depleted U to Canada for use as shielding for medical cancer therapy equipment License will be issued unless otherwise advised W/o encls PETERSDN,M R Assistant Director for Expor*/. port & International Safeguerds 80/04/02 tp
- 8006200582 Advises that Commission has accepted recommendation for approval of Reuter-Stokes application for license to export two ionization chambers for use as neutron detectors to Venezuela

 CHILK.S J Office of the Secretary of the Commission 80/06/05 in
- B006200590 Forwards pending license application favorable Execut; Branch views & proposed license for sport of special nuclear & source mati to West Germany License will be issued unless otherwise advised M/o encls PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/02 ip
- 8006200614 Forwards application by Borg-Warner Corp. Nuclear Valve Div. for license to export globe gate & check valves as connecting parts to Delgium HAN. S Y Borg-Warner Corp., Nuclear Valve Div CSH/80/218 80/05/29 2pp
- --8006200617 Application by Borg Harner Corp. Nuclear Valva Div. for license to export globe gate & check valves as connecting parts to Belgium HAN.8 Y Borg-Harner Corp., Nuclear Valva Div. A52208/501/505 80/05/29 p
- BOO6230005 License for Sigma Chemical Co to export 5 kg deuterium oxide to Argentina PETERBON,M R Assistant Director for Export/Import & International Safeguards D-44 BO/06/11 2pp
- 8006230007 License for Bigma Chemical Co to export 10 kg deuterium nxide to New Zealand PETERSON,M R Assistant Director for Export/Import & International Safeguards D-41 80/06/11 2pp
- BOO6230010 License for Aldrich Chemical Co. Inc to export 1 0 kg deuterlum, contained in 5 kg deuterium oxide, to Argentina PETERSON. M R Assistant Director for Export/Import & International Safeguards 8/80 80/06/11 2pp
- 8006230074 License for Mitsui & Co.Inc to export 79.200 lb Zirceloy-2 tube shells to Japan PETERSON.M R Assistant Director for Export/Import & International Bafeguards 136152 80/06/03 lp
- 8006230080 License for Metal Bellows Corp to export flexible metal hose w/assemblies, specially designed for use in nuclear reactor, to Spain PETERSON, MR Assistant Director for Export/Import & International Safeguards A14700 80/06/02 14
- 8006230106 Responds to FOIA request for documents re proposed nuclear reactors to be located mear Gymemm.Korem SECY-80-185 & License XR-0133 are available in PDR FELTON.J M Division of Rules and Records 80/06/17 lp.
- 8006230116 Executive Branch position re Ediow Intl Co application for license to export 117,242 kg natural U for storage to West Germany Ltr of assurance encl License should be granted NOSENZO L V. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs. 80/05/20 2pp
- 800623020B Discusses proposed export that no longer requires Commissioner review License application has been reviewed & raises no safeguards concerns BURNETT,R F Division of Safeguards 80/06/06 1p
- 8006230706 License for Matheson Qas Products to export 500 liters deuterfum to Australia PETERSON:M R Assistant Director for Export/Import & International Safeguards 101-83273 80/06/11. 2pp
- 8006230707 Submits application to amend license to export 5,000 liters deuterium gas to Japan. CIAMMARA Union Carbide Corp 80/06/10 1p
- 8006240004 Requests Executive Branch position re QE application for license to export SNM to Canada. PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/05 ip

- 8006240116 Requests NRC expedite approval for application to export in-core fission chamber to Australia # Australia 80/03/31 ip.
- 8006240120 Ltr of assurance re export of 7 g Pu & 10 g U-233 to Japan MIYABAYASHI.M Japan 80/05/21 ip
- B006240124 Notifies that Westinghouse informed embassy that all necessary documentation re use of in-core fission chamber being processed Processing will take approx three wks Requests expediting export approval approxal B0/06/30 ip.
- 8006240129 Ltr of assurance re Seamodal Transport Corp application to apport 23 75 g Pu to Belgium MARCHAL.J Euratom Supply Agency (Belgium) 80/05/27 1p
- 8006240207 Authorizes issuance of License XSNM-1654 since no matt changed circumstances since issuance of License XSNM-1636 MRIONT.B L Office of International Programs, Director 80/06/18
- 8006240275 Ltr of assurance re export of 921 kg U-235, contained in 33,665 kg U to Japan MiyaBAyABHI,M Japan 80/05/26 ip
- 8006240277 Ltr of assurance re export of 1,474 kg U-235, contained in 55,125 kg U to Japan MIYABAYA8HI.M Japan 80/05/26 ip
- 800.6240.602 Responds to 800.527 request for info re status of application to export waste gas mgt treatment sus to South Africa Elecutive Branch response has been delayed South Africa is not coherent to NPT No assurance of issuance by Nov 1980 PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/06/10 Ip.
- BOO6240609 License for GE to export 1,474 kg U-235, contained in 55,125 kg U as U dioxide gouder, to Japan PETERSON, M.R. Assistant Director for Export/Import & International Safeguards BDM BOO18 GO/06/11 2pg
- 8006240650 Add1 response to FGIA request for documents re proposed nuclear reactors located near Gyamma, Korea Forwards GW McCortle 790322 memo 8ECY-79-141 is also subj to request & is available in PDR.
 FELTON.J M Division of Rules and Records 80/06/20 ip
- ---B006240653 Discusses review of application for license to export reactors to Korea No physical security concerns apparent Requests that Executive Branch provide info re Korean sys of accounting & control & status of safeguerds implementation.

 HCCORKLE.O W Physical Security Licensing Branch. 79/03/22 1p
- BOO5240654 Confirms appointment of Tokyo Electric Power Co.Inc as authorized party for license to export 800 kg U-235, contained in 27:155 kg U.to Japan Matl transfer will conform to Agreement for Cooperation MIYABAYASAL,M Japan 80/06/11 1p
- 8006250001 Determined no matl changed circumstance associated w/export license application from conditions existing at time of issuance of License X8NN-1636 License may be issued.

 MOORE, N Assistant Director for Export/Import & International Safeguards 80/06/17 ip.
- BOO6250003 License for Sigma Chemical Co to export 5.0 kg deuterium oxide to Malaysia PETERSON,M R Assistant Director for Export/Import & International Safeguards D-40 80/06/11 2pp
- BOO6230020 Forwards itr from Talesyne Wah Chang Albany requesting cancellation of application XCOM-0189 to export Zircaloy tube shells to Nest Garmany W/o itr PETERBORN R A Assistant Director for Export/Import & International Bafaguards 80/05/30. ip
- 8005250022 Advises that Kawerki Berylco Industries, Inc allowed License XCOM-0127 to expire, Export is ready for immediate shipment Fifteen-day waiting period is waived License encl PETERBONN R Assistant Director for Export/Import & International Safeguards, 80/06/06. ip.
- --8006250024 License for Kawecki Berylco Industries, Inc to export 414, 4 ft Zircaloy 2 seemless tubing to West Germany PETERSON, M R Assistant Director for Export/Import & International Bafeguards 78408 80/06/06. ip

- 8006250036 License for Mathaeon Gas Products to export 500 liters (90 g) deuterium, chemically pure, contained in five cylinders, to Australia PETERSON, MR Assistant Director for Export/Import & International Safaguards 101-77252 80/06/11 2pp
- 8006250055 License for Reuter-Stokes, Inc to export one uncompensated & one compensated ionization chamber, models RS-C2-0808-129 & RS-C1-2514-115, respectively, to Venezuela SHEA, JR Office of International Programs, Director V-8446 80/06/05 ip
- 8006250058 Application by Mitsubishi Intl Corp for license to expurt 450 mCi Cf-252 to Japan KU9E.T Mitsubishi International Corp (subs of Mitsubishi Corp) 64-7434-80 80/05/28 ip
- 8006250070 Requests Executive Branch position re Teledyne Precision application for license to export one butt welder to Argentina PETERSON, MR Assistant Director for Export/Import & International Safeguards 80/06/05 1p
- 8006250092 License for Westinghouse to export one incore fission chamber. Model NL-2379B, to Australia PETERSON, M R Assistant Director for Export/Import & International Safeguards AS 97975 80/06/11 1p
- 8006250095 License for Matheson Gas Products to export 300 liters deuterium chemically pure to Australia PETERSON, M R Assistant Director for Export/Import & International Safeguards 101-84512 80/06/11 2pp
- 8006250096 License for GE to export 921 kg U-235, contained in 33,665 kg U,as U dioxide powder, to Japan PETERSON.M R Assistant Director for Export/Import & International Safeguards BDW 80016 80/06/11 2pp
- 8006250284 Advises that application for license to export spacially designed parts & components to India was denied on B00516 & will be referred to President for further consideration H/o encl order SHEA, J R Office of International Programs, Director 80/06/16
- 8006250285 Advises that application for license to export specially designed parts & components to India was denied on B00516 & will be referred to President for further consideration H/o encl order SHEA, J.R Office of International Programs. Director 80/06/16
- 8006280287 Executive Branch position ra GA Co application for license to export fuel cluster tools, fuel rod insp device & storage rack to Taiwan.Ltr of assurance encl License should be granted NOSENZO.LV State, Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/06/12 4pp
- 8006250336 Forwards application to export U-308 stds to Soviet Union CAPOROSO.L DRO International.Inc 80/05/14 1p
- 8006250367 License for Nuclear Metals. Inc to export 34,500 kg depleted U.as solid metallic pieces. to Canada PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/12 2pp
- 8006260002 Application by Sigma Chemical Co for license to export 10 to deuterium exide liquid over 2-ur period to France STERN.N C Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-45 B0/06/05 ip
- 8006260006 Forwards license for Seamodal Transport Corp to export 23.75 g Pu & 320 g natural U to Belgium PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/16 ip
- ---8006260008 License for Seamodal Transport Corp to export 23.75 g Pu & 520 g natural U to Belgium
 PEVERBON,M R. Assistant Director for Export/Import & International Bafaguards A0/B61. 80/06/16, 1p
- 8006260010 Application by Wastinghouse for license to export one proportional counter, Model WX33785, to France.
 POCHAL, W.F. Westinghouse Electric Corp. ZE-20356 80/06/05. 1p
- 8006260012 Forwards Mitsubishi Intl Corp application for license to export 493 kg U-235, contained in 15, 141 kg U, to Japan SHIMA, B Mitsubishi International Corp (subs. of Mitsubishi Corp.) H8A-5480-04, 80706/06 3pp

- -9006260013 Application by Mitsubishi Intl Corp for license to export 493 kg U-235 contained in 15.141 kg U. to Japan End use statement entl SHIMA.S Mitsubishi International Corp (subs of Mitsubish)
 - SHIMA, S Mitsubishi Corp) HSA-5480-04 80/06/06
- 8006260014 Forwards Mitsubish: Intl Corp application for license to export 718 kg U-235, contained in 25,184 kg U. to Japan SHIMA.S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-3480-05 80/06/06 3pp
- --8006260018 Application by Mitsubishi Inti Corp for license to export 718 kg V-235, contained in 25,184 kg V. to Japan End use statement encl SHIMA: S Mitsubishi International Corp (subs of Mitsubishi Corp) H9A-5480-05 80/06/06 2pp
- 8006260019 Forwards Transnuclear, Inc application for license to export 620 160 kg U-235, contained in 17,501 kg U, to West Germany MATSON, V Transnuclear, Inc 80/06/09 ip
- --8006260022 Application by Transnuclear Inc for license to export 620 160 kg U-235 contained in 17,501 U.to Hest Germany End use statement encl Transnuclear, Inc. RBU 332 80-130/ 80/06/09 3pp MATSON, V
- 8006260032 Executive Branch position re Byron Jackson Pump Div, Borg Warner Corp, application for license to export specially designed parts & components for primary coolant pumps to Taiwan Ltr of assurance encl License should be granted. NDSENZO, L V State, Dept of, Bureau of Greans & Internati Environ & Brientific Affairs 80/06/12 4pp
- 8006260034 Executive Branch position re Chem-Nuclear Sys Inc application for license to export demineralizer sys to Taiwan Ltr of assurance encl License should be granted NGSENZG.L V State.Dept of, Bureau of Greans & Internati Environ & Scientific Affairs 80/06/12 4pp
- 8006260036 Executive Branch position re Westinghouse application for license to export 180 uCi Np=207, in 12 radiation surveillance capsules, to Taiwan License should be granted NGENZO,L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 2pp
- 8006260044 Application by Westinghouse for license to export three compensated ionization chambers, Model WL6377, to France POCHAL, W.F. Westinghouse Electric Corp. ZE-20359 80/06/05 1p
- 8005250047 Executive Branch position re GE application for license to export 25 kg U-235,contained in 2 5 kg U, to Taiwan Etra of assurance and License should be granted NDERISOL V Btate,Dept.of. Bureau of Oceans & Internatl Environ & Boientific Affairs 80/04/12 4pp
- 8001260080 Executive Branch position re GE application for license to export 4,000 kg U-235, contained in 14,000 kg U-to Teiwan Ltr of assurance encl License should be granted. NGSENZOL V State, Dept of, Bureau of Cicens & Internati Environ. & Scientific Affairs 80/06/12 5pp
- 8006260032 Executive Branch position re Edlow Intl Corp application for license to export 508 kg depleted U.as U dioxide, to Taiwan Ltr of assurance encl License should be granted. NDSENZOL V. State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/04/12. 4pp
- 8006260204 Petition to intervene & request for hearing re nuclear reactor export to Taiwan Requests public availability of all pertinent data & urges USGS assessment of volcanic & seismic issues needed for adequate appraisal of risks.

 KONEIL.JE Center for Development Policy. MCNEIL.JE. McNeil.JE. 80/06/20
- BO06260208 Petition to intervene & request for hearing re nuclear reactor export to Taiwan Requests public availability of all partinent data & urges USQB assessment of volcanic & saismic issues needed for adequate appraisal of risks MCNEIL, J E Canter for Development Policy. MCNEIL, J E McNeil, J E 80/06/20 20pp
- BOO6270007 Forwards FR notice re applications for licenses to export huclear facilities or matls
 SHEA.JR Office of International Programs. Director 80/06/16
- --8006270240 Notice of receipt of applications for licenses to export facilities or matis. BHEA.J R Office of International Programs. Director 80/06/16.

- 8006300080 Informs that 770211 & 780718 export license applications denied due to failure to meet Atomic Energy Act denied due t requirements Office of International Programs, Director 80/05/30
- 8006300111 License for Mitsui & Co to export 25,463 lbs Zircaloy-2 tube shells (HF-100 ppm max), to Japan PETERSON, M R Assistant Director for Export/Import & International BO/06/18
- 8006300274 Advises that NRC could not find export license applications within Atomic Energy Act criteria Applications referred to President for further consideration Commission 800516 order & 800609 revision entl M/o entl
- 800630028B Notifies that export license application determined not to be within Atomic Energy Act criteria Application forwarded to President for further consideration Commission 800016 order & 800600 revision encl W/o encl SHEA.JR Office of International Programs, Director 80/06/16
- 8006300293 Notifies that application does not meet Atomic Energy Act requirements Application forwarded to President for Further consideration Commission 800516 order & 800607 revision encl W/o encl.
 SHEArJ R. Office of International Programs, Director. 80/06/16.
- BO06300276 Requests info & guidance to export of tritium self-luminous tubes to Australia MACHUTCHIN, J Q US Redium Corp B0/06/i1 1p
- 8006300297 License for Transnuclear, Inc to export 7 667 kg U.containing 0 073 ig U-235, to France
 PETERSON, M R Assistant Director for Export/Import & International
 Safeguards 80-116/01 TNP 3. 80/06/19 2pp
- 8006300327 Application by Aldrich Chemical Co.Inc for license to export 1 kg deuterlum in 5 kg deuterlum oxide.to Venezuela. EDELSTEIN.B Aldrich Chemical Co , Inc (subs of Rigma-Aldrich Corp.) 11/80 80/06/12 ip
- 8006300331 Application by Aldrich Chemical Co.Inc for license to export 1 kg deutarium in 5 kg deuterium oxide.to Israel EDELBYEIN.B Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 13/80 80/06/12 19
- 8006300332 License for Aldrich Chemical Co.Inc to export 1 kg dautarium.contained in 5 kg deuterium oxide.to India PETERSON.M R. Assistant Director for Export/Import & International Safeguards 80/06/18 2pp.
- 8006300560 Transcript of 770321 briefing in Washington.DC re Ediow Intl Co application to export SNM to India Pp 1-42 * Commission, 77/03/21, 42pp
- 8006300581 Forwards application for license to export 30 g enriched U-235 to Japan. SAIKI,T Mitsui & Co., Ltd 80/06/03 ip.
- --8006300584 Application by Mitsui & Co for license to export 30 g enriched U-235 to Japan. * Mitsui & Co , Ltd 80/06/03, 2pp
- 8006300698 Requests Executive Branch position re request for amend to export license adding airlines located in Angola, Cameroon & Libyan Arab Republic to list of ultimate consignees. PETERSON.M R Assistant Director for Export/Import & International Safeguards. 80/06/23 IP
- 8006300701 Responds to 800611 ltr re export of sealed.self-luminous tubular type sources to Australia License does authorize export of tritium gas in sealed sources but does not authorize shipment of gas in bulk form PETERBON.H R Assistant Director for Export/Import & International Safeguards. 80/06/23 iP

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
		50-289 O	AHEARNE, J F.	8006120065	COMMISSION	ANDOONINI, O C	8006270195	50-293 G
AAMODT	8006060400	50-257 R	AMEARNE, J F	8006120071*	COMMISSION	ANDREWS, D L	B006230202*	50-260 G
ABERCROMBIE: H ABRAHAM: K	8006170501 8006030184	50-257 K	AHEARNE, J F	B006120100	COMMISSION	ANDREWS, D L	8006250165*	50-259 Q
ABUAF I N.	B006300215	RES	AHEARNE, J F	8006120110	50-320 U	ANO, W P	8006030073*	50-364 G
ABUAF, N	8006200014	RES	AHEARN, C. D.	8006060541	50-445 M	ANGELO, J	8006020170	GEN TEC IB
ACKERMAN, W. C	8006170793	40-1162	AHEARN, C D	8004090175	50-445 H	APPELHANS, A D	8006200041	RES
ACKERMAN, W. C.	8006230111	40-8502	AHEARN: C, D	8004040541	50-445 M	ARCHITZEL, R	8006170816#	50-317 G
ACKERMAN, W C	04400E400B	40~1162	AHEARN, C D	8006090175	50-445 M	ARESENAULT, F J	B006190669*	ACRB 50-320 G
ACOSTA, A P	E0104040183	40-8384	AHEARNE, J F	8006130385	COMMISSION	ARNOLD, R C	B006040112* B006120257	50-320 G
ACCIOTA, A. J.	8004180429	ACRE	AHEARNE, J F	8006230137	COMMISSION	ARNOLD, R C		
ACOSTA, A.P.	8004020533	40-8564	AHEARNE, J F	8009530158	COMMISSION	ARNOLD, R C ARONOV, R	8006270290 8006160146	50-320 P 70-2909
ACOSTALA P.	8004140208	40-8584	AHEARNE, J. F.	8006300614	COMMISSION COMMISSION	ARONOV, R	B006160150*	70-2909
ACDSTA, A P	800754057	40~8584	AHEARNE, J. F	8004130197 8004130200*	COMMISSION	ARTHUR, D F	8004270398	NUREO
ADAMS, N. E	E006110133	50-255 R	AHEARNE, J. F. AHEARNE, J. F	8006130205*	COMMISSION	ARTIGAS, R.	8004130015*	70-1007
ADAMS, H S	8006170477*	50-389 M					000/04000	50-317 P
ADAMB, M. S.	8006170273*	50-389 M	AHEARNE, J F	8006130207*	COMMISSION	ASH.R.F. ABHER.T.R	8006040209 8006190639	XPORTLIC
ADLER, T A	8006160151	50-287 Q	AHEARNE, J. F.	9006130213#	COMMISSION COMMISSION	ABHER, T. R	8006170637	XPORTLIC
ADLER, T. A.	8006160151	50-289 0	AHEARNE, J. F.	8005130215* 8005130170	50-320 U	ASHLEY, E C	8004300015	State Proc
ADLER, T. A ADLER, T. A	8006120335 8006120335	50-289 0 50-289 0	AHEARNE, J.F. AHEARNE, J.F	8006130170	COMMISSION	ABHLEY, E G.	8006260215	State Prog
		50-289 Q	AHEARNE, J F	8006260075	50-443 T	ABHELL, D. L.	8006230109	50-382 G
ADLER, T. A	8006120330 8006120330	50-289 G	AHEARNE, J. F.	8006300531	COMMISSION	ABNELL, D L	8006110309	90-362 A
ADLER, T A	8004170428	50-287 Q	AHEARNE, J F	8006260152	COMMISSION	ABNELL,D L	8006170283	50-382 K
ADLER, T. A ADLER, T. A	8006170628	50-289 O	ALBERTS, J J	8006300127	NUREO	ASHELL, D L	8006170290*	50-382 K
ADDMAT, E A	8006170273*	50~389 M	ALBERTIN, L	*475070396	50-280 G	ABHELL, D. L.	8004180384	50-362 8
ADRIANO, D G	8006300127	NUREO	ALDEN, H M	8004020379	50-171 H	AUDIN, L.	8006120403	FOIA
AGEE, J. R	8006240172*	QA999	ALDEN, W. M.	8006170446*	50-277 R	AUSTIN, H. A	8006240198	70-344 70-135
AGUIRE, A	8006250305*	COMMISSION	ALDEN, W. M	8006190339	50-277 R	AUSTIN, M A	8006180344 8006180350*	70-135
AHEARNE, J F	8006190133*	SECY	ALLINA A A	8006190599 8006240589	50-275 H 70-2909	AUSTIN, K A	8006180353*	70-135
AHEARNE, J.	8006300612*	FOIA	ALLRED, W H	8000210387				
AHEARNE, J. F.	8006120499#	50-10 P	ALLRED, D. L.	8006170324	70-2909	AUSTIN, M A.	8004200154 8004200584	70-364 70-364
AHEARNE, J F	8004160186	COMMISSION	ANDERSON, W. O	8006270420	NUREO	AUSTIN, M. A.	8004200585	70-364 70-364
AHEARNE, J F	8004160190*	COMMISSION	ANDERSON, D. C.	8006060240*	GA999 50-282 P	AUSTIN.M A AUSTIN.M A	8006230103	70-135
AHEARNE, J. F.	8004160173*	COMMISSION	ANDERSON, T. M ANDERSON, J. L.	8003280527 8006260020	RES	AUSTIN, M. A	8006270177*	70-135
AHEARNE, J F	8004160176*	COMMISSION	Wunskellur o r					70-135
AHEARNE, J F	8004160200*	COMMISSION	ANDERSON, D Ø	8006240126*	GA999	AUSTIN M. A	8006230002 8006200554	70-135
AHEARNE, J. F.	8004160202#	COMMISSION	ANDERSON, T. M.	8006180404*	50-395 B 50-498 0	AUSTIN, M A AUSTIN, M A	8006190421	70-364
AHEARNE, J F	8004140203*	COMMISSION	ANDERSON, I. H	8006260200* 8006040223	50-498 0 Toprep	AVSTIN, M. A	B006250111	70-364
AHEARNE, J. F.	8004140206*	COMMISSION	ANDERSON, 1. M ANDERSON, T. M	8004040223	TOPREP	A MITBUA	8006300570	70-135
AHEARNE, J F	8004160209*	COMMISSION					8006170798	70~135
AHEARNE, J F.	8004160212*	COMMISSION	ANDERSON, T M	8006130320	TOPREP	AUSTIN, M R AUSTIN, M, A	8006170778	71-9009
AHEARNE, J F	8004160215#	COMMISSION	ANDERSON, T. M	8006160127 8006120349	TOPREP 50-445 A	AUSTIN, M A	8006130064*	71-7009
AHEARNE, J F	8004160220#	COMMISSION	ANDERSON, T. M	8008120349	50-289 H	AUSTIN, M A	9006040054	71-135
AHEARNE, J. F	8004180211	COMMISSION	ANDERSON, B. J ANDERSON, T. M	8006170666	TOPREP	AUSTIN, M A	8006300023	70-364
AHEARNE, J	8004060107*	50-327 P					8006070009	PR
AHEARNE, J F.	B005200503	COMMISSION	ANDERSON, T. M.	8006170358	TOPREP 50-293 G	AVRUTIK.R F AXELRAD.M	8006070007	50-376 G
AHEARNE, J. F.	8006070110	COMMISSION	ANDOGNINI, G C ANDOGNINI, G C	8006120342 8006030345	50-273 P	AXELRAD, M.	8004180158	50-376 G
AHEARNE, J. F	8004020154	COMMISSION	ANDOGNINI, Q C	8006030346	50~293 P	AXELRAD, M	8006060348	50-344 8
AHEARNE, J, F	B006300617*	COMMISSION 50-320 P	ANDOONINI, O C.	8006030407	50-273 P	AXELRAD, M	8006060497	50-344 Q
AHEARNE, J F	8006090091				50-273 F	AXELRAD, M	8006060497	50-344 Q
AHEARNE, J. F.	8006090100	50~320 P	ANDOGNINI, Q. Q.	900003039	50-273 F 50-273 P	AXELRAD, M	8004110338	50-344 O
AHEARNE, J. F	6006130023	COMMISSION	ANDOGNINI, O C	8004030310 8004130280	50-293 P	AXLERAD, M	8006120153	50-344 G
AHEARNE, J. F.	8006120260	COMMISSION	ANDOGNINI, G C ANDOGNINI, G C	B006130303	50-293 F	AYER, J. E	8004030146#	70~25
AHEARNE, J F	8006120528	50-320 F	ANDOONINI, O C.	8006260179	50-293 P	BABBIP D.	£150E04008	State Prog
AHEARNE, J F.	8005280455	COMMISSION	Minnesian A. A.					

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
BACCI.R R BACON, J L BADRAN, S BAER, T S BAGAGLIO, M J	8004040507* 8004180342 8004030379* 8004120199 8004040578*	50-275 H 50-329 K 50-237 8 71-6400 50-142 G	Baskin, k p Baskin, k p Baskin, k p Baskin, k p Baskin, k p	8006130210 8006130301 8006170584 8006170522 8006200464	50-206 S 50-361 A 50-206 P 50-361 I 50-206 P	BEROHOLZ, W E BEROLUND, R H BERNARD, J BERNARD, J	8006050465 8006200548 8006250338 8006020405 8006050384	PR PR RES 50-20 S 50-20 S
BAGAGLIO.M J	8006130067#	50-275 @	Baskin, k p	8006230519	50-361 A	BERNARD, J	8006230051	50-20 S
BAGAGLIO.M J	8006250083#	50-344 @	Baskin, k p	8006240440	50-361 A	BERNERO, R M	8006200074*	50-312 P
BAILEY.J	8006270344	NUREQ	Baskin, k p	8006270194	50-206 Q	BERNREUTER, D L	8006060481*	50-70 P
BAILEY.R D	8006300054	NUREQ	Basbin, n	8006180182*	FOIA	BERNSTEIN, D L	8006060527	50-287 G
BAILEY.R D	8006170164	NUREQ	Basbin, n	8006180245*	FOIA	BERNSTEIN, D L	8006120020	50-287 G
BAILEY.R J BAIN.E L BAIR.G G BAISDEN.L BAISDEN.L	8004270245* 8004230295* 8004110277* 8004090452 8004250041	50-317 G CONTRACT 50-344 R CONTRACT CONTRACT	n Aigeae N Aigeae N Aigeae N Aigeae N Aigeae	8006180145* 8006180141* 8006180203* 8006180110* 8006180336*	FOIA FOIA FOIA FOIA	BERNSTEIN, D L BERNSTEIN, D L BERQUIST, B BERRY, O T BERTELL, R	8004040527 8006110116 8006030270 8006040294 8006300568	50-287 Q 50-287 Q 50-440 B 50-286 P PRM
BAIBDEN,L	8004030044	CONTRACT	N.NIERAB	8006180283*	FOIA	BERTELL,R	8006250350	PR
BAKER,K R	8004130111*	50-315 G	BARBIN,N	7702140223*	FOIA	BETTENHAUGEN,L	8006060109*	50-272 G
BAKER,A G	8004020548	RES	BATEMAN,H	8006250233*	50-354 G	BETTENHAUGEN,L	8006030612*	50-277 G
BAKER,K R	8004180044*	50-255 G	H.RESTBB	8006200015*	70-1151	BETZLER,W F	8006030096	PR
BAKER,K R	8004170749*	50-358 G	BATEB,J,H	8006250035*	70-143	BEVAN,R B	7911060551	50-10 F
BAKER.K R	8006230113*	50-150 Q	BATJER,K	8006300585*	PRM	BEVAN,R B	8006270042*	50-324 P
BAKER.B	8006170286	50-466 G	BAUER,E G	8006050383*	50-277 P	BEYEA,J	8006040047	50-320 P
BAKER.K R	8006040360	50-306 S	BAUER,E R	8006180443*	50-317 S	BICKWIY,L	8006190127	BECY
BAKER.C E	8006180156	40-8681	BAUER,E R.	8006180480*	50-318 S	BICKWIT,L	8006170792	50-574 O
BAKER.C E	8006240531	40-8681	BAUER,E R	8006180518*	50-318 S	BICKWIT,L	8006200348*	100FR
BAKER, C E Baker, H A Baker, K R Baker, B Baker, B,	8006200634 8006110085* 8006170088* 8006190553 8006190557*	40-8681 50-302 F 50-409 G 50-466 G 50-466 G	BAUM.P W BAUM.E A BAUM.E A BAUM.E A BAUNACK.W	8006160023* 8006110005 8006240469 8006260183 8006020266*	50-133 R 50-338 F 50-338 F 50-338 F 50-220 G	BICKWIT, L BICKWIT, L BICKWIT, L BICKWIT, L	8006180117 8006180132* 8006230036* 8006250030* 8006190559	SECY 50-247 T CONTRACT 10CFR 50-275 Q
BAKER, B	8006190364*	50-466	BAUNACK,W	8006170371*	50-247 G	BICKWIT, L	8006230357	50-275 0
BAKER, B	8006180394*		BAUNACK,W H	8006250170*	50-333 G	BIDDLE, C T	8006190343	50-466 0
BALALIB, C O	8006180218		BAUBER,M A	8006070060	PR	BIDDLE, C T	8006120030	50-466 0
BALDWIN, W A	8006040194		BAUBER,M A	8006050474	PR	BIDDLE, C T	8006120030	50-466 0
BALDWIN, W A	8006040194		BAUBER,M A	8006050474	PR	BIDDLE, C T	8006050085	50-466 0
BALDWIN, J K BALL: B J BALLENTINE: J K BALLENTINE: J K BALLENTINE: J K	8006270401 8006270031 8006110250 8006110318 8006130295	NUREQ NUREQ 50-327 8 50-327 8 50-327 R	BAXLEY,8 X BAXLEY,9 X BAXLEY,8 X BAXLEY,8 X BAXTER,F,D	8006030432* 8006030366* 8006070333* 8006200444* 8006110008*	50-321 8 50-366 8 50-321 8 50-366 8 50-309 0	BIDDLE,C T BIDDLE,C T BIDDLE,C T BIDDLE,C T	8006050085 8006090204 8006090215 8006120061 8006120064	30-466 9 50-466 9 50-466 9 50-466 9
BALLINGER, P L. BALTER, M S BANNER, A P BARATHAN, D. BARDES, G R	8006090323* 8006120180 8006300586 8006260421 8006110050	50-298 R FOIA FOIA NURED MISC	BAXTER, F D BAXTER, T A BAYBUTT, P BAYNARD, P Y BAYNARD, P, Y	800&110029* 800&11033& 800&300183 800&060354 800&110080	50-271 G 50-312 T RE8 50-302 P 50-302 P	BIDDLE,C T BIDDLE,C T BIDDLE,C T BIDDLE,J G BIDDLE,C.T	8006120068 8006120097 8006090204 8006090215 8006120061	50-468 9 50-468 9 50-468 9 50-468 9
BARI.R A BARI.R A Barker,n R Barker,j L Barker,n S	8004200022 8004200027 8004040229* 8004170320* 8004040222*	REB REB GA777 50-10 G GA777	BAYNARD, PYBAYNARD, PY	9004170617 8004180511 8004200337 8004300550 8004230485	50-302 R 50-302 K 50-302 Q 50-302 Q 50-302 Q	BIDDLE,C T BIDDLE,C T BIDDLE,C T BIDDLE,C T	8006120064 8006120068 8006120097 8006160166 8006160170*	50-466 Q 50-466 Q 50-466 Q 50-466 Q
BARKER, D B	8006020543	NUREG	BAYNARD, P. Y	8004230403	50-302 P	BIDDLE,C T	8006160166	7 50-466 Q
BARLETTA, R E	8006040117*	50-320 P	BAYNARD, P Y	8004240324	30-302 P	BIDDLE,C T	8006160170*	50-466 Q
BARNARD, J	8006090016*	50-245 G	BAYNE, J P	8004120123*	50-286 G	BIDDLE,C T	8006170609	50-466 Q
BARNARD, J	8006240114*	GA999	BAYNE, J P	8004180499	50-333 P	BIDDLE,C T	8006170609	50-466 Q
BARNEICH, J A	8006110041*	50-361 G	BAYNE, J P	8004230435	50-286 P	BIDDLE,C T	8006300323	50-466 Q
BARNES, I,	8006170382*	QA997	BAYNE, J P	8006240501	50-333 P	BIDDLE,C T	8006300340	50-466 9
BARNES, I	8006300172*	QA999	BAYNE, J P	8006260168	50-286 P	BIDDLE,C T	8006300323	50-466 9
BARNES, I,	8006250127*	QA999	BAYNE, J P	8006260178	50-286 H	BIDDLE,C T	8006300340	50-466 9
BARNETT, E W	8006060036*	50-445 M	BAYNE, J P	8006260180	50-333 H	BIELAWSKI,A P	8006120263	50-255 9
BARNEICH, J A	8006110037*	50-361 O	BEACH, A B	8006030225#	50-458 Q	BIELAWSKI,A P	8006170524	50-255 9
BARNETT, J E	8006160020	70-1621	BEAN.R M	8006200018	RE6	BILES,M.B	8004300641	MISC
BARNETT, E W	8006110364	50-445 M	BECHHOEFER.C	8006060463	50-466 0	BINFORD,E C	8006240332	50-10 D
BARNIBIN, M A	8006170641	50-395 A	BECHHOEFER.C	8006120389	50-409 0	BIRKEL,R A	8006020015	50-369 A
BARNTHOUSE, L W	8006300069	NUREO	BECHHOEFER.C	8006160140	50-409 0	BIRKEL,R A	8006050174	50-369 A
BARNTHOUSE, L W,	8006300085	NUREO	BECHHOEFER.C	8006130272	50-358 0	BIRKEL,R A	8006070477	50-437 A
BARNUM, D. J Barrett, P. A. Barrett, P. A Barry, D. N Barth, C. A	8006020481 8006060333* 8006190182* 8006200150 8006020110	RES 50-373 Q 50-373 Q PROJ 50-358 Q	BECHHOEFER, C BECHOEFER, C BECHOEFER, C BECKER, F L. BECKMAN, D A	8006260263 8006020313 8006020307 8006250342 8006030268*	50-387	BIRKEL, R A BIRKEL, R A BIRKEL, R A BISHOP, T W BISHOP, T. W	8006130127 8006170033 8006230135 8006250172* 8006300591*	50-369 A 50-369 A 50-369 F 50-397 A
BARTH: C. A BARTH: C. A. BARTH: C. A BARTH: C. A BARTH: C. A	8006020116* 8006020123 8006020146 8006180297 8006230248	50-358	BEERJ L. BEERB, F C BEERB, F C BEERB, F. C BELING, D C	8006090557 8006170696* 8006170649* 8006170638* 8006050510	PR 50-309 R 50-271 R 50-29 R 40-8484	BISHOP, T W BISHOP, C J BISHOP, L L BISHOP, L L	8004050234 8004020314 8004020550 8004110224 8004170340	50-344 8 50-275 0 50-320 0 PR PR
Barth, C A	8006230266	50-282	BELKE, W.	8006300043*	50-334 Q	818HOP, L L	8006170340	PR
Barth, C A.	8006300476		BELKE, W L	8006230364	50-284 P	818HOP, L L	8006110224	PR
Bartlett, J W	8005080228		BELL, J M	8006180206*	FOIA	818HOP, L L	8006170340	PR
Bashford, A L	8006060528*		BELL, S	8006260155*	COMMISSION	818HOP, L L	8006170247	PR
Baskin, K, P	8006030295		BELL, K E.	8006060457*	70-398	818HOP, L L	8006170247	PR
Baskin, k p.	8006020340	50-206 F	BEMIB, J. M	8006300609	FOIA	BISHOP.C J	8004040572	50-498
Baskin, k p	8006030373	50-206 P	BENNETT, M	8005210116	50-546 H	BISHOP.C J	8006170146	
Baskin, k p	8006030439	50-206 P	BENNETT, J	8006190592	50-275 H	BISHOP.C J	8004070302	
Baskin, k p	8006110052#	50-361 Q	BERG, R. R.	8006020534*	50-128 Q	BISHOP.C J	8006120353	
Baskin, k p	8006170497	50-206 Q	BERG, R. E	8006020555	NUREQ	BISHOP.C J	8006170570	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J	8006230377 8006240415 8006260209 8006260269 8006300413	50-485 G 50-488 G 50-320 G 50-275 G 50-338 G	BOWERS.C E BOWERS.C E BOWERS.C E BOWERS.E S	8006180374 8006030102 8006240231 8006250016 8006190544	70-820 PR 70-820 70-820 50-445 0	BROWN, R L BROWN, O D BROWN, O D BROWN, O D. BROWN, O D	8006230238* 8006020135* 8006120274* 8006120267 8006020130	QA999 50-298 Q 40-3453 40-3453 50-298 Q
BISHOP.C J	8006300432	50-275	BOWERS, E S	8006190642	50-488 0	BROWN, C	8006070461*	50-263 Q
BISSERT.F J	8006200450		BOWERS, E S	8006230474	50-275 0	BROWN I NG, R. E	8006040117*	50-320 P
BIVINS.W S	8006190332		BOWERS, E S	8006240311	50-452 0	BROWN, R. L	8006180303*	GA999
BLACK.K E	8006190328		BOWERS, E S	8006240430	50-142 0	BROWN, W J	8006110406	PR
BLACK.S A	8006300014		BOWERS, E S	8006260199	50-514 0	BROWN, G D	8006230071*	50-285 Q
BLACKMON,D B Black,R L Black,R L Blakeley,J E Blake,J	8006170868 8006030188 8006030213 8006260042 8006180071*	PR 50-312 T 50-522 O RES 50-518 Q	BOWLE, T B BOYD, D C BOYD, D C BOYD, D, C BOYD, O J	8006170753 8006170321* 8006180046* 8006170052* 8006040086	70-1100 50-282 G 50-255 G 50-315 G NUREG	BRGWN. O D BROWN. O D BROWN. O F BROWN. O D	B006240008* B006230045 B006240007* B006050465 B006050110	50-267 Q 50-285 Q 50-267 Q PR 50-445 Q
BLAKE.J	8004020575*	50-324 0	BOYD.D C.	8006130198*	50-315 G	BROWN, E J	8006050029	GRG
Blake.e L	8004120084	50-269 0	BOYER.V B	8006050383*	50-277 P	BROWN, E J	8006050424	GRG
Blake.e L	8004120084	50-269 0	BRABB.E E	8006060471*	50-70 P	BROWN, O D	8006250081*	50-285 G
Blake.J	8004180390*	50-416 0	BRADFORD.P.	8006060112*	50-327 P	BROWN, O D	8006250085*	50-265 G
Blake.e L	80040483	50-269 0	BRADFORD.W H	8006060550*	50-348 G	BROWN, O D.	8006240005	50-267 G
BLAKE, É L	8006060423	50-287 0	BRADFORD,P A BRADLEY,E R BRADLEY,R D BRADLEY,E,J BRADLEY,E,J	8006260075	50-443 T	BROWN, O D.	8006250082*	50-285 G
Blake, E, L	8006120040	50-287 0		8006270022	NUREO	BROWN, O D.	8006300285*	40-8681
Blake, E L	8006120040	50-287 0		8006050425*	50-389 G	BROWN, O D.	8006020277	50-404 G
Blake, E, L	8006120022	50-289 0		8005190521	50-171 I	BROWN, O D	8006300281	40-8681
Blake, É L	8006120414	50-289 0		8006020330	50-352 A	BROWN, L J	8006190439*	50-133 G
BLAKE, E L	8006120414	50-287 0	BRADLEY, E J	8006050379	50-277 P	Brown, C. J.	8006250078	50-285 G
BLAKE, E L	8006180154	50-287 0	BRADLEY, E J	8006050383*	50-277 P	Brown, L. J.	8006190437	50-133 Q
BLAKE, E L	8006180154	50-287 0	BRADLEY, E J	8006110094	50-277 F	Brown, B. C	8006120392	50-339 P
BLAKE, E. L	8006110110	50-287 0	BRAEHLER, T F	8005210116	50-546 H	Brown, H. H	8006120332	50-275 Q
BLAKE, E L	8006110117*	50-287 0	BRAMLETT, L S	8006120283*	50-313 S	Brown, H. H	8006120334*	50-275 Q
BLAKE,E L	8006110117#	50-289 0	BRAMLETT, L SI	8006170630*	50-313 8	BRDWN, B C	8006200480	50-337 P
BLANDFORD,R K	8006020138	RES	BRAMLETT, L. SI.	8006190689*	50-313 R	BROWN, W M	8006240460	M190
BLASK,J K	8006180040	50-289 0	BRANAQAN, E F	8006090213*	50-409 0	BROWN, B C	8006250128	50-339 P
BLASK,J K	8006180043#	50-289 0	BRANAQAN, E F	8006300256	NUREG	BRUGGER, R M	8006300275*	50-186 Q
BODTKE,P J	8006110136#	50-255 R	BRANAQAN, E F	8006270003	NUREG	BRUGGER, R M	8006110137	50-186 B
BOODEN, O	8004030240	40-1162	BRANGH, M W	8006170749*	50-358 G	BRUGOER, R. M	8004110044	50-186 8
BOODEN, O	8006240305	40-1162	BRANGH, M. W	8006170088*	50-407 G	BRUNE, R. L	8004270349	NUREQ
BOHM, R E	8004120284	HASTE MOT	BRANDENBURG, B	8006260212	50-247 O	BRUNE, R. L	8004200546	NUREQ
BOHN, R J	8004030371	50-367 R	BRAY, T. C	8006110367	50-297 F	BRUNNER, E. J	8004050519	50-245 Q
BOHN, R J	8004040314	50-367 R	BRENNAN, J E	8006130233*	50-307 H	BRUNNER, E. J	8004020085*	50-333 Q
BOHN,R J	8006110119	50-367 R	BREWER, H E	8006190538*	50-361 I	BRUNNER, E. J	8006120132*	50-286 G
BOHN,R J	8006200370	50-367 R	BRIDENBAUGH, D	8006040047	50-320 P	BRUNNER, E. J	8006060032*	50-309 G
BOHN,R J	8006260195	50-367 R	BRIDENBECKER, R.	8006110055*	50-361 0	BRUNNER, E. J	8006030264*	50-334 G
BOLLINGER,Q A	8006270038	NUREQ	BRIGGS, L.	8006020180*	50-219 0	BRUNNER, E. J	8006020176	50-219 G
BONILLA,M Q	8006060476*	50-70 P	BRIGGS, L.	8006190153*	50-219 0	BRUNNER, E. J	8006020264	50-220 G
BONZON, L L	8006200598	NUREO	BRIGHT,R M	8004270283	50-302 P	BRUNNER, E J	8006050432*	50-244 G
BONZON, L L	8006230011	NUREO	BRIGHT,R M.	8004110475	PR	BRUNNER, E J,	8006030043	50-322 G
BONZON, L L	8006160141	NUREO	BRIGHT,R M	8004020159	50-302 F	BRUNNER, E, J	8006060105	50-272 G
BOOK, H E	8006190168*	50-320 G	BRIGHT,Q. G	8004090049	50-577 Q	BRUNNER, E J,	8006040055	50-245 G
BOOK, H E	8006190249*	50-277 G	BRIGHT,R M	8004090323	50-302 P	BRUNNER, E J	8006030106	50-309 G
BDOK, H E BOOK, H E BOOK, H E BOOK, H E	8006170378* 8006180082* 8006170274* 8006170292* 8006070030	50-277 G 50-320 G 70-25 70-25 70-754	BRIGHT, R M BRIGHT, R.M. BRIGHT, R M BRIGHT, R.M. BRIGHT, R M	8006110185 8006110290 8006170436 9006180531 8006170488	50-302 0 50-302 0 50-302 0 50-302 F 50-302 P	BRUNNER, E J BRUNNER, E J. BRUNNER, E, J. BRUNNER, E, J. BRUNNER, E J	8006030610 8006170810 8006170303 8006180053 8006180054	50-277 G 50-317 G 50-271 G 50-272 G 50-27 G
800K, H E.	8006090054*	70-754	BRIGHT,R M	8004300374	50-302 0	BRUNNER,E J	8006180121	50-272 Q
800K, H E	8006090513*	50-73 G	BRIMALER,J,E	8004090357*	50-309 8	BRUNNER,E J	8006020535	50-272 Q
800K, H E	8006090046*	70-25	BRINKLER,J E	8004110200*	50-309 8	BRUNNER,E J	8006170387	50-247 Q
800K, H E	8006090041	70-25	BRISTOL,D,C.	8004120111	XPORTLIC	BRUNNER,E J	8006170804	50-293 Q
800K, H E	8006090508	50-79 G	BRISTOL,D,C.	8004020572	XPORTLIC	BRUNNER,E J	8006030103	50-29 Q
BOOK, H E BOOK, H E BOOK, H E BOOKE, B L	8006250108 8006250112* 8006170302* 8006240289 8006240459*	50-275 G 50-275 G 70-25 27-48 40-1162	BROCKETT, T BROCKETT, T, BROCKETT, T BROCKETT, T. W. BROCKETT, T. W.	8004090530 8004090534 8004090545 8004240134 8004300458	14E 14E 50-280 8 50-324 8 50-259 8	BRUNNER, E J BRUNNER, E, J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8006250152 8006250161 8006250188 8006060027 8006120119	50-245 Q 50-29 Q 50-333 Q 50-309 Q 50-286 Q
BDDKE, B L	8006240459*	40-1162	BROCKETT, T W	8006300344	50-321 8	BRUNNER, E. J	8006300037	50-334 Q
BDDKS, P A	8006200599*	50-320 H	BROCKETT, T. W	8006300330	50-254 B	BRUNNER, E. J	8006030426	50-244 Q
BORDENICK, B M	8006060270	50-322 O	BROCKETT, T W	8006300333	50-346 B	BRUNNER, E. J	8006120191	50-272 Q
BORDENICK, B M	8006090242	50-322 O	BRODKEY, J R.	8006180262	50-387 Q	BRUNNER, E. J	8006300035	50-322 Q
BORDENICK, B M	8006110311	50-322 O	BROEWL, D	8006060350*	50-344 B	BRUNNER, E. J	8006030063	50-317 8
BORDENICK: B M	8006110289	50-514 0	BROEHL, D. J.	8006060411	50-344 8	BRUNNER; E. J	8006070451	50-317 8
BORDENICK: B M,	8006130162*	50-322 0	BROEHL, D. J.	8006240319	50-344 8	BRUNNER; E. J	8006050413	50-317 8
BORDENICK: B M	8006130159	50-322 0	BROEHL, D. J.	8006170516	50-344 F	BRUNNER; E.	8006160231	50-272 8
BORDENICK: B, M,	8006160083	50-322 0	BROEHL, D. J.	8006180472	50-344 Q	BRUNNER; E. J	8006180607	50-245 8
BORDENICK: B M	8006160087*	50-322 0	BROEHL, D. J.	8006200498	50-344 B	BRUNNER; E. J	8006180612	50-317 8
BDROMANN, E. A.	8006240064*	50-358 G	BROOKB, F H	8006300207*	50-249 G	BRUNNER, J. F	8006240399	50-329 K
BDROMANN, E. A.	8006120481	50-358 G	BROWN, R J	8006270362	NUREG	BRUSH, P. N	8006170823	XPORTLIC
BDROMANN, E. A.	8006260293*	50-358 G	BROWN, R A	8005230341*	50-10 G	BRUSKE, S. J.	8006260009	50-295 P
BDROMANN, E. A.	8006170682	50-358 A	BROWN, R. A,	8006170788*	50-277 G	BRYANT, J. C.	8006120145*	50-370 G
BDROMANN, E. A.	8006300242	50-358 G	BROWN, R. A	8006170827*	50-273 G	BRYANT, J. C.	8006180077*	50-518 G
BOBCHWITZ, R	8006170873	PR	erchn, R. A	8006180611*	50-333 Q	BRYAN, J. K	8004090531	PR
BOBTON, J W	8006270175	50-286 P	Brohn, R. A	8006190230*	50-220 G	BRYAN, J. K	8004230049*	50-483 @
BOUKNIGHT, J A	8006110266	50-445 M	Erchn, G. D.	8006050122*	50-445 Q	BRYAN, R. H	8004200531	NUREQ
BOUKNIGHT, J A	8006170493	50-389 M	Brohne, W. G.	8006170398*	50-277 G	BRYAN, J. K.	8004110240	50-483 H
BOURNIA, A	8006190089	50-373 A	Brohne, W. G.	8006050115*	50-445 Q	BRYAN, J. K	8004240441	50-483 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
BUCHANAN, J R BUCHHOLZ, R H BUCHHOLZ, R H BUCHHOLZ, R H BUCKLEY, B C	8004240041	NUREO	CALHOUN, J R	8006170497	50-257 6	CARLSON,R T	8006200183	50-387 8
	8004020247	TOPREP	CALHOUN, J R	8006170554	50-327 9	CARLSON,R T	8006200232	50-397 8
	8004020270	TOPREP	CALHOUN, J R	8006170581	50-276 8	CARLSON,R T	8006240098*	50-352 9
	8004110319	TOPREP	CALHOUN, J R	8006170506	50-276 8	CARLSON,R T	8006200200	50-387 8
	8004130117	50-275 A	CALHOUN, J R	8006170536	50-327 8	CARLSON,R T	8006250223	50-354 0
BUCKLEY, B C BUCKNER, S P BUDNITZ, R J BUDNITZ, R J	8005180627	50-275 A	CALHOUN, J R	B006170603	50-296 8	CARLBON:R T	8006300236*	50-245 Q
	8005230028	50-461 A	CALHOUN, J R	B006170689	50-327 8	CARLBON:R T	8006300226	50-245 Q
	8005300149*	GA999	CALHOUN, J R	B006180521	50-327 8	CARLBON:R T	8006240091	50-352 Q
	8005250355	Res	CALHOUN, J R	B006180527	50-327 6	CARLBON:R T	8006240369	50-387 Q
	8005120157	MISC	CALHOUN, J R	B006170543	50-327 8	CARLBON:R T	8006250394	50-482 S
BUHL, T E	8004040185	WASTE HOT	CALHOUN, J R	8006180484	50-327 8	CARLBON, R T	8004300289	50-412 8
BULLIBCHECK, T	8004300234	RES	CALHOUN, J R	8006180502	50-296 8	CARLBON, R T	8004300005	50-354 8
BURANEK, D	8004140225	WASTE HOT	CALHOUN, J R	8006180530	50-327 8	CARLBON, R T	8004250399	50-387 6
BURCHETTE, W H	8004250173	50-445 M	CALHOUN, J, R	8006190468	50-259 8	CARLBON, R T	8004250401	50-423 8
BURCHETTE, W H	8004250173	50-445 M	CALHOUN, J R	8006200451	50-327 8	CARLBON, R T	8004250403	50-482 8
BURCHETTE, W H BURDETTE, T E BURDEN, H BURGER, J F BURKE, D J	8006190454	50-445 M	CALHOUN, J R	8006200488	50-327 8	CARLSON,R T	8006250407	50-354 8
	8006160219#	50-395 G	CALHOUN, J R	8006200475	50-327 8	CARLSON,R T	8006250414	50-387 8
	8006200179#	50-387 B	CALHOUN, J R	8006240425	50-327 8	CARLSON,R T	8006300041	50-387 9
	8006170331	PR	CALHOUN, J R	8006240363	50-327 8	CARNEY,J A	8006170242	50-445 N
	8006250107#	50-280 G	CALHOUN, J R	8006240388	50-327 8	GARR,A V	8006060497	50-344 0
BURKHARDT, W	8006040136	70754	CALHOUN, J R	8006240499	50-296 8	CARR, A V	90040497	50-344 0
BURKHARDT, W	8006030146*	7025	CALHOUN, J R	8006240412	50-327 8	CARRIER, M J	9004230287	70-778
BURNETT, R F	8006180219*	Foia	CALHOUN, J R	8006240374	50-327 8	CARRICK, J, T	9004090515*	50-274 0
BURNETTE, G W	8006120247	Reb	CALHOUN, J R	8006240410	50-327 8	CARROLL, D E	8006200119	50-10 0
BURNETT, P T	8006230237*	50321 G	CALHOUN, J R	8006300516	50-327 8	CARROLL, D E	8004200123	0R9
BURNETT, P. T	8006090088*	50-339 G	CAMM, F A	8006170808*	50-171 H	CARROLL.J T	8006060156	50-219 B
BURNETTE, G. W	8006170721	RE8	CAMPBELL, D H	8006200147*	50-482 P	CARROLL.J T	8006120294	50-219 B
BURNETT, P T	8006250076*	50-302 G	CAMPBELL, J E	8006200535	NUREO	CARTER.K W	8006050090	50-320 Q
BURNETTE, G W	8006260425	RE8	CANNON, J M	8006200122	27-39	CARTER.K W	8006180190	50-289 Q
BURNETT, R F	8006230208	XPORTLIC	CANNON, J M	8006260210	27-39	CARTER.K W	8006060408#	50-289 Q
BURNS, S Q BURSTEIN, S BURSTEIN, S BURNELL, S B	8006260196 8006180558* 8006050034 8006200547* 8006120087	30-498	CANYON, J M CANTER, H L CANTER, H L CANTRELL, F S CANTRELL, F S	8006260210 8006250066* 8006250184* 8006050103* 8006180051*	27-39 50-312 G 50-312 G 50-566 G 50-416 G	CARTER, K. W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W CARTWRIGHT, W	9006190549 9006050333# 9006050339# 9006060407 9006060410#	50-320 0 50-339 P 50-339 P 50-338 B 50-338 B
BURWELL, 6 B BURWELL, 5 B BURWELL, 5 B BURWELL, 6 B BURWELL, 6	8006070484 8006300018 8006300020 8006250325 8006260422	50-445 A 50-445 A 50-445 A 50-445 F 50-445 A	CANTRELL, F 8	8004030511* 8004050420* 8004140219* 8004180397* 8004250215*	50-518 Q 50-553 Q 50-995 Q 50-328 Q 50-370 Q	CARTHRIGHT, W R. CARTHRIGHT, W R CARTHRIGHT, W. R, CARTHRIGHT, W. R CARTHRIGHT, W. R	8006070359 8006070361* 8006110252 8006110257* 8006120331	50-338 8 50-338 B 50-339 8 50-339 8 50-338 8
BUSCH,RW BUSSELMAN,OJ BUSTION,DR BUTTON,WH BUTTON,WH	8006070143 8006250105> 8006170331 8006060445 8006300559	50-522 A Toprep Pr Foia Foia	CANTRELL, F 8 CAPHTON, D L CAPHTON, D L CAPHTON, D CAPLAN, J 8	8006050130 8006040107* 8006030612* 8006040337 8006050032*	50-518	CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H. R, CARTHRIGHT, H R, CARTHRIGHT, H R	900612033* 9006120357 9006120362* 9006160053 9006160056*	50-338 & 50-338 & 50-338 & 50-339 &
BYRNE, J P CAHILL,W J CAHILL,W J CAHILL,W J CAHILL,W J	8006120372 8006060521 8006110471 8006110051 8006060280	PRM 50-247 G PR 50-247 P 50-247 F	CAPOROSO.L. CAPRA.R A CAPRA.R A CAPRA.R CAPRA.R	8006250336 8006170843* 8006170839 8006060524 8006300250	XPORTLIC TOPREP TOPREP TOPREP TOPREP	CARTWRIGHT, W R CARTWRIGHT, W R, CARTWRIGHT, W, R, CARTWRIGHT, W, R CARTWRIGHT, W, R	8006160076 8006160079* 8006170580 8006170587* 8006170643	50-339 8 50-339 8 50-339 8 50-339 8
CAHILL,W J CAHILL,W J CAHILL,W J CAHILL,W J	8006170451 8006170454* 8006180526 8006180108 8006180434	50-247 P 50-247 P 50-247 F 50-247 P 50-247 P	CAPRA,R A. CAPRA,R A CAPRA,R A CAPRA,R A CAPRA,R	8006200556 8006170833* 8006060287 8006060272 8006050539	TOPREP TOPREP NUREO 50-312 O 50-269 P	CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R. CARTWRIGHT, W, R. CARTWRIGHT, W R	8006170650* 8006170694 8006170701* 8006230417 8006230418*	50-338 8 50-339 8 50-339 8 50-339 8
CAHILL.W J CAHILL.W J CAHILL.W J CAHILL.W J	8006180529 8006180426 8006190626 8006190535 8006240350*	50-3 R 50-3 R 50-247 R 50-247 B 50-247 P	CAPRA,R A CAPRA,R A CAPRA,R A CARBON,M W CARBONEAU,M L	8006060278 8006060600 8006060283 7908270476 8006300301	50-313 P 50-312 G 50-269 P 50-320 C REB	CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R CARTHRIGHT, W R. CARTHRIGHT, W R	8006230442 8006230447* 8006230503 8006230509* 8006230544	50-337 8 50-339 8 50-338 8 50-338 8 50-339 8
CAHILL, W. J	8006240364*	50-247 P	CARDILE, F. P	8004300254	NUREO	CARTWRIGHT, W R CARTWRIGHT, W R, CARTWRIGHT, W R, CARTWRIGHT, W, R, CARTWRIGHT, W R	8006230551*	50-339 8
CAHILL, W. J	8006240349	50-247 P	CARDILE, F. P	8004270003	NUREO		8006230494	50-339 8
CAHILL, H. J	8006240361	50-247 P	CAREY, J. J.	8004110194*	50-334 G		8006230500*	50-339 8
CAHN, A. L	8006190333	REGOD	CAREY, J. J.	8004200492	50-271 J		8006230516	50-338 8
CALDER, W	8006120472*	GA999	CAREY, J. J.	8004240379	50-334 E		8006230524*	50-338 8
CALDWELL, J J	8004180247	RE8	CARLOS,P G	80060&0009*	40-8349	CARTHRIGHT, W R CARTHRIGHT, N. R. CARTHRIGHT, W R. CARTHRIGHT, W R CARTHRIGHT, W R	8006230534	50-337 8
CALHOUN, J, R	8004030397	80-327 8	CARLEON,R T.	8006240379*	50-387 G		8006230539*	50-337 8
CALHOUN, J R	8004030480	50-327 8	CARLEON,R T.	8006060194*	50-412 G		8006270236	50-337 8
CALHOUN, J R	8004030427	50-327 8	CARLEON,R T	8006250229*	50-354 G		8006270241*	50-337 8
CALHOUN, J R	8004030453	50-327 8	CARLEON,R T	8006020253	50-387 G		8006270262	50-336 8
CALHOUNIJR. CALHOUNIJR CALHOUNIJR CALHOUNIJR GALHOUNIJR	8006030442 8006030457 8006060374 8006060309 8006060412	50-259 B 50-327 B 50-327 B 50-327 B 50-327 B	CARLEON, R.T. CARLEON, R.V. CARLEON, R.T. CARLEON, J. D. CARLEON, R. T.	8004030084 8004040056* 8004190274 8004050411* 80040904459	50-311 Q 71-135 50-334 Q 50-361 Q 50-423 B	CARTHRIGHT, W R CARTHRIGHT, W, R CARTHRIGHT, W, R, CARTHRIGHT, W R CARTHRIGHT, W R,	8006270265* 8006270310 8006270315* 8006270270 8006270275*	50-338 8 50-338 8 50-339 8 50-339 8
CALHOUN, J. R.	8006110143	50-240 8	CARLEON, R.T.	8006090297#	50-387 Q	CASAUSON: M	8006300422*	50-390 A
GALHOUN, J. R.	8006110270	50-327 8	CARLEON, R.T.	8006090283	50-387 Q	CASIOLIA: J. H.	8006270286*	50-341 B
GALHOUN, J. R.	8006110287	50-259 8	CARLEON, R.T.	8006280183	50-289 Q	CASPERS: R. H.	8006250210*	CONTRACT
CALHOUN, J. R.	8006110173	50-327 8	CARLEON, R.T.	8006060184	50-412 Q	CATCHPOLE: G. J.	8006040063	40-8693
CALHOUN, J. R.	8006110269	50-259 8	CARLEON, R.T.	8006090083	50-352 8	CATCHPOLE: G. J.	8006120047	40-8745
CALHOUN, J R	8006110104	50-296 S	CARLBON, R. T	8006120102	50-387 8	CATTON, I	8006120275	ACRS
CALHOUN, J, R	8006110219	50-327 S	CARLBON, R. T	8006250173	50-423 G	CATTON, I	8006160182	ACRS
CALHOUN, J R	8006110283	50-327 S	CARLBON, R. T	8006250202	50-322 G	CATTON, I	8006160189	ACRS
CALHOUN, J R.	8006170566	50-259 S	CARLBON, R. T	8006250207	50-412 G	CATTOIR, H	8006170514	50-275 H
CALHOUN, J R	8006170635	50-259 S	CARLBON, R. T	8006250178	50-287 G	CATTON, I.	8006160175	ACRS

AUTHOR	ACCESSION NUMBER	TOBLEVE CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESION NUMBER	SUBJECT CATEGORY
CAVANAUGH, H CELLIER, F CERNE, A C. CHADWELL, H M CHAMBERB, R	8006200489 8006250162 8006250176* 8006250176* 8006260031	50-313	CHILK,8 J CHILK,8 J CHILK,8 J CHILK,8 J	8006260061 8006170812 8006170818* 8006260139* 8006250077	10CFR PRM PRM PRM PR	CLARK,R A CLARK,R A CLARK,R A CLARK,R A CLARK,R A	8006030536 8006060247 8006090537* 8006020011 8006040192	50-344 50-344 50-336 50-338 50-317
CHAN, B P	8006170095*	50-373 A	CHILK, B J	8004240134	PRM	CLARK.R A	8006090525	90-338
CHANANIA, F D	1006110162	50-445 M	CHILK, B J	8004240173*	PR	CLARK.R A	8006090529*	50-338
CHANANIA, F D	1006110352	50-445 M	CHILK, B J	8004240223	10CFR	CLARK.R A	8006170244	50-266
CHANDLER, L J	8006030232*	50-320 G	CHILK, B, J	8004250349	REGGD	CLARK.R A.	8006170249*	50-266
CHANDLER, L J	8006030217	50-320 G	CHILK, B J	8004240170	PR	CLARK.R A	8006170256*	50-266
CHANDLER, L J CHANDLER, L J CHANDLER, L J CHANG, H B CHAPLIN, B D	8006090013 8006240470 8006300342 8006120469 8006030472#	50-320 Q 50-320 Q 50-361 Q NUREQ 50-320 B	CHILK:8 J CHILK:8 J CHILK:8 J CHILK:B J	8006020301 8006020323 8006170709 8006240630 8006260329	50-224	CLARK,R A CLARK,R A CLARK,L CLARK,L CLARK,L	8006130037 8006190146 8006020405 8006050384 8006230051	50-266 50-344 50-20 50-20 50-20
CHAPLIN.S D	8004040271*	50-320 S	CHILK, B J	8006170777	PR	CLARKIR J	B006050177	50-257
CHAPLIN.B.D	8004140027*	50-320 S	CHILK, B J	8006020477	PR	CLARKIR J	8006050394	50-257
CHAPLIN.B D	8004230335*	50-320 S	CHILK, B J	9006020487	50-320 G	CLARKIR A	8006120017	50-265
CHAPLIN.B D	8004240510*	50-320 S	CHILK, B. J	8006160152	PR	CLARKIR A.	8006120023*	50-265
CHAPHAN.L D	8004240284	NUREO	CHILK, B J	8006160160*	PR	CLARKIR A	8006120028*	50-265
CHAPMAN, M. C.	8006270038	NUREQ	CHILK, B J	8006020310	50-488 0	CLARK,R A.	8006170859	50-309
CHAPMAN, L. D.	8006130360	RES	CHILK, B. J	8006060529	50-485 0	CLARK,R.A.	8006180416	50-336
CHAPMAN, L. D.	8006170330	RES	CHILK, B. J.	8006180602	50-272 0	CLARK,R A	8006180417*	50-336
CHARNOFF, G.	8006170399	50-244 G	CHILK, B. J.	8006190018	50-338 0	CLARK,R A	8006180418*	50-336
CHARNOFF, G.	8006170399	50-244 Q	CHILK, B. J	8006060523	50-247 0	CLARK,R A	8006190120	50-335
CHABE; J H	8006240273#	50-259 G	CHILK, B J	8004250376	10CFR	CLARK.A T	8006130123	70-1308
CHABE; J H	8006240174#	50-259 G	CHILK, B, J	8006160162	XPDRTLIC	CLARK.R.A	8006240598	50-245
CHABE; J H	8006050434#	50-364 G	CHILK, B J	8006200642	REGGD	CLARK.R A	8006240604*	50-245
CHAUDHARY, B K	80063U0236#	50-245 G	CHILK, B J	8006240194	REGGD	CLARK.R A	8006240607*	50-249
CHECK; P 8	8005280473#	COMM 18810N	CHILK, B J	8006240211	10CFR	CLARK.R A	8006180104	50-317
CHERN, W. 8. CHERN, M. 8. CHESTER, R. O CHIANGI, N. J. CHIANGI, N. J.	8006190060 8006120469 8006200021 8006110234 8006110244	RES NUREO RES 50-400 S 50-400 S	CHILK,S J CHILK,S J CHILK,S J CHILK,S J	8006160167 8006230278 8006240623 8006300321 8006200582	10CFR 10CFR 10CFR PRM XPORTLIC	CLARK,R A. CLARK,R.A. CLARK,R.A CLARK,R A	8005240171 8005240175* 8005240179* 8005250279 8005250003	50-344 50-344 50-344 50-70 50-344
CHIANGI:N J. CHIANGI:N J. CHILDB:N V. CHILDB:N V.	8006070306 8006160070 8006240383 8006020318# 8006020361#	50~400 8 50-400 8 50-400 8 50-333 8 50-333 8	CHILK.B.J. CHILK.B J CHILK.B J CHILK.B J CHILK.B J	8006120393* 8006160142* 8006120242 8006120314 8006130271	50-409	CLARK,R A CLARK,R A CLARK,R A CLARK,S CLARK,H K	8006260007* 8006270422 8006260040* 8006270259* 8006230380	50-344 50-285 50-344 50-295 50-329
CHILDS, W V	B004020394*	50-333 8	CMILK, B J,	8006160091	50-331 0	CLARK, L	8006300270	50-20
CHILDS, W V	B004110010*	50-333 8	CHILK, B J	8006160100	50-443 0	CLAY, E. L	8006160242*	70-143
CHILDS, W V	B004110021*	50-333 8	CHILK, B, J	8006180406	50-443 0	CLAYTON, F L	8006250142	50-344
CHILDS, W V	B004110077*	50-333 6	CHILK, B, J	8006190537	50-320 0	CLAYTON, F L	8006060531*	50-348
CHILK, S, J,	B004020530*	8ECY	CHILK, B J	8006300308*	50-320 0	CLAYTON, F L	8006030066	50-344
CHILK.8.J.	8004020526*	CONTRACT	CHILK: B. J.	8004180402	50-289 0	CLAYTON, F.L	8004030305	50-364
CHILK.8 J	8005280084	ACRS	CHILK: B. J.	8006190547	50-3 0	CLAYTON, F.L	8004030312	50-348
CHILK.8 J	8005270043	ACRS	CHILK: B. J.	8006190543	50-320 0	CLAYTON, F.L	8004030272	50-364
CHILK.8.J.	8005270053	ACRS	CHILK: B. J	8006300583	FOIA	CLAYTON, F.L	8004030370	50-364
CHILK.8.J	8004040102*	50-327 P	CHILK: B. J	8006240439	50-293 M	CLAYTON, F.L	8004050033	50-348
CHILK.B.J CHILK.B.J. CHILK.B J. CHILK.B.J.	8005230274 8005230383 8006030204 8003230071 8005230109	ACRS ACRS 50-486 A ACRS ACRS	CHILK, 8. J. CHILK, 8 J. CHILBON, V. T CHILBON, V. T. CHILBON, V. T.	8006240307 8006300366 8006170471* 8006170474* 8006170479*	50-466 G 50-320 O 50-250 R 50-250 R 50-250 R	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8006050350 8006110260 8006250015 8006110017 8006180440	50-346 50-364 50-348 50-349 50-349
CHILK, 8. J. CHILK, 8. J CHILK, 8. J CHILK, 8. J. CHILK, 8. J.	8005230374 8005270230 8004300546* 8005230247 8005230560	ACRB ACRB FOIA ACRB ACRB	CHIN.B. CHINNERY,M A CHONO,T.W. CHOU,C K CHOU.C K	9006170057 9006160093* 9006030101* 9006300054 9006170164	71-6400 50-443 Q 50-322 Q Nureq Nureq Nureq	CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8006230182 8006170598 8006190410 8006180415 8006190493	50-348 50-348 50-344 50-364 50-348
Chilk, 8. J.	8004130048*	PR	CHOULEB, N.C.	8006130120*	50-282 0	CLAYTON, F L	8006300159	50-364
Chilk, 8. J.	8004130079	10CFR	CHOULEB, N.	8006090461*	50-263 0	CLAYTON, F L	8006300572	50-348
Chilk, 8. J.	8004170801	REGOD	CHRIBBOTIMOB, N	8006230078*	50-254 0	CLAYTON, F L	8006180432	50-348
Chilk, 8. J	8004230313	10CFR	CHRIBTOFFER, O. M	8006030083*	50-346 0	GLAYTON, F L	8006230348	50-348
Chilk, 8. J	8004130051*	PR	CHRIBTENBURY, E	8006120011	50-261 1	CLAYTON, F L	8006240368	50-348
CHILK, S, J. CHILK, S J. CHILK, S J. CHILK, S J. CHILK, S J.	8006130047	PR	CHRISTENSEN, S. W	8006300069	NUREC	CLAYTON: F L.	8004240414	50-364
	8006130066	PR	CHRISTENSEN, S	8006230423	30-344 G	CLAYTON: F L.	8004240176	50-364
	8006130087	10GFR	CHURCH, L. B.	8006020376	30-288 P	CLAYTON: F L	8004240334	50-364
	8006130094	PRM	CHURCH, L. B	8006020216	50-288 F	CLEMENT: G	8004170461*	50-336
	8006130100	10GFR	CHURCH, J. D.	8006110089	70-1314	CLEMONB: P.	8006270188*	70-135
CHILK.8.J CHILK.8.J CHILK.8.J CHILK.8.J	8006250354 8006250345* 8006130061* 8006250344 8006260011;	10CFR PR NUREO PR 10CFR	CHURCHILL, B W. CHURCHILL, B.W CIAMMARA CIESZKIEWICZ, S CIESZKIEWICZ, S.	8006160078 8006160078 8006230709 8006110102* 8006170452*	50-320 Q 50-320 Q XPORTLIC 50-10 R 50-10 R	CLEMONS, P. GLEMONB, P CLEVELAND, J. G CLEVELAND, C. J GLINE, J. E	8006050088* 8006170208* 8006270031 8006120503 8006020348	70-33 50-201 NUREG 50-324 50-320
CHILK, S J	8006130057	NUREG	CLESZKIEWICZ,S,	8006170457*	50-10 R	CLOUGH, R. L	8006230011	NUREG
CHILK, S J	8006260005	REGOD	GIESZKIEWICZ,S,	8006170461*	50-10 R	COFFEY, E C	8006200093*	CENTRACT
CHILK, B J	8006260021	10CFR	GIPOLLA,A J	8006300370	40-3372	COGGIN, C L	8006200481*	50-366
CHILK, B, J.	8006120427	10CFR	GIRISTMAN,J N	8006240347	50-338 G	COGGIN, C, L	8006170679*	50-321
CHILK, S J	8006130070	NUREG	CLANCY,P	8006060537*	50-275 H	COGGIN, C L	8006190588*	50-321
CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J.	8006130073 8006130105 8006250199 8006230342 8006240201	DRO REOGD 100FR PR 100FR	CLARK, JR CLARK, D. L CLARK, R. W CLARK, R. W CLARK, R. W	8006200579 8006270065 8006120158* 8006120161* 8006230123*	50-201 P Nureg Hibc Mibc Commibbion	CDQQIN, C.L COGOIN, C.L COHEN, B.L COHEN, I GOHEN, I	8006170574* 8006240458* 8006300116* 8006030027* 8006200538*	50-321 50-366 ACR8 70-371 70-33

AUTHOR	ACCESS 10N NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB JECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
COHEN, B COHEN, D COHEN, D COHN, D COHN, D B	8004030049* 8004180043* 8004300555* 8004110382* 8004110354	CONTRACT 50-287 0 CONTRACT 50-367 0	CONTE,R J CONVER,B CONWAY,J T CONWAY,W F CONWAY,W F	8006130226 8006130151* 8006040039* 8006040061 8006170645	50-320 S F01A 71-9001 71-9039 50-271 R	COUNBIL, W G COUNBIL, W G COUNBIL, W G COUNBIL, W G COUNBIL, W G	8006030064 8005300283 8006040011 8006240617* 8006020436	50-245 Q PR 50-336 Q 50-293 Q NUREQ
COHN. D B COHN. D B COHN. D B COHN. D B	8006110376* 8006110378* 8006300396 8006300396 8006300396	50-347 0 50-347 0 50-347 0 50-347 0 50-347 0	COBK'Y M COBK'Y H COBK'Y H COBK'B N	8004170743* 8004020101 8004040224* 8004240537* 8004240342*	50-327	COUNBIL.W C. COUNBIL.W C COUNBIL.W C COUNBIL.W C	8006020203 8006240017 8006020203 8006050369 8006060306	50-213 P 50-213 Q 50-213 P 50-245 P 50-336 P
COLE.R F COLEMAN.A C COLEMAN.R COLEMAN.L R COLEMAN.R W	8006060377 8006060339 8006060060 8006030465 8006200086	50-376 0 50-272 0 CONTRACT PR CONTRACT	CDOX'1 # CDOX'1 # CDOX'1 # CDOX'N B CDOX'N D	8004040167 8004070308 8004070309* 8006230213 8006110073	50-157 P 50-329 K 50-329 K 50-329 G 50-329 H	COUNBIL. H O COUNBIL. H O COUNBIL. H O COUNBIL. H O	8006040367 8006060367 8006030474 8006070286 8006110163	50-213 F 50-213 F 50-336 P 50-245 P 50-245 P
COLEMAN,R W COLEMAN,R COLEY,J L COLEY,J L COLINB,P	8006130005 8006180343 8006120041# 8006190257# 8006250225#	CONTRACT CONTRACT 50-438 G 50-390 G CONTRACT	COOK, J # COOK, J # COOK, J # COOK, J. #	8006240585 8006180266 8006200361 8006200365* 8006160005	50-329 Q 50-329 B 50-329 A 50-329 A 50-329 B	CONNSIT'M O CONNSIT'M O CONNSIT'M O CONNSIT'M O	8006110237 8006110091 8006160045 8006110226 8006110307	50-213 P 50-245 P 50-245 P 50-245 P 50-336 P
COLLING, T COLLING, J COLLING, J COLLING, J COLLING, J T	8006110093 8006240055* 8006040113 8006060197 8006060349	50-250 P 50-267 Q 50-320 P 50-320 B 50-320 P	600K17 H 600K17 H 600K17 H 600K17 H	8006300439 8006300439 8006300277 8006300277	50-330 A 50-329 R 50-329 S 50-329 S 50-329 A	COUNBIL: W. C COUNBIL: W C COUNBIL: W C COUNBIL: W C	8004140047 8004130329 8004130314 8004110272 8004190457	50-336 P 50-213 P 50-213 P TOPREP 50-213 P
T U.BNIJLOD T U.BNIJLOD T U.BNIJLOD T U.BNIJLOD F M	8004040351* 8004110510 8004110517 8004070040 8004200003*	50-320 P 50-320 P 50-320 P 50-320 R CONTRACT	COOLEY, W J COOLEY, W J COONEY, M J COONEY, M J.	8006170292* 8006090054* 8006090046* 8006170445 8006250240	70-25 70-754 70-25 50-277 R 50-277 B	COUNBIL, W G COUNBIL, W, Q COUNBIL, W O COUNBIL, W O COUNBIL, W Q	8006200456 8006190457 8006200491 8006190602 8006190602	50-213 P 50-213 P 50-245 Q 50-336 P 50-336 P
COLLING, J T COLLING, J T COLLING, J T COLLING, J T	8004040204 8004130219 8004130224 8004020118 8004090349	50-320	COONEY, M J. COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q	8006250241* 8006180176 8006180200* 8006180205* 8006180176	50-277 8 50-466 9 50-466 9 50-466 9 50-466 9	COUMBIL, H 0 COUMBIL, H 0 COUMBIL, H 0 COUMBIL, H, 0 COUMBIL, H, 0	8006170408 8006240466 8006170408 8006300377 8006270198	50-336 P 50-334 P 50-336 P 50-245 P 50-213 P
COLLINS.S T COLLINS.J T COLLINS.J T COLLINS.J T	8006120027 8006250026 8006160165 8006250362 8006170670	50-320 R 50-289 8 50-320 R 50-289 8 50-320 R	COPELAND, J O COPELAND, R. L COPELAND, R. L COPELAND, D Q	8006180200* 8006180205* 8006070125 8006110301 8006180378*	50-466	COUNSIL, W. O COUNSIL, W O COUNSIL, W O COUNSIL, W O COWAN, F. E.	8006270293 8006300460 8006300383 8006300383 8006120070	50-245 P 50-245 P 50-213 P 50-213 P 50-448 0
COLLING. J T COLLING. P F. COLOMBO. R C COLOMBO. R W COLOMBO. R W	8006250335 8006270421 8006170641* 8006250238* 8006300405*	50-320 R 50-271 V 50-312 R 50-312 8 50-312 8	COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q	8006180346 8006180346 8006240457 8006240464 8006270327	50-466	COMAN, F. E. COMAN, F E COMAN, F. E COMAN, F E COMAN, F. E.	8006120278 8006060478 8006200129 8006060478 8006110267	50-498 0 50-498 0 50-498 0 50-498 0
COLOMBO:R W COLUMBO:R W COMELLA:P A COMPTON:R W CONGEL:F J	8004300533* 8004030387* 8004250311 8004300243* 8004300254	50-312 8 50-312 8 MISC 50-280 G NUREG	COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q COPELAND, J. Q	8006270327 8006300307 8006300317 8006300334 8006300307	50-466	COMAN, F. E COMAN, F. COMOILL, C J COZZUOL, J M	8006110340 8006180506 8006180506 8006060047* 8006260042	50-498 Q 50-498 Q 50-498 Q 50-277 Q RES
CONGEL,F.J CONKLIN,J.C CONLON,T.E CONLON,T.E CONLON,T.E	8006270003 8006270031 8006170228# 8006170768# 8006270214#	NUREQ NUREQ 50-327 G 50-546 G 50-430 Q	COPELAND, J. G COPELAND, J. Q. COPELAND, R. L. CORBETT, J. B CORBETT, J. S	8006300317 8006300334 8006270205 8005270516 8005130121	50-466	CRAIQOE, E. A CRAMOND, W R CRANE, P. A. CRANE, P. A. CRANE, P. A	8006180524* 8006040086 8006180297 8006020345 8006020168	50-327 8 NUREG 50-275 0 50-275 A 50-275 A
CONLON, T E CONLON, T, E CONLON, T E CONLON, T E CONLON, T E	8006070156* 8006130038* 8006170784* 8006230126* 8006070074*	50-491 Q 50-935 Q 50-921 Q 50-280 Q 50-280 Q	CORBETT, J. S CORBETT, J. S CORBIN, K. D CORBIN, K. D CORDANI, R. A	8006040076 8006190146 8006230056 8006230112 8006230125*	71-6275 71-6375 70-36 70-36 70-27	CRANE, P, A CRANE, P, A CRANE, P, A CRANE, P, A CRANE, P, A	8004030330 8004140040 8004140044* 8004140037 8004180424	50-275 A 50-275 A 50-275 A 50-275 F 50-275 H
CONLON, T E CONLON, T E CONLON, T E CONLON, T E CONNER, T B	8006170268* 8006230336* 8006230371* 8006260357* 8006060547	50-302 0 50-439 0 50-367 0 50-416 0 50-320 0	CORDANI, R A CORDERO, Z C	8006230121 8006230052 8006180416 8006180381 8006020024#	70-27 70-27 70-27 70-27 50-546 Q	CRANE, P. A GRANE, P. A. CRANSTON, A GRAPO, H. S. CRANFORD, H. L.	8006170488 8006240416 8006300347 8006020561 8006020529	50-275 A 50-275 A 50-275 H REB 71-6639
CONNER, T B CONNER, T B CONNER, T B, CONNER, T B CONNER, E, L	B004140154 B004140154 B004040547 B004040547 B004050217	50-358 0 50-358 0 50-320 0 50-320 0 50-317 P	CORDERO, Z. C CORDERO, Z. C CORE. M CORREA. M. A CORREA. M. A	8004190323* 8004300182* 8004110015* 8004110097 8004140109	50-546 Q 50-546 Q 50-285 S 50-272 J 50-18 J	CREED: J R CREWS: J. L. CREWS: J. L. CREWS: J. L. CREWS: J. L	8006110444* 8006130083* 8006060357 8006180305* 8006250057*	50-202 Q 50-344 Q 50-142 Q 50-206 Q 50-312 Q
CONNER, E L CONNELL, C CONNER, E L CONNER, T. B CONNER, T. B	8006110407 8006170561* 8006270011 8006170501 8006170501	50-336 P 50-286 R 50-317 P 50-358 G 50-358 G	CORREALM. A CORYELL, Q P CORYELL, Q. P COSTALC, F. COSTELLO, J R	8006300434 8006050467 8006050418 8006110103 8006200148#	50-70 J 70-1151 70-1113 50-320 R GA999	CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L.	8006130059 8006050405 8006060082 8006250080 8006250088	50-275 G 50-361 G 50-275 G 50-344 G 50-344 G
CONNER, E. L CONNER, E. L CONNER, E. L CONNOLLEY, J CONOVER, W. J	8006260001 8006300652 8006300337 8006110015* 8006200535	50-317 P 50-336 P 50-335 P 50-285 S NUREO	COSTELLO.J R COSTELLO.O J COSTLE.D.M COTE.L A.	8004240126# 8004170517# 8004130031# 8004130027# 8004030355	0A777 50-280 R COMMISSION COMMISSION 50-307 F	CREWS, J L CREWS, J L, CREWS, E, H, CREWS, E H CREWS, E H	8004250114 8004250181 8004050019 8004230455 8004030358	50-312 G 50-312 G 50-395 8 50-395 A
CONSTABLE, 0 L CONSTABLE, 0 L CONTE, R. J CONTE, R. J	8006030534* 8006170289* 8006200517* 8006060206 8006130219	50-278 Q 50-278 Q 50-382 Q 50-320 S 50-320 S	COTNER, M L COTTLE, W. T. COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G	8006170453 8006070521* 8006170361 8006070474* 8006200571	50-10 D 50-327 G REGOD 50-423 S 50-213 P	CREWS, E. H. CREWS, E. H CREWS, E. H CREWS, E. H CREWS, E. H	8006030477 8006040241 8006040304 8006050042 8006110254	50-395 A 50-395 8 50-395 8 50-395 6 50-395 6

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AÜTHOR	ACCESSION NVMBER	SUBJECT CATEODRY
CREWS, J L CREWS, E H CREWS, J L CREWS, J L	8004180295 8004040343 8004240274 8004250051 8004180401	50-204	CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	8006120418 8006190103 8006160188 8006160194* 8006200055	50-409 G 50-244 G 50-10 D 50-10 D 50-10 D	D'AMORE, M D'AMORE, M DAGBJARTSSON, S DAHLSTROM, C G DAHLSTROM, C G	8004180002* 8004200007* 8004200041 8004120532 8004120452	70-1151 70-1151 RES XPORTLIC 70-2542
CREWS,E H	8006230186	50-395 K	CRUTCHFIELD, D M	8006208080	50-10 D	DAIL,L C	8006090142	50-491 Q
CRISCIONE,J	8006020372*	50-336 B	CRUTCHFIELD, D M	8006230014	50-10 D	DAIL,L C	8006240228	50-488 Q
CRITZ,H Q	8006270027*	50-317 P	CRUTCHFIELD, D M	8006230070	50-10 D	DALE,L F	8006050266	50-416 S
CRNICH,J.	8006180371*	50-382 S	CRUTCHFIELD, D M	8006160213	50-204 F	DALE,L F	8006060267	50-416 S
CRNICH,J	8006170313	50-382 S	CRUTCHFIELD, D M	8006170047	50-255 P	DALE,L F	8006050316	50-416 S
CROAK,C	8006230086	FOIA	CRUTCHFIELD, D	8006170221	50-204 P	DALE, L. F	8006050357	50-416 B
CROCKER,H W	8006170750*	50-309 Q	CRUTCHFIELD, D	8006180354	50-409 P	DALE, L. F	8006110192	50-416 A
CROCKER,H W	8006270188*	70-135	CRUTCHFIELD, D	8006180557	50-245 P	DALE, L. F	8006160098	50-416 C
CROCKER,H W	8006120095*	50-54 Q	CRUTCHFIELD, D	8006190078	50-29 P	DALE, L. F	8006160128	50-416 K
CROCKER,H W	8006060472*	70-398	CRUTCHFIELD, D	8006190402	50-213 P	DALE, L. F	8006160462	50-416 A
CROCKER, H W	8006050661*	70-442	CRUTCHFIELD, D	8006190404	50-244 P	DALE,L F	8006180468*	50-416 A
CROCKER, H W	8006060041*	70-687	CRUTCHFIELD, D	8006200551	50-10 P	DALE,L F	8006300469	50-416 A
CROCKER, H W	8006180114*	70-371	CRUTCHFIELD, D	8006230263	50-219 P	DALLINGER,J F	8006120142	71-7039
CROCKER, H, W	8006190088*	70-820	CRUTCHFIELD, D M	8006250385	50-155 P	DALTROFF,S L	8006060039*	50-277 Q
CROCKER, H W	8006270029*	70-2260	CRUTCHFIELD, D	8006270235	50-155 P	DALTROFF,S L	8006030121	50-277 Q
CROCKER, H W.	8006050655	70-442	CRUTCHFIELD, D C	8006240604*	50-245 P	DALTROFF, S L	8006020001	50-277 Q
CROCKER, H H	8006060072	70-1992	CRUTCHFIELD, D	8006240542	50-244 F	DALTROFF, S L	8006130279	50-277 P
CROCKER, H W.	8006020054	I&E	CRUTCHFIELD, D	8006240578	50-255 F	DALTROFF, S L	8006130324	50-277 F
CROCKER, H.	8006050401	50-293 8	CRUTCHFIELD, D M	8006260029	50-155 P	DALTROFF, S L	8006200487	50-277 P
CROCKER, H W	8006200237	40-8576	CRUTCHFIELD, D	8006300564	50-409 D	DALTROFF, S L	8006260176	50-277 P
CROCKER: H N	8006270021	70-2260	CRUTGHFIELD, D	8006300230	50-206 P	DANCE, H C	8006130141*	50-10 Q
CROSBHAN; W. A.	8006110325*	50-362 A	CULP, R, H	8006180506	50-499 0	DANCE, H C	8006180338*	50-321 Q
CROSBHAN; W. A.	8006050528*	50-482 G	CULP, R, H	8006180506	50-499 0	DANCE, H C	8006030573*	50-370 Q
CROSBHAN; W. A.	8006030225*	50-458 G	CULP, R, H	8006300334	50-466 0	DANCE, H C	8006240273*	50-257 Q
CROSBHAN; W. A.	8006060131*	50-462 G	CULP, R, H	8006300334	50-466 0	DANCE, H. C.	8006240174*	50-257 Q
Crobbhan, H. A.	8006120231*	50-445	Culver, m w	8006190621*	50-302 R	DANCE, H. C	8006090521*	50-327 Q
Crobbhan, H. A.	8006070077*		Cunningham, o e	8006120480*	71-9044	DANCE, H. C	8006230237*	50-321 Q
Crobbhan, H. A.	8006170159*		Cunningham, m e	8006270022	NUREQ	DANCE, H. C	8006130381	50-321 8
Crobbhan, H. A.	8006070234*		Cunningham, o e	8005210456	71-5942	DANFORTH, J. C	8006120520	50-483 U
Crobbhan, H. A.	8006130074*		Cunningham, o e	8005290066	71-9044	DANIEL, J. L	8006270022	NUREQ
Crosbman, W. A. Crosbman, W. A. Crosb, J. L. Crosmell, T. Crosmell, R.	8006170226* 6006250221* 8006240254 8006300228 8006170355	50-445 @ 50-445 @ 50-327 @ 50-257 @ 50-358 @	Cunninoham, o e Cunninoham, a l Cunninoham, o, e Cunninoham, o, e Cunninoham, a l	8006030017 8006030585# 8006030034 8005270337 8006170775#	71-9050 50-424	DANIELBON, L J DANIELBON, D H DANIELBON, L. J DANIELBON, D H DANIELBON, D H	8006200587 8006130259* 8006040328 8006170219* 9006020016*	70-2709 30-373 G 40-4492 50-454 G 50-454 G
CROUBE, R. P. CROUBE, R. P CROUBE, R. P. CROUBE, R. P CROUBE, R. P	8004030322 8004030210 8004030327 8004030317 8004030372	50-346 Q 50-346 Q 50-346 Q 50-346 P 50-346 S	Cunninoham, Q E Cunninoham, A L Cunninoham, Q E Cunninoham, J Curran, J, M	8006120464 8006240052* 8006300336 8006240343 8006060307*	71-9044 50-395	DANIELBON, DH DANIELBON, DH DANIELBON, DH DANIELBON, DH DANIELBON, DH	8006020024* 8006170774* 8006020089* 8006020077* 8006170766*	50-546 G 50-373 G 50-265 G 50-249 G 50-331 G
CROUSE, R. P	8006030311	50-346 R	Curran, J. M	9004030438*	50-206 8	DANIELBON, D. H	8006190366*	50-373 G
CROUSE, R. P.	8006060303	50-346 F	Curran, J. M	9004030434*	50-206 8	DANIELBON, D. H	8006190475*	50-255 G
CROUSE, R. P.	8006230201	50-346 Q	Curran, J. M	8006030517*	50-206 8	DANIELB: F. T	8006230092*	50-358 G
CROUSE, R. P.	8006170456	50-346 P	Curran, J. M.	8006120290*	50-206 8	DANIELBON, D. H	8006230151*	50-461 G
CROUSE, R. P.	8006170463*	50-346 P	Curran, J. M.	8006130218*	50-206 8	DANIELBON, D. H	8006300073*	50-483 G
CROUSE, R. P	8004200379	50-346 Q	CURRAN, J M	800&1&0011	50-206 R	DANIELBON, D.H.	8006230091*	50-409 G
CROUSE, R. P.	8004240494	50-346 P	CURRAN, J M.	800&230323*	50-206 8	DANIELBON, D.H.	8006250310*	50-329 G
CROUSE, R. P	8004230460	50-346 P	CURTIB, N W	800&0&0044*	50-387 A	DANIELBON, D.H.	8006300182*	50-546 G
CROW, W. T	8004040129	70-27	CURTIB, N, W.	800&0&0055*	50-387 A	DARLEY, V. D	8006160169	NUREO
CROW, W. T.	8004020045	70-820	CURTIB, N, W	800&12010&*	50-387 8	DATTILO, T.M.	8005210208*	50-546 T
CROM, M. T. CROM, M. T. CROMLEY, B. R. CROMLEY, B. R. CRUMLEY, J. J	8004020557* 8004030057 8004090435* 8004300273* 8004230349	70-27 70-2909 50-321	CURTIE, N W. CURTIE, N W CURTIE, N W CURTIE, N W CURTIE, C. E	9006060369 9006060490 9006090311 8006110222 9006200569	50-387 A 50-387 D 50-387 8 50-387 A 50-574 0	DATTILO,T M DAVIDBON,D R DAVIDBON,D R DAVIDBON,D R DAVIB,C.E.	8006130187* 8006240378 8006270278 8006270295 8006300071	50~546 H 50~440 Q 50~440 C 50~440 I NUREG
CRUTCHFIELD, D	8006130016	50-255 P	CURTIB, C E	8006200569	50-574 0	DAVIS.E.P	8006170813	FGIA
CRUTCHFIELD, D,	8006040128	50-217 F	CURTIB, C E	8006200569	50-574 0	DAVIS.S M	9006060582	50-317 S
CRUTCHFIELD, D	8006040131	50-10 F	CURTIB, C E	8006200569	50-574 0	DAVIS.G D	8006060140*	Habte Mot
CRUTCHFIELD, D	8006130010	50-245 P	CURTIB, C E	8006200569	50-574 0	DAVIS.A S	8006020185	50-254 G
CRUTCHFIELD, D	8006060426	50-213 F	CURTIB, J. H.	8006170561*	50-327 8	DAVIS.O R	8006060136	Waste Mot
CRUTCHFIELD, D. CRUTCHFIELD, D. M CRUTCHFIELD, D. M CRUTCHFIELD, D. M CRUTCHFIELD, D. M CRUTCHFIELD, D.	8006040123 8006060557 8006060573* 8006060576* 8006250002	50-155 F 50-204 P 50-204 P 50-204 P 50-255 P	CURTIE, J. W. CURTIE, N. W. CURTIE, N. W. CURTIE, N. W. CURTIE, N. W.	8006170541* 8006200163 8006200171 8006200366 8006270321	50-327 8 50-387 8 50-387 8 50-387 8 50-387 8	DAVIS, J H DAVIS, A. B DAVIS, A. B DAVIS, A. B DAVIS, A. B	8006230230* 8006180070 8006170057 8006180574 8006160245	70-1319 50-243 @ 70-1308 50-266 @ 50-263 @
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8006250037 8006250141 8006250158 8006250157 8006250177	50-219 P 50-155 P 50-204 P 50-29 P 50-10 P	CURTIB, N. W. CUTCHIN, J M CUTCHIN, J M CUTCHIN, J M CUTHBERTBON, T	8006270342 8006040122 8006180311 8006270234 8006300027	50-387 8 50-289 0 50-387 0 50-289 0 71-6717	DAVIS.A B DAVIS.A.B DAVIS.A B DAVIS.W.W DAVIS.P L	8006020061 8006190378 8006250043 8006120217 8006030055*	ire 50-295 g 50-294 g Pr Contract
CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	6004250180 8004260047 8004120004 8004250039 8006030580	50-213 P 50-409 P 50-409 P 50-245 P 50-255 F	CYBULSKIS, P. CYPHERT, S. B. CYPHERT, S. B. CYPHERT, S. B. CYPHERT, S. B.	8006300183 8006120036 8006060492 8006180189 8006200142	RES 50-445 M 50-445 M 50-445 M 50-445 M	DAVIS.A B DAVIS.A B DAVIS.A B DAVIS.A.B DAVIS.A B	8004230014 8004040113 8004040192 8004300030 8004040453	50-10 q I&E 50-254 8 50-341 q I&E
CRUTCHFIELD, D. CRUTCHFIELD, D. M CRUTCHFIELD, D. CRUTCHFIELD, C. CRUTCHFIELD, C.	8006040016 8006090383 8006250154 8006230117* 8006200627	50-155 F 50-255 P 50-244 P COMMISSION 50-10 F	CYPHERT, S. B.	8004140143 8004170007* 8006170004 8006110357 8006230254	50-445 M 50-445 M 50-445 M 50-445 M 50-445 N	DAVIS, A B DAVIS, A, B DAVIS, P L DAVIS, R, S DAVIS, B M	8004020062 8004070509 8004230040* 8004030363 8004050035*	50-331 0 50-274 G CONTRACT 50-387 D 50-317 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	GUÐJECT GATEGORY
DAVIS, R E DAVIS, A B DAVIS, S M DAVIS, A B DAVIS, S M	8006040117* 8006250605 8006070348* 8006170389 8006180480*	50-320 P 70-2619 50-317 8 50-116 Q 50-318 8	DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W	8006090086# 8006050516# 8006190075# 8006200257# 8006240188#	50-201 G 70-1143 50-184 G 70-33 70-820	DISE, D P DISE, D P, DOBBE, C A DODA, R J DODDS, R, T	8004270289 8004300378 8004300455 8004300478 8004300678	\$0-220 P \$0-220 P RES State Prog \$0-312 Q
DAVIS.S M DAVIS.S M DAHSON.D M DAHSON.D M DAHSON.D M	8006180490* 8006180518* 8006160220 8006060067 8006110298*	50-318	DEVLIN, J W DEVLIN, J W DEVLIN, J DEWITT, R B	8006270245* 8006300602* 8006300610* 8006050474 8006130124*	50-317 Q 50-54 Q 50-225 Q 50-247 S 50-255 Q	DODDS, R. T DODDS, R. T, DODDS, R. T DODDS, R. T DODDS, R. T	8006050141* 8006250192* 8006250172* 8006250179* 8006300591*	50-440 Q 50-528 Q 50-397 Q 50-312 Q 50-397 A
DE LISSOVOY, J DEALE, V B DEAN, S R DEAN, S	8006180174 8006180429 8006180411 8006030534* 8006240182*	70-2909 50-338	DIAMOND, M J DIAZ, N J DIAZ, N J DICKERSON, H W DICKERSON, M W	8006170345 8006070485* 8006020365 8006250345 8006240055*	PR 50-83 Q 50-83 S RES 50-267 Q	DODBON, D DOEPKEN, H C DOGGETT, S A DOGGETT, S A DOHERTY, J F	8006120149 8006170145 8006060380 8006170569 8006090084	71-9073 50-289 H 50-466 Q 50-466 Q 50-304 P
DEAN, N J DECHER, U DELANEY, H M DELIGSOVOY, O DELONO, B D	8006030506* 8006060317* 8006260009 8006180371 8006300508*	50-295 B 50-335 P 50-295 P 70-2909 50-315 B	DICKBON, H W DICKBON, H W DICKBON, H W DICKBON, H W	8006300298 8006270078 8006300500 8006110011 8006060395	RES RES RES 50-341 P 50-341 A	DOHERTY, J F DOLAN, J E. DOLAN, J. E DOLAN, J. E DOLAN, J. E	8006190101 8006180600* 8005210255 8006030300 8006190386*	50-466 0 50-315 0 50-315 J 50-315 P 50-315 0
DEMARIA.E DEMARIA.E DEMENT.J DEMPSEY.P DENIBE.R.P	8006230260* 8006230257 8006020614* 8006130162* 8006200626	71-384 71-384 MISC 50-322 Q 50-267 E	DIETCH, R Digob, R M Digob, R M Digob, T G Digob, T, G,	8006250214 8006090425 8006300554 8006060447 8006060447	50-361 A 50-289 P 50-302 P 50-309 0 50-309 0	DDLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J. E	8006050037 8006230407 8006230487 8006260177 8006240491	50-315 P 50-315 P 50-315 P 50-315 P 50-315 P
DENNISON, A B DENNISON, A B DENNINO, R B DENNINO, R B DENNY, I L	8006130021 8006060371 8006300183 8006300189 8006170121	50-358	DIONAN, T. G DIOMAN, T. G DIONAN, T. G DIONAN, T. G DIONAN, T. G	8006180274 8006180326 8006180274 8006180326 8006230261	50-309 0 50-309 0 50-309 0 50-309 0 50-443 0	DOLE, R DOLSON, T C DONAT, T J DONAT, T. J. DONAT, T. J.	8004120520 8004030142* 8004070545* 8004070088* 8004200525*	50-483 U QA997 50-369 Q 50-338 Q 50-302 Q
DENTON, H R DENTON, H R DENTON, H R DENTON, H R, DENTON, H R	7911190148 8006190033 8006120439 8006020027 8006020157	50-3 P 50-320 J 50-320 H 50-3 H 50-320 H	DITANNI.D.C DINEAUZE.D F DINGMAN.B E DIPIAZZA.R P DIPIAZZA.R P	8006110503 8006120104 8006180097 8006200576 8006200591	50-320 F PR REB 70-1143 70-2909	DONAT, T. J. DOPSOVIC, D A DOPSOVIC, D A DOPSOVIC, D A, DOPSOVIC, D. A,	8006180246* 8006120056 8006060492 8006180189 8006160163	50-369 Q 50-445 H 50-445 H 50-445 H
DENTON, H R	8004020162 8006020181 8006300575 8006180138* 8006070104*	50-320 H 50-320 H 8ECY 50-247 T 50-561 A	DIPIAZZA,R P DIPIAZZA,R P DIPIAZZA,R P, DIPIAZZA,R P, DIPIAZZA,R P,	8004200101 8005120001 8004200120 8004300292 8004300592	70-498 71-5450 70-1143 70-1181 70-1143	DOPEDVIC, D A DOUGHERTY, D J, DOUGHERTY, D, J, DOUGHERTY, D, J, DOUGHERTY, D, J, DOUGHERTY, D, J	8006170007* 8006250034* 8006160234* 8006230083* 8006250070*	SO-445 K CONTRACT SO-389 A CONTRACT CONTRACT
DENTON, H R	800&1&0235* 800&020232 800&0&0078 800&300264 800&030552	ORO 50-320 P 50-327 P 50-320 H 50-344 9	DIPIAZZA,R P DIPIAZZA,R P DIPIAZZA,R P, DIPIAZZA,R P, DIPIAZZA,R P	8006160217 8006040150 8006190139 8006230304 8006230308*	70-698 PR 70-1143 70-1143 70-1143	DOUGHERTY, J, L. DOUGHERTY, D. J.	8006180194* 8006250330 8006270014* 8006190662 8006060495*	50-289 G CENTRACT FOIA CONTRACT CONTRACT
DENTON, H R DENTON, H R DENTON, H R DENTON, H, R DENTON, H R	8006240614 8006070057 8006040026 8006160127 8006170235	SO-224 Q OEN TEC IS SO-409 Q OEN TEC IS TOPREP	DIPIAZZA,R P DIPIAZZA,R P DIRCKB,W J DIRCKB,W J. DIRCKB,W J.	8004230050 8004300017 8004080351 8004180131* 8003100181*	70-1151 70-1151 BECY BECY 10CFR	DOUGHERTY, D. J DOUGHERTY, D. J DOUGHERTY, D. J DOUGHERTY, D. J DOUGHERTY, D. J.	8006130250* 8006190104* 8006230046* 8006250059* 8006230040*	CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H, R DENTON, H R DENTON, H R DENTON, H R, DENTON, H R	8006020126 8006060224 8006120156 8006120164 8006120170	50-320 H 50-320 H NUREQ NUREQ NUREQ NUREO	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8006170255 8006300572* 8006170178 8006020567 8006300617*	40-2041 FOIA 50-320 H 40-8502 COMMISSION	DOUGHERTY, D. J.	8006230038* 8006230041* 8006230200* 8006300343* 8006300555*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R DENTON, H R. DENTON, H R DENTON, H R DENTON, H R	8006120171 8006020249 8006020547 8006230176 8006090106	NUREG HISC 30-206 P 50-272 9 50-320 P	DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8006130077* 8006180210 8006250204* 8006120120 8006120126	PR 70-2423 10CFR MISC 50-358 H	DGUQLAB.M.H DRAQONETTE.K.S DRAKE.J.H DRAPER.E.L DRAPER.E.L.	8004300450 8004190338 8006110009 8006110268 8006230100	50-320 H 27-47 50-206 P 50-458 S 50-458 Q
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R,	800&120250 800&120476 800&240035 800&240043* 800&170802	50-320 P 50-10 P 50-416 M 50-416 M 50-171 K	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8006120074 8006300489 8006200574 8006130229 8006280317	50-311 U PR COMMISSION 50-309 H PR	DRISKILL,D D DROMERICK,A W. DROMERICK,A W DROMERICK,A W DROMERICK,A W	8006130178* 8006030087 8006070063 8006120081 8006200302	50-482 Q 50-339 P 50-339 F 50-339 P
DENTON, H R DENTON, H R DENTON, H R DENTON, R, E H R,	8006200601 8006240034 8006200540 8006090368* 8006270163	50-320 P 50-320 P 50-275 H 50-317 B PR	DIRCKS'M J DIRCKS'M J DIRCKS'M' J DIRCKS'M J	8006120082 8006120141 8006200051 8006170281 8006120089	50-254 H 50-546 H Btate Prog 50-341 H 50-272 H	DROMERICK, A, W DROMERICK, A, W DROMERICK, A W, DROMERICK, A W, DROMERICK, A, W	8006200602 8006130125 8006130135 8006230138 8006250308	50~339 P 50~339 P 50~339 P 50~311 P
R R ያኔ R	8006240168 8006300240 8006260141 8006260146*	50-320 H 50-443 H 50-304 0 50-304 G 50-275 G	DIRCKS, W J DIRCKS, W J, DIRCKS, W J, DIRCKS, W J	8006270126 8006270134 8006270141 8006270147 8006270152	50-341 H 50-171 H 50-171 U 50-171 U 50-171 H	DROMERICK, A W DROMERICK, A W DRUCKENMILLER DRUCKENMILLER, H DRYER, J. R	8006250361 8006300303 8006160074 8006260173 8006030224*	50-337 F 50-337 P 50-407 D 50-409 D
		50-275	Dircks, W. J Dircks, W. J Dircks, W. J. Dircks, W. J.	8006370115 8006270115 8006270171 8006270171	50-320 H 50-320 H 50-155 H 50-313 H 50-155 H	DUBOST, E L DUBOST, E L DUBOST, E DUBOST, E DUBRY, N E	8006070346# 8006070380# 8006170665# 8006270274# 8006130178#	50-331 8 1 50-331 8 5 50-331 8 5 50-315 0 1
		50-217 H 70J)+443 G -407 J 720 G	DIRCKS, W J. DIRCKS, W J. DIRCKS, W J DISE, D. P. DISE, D. P.	8006270088 8006270102 8006300569 8006190475 8006300305	50-302 H 50-289 H F01A 50-220 F 50-220 P	DUCKHORTH, J. P DUCKHORTH, J. P DUCKHORTH, J. P DUCKHORTH, J. P. DUNBAR, J	80062301573 8006230141 8006230244 8006190197* 8006030349*	50-201 R 50-201 R 50-201 R 50-201 Q 50-237 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DUNGEY, C E DUNGEAN, L E DUNN, C N DUNN, C N	8006300032 8006190413 8006030262* 8006090137 8006040098	40-645 50-320 H 50-334 Q 50-334 Q NUREO	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8006250133 8006250137 8006250163 8006300009 8006300012	50-466 A 50-373 A 50-387 A 50-387 A 50-367 A 50-410 A	FARNELL, A S	8006120045 8006120045 8006050044 8006050044 8006110282*	50-327 0 50-329 0 50-329 0 50-329 0 50-445 M
DUNN, C N	8006060390	50-334 R	EIBENHUT, D O	8006300013	50-397 A	FABAND, A	8006060197	50-320 S
	8006110191	50-334 Q	EIBENHUT, D, O	8006300049	50-322 A	FABAND, A	8006060206	50-320 S
	8006110061	50-334 Q	EIBENHUT, D O	8006260057	50-354 A	FABAND, A	8006230362	50-287 B
	8006110275	50-334 Q	EIBENHUT, D O	8006260064	50-461 A	FAUBLE, T	8006180097	RES
	8006300552	50-334 Q	EIBENHUT, D O	8006260070	50-416 A	FAULKENBERRY, B	8006180314*	50-204 Q
DUNN, C. N DUNN, C. N DUNN, C. N DUNN, C. N DUNN, C. N	8006110360 8006170532 8006160014 8006200310 8006240429	50-334 Q 50-334 P 50-334 R 50-334 P 50-334 Q	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8006240232 8006240616 8006240620 8006260026 8006300086	50-528 A 50-458 A 50-553 A 50-344 G 50-337 P	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAVRETTO, R J	8004250046* 8004050411* 8004250124* 8004250184* 8004030390	50-312 0 50-361 0 50-312 0 50-312 0 50-416 M
DUNN, C. N DUNN, D. R DUNSTON, P. DURALL, J. R DURENBERGER, D	8006240291 8006260053 8006060284 8006230438 8006300392	50-334 F NUREO 50-498 H 50-259 P 50-329 H	EISENHUT, D O EL-ABHRY, M T EL-ABHRY, M T EL-ABHRY, M T EL-OENK, M B	8006260055 8006110315 8006160069 8006170599 8006180038	50-289 P 50-438 A 50-327 S 50-327 S RES	FAVRETTO,R J FAY,C W FAY,C W FAY,C W FAY,C W	8006170240* 8006040060 8006030344 8006170650 8006110149	50-416 M 50-266 P 50-266 P 50-266 G
DURHAM, J W DUTTON, D DUTTON, D DUTTON, D. EADIE, Q Q	8005280231 8006190135 8006240277 8006270337 8006030088	PR 50-424	ELD,M E ELIN,J O ELKIN,B L ELLERBHAN,L,E ELLERBHAN,L E	8006120281 8006250179* 8006130342 8006190382* 8006250127*	PRM 50-312 G State Prog GA999 GA999	FAY, C W Fay, C W Fay, C W Fay, C W, Fay, C W	8006110161* 8006110279 8006110129 8006110271 8006170477*	50-246 8 50-266 P 50-266 P 50-266 V 50-266 R
EAGLETON,T F	8006120520	50-483 U	ELLIOTT.C P	8006170137	50-206 H	FAY, C W	8006300262	50-266 Q
EAGLE,J	8006230372#	50-254 S	ELLIB.J	8006060255	50-445 0	FAY, C, W	8006160092	50-301 Q
EARLY,P J	8006030384	50-266 P	ELLIB.J	8006060257*	50-445 0	FAY, C W	8006170473	50-266 R
EARLY,P J	8006030315	50-266 P	ELLIB.J	8006060261*	50-445 0	FAY, C W	8006200460	50-266 P
EARLY,P J	8006060373	50-266 P	ELLIB.J	8006060346	50-445 0	FAY, C W	8006300452	50-266 F
EARLY, P. J.	8004040280	50-247 F	ELLISON, C.	8006160049	50-312 0	FEE.W F	8004110081	50-245 P
EARLY, P. J.	8004110083	50-286 G	ELLBHORTH, H L	8006060473*	50-70 P	FEIERABEND.C D	8004170321*	50-202 G
EARLY, P. J.	8004170451	50-247 P	ELROD, S	8006130376	50-251 B	FEINSTEIN.H W	8004180172*	FOIA
EARLY, P. J.	8004170454+	50-247 P	ELROD, S	8006250028	50-250 B	FEINSTEIN.H W	8004180152*	FOIA
EARLY, P. J.	8004140137	50-333 P	ELROD, S,	8006160077*	50-389 6	FEINSTEIN.H W	8004180135*	FOIA
EARLY, P J EARLY, P. J EASTER, J. H EASTER, K W,	8006160108 8006160003 8006300664 8006270016* 8006200524	50-247 P 50-284 Q 27-39 50-317 P NUREQ	ELTIB,M. EMBWILER,T R ENGEL,R.E ENGELKEN,R H ENGELKEN,R H	B006200149 B006040069 B006020243* B006130082* B006200116	70-33 71-6400 50-325 P 50-255 Q 50-133 Q	FEINSTEIN.H W FEINSTEIN.H W FEINSTEIN.H W FELD.8,E. FELTON.J M	8006180129* 8006180119* 8006180115* 8006090235* 8006190114	FDIA FDIA FDIA 50-409 Q FDIA
EASTMAN.C R	8006170183*	50-443 H	ENGELMANN, R. ENGEL, R E ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8006170051	40-8348	FELTON, J M	8006190116	FOIA
EBNETER.S	8006240584*	50-387 G		8006260084*	TOPREF	FELTON, J, M	8006130098*	PRM
EBNETER.S D	8006250186*	50-287 G		8006200047	50-344 G	FELTON, R W.	8006050529*	CONTRACT
EBNETER.S.	8006250182*	50-289 G		8006200052	50-133 G	FELTON, J M	8006130076	50-10 G
ECKERBON.M	8006130021	50-358 O		8006200053	50-312 G	FELTON, J M	8006180016	FOIA
ECKERT, J P,	8006300524*	70-27	ENGELKEN, R H. ENGELHEN, R H ENGELHARDT, T F ENRIETTO, J EPLER, E, P	8004200054	50-204 Q	FELTON, J M	8006020111	FOIA
ECKERT, R M.	8006120210*	50-311 P		8004300587	50-397 A	FELTON, J M	8006130207	FOIA
ECKHOUT, A	8006120448	XPORTLIC		8004260189	70-1727	FELTON, J, M	8006060441	FOIA
ECONOMOS, N	8006030085*	50-302 G		8004070396*	50-280 Q	FELTON, J, M	8006170811	FOIA
ECONOMOS, N	8006200114*	50-330 G		8004120293	ACRB	FELTON, J, M	8006120165	FOIA
EDELBTEIN, B	8006190025*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC CONTRACT	ERBIC M	8006170366*	50-373 0	FELTON, J M	8006120169	FOIA
EDELBTEIN, B	8006190021		ERDMAN,C A	8006300102	NUREO	FELTON, J M	8006120176	FOIA
EDELBTEIN, B	8006300327		ERICKBON,L	8006060415*	50-344 8	FELTON, J, M	8006120184	40-1341
EDELBTEIN, B.	8006300331		ERICKBON,P B,	8006250353	50-30 W	FELTON, J, M	8006170269	70-25
EDGEWORTH, P. J	8006190100		ERICBON,D M	8006300218	RES	FELTON, J M	8006200060	FOIA
EDOEHORTH, P. J.	8006230044	CONTRACT	ERICBON, D. M	8006300204	reb	FELTON, J M	8006120516	FOIA
EDOEHORTH, P. J.	8006230035	CONTRACT	ERICBON, D M	8006300211	reb	FELTON, J M	8006120521	FOIA
EECKHOUT, A.	8006070366	XPORTLIC	ERTEL, A E	8006300571*	50-320 H	FELTON, J M	8006120401	FOIA
EECKHOUT, A.	8006120155	XPORTLIC	ERTEL, A. E.	8006300481*	50-320 H	FELTON, J, M	8006120409	FOIA
EECKHOUT, A.	8006120489	XPORTLIC	ERTEL, A E	8006300518*	50-320 H	FELTON, J M	8006170791	50-302 P
EMREBNPERGER, W	9006180379	50-424 A	ERTEL, A. E	8006120114*	50-320 U	FELTON, R W. FELTON, J H FELTON, J H FELTON, J M FELTON, J M,	8006250042*	CONTRACT
EIBER, R J.	8006270097	NUREO	ERTEL, A E	8006120117*	50-320 U		B006190237	FOIA
EICH, E	8006190630*	50-247 R	ERTEL, A E	8006130173*	50-320 U		B006190072	FOIA
EIBENHUT, D	8006300027	NUREO	ERTEL, A E	8006130176*	50-320 U		B006190096	50-466 O
EIBENHUT, D G	7911200331	50-3 P	E8910. T H	8006020192*	50-254 Q		B006190115	FOIA
EIBENHUT,D Q EIBENHUT,D Q EIBENHUT,D Q EIBENHUT,D Q, EIBENHUT,D Q	8005130109 800002008 *0&1021&008 *1700E1&008	50-320 P 50-312 P NUREO NUREO 50-320 F	E8810.T.H E8810.T H E8810.T H. E8810.T H E8810.T H	8006160215# 8006190379# 8006200199# 8006250047# 8006300033#	50-184 Q 50-295 Q 50-315 Q 50-294 Q 50-341 Q	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8004230047 8004230057 8004230069 8004230097 8004300473	FOIA FOIA FOIA 40-1341 50-320 H
EISENHUT,D 0	8004090165	50-320 P	EBBIQ, T. H	9006190398*	50-116	FELTON, J M	8006230073	FOIA
EISENHUT,D,0	8004090487	50-320 F	EBTEY, H P	8006200081		FELTON, J M	8006230081	FOIA
EISENHUT,D 0	8004130122	50-320 P	EVANB, J. C.	9006290352		FELTON, J M	8006230106	FOIA
EISENHUT,D 0	8004230013	GEN TEC IS	EVANB, V R.	8006060317		FELTON, J, M	8006300535	FOIA
EISENHUT,D 0	8004230110	50-275 A	EWALD, B C	8006190692*		FELTON, J M	8006300553	FOIA
EIBENHUT, D. O EIBENHUT, D. O EIBENHUT, D. O, EIBENHUT, D. O EIBENHUT, D. O	8006130063 8006060449 8006090032 8006090372 8006230029	50-320 F 50-70 P 50-313 P 50-259 P 50-247 P	EWALD:8 C. EWERB:B J. EYED:J.A. EYED:J.A FAHRNER:W J.	8006200516* 8006200548 8005210187* 8005210202* 8006270282	50-280 Q PR 50-546 T 50-341 8	FELTON, J K FELTON, J K FELTON, J K FELTON, J M	8004300588 8004240444 8004300022 8004240450 8004270010	FOIA FOIA FOIA FOIA FOIA
EISENHUT, D Q EISENHUT, D, Q, EISENHUT, D Q EISENHUT, D, Q EISENHUT, D Q,	8006240063 8006240067 8006250005 8006190310 8006300604	50-317 P 50-295 P 50-245 P 50-247 G 50-10 P	FAHRNER:W J. FAHRNER:W.J FALIBE:M J FALIBE:M.J. FALK:K M	8006270230 8006270330 8006090362* 8006090376* 8006030289	50-341 8 50-341 8 50-220 8 50-220 8 50-226 0	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8006270413 8006270414 8006270416 8006300220 8006300582	50-302 H • FOIA FOIA 50-320 H FOIA

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	
FELTON, J M	8006300601 8006300607 8006300665 8006300672 8006300662	FOIA FOIA FOIA FOIA 50-275 H	FIGRELLI.G FIGRELLI.G FIGRELLI.G FIGRELLI.G FIGRELLI.G	8004250200 8004250243 8004250340 8004250363 8004250364	50-327 8 50-373 0 50-327 8 50-341 8 50-358 8	GAD.R K GAD.R K GAGE.L GAGE.L	8006180326 8006180274 8006180326 8006240584* 8006230186*	50-309 0 50-309 0 50-309 0 50-387 0 50-287 0	
FELTIDE FERGUSON, J H FERGUSON, J H FERGUSON, J H	8005230420 8005130297 8006050223 8005170519 8005190463	50-128 S 50-280 P 50-338 P 50-339 E 50-339 P	FIGRELLI, G FIGRELLI, G FIGRELLI, G FIGRELLI, G FIGRELLI, G	8004250348 8004250370 8004250372 8004240325 8004260352	50-341 9 50-341 9 50-461 9 50-329 9 50-546 9	GAGE:L Gahm.J W Gahm.J W Gajic,Z Gallagher.e J	8006250182* 8006160036* 8006160118* 8006110115* 8006020084*	50-289 Q 50-267 R 50-267 S 50-304 S 50-330 Q	
FERNOS.O FERRONE,O FIDELL.E R FIDELL.E R FIDELL.E R	9004190132 8004190525* 8004230094 8004120412 8004300224	50-376	FIORELLI.G. FIORELLI.G FIORELLI.G FIORELLI.G FIORELLI.G	8006260288 8006260305 8006270082 8006300613 8006300563	50-358 Q 50-454 Q 50-341 Q 50-461 Q 50-358 S	GALLAGHER, J W GALLO,R W GALLO,J GALLO,J GALLO,J	8004060557 8004090297* 8004140139 8004140139 8004240128	50-277 Q 50-387 Q 50-155 Q 50-155 Q 50-155 Q	
FIDELL, E R FIELDER, J FIELDER, J FIELDER, J FINDLEY, D E	8006120174 8006030421 8006160019 8006160113 8006190104*	FOIA 50-335 J 50-302 J 50-335 J CONTRACT	FISCHER, M L FISHER, W L FISHER, W L FISHER, W L FISHER, W L	8006020566* 8006070513* 8006180075* 8006180581* 8006170064*	50-206 P 50-73 G 50-263 G 50-266 G 70-1308	GALLO, J OALYARDT, D L GALYARDT, D L GAMBLE, O C OANOHER, T E	8006240128 8006200608 8006270035 8006110032 8006040119*	50-155 0 NUREO NUREO 71-4717 50-320 P	
FINDLEY, D E FINEMAN, C P FINFROCK, I R FINFROCK, I R FINFROCK, I R	8006270391* 8006180306 8006030009 8006030012* 8006090249	CONTRACT RES 50-217 P 50-217 P 50-217 F	F18HER, W L F18HER, W L F18HER, W T F18EE, L F F1TZGERALD, W J	8006230024* 8006160257* 8006060192 8006130021 8006300410	50-10 G 50-243 G 50-254 B 50-358 G 50-10 D	GARCIA.P J GARCIA.P J GARDNER.R S GARLAND.R GARLAND.B	8004030021 8004250075 8004120454 8004050535 8004300440	40-1162 40-1162 PR 40-8502 40-1162	
FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8006160018 8006160030 8006160080 8006170496 8006180423	50-219 8 50-219 8 50-219 8 50-219 P 50-219 P	FITZSIMMONS, T FITZBIMMONS, T FLANDERS, W FLEISCHAKER, D FLEISCHAKER, D	8006020415 8006300483 8006030369* 8006040199 8006060031	71-6400 71-6697 50-309 R 50-275 G 50-275 G	GARNER.D J GARNER.D J GARRETT.E G GARRITY.J H GARRITY.J H	8006190280 8006300448 8006030427 8006020221 8006030368	50-346 P 50-346 F PR 50-309 R 50-309 R	
FINFROCK, I R FINFROCK, I R FINFROCK, I R FINICLE, D P FINLEY, A O	8006190453 8006300356 8006300472 8006020503 8006030410*	50-219 8 50-219 F 50-219 8 RES 70-27	FLEISCHAKER, D FLETCHER, C D FLEWHR, J FLOYD, W FLYNN, J D	8006180519 8006260009 8006300475* 8006200597 8006250340	50-275 0 50-295 P 50-285 8 NUREO 70-2838	GARY, O R GARY, R J. GARY, R J GARY, R J GARY, R. J	8006180263* 8006090140 8006060570 8006230156 8006050113*	FOIA 50-445 0 50-445 B 50-445 B 50-445 Q	
FINLEY, A Q FINSTON, R A FIORELLI, O FIORELLI, O	8004230043* 8004110122 8004040333* 8004020073* 8004050504	50-266	FLYNN, J D FLYNN, M FLYNN, M J FLYNN, M J	8004040138 8004030052 8004180081 8004250222 8004250273	PR CONTRACT CONTRACT CONTRACT CONTRACT	QARY,R,J QARY,R J. Gary,R J Qary,R J Qary,R J	8006090584* 8006190063 8006180118 8006120245* 8006190740	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	
FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	800&200109 800&090032 800&200118 800&020020 800&020013	50-359	FOLEY, T FOLEY, T FOLEY, T FOLK, J, FOLLEY, T.	8006180057* 8006030110* 8006250164* 8006170150 8006190308*	50-29 Q 50-27 Q 50-29 Q 50-287 H 50-271 Q	GARY, R. J GARY, R. J GARY, R. J GABCHLER, J. A. GASSER, R. D.	8006230115 8006190458 8006240242 8006240335 8006250201	50-445 Q 50-445 A 50-445 B 50-267 B RES	
FICRELLI, O FICRELLI, O FICRELLI, O FICRELLI, O	8006020059 8006020070 8006020080 8006020082 8006130255	50-544 Q 50-249 Q 50-330 Q 50-265 Q 50-373 Q	FONO, F T FOOTE, V B FORBES, R L FORD, W H FORD, W H	8006170249* 8006230107 8006230448* 8006120150* 8005210113	50-277 Q F01A 50-255 6 50-546 H 50-546 H	GAULT, O W GAVUTIB, B GAY, G M GAY, G M GAY, G M	8006060403* 8006170183* 8006070005 8006070007 8006070005	50~327 B 50~443 H 50~445 Q 50~445 Q	
FIGRELLI.0 FIGRELLI.0 FIGRELLI.0. FIGRELLI.0 FIGRELLI.0	8006170196 8006170755 8006170756 8006180410 8006190319	50~483	FORD, C K FORD, E J FORNEY, W L FORNER, W L FORSTER, J	8006120177 8006200128# 8006170749# 8006170088# 8006300603	PR 50-337	GAY, G M Geckler, R P Gehr, A C Gehr, A C Gendler, M W	8006090007 8006170417* 8006110417 8006110417 8006190447	50-445 Q 50-409 Q 50-275 Q 50-275 Q 50-522 Q	
FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.G FIORELLI.O	8006170187 8006170195* 8006170761 8006170771 8006190177	50-483 Q 50-483 Q 50-331 Q 50-456 Q 50-373 Q	FOSTER, WE FOSTER, WE FOSTER, ER. FOSTER, JM FOSTER, JM	8006240080* 8006120483* 8006110256* 8006230037 8006230174	GA999 GA999 SO-336 B CONTRACT CONTRACT	GENDLER, M W OENNARO, D V. OENTIEU, L. P. GENTIEU, L., P. GEOROIOU, B, S	8006190447 8006170360* 8006040213 8006170711 8006120332	50-522 Q TOPREP 50-289 Q 50-320 1 50-275 Q	
FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O FIORELLI.O	8004170357 8004170473 8004230145 8004040223 8004230055	50-373	FOUKE.R.L FOX.D F FOX.D F FOX.R A FRALEY.R F	8006090001 8006060240* 8006160138* 8006090446 8006090118*	50-445	GERBIG.R H GERETY, H F GERETY, H F GERETY, H. F GERBTNER, W. C	8006120195 8006030411 8006240498 8006300441 8006250375*	71-6144 50-320 J 50-219 J 50-219 50-461 Q	•
FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0	8006230049 8006230085 8006300067 8006240032 8006250306	50-461	FRANCIB, E FRANCIB, E FRANCIB, E FRANCO, F FRANCO, F	8006040257 8006060135 8006040096 8006040071 8006110030*	40-1162 40-8745 40-1162 71-9113 50-285 \$	GERSTNER, W C GIBBONS, T D GIBBONS, T D GIBBS, D C GIBBS, D C.	8006300616* 8006230336* 8006260357* 8006120013 8006030286	50-461 Q 50-439 G 50-416 Q PR NUREO	•
FIGRELLI.G FIGRELLI.G. FIGRELLI.G FIGRELLI.G FIGRELLI.G	80063001564 8006090044 8006250166 80063001524 8006300175	50-456 Q 50-546 Q	FREEDMAN, B FROST, M FRYE, M E FUKUDA, B K FUQUAY, J J	8006230131* 8006130387* 8006180535* 8006180038 8006200288	COMMISSION	OIBSON, A F OIBSON, A F OIBSON, A F OIBSON, O OIBSON, O T	8006190692* 8006230230* 8006200516* 8006040356 8006050126	50-302 G 70-1317 50-280 G 50-302 S 1&E	•
FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8004030001 8004020544 8004170286 8004180547 8004170276	50-483	FUGUAY, J FURBUSH: M H, FURR: B J FURR: B J FURR: B, J	8006270004 8006110417 8006180228 8006060336 8006190638	71-6387 50-275 0 50-324 0 50-325 0 50-325 Q	OIESEKE, J. A OILBERTS, D. E. OILBERT, L. D. OILBERTS, D. E. OILBERTS, D. E.	8006260048 8006030203 8006250221* 8006230253 8006240558	NUREO 50-282 0 50-445 Q 50-282 0 50-282 0	3
FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8006200527 8006230063 8006230312 8006240084 8006240092	50-327 G 50-483 G 50-454 G 50-358 S 50-440 S	FURR, B J. FURR, B J GAD, R K GAD, R K GAD, R K	8006190672 8006250301 8006060447 8006040447 8006180274	50-261	QILBERT,C OILLINGKY,V QILLAM QILLESPIE,F P. OILLESPIE,F P.	8006230365 8006260075 8005210130 8006200015* 8006200338*	50-327 Q 50-443 T 50-544 H 70-1151 70-143	Ŧ

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GILLESPIE, F P	8006250264*	50-321 Q	GOUGE, M. J.	8006180051*	50-416 Q	GROCE:R H	8006030178	50-307 Q
GILLEN, K T	8006230011	NUREG	Graham, M. J.	8006090565*	50-369 Q	GROCE:R H	8006090271	50-307 P
GILLESPIE, F P	8006020067	70-1113	Graham, M. J.	8006050406	50-302 G	GROCE:R H	8006090280	50-307 P
GILLESPIE, F	8006050477	50-250 S	Graham, M. J.	8006040346	50-302 G	GROCE:R H	8006200424	50-307 P
GILLEN, D M	8006030015	40-2259	Grant, J.	8006180178*	50-271 H	GROCE:R H	8006230386	50-307 F
GILLEN,D M	8004030038	40-2259	GRANT, W B	8006020192*	50-254 0	GRODME, K	8006040004*	GA799
GILLEN,D M	8004140212	40-4492	GRAVES, R H	8006120270	50-213 8	GROSSMAN, H	8006140202	50-367 9
GILLESPIE,F P	8004140242*	70-143	GRAVES, R H	8006240297	50-213 8	GROSSMAN, H	8006140104	50-244 9
GILLETT,W T	8004170550*	50-315 R	GRAVES, R H	8006030510	50-213 8	GROSSMAN, H	8006240259	50-155 9
GILLET,W T	8004170704*	50-316 R	GRAVES, R H	8006130270	50-213 8	GROTENHUIS, M	8006260056	50-250 F
GILLESPIE.F P	8006250035#	70-143	GRAVES,R H	8006120375	50-213 8	GROVES, K L GROVES, K L GUILBERT, D E GUILBERT, D E GUINN, P R	8004300620	71-145
GILLIESPIE.F	8006050467	70-1151	GRAVES,R H	8006170526	50-213 R		8004300594	71-371
GILMAN,D W	8006120291	PRM	GRAVES,R H	8006300420	50-213 8		8006140119*	GA999
GILMARTIN,D J	8005220614	PR	GRAY,R J	8006300577*	50-320 H		8006120254	GA999
GILMARTIN,D J	8006130020	50-322 0	GRAY,F S	8006120495	PR		8006180276*	FOIA
GILMAN, A R	8006130033*	XPORTLIC	GRAY.J R	8006030135	50-344	OUMBLE, F W	8006300467*	50-286 S
GILPIN, J	8006050502*	State Prog	GRAY.J R	8006130252		OURNEY, P V	8006060285*	50-336 B
GINSBERG, T	8006170070	RES	GRAY.J R	8006180271		OUSTAVE, R P	8006190261	CONTRACT
GINSBERG, T	8006200025	RES	GRAY.J R	8006260206		GUSTAVE, R P	8006240241	CONTRACT
GIRARD, E H	8006120151*	50-370 Q	GREEN.J H	8006120246*		OUSTAVE, R P	8006230120	CONTRACT
GIRARD,E H GIRARD,E H GIVEL,M GLAGOLA,A F GLAGOLA,A F	8006190257* 8006300325* 8006170797 8006250029 8006160232	50-390 G 50-395 G FOIA CONTRACT 50-389 A	GREENMAN, E O GREENBURG, M GREEN, A R GREENBERG, R B GREENMAN, E Q	8006060047* 8006180577 8006030157 8006020540 8006300043*	50-277 @ 50-320 P XPORTLIC PR 50-334 @	OUTMANNIP M GUYEAGNIM J GUYEAGNIM J HARRESIN P	8006230083* 8006200573 8006040328 8006060207 8006040120	CONTRACT NUREO 40-4492 TOPREP TOPREP
GLAGOLA,A F	8006230004	CONTRACT	GREEN,D G	8006060033	50-445 M	Haass, w P	8006170126	50-241 P
GLAGOLA,A F	8006250086	CONTRACT	GREEN,D G	8006110238	50-445 M	Haass, w P	8006170745	TOPREP
GLAGOLA,A F	8006250049	CONTRACT	GREENE,G A	8006200014	RES	Haass, w P	8006170325	50-482 F
GLAGOLA,A F	8006250033	CONTRACT	GREER,R J	8006160215*	50-186 Q	Haass, w P	8006170327	50-327 A
GLAGOLA,A F	8006300338	CONTRACT	GREER,R J	8006200177*	50-315 Q	Haass, w P	8006230242	TOPREP
QLASSIER, O E	800&120459	40-8481	GREER,R J	8006250047*	50-294 G	HAASSIN P	8006240386	GA999
QLAZIER, R E	800&090105	NUREG	GREER,R J	8006190398*	50-116 G	HABER, D R	8006180252*	POIA
QLENN, T D	800&300&22*	71-145	GREGO,R J	8006250153	70-820	HABER, D R	8006180234*	FOIA
QLENN, T D	800&300&2&*	71-145	GREGORY,W S	8006170705	RES	HABER, D R	8006180227*	FOIA
QLENN, J	800&120129*	50-358 H	GREW.P	8006050447	PR	HACKETT, D B	8006130040*	50-266 P
GLENN, J E	8006070550	1&E	ORIER, B H	8006050498*	50-333 G	HAGAN, T F	8006270386	CONTRACT
GLENN, J E	8006120005	1&E		8006170744*	50-309 G	HAGEY, H A	8006230150	CONTRACT
GLENN, J	8006060289	50-346 H		8006060251	50-443 G	HAGEY, H	8006190244	CONTRACT
GODWIN, A V	8006060322	50-259 F		8006090157*	50-320 G	HAGEY, H	8006200073	CONTRACT
GOESER, D	8006120404	50-3 P		8006060042*	50-277 G	HAGUE, R L	8006200097*	50-305 Q
ODGCL, E ODGCL, E. OOLDBERG, B C OOLDBERG, R OOLDBERG, R	8006170560 8006170570* 8006300696 8006060314 8006060314	50-599 0 50-599 0 50-250 H 50-346 M 50-346 M	GRIER, B H ORIER, B H GRIER, B H GRIER, B H ORIER, B H	8006120090 8006200075 8006200077 8006200079 8006200082	50-54	HAIRSTON, W O	8006050036# 8006050043# 8006180442# 8006170604# 8006230363#	50-348 8 50-348 8 50-348 R 50-348 8 50-348 8
ODLDBERG, B C OOLDENBERG, M A OOLDBMITH, W OOLDBMITH, W	8006250237 8006260048 8005080533 8006170370* 8006240314	50-367 Q NUREQ 71-7015 QA999 REGOD	GRIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	8006200085 8006200089 8006200090 8006090155 8006020072	50-245 Q 50-220 Q 50-219 Q 50-320 Q 50-333 Q	HAIRSTON, W C HAIRSTON, W C HAIRSTON, W C HALE, C G HALE, C J	6006230376# 8006240375# 8006240376# 8006060240# 8006230238#	50-348
ODLLER, K. R. ODMER, D. A. QUMER, D. QUOD, R. R. QUOD, R. C. QUODHOPE, A. C.	8006240199*	REQOD	GRIER: B H	8004060049	50-387 A	HALE,C J	8006160138*	0A999
	8006130030	XPORTLIC	GRIER: B H	8006030074	50-244 P	HALE,C J	8006200148*	QA999
	8006170821	XPORTLIC	GRIER: B H	8006030256	50-334 Q	HALE,C,J	8006240126*	QA999
	8006020141	RES	GRIER: B H	8006060037	50-277 Q	HALL,W J	8006200046	70-754
	8006090304	70-1309	GRIER: B H	8006190079	50-219 F	HALL,W J	8006200050*	70-754
QOODHOPE, A C QOODHOPE, A C QOODHING, B QOODLING, B.	8006070307 8006070320 8006260254 8006300505* 8006300525*	70-1308 70-1308 70-1308 50-320 H 50-320 H	ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	8006240085 8006270172 8006170148 8006250220 8006070405	50-317 P 70-135 50-217 Q 50-333 Q 50-213 Q	HALL,R E HALL,D G HALL,R E HALL,R E HALL,R E	8006120274* 8006020552 8006250221* 8006030308 8006030365	40-3453 REB 50-445 Q TOPREP 50-331 F
GOODLING, B GOODLING, B GOODRICK, L GOODHIN, W L	8006300510* 8006300515* 8006130276* 8006020184 8006200007*	50-320 H 50-320 H 50-409 R REB 70-1151	ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8004200028 8004200027 8004200030 8004200032 8004200033	50-244 Q 50-272 Q 50-443 Q 50-485 Q 50-363 Q	HALL,R E HALL,R E HALLIOAN,T J HALLIOAN,T J HALTERMAN,H L	8006050276 8006230374 8006060487 300606040486 8006230459*	50-237 F 50-263 F 50-387 Q 50-387 Q 50-70 Q
QOODWIN, C QOODWIN, C QOODWIN, C QOODWIN, C	8004030391 8004050321 8004050324* 8004110313 8004140124	50-344 P 50-344 P 50-344 P 50-344 B 50-344 P	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8004200034 8004200035 8004200034 8004200037 8004200038	50-514	HALTERMAN, H L HAMM, K HAMMER, S J HAMPTON, N L HAN, S Y	8006230456 8006020014 8006050378* 8006260031 8006200614	50-70 0 50-3 H 50-263 B REB XPDRTLIC
00000000000000000000000000000000000000	8006230409 8006230604 8006230590 8006230593* 8006240329	50-344 P 50-344 P 50-344 P 50-344 P 50-344 P	ORIER, B H GRIER, B H GRIER, B H GRIER, B. H GRIER, B H	8006200040 8006200042 8006200043 8006200044 8006200045	50-320 Q 50-412 Q 50-307 Q 50-3 Q 50-286 Q	Y B Y HANCHETT, J O HANCHETT, J O HANCHETT, J O HANCHETT, J O	8006200617* 8006060530* 8006060504 8006250303 8006060561	XPDRTLIC 50-275 H 50-275 H CDMHIBBION 50-302 G
OGODMIN, C OGODMIN, C OGPPEL, M OGPPEL, M	8006240331* 8006240365 8006240401 8006030230 8006030238	50-344 P 90-344 P 50-344 F XPORTLIC XPORTLIC	ORIER, BH ORIER, B, H ORIFFITH, DG ORIFFITH, W ORIFFITHS, R	8006250191 8006270084 8006020374 8006170345 8006180507	50-277 F 50-219 G 71-368 PR 50-272 J	HANCOCK, J A HANCOCK, J A HANCOCK, J A HANCOCK, J A	8006240573* 8006190683* 8006020403 8006030303 8006030493	50-302 0 50-302 0 50-302 0 50-302 8 50-302 S
OGROOM, C.	8006020003	8tate Prog	ORIMES, B	8004300027	NUREG	HANGOCK, J. A	8006030505	50-302 S
CORDON, L. L.	8006170263	70-1308	ORIMES, C I	8004030514	50-219 P	HANGOCK, J. A	8006110123	50-302 S
CORE. J W	8006300313	50-317 G	ORIMES, B K	8004270351	50-309 H	HANGOCK, J. A	8006200638	50-302 S
COBSICK, L. V	8006190125*	FOIA	OROCE, R H	8004070482	50-309 G	HANGOCK, J. A	8006110128	50-302 S
COTCHY, R. L.	8006090223*	50-407 G	OROCE, R H	8004070450	50-271 Q	HANGOCK, J. A	8006170484	50-302 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HANCOCK, J. A. HANCOCK, J. A. HANCOCK, D. HANCOCK, J. A. HANCOCK, J. A.	6006170576 6006240417 6006240341 8006240446 8006240341	50-302 8 50-302 8 50-466 9 50-302 8 50-466 9	HEIDER, L. H HEIDER, L. H HEIDER, L. H HEIDER, L. H HEIDER, L. H	80060502E3 8006060469 8006110018 8006200501 8006170548	50-29 0 50-29 0 50-27 0 50-271 0 50-271 0 50-271 P	HERBE IN. J G HERBE IN. J G HERBE IN. J G HERBE IN. J G HERBE IN. J G	8004090243 8004090344 8004090313 8004090319 8004110071	50-289 F 50-320 P 50-289 Q 50-289 Q 50-320 F
HANCOCK, JA HAND, RL HANRAHAN, EJ HANRAHAN, EJ HANSELL, D	8006300378 8006270401 8006300539+ 8006070020 8006270417	50-302 5 NUREG FDIA COMMISSION FOIA	HEINZ, J HEINZ, J HEINZ, J HEIGHMAN, R F HEIGHMAN, R F	8006300538* 8006300541* 8006300551* 8006170052* 8006170308	50-320 H 50-320 H 50-320 H 50-315 Q 50-10 Q	O L'NI BERBH HERBE IN. J O HERBE IN. J O HERBE IN. J O HERBE IN. J O	8006110182 8006110066 8006130312 8006120317 8006200371	50-320 F 50-289 Q 50-289 F 50-289 F 50-320 E
HANSELL, D HANSELL, D HANSELL, D HANSEN, W HANSELL, D	8005200004 8005240281 8005130510 8005050511* 8006190352	PRM PRM PR 50-483 G 50-367 G	MEISHMAN, RF MEISHMAN, RF MEISHMAN, RF MEISHMAN, RF MEISHMAN, RF	8006170316 8006180041 8006170727 8006170291 8006170268	50-282	HERBEIN, JOHERBEIN, JO	8006200495 8006240303 8006230366 8006270332 8006300370	50-289 R 50-320 1 50-289 0 50-289 P 50-289 0
HANSELL, D HANSELL, D HANSELL, D HANSELL, D HANSELL, D	8006250315 8006050487 8006050487 8006050487 8006050487	71-9113 PR PR PR PR PR	HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF, HEISHMAN, RF, HEISHMAN, RF,	8006170795 8006130189 8006090453 8006170726 8006170742	50-346	HERBEIN.J G HERBEIN.J G HERD.D G HERDT.A R HERDT.A R	8006300451 8006300471 8006060471* 8006120151* 8006180091*	50-289 Q 50-289 B 50-70 P 50-370 Q 50-518 Q
HANSELL,D HARSELL,D HARSEN,L E HARDIN,A K HARDWICK,R J	8004120008 8006120019* 8006300621 8006040351 8006170784*	PR PR 71-6581 50-281 S 50-321 Q	HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F	8004230102 8004200131 8004200141* 800420008B 8004230070	50-150 0 50-373 9 50-373 0 50-305 0 50-295 0	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A R	8004020575* 8004090435* 8004030085* 8004120041* 8004030073*	50-324 @ 50-321 @ 50-302 @ 50-438 @ 50-364 @
HARDHICK: R J HARDHECK: R J HARMON: D W HARMON: D HARMON: D	8006070074* 8006230371* 8006200246* 8006130041 8006170862	50-280 G 50-369 G 40-8976 XPORTLIC XPORTLIC	HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F. HEISHMAN.R.F.	B006230082 B006050530 B006200256 B006200272 B006230075	50-358 0 50-255 0 50-341 0 50-266 0 50-254 0	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A, R	8006130065* 8006230350* 8006160206* 8006170774* 8006180390*	50-413 Q 50-327 Q 50-370 Q 50-389 Q 50-414 Q
HARRAN, O HARRIG, K HARRIG, J R HARRIG, J R HARRIGON, H C	8006170440* 8006120279 8006020063* 8006170768* 8006020135*	50-245 R PR 50-546 Q 50-566 Q 50-298 Q	HEISHMAN.R F. HEISHMAN.R F. HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F	8004040340 8006040041 8006240044 8006230205 8006170098	50-306 8 50-346 8 50-305 0 50-331 0 50-282 F	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A R	B004200114* B004190257* B004300273* B004300325* B004300243*	50-338 Q 50-390 Q 50-335 Q 50-395 Q 50-280 Q
HARRIS,JR HARRISON.H C HARRISON.H C HARRISON.J J HARRISON.D W	8004070154* 8004230071* 8004240008* 8004250170* 8004200061*	50-491	HEISHMAN.R F HEISHMAN.R F HEISHMAN.R F. HEISHMAN.R F. HEISHMAN.R.F.	8006170073 8006180555 8006170383 8006240060 8006300274	50-407 Q 50-266 P 50-315 Q 50-358 G 50-407 B	HEREFORD.J M HEREFORD.J M HEREFORD.J M HEREFORD.J M HEREFORD.J M	8006030447* 8006060416* 8006110276* 8006170549* 8006240423*	50-327 E 50-327 E 50-327 E 50-327 E 50-327 E
HARRIS, JR HARRIS, BJ HART, J HART, J HARVEY, BL	8004190300* 8004110282* 8004180391* 8004190313 8004050330*	50-546 G 50-445 M 50-382 B 50-382 B 50-337 P	HELFRICH, O.F. HELM, R. W HELWICK, C. HEMBY, E. D HENDERSON, R	8006170382 8006240306* 8006160117 8006160275 8006190403	XPORTLIC 40-1162 50-142 G MIBC 50-275 A	HEREFORD, J M HERLIHY, D HERLIHY, D HERLIHY, D HERLIHY, D	8006240420# 8006020034 8006070004 8006070520 8006250130	50-327 8 40-8693 40-8693 40-8720 40-8728
HARVEY, S.L. HARVEY, S.L. HARVEY, S.L. HARVEY, S.L. HARVEY, S.L.	8004050341* 8004050333* 8004050334* 8004050339* 8004120304*	50-339 P 50-339 P 50-339 P 50-339 P 50-338 R	HENDERSON, J. HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M	B006300219 B006260190* B006260192* B006270419* B006130154*	50-397 8 50-247 0 50-247 0 FOIA FOIA	HERLIHY, D HERLIHY, D HERMAN, T R HERR, R K HERR, R K	8006110348 8006110359 8006130021 8006250081* 8006250085*	40-8728 40-8728 50-338 50-285 50-285
HARHARD, J E HATCH, B. H HAUCK, F HAUCK, F HAUCK, F	8006120275 8006040086 8005210217= 8006170342= 8006070585	50-309 J Nureo 50-546 T 50-546 H 50-546 H	HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M	8006300629* 8006120261 8006130002 8006120201	FOIA 50-416 A COMMISSION COMMISSION COMMISSION	HERR, 8 K HERSCH, M M HERSCH, M M HERSCH, M M HERSCH, M, K	8006130178* 8006120258* 8006120442 8006120446* 8006120450*	50~482 ** XPORTLIC XPORTLIC XPORTLIC XPORTLIC
HAUGHNEY, C J HAUGHNEY, C J HAUGHNEY, C J HAVERKAMP, D HAVERKEMP, D	8006130110 8006130164 8006240597 8006250026 8006250362	50-201 P 50-201 P 50-201 P 50-289 8 50-289 8	HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J, M	8006120264 8006230119 8006230112 8006270046 8006190609	COMMISSION COMMISSION COMMISSION 50-320 H 50-275 Q	HERBCH, M M HERBCH, M M HERBH, L. HESB, W, N HESB, R J	8006120449 8006120439 8006110035* 8006250034* 8006120252	XPORTLIC XPORTLIC 50-361 CONTRACT XPORTLIC
Hawkins, F C Hawkins, F C Hawkins, W C Hawkins, F C Hawkins, R E	8004020043* 8004070054* 8004300610* 8006170300* 8006240381	50-546 G 50-546 G 50-225 G 50-546 G 50-448 G	HENRY, J J HENRY, L, O HENBLEY, K D HENBLEY, K, D HENBLEY, K D	8005220952 8006170677 8006200558 8006170203 8006120382	M19C 70-267 70-143 70-143 70-143	HESB.C R HENITT.J.R. HICKEY.W.F HICKLE.B J HIEBTAND.D S.	8006240111 8006180097 8006160065 8006170443* 8006040029*	71-9039 REB 50-471 50-285 50-409
HAYES, D. H HAYES, D. H HAYES, D. H	8004020063* 8004020084* 8004090036* 8004020073* 8004180414*	50-544 @ 50-330 g 50-546 @ 50-546 @ 50-483 @	HENSLEY, K. D HENSLEY, K. D. HENSLEY, K. D. HENSLEY, K. D HENSLEY, K. D	8006170330 8006170334 8006120376 8006300003 8006170481	70-143 70-143 70-143 70-143 70-143	HIQOINB, J.C HIQOINB, J.C HILL, W M HIND, J A HIND, J A	8006030101* 8006300060* 8006160231 8006030410* 8006030083*	50-322 50-322 50-272 70-27 50-346
	8004170776* 8004190300* 8004090447* 8004090418*	50-456 G 50-546 G 50-460 G 50-460 G Waste Mot	HENSLEY, K. D. HENSLEY, K. D. HENSLEY, K. D. HEPLER, W. HERBEIN, J. G	8006190579 8006240391 8006250235 8005210130 8006020210*	70-143 70-143 70-143 50-546 H 50-289 P	A L, GMIH A L, GMIH A L, GMIH A L, GMIH A L, GMIH	8006030081 8006110444* 8006110436 8006180594 8006180161	50-346 50-282 50-282 50-315 50-255
		WASTE MGT 40-7869 50-271 H NUREO 40-8502	HERBEIN, J.G HERBEIN, J.G HERBEIN, J.G HERBEIN, J.G, HERBEIN, J.G	8006060574 8006020205* 8006070419 8006020195 8006050280	50-287 Q 50-287 P 50-287 Q 50-287 P 50-287 P	HIND, J.A HIND, J.A HIND, J.A HINDERBTEIN, C HINEB, E	8004200541 8004230038 8004230043* 8006110170 8006040253	50-266 50-266 50-266 50-266 50-341
		NUREO R 0-317 B 0-271 G 0-271 G	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBEIN, J G,	8004030302 8004030335 8004050344 8004050380 8004040404	50-289 P 50-289 P 50-320 J 50-320 P 50-289 S	HINKLE, L. S HINKLE, L. S HINKLE, L. S HINKLE, L. S	8006240481 8006230681 8006300566 8006040352* 8006050045*	50-341 50-341 50-341 50-318 50-318

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCEBSION NUMBER	SUBJECT	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
HINKLE, L HIRIY, J W HINKLE, L O HOBBEN, T W HINKLE, L	8006180490* 8006180308 8006190645* 8006230067 7910310452	30-318 8 FOIA 50-344 I 70-398 PR	HOVEY. 0 K HOVEY. 0 K HOVEY. 0 K	9006060304 9006110204 9006110317 9006110070 9006110300	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	HUBACEK, W G HUBBARD, L B HUBBARD, L B HUBBLE, W H HUBBLE, W H	8004090234* 8004030127 8004240647 8004270045 8004300504	50-49B Q PR FDIA NUREO NUREO
HOEFLING, R K HOEFLING, R K HOEFLER, J HOFFMAN, D P HOFFMAN, D P	8006180538 8006190606* 8006110312* 8006030077 8006050533*	70~2623 50~269	HOVEY, OK HOVEY, OK HOVEY, OK HOVEY, OK	8004110104 8004110114 8004110145 8004110167 8004120374	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	HUBBLE, W H HUBBLE, W H HUBER, P W HUETER, L J HUETER, L J	8006300514* 8006300520* 8006270420 8006180075* 8006060172	NUREO NUREO NUREO 50-263 O 50-254 8
HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8006180166* 8006110487 8006120144 8006170870 8006020272	50-255 Q PR REGOD PR 50-255 P	HOVEY, O K HOVEY, O K HOVEY, O K	8006170583 8006300689 8006160024 8006230344 8006230326	50-320 Q 50-320 Q 50-320 S 50-320 P 50-320 S	HUFFMAN, D E HUGHEB, J HUGHEB, H J HUGHEB, M J HUNNICUTT, D M	8006190360 8006200113= 8006120508 8006300693= 8006190382*	50-416 A 50-358 G 50-219 H 50-219 H GA999
HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8006040311 8006040300 8006090300 8006110130 8006110133	50-255 P 50-155 B 50-255 P 50-255 B 50-255 P	HOVEY, OK HOVEY, OK HOWE, P. W HOWELL, OL HOWELL, B, H	8006240504 8006300447 8006090202* 8006270073 8006060017	50-320 S 50-320 P 50-400 G NUREO 50-329 G	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, K M HUNNICUTT, D M	8006300172* 8006240080* 8006250127* 8006040010* 8006120483*	0A979 0A999 0A999 0A999 0A999
HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P	8006070291 8006110068 8006110165 8006120308 8006170670	50-255 P 50-155 R 50-255 P 50-155 G 50-155 P	HOWELL, J C HOMELL, B H HOWELL, B H HOWLETT, O H HOYLE, J C,	8006050479 8006160236* 8006090114 8006230515* 8006190221	50-250 S GRO PR 50-336 R ACRB	HUNNICUTT, D M HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNT, M D	8006240172* 8006180451* 8006180453* 8006300477* 8006130054*	QA999 50-282 R 50-282 R 50-282 B 50-424 Q
HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P.	8006170706 8006170414 8006270307 8006200445 8006200352	50-155 8 50-255 8 50-155 8 50-255 8 50-255 G	HOYLE, J. C. HOYLE, J. C. HOYLE, J. C. HOYLE, J. C.	8006200619 8006230079 8006200039 8006230015 8006230084	ACRB ACRB ACRB ACRB ACRB	HUNT.M.D HUNTER.D R HUNTER.V H HUNTER.R 8 HUNTER.R S	8006300176* 8006130120* 8006230126* 8006120426 8006110477	50-364 G 50-282 G GA999 PRM PR
HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8006200356 8006200499 8006250268 8006270209 8006300377	50-155 Q 50-255 Q 50-155 P 50-255 Q 50-255 P	HOYLE, J. C HOYLE, J. C. HOYLE, J. C. HOYLE, J. C HOYLE, J. C	8004230234 8004230027 8004190190 8004230023 8004230033	ACRB ACRB ACRB ACRB ACRB	HUNTER, R. 8 HUNTER, R. 8 HUNTER, R. 8 HUNTER, R. 8 HUNTER, M	8006030281 8006060019 8006030284 8006240072 8006200167	50-315 Q 50-315 Q 50-315 P 50-315 G 50-445 M
HOGAN, B. T. HOGAN, J. P. HOLEMAN, G. R. HOLLAND, P. HOLLAND, P.	8006090446 8006060154 8006110481 8006040208* 8006230577*	NUREO PR PR 50-249 B 50-249 B	HOYLE, J C HOYLE, J C, HOYLE, J C HOYLE, J C	8004230058 8004230044 8005280090* 8004230018 8004250147	ACRS ACRS ACRS ACRS ACRS	HUNTER, M HUNTER, R B HUSEBY, D E HUSTON, R W HUSTON, R W	8006200167 8006240482 8006050035* 8006120384 8006130285	50-445 M 50-315 P 50-317 8 50-255 P 50-255 Q
HOLLAND; P. HOLLINGBHAUS; H HOLLOHAY; C. J. HOLM; J. S. HOLM; W. M.	8006230565* 8006200179* 8006020220 8006250105* 8006090035	50-249 B 50-387 B 50-566 A TOPREP XPORTLIC	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C	8005270030* 8006190209 8006190215 8006230227 8005270059*	ACRS ACRS ACRS 50-327 O ACRS	HUSTON, R. W HUSTON, R. W HUSTON, R. W HUSTON, R. W HUSTON, R. W	800&130247 800&160031 800&170515 800&170593 800&240508	50-255 G 50-255 P 50-155 S 50-255 G 50-255 S
HOLMES, J A HOLODY, D J HOLOMAY, C. F. HOLOMAY, C F. HOLOMAY, C F.	8004110122 8004050517* 8004250345 8004270078 8004300500	50-141 W 70-1143 REB REB REB	HOYLE, J.C. Hoyle, J.C. Hoyle, J.C Hoyle, J.C Hoyle, J.C	8006230229 8006260082 8006300312 8005230280* 8006190200	ACRB ACRB ACRB ACRB ACRS	HYDE, H. J IMAN, R. L INDUSI, J. P INGRAM, F. INGRAM, W. D	8004300545# 8004200535 8004240025 8004170878 8004240242#	50-320 H NUREO RES 50-302 B State Prog
HOLTER, O M HOLTON, R L. HONEY, D. D. HOOD, D. S. HOOD, D. S	8006250171 8006090049 8006240104 8006250010 8006200062	NUREO 50-599 O PR 50-329 A 50-329 A	HOYLE, J. C HOYLE, J. C. HOYLE, J. C. HOYLE, J. C HOYLE, J. C	8006270005 8005230387* 8006170175 8006170206 8005230082*	ACRS ACRS ACRS 50-327 O ACRS	IPPOLITO, T A IPPOLITO, T A, IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A	8006020175 8006040147 8006040144 8006020060 8006060003	50-133 F 50-259 F 50-331 F 50-324 Q 50-331 Q
HOOD, D. 8. HOOD, D. 8. HOOMER, C. D. HOOMELESEN, J. E. HORIN, W. A.	8006200594 8006230031 8006090446 8006040032* 8006060347	50-419 A 50-329 F NUREO 71-9001 50-445 Q	HOYLE, J. C HOYLE, J. C HOYLE, J. C HOYLE, J. C. HOYLE, J. C	6004300319 8005230116* 8005230398* 8004300549 8005270078	ACRB ACRB ACRB ACRB 10CFR	IPPOLITO, T A IPPOLITO, T A. IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A	800&0&0587 800&200577 800&020010 800&070027 800&020046	50-333 G 50-220 G TOPREP 50-271 P 50-220 G
HOR I N. H. A. HORN, A. J HORN, A. J HORN, H. C HORNBERGER, K. D	8004040347 8004040578* 8004250083* 8004110056 8004110492	50-445 0 50-142 0 50-344 0 PROJ PR	HOYLE, J. C. HOYLE, J. C HOYLE, J. C HOYLE, J. C. HOYLE, J. C.	8005270236* 8005270581* 8006300567 8005230253* 8006300324	ACRB 10CFR ACRB ACRB ACRB	IPPOLITO, T A	8005070018 8005070552 8005070545 8005120433 8005180171	50-254 F 50-324 F 50-333 F 50-263 F 50-271 H
HOBBLER, D. HOUCHIN, B HOUGHNY, C J HOUGHTON, T, C HOUGHTON, T, C.	8004240343 8004030050 8004200059 8004090511 8004190432	50-320	HOYLE, J.C. HOYLE, J.C HOYLE, J.C HOYLE, J.C	8005230546* 8004300329 8004300541 B004130072 8006250074	ACRB ACRB ACRB PR 50-327 D	IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T. A	8006200162 8006200178 8006170803 8006170037 8006170113	50-265 P 50-271 F 50-259 F 50-220 F 50-331 F
HOUGHTON, T. C. HOUSER, F M HOUSER, F M HOUSTON, D HOVEY, G. K	8006300299 8006030074 8006240594 8006250276 8006160144	50-416 A 70-2623 50-267 Q 50-440 A 50-320 B	HOYLE, J. C. HOYLE, J. C. HOYLE, J. C. HOYLE, J. C HOYLE, J. C	8006250091 8006240608 8006240599 8006240603 8006240595	ACRB ACRB ACRB ACRB 50-327 0	IPPOLITO, T. A IPPOLITO, T A IPPOLITO, T A, IPPOLITO, T A IPPOLITO, T, A	8006190117 8006190186 8006190316 8006200070 8006190108	50-133 F 50-263 P 50-333 F 50-324 F 50-263 F
HOVEY, Q. K. HOVEY, Q. K. HOVEY, Q. K. HOVEY, Q. K.	8006030457 8006030325 8006030362 8006030465 8006050038	50-320 S 50-320 P 50-320 P 50-320 S 50-320 P	HOYLE, J.C. HOYLE, J.C. HOYLE, J.C. HOYLE, J.C.	8006260072* 8006240519 8006240588 8006240591 8006260364*	10CFR 50-70 D ACRB ACRB ACRB	IPPOLITO, T A. IPPOLITO, T A IPPOLITO, T A IPPOLITO, T. A IPPOLITO, T. A	8006190122 8006230221 8006260081 8006270034 8006270037*	50-331 F 50-263 F TOPREP 50-324 P 50-324 P
HOVEY.O.K HOVEY.O.K HOVEY.O.K HOVEY.O.K	8004030359 8004040348 8004090374 8004050327 8004040243	50-320 Q 50-320 P 50-320 Q 50-320 P 50-320 S	HOYLE, J.C. Hoyle, J.C Hoyle, J.C Hoyl, O.W Huang, T.L	8006240520 8006240327 8006280087 8006190532* 8006280046	ACRS ACRS ACRS 50-361 I ORG	IPPOLITO, T A IRELAND, R IRELAND, R IRWIN, O R IBRAEL, B, L,	8006300255 8006120004 8006230046 8006020543 8006240237	50-271 H MIBC MIBC NUREO 50-249 P

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB JECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY
ISRAEL, S & IWANICKI, R E IWANICKI, R E JACKIM, I N JACKBUN, O	8006060300 8006240268 8006260079 8006170276* 8006180274*	TOPREP 40-8697 40-8380 50-254 G FOIA	JONES, W C JONES, Y I JONES, E W JONES, E W JONES, E W	8006040299 8006240313 8006240217 8006240222 8006170442	50-285 F 50-275 0 50-247 8 50-247 8 50-247 R	KAPLAN, A L KAPLAN, A L KAPLAN, A L KAPLAN, A L KAPLAN, A L	8006160223 8006270369 8006270365 8006130006 8006090489	70-1113 70-1113 70-1113 70-1007 70-1113
JACKSON, 0 JACKSON, 14 M JACKSON, 0 JACKSON, R W JACOBS, P T	8006180288* 8006170136 8005270522* 8006070148* 8006270065	FOIA PRM 71-9094 QA999 NUREG	JONES, W C JONES, W C JONES, W C JONES, W C JORDAN, E J	8006230422 8006240324 8006200014 8006300372 8006130120#	50-285 P 50-285 P RES 50-285 P 50-282 Q	KAPLAN, A L KAPPLE, A W KAPPLE, A W KAPPLE, A W KAPPLE, A W	8006200431 8006050371* 8006300373* 8006300424* 8006300465*	70-1113 50-272 8 50-272 8 50-272 8 50-272 8
JACOBS, A JACOBS, A JAECH, J L JANECEK, R F JANECEK, R F	9006190272 9006230129 9006250105* 7903160172 9006030478	CONTRACT CONTRACT TOPREP 50-237 P 50-237 P	JORDAN, E. L. JORDAN, L. V. JORDAN, L. V. JORDAN, W. S. JORDAN, W. S.	8004060603* 8006200132 8006230072 8006170336 8006110224	50-312 G 70-27 70-27 PR PR	KARMAN.M KATZ.L KAUFMAN.N C KAUFMANN.R B KAUFMANN.R B	8004020105 8004190356* 8006200572 8006170127 8006230326	50-454 9 0A999 PROJ 40-8502 40-8502
JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F	8006190305 8006090356 8006170559 8006190456 8006200386	50-10 P 50-254 P 50-254 F 50-10 P 50-10 P	Jordan, H 8 Jordan, W 8 Jordan, W 8 Jordan, W 8 Jordan, W 8	8006170336 8006170336 8006110224 8006170247 8006170247	PR PR PR PR PR	KAY, J A KAZANAB, N C KEARNEY, J KEATEN, R W KEEN, N	7450504008 *0120204008 E000404008 6010714008 *8710444008	50-27 P 50-289 P PR 50-289 9 50-498 9
JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F JANICEK, M	8006170417 8006230176 8006270273 8006250277 8006240256	50-237 P 50-249 P 50-265 P 50-237 P State Prog	Jordan, W S Jordan, D D Jordan, E L Jordan, W H Jordan, W S	8006170247 8006110282* 8006250089 8006160061 8006240537	PR 50~445 M M18C 50~289 O COMMISSION	KEHOE, D KEHOE, D. V KEIMIO, R R KEIMIO, R R KEIMIO, R R	8006070176* 8006170805* 8006020180* 8006040057* 8006180056*	50-213 0 50-293 0 50-219 0 50-245 0 50-272 0
JANUSKA: A G JAPE: F JASANI: K M JAHORSKY: M J JAYE: B	8006170377* 8006060152* 8006110148* 8006180101 8006110059*	50-295 Q 50-269 Q 50-320 P 50-282 P 50-361 Q	Jordan, W 8 Jordan, W 8 Jordan, W 8 Jordan, W 8 Jordan, W 8	8006240358 8006240483 8006240358 8006240483 8006260188*	50-155	KEIMIO,R R KEIMIO,R,R, KEIMIG,R R KELLAME,J D KELLAME,J D	8006180126* 8006250157* 8006190153* 8006050341* 8006050336*	50-272 0 50-245 0 50-217 0 50-337 P 50-339 P
JEFFERBON,R M JEFFRIEB,G JENKINS,OR JENKINS,OR JENKINS,OR	8006060168 8006270344 8006180003* 8006230202* 8006030585*	71-6400 NUREG 70-1151 50-280 G 50-424 G	Jordan, W 8 Jordan, W 8 Jorgensen, B L Joy, J H Joya, N	8006260186 8006260188* 8006180046* 8006160013* 8006190446	50-247	KELLEY, D C KELLEY, H D KELLEY, H D KELLEY, H D	8006200135* 8006030167* 8006230223* 8006070097* 8006170159*	0A999 GA999 GA999 50-382 G 50-382 G
JENKINS, O R JENKINS, G R JENKINS, G R JENKINS, G R	8006170775* 8006250163* 8006240052* 8006040356 8006050126	50-321	JOYCE, J JOYNER, J H JOYNER, J H JOYNER, J H JOYNER, J H	8006130182 8006060101* 8006040270* 8006030029* 8006050517*	MISC 50-293 Q 70-135 70-371 70-1149	KELLOGO,P J KELLEY,D C KELLEY,D C KELLEY,D C	8004040127* 8004250081* 8004250085* 8004090547* 8004090505*	50-285 0 50-285 0 50-285 0 50-321 0 50-83 0
JENKINS, R V JENKINS, R V JENS, H H JOHN, D F	8006110125* 8006170505* 8006270252* 8006030613* 8006130243	50-304 6 50-295 8 50-295 8 NUREO 50-445 M	UCYNER, J H H L , NBAYDU H L , NBAYDU H L , NBAYDU H L , NBAYDU	8006250017# 8006070176* 8006050147* 8006200538* 8006300131*	50-217	KELLOGG.P.J KELLOGG.P.J KELLOGG.P.J KELLOGG.P.J	8004250107* 8006130391* 8006160186* 8006040351 8006250106*	50-280 0 50-261 0 50-338 0 50-281 5 50-395 0
JOHN, D F JOHN, D F JOHN, D M JOHNSON, M B JOHNSON, B	8006130243 8006200167 8006200167 8006300102 8006170874	50-445 M 50-445 M 50-445 M NUREQ PR	Jurgenben, R W Kalivianakib, N Kalivianakib, N Kalivianakib, N Kalivianakib, N	8006030296 8006110141 8006110304 8006110320 8006110363	NUREO 50-254 8 50-254 8 50-265 8 50-265 8	KELLOOO,P J KELLOOO,P J KELMIO,R KEMPER,J B KEMPER,J B	8006300266* 8006130370 8006180609 8006120348 8006110329	50-324
704N80N' D 204N80N' C 304N80N' C 304N80N' D 304N80N' D 4	8006120147* 8005120430 8006120058 8006020266* 8006050440*	50-286 0 70-1510 50-155 0 50-220 0 50-244 0	KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALHAN, O	8006110078 8006110034 8006230391 8006270266 8006060197	50-254 R 50-254 R 50-254 S 50-245 S 50-320 B	KEMPER.JS KEMPER.JS KEMPER.J.S. KENDALL.H.W KENNA.WB	8006170627 8006260181 8006270217 8006040047 8006200010*	NUREG 50-277 P 50-352 B 50-320 P 70-1151
N WOSUNDO TOWNSTON A P TOWNSTON A P TOWNSTON A P TOWNSTON A M TOWNSTON	8006160138* 8006060264 8006040199 8006040199 8006170139	9A777 50-387 0 50-275 9 50-275 0 50-344 0	KAMMERER, C RAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006300231* 8006300237* 8006300245* 8006300254* 8006300263*	50-320 H 50-320 H 50-320 H 50-320 H	KENNA, W B KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8004250258* 8004040254 8004050379 8004200329 8004020047	50-321 0 70-143 70-27 70-143 70-1113
JOHNBON, A D JOHNBON, C JOHNBON, R E JOHNBON, R E JOHNBON, W W	8006050411* 8006240071* 8006120167 8006020198 8006250093*	50-36! Q 50-32! Q FOIA GEN TEC IS 50-344 Q	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006300315* 8006300321* 8006300503* 8006300326* 8006300337*	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	KENNA, W B KENNA, W B KENNA, W B KENNA, W, B KENNA, W B	8006050418 8006160237 8006200004 8006250032 8006250245	70-1113 70-149 70-1151 70-143 50-321 &
JOHNSTON, M P JOHNSON, N 8 JOHNSON, M C JOHNSON, J H JOHNSON, C R	8004300463 8004200249 8004230426 8004040377 8004160157	50-275 H XPORTLIC 50-395 B 50-387 Q 71-6498	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006300345* 8006300352* 8006300354* 8006300357*	50-320 H 50-320 H 50-320 H 50-320 H	KENNA, W B. KENNEDY, R T KENNEDY, R T KENNEDY, E M KENNEDY, W E	8004300216 8001040476 8004300635* 8006120280 8006250171	70-824 COMMISSION FOIA 50-271 U NUREQ
7 א אספאאטע מ א אספאאטע ז א אספאאטע ז אספאאטע ט אספאאטע נ	800&120445 800&190&54 800&110221 800&190597 800&160028	XPDRTLIC 50-395 Q 50-344 Q 50-275 H 50-446 Q	KAMMERER, C KAMMERER, C Kammerer, C Kammerer, C. Kanak, K. K	8006300428* 8006300431* 8006300437* 8006300445* 8006200021	50-320 H 50-320 H 50-320 H 50-320 H RES	KENYON, M KEPFORD, C KEPFORD, C KEPFORD, C	8006060230 8006090199 8006060245 8006090002 8006160067*	50-518 8 50-320 0 50-320 9 50-387 9 50-289 0
JONES' A T TONES' A C TONES' M C TONES' M C TONES' M C	8006160029* 8006300320 8006130070* 8006040176* 8006170828	50-466 0 50-375 G 50-265 G 50-275 G PRM	KANE: W. KANE: W. KANN: Q. A KANN: Q. A KANN: G. A	8006180583 8006170876 8006170615* 8006170621* 8006170626*	TOPREP TOPREP 50-339 P 50-337 P 50-339 P	KEPFORD,C KEPPLER,J.O KEPPLER,JO. KEPPLER,JO. KEPPLER,J.G	8006120379 8006130080* 8006130077* 8006020228 8006020231	50-287 9 50-255 9 50-255 9 50-358 F 50-263 F
JONEB, H C JONEB, Y I JONEB, C E JONEB, C, JONEB, H C	8006040024 8006040194 8006230060* 8006090061 8006300543	50-285 Q 50-275 Q 50-373 Q PR 50-285 Q	Kann, G. A Kanuch, B. M Kaplan, A. L Kaplan, A. L Kaplan, A. L	8006170633* 8006300454 8006200544 8006230045 8006180363	50-339 P TOPREP 70-1113 70-1113	KEPPLER, J O Keppler, J O Keppler, J O Keppler, J O, Keppler, J O	8004020234 8004020234 8004020240 8004020247 8004020250	50-255 F 50-409 F 50-10 F 50-331 F 50-346 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KEPPLER, J Q	8006020254	50~373 F	KETZLACH, N	8004070046*	70-25	KNUTH, D F	8006190248	FOIA
KEPPLER, J Q	8006020257	50~305 F	KETZLACH, N	8004020041	70-924	KNUTH, D F	8006090108	PR
KEPPLER, J G	8006020260	70~925	KETZLACH, N	8004020557*	70-27	KNCH, L J	8006030071	PR
KEPPLER, J Q	8006030177	50~266 F	KETZLACH, N	8004300171	70-698	KOCIS, R	8006120357*	50-346 S
KEPPLER, J Q	8006200102	50~331 Q	KETZLACH, N	8004300280	70-27	KODNER, J L	8006170560	50-599 Q
KEPPLER, J G	8004200104	50-155 Q	KEVERN, T A	8006020161	50-263 P	KODNER, J L	8004170570*	50-599 G
KEPPLER, J G	8004200108	50-263 Q	KEVERN, T A	8006250270	50-331 F	KODNER, J L	8004170540	50-599 G
KEPPLER, J G	8004200110	50-10 Q	KEVERN, T A	8006250279	50-331 P	KODNER, J L	8004170570*	50-599 G
KEPPLER, J G	8004040325	50-373 Q	KEY, W J	8006020089*	50-265 Q	KOESTER, G L	8004200144	50-482 P
KEPPLER, J G	8004170208	50-454 Q	KEY, W J	8006170766*	50-331 Q	KOESTER, G L	8004120354	50-482 G
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J, G KEPPLER, J G	8004020069 8004170044 8004140210 8004200194 8004300154*	50-546	KIM, 8 M KIM, 5 M KIM, 3 J KIM, 8 M	8006160186* 8006180183 8006180342* 8006180348* 8006180335*	50-938 Q PR FOIA FOIA FOIA	KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L	8006180525 8006070188* 8006250012 8006240200 8006240204	50-482 6 50-482 9 50-482 8 50-482 8
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8006060088 8006300148 8006050531 8006070479 8006070501	40-4337 50-341	KIM, S M KIM, S M KIM, S M KIM, S M	8006180269* 8006180272* 7703140178 8006180292* 8006180307*	FOIA FOIA FOIA FOIA FOIA	KOESTER, G L KOHLER, J E KOHLER, J KOHLER, J E KOHLER, J F	8006230384 8006170738* 8006170295* 8006230077* 8006050377	50-482 F 50-295 Q 50-295 Q 50-295 Q 50-304 B
KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8004070504 8004070518 8004070523 8004070527 8004110400	State Prog State Prog State Prog State Prog State Prog	KIM,8 M KINNEY,W W KINNEY,W W KINNEY,W W	8006180300* 8006180286* 8006120095* 8006060041* 8006180114*	FOIA FOIA 50-54 G 70-697 70-371	KDHLER, J E KONKL IN, J E KOPLIK, B KOPPELHAN, R KORSTAD, P A	8006040333 8006170323* 8006200583 8006030341 8006260045	50-304 S 50-546 G NUREO 50-129 W NUREO
MEPPLER, J O	8006120066	Btate Prog	KINNEY,W W	8006190088*	70-820	KOSTMAYER,P H	8006200071*	50-320 U
MEPPLER, J O	8006120408	State Prog	KINNECH,D L	8006230554*	50-361 A	KOTKOFF,D N	8006230531*	50-361 A
MEPPLER, J O	8006300139	50-329 G	KINTER,L	8006230130	50-364 P	KOTSCH,J L	8006050534	40-6659
MEPPLER, J O	8006170326	50-295 G	KINTER,L	8006250343	50-364 A	KOTSCH,J	8006170037	40-299
MEPPLER, J O	8006170173	50-346 P	KINTNER,L	8006190163	50-364 P	KOTTAN,J J	8006060041*	70-687
Keppler, J o	8006190176	50-263 F	KIPER,K L	8006130150	50~410 A	KOZIBEK,PB	B006240451	40-1162
Keppler, J o	8006190696	50-546 G	KIPPEN,T A	8006110088	40~1162	KRAMER.C O	B006170365	50-395 A
Keppler, J o	8006190700*	50-546 G	KIRK,W F	8006060158	70~371	KRATZ,L A	B006120415*	CONTRACT
Keppler, J o	8006190703*	50-546 G	KIRK,W F	8006110466	PR	KRAZINBKI,J L	B006120476	NUREO
Keppler, J o	8006190706*	50-546 G	KIRK,B L	8006300069	NUREQ	KROEB,R J	B006230518	50-493 F
KEPPLER, J O	8006190713*	50-546	KIRK, B L	8006300085	NUREQ	KROGER, R C	8006170107	XPORTLIC
KEPPLER, J O	8006190719*		KIRKLAND, M W	8006190424	70-754	KUGE, T	8006250058	XPORTLIC
KEPPLER, J, O	8006240535		KIRKLAND, R S	8006110118	50-160 8	KUMAR, K D	8006300085	NUREQ
KEPPLER, J O	8006180031		KIRKLAND, R S	8006250248	50-160 F	KUNDER, G A	7812270073	50-320 8
KEPPLER, J O	8006180543		KIRSCH, D F	8006250172*	50-397 G	KUO, P, T	8006110228*	50-275 Q
KEPPLER, J O	8006240087	50-315 P	KIRSCH, D F	8006300591*	50-397 A	KUSHNER, W. L	8006040270*	70-135
KEPPLER, J O	8006300268	50-186 G	KIBTER, H	8006120147*	30-286 G	KUSHNER, W. L	8006300131*	70-1143
KERR, O. W.	8006050477	Btate Prog	KIBTER, H B	8006020092*	50-333 G	LAATS, E. T	8006260031	RES
KERR, O W	8005130512	WABTE MOT	KIBTER, H, B	8006030101*	50-322 G	LACEY, W. S	8006030415*	50-334 S
KERR, O W	8006070430	Btate Prog	KIBTER, H, B	8006020266*	50-220 G	LACEY, W. S	8006060374*	50-334 S
MERR, O W MERR, D W. MERR, O. W. MERR, O W. MERR, Q. W	9004090445* 9004020004 9004030143 9004110404 9004120512	Btate Prog State Prog HASTE MOT State Prog State Prog	KISTER,H B KISTER,H. KISTER,H B KISTER,H.B KITE,M B	8006030440* 8006170391* 8006230190* 8006300060* 8006110088	50-244	LACEY, W. 8 LACEY, W. 8 LACEY, W. 8 LACEY, W. 8 LACEY, W. 8	8006060385* 8006090389* 8006090389* 8006110112* 8006110126*	50-334 8 50-334 8 50-334 8 50-334 8
KERR, O W MERR, O W KERR, O, H KERR, O W, KERR, O W	8006300647 8006240548 8006250008 8006300449 8006300540	State Prog 50-83	KITE, M B KLEINBORGE, W. KLEINBORGE, W P KLEINBORGE, W P KLIMBERG, S, B	8006110088 8006180091* 8006120041* 8006130065* 8006110225	40-1162 50-518 G 50-438 G 50-413 G 50-244 G	LACEY, H. B. LACEY, H. B. LACEY, H. B LACEY, H. B LACHANCE, J. L	8006170563* 8006170571* 8006170576* 8006230562* 8006300455	50-334 8 50-334 8 50-334 8 50-334 8 RES
MERR. O. H	8006230075	State Prog	KLINE, JA	8006120332	50-275	LACKER, D K	8006130003*	COMMISSION
MERR. O. W.	8006230177	State Prog	KLOPPING, J	8006170517		LADUN, R H	8006090170*	50-320 Q
MERR. O. W	8006230187	State Prog	KNAPP, PJ	8006230452*		LADUN, R, H	8006090086*	50-201 Q
MERR. O. W	8006230192	REGOD	KNAPP, P,	8006050088*		LADUN, R	8006050516*	70-1143
MERR. O. W	8006240215	State Prog	KNAPP, P	8006170208*		LADUN, R	8006190075*	50-184 Q
KERR, O W.	8006250014	State Prog	KNAFP,F J	8006270406*	50-217 G	LADUN,R H	8006200257#	70-33
KERR, O W.	8006260132	State Prog	KNAPP,P.J,	8006190153*	50-217 G	LADUN,R H	8006240188#	70-820
KERR, O. W	8006300044	State Prog	KNAPP,P	8006040337	50-217 S	LADUN,R.H	8006300610#	50-225 @
KERR, O. W	8006300350	State Prog	KNAPP,P J	8006300223	50-277 S	LAFLEUR,J D	8006200527	50-320 P
KERR, O W	8006240106	State Prog	KNEBEL,J A	8006030153	40-9502	LAGIEWSKI,J 8	8006040352#	50-318 S
KERR, O W	8004240443	State Prog	KNIOHT, J P	8004030195	50-275 A	LAGIENSKI, L	8004050045*	50-318 \$
KERR, O W,	8004250115	State Prog	KNIOHT, J P	8004300450	50-329 A	LAGOMARBINO, R.	8004040516*	50-275 H
KERR, O W	8004300537	State Prog	KNOP, R C	8004200113*	50-359 G	LAGOMARBINO, R J	8004170445	50-275 H
KERR, O, W.	8004300542	State Prog	KNOP, R, C	8004050511*	50-483 G	LANCASTER, K. F	8004030304*	50-302 8
KERR, W	8004180254	50-2	KNOP, R C	8004200124*	50-461 G	LANCASTER, K. F.	8004030500*	50-302 8
KERRIOAN, J	8006090507	50-311 P	KNOP, R.C.	8006170763*	50-327	LANCABTER, K F	8006030508*	50-302 8
KERRIOAN, J	8006250069	50-311 P	KNOP, R.C.	8006170201*		LANCASTER, K F	8006110140*	50-302 8
KERRIOAN, J	8006240236*	50-528 A	KNOP, R.C.	8006190182*		LANCASTER, K F	8006190603*	50-302 8
KERRIOAN, J,	8006250098	50-311 P	KNOP, R.C.	8006060226*		LANCASTER, K F	8006300401*	50-302 8
KERRIOAN, J D	8006250308	50-311 P	KNOP, R.C.	8006230061*		LANCASTER, K F	8006240450*	50-302 8
KERS, D.	8006200597	NUREO	KNOP, R. C.	8006300152*	50-329 G	LANCASTER, K F	8006240426*	50-302 S
KERWIN, D. K	8006200542	NUREO	KNOTTB, J. B	8006050555	50-445 M	LANDAUER, R, S	8006070010	PR
KETCHEN, E. G.	8006030196	50-244 O	KNOTTB, J. B	8006050458	PR	LANDSMAN, R B	8006180414*	50-483 Q
KETCHUM, A. G	8006120351	50-387 D	KNOTTB, J. B	8006050458	PR	LANGLEY, E, B,	8006160044*	50-275 A
KETCHEN, E. G.	8006110196	70-2623	KNOTTB, J. B.	8006120052	50-445 M	LANGNER, R R.	8006170582	50-264 F
KETCHEN, E, G KETCHEN, E, G, KETCHEN, E, G, KETCHEN, E, O KETZLACH, N	8006110210 8006190893 8006190606* 8006200317 8006040129	50-275	KNOTTS: J. 8 KNOTTS: J. 8 KNOTTS: J. 8 KNOTH: D. F KNOTH: D. F	8004120052 8004110302 8004110302 8004120434 8004120441*	50-445 M 50-445 M 50-445 N PRM PRM	LANIK, Q LANNING, D D LANTZ, P M LANTZ, P M LARDER, R A	8006250357 8006260038 8006270078 8006300500 8006270398	TOPREP NUREQ RES RES NUREQ

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION REEMUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEOORY
CARKIND H	8004020570	4Q-8502	LEWIS, R C	8005230222#	50-321 Q	LING, D	8006060513*	50-275 K
LARKINS, J T	8004090439*	TGPREP	LEWIS, R C	8005230225#	50-321 Q	LITRACK, S M	8006120137*	50-458 K
LARKINE, J T	8004090434	TGPREP	LEWIS, S R	8005030344#	50-267 S	LITTLE, W S	8006170738*	50-295 G
LARSON, T K	8004240020	RES	LEWIS, R C	8005240055	50-321 Q	LITTLE, W S	8006170275*	50-295 G
LATHAM, S B	8004190570	50-322 0	LEWIS, R C	8005170851	50-324 Q	LITTLE, W S	8006200266*	50-341 G
LATHAM, S B LAUBEN, N LAUDIO, S LAURINO, O F LANTON, M D	8006180087* 8006250354 8006110427 8006300300 8006040187	50-322	LEMIS, R. C. Lemis, R. C. Lemis, R. C. Lemis, R. C. Lemis, R. C	8006260017 8006250073 8006250102 8006300199* 8006300272	50-302	LITTLE, W 8 LITTLE, W 8 LITTLE, L W LITTLE, J L	8004230077* 8004090377 8004040333 8004140041 8004170340*	50-275 0 50-304 8 50-304 8 50-287 0 TOPREP
LAZARUS,W J	8006060035*	50-307 G	LENIB, R C	8004300261	50-324 @	LITVACK.S M	8006180215*	50-458 H
LAZARUS,W	8006030107*	50-307 G	LENIB, R C	8004090528	50-321 @	LIVERMORE,H H	8006230061*	50-461 B
LAZO,R M	8006020150	50-466 G	LENIB, R C	8004090479	50-83 @	LO.R	80062300027	NUREQ
LAZO,R M	8006120325	50-142 G	LENIB, B R	8004020343*	50-287 8	LOADER,J Q	8006240495	50-302 [
LAZO,R M	8006230372	50-133 G	LENIB, B R	8004040302*	50-269 8	LOCHBTET,W A	8006170863	PR
LAZO, R. M	8006240435	50-367 C	LEWIS, R C	8006240068	50-280 0	LOCHSTET,W A	8006240422	50-320 ¢
LAZO, R. M	8006300419	50-282 G	LEWIS, R C	8006180017	50-250 0	LOCKE,R F	8006180522*	50-275 ¢
LEACH, L. P	8006020184	RES	LEWIS, R. C	8006180317	50-321 0	LOCHENSTEIN,W	8006040322	NUREQ
LEAHEY, H. S	8006250090*	CONTRACT	LEWIS, R. C	8006230159	50-335 0	LONG,R L	8006020210*	50-289 F
LEAGE R. S	8006240476*	50-316 S	LEWIS, R C	8006230210	50-321 0	LONG,C D	8006270150*	50-171 V
LEBO.C.D LEBO.C.D LEDUC.B K LEE.B LEE.B	8006050526 8006250040 8006200563 8006130142* 8006170681	CONTRACT CONTRACT NUREC 50-10 Q 50-10 H	Lewis, R C Lewis, R C Lewis, B H Lewis, S. H Lewis, S H	8004240140 8004240251 8004050272 9004110020 8004110023	50-259 Q 50-259 Q 50-445 M 50-549 Q 50-263 Q	TONG'Y D TONG'R D TONG'R D TONG'R D	8006130269 8006040002 8006270020* 8006160122 8006270047	70-824 50-247 P 50-317 P 70-824 50-247 P
LEE, E W K	8004020014*	50-454 Q	Lenis, 8 H	8006110038	50-471 0	LORIO,P M	8004090352	50-208 F
LEE, E W K	8004230151*	50-461 Q	Lenis, 8. H	8006050274	50-596 0	LOUDERBACK,T E	8004020458	40-8714
LEE, K W	8004240048	NUREQ	Lenis, R C	8006200212	50-250 0	LOUDERBACK,T E	8004120253	40-8714
LEE, O. R	8004040041	50-267 Q	Lenis, B. R	8006110096*	50-287 B	LOVE,E	8004120285	PRM
LEE, R. E	8004040057*	50-267 Q	Lenis, B. R	8006110326*	50-270 B	LOVENDALE,P C	8004020192*	50-254 G
LEE, T. D	9006200338*	70-143	LEHIB, 8. M	8006060239	50-482 0	LOVENDALE, P C	8004180581*	50-266 G
LEED. R M	9006060299	50-522 0	LEHIB, 8. M	8006090237	50-247 0	LOWE, H D	8004120272	MIBC
LEED. R M	8006060279	50-522 0	LEHIB, 8. M	8006110113	50-286 0	LOWERRE, R W	8004040353	PR
LEED. R M	8006190447	50-522 0	LEHIB, R. C	8006250094	50-280 0	LOWRY, L H	8004040081	NUREG
LEED. R M	8006190447	50-522 0	LEHIB, 8. H	8006110209	50-261 0	LUBENAU, J D	8004040012	Btate Prog
LEHMAN, L. J LEHMAN, L. J LEMPQES, T. E LEMPQES, T. E. LEMPQES, T. E.	8006130256 8006130315 8006030058 8006030590 8006020462	50-320 P 50-320 D 50-220 G 50-220 P 50-220 G	LEWIS,R C LEX,B,L LEX,B L. LIBARKIN,M W LIBERATORI,L F	8006170530* 8006060204* 8006060170* 8006170287 8006250259	50-269 8 50-424 8 50-424 8 ACRB 50-247 P	LUBENAU, J O LUGE, H L LUGUE, N LUJAN, M.	8006240641 8006300680 8006170360* 8006180189 8006200091*	State Prog State Prog TOPREP 50-445 M 50-320 U
LEMPOES, T E	8004120358	50-220 G	LIBRIZZI.F P	8006050364	50-272 8	LUKZ:F. J	8006250064*	CONTRACT
LEMPOES, T E	8004300271	50-220 G	LIBRIZZI.F P	8006120203	50-311 P	LUNDVALL:A E	8005190447	50-317 B
LEMPOES, T, E	8004070340	50-220 S	LIBRIZZI.F P	8006170450	50-272 P	LUNDVALL:A E.	8006240011	50-317 O
LEMPOES, T E	8004070370	50-220 S	LIBRIZZI.F P	8006170651	50-272 P	LUNDVALL:A E	8006020149	50-317 P
LEMPOES, T E	8004110171	50-220 R	LIBRIZZI.F P	8006170620	50-272 P	LUNDVALL:A E	8006240020	50-317 O
LEMPOES, T E	8006300265	50-220 G	LIBRIZZI,F P	8006170573	50-272 B	LUNDVALL: A E LUNDVALL: A E LUNDVALL: A. E LUNDVALL: A. E LUNDVALL: A E LUNDVALL: A E	9006030237	50-317 F
LENAHAN. J. J	8006270214*	50-438 G	LIBRIZZI,F.P	8006170664	50-272 B		9006030244	50-317 F
LENTSCH, J W	8006300504	PR	LIBRIZZI,F P	8006230527	50-272 B		9006170439	50-317 F
LENTSCH, J W	8006230423	50-344 G	LIBRIZZI,F P	8006240443	50-311 B		9006180435	50-318 P
LEONARD, J D	8006050505*	50-333 G	LIBRIZZI,F P	8006240486	50-272 B		9006180260	50-317 P
LEONARD. J D	6006050493	50-333 G	LIBRIZZI,F P	B006300370	50-272 8	LUNDVALL, A E	8006230270	50-317 P
LERNER. N C	8006230059*	CONTRACT	LIBRIZZI,F P.	B006300421	50-272 8	LUNDVALL, A E	8006240320	50-317 F
LESSOR. L C	8006090322	50-298 R	LIBRIZZI,F P	B006300459	50-272 8	LUQUE, N	8006120036	50-445 M
LEUNG. J C	8006040093	Org	LIBRIZZI,F P	B006300479	50-311 8	LUQUE, N	8006060492	50-445 H
LEUNG. J C	8006040093	Org	LICCIARDO,R	B006120014	50-305 P	LURIE, N A	8006200598	NUREO
LEVINE, M M	8006200031	REB	LICCIARDD, R B	8006240638	50-305 P	LUTON, E,	8006180010#	50-244 Q
LEVINE, S H	8006130278	50-5 F	LICHTENBERGER, H	8006200151	70-1100	LYNCH, M D.	8006110414	50-397 A
LEWIS, O	8006300397#	50-390 A	LICHTENBERGER	8006190417	70-34	LYTTON, M	8006120075#	50-320 P
LEWIS, J G	8006300517#	50-235 Q	LICHTENBERGER, H	8006090103*	GAFFF	MAGARTHUR, T C	8006180005#	70-1151
LEWIS, R C	8006060564#	50-302 Q	LIEBERMAN, J	8006260196	50-498 Q	MAGARTHUR, T C	8006170775#	50-321 Q
Lehis, R C. Lehis, R C Lehis, R C Lehis, R C Lehis, M I	8006070540* 8006070471* 8006060534* 8006180028* 8005220680	50-321 G 50-83 G 50-348 G 50-250 G PR	LIENHARD, J H LIENKAEMPER, J LINDER, F LINDER, F, LINDER, F	8006120298 8006060476* 8006040031* 8006020545 8006050363	ACRE 50-70 F 50-409 G 50-409 G	MACARTOR, J D MACARTOR, J D MACDONALD, C E MACDONALD, C E MACDONALD, C, E	8004040028 8004110144 8004130008* 8004130012* 8004180223*	50-272 T PR 70-1007 70-1007 71-9103
LEWIS, R C	8004230171*	50-235	LINDER, F	8006070316	50-409 P	MACDONALD, C E	8005200094	71-185
LEWIS, R C	8004030592		LINDER, F,	8006130273	50-409 R	MACDONALD, C E	8005200100#	71-185
LEWIS, R C	8004040144		LINDER, F	8006110343	50-409 F	MACDONALD, C E	8005170077	71-6058
LEWIS, R C	8004240264*		LINDER, F	8006180523	50-409 P	MACDONALD, G E	8005030067	71-9135
LEWIS, R C,	8004240267*		LINDER, F,	8006200420	50-409 P	MACDONALD, C. E	8005020582	71-9096
LEWIS, R. C.	8006240167*	50~259	LINDSTROM, JB	8006300032	40-465	MACDONALD, C. E	8006020585*	71-9096
LEWIS, R. C.	8006050431		LINDSAY, WW	8006130308	50-397 D	MACDONALD, C. E.	8006030033	71-9094
LEWIS, R. C.	8006200219*		LINESERGER, G	8006060577	50-376 Q	MACDONALD, C. E.	8006030035*	71-9094
LEWIS, R. C.	8006070516		LINEHAN, JJ	8006060063	40-8304	MACDONALD, C. E.	8006070407	71-9141
LEWIS, R. C.	8006250103*		LINEHAN, J, J.	8006070079	40-1162	MACDONALD, C. E.	8006070410*	71-9141
LEWIS, R C. LEWIS, R C LEWIS, R C. LEWIS, R C. LEWIS, R C.	8006130389 8006160181 8006230228* 8006060581 8006090561*	50-261	LINEHAN, J. J LINEHAN, J. J LINEHAN, J. J LINEHAN, J. J	8006090124 8006090139 8006090556 8006030032 8006030015	40-1162 40-1162 40-1162 40-8698 40-2259	MACDONALD, C.E. MACDONALD, C.E MACDONALD, C.E MACDONALD, C.E MACDONALD, C.E	8006090413* 8006090486 8006060429 8006060433* 8006060437*	71-7141 71-9141 71-9132 71-9132 71-9132
Lewis, R. C	8004070082	50-338	Linehan, J. J	8004030038	40-2259	MACDONALD, C E	8006120405	71-384
Lewis, R. C.	8004200517		Linehan, J. J,	8004230139	40-4492	MACDONALD, C E	8006060421	71-9853
Lewis, R. C.	8004060525		Linehan, J. J	8004200440	40-8802	MACDONALD, C E	8006060425*	71-9853
Lewis, R. C.	8004180240*		Linehan, J. J.	8004250378	Waste Mgt	MACDONALD, C E	8006060612	71-5939
Lewis, R. C.	8004200124		Linehan, J. J	8004170804	40-1162	MACDONALD, C E,	8006060616*	71-5939

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MACDONALD, C E	8006060276	71-9079	MALLORY.C W	8005120181	71-9086	MARTIN,T T	8006030107*	50~307 G
	8006060282*	71-9079	MALLORY.C W	8006050433	71-9079	MARTIN,T J	8006250226*	50~354 G
	8006060603	71-9007	MALMROS.K H	8006250093*	50-344 G	MARTIN,T T	8006170805*	50~273 G
	8006060607*	71-9007	MALTESE.M J	8006300440	50-333 F	MARTIN,H G	8006050048	50~273 G
	8006070416	71-5364	MANCINI.T	8006060155	40-8745	MARTIN,H G	8006060097	50~273 G
MACDONALD, C E	8006070421*	71-5364	MANDLER, J W	8006130393	RES	MARTIN,R D	8004200227*	50-250 G
MACDONALD, C E	8006070022	71-388	MANLEY, E	8005270296*	40-8434	MARTIN,R D	8004060152*	50-269 G
MACDONALD, C E	8006070024*	71-388	MANLEY, E A	8005270304*	40-8434	MARTIN,T T	8004170308*	50-271 G
MACDONALD, C E	8006070174	71-135	MANN, D	8006170503	50-387 D	MARTIN,W G	8004170067	50-184 G
MACDONALD, C E	8006070177*	71-135	MANRY, M	8006020483	71-6601	MARTIN,T T	8004180057*	50-29 G
MACDONALD, C E	8006110449	71-9039	MANRY, M	8006020497	71-6144	MARTIN, W Q	8004200239	70-33
	8006120226	71-230	MANRY, M	8006020518	71-6275	MARTIN, T T	8004030110*	50-29 G
	8006120234*	71-230	MANRY, M	8006020565	71-5026	MARTIN, W Q	8004200520	70-33
	8006170815	71-9094	MANRY, M	8006020567	71-9044	MARTIN, R D	8004090565*	50-369 G
	8006170817*	71-9094	MANRY, M	8006050541	71-5026	MARTIN, W J	8004090078	50-201 G
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8006190174 8006260015 8006170200 8006170203 8006170207	71-9094 REB 71-9039 71-9113 71-9111	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8006170337 8006050367 8006030413 8006030458 8006030438	50-321	MARTIN,T T MARTIN,U O MARTIN,U O MARTIN,R D MARTIN,J B	8004250164* 8004270239 8004240180 8004200525* 8004200043	50-29 G 50-317 G 70-820 50-302 G MISC
MACDONALD, C. E MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	8006170212 8006170214 8006180595 8006180603 8006190110	71-6601 71-9081 71-9023 71-15 71-9070	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8006050338 8006050360 8006230548 8006050348 8006050334	50-366 8 50-321 8 50-366 8 50-366 8	MARTIN,W O MARTIN,R D MARTIN,T J MARTIN,W G MARTIN,R	8006060185 8006180246* 8006020475 8006300120 8006260023*	70-135 50-369 Q 50-354 Q 70-1143 50-302 Q
MACDONALD, C E	B006230167	71-5026	MANRY, M	8004050347	50-321 8	MARTIN,W O	8006300597	50-54 Q
MACDONALD, C E	B006230174	71-108	MANRY, M	8004050345	50-364 8	MARTIN,W O	8006300606	50-225 Q
MACDONALD, C E	B006230032	71-5939	MANRY, M	8004230574	50-321 8	MARTIN,W	8006050474	50-247 8
MACDONALD, C E	B006230037*	71-5939	MANRY, M,	8004090327	50-321 8	MARTIN,W O	8006240611	50-293 Q
MACDONALD, C, E	B006230064	71-5942	MANRY, M	8004230522	50-321 8	MARTIN,T J	8006020407	50-354 8
MACDONALD, C. E.	8006250031	71-9093	MANRY, M	8006170674	50-321 B	MARTIN, J. B	8006200568*	40~8502
MACDONALD, C. E	8006250063	71-6771	MANRY, M	8006170683	50-366 B	MARTIN, H. G	8006250007	50-219 Q
MACDONALD, C. E	8006250118	71-6206	MANRY, M	8006170673	50-321 B	MARTINSON, A. R	8006180038	REB
MACDONALD, C. E.	8006250122	71-9007	MANRY, M.	8006190578	50-321 S	MARTIN, H.	8006240217	50-247 B
MACDONALD, C. E.	8006250125	71-6375	MANRY, M	8006180438	80-321 R	MARTIN, W	8006240222	50-247 B
MACDONALD, C E	8006250197	71-389	MANRY, M	8006180494	50-346 R	MARTIN,R.	8006230142	50-282 P
MACDONALD, C E	8006300039	71-4717	MANRY, M	8006190566	50-321 B	MARTIN,R.E	8006240039	50-282 P
MACDONALD, C E.	8006250027	71-5975	MANRY, M	8006200437	50-346 B	MARTINSON,R K	8006230228	50-275 A
MACDONALD, C E	8006270041	71-9032	MANRY, M	8006190607	30-321 B	MARTY,R	8006120219*	COMMISSION
MACDONALD, C E	8006200503	71-6786	MANRY, M,	8006200441	50-321 B	MARUSICH,R M	8006240233	50-255 P
MACDONALD, C. E.	9006250101	71-5862	HANRY, M.	8006200468	50-366 8	Masse, R e	8006170052*	50-315 G
MACDONALD, C. E.	9006250131	71-4888	HANRY, M.	8006200476	50-366 8	Masse, R e	8006130198*	50-315 G
MACDONALD, C. E.	9006250134	71-8940	HANRY, M.	8006200478	50-366 8	Masse, R	8006200197*	50-315 G
MACDONALD, C. E.	9006300126	71-5071	HANRY, M.	8006230580	50-321 8	Massie, H W	8006180540	RES
MACDONALD, C. E.	9006300134	71-5830	HANRY, M.	8006200452	50-321 8	Mathews, E, R.	8006160095	50-305 R
MACDONALD, C. E.	8004270055	71-164	MANRY, M.	B006240431	50~366 8	MATHEWS, E. R	8006170426	50-305 P
MACDONALD, C. E.	8004300411	71-390	MANRY, M.	B006240454	50~366 8	MATHEWS, E. R	8006200463	50-305 B
MACDONALD, C. E.	8004300418*	71-390	MANRY, M.	B006240442	50~366 8	MATHEWS, T. C	8006250255	50-287 B
MACDONALD, C. E.	8004270057	71-5980	MANRY, M	B006240507	50~366 8	MATHEWS, E. R	8006240299	50-305 G
MACDONALD, C. E.	8004300007	71-6144	MANSER, H. C	B006120391	70~143	MATHEWS, E. R.	8006240493	50-305 P
MACDONALD, C.E.	8006300108	71-9039	MANBER, W. C.	8006120306	70-149	MATHENS, E. R	8006250185	50-305 G
MACFARLAND, G.R.	8006180397*	50-328 G	MANBER, W. C.	8006180387	70-149	MATHIAS, C. M	8006270155*	50-171 H
MACHUTCHIN, J.O.	8006300296	XPORTLIC	MANBER, W. C.	8006240403	70-149	MATSON, V	8006030059	XPORTLIC
MADDEN, W.	8006050516*	70-1143	MARBET, L. K.	8006110235	50-514 G	MATSON, V	8006030063*	XPORTLIC
MADDEN, J. J.	8006170478*	50-295 B	MARCHAL, J.	8006240127	XPORTLIC	MATSON, V.	8006120420	XPORTLIC
MADEDA, T. J.	8006030083*	50-346 G	MARCHAL, J	8006190067	XPORTLIC	MATBON, V.	8006120424*	XPORTLIC
MADIBON, S. R.	8006110214	50-576 O	MARGUARDT, W.	8006110282*	50-445 H	MATBON, V	8006120500*	XPORTLIC
MADIBON, H. R.	8006030304	50-338 B	MARHEALL, W. H	8006110258	50-329 H	MATBON, V	8006120497	XPORTLIC
MADBEN, G. L.	8006030519	50-278 G	MARKS, S. M.	8006060473*	50-70 P	MATBON, V.	8006260019	XPORTLIC
MADBEN, G. L.	8006060118	50-172 G	MARKWORTH, A. J	8006040081	NUREO	MATBON, V	8006260022*	XPORTLIC
MADSEN, G. L.	9004060121*	50-192	MARRACK, D.	8006060392	50-466 Q	MATTHEWB,P R.	8006170103	TOPREP
MADSEN, Q. L.	9004060125		MARSHALL, W. H.	8006300395#	50-329 H	MATTIA,M.J.	8006060601*	CONTRACT
MADSEN, Q. L.	9004240178		MARSHALL, W. H.	8006110261	50-329 Q	MATTIMOE,J J	8006180632	50-312 Q
MADSEN, Q. L.	9004240034		MARSHALL, W. H.	8006170569	50-329 H	MATTIMOE,J J	8006130341*	50-312 Q
MADSEN, Q. L.	9004240050		MARSHALL, W. H.	8006300423	50-329 Q	MATTIA,H J	8006030055*	CONTRACT
MADSEN, Q.L.	8006170284	50-278	MARSHALL, H R	8006270203	50-269 H	MATTIHOE, J, J.	8006030361	50-312 8
HADSEN, Q.L.	8006200510		MARSTON, T. U.	8006020208*	GEN TEC 18	MATTIA, M. J	8006060077*	CONTRACT
MADSEN, Q.L.	8006020527		MARTIN, H Q	8006090191	50-213 G	MATTIA, J C	8006240098*	50-352 G
HADSEN, Q.L.	8006050396		MARTIN, H Q	8006090160*	50-320 G	MATTIHOE, J J	8006030342	50-312 P
MADSEN, Q.L.	8006060053		MARTINELL, J B	8006020361	RES	MATTIA, H J	8006030529*	CONTRACT
MADSEN, Q. L. MADSEN, Q. L. MAEHR, G. R MAEULEN, S. MAGEE, H	8006230143 8006240184 8006240396* 8006300270* 8006250358*	50-128	MARTIN, H. G. MARTIN, T. T. MARTIN, R. D. MARTIN, R. MARTIN, R. D	8006090081# 8006060035# 8006170769# 8005050138 8006060568#	50-302 Q 50-302 Q 14E 50-302 Q	MATTIA: M. J MATTIA: M. J MATTIMOE: J. J. MATTIMOE: J. J MATTIA: M. J	B006090432* B006270391* B006110065 B006110131 B006180087*	CONTRACT CONTRACT 50-312 P 50-312 P CONTRACT
MAGEE, H	8006130103*	10CFR	MARTINELL, J S	8006020144	REB	MATTIA, M. J	8006240649*	CONTRACT
MAGEE, H.	8006260028*	10CFR	MARTIN, R. D.	800606050*	50-348 G	MATTIA, M. J	8006250210*	CONTRACT
MAGEE, H.	8006240206*	10CFR	MARTIN, R. D.	8006180036*	50-250 G	MATTIMOE, J. J	8006130339	50-312 G
MAIMON1, A	8006260053	NUREQ	MARTIN, J B	8006030098	ORO	MATTIA, M. J	8006180587*	CONTRACT
MAJUMDAR, D	8006260025	RES	MARTIN, H. Q	8006040045	70-135	MATTIA, M. J	8006200093*	CONTRACT
MAKEPEAGE, J. M.	9006160068*	50-247 B	MARTIN, L. E	8006050528*	50-482 G	MATTIA, M, J,	8006200137*	CONTRACT
MAKEPEAGE, J. M	9006190341*	50-247 B	MARTIN, H. O	8006050514	70-1143	MATTIA, M, J	8006250225*	CONTRACT
MALARD, J. C.	9006120237	50-201 P	MARTIN, H. O	8006030026	70-371	MATTIA, M, J	8006130337	50-312 1
MALLORY, G. H.	9003070261	71-9079	MARTIN, H. O,	8006050513	70-1143	MATTIA, M, J	8006130007*	CONTRACT
MALLORY, C. H.	9003070360	71-9089	MARTIN, H. O,	8006250013*	50-219 G	MATTIA, M, J,	8006180349*	CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESS ION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOURUS VROCETAD
MATTIAM J MATTIAM J MATTIAM J U.JONITTAM U.JONITTAM	8006250295# 8006230178# 8006250042# 8006240498 8006300394	CONTRACT CONTRACT CONTRACT 50-312 P 50-312 B	MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M	8004170141* 8006170157* 8006170141* 8006170141*	PRM PRM PRM PRM PRM	MEACHUM, T R MECCA, J E MECCA, J E MEDLOCK, R L MEDROW, L A K	8006020141 8006180189* 8006110249 8006120101 8006090429	RES 50-522 O NUREO 40-8452 CONTRACT
MATTIMOE, J J	8006300529	50-312 6	MC.YRRADDM	8006170157*	PRM	MEDROW, LAK	8006250206	CONTRACT
MATTIA, M J	8006160227*	CONTRACT	MC.YRRADDM	8006170141*	PRM	MEDROW, LAK	8006230170	CONTRACT
MATTHUELLER, F C	8006060442*	71-5607	MC.YRRADDM	8006170157*	PRM	MEDRAW, RE	8005220706	PR
MATTBON, R J	8006300201*	REGGD	MC.YRRADDM	8005230577	50-269 G	MEISS, RL	8006190573	PROJ
MATTBON, R J	8006300497	NUREG	MC.YRRADDM	8006120024	50-488 G	MENARD, HW	8006190407	70-2909
MATTSON,R J MATTSON,R J MATTSON,R J MATTU.R K MAUGHAN,F J	8006160233 8006200300 8006300341 8006090522 8006090106	080 50-320 H 080 NUREO 50-320 F	MCGARRY, J II MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M	8006120024 8006060267 8006060281* 8006060281*	50-488 Q 50-269 Q 50-269 Q 50-269 Q 50-269 Q	MENCINSKY, G J MENDELBON, I N MERRIWEATHER, N MERRILL, J A MERTZ, R L	8006020354 8006240649* 8006230336* 8006270362 8006200159	50-320 P CONTRACT 50-438 G NUREO 70-1359
MAURA.F MAURA.F MAXEY.W A MAXWELL.R.B MAXWELL.OF	8006130141* 8006200141* 8006270097 8006300457* 8006270231*	50-10	MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M	8006060286* 8006110205 8006110205 8006110297 8006110297	50-267 Q 50-367 Q 50-367 Q 50-488 Q 50-488 Q	MESSITT, B R MESSIER, M METILER, E R METZGER, J MEYERS, B L	8006060585* 8006230042 8006200064 8006250007* 8005300461	50-280 G 50-482 H FOIA State Pro 50-482
MAYER L O	8006020334	50-263 F	MCGARRY, J M	8006170423	70-2623	MEYER, J F	8006090493	50-247 F
MAYER, L O	8006020258	50-292 F	MCGARRY, J M	8006180517	50-267 ©	MEYER, J F	8006250280	50-247 F
MAYER, L O	8006050247	50-263 P	MCGARRY, J M	8006170423	70-2623	MEYER, J F	8006200553	50-247 F
MAYER, L O	8006070400	50-292 P	MCGARRY, J M	8006180517	50-267 ©	MIAD, C C	8006120476	NUREQ
MAYER, L O	8006050375	50-263 8	MCGARRY, J M	8006240143	50-488 ©	MICHEL, C J	8006230297	50-201 I
MAYER, L Q MAYER, L Q MAYER, L Q MAYER, L Q MAYER, L Q	8006060376 8006070278 8006130265 8006170486 8006170377	50-263 R 50-263 P 50-263 R 50-282 P 50-282 P	MCGARRY, J. M MCGARRY, J. M MCGARRY, J. M MCGARRY, J. M MCGAUGHY, R. W	9006240143 9006250251 9006250253 8006250253 9006250233*	50-488 0 50-488 0 50-367 0 50-367 0 50-367 0	Michelbon, C Michel, C. J Midura, H. J Midura, H. J Midura, H. J Midura, H. J	8006180099 8006180428 8006230454 8006160107 8006160009	50-206 70-143 50-272 50-272 50-272
MAYER, L O	8006170429	50-263 P	McGaughy, R W	8004090297*	50~387	MILHIEBER,R J	8006180391*	50-382
MAYER, L O	8006200466	50-263 S	McGaughy, R W	8006250174*		MILHIBER,R J	8006190313	50-382
MAYER, L O	8006180448	50-282 R	McGaughy, R W	8006250205*		MILLER,L C	8006230355	PR
MAYER, P E	8006200373	50-263 P	McGaughy, R W	8006250209*		MILLER,R P	8006030042*	CDNYRACT
MAYER, L O	8006230337	50-263 F	McGaughy, R W	8006240098*		MILLER,C F	8006270045	NUREO
MAYER,L D	8006230437	50-263 P	MCGAUGHY, J P	8004030375	50-416 R	MILLER, H J	8004040501*	40-8727
MAYER,L D	8006240266	50-263 F	MCGAUGHY, J P	8004110109	50-416 B	HILLER, W H	8004170228*	50-327
MAYER,L D	8006300493	50-262 B	MCGAUGHY, J P	8004110150	50-416 B	MILLER, L	8004180314*	50-206
MAYS,B E	8006020339	RES	MCGAUGHY, J P	8004110303	50-416 B	MILLER, D E	8004180381*	50-266
MCARTHUR,T C	8006180012*	50-324 Q	MCGAUGHY, J P	8004240343	50-416 B	MILLER, W O	8004180565	70-1257
MCBREARTY,R A	8006020257*	50-387	MCGAUOHY, J P	8006160103	30-416 8	MILLER, F	8004130290	70-623
MCBREARTY,R A	8006030090*		MCGAUOHY, J P	8006180239	50-416 8	MILLER, M I	8004170218	50-295
MCBREARTY,R	8006190278*		MCGAUOHY, J P	8006190577	50-416 8	MILLER, M I	8004170218	50-295
MCCABE.E C	8006050524*		MCGAUOHY, J P	8006180287	50-416 8	MILLER, H J	8004020542	Waste Mg
MCCABE.E C	80060600047*		MCGAUOHY, J P	8006240487	50-416 9	MILLER, T	8004170282	Fota
MCCABE.E C	8004030268*	50-334 Q	MCGAUGHY, J P	8006240384	30-416 B	MILLER, H J	8006030030	WARTE MO
MCCABE.E C	8006170814*	50-317 Q	MCGAUGHY, J, P	8006270284	50-416 B	HILLER, J. R	8006020032	50~170
MCCABE.E C	8004050063	50-317 S	MCGILL, B L	8006200588	Nureg	HILLER, T D	8006250117#	GA799
MCCABE.E C	8004090451	50-317 S	MCGOVERN, K B	8006050465	Pr	HILLER, M I	8006120263	50~255
MCCABE.E C	8004050413	50-317 S	MCGRATH, E J	8006120077	Waste Mgt	HILLER, M I	8006120263	50~255
MCCABE, E C	8004180412	50-317 S	MCGRAIL, B J	8006180407	PR	MILLER, W. O	8006070151	50-155
MCCABE, J M	8004110244	50-409 D	MCGRAIL, B J	8006200229	PR	MILLER, W. O	8006060586	40-299
MCCALLISTER, P	8004300455*	50-329 A	MCGREH, J. W	8006300630	71-5862	MILLER, D. W	8006020346	MISC
MCCARTHY, E	8004050550	State Prog	MCGRIFF, J H	8006030463*	50-327 8	MILLER, M. E.	8006020500	50-344
MCCARREL, B F	8004040343	50-344 P	MCGUIRE, W, F	8006030463	50-498 F	MILLER, W. O	8006020051	50-272
MCCARTHY.E	800&020224	State Prog	MCQUIRE.P J	8006180444	50-273 R	MILLER,W Q	8006020509	40-2259
MCCARTHY.E	800&250359	State Prog	MCQUIRE.P J	8006170640	50-273 R	MILLER,W O	8006030010	40-2259
MCCARREL.S F	800&240382	50-344 P	MCQUIRE.P J	8006070385	50-273 B	MILLER,H J	8006190365	40-1341
MCCABLAND.K G.	800&300414*	50-390 A	MCQUIRE.P J	8006250242	50-273 B	MILLER,H J	8006190369#	40-1341
MCCABLAND.K	800&300409*	50-390 A	MCQUIRE.P J	8006250244	50-273 B	MILLER,H,J	8006240243	Wate Ma
MCCLAIN,C M	8004200458*	50-219 R	MCQUIRE, P J	8006240471	50-293 8	MILLER, H. J	8006190058	40-1341
MCCLINTOCK,R. O	7903270178	FOIA	MCQUIRE, T J	8006240479*	50-293 8	MILLER, W O.	8006060051	50-566
MCCLINTOCK,J T	8004090094	PR	MCQUIREN, H J	8006030139	50-498 0	MILLER, H J.	8006230168	Wabte M
MCCLURE,J. D.	8004020225*	State Prog	MCKEOWN, L M,	8006270245*	50-317 0	MILLER, L R.	8006200539	50-264
MCCOLLIGAN,J V	8004140010	50-312 8	MCKEOWN, L M	8006300602*	50-54 0	MILLER, W. O	8006120465	50-316
MCCORKLE, Q. H MCCORKLE, Q. H MCCORKLE, Q. H MCCORKLE, Q. H MCCORKAC, J. B	8006240653# 8006170073 8006020586 8006050486 8006130032	FOIA 70-754 50-217 P 50-213 P 71-15	HCKIBBEN, J C HCKIBBEN, J C HCKLYEEN, J W HCKNIGHT, T R HCLENDON, O, D	8006110137 8006110064 8006130170 8006200606 8006050297	50-186 8 50-186 8 40-8752 71-9138 50-382 G	MILLER, W. O MILLER, W. O MILLER, M. E. MILLER, M. E MILLER, J. R	8006200595 8006200600 8006030080 8006030060	70-27 70-824 PR PR 50-223
MCCORKLE, O W MCCULLOCK, R N MCCULLOUGH, E R MCDONALD, J A MCDONALD, D D	8004300001 8004270045 8004300487* 8004030593* 8004120518	70-754 NUREQ 50-10 H 50-390 G FOIA	MCLOUGHLIN, M T MCLOUGHLIN, M T MCLOUGHLIN, M T MCMULLEN, R, B. MCNAMARA, A E	B004070391* B006250243* B006250246* B004030557* B00614003B*	50-273 8 50-273 8 50-273 8 50-273 8 50-344 6 50-244 R	MILLER, J MILLER, M E MILLER, W. O MILLER, W O. MILLER, L. C	8006110310 8006060293 8006170309 8006180604 8006110366	50-416 50-344 50-315 50-516 Nureo
MCDONOUGH, M D	8004200274	XPORTLIC	MCNEILL, H M	8006070122*	GA999	MILLER, W O	8006250148	70-364
MCDOUGALL, A J	8004180349*	CONTRACT	MCNEILL, H, M	8006240107*	GA999	MILLER, W. O	8006230006	70-135
MCDOHELL-BOYER	8004200023	RES	MCNEILL, R L	8006110046*	50-361 Q	MILLER, W. O	8006170841	50-324
MCDUFFIE, M A	8004190444	50-400 G	MCNEIL, J, E,	8006260204	XPORTLIC	MILLER, W. O.	8006180034	50-267
MCDUFFIE, M A	8004240285	50-400 Q	MCNEIL, J, E	8006260208	XPORTLIC	MILLER, W O	8006240573	50-267
MCDUFFIE, M. A	8006160145	50-400 A	MCNEIL; J E	8006760204	XPDRTLIC	Miller, W O	8006240596	50-324
MCFARLAND, C. F.	8006160176*	50-280 Q	MCNEIL; J E	8006260208	XPORTLIC	Miller, W, O.	8006260244	70-824
MCFARLAND, C. R	8006070473*	50-250 Q	MCDBCAR; J J	8006030110*	50-29 Q	Miller, M E	8006160126	70-262:
MCFARLAND, J E	8006200137*	9A999	MCPHILLIPS; J,	8006160146	70-2909	Miller, L, X	8006160012*	50-272
MCGARRY, J. M	8006170133	PRM	MCPHILLIPS; J,	8006160150*	70-2909	Miller, M I.	8006190524	50-255

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION R3EMUN	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER, G M MILLER, M I MILLER, J R MILLER, K L MILLER, K L	8006170273* 8006190524 8006300443 8006270220* 8006250224	50~389 M 50-255 9 TOPREP 50-320 9 50~320 G	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8006190391 8006190615 8006200321 8006200375 8006200432	50-327 K 50-327 P 50-327 P 50-327 P 50-566 S 50-518 S	MOON, J MOON, B T MOORE, P MOORE, T P MOORE, G C	8006030347* 8006300278* 8006170240 8006270038 8006170760	50-244 P 50-364 Q PR NUREQ 50-302 Q
MILLER, M I MILLER, M I MILLER, W O MILLER, C F MILLER, C	8006300513 80063000513 8006300045 8006300504 8006300514*	50-255 G 50-255 G 50-313 P NUREG NUREG	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8006230514 8006240323 8006240328 8006240372 8006240405	50-259 P 50-327 P 50-327 S 50-327 S 50-438 A	MOORE, O W MOORE, J S MOORE, P D MOORE, R N MOORE, G W	8006060391* 8006240101* 8006250110* 8006040106	50-334 R GA999 GA999 XPCRTLIC 50-334 R
MILLER, C MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8006300520* 8006180232 8006120286 8006030608* 8006180072*	NUREO 70-1966 40-1341 50-553 G 50-518 G	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8006240453 8006260160 8006240377 8006240390 8006250252	50-390	MOORE R N MOORE, J E MOORE, J E MOORE, J E MORATEZ, P	8004250001 8004240505 8004270227 8004270233* 8004170441	XPORTLIC 50-272 G 50-272 G 50-272 G 50-275 H
HILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8006040256* 8006040245* 8006040007 8006060119 8006170211*	50-566 Q 50-566 Q PR PR 50-327 Q	MILLB.L M MILLB.L M MILLB.L M MILLB.L M MILLB.L M	8006250257 8006250275 8006260164 8006240472 8006250198	50-553 8 50-518 8 50-327 F 50-327 P 50-370 8	MORIARTY, J M MORRIS, R H MORRIS, R H MORRIS, S W MORRIS, R H	8006200012 8006060457* 8006060462* 8006020336 8006120305	50-395 B 50-70 P 50-70 P 50-352 H 50-70 P
MILLS.L M MILLS.L M MILLS.L M MILLS.L.M MILLS.L.M	8006180064* 8006030604* 8006250053 8006250062 8006110263	50-518 Q 50-553 Q 70-2910 50-391 A 50-438 S	MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8006250227 8006250234 8006250256 8006270206 8006270269	50-43B B 50-390 S 50-51B B 50-390 G 50-259 P	MORROW, D MORROW, D MORROW, D MORROW, A MORTON, K V	8006300260* 8006120504 8006300118 8006170125 8006090459*	50-271 H 40-8502 40-8502 50-409 G CONTRACT
MILLS, L, M MILLS, L, M MILLS, L, M MILLS, L, M MILLS, L, M	8006120037* 8006130004 8006120113 8006170746* 8006270197*	50-43B	MILLB, L M MILLB, L M MILLB, L M MILLB, L M MINEGK, D L	8004300387 8004300371 8004300430 8004300248 8004110335	50-327 P 50-390 A 50-328 P 50-327 P 50-331 S	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8005250054* 8005030042* 8005250051 8005250045* 8006120415*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLB, L M MILLB, L M MILLB, L M MILLB, L, M MILLB, L M	8005230276 8006240164* 8006240258* 8006020338 8006070456	50-327 P 50-259 Q 50-259 Q 50-438 A 50-518 Q	Mineck, D L Mineck, D L Mineck, D L Mineck, D L Mineck, D L	8004030297 8004030299 8004030467 8004090339 8004090371	50-331 8 50-331 8 50-331 8 50-331 8 50-331 6	MORTON, K H MORTON, K V MORTON, K V MORTON, K V MORTON, K V	8006190109 8006190267# 8006230164# 8006030049# 8006190276#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8006250144* 8006230033* 8006230267* 8006030392 8006030417	50-259 Q 50-390 Q 50-327 Q 50-328 6 50-327 P	Mineck, D L Mineck, D L Mineck, D L Mineck, D L Mineck, D L	8004170658 8004180400 8006230432 8006170461 8006270258	50-331 8 50-331 F 50-331 8 50-331 R 50-331 8	MORTON, K V MORTON, K V MORTON, K, V MORTON, K V MORTON, K V	8006190252* 8006200078* 8006240246* 8006230034 8006230124*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLB, L M MILLB, L M MILLB, L M MILLB, L M	8006050002 8006110274 8006020176 8006040230 8006040306	50-566 8 50-566 8 50-327 P 50-518 8 50-328 8	Mineck, D. L. Mineck, D. L. Miner, B. Minnerg, W. Minoque, R. B.	8006270264 8006270271 8006030071 8006300580 8006030118	50-331 8 50-331 8 50-315 F State Prog 8ECY	MORTON, K V MOBCHNER, R A MOSIYNBKI, J R, MOHRY, W R MOWRY, W, R	8006230133* 8006190184 8006190070 8006040252* 8006040258*	CONTRACT 70-754 RES 70-2523 SECY
MILLB, L M MILLB, L. M MILLB, L M MILLB, L M MILLB, L M	8006050026 8006050076 8006030366 8006060270 8006060383	50-327 8 50-391 F 50-438 A 50-390 8 50-438 8	Minoone, R B Minoque, R B Minoque, R, B Minoque, R B Minoque, R B	8006130091* 8006170807* 8006020004 8006130075* 8006250373*	10CFR REQOD PR ORO REOOD	MOURY, W. R. MOURY, W. R. MOURY, W. R. MRDCZKA, E. J.	8004040254* 8004040262* 8004040264* 8004200565 8004170464	SECY 70-2523 SECY 70-734 50-245 H
HILLS, L M HILLS, L M HILLS, L M HILLS, L M	8006060484 8006060235 8006060274 8006060313 8006060401	50-390 8 50-259 F 50-327 F 50-259 F 50-518 8	MINGOUE,R B MINGOUE,R B, MIRANDA,J E, MITCHELL,D,O MITCHELL,D O	8006200645* 8006300399* 8006260043 8006060409* 8006200496*	REGQD 50-367 & NUREO 50-289 & 50-289 R	MROCZKA, E J. MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8006110248 8006170657 8006170438 8006240387 8006230506	90-334 8 50-334 8 50-245 R 50-245 8 50-336 R
MILLB, L M MILLB, L M MILLS, L M MILLB, L M MILLB, L M	8006070330 8006070334 8006070471 8006230327* 8006080370	50-327 6 50-438 8 50-438 8 50-438 9 50-553 A	MITCHELL.D O MIYABAYASHI,M MIYABAYASHI,M MIYABAYASHI,M MIYABAYASHI,M	8006300478* 8006120249 8006120505 8006240120 8006240275	50-289 B XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MUCHNICKI,E D MUENCH,O W MULLER,R E MULLER,D R MUNNO,F J	8006110406 8006300368 8006130236 8006020521 8006300130	PR 50-556 A XPORTLIC 50-320 P NUREG
MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8004110034 8004110074 8004110284 8004110328 8004110048	50-370 8 50-438 8 50-257 P 50-438 8 50-518 8	MIYABAYASHI, M MIYABAYASAL, M MODENOS, L MOHR, C, L MOLNAR, J	8006240277 8006240654 8006160206* 8006260038 8006060163*	XPORTLIC XPORTLIC 50-390 G NUREO 50-219 8	MURPHY, C, E MURPHY, C, E, MURPHY, C, E, MURPHY, C, E, MURPHY, C, E	8004020002 8004050095 8004020573 8004170215* 8004030078	50-241 0 50-566 0 50-324 0 50-327 0 50-302 0
HILLS,L M MILLS,L M HILLS,L M MILLS,L M MILLS,L H	8006110138 8006120309 8006230488 8006120282 8006110259	50-438 8 50-518 8 50-438 8 50-438 A 50-327 K	MOMENI, J B MOMENI, M. H MONDEN, T MONEY, O F, MONTODMERY, O V	8006300032 8006260043 8006190026 8006030153 8006120221	40-665 NUREO XPORTLIC 40-8502 PR	MURPHY, C, E MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8006070422* 8006030478 8006050415 8006120039* 8006030068*	50-321 0 50-518 0 50-553 0 50-438 0 50-364 0
HILLB.L H HILLB.L M HILLB.L.H HILLB.L.H HILLB.L.H	8006170485 8006170525 8006170596 8006170605* 8006130246	50-438 S 50-390 S 50-390 S 50-390 B 50-390 G	MONTOCMERY, D. M MONTI, W. A MONTOYA, D. F MOODY, D. E MOODY, D. E	8006170185# 8006170431 8006130212 8006170739# 8006230440#	50-250 Q 50-3 R FOIA 50-307 Q 50-307 Q	MURPHY, C E MURPHY, C, E MURPHY, C E MURPHY, P M MURPHY, P M	8006130056# 8006170751# 8006270207# 8006060469 8006060465	50-413 Q 50-564 Q 50-438 Q 50-255 Q 50-255 Q
HILLE, L M HILLE, L, M MILLE, L, M MILLE, L, M MILLE, L M,	8006170582 8006240260 8006160054 8006170540 8006130307	50-327 G 50-327 G 50-390 G 50-366 G 50-327 F	MOODY, D E. MOODY, D, E MOODY, D E MOODY, D E MOODY, D, E	8006230379# 8006230379# 8006060503 8006030028 8006240590	50-309 (1 50-309 (1 50-29 (1 50-29 F 50-29 (1	MURPHY, C. E.	8006050423 8006180068* 8006030606* 8006070144* 8006130035	50-389 0 50-518 0 50-553 0 50-491 0 50-335 0
MILLE, E M, MILLE, E, M MILLE, E, M MILLE, L, M MILLE, L M	8006170545 8006170659 8006170385 8006170466 8006170586	50-328 S 50-328 S 50-370 S 50-553 G 50-327 G	HOODY, D, E HOODY, D E HOODY, D E HOODY, D, E	8006170241 8006170687 8006170236 8006170636 8006230376	50-309 P 50-309 R 50-29 P 50-29 R 50-29 F	MURPHY, C. E	8004140170 8004140200 8004170779 8004170789 8004090470	50-280 G 50-390 G 50-321 G 50-389 G 50-250 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCEBSION NUMBER	EUBJECT CATEODRY
MURPHY, C E	8006130042 8006230114* 8006230273* 8006090066 8006160216	50-424 50-280 50-327 50-280 50-395		NALEPKA, D S NAPUDA, Q NARBUT, P P NARBUT, P P NARROW, L	8006200473* 8006200043* 8006090503* 8006060141* 8006250205*	50-305 50-334 50-312 50-440 50-322	5 9 9	MIX.R T MIX.R T MIX.R T MIX.R T MIXON.W A	8006200483* 8006240436* 8006240455* 8006240514* 8006180584	50-366 8 50-366 8 50-366 8 50-366 8
MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E	8006170262 8006230331* 8006120128 8006180386 8006180373	50-302 50-438 50-370 50-416 50-328	G G G G	NARROW, L NABH, D A NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8006250209* 8006090226* 8006030309 8006020347 8006030062	50-412 50-409 50-454 50-295 50-10	Q O H P P	NIXON,W A NOCELLA,B J NORDERHAUG,L R NORDERHAUG,L R NORDERHAUG,L R	8006040124 8006270012 8006250068 8006180377 8006170846	70-135 F01A 50-275 8 50-275 0 70-734
MURPHY,C E MURPHY,C E MURPHY,P M MURPHY,P M MURPHY,C E	8005200105 8005170246 8005120263 8005120263 8005250212	50-338 50-390 50-255 50-255 50-390	G G G G	NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NEELY, D R	8004070254 8004110040 8004070305 8004270327 8004300223	50-295 50-454 50-295 50-295 50-277	P A P B	NORELIUB, C E NORRHOLM, L J NORRHOLM, L J NORRHOLM, L J NORTH, H, 8	8006300156* 8006180056* 8006180126* 8006160231 8006250112*	50-341 q 50-272 q 50-272 q 50-272 S 50-275 q
MURPHY, J D MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	8006130044 8006230367* 8006260353* 8006300267 8006040013	71-9071 50-369 50-416 50-335 50-250	a a a	NEHEMIAS, J V NEISLER, J H NELSON, J D NELSON, R NELSON, R L	8006090219* 8006240041* 8006040173 8006170295* 8006200097*	50-409 50-373 WABTE MG 50-295 50-305	G G G G	NORTON, B NORTON, B NORTON, B NOBENZO, L V NOBENZO, L V	8006040519* 8006110417 8006110417 8006120430* 8006050532	50-275 H 50-275 0 50-275 0 SECY XPORTLIC
MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E MURPHY.C E	8006040232 8006270222* 8006300237 8006030602 8006090182	50-566 50-413 50-280 50-553 50-400	() () () () ()	NELBON, R NELBON, C C NELBON, H W NEUMANN, M R	8006260077* 8006130106 8006240113 6006180247 8006060089	50-305 50-309 50-70 50-281 40-8697	G P P P	NOBENZO: L. V NOBENZO: L. V NOBENZO: L. V NOBENZO: L. V NOBENZO: L. V	8006130185 8006060079 8006060083 8006060087 8006120473*	XPORTALIC XPORTALIC XPORTALIC XPORTALIC SECY
MURPHY, C E MURPHY, C E MURPHY, C E. MURPHY, C E MURPHY, C E	8006180061 8006300322* 800612003 8006200166* 8006090408	50-518 50-395 50-438 50-364 50-321	0 0 0 0	NEUMANN, M R NEUMANN, M R NEUMANN, M R NEWACHECK, R L NEWCOMB, C	8006190344 8006190670 8006240271 8006190298 8006300393*	40-8380 40-8380 40-9380 50-228 50-367	F U	NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	8006120477* 8006120482* 8006030056 8006030061	SECY SECY XPORTL IC XPORTL IC XPORTL IC
MURPHY, C E MURPHY, C E MURPHY, W J MURPHY, C E MURPHY, C E	8006090428 8006170193 8006190160 8006130050 8006180567	50-416 50-927 XPORTLIC 50-413 50-559	0 G G	NEWMARK, N K NEWMARK, N K NEWMAN, J R NEWMAN, J R NEWMAN, J R	8006200046 8006200050* 8006120030 8006120030 8006040478	70-754 70-754 50-466 50-468 50-498	G G O	NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8004030114 8004030114 8004170120 8004230114 8004040201	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MURPHY, H P. MURPHY, H P MURPHY, C E MURPHY, C, E. MURPHY, C E	8006030329 8006030333* 8006170740 8006230249 8006120303*	50-271 50-271 50-566 50-327 50-316	5 G Q S	R. INAMUSH R. INAMUSH R. INAMUSH J. INAMUSH R. T. INAMUSH R. INAMUSH	8004040478 8004050095 8004050085 8004120097 8004090204	50-498 50-466 50-466 50-466 50-466	0000	NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	8006060203 8006070080 8006070424 8006170075 8006120507	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MURPHY, C E MURPHY, C E MURPHY, C E MURPHY, C E	900620099 8700623008 900623008 900623008	50-327 50-260 50-255 50-390 50-438	G G G	NEWMAN, J R. NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8006120061 8006120064 8006120068 8006070204 8006120061	50-466 50-466 50-466 50-466 50-466	0000	NOBENZO, L. V, NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V	8006120078 8006250287 8006260032 8006260034 8006260036	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MURPHY, C E MURPHY, C E MURPHY, M J MURPHY, M J MURPHY, H P.	8006240566 8006270191 8006170578* 8006170671* 8006170589	50-302 50-438 50-272 50-272 50-271	0 0 5 8 8	NEUMAN, J R NEUMAN, J R NEUMAN, J R NEUMAN, J R	8004120044 8004120048 8004120097 8004120417 8004170409	50-466 50-466 50-466 50-466 50-466	0	NOBENZO, L. V NOBENZO, L. V NOBENZO, L. V, NOVAK, T. M NOVAK, T. M	8006260047 8006260050 8006260052 8006300188 8006060013	XPORTLIC XPORTLIC XPORTLIC REGOD 50-147 9
MURPHY, W P. MURPHY, P M MURPHY, P M MURPHY, M J MURPHY, M J	8006170575* 8006190524 8006190524 8006230535* 8006240447*	50~255	S 0 0 8 6	NEWAN, J R NEWAN, J R NEWAN, J R NEWAN, J R	8006170609 8006180346 8006180346 8006240341 8006240341	50-466 50-466 50-466 50-466 50-466	0	NOVAK, T. M. NOVAK, T. M. NOVAK, T. M. NOVARRO, J. P.	8006250006 8006240121 8006250355 8006300319 8006300267	50-338 P 50-366 P 50-289 0 50-313 0 50-322 0
MOKENA'N 6 WANGENA'N A WANGENA'N W WANGENA'N A	8006240472* 8006300513 8006300513 8006300487* 8006130145*	50-255	B 0 0 8	R L MAMHEN B L MAMHEN B L MAMHEN B L MAMHEN B	8006270327 8006270327 8006300307 8006300317 8006300323	50-466 50-466 50-466 50-466 50-466	0 0 0	NOVARRO, J. P. NOVARRO, J. P. NOWRY, W. R. NUGENT, E. L. NUGENT, E. L.	9006170261 9006170601 8006120279 9006170254 9006180474	50-322 A 50-322 G XPORTLIC 40-2259 40-2259
MURRAY, J P. MURRAY, J P. MURRAY, J P. MURRAY, T D. MURRAY, J P.	8006130148* 8006130152* 8006130144* 8006020495 8006230180*	FOIA FOIA FOIA 71-9081 50-272	o	NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R.	8004300340 8004300307 8004300317 8004300323 8004300340	50-466 50-466 50-466 50-466 50-466	0	NUGENT, E L NYGAARD, O R O'BRIEN, J, P, O'CONNELL, J, M, O'HANLON, J P	8006170585 8006170125 8006250184* 8006070315 8006230412	40-2259 50-409 9 50-312 9 50-320 J 50-316 8
MURRAY, T D. MURRAY, T. D MURRAY, R MURRAY, T D. MURRAY, T D.	8006120192 8006090554 8006110369* 8006120354 8006120343	50-346	8 8	NICHOLBON, P NICHOLBON, P NICHOLBON, P NICHOLBON, P	8006190079 8006200545 8006300060* 800611003D* 8006240468	RE6 50-458 50-322 50-285 50-389	M 0 8 M	O'HANLON, J. P D'HALLEY, C. M D'NEILL, J O'NEILL, J. H. O'NEILL, J. H	8006230530 8006060562* 8006120058 8006170399 8006170399	50-388 8 50-320 9 50-155 9 50-288 9 50-288 9
MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T. D	8006120345 8006120350 8006130274 8006160082 8006170351	50-346 50-346 50-346	8 8 8	NICHOLBON, P NICODEMUS, M L NIENAUS, P W. NIMITZ, R L NIMITZ, R.	8004240473* 8004200573 8004040213* 8004270404* 8004040337	50-389 NUREQ QA999 50-219 50-219	M G G	G'REILLY, J P G'REILLY, J, P G'REILLY, J, P G'REILLY, J, P G'REILLY, J P	8006130096* 8006130086* 8006170762* 8006180045 8006200092	50-333 6 50-255 6 50-302 0 50-416 0 50-324 0
MUSCHOL, E MUSE, L. A MYNATT, F. R. MYRABO, A. L. MYRABO, A. L.	8006300585* 8006050454 8006230096 8006060398* 8006130267*	PRM 71-389 RES 50-263 50-263	R R	NIMITZ, R. L NIX, R. F. NIX, R. F NIX, R. T. NIX, R. T.	8006270090* 8006030445* 8006050340* 8006050355* 8006050372*	50-219 50-366 50-366 50-366 50-366	8 8 8 G	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	800620095 800620098 8006250250* 8006300532*	50-321 0 50-259 0 50-321 0 50-321 0 70-27
NAGAI, Y. NAGAL, Y. NAIDU, K. NAIDU, K. R. NALEPKA, D. S.	8006190604 8006090335 8006200124# 8006170776# 8006200469#	50-217 50-461 50-456	P G G S	NIX.R.T NIX.R.T NIX.R.T NIX.R.T NIX.R.T.	8006170680* 8006170687* 8006190619* 8006200474* 8006200461*	50-321 50-366 50-321 50-366 50-321	5 5 5 6 5 6 5 6 5	O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P O'REILLY, J.P.	8004040159 8004040414 8004040418 8004040427 8004040434	50-327 Q 50-348 Q 50-339 Q 50-369 Q 50-437 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8006060437 8006060448 8006060458 8006060485 8006060488	50-414 G 50-344 G 50-400 G 50-395 G 50-395 G	OPREA, O W OPREA, O W, ORDERB, W T OSTRANDER, F W OSTRANDER, F W	8006180370 8006300435 8006060182* 8006060533 8006060537*	50-498 K 50-498 B 50-269 G 50-344 G 50-344 G	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8006170637 8006240282 8006270219 8006170229 8006170458	50-369 B 50-413 Q 50-413 Q 50-269 P 50-269 P
O'AEILLY, J P	8006060493	50-488 Q	OSTRANDER, F W	8004040544*	50-344 0	PARKER, W O	8006170523	50-269 8
O'REILLY, J P	8006060498	50-424 Q	OTTOSON, H L	8004040297	50-206 9	PARKER, W O	8006300170	50-269 0
O'REILLY, J P	8006060500	50-387 Q	OTTOSON, H L	8004030430	50-206 8	PARKER, W O	8006300478	50-269 P
O'REILLY, J P	8006060510	50-267 Q	OTTOSON, H L	8004030420	50-206 8	PARKER, W O	8006300213	50-269 0
O'REILLY, J P	8006060515	50-280 Q	OTTOSON, H L	8004030513	50-206 8	PARKER, W O	80063004465	50-269 P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004040535 8004060549 8004060575 8004060583 8004090058	50-302 G 50-250 G 50-321 G 50-261 G 50-259 G	OTTOSON, H L OUZTS, J E OVERLID, T W OWEN, R F OWEN, R F OWEN, R F	8006120286 8006230313 8006300266* 8006200472* 8005210116	50-204 S 50-204 B 50-324 G 50-263 S 50-546 H	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8006240506 8006240411 8006240209 8006240485 8006260174	50-270 8 50-413 B 50-269 F 50-369 A 50-269 B
O.WEIFTA'N b O.WEIFTA'N b O.WEIFTA'N b O.WEIFTA'N b	8006040226 8006040244 8006040248 8006040261 8006040267	50-321 0 50-416 0 50-280 0 50-337 0 50-259 0	OWEN.R H OWEN.W H OWENB.P.L OWBLEY.O.F OHBLEY.O F	8006120288 8006270268 8006130342 8006250100 8006240424	50-409 G NUREO State Prog TOPREP TOPREP	PARKER, W O PARMENTER, F	B006260169 B006260233 B006300362 B006300406 B006120056	50-287 S 50-269 P 50-269 P 50-269 P 50-269 M
O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J, P	8006040274 8006040275 8006040355 8006050286 8006050287	50-389 Q 50-369 Q 50-488 Q 50-250 Q 50-302 Q	PADDOCK, K M PAGE, R G PAGE, R. G PAGE, R G. PAGE, R G	8006300136 8006190732 8006190745* 8006190744 8006040050	71-6400 70-820 70-2709 70-2709 70-734	PARMENTER, F PARMENTER, F PARMENTER, F PARMENTER, F PARR, O D	8006060472 8006180187 8006160163 8006170007* 8006070146	50-445 M 50-445 M 50-445 M 50-445 M TOPREP
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8004050287 8004050291 8004050275 8004050300 8004050302	50-261 G 50-348 G 50-269 G 50-285 G 50-437 G	PAGE,R.G. PAGE,R.G. PAGE,R.G PAGE,R.G PAGE,R.G	8004070347 8004070378 8004120234 8004020551 8004300048	70-734 70-143 40-2061 70-27 70-27	PARRIR Q PARRYIJ, C PARBONBIW. D PARTLOWIJ Q PARTLOWIJ Q	8006190252* 8006090384* 8006170437 8006230147 8006040135	CONTRACT 50-344 S 50-407 D 70-820 70-1201
O'REILLY, J. P	8004050305	50-395 G	PAGE, R.O.	8005300214	70-820	PARTLOW, J G	8005300227	70-1143
O'REILLY, J. P	8004050307	50-395 G	Pahna, B.B.	8005270002	NUREO	PARTLOW, J G	8005200515	70-1257
O'REILLY, J. P	8004050309	50-364 G	Pallob, M.G.	8005200084	PT21	PARTLOW, J G	8005170301	70-143
O'REILLY, J. P.	8004050311	50-324 G	Panetta, L.E.	8005230463	50-275 H	PARTLOW, J G	8005300155	70-1257
O'REILLY, J. P	8004120034	50-257 G	Pankaskie, P.J	8005070502	NUREO	PARTLOW, J G	8005230207	70-1193
O'RETLLY,J.P	8006300074	50-348 G	PAGLINO, R	8006250186*	50-287 Q	PARTLON, J G.	800&170352	70-1193
O'RETLLY,JP,	8006300075	50-416 Q	PAGLINO, R, J.	8006250205*	50-322 Q	PARTLON, J Q	800&2&0230	70-364
O'RETLLY,JP,	8006300079	50-437 G	PAGLINO, R.	8006250182*	50-287 Q	PARTLON, J G	800&2&0237	70-371
O'RETLLY,JP	8006300083	50-302 G	PAPAY, L. T.	8006180301*	50-204 Q	PARTLON, J G	800&300534	70-1100
O'RETLLY,JP.	8006300087	50-375 Q	PAPAY, L. T	8006060337	50-361 B	PARTLON, J G	800&300283	70-143
O'REILLY,J P.	B004300090	50~375	PAPAY,L.T	8006060359	50-361 8	PASTERNAK,R J	8006020076*	50-333 0
O'REILLY,J P	B004300107		Papay,L.T.	8006190440	50-361 8	PASTERNAK,R J	8006020081*	50-333 0
O'REILLY,J P.	B004300110		Paperiello,C.J.	8006020061	14E	PASTERNAK,R J	8006030246	50-333 0
O'REILLY,J P.	B004300119		Paperiello,C.J	8006060115	14E	PASTERNAK,R J	8006240013	50-333 0
O'REILLY,J P.	B006300123		Pappag,H	8006200057	50-10 0	PASTERNAK,R J.	8006020308	50-333 8
O'REILLY,J P O'REILLY,J.P. O'REILLY,J.P. O'REILLY,J.P	8006300128 8006300137 8006270411 8006240107 8006300519	50-261	PARIB, O H PARKER, W O, PARKER, W. O PARKER, W. O, PARKER, W. O	8006060463 8006120137* 8006050337 8006120134* 8006030130	50-466 0 50-370 0 50-413 8 50-370 0 FR	PASTERNAK,R J PASTERNAK,R J PASTERNAK,R. J PASTERNAK,R. J PASTERNAK,R. J	8006020355 8006020347 8006020372 8006020393 8006020391	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8
D'TOOLE, J. D.	8006130294	50-247 P	PARKER, W. O.	8006200562	50-269 P	PASTERNAK, R. J.	8006020412	50-333 8
DAK. H. D.	8006280171	NUREQ		8006200065	70-2623	PASTERNAK, R. J.	8006110181	50-333 R
DBERG. C. R.	8006030528*	50-482 Q		8006240117*	50-269 0	PASTERNAK, R. J.	8006110006	50-333 8
DBERG. C. R	8006030225*	50-458 Q		8006050343	50-269 8	PASTERNAK, R. J.	8006110016	50-333 8
DBERG. C. R	8006060131*	50-462 Q		8006020548	NUREO	PASTERNAK, R. J.	8006110069	50-333 8
DDEGAARDEN, R. H.	8006040039#	71-7001	PARKER, W. O	8006040217	50-269 P	PASTERNAK,R J	8006180500	50-333 8
DESTMANN, K. J.	8006300033#	50-341 q	PARKER, W. O.	8006130053*	50-413 Q	PATON,H.D.	8006160073	50-367 8
DESANIK, H. J.	8006030070	XPDRTLIC	PARKER, W. O.	8006180254	50-269 Q	PATON,U D	8006180302	50-327 0
DEDEN, D. H	8006260035	RES	PARKER, W. O.	8006050241	50-270 S	PATON,H D	8006240505	50-272 0
OGDEN, D. H	8006180026	RES	PARKER, W. O.	8006090560	50-369 Q	PATON,H D	8006270233*	50-272 0
OHKI.A.	8006200333*	50-320 P	PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. FARKER, W. O.	8006060345	50-369 A	PATTERSON, J P	8006050410*	70-27
DLEBEN.D E	8006230022*	70-984		8006070266	50-369 A	PATTERSON, J D.	8006300511	PR
OLEBEN.D E.	8006230019	70-984		8006020341	50-287 S	PATTERSON, J P	8006230043*	50-266 0
DLER.R.E.	8006040010*	QA999		8006180237	50-369 G	PAUL, R A	8006230024*	50-10 0
DLBEN.A.F.	8006250011	70-824		8006040278	50-269 B	PAHLICKI, S. S	8006070832	50-301 8
OLSEN, A. F.	8004250208	70-824	PARKER, H O PARKER, R. A. PARKER, W. O PARKER, H. O PARKER, H O	8006050361	50-270 P	PEARLMAN, J	8006180582	CONTRACT
OLSEN, A. F.	8004200165	70-824		8006200586	71-102	PEARL, W. L	8006250143*	50-33B P
OLSEN, A. F.	8004180142	70-824		8006050108	50-269 F	PEAVER, R C	8006170246	PR
OLSEN, A. F.	8004180378	70-824		8006060364	50-269 P	PECK, C. C	8006170168*	50-320 Q
OLSEN, A. F.	8004040089	70-824		8006090343	50-413 S	PECK, C. C	8006180082*	50-320 Q
OLBEN, A. F	8006050157	70-824	PARKER; W. O.	8006110144	50-267 P	PEGK.C C	9006170064*	70-1308
OLBEN, A. F	8006250156	70-824	PARKER; W. O.	8006110351	50-267 P	PEGK.C C	9006160257*	50-243 G
OLBEN, A. F	8006270067	70-824	PARKER; W. O.	8006130322	50-267 P	PEGK.G.H.	9006190478*	50-244 B
OLBHAN, L	8006020172	50-247 P	PARKER; W. O.	8006110101	50-267 8	PEERY,W W	9006170371*	50-277 G
OLBHAN, L. N.	8006240165	50-245 P	PARKER; W. O	8006110321	50-270 8	PEERY,W.W	9006170796*	50-247 G
OLBON, J. F.	8006170715	PR	PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O	8006110354	50-367 A	PEERY, W. W.	8006180624*	70-687
OLBON, R. G.	8006190530	50-317 P		8006230360	50-369 Q	PEERY, W. W.	8006200564*	40-672
OLBON, R. G.	8006240339	50-317 Q		8006300016	50-369 Q	PEERY, W. W.	8006180093*	50-273 Q
OPEKA, J. F.	8006020386	50-336 B		8006110091	50-287 B	PELTIER, I.	8006020122	50-358 A
OPEKA, J. F	8006060275	50-336 B		8006110327	50-369 A	PELTIER, I	8006200575	50-358 A
OPREA, O. H.	8004030018	50-498 Q	PARKER, W. D	8006120367	50~369 A	PELTIER, I	8006230168	50-358 A
OPREA, O. H	8004030023	50-498 Q	PARKER, W. O	8006130283	50-269 8	PENDERORAFT, R	8006090394*	50-348 8
OPREA, O. H.	8004030172	50-498 G	PARKER, W. O	8006240248	50-269 G	PENDERORAFT, R	8006230457*	50-348 8
OPREA, G. H.	8004180373*	50-498 K	PARKER, W. O	8006160032	50-270 P	PENDERORAFT, R	8006190589*	50-348 R
OPREA, G. H.	8004240272	50-498 B	PARKER, W. O.	8006160074	50-269 F	PENDERORAFT, R	8006200363*	50-348 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY
PENDERGRAFT, R PENGOV, C A PEGPLES, D L PEGPLES, D L PEGPLES, D L	8006200434* 8006040189 8006200555 8006240274 8006120125	50-348 S 71-5796 70-2609 70-2609 PR	PETERSON, M R	8006180597 8006200207 8006230074 8006230001 8006180259	XPORTLIC XPDRTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET, M S	8002150044 8006170130* 8006250371 8005280077* 8006180556*	ACRS SECY ACRS 50-437 O 50-437 O
PEOPLES. D L	8006180550* 8006020071 8006090047* 8006090048 8006180552*	50-373 Q FR 50-456 Q REGGD 50-373 Q	PETERBON M R PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8006180270 8006240004 8006250070 8006250022 8006250024*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET, M S	8005280074 8004030584 8004300441 8004050475 8004070004*	50-437 D COMMISSION ACRS ACRS 50-489 D
PEOPLES: D L	8004200104 8004020008 8004260312* 8004230318* 8004070274	REGOD 50-237 0 50-454 0 50-454 0 50-295 F	PETERSON, MR PETERSON, MR PETERSON, MR PETERSON, MR PETERSON, MR PETERSON, MR	8006170747 8006180204 8006180214 8006180066 8006180071	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET.M S PLESSET.M S PLESSET.M S PLESSET.M S PLESSET.M S	8006200536* 8006200611* 8006250374 8006300010 8006160072	50-471 D 50-514 D ACRB ACRS ACRS
PEOPLES, D L	8006250266* 8006170160 8006180293 8006180278 8006180364	50-373 0 50-454 0 50-10 F 50-373 A 50-373 K	PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8006180221 8006180225 8006240602 8006170224 8006170231*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLESSET, M S PLESSET, M S PLESSET, N S PLESSET, M S PLESSET, M S	B006160096 B006160111 B006160059 B006160059	ACRB ACRB ACRB ACRB ACRB
PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8004140071 8004170459# 8004130240 8004300558 8004190307	50-295 P 50-247 P 50-237 P 50-10 Q 50-10 P	PETERSON, M R	8006230005 8006230009 8006230010 8006230706 8006240609	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLUMLEE, K E POCHAL, W F POCHAL, W F POCHAL, W F POCOIO. A J	9006170750* 9006090179 9006260010 9006260044 9006020189	50-307 G XPORTLIC XPORTLIC XPORTLIC RES
PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PERCY.D E	8006240316 8006240470 8006300453 8006270306 8006250045*	50-10 F 50-10 F 50-373 A 50-10 P CONTRACT	PETERSON, M R	8006250003 8006250036 8006250072 8006250075 8006250076	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POIRIER.M R PORTER.S W PORTER.W L PORTER.W L POSER.E B	8004040024 8004020275 8004257251 8004250253 8004200177*	50-478 M 50-320 R 50-489 0 50-369 9 50-387 8
PERKINS, M A PERLMAN, J PERNY, C. D PERNY, C. D PERRIGO, L D	8006160006 8006200134 8006250254* 8006250264* 8006170716	50-29 S CONTRACT 50-321 Q 50-321 G RES	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M E PETERSON, M R	8006250367 8006260006 8006260008* 8006230356 8006300111	XPORTLIC XPORTLIC XPORTLIC 50-285 J XPORTLIC	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8006060234* 8006300153* 8006190347 8006040035* 8006090153*	9A777 9A777 9A777 71-7901 9A779
PERRIN.JS PERRIOLD PERROTTI,DJ PERROTTI,DJ PERROTTI,DJ	8006040081 8006250349 8006230202* 8006250165* 8006170535	NUREO RES 50-280 G 50-259 G TOPREP	PETERSON, M R	8006300332 8006300277 8006300698 8006300701 8006250018	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-482 8	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8006090109* 8006240065* 8006250121* 8006040005* 8006120475*	94777 94777 94777 94777 94777
PERRY, J C PERSON, L PERSON, L 8 PETERSON, R J PETERSON, R M	B004300492* B006030032 B006230163 B006120287 B006040181	50-344	PETRICK, N A PETRICK, N A PETRY, B F PEVEY, L E PFEFFERKORN, W	8006120311 8006120312 8006060446* 8006170074 8006070014	50-482 8 50-482 0 71-5607 71-390 50-488 0	POTAPOUS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U POTAPOVS, U	8004200133 8004230233 8004040227* 8004030143* 8004140131*	9444 9444 9444 9444 9444
PETERSON, K R PETERBON, M R PETERBON, M R PETERBON, M R PETERBON, M R	8006030051 8006170783 8006170845 8006170850 8006170854	XPORTLIC XPORTLIC XPORTLIC XPORTLIC * XPORTLIC	PFEFFERKORN,W PFEFFERKORN,W PHILLERICK,S B PHILLIPS,H S PHILLIPS,Q A	8006110342 8006180341 8006120302 8006130074* 8006200504	50-488 0 50-488 0 50-70 0 50-498 0 50-341 H	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8006230216* 8006240103* 8006200143* 8006250114* 8006240153*	04777 04777 04777 04777
PETERSON, H R	8006170859 6006170864 8006170867 8006180385 8006180391	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILPOTT, F T PHILPOTT, F. T PHICKEL, T W PICKEL, T W PICKEISBEN, K O.	8006110105* 8006240512* 8006260175* 8006160203 8006060163*	50-269 8 50-270 6 50-269 8 ACRS 50-219 8	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8006240119* 8006090094 8006090138 8006060208 8006180298	98799 98799 98799 98799 98799
PETERSON, H R PETERSON, H R PETERSON, M R PETERSON, M R PETERSON, M R	8006070157 8006070161 8006070184 8006070189 8006070192	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIENTA, R PIQUYT, D R PIQUYT, D R PIQUYT, D R PIQUYT, D, R	8006130165 8006110014 8006110019* 8006110024* 8006110028*	50-275 P 50-361 0 50-361 G 50-361 0 50-361 0	POTAPOVB. U. POTAPOVB. U. POTAPOVB. U. POTAPOVB. U POTAPOVB. U	8004040030 8004040214 8004040001 8004030155 8004230212	71~900\$ QA999 QA999 QA999 QA999
PETERSON, H. R. PETERSON, M. R. PETERSON, M. R. PETERSON, M. R. PETERSON, H. R.	8006070174 8006130026 8006130028* 8006130048 8006170752	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIGOTT, D R PIGOTT, D R PIGOTT, D R PIGOTT, D R PIGOTT, D. R	#1006110031 #006110078 #006110107* #1006110008 #2006110008	50-361	POTAPOVE, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVE, U	8006120467 8006240054 8006160116 8006200138 8006240097	04999 04999 04999 04999 04999
PETERBON.M R. PETERBON.M R PETERBON.M R PETERBON.M R. PETERBON.M R	8006180130 8006090112 8006090121 8006090141 8006130049	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIGOTT, D. R PIGOTT, D. R PIGOTT, D. R PIGOTT, D. R PIGOTT, D. R	8006110028* 8006110031* 8006110098 8006110107* 8006110019*	50-361 0 50-361 0 50-361 0	V SVORATOR TAPOVRATOR V SVORATOR V SVORATOR V SVORATOR	8006240110 8006240141 8006250097 8006250113 8006300143	99999 99999 99999 99999 99999
PETERSON, M R	8006160173 8006160199 8006170737 8006180593 8006250020	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIGDIT.D R PIGDIT.D R PIGDIT.D R PIGDIT.D R PIGDIT.D R	8006110024* 8006110028* 8006110031* 8006110078 8006110107*	50-361 0 50-361 0 50-361 0	POTE,DR POTTER.JP POTTER.JP POTTER.JP POTTER.JP	8006190267* 8006190371* 8006170796* 8006180624* 8006200564*	70-687 40-672
PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8006070116 8006070152 8006160178 8006170225 8006170388	XPORTLIC 70-2542 XPORTLIC XPORTLIC XPORTLIC	PILANT, J. M PILANT, J. M PILANT, J. M PILANT, J. M PILANT, J. M	8006040046 8006030461 8006090318 8006110075 8006110251	50-278 G 50-278 P 50-278 F 50-278 P 50-278 F	POTTER, J P POTTER, J P POTTER, J P. POTTER, J P POTTER, J P.	8006180073* 8006170829* 8005230341* 8006170788* 8006180611*	50-293 G 50-10 G 50-277 G 50-333 G
PETERBON, M R	8006200581 8006200590 8006230080 8006170773 8006180590	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT, J M PILANT, J M PILLARD, C H PIRTLE, O L PLASKON, R E	800A240500 800A230542 800A110255 800A110444* 800A240A00	50-298 P 50-298 P NUREO 50-282 Q 50-516 Q	POTTER, J P POTTER, J P POTTE, W E POWERS, M B, PRATT, W, T	8006170230* 8006040082* 8006040080 8006040080 8006250201	27-47

AUTHOR	ACCESSION REMUN	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PRATTIC M PRELLIJ A PREVOIJ C PROCHAZKAID R PROFIDIA E	8006260212 8006300091 8006110294* 8006240058* 8006030425	50-247	REID.R W REID.R W REID.R W REID.R W REID.R W	8006090526 8006130022 8006230134 8006200631 8006200636*	50-302 F 50-269 P 50-269 P 50-289 P 50-289 P	RICKDVER, H G RIDGWAY, K R RIDGWAY, D A RILEY, L L RINGLE, J C	8004090098 8006230113* 8004140078 8004110246 8004110183	50-541 A 50-150 G 50-320 G 70-2623 50-243 S
PROXMIRE, W PURCELL, J F PURR, J P PURSELL, C D GUATTROCCHI, J	8006300562* 8006110146 8006060200* 8006270127* 8006030380	50-320 H 50-367 R 50-412 G 50-341 H 50-320 J	REID,R W REID,R W REID,R W REID,R W REID,R W	8006200643* 8006240582 8006240096 8006240163 8006240193	50-287 P 50-321 F 50-313 B 50-269 P 50-321 P	RINGLE, J C RISCHLING, J L RITSHER, J A RITTER, D RITTS, F H	8006300286 8006170677* 8006230261 8006120107* 8006250193	50-243 F 50-316 S 50-443 Q COMMISSION 50-445 M
QUATTROCCHI, J GUATTROCCHI, J QUICK, D R, QUICK, D QUICK, D	8006180408 8006170631 8006060568* 8006260023* 8006040343	50-320 J MISC 50-302 G 50-302 S	REID.R W REID.R W REID.R W REID.R W REID.R W	8006240203* 8006240212* 8006250269 8006250271* 8006250274*	50-321 P 50-321 P 50-321 P 50-321 P 50-321 P	RITTS:F H RITTS:F H RIVELLO, J RIZICKA, W G RIZZI:R A	8006250173 8006170454 8006120228 8006200262 8006200150	50-445 M 50-445 M PR 50-54 S PROJ
QUICK, D R QUICK, D QUICK, D QUICK, D QUICK, D R	8006050406 8006040346 8006130376 8006250028 8006160077*	50-302 8 50-302 8 50-251 6 50-250 8 50-387 8	REID.R H REID.R H REID.R H REID.R H REID.R H	8004250288 8004250290* 8004250294* 8004300002 8004300004	50-313 P 50-313 P 50-313 P 50-277 F 50-249 F	RIZZI.R A ROBART.A ROBBINS.R L ROBBINS.R L ROBERDS.H W	8006270018± 8006270018± 8006300393± 8006090251 8006090173±	PROJ 50-317 P 50-367 U 50-367 G 0A979
GUIGO,C GUINTENZ,T E GUIST.A B RADER.R M RADER.R M	8006170786 8006120297* 8006110488 8006060262 8006060262	PR 50-219 8 PR 50-320 0 50-320 0	REID.R W REID.R W REID.R W REID.R W REID.R W	8006300006 8006300052 8006300221 8006300351 8006300444	50-313 P 50-346 P 50-321 P 50-269 P 50-302 P	ROBERTSON, D E ROBERTS, K ROBERTS, G W RODERTS, F P ROBEY, J	8006170708 8006070176* 8006230214* 8006270362 8006300024	RES 50-213 G GA999 NUREG FOIA
RADER,R M RAGER,M RAILSBACK,T RAILSBACK,T RAMBELL,R	8006060262 8006270267* 8006120086* 8006120122* 8006300409*	50-320 Q 50-331 8 50-254 H MISC 50-390 A	REID.R W REID.R W REID.R W REID.R W REID.R W	8004300524 8006270357 8006270361* 8006270368* 8006250380	50-277 P 50-277 P 50-277 P 50-277 P 50-313 P	ROBISON, R W RODEN, J W RODEN, J P RODRIOVES, R J	8006040160* 8006180439* 8006180497* 8006040087 8006170636	State Prog 50-321 R 50-366 R XPORTLIC 50-312 R
RAMSEY, R U RANDALL, J D RANDAZZO, A F RANDOLPH, M L RANSOME, J W	8005180313 8006230152* 8006230133* 8006200021 8005270310*	F01A 80-128	REID:R W REID:R W REIDHAAR:D L REILLY:M K REIMANN:F	8006260059* 8006300210 8006160117 8006090438* 8006200141*	50-289 P 50-289 P 50-142 G 50-416 G 50-373 G	ROGERB, R F ROGERB, R F ROGERB, T R ROGOVIN, M ROGOVIN, M	80040 90547* 80061 80338* 80062 30164* 80061 30313 80061 70107	50-321 Q 50-321 G CONTRACT MISC 50-443 H
Ransone, J, W Rad, Q, V Rad, Q, V Rard, C Raskin, D, B,	8005270286 8006090394* 8006050032* 8006240632 8006230433	40-8434 30-280 G 50-244 S 50-344 H 50-466 Q	REIMANN.F W REIS.E J REIS.E J REIS.H F REIS.E,J	8006200280* 8006110172 8006130251 8006260202 8006240467	50-266 @ 50-485 @ 50-309 @ 50-250 @ 50-452 @	ROGOVIN, M ROHATOI, U B ROHRER, E H ROMINE, P F ROMINE, D	8005230036* 8006190079 8006120347* 8006110193* 8006240380*	CONTRACT RES 50-346 8 50-327 8 50-327 8
RATHLEBHERGER, J RAUSCH, J K RAUSCH, J K RAUSCH, J K RAUSCH, J K	8006030307 8006050425* 8006160196* 8006090473* 8006130054*	50-387 D 50-389 G 50-280 G 50-280 G 50-424 G	REIB.E J REIB.E J REMLEY,M E REMBEROER,D L	8006260205 8006300491 8006250056 8006170297# 8006090414#	50-452	ROOD, H ROOD, H ROONEY, M A ROONEY, V L ROONEY, M A	8006110455 8006090541 8006110293 8006110412 8006240148	50-361 T 50-361 T 70-1308 50-271 P 70-1308
RAUSCH, J K RAUSCH, J K RAUSCH, J K RAVEN-HANBEN, P RAHLB, N	8006020074 8006270231* 8006300176* 8006090113* 8006190575	50-413	RENBERGER, D.L. RENBERGER, D.L. RENBERGER, D.L. RENBERGER, K.L. RENBERGER, D.L.	8005070404* 8006050490 8006110135 8006030464 8006050358	50-460 Q 50-397 Q 50-397 K 50-460 A 50-460 A	ROOT, L D ROOT, L D ROOT, L D ROOT, L D ROOT, L D	8006230207* 8006030467 8006020064* 8006030483 8006160133	50-331 G 50-331 G 50-331 G 50-331 G 50-331 F
RAYMOND, W J REAVEG, T E REAVED, W J REBELOWBKI, J	8004050440* 8006170308* 8006250164* 8006200381 8006120147*	50-244 G 50-271 G 50-29 G 50-416 H 50-284 G	RENBEROER, D. L.	8006050540 8006110278 8006130305 8006170509 8006270324	50-397 A 50-397 A 50-397 A 50-397 K 50-460 F	ROOT, L. D ROOT, L. D ROOT, L. D ROOT, L. D ROOT, L. D	8006170539 8006230362 8006230370 8006230501 8006240183	50-331 F 50-331 P 50-331 P 50-331 P 50-331 F
RECORD.D.J RECORD.D.J RECORD.D.J RECORD.D.J RECORD.D.J	8006110223* 8006170691* 8006180533* 8006200484* 8006240433*	50-327 8 50-327 8 50-327 8 50-327 8 50-327 8	RENBERGER, D L RENBERGER, D L RENFRO, W E RESNIKOFF, M RESNIKOFF, M	8006240404 8006300381 8006060392 8006180216 8006020113	50-397 F 50-397 A 50-466 G Foia Foia	ROOT, L. D RORABACHER, J A ROBA, F ROSA, F ROSB, D F	8006260255 8006030072 8006250044 8006300637 8006200547	50-331 G PR 50-282 P 50-382 A TDPREP
RECORD.D J REEDER.D L REEVES.E REGAN.W H REGER.B S	8006300523* 8006260037 8006020172 8006170371 8006270418*	50-327 8 REB 50-247 P 50-458 A FOIA	RESNIKOFF,M REVELEY,W T REVELEY,W T REYES,L A REYES,L A	8006300576 8006130162* 8006300425 8006170799* 8006060061	FDIA 50-322	R088, D, R089, D R089, D R089, Q L R089, D	8006180580 8006060554 8006060276 8006070028 800606040438	MISC NUREO TOPREP 40-8502 71-3607
REHMIT A REHMIT A REHMIT A REHMIT, A REICHIM	8004110393 8004120059 8004180074 8006240401 8006180241	COMMISSION COMMISSION COMMISSION RES RES	REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	8006060347 8006060347 8006230059 8006110454 8006120398	50-445 @ 50-445 @ F01A PR 50-445 T	ROSS, D. A ROSS, D. F ROSS, D. A ROSS, D. A ROSS, D. A	8006020467 8006020574 8006030444 8006030450* 8006060417	50-219 @ MISC 50-219 S 50-219 S
REICHHOLD, W, P REICH, M REID, R W REID, R W REID, A B	8006040246 8006200583 8006030249 8006190624 8006230076	70-2486 NUREO 50-289 F 50-289 F FOIA	RHODE, O K RHOADS, E W RHOADS, C O RHOADS, C O RHOADS, C W	8006120398 8006200497* 8006030268* 8006090478 8006240012	50-445 T 50-327 S 50-334 Q 50-358 S 50-410 Q	ROSS. D A ROSS. D F ROSS. D F ROSS. D. A ROSS. D A	8006060424* 8006180544 8006180560 8006160021* 8006160055*	50-219
REID, A B REID, A B REID, R W REID, R W REID, R W	8006230101 8006120186 8006070532 8006120423 8006130018	FOIA FOIA 50-346 Q 50-277 Q 50-321 Q	RHODE.O K RHODES,F T RHODE,O.K RHODE,O K RHODE,O K.	8006030471 8006160015 8006160070 8006170323 8006230550	50-220 P NUREG 50-410 A 50-410 A 50-410 A	ROSS, D A ROSS, D, A ROSS, D A ROSS, D A ROSS, D A	8006160086# 8005200455 8006240497 8006240502# 8006260185	50-219 S 50-219 R 50-219 S 50-219 S 50-219 S
REID.R W REID.R W REID.R W. REID.R W REID.R.W	8006170065 8006060584 8006090027 8006120491 8006020095	50-269 0 50-346 F 50-313 F 50-289 0 50-285 H	RHODE, G K RIBERA, J R RICHARDSON, J, R RICHARDSON, J R RICHTER, H J	8006240406 8006230048* 8006170064* 8006170375* 8006260421	50-410 8 CONTRACT 40-1341 40-1341 NUREO	ROSS.D A. ROSS.D A ROSS.D A ROSS.D A ROSS.D A	8006260187* 8006260171 8006260172* 8006270277 8006270303*	50-217 S 50-219 S 50-219 S 50-219 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	АОНТИА	ACCESSION NUMBER	GURJEC: CATEGO
ROSS, D A ROSS, D A ROSS, D A ROSITOCIY, I R ROSITOCIY, I R	800 6300474 800 6300477* 800 6300482* 800 6060517 800 6060292	50-219 8 50-219 8 50-219 8 TOPREP NUREO	SARSTEN, C E SARSTEN, C E BARSTEN, C E SASTRE, C SATTERFIELD, R M	8004170830 8004020082 8004020082 8004180372	50-443 B 50-460 S 50-443 S RES TOPREP	SCHULTR, T R BCHULTE, R T BCHULTE, G R SCHULTE, W B BCHULTE, W B	8006030347* 8006300334* 8006120027 8006110356 8006110376*	50-244 50-320 50-367 50-367
roth, J Roth, G V Roth, J Rothpleisch, J, E Rothpleisch, J	8006060472* 8006120079* 8006020054 8006030045 6006130117	70-398 50-311	BATTERFIELD, R M BAUER, R C BAUER, R C BAURDERS, R BAVAGE, J W	8006120370 8006070547* 8006130371* 8006170517* 8006300198	50-241 Q	BCHUBTER.M D BCHUTT,P F BCHWARTZ.Q X BCHWARTZ.A R BCHWARTZ.Q X	8006230068 8005120430 8006200605# 8006070083# 8006230467	30-275 70-1510 50-320 50-464 50-332
rothfleigch. J Rothfleigch. J e Rothfleigch. J Rothfleigch. J Rothfleigch. J e	800&050207 600&030024 800&2301&0 800&250341 800&300&95	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 40-8748	BAVAGE, J W BAWOCHKA, B O BAXE, R F BCARAND, R A BCARANO, R A	8006200078* 8006250143* 8006170478 8006120193 8006080494		SCHWENCER, A SCHWEIBINZ, E R SCHWEIKER, R S SCHWENSFEIR, R SCHWEIBINZ, E R	800401,0004 8004060333# 8004300529# 80040050078# 8004020073#	50-295 \$9-373 \$0-320 70-33 50-546
ROTHMAN, R. ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U	8006110228* 8006020099 8006020128 8006090244 8006180109	50-275 0 50-445 0 50-445 0 70-1308 70-1308	SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R A	8004060494* 8004200509 8004090558 8004120220 8004090024	40~8727 40~3453 40~279 40~1162 Waste Mot	BCHWENCER, A BCHWEITZER, D BCHWENCER, A BCHWENCER, A BCHWENCER, A	8006170749 8006040118* 8006020435 8006020440* 8006020445*	50-313 50-329 50-291 50-281 50-281
ROTHSCHILD, M U ROUBE, L C ROUSE, L C ROUSE, L C ROUSE, L C	0006260203 0410404008 1410606008 9620214008 960066008	70-130B 70-1143 70-25 70-1143 70-467	SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A SCARANO, R A	8006070127 8006070133 8006240247 8006200366 8006200370*	Waste Mot Waste Mot 40-8502 40-8502 40-8502	Schwencer, A, Bchwencer, A, Bchwendpetr, R Schwencer, A Bchwencer, A	8006120443 8006120447# 8006300011 8006070034 8006040259	50-416 50-416 70-33 50-364 50-478
ROUSE, L C ROUSOME, F H RUDMAN, R J RUDGLPH, J P. RUFF, A B	8004200140 8004200074* 8004140002 8004120352* 8004130038*	70-1308 50-312 F 50-244 P 50-346 B 50-335 Q	BCARANO,R A BCARANO,R A BCARANO,R A BCHAEFFER,N M BCHAFFER,B G	9006230708 8006230146 8006300291 8006180587* 8006020021*	40-8452 40-1162 40-1162 CONTRACT 50-934 Q	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8004090130 8004110431 8004120914 800409037 8004090533	50-275 50-266 50-241 50-241 50-416
RUFF.A B RUITER.G, H RUNTE.W O RUNYON, J RUNYON, J	8006170268* 8006160099* 8006170495 8006170560 8006170570*	50-302 @ 50-303 R 50-320 P 50-579 @ 50-579 @	BCHENDEL, K R SCHENDEL, K R SCHERER, A E SCHMITZ-FEUERHA SCHMIDT, O D	8004090075 8006120191 8006300415 8006300385* 8006080656*	PR PR TOPREP PRM 70-442	BCHWENCER, A BCHWENCER, A, BCHWENCER, A BCHWENCER, A BCHWENCER, A	8004070344 8004110371 8004170385 8004200572 8004200513	50-311 50-315 50-522 50-534 50-384
RUSHMORE, J W RUSHELL, L B RUSHELL, L B RUSHELL, L B RUSHELL, L B	8006110241 8006110253 8006020532 8006120262 8006120276	50-220 J 50-220 J 50-317 P 50-317 S 50-317 S	Schmieder, J R Schmidt, A D Schmidt, A. D Schmidt, A. D Schmidt, A. D Schmidt, A. D	B004040999 B004030449 B004030494 B004110025 B004110037	50-286 0 50-335 8 50-251 8 90-250 8 50-335 8	BCHWENCER, A. BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A.	8005200510 8005180385 8005200530 8005240151 8005240505	50-514 50-321 50-471 50-321 50-35
RUSSELL.J L RUSSELL.L D RUSSELL.L D RUSSELL.L D	B006020421 B006050028 B006040347 B006050039 B006070344	50-160 F 50-317 8 50-316 5 50-316 8 50-317 8	BCHMIDT, A. D.	8006190258 8006170675 8006090397* 8006170542 8006170647	50-251	· BCHJENCER, A BCHHENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8006240102 8006280067 8006300087 8006250334 8006240308	50-27/ 50-27/ 50-3() 50-36/ 50-3()
RUBSELL, L B RUBBELL, L B RUBBELL, L B RUSBELL, L B. RUSBELL, L, B	8006090365 8006180493 8006180473 8006180483 8006180515	50-317 8 50-317 8 50-318 8 50-316 8 50-318 8	BCHMIDT, A D	8004170447 6004230547 8004230483 8004230553 8004230561	50-250 R 50-251 S 50-335 B 50-250 B 50-250 B	Bchhenger, a Bchhenger, a Bghhenger, a, Bchhenger, a Bghhenger, a	9006240310* 8006240441* 8006240624 8006200287 8006200392	50-01 50-01 50-09 50-09 50-04
RUTBERG, J RYAN, R. O RYAN, R. O RYAN, R. O RYAN, J. H	8006260207 8006020026 8006040158 8006200578 8006230124#	50-443 M State Prog State Prog State Prog CONTRACT	SCHMIDT.A D. SCHWIDT.A D SCHWEIDER, F W. SCHNEIDER, R A. SCHWEIDER, F W	8006230579 8006230464 8006060212 8006250146 8006250163	50-250 B 50-335 B 50-272 B 70-1257 50-272 F	BCHWENCER, A. BCHWOERER, F. BCHWOERER, F. BCOT, W. J. BCOTT, W. J.	8004270009 8004030594 8004120249 8004120008 8004240281	50-34 INAEO MUREO PR PRM
RYAN,R O RYAN,R O RYAN,R O RYAN,R O BABOL,A R.	8004240045 8004230108 8004230136* 8004230003 8004240575*	State Prog DRO DRO State Prog 50-387 G	SCHNEIDER, F H BCHNELL, D F SCHNEIDER, F H SCHNEIDER, H BCHNEIDER, F H	8004120349 8004170240 8004030340 8004180289* 8004110231	50-272 Q 50-483 A 50-311 P 50-295 Q 50-272 Q	SCOTT, J. SCOTT, W.J. SCOTT, J. SCOTT, J. SCOTT, W.J.	8004180013 8004050487 8004120019* 8004110344 8004240587*	50-46 PA PA 50-41 70-1;
SADE,T. BAHA,P BAHA,P. BAIKI,T BAIKI,T	8006170503 8006190079 8006300171 8006120179 8006300581	50-387 D #E9 RE8 40-9052 XPORTLIC	BCHNEIDER, F U BCKNEIDER, F U BCKNEIDER, F W BCKNEIDER, F W BCKNEIDER, K, N	8006160136* 8006300233 8006300282 8006300490 8006260219	50-272 R 50-272 G 50-272 G 50-272 G State Prop	SCOTT, W J SEAL, M M. SEAL, M, M SEARS, J A SEARS, J, A	80062405724 8006300251* 8006300547* 8006300414* 8006300407*	70-1; 50-4; 50-3; 50-3; 50-3;
SALTZMAN, J. BALTZMAN, J. BALTZMAN, J. BALTZMAN, J. BALTZMAN, J	8004180197 8004120131 8004190232 8004230088 8004300474	50-458 M 50-459 M 50-416 M 50-416 M 50-320 J	BCHNEIDER, F. M BCHNEIDER, F. W BCHNEIDER, F. W BCHOPPMAN, M. A. BCHOPPMAN, M. A.	8006240375 8006170647 8006240371 8006030447* 8006030456*	50-272 Q 50-272 F 50-272 Q 50-235 8 50-251 B	BEAY, J L BEOQEL, R L BEIDEL, W C BEIDEL, W C	8005200024 8005020302* 8006110174* 8006130067 8006300636	50-2 50-3 50-4 50-4
BALTIMAN, J BAM, J BAMPELS, M D BAMPELS, M D BAMPELS, M D	8006300246 8006200078# 8006050561# 8006050561# 8006110302	50-322 M CONTRACT 50-445 M 50-445 M 50-445 M	Bchoppman, M. A Bchoppman, M. A. Bchoppman, M. A Bchoppman, M. A Bchoppman, M. A	8004110033* 8004110042* 8004170285* 8004170684* 8004170651*	\$0-250 8 50-335 8 50-251 8 50-335 8 50-335 B	SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C. SEIDLE, W. C.	9004110314* 9004040149 9004030144 9004050523 8004030218	50-3 50-4 50-4 50-4
SAMPELS, M D SAMDERON, J L SAMPORD, R J. SAMOER, H S SAMOER, H B	8004040354 8004110087	50-445 M 50-275 H NUREO 50-518 Q PR	BCHOPPMAN, M, A BCHOPPMAN, M, A BCHOPPMAN, M, A BCHOPPMAN, M, A BCHOPPMAN, M, A	8006170652* 8006230571* 8006230495* 8006230564* 8006230588*	50-335 8 50-251 8 50-335 8 50-250 8 50-250 8	SEIDLE, W C SEIDLE, W C SEIDLE, W: C SEIDLE, W: C	8004040128 8004120223 8004070090 8004170184 8004190224*	50-4 50-1 50-1 50-1
SANTORD, M P SARBANES, P B SARBANES, P B SARBANES, P S SARBOUR, B	8006270106* 8006300522* 8006270146*	71-9007 50-289 H 50-320 H 50-171 U 50-346 R	Bchuppman, M, A Schuppman, M A Bchreiner, W Bchuler, T, R Bchultz, W, B	8006230586* 8006230476* 8006300422* 8006030328* 8006110382*	50-250 B 50-335 S 50-390 A 50-244 P 50-367 G	SEIDLE, W, C. BEIDLE, W C BEIDLE, W C. BEIDLE, W C. BEIDLE, W C	8006070225 8006170218 8006070017 8006070580 8006110445	50-7 50-7 50-7 50-7

ROHTUA	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SEIDLE, H. C.	800 6250217	50-445 G	SHEA, J R	8004030074	XPORTLIC	SMEDIRA, C.	8006120183	71-5364
BEIDLE, H. C.	800 6070012	50-458 G	SHEA, J M	8004030084	XPORTLIC	SMITH, C V	8006030118	SECY
BEIDLE, H. C.	800 6070183	50-482 G	SHEA, J R	8004140207	SECY	SMITH, C V	8006020523	SECY
BEIDLE, H. C.	800 6120240	50-445 C	SHEA, J R	8004300080	XPORTLIC	SMITH, M H	8006300127	NUREO
BEIDLE, H. C.	800 6180321	50-445 A	SHEA, J R	8006140185	XPORTLIC	SMITH, P D	8006300054	NUREO
SEIGEL, B SEIKEN, B J SEIKEN, B J SEKULER, B N BEKULER, B N	8004300122 8004170492 8004170612 8004190335 8004180333	NUREG 50-492 8 50-492 8 27-39 70-1908	SHEA, J. R BHEA, J. R, SHEA, J. R SHEA, J. R SHEA, J. R	8006250055 8006250284 8006250285 8006270007 8006270240*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	BMITH, M H SMITH, G H SMITH, R D SMITH, R D	8006230446* 8006270180* 8006060464* 8006200013* 8006050082*	50-309 G 70-135 70-398 WASTE MOT 70-33
BEKULER, 8 N	8006240521	70-1908	SHEA, JR	8006300274	XPORTLIC	SMITH, O H	8006230382*	50-309 G
SEKULER, 8 N	8006240587*	70-1908	SHEA, JR.	8006300288	XPORTLIC	SMITH, P D	8006170164	NUREO
SEKULER, 8 N	8006240592*	70-1908	SHEA, JR	8006300293	XPORTLIC	SMITH, O. H	8006060036	70-487
SELCHO, H. 8	8006020481	REB	SHEAKS, DJ	8006300130	NUREO	SMITH, O H	8006170201*	50-201 G
BELLB, D	8006120121	50-352 A	SHEDLOSKY, JT	8006030324*	50-245 G	SMITH, O H	8006170395	50-277 G
SELLS, D. SELLS, D & SELLS, D & SELLS, D SELLS, D. E	8006130158 8006180075 8006180337 8006190688 8006200058	50-498 A 50-498 V 50-498 V 50-498 A 50-352 V	SHEDLOSKY, J. T SHELBOURN, J L SHELLEY, W J SHELLY, W J	8004040059* 8004250157* 8005210130 8004140192 8005090057	50-245 G 50-245 G 50-346 H 71-9091 40-8027	SMITH, O. H SMITH, O. H SMITH, O. H SMITH, O. H SMITH, O. H	8006170782 8006170790 8006170822 8006180059 8006180092	50-277 G 50-247 G 50-293 G 50-320 G 50-293 G
SELLB, D. SENECHAL, M E SERAPIAN, J SEYFRIT, K V SEYFRIT, K V.	8006170330 8006170715 8006170371# 8006170374# 8006170362#	50-352 A PR 50-247 G GA999 GA999	SHEFFEA' M 7 SHEFFEA' M 7 SHEFFEA' M 7 SHEFFEA' M' 7	8006250333 8006090524 8006090553 8006300026 8006300643	70-1193 40-2061 40-8027 40-8027 40-8027	BMITH, O. H BMITH, O. H BMITH, C. H SMITH, O. H SMITH, O. H	8006180607 8006180617 8006190559 8006190222 8006190243	50-333
SEYFRIT, K V. SEYFRIT, K V SEYFRIT, K V. SEYFRIT, K V.	8006300042 8006300047 8006300050 8006300053 8006300058	50-382 Q 50-482 Q 50-445 Q 50-498 Q 50-458 Q	SHEPHERD, R E BHERWOOD, Q Q SHERWOOD, M R BHEU, J. P	8004090170* 8004030489 8004180359 8004190439* 8004140148*	50-320 G REGOD PT21 50-133 G 50-320 P	SMITH.O.H BHITH.OH SMITH.R SMITH.OH SMITH.O.H	8006190361 8006200357 8006060121* 8006180111 8006190083	50-277 G 40-672 50-192 G 70-371 70-820
BEYFRIT, K V.	9006200115	50-298	Shideler, J J.	8005200147*	50-482 P	SMITH, O H	8006050053	70-33
BEYFRIT, K V.	9006060587		Shields, W C	8005260082	ACRE	SMITH, O H	8006060455	70-398
SEYFRIT, K V.	9006060593		Shields, W M	8005300548	ACRE	SMITH, J. H	8006130370	RES
SEYFRIT, K V.	9006060597		Shields, W C	8005300557	ACRE	SMITH, P. A	8006130241	CONTRACT
BEYFRIT, K V.	9006060597		Shield, W. C	8005300324	ACRE	SMITH, C. H	8006020054	I&E
BEYFRIT, K V	8006040286	50-445 Q	SHIELDS, W C	8006300329	ACRB	SMITH, G. H	8006270403	50-219 0
BEYFRIT, K. V	8006040287	50-278 G	SHIELDS	8006300561	ACRB	SMITH, G H	8006050401	50-293 B
BEYFRIT, K V	8006040288	50-247 G	SHIELDS, S W	8006260356*	50-546 G	SMITH, R D	8006170270	27-47
SEYFRIT, K V	8006040289	50-498 G	SHIELDS, S W	8006200069	50-546 B	SMITH, J D	8006200280*	50-266 0
BEYFRIT, K V	8006040292	50-382 G	SHIELDS, S W	8006230162	50-546 Q	SMITH, I F	8006120387	50-387 A
SEYFRIT, K. V	8006040345	50-458 G	GHIELDB, B W.	8006170531	50-546 H	SHITH.0 H	8006090550	14E
SEYFRIT, K. V	8006040350	50-482 G	BHILEDB, W. C.	8006300319	ACRS	SHITH.0 H	8006120005	14E
SEYFRIT, K. V	8006059317	50-313 G	BHIMA, B	8006260012	XPORTLIC	SHITH.J	8006260077*	50~305 G
SEYFRIT, K. V	8006060164	50-424 S	BHIMA, B	8006260013*	XPORTLIC	SHITH.1 H.	8006050565	50~327 G
SEYFRIT, K. V.	8006090011	50-245 G	BHIMA, S.	8006260014	XPORTLIC	SHITH.P A	8006130234	CONTRACT
SEYFRIT, K. V.	8004300062	50-498	SHIMA.B.	8006260018*	XFORTLIC	SMITH,P A	8006050491	CONTRACT
SEYFRIT, K V	8004300063		SHIMECK,DJ.	8006260020	RES	SMITH,O H	8006170735	50-309 Q
SEYFRIT, K V	8004300064		SHIPLEY.BL	8006270002	NUREO	SMITH,G H	8006190192	50-201 Q
SEYFRIT, K V	8004300065		SHIVELY.C.N.	8006230437*	50-313 S	SMITH,I W	8006020511	50-289 Q
SEYFRIT, K, V	8004300068		SHIVELY.CN	8006180460*	50-348 S	SMITH,P A	8006130244	CONTRACT
SEYFRIT, K. V. BEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SHAH, V. L.	8006020841 8006200048 8006130171 8006130178* 8006120476	50-267 F 50-498 G 50-492 G 50-482 G NUREG	BHIVELY, C.N SHIVELY, C.N. SHIVELY, C.N. SHOCKLEY, V.E	8006170634* 8006180459* 8006180467* 8006200493* 8006200517*	50-348 8 50-348 8 50-348 8 50-348 8 50-255 0	SMITH.O H SMITH.M T. SMITH.R L SMITH.R L SMITH.R L	8006270090* 8006200389 8006020274 8006030314 8006030468	50-219 0 40-8481 50-271 P 50-271 P 50-271 P
BHAH, PR	8006230526*	50-361 A	SHOEMAKER, C.L.	8004180358	50-317 J	8MITH.0 H	9006230373	50-309 0
BHALLER, DV	8006130115*	50-315 G	SHOLLY, S.C.	8004040420	50-289 0	8MITH.I.W.	9006060536	50-289 0
BHALLER, DV	8006050306	50-316 B	SHOLLY, S.C.	8004240343	50-320 9	9MITH.R.D	9006200009	Waste Hot
BHALLER, DV	8006120300	50-316 B	SHON, F.J.	800404043	50-466 9	8MITH.J L	9006110047*	50-361 0
BHALLER, DV	8006170669	50-316 B	SHORB, E. M	8004110331	50-367 A	8MITH.J L	9006060579	50-255 0
SHALLER, D V. SHALLER, D V SHALLER, D V SHALLER, D, V	8006170521 8006170698 8006240462 8006300495 8006300502	50-315 R 50-316 R 50-316 S 50-315 S 50-315 S	Shum, e y Bhum, e y Shumway, r, w Sieck, p, e, Bilberg, j e	8006180570 8006300034 8006260046 8006090087 8006040012	70-2909 70-2909 REB PR PR	BMITH, I. W BMITH, R. O BMITH, R. L SMITH, I. W BMITH, I. W.	8006170232 8006230281* 8006070260 8006110155 8006120346	50-255 G 10GFR 50-27 P 50-289 G 50-255 G
Shanaman; S. K.	8006070102*	50-320 P	BILBERO, J E	8006170733	50-387	Smith, I &	8004120380	50-289 0
Shanbaky, M. M	800613021*	50-320 8	BILBERO, J. E	8006170733		Smith, O. H	8004300223	50-277 8
Shanbaky, M. M	8006130226	50-320 8	BILBERO, J. E	8006170733		Smith, I &	8004140041	50-289 0
Shanbaky, M.	8006250026	50-289 8	BILBERO, J E	8006060262		Smith, P. A	8004300545	CONTRACT
Shannon, R. E.	8006060242*	50-275 9	BILBERO, J E	8006060262		Smith, I, W	8004170533	50-289 0
SHANNON, J. B.	8004230429	40-8102	BILBERG, J E. BILBERG, J E BILKER, W B BILVER, H GIMPSON, D, B.	8006170484	50-387 0	SMITH.I, W	8004240447	50-287 0
SHANNON, H D	8006270052*	50-320 H		8006170484	50-387 0	SMITH.I W.	8004240191	50-287 0
SHAPAR, H. K	8006180123*	8ECY		8006270017	NUREO	SMITH.I W.	8004240194	50-287 0
SHAPAR, H K	8006040033*	50-409 Q		8006020215	50-289 P	SMITH.I.W	8004240243	50-287 0
SHAPAR, H K	8006200559	50-272 Q		8006200588	NUREO	SMITH.I W	8004240197	50-361 0
SHAPAR, H. K SHEA, T. R. SHEA, J. R. SHEA, J. R. SHEA, J. F.	8006300328 8006190118* 8006090436* 8006190129* 8005280885	CONTRACT	SINKIN, L. SINKIN, L SISTER DANIEL H SKOLDS, J L. SLABACK, L A	8006170575 8006170575 8006270025 8006250106 8006060167		SKITH, I W SMITH, I W SNAPP, B A SNAPP, B A SNEPEÇOR, E	8006300408 8006300427 8006170328 8006180151 8006190625	50-289 0 50-289 0 50-387 0 50-289 0 50-344 I
SHEA, JR. SHEA, JR. SHEA, JR. SHEA, JR.	8004120425	BECY	SLABECK, L A	800&050543	PR	Snider, D M	8006280039	RES
	8004120485*	BECY	SLACK, B T	800&030341	50-129 W	Gniezek, J. H	8006300549*	State Prog
	8004120340	9ECY	SLEMMONS, D, B	800&200137:	CONTRACT	Sniezek, J H	8006160164	50-278 G
	8004040250	70-2523	SLOAN, D E	800&200008	50-329 B	Snow, B A	8006030587	50-244 S
	8004120448	BECY	BLONE, B, B.	800&180025	PR	Snow, B. A	8006090317	50-244 S

AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION RUMBER	SUBJECT CATEGORY
SNOW B A SNOW B A SNYDER B J SNYDER B J SNYDER B J	8006230601 8006160037 8006200087 8006030137 8006090033	50-244 S 50-244 R 50-320 U 50-320 P 50-320 P	STELLO, V STELLO, V STELLO, V STELLO, V	8006050447* 8006050461 8006050464* 8006070071 8006070462	50-546 Q 50-206 G 50-206 Q 50-346 A 50-206 Q	SUBUDHI,M SUBUDHI,M SULLIVAN,J SULLIVAN,R F SULLIVAN,R F	8006180261 8006200583 8006240267* 8006240273* 8006240174*	RES NUREG 50-259 G 50-259 G 50-259 G
SNYDER, B J	8006170250 8006120072 8006200596 8006300304 8006300311*	50-320 H 50-320 P 50-320 H 50-320 0 50-320 0	STELLO, V STELLO, V STELLO, V STELLO, V	8006070466* 8006120146* 8006120463 8006130184 8006170335	50-206	SULLIVAN, J H SUMMERS, R SUMMERS, R SUMMERS, R SUMPTER, J R	8006240369* 8006060101* 8006250017* 8006050149* 8006020068	50-327 S 50-273 G 50-217 G 50-273 G PR
SOHINKI, S M SOHINKI, S M SOHINKI, S M SOLBRIG, C W SONIN, A A	8004030145 8004040115 8004130157 8004020481 8004270420	50-437	STELLO, V STELLO, V STELLO, V STELLO, V	8006070512 8006130195 8006230093 8006240047 8006240083	50-312 Q 50-280 Q 50-341 H 50-324 Q 50-397 Q	SUTTNER, T A SWALES, J SWAN, W B SWANBY, O T SWANBON, E R	8006120307 8006110151* 8006030511* 8006030574 8006170321*	50-266 P 50-254 B 50-518 G 40-3453 50-282 G
SPANGLER,R G SPATH, J P SPEIS, T P SPELL, W H SPENCER, Q S	8006190289* 8006180236* 8006190783 8006120208 8006090441*	50-298	STELLO, V STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B	B006240086* B006110100 B006030374 B006030340 B006030364	50-397 Q 50-10 R 50-237 B 50-237 B 50-237 S	SWANSON, E.R SHANSON, E.R SHANSON, N.E SHANSON, D. G SHANSON, D. T	8006170276* 8006200266* 8006240146* 8006230200* 8006170443	50-254 G 50-341 G GAPP7 CONTRACT 50-289 G
SPENCER, Q S	8008070409* 8008070495 8008080134 8008250187 8008250189	50-460 0 50-312 0 50-460 0 50-528 0 50-397 0	STEPHENSON. B B STEPHENS. R M STEPHENSON. B B STEPHENSON. B B STEPHENSON. B B	8006040203 8006200103 8006160097 8006160121 8006170510	50-247 S TOPREP 50-237 S 50-249 S 50-237 B	SWART.F E SWART.F E SWART.F E SWARTZ,L L SWARTZ,L L	8006040040 8006060266 8006060273 8006040111 8006160042	50-267
SPENCER. Q S SPENCER. Q S SPENCER. Q S SPENCE. M D SPEROFF. R	8006250174 8006090402 8006090406 8006110282* 8006230387*	50-312 Q 50-460 Q 50-460 Q 50-445 M 50-247 S	STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPTOE, P	8006170448 8006230381 8006230559 8006230570 8006060236	50-10 R 50-247 B 50-249 B 50-249 B 50-249 B	SWARTZ, L L SWARTZ, L L SWART, F E SWARTZ, L L SWEARINGEN, J D	8006200335 8006300335 8006270197 8006260213 8006030408*	50-287 Q 50-289 Q 50-267 P 50-289 Q 50-327 S
SPESSARD, R L SPESSARD, R L SPESSARD, R L SPIEGEL, G SPIEGEL, G	8004170320* 8004170736* 8004230078* 8004230157 8004230157	50-10 Q 50-373 Q 50-254 Q 50-445 M 50-445 M	STEPTOE, P P STEPTOE, P P STEPTOE, P P STEPTOE, P P STEPTOE, P	8006170218 8006170218 8006060366 8006060357 8006170814	50-295	BHEAR INGEN, J D BHEAR INGEN, J D BHEAR INGEN, J, D BHEENEY, F J BHETLAND, P D	8006030490* 8006030460* 8006200457* 8006300598 8006060035*	50-327 8 50-327 8 50-327 8 RES 50-309 Q
SPIEGEL, Q SPIEGEL, Q SPIEGEL, Q SPRAKTES, F W SPRAVL, J	8006060361 8006110371 8006110371 8006270401 8006020097	50-498 M 50-445 M 50-445 M NUREO 50-295 P	STEPTOE.P STERNBERG.D M STERNBERG.D M STERNBERG.D M STERNBERG.D M	8006170814 8006060578* 8006060084* 8006130067* 8006250093*	PR 50-142	SHITZER, D C SYLVIA, B R SYLVIA, B, R SYLVIA, B R SYLVIA, B R	8006240617* 8006230187* 8006230099* 8006020173 8006030016	50-293 Q 50-280 Q 50-280 G 50-280 P 50-338 F
Springer. D Springer. D Springer. D Springer. D Sreniawski. D J	8006200071* 8006170237 8006170189 8006200066 8006060453	50-488 G 50-488 G 50-488 G 50-488 G	STERNBERG, D M STERN, W C STETKA, T F STETKA, T F STETKA T	8006250083* 8006260092* 8006250190* 8006260023*	50-344 G XPORTLIC 50-333 G 50-333 G 50-302 G	SYLVIA, B R SYLVIA, B R SYLVIA, B, R SYLVIA, B R SYLVIA, B R	8006040174 8006050329 8006200604 8006050323 8006090388	50-280 F 50-337 P 50-280 G 50-280 F 50-280 G
STAGGERS, H () STAGGERS, H () STAHL, D M STAHL, D M STAHL, D M	8005200512* 8006130191* 8006060428 8006240250 8006240250	COMMISSION COMMISSION 50-445 M 50-445 M 50-445 M	STETKA, T F STEVENSON, R L STEVENS, S C STEVENS, S C STEVENS, S C	8006040343 8006020045 8006230414 8006110012 8006110026	50-302 S 70-820 50-285 S 50-285 S 50-285 S	SYLVIA, B. R SYLVIA, B. R SYLVIA, B. R SYLVIA, B. R SYLVIA, B. R	8006070252 8006070341 8006110063 8006110324 8006130334	50-338 R 50-339 P 50-280 P 50-280 B 50-280 P
STAHLE, C STAHL, D M STAHL, D M STAHLE, C R BTAMPLEY, N L	8006170778 8006110375 8006110375 8006250308 8006030223	50-327 P 50-445 M 50-445 M 50-311 P 50-416 C	STEVENS,S C STEWART,R C STEWART,R C STEWART,M J STEYAERT,L T	8006300468 8006110325* 8006170159* 8006130034 8006200563	50-285 S 50-382 A 50-382 Q 71-387 NUREO	BYLVIA: B. R BYLVIA: B R BYLVIA: B R BYLVIA: B R BYLVIA: B R.	8006230499 8006120301 8006120388 8006120395 8006130174	50-200 8 50-330 R 50-339 P 50-339 P 50-338 8
STAMPLEY, N L STAMPLEY, N L STAMPLEY, N L STAMPLEY, N L	8004030005* 8004030003 8004200345 8004300375 8004300382*	50-416 K 50-416 K 50-416 M 50-416 F 50-416 F	STIEDE, W L STIMMEL, K Q STOCKHAMER, S STOHR, J P STOHR, J P	8004020248 8004070514 8004170781 8005230330 8004180003*	TOPREP NUREQ PR 50-10 Q 70-1151	SYLVIA, BR. SYLVIA, BR. SYLVIA, BR. SYLVIA, BR. SYLVIA, BR.	8006230444 8006240238 8006120378 8006120386 8006300253	50-338 8 50-260 0 50-337 P 50-336 0 50-280 0
STARKEY, R B STARK, R STARKEY, R B STARKEY, R B STARKEY, R B	8004050374 8006120002 8006050328 8006050332* 8006090510	50-261 8 50-387 A 50-261 8 50-261 8 50-387 F	9 L, SHOTE 9 L, SHOTE 9 L, SHOTE 9 L, SHOTE 9 L, SHOTE	8004040077 8006170687* 8006230195* 8006030581 8006170767	27-47 50-302	SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B, R SYLVIA, B R	8006170679 8006300235 8006170513 8006300349 8006170611	50-280 P 50-280 Q 50-280 R 50-280 G 50-337 P
STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B	8006110347 8006110358* 8006160025 8006230572 8006230584*	50-241 8 50-241 8 50-241 R 50-241 9 50-241 9	PAHOTE PLANDTE TLANDTE PLANDTE PLANDTE PLANDTE	8006170176* 8006250150* 8006230224 8006180008 8006200076	50-250 G 50-259 G 70-1319 50-324 G 50-348 G	SYLVIA, B R SYLVIA, B, R SYLVIA, B R SYLVIA, B R SYLVIA, B R	8006180532 8006190545 8006190562 8006250139 8006230507	50-337 P 50-280 P 50-280 P 50-338 P 50-280 P
STARKEY, R B STEARUS. C J STEELE. F STEFFEE, C STEINER, J L	8006240438 8006300624 8006190450 8006270272* 8006260039	50-261 0 70-2474 50-275 H 50-265 5 RES	9 L,9HOT8 9 L,9HOT8 9 L,9HOT8 9 L,9HOT8 9 L,9HOT8	8006200074* 8006200514 8006240045 8006170165 8006180001	50-348 G 50-280 G 50-395 G 50-250 G 70-1151	SYLVIA, B, R SYLVIA, B R SYLVIA, B R SYLVIA, B R SYLVIA, B, R,	8006240484 8006300673 8006240283 8006240356 8006250287	50-280 Q 50-280 Q 50-281 Q 50-280 Q 50-337 P
STEINNI NDER, J STELLO, V STELLO, V STELLO, V	8006200350 8006300201* 8006210177* 8006120517 8006040153	70-2909 REGOD 50-546 T GA999 50-255 G	STOHR, J, P STOHR, J P STOHR, J P STONE, R STOVER, J R	8006170681 8006230135 8006230183 8006270095* 8006170732	50-302 G 50-257 G 50-280 G 50-302 H CONTRACT	SYLVIA, B. R BYLVIA, B R BYLVIA, B R BYLVIA, B. R BZWAJKOWSKI, R	8004250120 8004250132 8004300501 8004300454 8004240148	50-339 P 50-339 Q 50-339 P 50-280 P 70-1308
STELLO, V STELLO, V. STELLO, V. STELLO, V STELLO, V	8006040164 8005210137 8006020018 8006040166 8006050443	50-498 G 50-544 T 50-334 Q 50-382 G 50-546 Q	STRAUSS, P.L. STRENGE, D.L. STROMMEN, N.D. STUKENBRDEKER, G. SU, T. M.	8006030120# 8006200532 8006200563 8006200130 8006230001	SECY NUREG NUREG XPORTLIC 50-322 A	tangling, t Tangling, t Tangling, t Tangling, t Tangling, t	8006240148 8006170799* 8006230092* 8006060061 8006120274*	70-1308 50-346 G 50-358 G 50-346 8 40-3453

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEORY
TAYLOR,R R TAYLOR,R R TAYLOR,R Q TAYLOR,R Q TAYLOR,R Q TAYLOR,P A	8006170213 8006170217* 8006120231* 8006170226* 8006130381	70-572 70-572 50-445 G 50-445 G 50-321 B	TOLLISON, A C	8006040307 8006040310* 8006030331 8006030352 8006040335	50-324 S 50-324 S 50-324 S 50-324 S 50-325 S	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIPP.L E TRIPP.L E	8006200430 8006200485 8006230401 8006060200# 8006020259#	50-368 8 50-368 8 50-313 P 50-412 Q 50-387 Q
TEBOR, M A TEDESCO, R L	8006110086 8006200613 8006250071 8006240635 8006250138	50-285 H 50-546 A 50-322 G 50-382 F 50-373 A	TOLLISON.A C TOLLISON.A C TOLLISON.A C TOLLISON.A C TOLLISON.A C TOLLISON.A C	8006040337* 8006050007 8006050015* 8006030375 8006030377*	50-325 8 50-325 8 50-325 8 50-324 8 50-324 8	TRIPP, L E TRIPP, L E TRIPP, L E TROUP, O TROUP, O L	8004030090* 8006190278* 8006300236* 8006170185* 8006180012*	50-311 G 50-334 G 50-245 G 50-250 G 50-324 G
TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8006250140 8006250145 8006250149 8006250151 8006300306	50-50H A 50-454 A 50-466 A 50-471 A	TOLLISON, A C	8006070314 8006070347 8006070355* 8006070372 8006070378*	50-325 8 50-324 8 50-324 6 50-325 6 50-325 8	TROUP, Q L TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F TROWBRIDGE, G F	8004200094* 8004040475 8004040475 8004120034 8004120034	50-348 Q 50-289 0 50-289 0 50-289 0 50-289 Q
TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R. L	8006300310 8006300314 8006300316 8006240077 8006250136	50-43B A 50-483 A 50-437 A 50-566 A 50-412 A	TOLLIBON; A C TOLLIBON; A, C TOLLIBON; A C TOLLIBON; A C TOLLIBON; A C	8006110184 8006110198* 8006110092 8006180365 8006180447	50-325 8 50-325 8 50-324 R 50-324 0 50-325 8	TROWBRIDGE, G F	8006040507 8006040509 8006170785 8006170785 8006170239	50-448 0 50-448 0 50-289 0 50-289 0 50-289 0
TEDESCO.R L TEDESCO.R L TEDESCO.R.L TEDESCO.R.T TEDESCO.R L	8004250387 8004250389 8004300275 8004250175 8004300185	50-471 A 50-395 A 50-275 A 50-508 F 50-528 A	TOLLIBON, A C	8006180449* 8006180481 8006180496 8006180505* 8006180425	50-325 8 50-325 P 50-324 8 50-324 8 50-324 8	TROWBRIDGE, 0 F	8004130239 8004140052 8004140078 8004140052 8004140078	50-287 0 50-287 6 50-320 0 50-287 0 50-320 0
TENNEY, F. H. TERRELL, J, E TERRY, B. H THADANI, A C THOMAS, C	8006120207# 8006180087# 8006070515# 8006020127 8006170679#	COMMISSION CONTRACT 50-294 Q TOPREP 70-267	TOLLIBON, A C	8006250267 8006180452 8006180454* 8006180455 8006180465*	50-324 S 50-325 S 50-325 S 50-324 B 50-324 S	TROWBRIDGE, 0 F	8006180534 8006180534 8006190435 8006190435 8006270237	50-320 0 50-320 0 50-289 0 50-289 0 50-289 0
D REAMONT TO REAMONT TO REAMONT TO REAMONT TO REAMONT TO REAMONT	8006190249* 8006190168* 8006170398* 8006050103* 8006090054*	50-277 G 50-320 G 50-277 G 50-566 G 70-754	TOLMAN, E L TOMPKING, B A TOMPKING, B A TONE, M M TONGUE, T M	8006300301 8006020522 8006110397 8006170231 8006170320*	RES 50-275 0 50-485 0 PR 50-10 G	TROWBRIDGE, 0 F	8006270237 8006280276 8006270216 8006280276 8006270216	50-289 0 50-289 0 50-320 0 50-289 0 50-320 0
THOMAB; M THOMAB; L. M THOMAB; R D THOMAB; R THOMAB; R H	8004250215* 8004120157 8004050422 8004060435 8004030518*	50-390 0 NUREO 27-48 70-1729 50-213 8	TOOKER, D W TOOKER, D W TOOKER, D W TOOKER, D W COOLE, R. J.	8006030278* 8006030441* 8006030473* 8006270261* 8006120400	50-331 8 50-331 8 50-331 8 50-331 8 50-289 8	TROY, M TRUBBELL, M H TBAI.C TBCHAECHE, A N TBGUDEROB, G	8006270415 8006030124 8006130685 8006130013* 8006110008*	FOIA 40-8064 REB 70-1007 50-309 Q
THOMAS, C. D. THOMAS, R. D. THOMAS, R. D. THOMAS, J. L. THOMAS, R. D.	8004020348 8004170158 8004240274 8004170478 8004240300	50-320 P 27-48 27-48 50-111 W 27-48	TOTH, A D. TOTH, A D. TOURTELLOTTE, J TOURTELLOTTE, J TOY, H L	8006090447* 8006090418* 8006200633* 8006270305 8006190239	50-460 Q 50-460 Q 50-289 P 50-275 Q 70-8	TEGUDERGE, G TUCKER, E E TUITE, P T TURI, J A TURNAGE, K G	8004110029* 8004300417* 8004180195* 8004200380 8004300071	50-271 G COMMISSION FOIA 50-201 H NUREO
THOMAS, R. D THOMAS, R. D THOMAS, E. B THOMAS, W. N THOMPSON, H. L	8006240302 8006250187 8006170404 8006300388 8006300605#	27-48 50-320 8 50-341 I 50-280 P FOIA	TRAMM,T.R. TRAMHELL.C M TRAVERS,W TRAVIS,W H TRAVIS,W H	8006060246* 8006060219 8006090036 8006040088 8006120453	50-295	TURNER: E A TURNER: E A TURNER: E A. TURNER: E A TURNER: E B	8004090871 8004090021* 8004180638 8004300644* 8004030353	50-498 8 50-498 9 50-498 8 50-498 9 Nureo
THOMPSON, M D THOMPSON, D. THOMPSON, M A THOMPSON, D THOMPSON, D.	8006270002 8006040179 8006020590 8006090530 8006090536	NUREO WASTE MOT WASTE MOT I&E I&E	TRAVIB,C C TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIESO-DIAZ	8006200023 8006060547 8006060547 8006170484 8006170484	RES 50-320 Q 50-320 Q 50-387 Q 50-387 Q	TURNER.E A TURNER.E A TURNER.E A TWEED.R M TWEED.R.M	8006110314 8006110337 8006300578 8006130084* 8006250320*	50-498 8 50-498 8 50-498 0 10CFR 10CFR
THOMPBON, D THOMPBON, M A THOMPBON, D THOMPBON, D THOMPBON, D	8006090345 8006170366 8006240134 8006300658 8006300344	50-280 8 Waste mot 30-324 8 30-259 8 50-321 8	TRAVIEBO-DIAZ TREVINO,T TREVINO,T TRIBBLE,J E TRIEBCHMAN,W E	8006170484 8006250330 8006230041* 8006270172 8006020377	50-387 Q CONTRACT CONTRACT 50-271 P 50-387 D	TWEED, R M TWEED, R. M TWEED, R M TWEED, R M TWEED, R M THEED, R M	8006260016* 8006120431* 8006240225* 8006240636* 8006250377*	10CFR 10CFR 10CFR 10CFR 10CFR
THOMPSON, D THOMPSON, D THOMSEN, F. T THOMSEN, F. T THOMSEN, F. T,	8006300330 8006300333 8006060328 8006180181 8006180181	50-254 8 50-346 8 50-522 0 50-522 0 50-522 0	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8006040132 8006040051 8006240186* 8006110142 8006230434	90-313 Q 50-313 Q 50-313 Q 50-313 R 50-313 B	TWEED, R M TWEED, R M UDALL, M K UDY, A C UDY, A. C	8006240213* 8006240626* 8006200091* 8006200047 8006260004	10CFR 10CFR 50-320 U 50-250 P 50-287 P
THONUB, L. H. THORNBUROH, R. THORNBURO, H. P. THORNBURO, H. D. THORNBURO, H. D.	8006230452* 8006090095* 8006190015 8006240089 8006160171	50-309 Q 50-320 P 50-341 H 50-341 H 50-498 Q	TRIMBLE, D G TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D. C	8006050331 8006110001 8006110242 8006130264 8006090386	50-313 G 50-313 R 50-313 F 50-313 8 50-368 8	UHRIO,R E UHRIQ,R E UHRIQ,R E UHRIO,R E UHRIO,R E	8006040025# 8006040021# 8006180024# 8006180021# 8006180070	50-250 G 50-250 G 50-250 G 50-250 G PR
THORNBURO, H D THURLOW, E. W TIEPEL, E. W TIEPEL, E. W TIEPEL, E. W.	8006300219 8006300358 8006120163 8006120173* 8006050444	50-397 8 50-309 P 40-8502 40-8502 40-8502	TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D. C TRIMBLE, D. C	8006230450 8006120277 8006130326 8006120315 8006170700	50-348 8 50-313 8 50-348 P 50-348 P 50-313 P	UHRIO,R.E UHRIO,R.E. UHRIO,R.E. UHRIO,R.E. UHRIO,R.E.	8004230146* 8006070072 8006170171* 8006200216* 8006030053	50-335 @ PR 50-250 G 50-250 G 50-250 P
TILLMAN, A. TIMKO, D. R TIMKO, D. R TIMBLEY, J. C TOBIN, W. J	8006250264* 8006060391* 8006160016* 8006060476* 8006250254*	50-321 G 50-334 R 50-334 R 50-70 P 50-321 G	TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D, C	8005180498 8005180528 8005170525 8005180455 8006180463	50-348 8 50-313 P 50-348 9 50-348 8 50-348 8	UHRIG,R.E UHRIG,R.E UHRIG,E E UHRIG,R E. UHRIG,R E	8004110099* 8004050235 8004040310 8004240129 8004170644	50-250 F 50-335 P 50-335 P 50-250 Q 50-250 Q
TODD, Q. A TOKARZ, F. J. TOKUHATA, Q. K TOLF, M. L. TOLLIBON, A. C	8006200338* 8006060481* 8006060402* 8006300422* 8006170857*	70-143 50-70 P 50-289 O 50-390 A 50-324 Q	TRIMBLE, D. C.	8006170623 8006180510 8006170583 8006170686 8006200359	50-313 8 50-313 F 50-368 R 50-313 R 50-368 B	UHRIO,R E. UHRIO,R E. UHRIO,R E. UHRIO,R E. UHRIO,R E.	8004040341 8004040342 8004070340 8004070370 8004300021	50-250 P 50-250 P 50-251 0 50-250 P 50-250 G

ACCESSION	SUBJECT		ALITI IÜLD	ACCESSION NUMBER	BUBJECT CATEGORY	,	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGURY	
NUMBER 304110217 304230184 304130254 304170301 304250274	50-250 50-250 50-250 50-250 50-335 50-335	F Q F F G	AUTHOR VARGA: S A VARGA: B A VARGA: S A VARGA: S A VARGA: S A VARGA: S A	8006200174 8006120009 8006250292 8006250297 8006160057	50-247 50-295 50-280 50-295	P F G G P	WARD, K D WARD, K D WARD, E C WARD, E C WAREMBOURG, D W	8006190675* 8006230091* 8006030479 8006090289 8006030233	50-255 Q 50-409 Q 50-292 B 50-282 B 50-287 Q	AUTHOR WEISS, E.R. WEISS, E.R. WEISS, E.R. WEISS, E.R. WEISS, E.R. WEISS, E.R.
)06250304)06250307)06300579)06170267)06180471	50-250 50-335 50-250 50-387 50-335	а а м Р	VARGA, S A VARGA, B A VARGA, B A VARGA, S A VARGA, B A	B004260147 B006260074 B006260080 B006200523 B00623000B	50-250 50-261 50-261	F P P P	WAREMBOURO, K WAREMBOURO, D W WAREMBOURO, D W WAREMBOURG, D WAREMBOURO, D	8004040043 8004030455 8004050301 8004070375 8004140034	50-267 G 50-267 P 50-267 R 50-267 P	WENNERHOLM J WENBLANBKI.F A WENBLANBKI.F WERLING, J A WERLING, J A
106200479 106230578 106240261 106240192 106250203	50~250 50~397 50~250 50~250 50~335	P P F F	VARGA, S. A VARGA, S. A VARGA, S. A VARGA, S. A VARGA, S. A	8004230017 8004200507 8004200521 8004300207 8004300229	50~280 50~295	P P P P	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8006170692 8006160017 8006160030 8006160115 8006180419	50-267 P 50-267 R 50-267 B 50-267 B 50-267 P	WERLING, J A
06240187 06240196 06270311 06230566 06020385*	50-335 50-250 50-335 50-278 50-171	P F 8 H	Varindis, C Vasser, E. Vernig, P & Vint. B & Viesing, O	8006110166* 80062503R9 8006040175 8006090399 8006130112	70-2707 71-9070 HISC	S P	WAREMBOURG,D W WARNICK,R,F WARNICK,R F WARNICK,R F WARNICK,R F	8006240400 8006130111* 8006090461* 8006200097* 8006200280*	50-267 P 50-315 Q 50-305 Q 50-266 Q	Herling, J A Herling, J A Herling, J A Herling, J, A Herling, J A
06110092 06190345* 06050434* 06060585* 06090088*	50-277 50-277 50-364 50-280 50-338	S R Q Q Q	VOOT-LONELL, R VOOT-LOWELL, R VOIOT, H H VOIOT, H H VOIOT, H H	800&180036* 800&200227* 800&110424 800&110424 800&090134	50-250 50-546 50-546	н 6 6 6 6	WARNICK,R F WARNOCK,D WARREN,B.K WASSERBACH,A E WATERMAN,M E	8006260077* 8006190068 8006090101 8006120235 8006260015	50-305 Q F01A PR PR REØ	WERNER, B J WERNER, J WESCOTT, H. M. WESCOTT, H. M. WESCOTT, H. M.
36240071* 54200128* 36250076* 36300209* 36300278*	90-321 50-339 50-302 50-249 50-344	G G G	VOIGT, H H VOIGT, A F VOIGT, H L VOIGT, H L VOIGT, H H	8006060456 8006070352 8006060552 8006060552 8006180006	50-548 71-5957 50-320 50-320 50-244	e 0 0	WATFORD, M WATSON, W. K WATSON, A P WATSON, L. R WATSON, W A	8006140026* 8006170149* 8006200023 8006020322 8006180487*	50-261 R PRM RES HISC 50-327 S	WEBTERMAN, T F. WEBTERMAN, T. F. WEBTERMAN, T. F. WEBTERMAN, T. F. WEBTERMAN, T. F.
)6050447)6110008*)6110029*)6170555)6020230	PR 50-309 50-271 50-346 50-325	О О М Р	VOIOT, H H VOILLEQUE, P O VOLD, E VOLOENAU, E VOLLMER, R H	8006180006 8006020348 8006170277 8006130102* 8006190255*	PR	Ç P G	WEAVER, G L WEBER, D A WEBSTER, D A WEBSTER, E H WEEKS, E D	8004020380 8004300574 8005120430 8004130370 8004140022	50-397 D 50-267 P 70-1510 50-338 S 50-133 R	Westerman, T. F Westerman, T. F Westerman, T. F Westerman, T. F Westerman, T. F.
6030374 6030470 6030370 6050251 6070325	50-324 50-324 50-324 50-324 50-325	P P Q	VOLLMERIR H VON HIPPELIF. VORDERBRUGGEN VOTHIM H WACTOR, J A	8004300527 8004090113* 8004250172* 8004230021 8004040304	NRC COMMISSIC 50-528 70-687 50-395	o G B	WEGNER,M 8 WEGST.W.F WEIGAND,J 0 WEIGAND,J 0 WEIGAND,J 0	8004250347 8004240138 8004040545 8004090015* 8004180329*	PR PR 50-458 8 50-458 Q 50-458 A	WESTFALL, R M WETHY, C M WETHY, C M WETTERHAHN, M J WETTERHAHN, M J
6060362 6070310 6110127 6160058 6180471	50-241 50-241 50-325 50-241 50-241	8 P P	WAGNER,A O WAGNER,H WAGNER,P C WAHLGUIST,E J WAHLGUIST,E J.	8004070505* 8004040141* 8004070480 8004240074 8004240073	50-83 50-460 50-285 50-201 50-201	G G P H H	WEINBERG, A M WEINER, R, E WEINHOLD, E H WEINHOLD, E H WEINHOLD, E H	8006120266* 8006020344 8006040182 8006040191* 8006060479	CDMMI88IBN MIBC 50-443 0 50-443 0 50-443 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J
6180341 6180493 5230389 5240312 5240319	50-261 50-261 50-324 50-261 50-324	P F F	WAITE,R T. WALBRIDDE,W C WALBRIDDE,W C WALKER,R D WALKER,R S	8006090067 8006250084* 8006250237 8006170736* 8006300857*	REGOD 50~312 50~312 50~373 50~320	о 8 С Н	WEINREB-KUCHM WEINSTEIN, M WEINSTEIN, M. WEISENHAHN, J WEISS, D.	B006090076* B006270349 B006200546 B0061703B5 B006060006	50-466 @ NUREQ NUREQ 50-358 @ 40-8348	HETTERHAHN, M J HETTERHAHN, M J HETTERHAHN, M J HETTERHAHN, M J HETTERHAHN, M J.
\$230396 \$240479 \$110330# \$030351 \$110308	50~261 50~324 50~265 50~528 50~528	P P S S T	WALLACE, R WALLACE, R WALLACE, R WALLACE, R WALLACE, R	8006120056 8006060492 8006180189 8006160163 8006170007*	50-445 50-445 50-445 50-445 50-445	# # # #	WE188, D WE188, D WE188, D. WE188, D WE188, D	8004190227* 8004040002 8004040083 8004020592 8004040142	70-572 71-4986 70-36 70-1201 70-1100	HETTERHAHN, M J HETTERHAHN, M J HEXLING, J A HHEATON, H R WHEELER, R Y
230676 230686 230691 230693 230694	50-528 50-528 50-528 50-528 50-528	A C F A K	WALLACH,T WALLEY,P J WALLES,O B WALPOLE,J R WALPOLE,J R	8006170130 8006120232* 8006260421 8006110089 8006110088	50-155 PR NUREO 40-1162 40-1162	н	WE188.D WE188BERG.8 WE188.J WE188.D. WE188.E R	8006040247 8006070023 8006070547 8006300031* 8006110465	70-1113 State Prog 70-754 71-6717 PR	WHITAKER, M. B. WHITAKER, K. WHITEBELL, D. E. WHITEBELL, D. E. WHITE, R. L.
260201* 300234 190464* 110060 110003	50-498 RES 50-33] PR 50-309	о я о	WALSH,P J WALSKE,C WALTERS,E WALTERMANN,H A WALTON,O	8004040332 8004270030 8004170778 8004200524 8004020180*	70-1308 PR PR NUREQ 50-219	G	WEI88, E.R. WEI88, E.R WEI88, J.D WEI88, J.D WEI88, E.R	8006110465 8006110465 8006090490 8006090492 8006110049	PR PR 70-1257 40-8027 50-443 0	WHITESELL, DE WHITESELL, DE WHITESELL, DE
300418 110177 160110 170794# 350453*	50-307 50-27 50-307 50-387 PR	P P Q	WAMBACH, J L Wanat, S W Wanat, B W Wandke, N E, Wandke, N E	8004020561 8004200122 8004240210 8004180285 8004030497	RES 27-39 27-39 50-295 50-295	B \$	WE188, E.R. WE188, E.R. WE188, J. D WE188, J. D WE188, D	8006110049 8006300670 8006120432 8006120434 8006120438	50-443 0 FOIA 70-25 70-1257 70-8	WHITENER, H. L. WHITEHEAD, M WMITE, L D WHITESIDES, Q E WHITESELL, D E
250233* 250176* 250209* >60588)40139	50~354 50~423 50~412 50~305 50~266	G G C P F	WANDKE, N E WANDKE, N E WANDKE, N E. WANDKE, N E.	8006110111 8006110120 8006170470 8006170498 8006230340	50-304 50-304 50-295 50-295 50-295	5 6 5 5	WEIBB, D WEIBB, J, D. WEIBB, J, D WEIBB, E, R WEIBB, E, R	8006120440 8006120534 8006190013 8006110370 8006110380*	70-1359 40-8027 70-1257 50-289	HHITE, L. D HHITENER, H. L. HHITE, L. D. HHITE, L. D HHITE, L. D
190068 70836 90171 30192 30196*	50-250 50-247 50-295 50-315 50-315	H P P P	WANDKE, N, E WANDKE, N E, WANDKE, N E, WANDKE, N E, WANDKE, N E	8006270248 8006270251 8006270254 8006300403 8006300407*	50-295 50-295 50-295 50-295 50-295	8 8 8	WEI88, E R WEI88, E, R WEI88, E, R WEI88, E, R	8004110370 8004110380* 8004200204 8004120371 8004120371	50-289 G 80-289 G 8tate Prog 50-289 G 50-289 G	WHITE, L. D WHITE, L. D WHITE, L. D. WHITE, L. D. WHITE, L. D
30206* 30208 30214* 30223* 90180	50-315 50-247 50-247 50-247 50-296	የ የ የ	Wandke-n e Wang C H, Ward, R A Ward, R A Ward, K	8006300412* 8006240387 8006120383 8006200632 8006200124*	50-295 50-243 PT21 PT21 50-461	s P G	WEI68,E R WEI68,E R WEI68,E.R WEI68,E.R WEI68,E R	8006120381 8006120381 8006300461 8006230206 8006160089	50-287 0 50-287 0 40-8681 COMMISSION 50-443 0	WHITE, L. D. WHITE, M. D. WHITE, L. D WHITE, L. D WHITE, L. D

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WEISS,E R WEISS,E R WEISS,E R WEISS,E R WEISS,E R	8006240483 8006240483 8006260186* 8006260186 8006260188*	50-247 Q 50-247 Q 50-247 Q 50-247 Q 50-247 Q	WHITE, L D. WHITE, L D WHITE, L D WHITE, L D. WHITE, L D.	8006300494 8006110355 8006180537 8006180514 8006190473	50-244 G 50-244 F 50-244 P 50-244 P 50-244 S	WILSON, J L WILSON, J L WILSON, J N WILSON, J L	8006170662* 8006180470 8006180476* 8006250321 8006240427	50-280 5 50-280 8 50-280 8 50-322 A 50-280 8
WENNERHOLM J WENSLAWSKI,F A WENSLAWSKI,F WERLING,J A WERLING,J A	8006270256* 8006070513* 8006250112* 8006120268 8006020362*	50-295 8 50-73 0 50-275 0 50-334 8 50-334 9	WHITE, LD. WHITE, LD WHITHAN, GD WHITHAN, GD WHITHEY, GG WHITHEY, GG	8006250262 8006300433 8006200531 8006180446# 8006190643*	50-244 P 50-244 P NUREO 50-293 R 50-293 R	HILBON, J L HILBON, J L HILBON, J L HILBON, J L	8006240434* 8006270279 8006270287* 8006270292 8006270294*	50-280 \$ 50-280 \$ 50-280 \$ 50-281 \$ 50-280 \$
WERLINO, J A WERLING, J A WERLING, J A WERLING, J A WERLING, J A	8006120265	50-334 6	WHITBELL, DE	8006230223*	GA797	WILSON, J L	8006270302*	50-281 B
	8006030406	50-334 6	WICHERS, D. L	8006050164	40-8502	WENANS, L F	8006120216	PR
	8006060365	50-334 6	WICHERS, D. L	8006090008	40-8502	WISE, W C	8006240137	50-250 M
	8006090373	50-334 8	WICHERS, D. L	8006060431	40-8502	WISE, W C	8006240137	50-250 M
	8006110108	50-334 8	WICHERS, D. L	8006180282	40-8502	WIZNER, D O	8006050312*	50-314 B
Herling, J A	8006110121	50-334 8	HIDMER,W A	8006110288	50-366 P	WIXNER,D 0	8006050315*	50-316 8
Herling, J A	8006160041	50-334 8	WIDMER,W A	8006070535*	50-321 Q	WOLF,B	8006180149*	50-247 T
Herling, J A	8006170558	50-334 8	WIDMER,W A	8006070415*	50-321 Q	WOLF,J F	8006070049	50-599 0
Herling, J A	8006230557	50-334 8	WIDMER,W A.	8006250072	50-321 Q	WOLF,J F	8006110160	50-320 0
Herling, J A	8006250260	50-334 8	WIDMER,W A	8006180323*	50-321 Q	WOLF,B	8006170436	50-247 H
WERNER, BJ WERNER, J WESCOTT, HM WESCOTT, HM WESCOTT, HM,	8006160085* 8006120344* 8006200113* 8006050511* 8006170201*	50-346 8 50-346 8 50-359 Q 50-483 Q	WIDNER, W.A WIDNER, W.A WIDNER, W.A WIDNER, W.A WIDNER, W.A	8006230218* 8006030241 8006250249* 8006060376 8006110239	50-321 Q 50-321 F 50-321 Q 50-321 P 50-321 P	WOLFE, B WOLFE, B J WOLFE, B J WOLFE, B J WOLFE, B J	8006240202 8006020466 8006060577 8006070065 8006170224	70-1308 50-466 G 50-376 G 50-466 G
WESTERMAN, T F.	8006130088* 8006030534* 8006070097* 8006060129* 8006240182*	50-255 @ 50-298 @ 50-382 @ 50-285 @ 50-267 @	HIDNER, W.A. WIDNER, W.A. WIDNER, W.A. WIDNER, W.A. WIDNER, W.A. WIDNER, W.A.	8006110053 8006170640 8006170310 8006240276 8006240325	50-366 P 50-321 P 50-321 I 50-321 Q 50-321 Q	WOLFE,8 J WOLFE,8 J WOLLETT,8 A WOLLETT,8 A WOLTNER,E	8006180395 8006260211 8006030039 8006120413 8006060101*	50-466 Q 50-466 Q CONTRACT CONTRACT 50-293 Q
WESTERMAN, T F.	8006240046* 8006240055* 8006170287* 8006200517* 8006050376	50-313	WIDDFF,M P. WIDDFF,M P WIDDFF,M P. WIDDFF,M P. WIDRIG,R D	8004040388 8006120085 8004040388 8006120085 8006060613	50-289 0 50-289 0 50-289 0 50-289 0 Toprep	WOLTNER, E WOND, K B WOOD, J C WOOD, J C WOOD, L	8006050147* 8006170292* 8006120292 8006120292 8006120366	50-273 G 70-25 50-478 M 50-478 M XPORTLIC
WESTFALL,R M	8006160174	RES	HIEDEMANN, L. H	8006160161*	71-6698	₩000,J C	8006110076	50-498 M
WETHY,C,M	8006050325	50-335 8	HIEDEMANN, L. H	8006160172*	71-6698	₩000,E C	8006090353	50-309 B
WETHY,C M	8006230405	50-335 8	HIEDEMANN, L. H	8006160176*	71-6698	₩000,E C	8006110189	50-309 B
WETTERHAHN,M J	8006090069	50-272 0	HIEDEMANN, L. W	8006160179*	71-6698	₩000,E C	8006110334	50-309 B
WETTERHAHN,M J	8006090072*	50-272 0	HIEDEMANN, L. W.	8006160184*	71-6698	₩000HEAD,C P	8006090210	50-409 G
WETTERHAHN, M. J.	8006070067 8006070072* 8006130024 8006160156 8006200567*	50-272 Q 50-272 Q 50-272 T 50-358 Q 50-272 Q	Miedemann, L, W Higging, E Higging, E Higging, E Higging, L, W	8006160157 8006230050 8006060574 8006200002 8006240645	71-6698 Foia Contract Contract Contract	MOODHEAD, C P MOODRUFF, R. L MOODRY, N L MOOLEYER, E J	8006170413 8006270202 8006040082* 8006270014* 8006110168	50-409 0 50-409 T 27-47 FOIA 50-412 G
HETTERHAHN, M J	B004140154	50-358 Q	WIGOINB,E.J.	8006160224	CDNTRACT	WOOLEVER,E J	8006170315	50-412 8
HETTERHAHN, M J	B006130024	50-272 T	WILBORN,L.	8006050122*	50-445 Q	WOOLSEY,R T	8006030027	40-277
HETTERHAHN, H J	B006180507	50-272 Q	WILBORN,L.	8006300285*	40-8661	WOOLSEY,R.	8006250331	40-277
HETTERHAHN, H J	B006180513*	50-272 Q	WILCOX,J D	8006160196*	50-260 Q	WORDEN,W P	8006130138*	50-10 Q
HETTERHAHN, M J	B006180513*	50-272 Q	WILCOX,J D.	8006090473*	50-250 Q	WRAY,J R	8006200074*	50-348 Q
HETTERHAHN, H J	8006170501	50-538 0	WILD,P.A.	8006160261	50-939 8	WRIGHT,R W	8004050420*	50-553 Q
HETTERHAHN, H J	8006170501	50-358 0	WILKINBON,T A	8006060384	50-220 P	WRIGHT,F S	8004070148	50-471 Q
HEXLING, J A	8006020358	50-334 8	WILLIB,D E	8006300400*	50-390 A	WRIGHT,K H	8004120187	40-4492
HHEATON, H R,	8006180356	PT21	WILLIAMB,J A	8006270044	NUREO	WRIGHT,D,	8004300017	70-1252
HHEELER, R, V,	8006070010	PR	WILLIAMB,C.E	8004220225	71-9010	WRIGHT,B L	8004070517	XPORTLIC
WHITAKER, M B. WHITAKER, K WHITEBELL, D E WHITEBELL, D, E WHITE, R. L.	8006040116	PR	HILLIAMB, C. C	8006260038	50-546 G	WRIGHT, B L	8006120204	XFORTLIC
	8006300462	27-47	HILLIFORD, R. E.	8006260038	NUREO	WRIGHT, R W	8006030130	SO-SIB B
	8006040039*	71-9001	HILLIAMB, C. C	8006230060*	50-373 G	WRIGHT, B L	8006110439	XPORTLIC
	8006070122*	GA999	HILLIAMB, C. C	8006240041*	50-373 G	WRIGHT, B L	8006120211	XPORTLIC
	8006250052*	50-262 P	HILLIAMB, C. C.	8006250170*	50-546 G	WRIGHT, R W	8006170276#	CONTRACT
WHITESELL, D. E WHITE, D. WHITESELL, D. E. WHITESELL, D. E WHITESELL, D. E	8006200135# 8006030572# 8006250126# 8006030167# 8006240107#	GA797 50-344 G GA797 GA797 GA797	WILLIB, E. WILLIAMB, C WILLIAMB, C WILBOM, B. D. WILBOM, B. D	8006110095* 8006250216* 8006250218* 8006130015* 8006120365*	50-324 R 50-361 A 50-361 A 70-1007 BECY	HRIGHT, B L HRIGHT, B L HRIGHT, B L HU, O	80060 70120 80060 70538 80062 00561 80062 4020 7 80060 6050 1 *	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 40-8727
WHITENER, H L. WHITENEAD, M WHITE, L. D. WHITESIDES, G E WHITESELL, D. E.	8006050434*	50-364 Q	Wilson, B, D.	8006090038	XPORTLIC	WULLER: Q E	8006300438	50-461 F
	8006240190	PR	Wilson, B D	8006120510	50-392 P	WYATT: J M	8006040169*	50-382 Q
	8006050429*	50-244 Q	Wilson, B	8006090504	XPORTLIC	YACKLE: T R	8006260013	RES
	8006160174	RES	Wilson, J N	8006090539	50-322 A	YAMANA: K	8006020165	70-2805
	8006180303*	GA777	Wilson, J, L	8006030336	50-280 8	YANDELL: L A	8006060129*	50-285 Q
WHITE, L. D. WHITENER, H L WHITE, L. D. WHITE, L. D. WHITE, L. D.	8006110238 8006300278* 8006020394 8006030318 8006030324	50-244 V 50-364 0 50-244 F 50-244 P 50-244 P	WILBON, J, L WILBON, J, Y WILBON, W E WILBON, J N. WILBON, J, L	8004030348* 8004030354* 8004040311 8004180007 8004110204	50-280 8 50-280 8 50-27 P 50-322 A 50-281 8	YATES, B R YATRON, Q YBARRONDO, L J YBARRONDO, L J YBARRONDO, L J YEAQER, L L	8006300389 8006300484* 8006270015 8006020346 8006200017	50-367 U 50-320 H NUREQ RES RES
WHITE, L. D.	8006050030	50-244 8	WILBON, J.L	8006110265*	50-281 9	YIM, I T	8006020077#	50-249 Q
	8006030294	50-244 P	WILBON, J.L	8006120317	50-280 8	YIN, I T	8006130259#	50-373 Q
	8006030338	50-244 F	WILBON, J.L	8006120323*	50-280 8	YIN, I. T	8006170219#	50-454 Q
	8006240605	50-244 G	WILBON, J.L.	8006120328*	50-280 6	YIN, I. T	8006170774#	50-373 Q
	8006040237	50-244 P	WILBON, K.R	8006130284*	50-249 8	YIN, I T	8006300073#	50-483 Q
WHITE, L. D. WHITE, M. D. WHITE, L. D. WHITE, L. D. WHITE, L. D.	8006040338	50-244 P	WILBON, J. L.	8006120336	50-281 8	YIN, I T	8004250310*	50-327 G
	8006200518	NUREO	WILBON, J. L.	8006120337*	50-281 8	YOCOM, H, E	8004170345	50-395 A
	8006070326	50-244 P	WILBON, J. L.	8006120341*	50-281 8	YOCOM, H E	8004170441	50-395 A
	8006070331	50-244 P	WILBON, J. N	8006180621	50-322 A	YOUNO, T	8004040084*	50-275 G
	8006300346	50-244 G	WILBON, J. L	8006170653	50-280 8	YOUNOBLOOD, B J	8004040019	50-456 F

YOUNGBLOOD, B	AUTHOR YOUNGELOOD B J 800	106.18008b 106.180489 106.160297 106.170855 106.200047 106.200104 106.200104 106.200612 106.200612 106.200612 106.200612 106.200612 106.200612 106.200612 106.200612 106.200612	50-443 A 50-454 F 50-322 A 30-373 Q 50-329 P 30-339 P 50-438 A 50-438 A 50-454 A 50-454 A	ZAHLER, R E ZAJAC, L D ZAJAC	8006180199 8006160043 8006160043 8006160046* 8006160046* 800630325* 800630325* 8006120355 8006120355 8006170724 80063303272 80063303272	50-287 50-287 50-287 50-287 50-287 50-287 50-287 50-287 50-287 50-287 50-327 50-327 50-327 50-347 NREO 70-1201 70-1201	E ZEFF, D W ZEFF	BDD6300483 BO0625004 BO0625004 BO06200538* BO06200537 BO06200557 BO06200557 BO0620057 BO0620057 BO0620057 BO0620057 BO0620057 BO0620057 BO0620057 BO0610059* BO06200590	50-237 8 REB REB REB ACRB ACRB 30-200 R 50-284 B 50-284 B
---------------	---	--	--	--	--	--	--	---	---

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
OM Co , Minnesota Mining & Mfg Co Acme-Cleveland Co , Namco Controls Div Acton Environ Testing Corp	8006300136 8006240146* 8006300407* 8006300414* 8006300422*	71-6400 9A979 50-390 A 50-390 A
Advanced Technology, Inc Aeronautical Research Associates of Princeton	8006270012 8006120415*	FOIA CONTRACT
Agriculture, Dept of Agriculture, Dept of Agriculture, Dept of, Forest Service	8006170278 8006170453 8006040181	50-228 F 50-10 D Waste Hot
Alabama Power Co	8004030044 8004030292 8004030303 8004030312 8004030312	50-364 G 50-364 A 50-364 F 50-348 P 50-348 P
	8006030370 8006050033 8006050036* 8006050043* 8006050350	50-364 A 50-348 8 50-348 8 50-348 8 50-348 P
	8004050353* 8004040531* 8004110017 8004110240 8004170598	50-348 P 50-348 G 50-348 P 50-364 A 50-349 8
	8006170604# 8006180413 8006180432 8006180432 8006180440	50-348 8 50-364 A 50-348 8 50-348 8 50-348 R
	8006180442* 8006190410 8006190493 8006230182 8006230348	50-348 R 50-364 A 50-348 P 50-348 Q 50-348 8
	8006230363* 8006230376* 8006240376 8006240334 8006240368	50-348 8 50-348 8 50-364 P 50-364 A 50-348 9
	8006240375* 8006240376* 8006240414 8006250015 8006250142	50-348 S 50-348 S 50-364 A 50-348 G 50-364 J
Alabama. State of	8906300157 8906300572 8906300572 8906060322 8906180025	50-364 0 50-348 0 50-348 0 50-259 F
Alaska, State of Aldrich Chemical Co , Inc. (subs of Signa-Aldrich Corp)	8006240190 8006190021	PR XPORTLIC
and the second s	8006190025*	XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Allegheny Electric Cooperative, Inc	8004300327 8004300331 8004170733 8004170484 8004270401	XPORTLIC XPORTLIC 50-387 G 50-387 G NUREG
Amearth Excavators American Association for the Advancement of Science	8004300570 8004050535 8004090113#	40-3372 40-8502 COMMISSION
American Association of Physicists in Hedicine	8006240647	FOIA
American Electric Power Go , Inc	8006030296	NUREG
American Friends Service Committee American Mine Services, Inc American Nuclear Insurers	8006230059 8006180349* 8006030380 8006110050 8006120275	FDIA CONTRACT 50-320 J MISC 50-309 J
American Nuclear Society	8006170631 8006180408 8006110052* 8006200122 8006260210	MISC 50+320 J 50-361 0 27-39 27-39
American Warming & Ventilating, Inc Ames Laboratory, Energy & Mineral Resources Res Institute	8006200008 8006090552	50-327 S 71-5957
Ametek, Inc. Anaconda Co., Anaconda Copper Co. Div	8006230538* 8006060136 8006060140*	50-361 A Waste Mgt Waste Mgt
Anaheim, CA Analysis & Technology, Inc	6006190525* 6006190525* 6006190532* 6006190532* 6006270014*	50-361 I 50-361 I 50-361 I 50-361 I FDIA
Anderson-Greenwood & Ca Anefco, Inc. Applied Science Associates, Inc	8006270017* 8006030162* 8006130044 8006130045* 8006230200*	FOIA 0A999 71-9071 71-9071 CONTRACT
Argonne National Laboratory Arizona Public Service Co	8006040093 8006120476 8006260043 8006300032 8006030351	ORQ NUREQ NUREQ 40-465 50-528 8
	8004110308 8004230473 8004230473 8004230473 8004230474	50-528 T 50-528 K 50-528 K 50-528 K 50-528 A
	8004230474 8004230474 8004230477 8004230477 8004230477	50-528 A 50-528 A 50-528 K 50-528 K 50-528 K
	8004230480* 8004230480*	50-528 A 50-528 A

AUTHOR APT ILIAT LON	ACCESSION NUMBER	SUBJEC CATEGOI	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	RΥ
	8004230480* 8004230483 8004230483 8004230483 8004230484	50-528 50-528 50-528 50-528 50-528	A K K K		8006110142 8006110154* 8006110154* 8006110242 8006110242	50-313 50-313 50-313 50-313 50-313	R R F F
	8004230484 8004230484 8004230488 8004230488	50-528 50-528 50-528 50-528 50-528	С К К К		8006120277 8006120283* 8006120315 8006120316* 8006130264	50-313 50-313 50-348 50-368 50-313	8 P P
	8006230691 8006230691 8006230692* 8006230692*	50~528 50~528 50~528 50~528 50~528	F F C C		8006130326 8006170623 8006170625 8006170630* 8006170634*	50-368 50-313 50-368 50-313 50-368	8 8 8 9
	8006230692* 8006230693 8006230693 8006230693 8006230694	50-528 50-528 50-528 50-528 50-528	C A A K		8006170700 8006170700 8006180456 8006180458 8006180459*	50-313 50-313 50-368 50-368 50-368	888
	8006230674 8006230674 8006230695 8006230695 8006230695	50-528 50-528 50-528 50-528 50-528	K K K K		8006180460* 8006180463 8006180467* 8006180510 8006180510	50-348 50-348 50-348 50-313 50-313	8 8 F
	8006230696* 8006230696* 8006230696* 8006230697*	50~528 50~528 50~528 50~528 50~528	F F C C		8006180528 8006180528 8006190583 8006190589* 8006190686	50-313 50-313 50-368 50-368 50-313	P R R R
	8004230497* 8004230498* 8004230498* 8004230498*	50-528 50-528 50-528 50-529 50-528	G K K K		8006190689* 8006200369* 8006200430 8006200434*	50-313 50-348 50-368 50-369 50-368	8 9 9
	8006230701 8006230701 8006230702* 8006230702* 8006230702*	50-528 50-528 50-528 50-528 50-528	K C C C		8006200485 8006200489 8006200489 8006200493* 8006230401	50-349 50-313 50-349 50-313	8 9 8 P
	8006230703 8006230703 8006230703 8006230705* 8006230705*	50-528 50-528 50-528 50-528 50-528	к к С С		6006230412 8006230434 8006230439* 8006230450 8006230457*	50-316 50-313 50-313 50-368 50-368	9 8 8
	8006230705* 8006230710 8006230710 8006230710 8006230711	50-528 50-528 50-528 50-528 50-528	С К К К	Army, Dept. of	8006230530 8006240186* 8006020359 8006170437 8006250038*	50-348 50-313 50-387 50-409 CONTRACT	g D D
	8006230711 8006230711 8006230713 8006230713 8006230713	50-528 50-528 50-528 50-528 50-528	K K K K	Army.Dept of, Corps of Engineers Asher, T. R , PC	8004040384 8004200112 8004230054 8004300455* 8004170437	50-220 70-36 70-36 50-329 XPORTLIG	, A
	8006230714 8006230714 8006230714 8006230716 8006230716	50-529 50-528 50-528 50-529 50-528	K K K K	Association of Community Organizations for Reform Now-Texas Atlas Minerals	8006070005 8006070005 8006070007 8006070007	50~445 50~445 50~445 50~445 40~3453	9 9 9
	8006230716 8006230717 8006230717 8006230717 8006230718	50-528 50-528 50-528 50-528 50-528	K K K K	Atomic Industrial Forum	8006030286 8006030458 8006070114 8006120013 8006160236#	NUREG PR PR PR ORG	
	8006230718 8006230718 8006230720 8006230720 8006230720	50-528 50-528 50-528 50-528 50-528	K K K	Australia Automatic Switch Co Automation Industries, Inc.	8096270030 8096240116 8096240124 8096240460 8005070013	PR XPORTLIC XPORTLIC MIEC 71-9007	
	8006230721 8006230721 8006230721 8006230722 6006230722	50-528 50-528 50-528 50-528 50-528	K K K	BRK Electronica	8005070015# 8005070023# 8005070022# 8005070032# 8006120279	71-9007 71-9007 71-9007 71-9007 PR	
Arkansas Power & Light Co	8006230722 8006040051 8006050331 8006050331 8006060132	50-528 50-313 50-313 50-313 50-313	K G G G	Babench & Wilcox Co.	8004040054 8004040056* 8004040089 8004040092* 8004050159	71-135 71-135 70-824 70-824 70-824	
	8006070386 8006070374* 8006110001 8006110002* 8006110142	50-348 50-348 50-313 50-313 50-313	S R R R		8006120254 8006130269 8006160119* 8006160122	GAPPP 70-824 GAPPP 70-824	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łΥ
	8006170724 8006170729* 8006180162 8006180165* 8006180169*	70-1201 70-1201 70-824 70-824 70-824		Baldwin, W A Baltimore Gas & Electric Co	8006300323 8006300334 8006300340 8006040194 8005190447	50-466 50-466 50-466 50-275 50-317	000
	8006180344 8006180350* 8006180353* 8006180378 8006200132	70-135 70-135 70-135 70-135 70-824 70-27			8004020149 8004020149 8004020532 8004030237 8004030237	50-317 50-317 50-317 50-317 50-317	P P F F
	8006200165 8006200169* 8006200172* 8006230002 8006230072	70-824 70-824 70-824 70-135 70-27			8006030244 8006030244 8006040209 8006040209 8006040347	50-317 50-317 50-317 50-317 50-318	P P P ₽
	8006230272 8006230302 8006240315 8006240318* 8006250004	70-1201 70-1201 70-1201 70-1201 70-1201			8006040352* 8006050028 8006050035* 8006050039 8006050045*	50-318 50-317 50-317 50-318 50-318	888
	8004250011 8004250019 8004250111 8004250156 8004250160#	70-824 70-1201 70-364 70-824 70-824			8004040317 8004040317 8004090344 8004090348# 8004090345	50-317 50-317 50-317 50-317 50-317	F 8 8
	8006250208 8006250211* 8006270067 8006270071* 8006300023	70-824 70-824 70-824 70-824 70-364			8006070368* 8006120262 8006120276 8006170437 8006170441*	50-317 50-317 50-317 50-317 50-317	8 8 8 F
Babcock & Wilcox Co , Naval Nuclear Fuel Div		70-1201 70-1201 70-27		•	8004180240 8004180358 8004180358 8004180433	50-317 50-317 50-317 50-317	۵ ر ر 8
	8006180616 8006230052	70-27 70-27			8006180435 8006180436*	50-318 50-318	P
Babcock & Wilcox Co , Nuclear Material Div	8006230121 8006230125* 8006300524* 8006110085*	70-27 70-27 70-27 50-302	Р		8006180443* 8006180473 8006180480* 8006180483	50-315 50-318 50-318 50-318	8 8
	E006130062	71-9009			8004180490* 8004180515	50-318 50-318	8 8
	8006130064* 8006170798 8006190421 8006200156 8006200554	71-9009 70-135 70-364 70-364 70-135			6006180318* 6006190530 6006230270 6006240011	50-318 50-317 50-317 50-317	8 P P
	8006200585 8006200585 8006230103 8006240178	70-364 70-364 70-135 70-364			8006240020 8006240020 8006240320 8006240320	50-317 50-317 50-317 50-317	Q Q F
Baker & Botts	8006270177* 8006300590 8006300593 8006050085	70-135 70-135 70-135 50-466	٥	Battelle Memorial Institute, Columbus Laboratories	8006240339 8006240339 8006300313 8006040068	50-317 50-317 50-317 71-4400	9
	8006060478 8006060478	50-498 50-498	0	•	80060400B1 8006250064*	NUREO CONTRACT	
	8004090204 8004090215 8004110247 8004110340 8004110344	50-466 50-466 50-498 50-498 50-445	1000E		8006260048 8006270097 8006300183 8006300187	NUREO NUREO RES RES	
	8004120030	50-466	Q	Battelle Memorial Institute, Pacific Northwest Laboratory	8006020537	NUREC	
	8006120061 8006120064 8006120068 8006120070	50-466 50-466 50-466 50-498	0000		8006060005* 8006060008* 8006060010* 8006060014*	71-4986 71-4986 71-4986 71-4986	
	8006120097 8006120278 8006160166 8006160170* 8006170609	50-466 50-466 50-466 50-466 50-466	99999		8004040020* 8004040022* 8004040024* 8004040025* 8004040413	71-4984 71-4984 71-4984 71-4984 TOPREP	
	8006180196 8006180200* 8006180205* 8006180346 8006180398*	50-466 50-466 50-466 50-466 50-466	0000		8004070445 8004070502 8004170708 8004170716 8004170237	NUREO NUREO RES RES 70-8	
	8006180506 8006190343 8006200129 8006200129 8006240341	50-498 50-466 50-498 50-498 50-466	00000		8004200018 8004200298 8004200272* 8004200532 8004230017	RES 7 7 1	
	8004270327 8004300307 8004300317	50-466 50-466 50-466	000		8006230026* 8006230025* 8006230022*		

AUTHOR AFFILIATION	ACCESSION	SUBJECT	!Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8006250171 8006250342 8006250349 8006250352 8006260038	NUREO REB RES RES NUREO			8006230687* 8006230689* 8006230690* 8006230699* 8006230704*	50-344 50-344 50-344 50-344 50-344	P P P
	8004260045 8006270004 8006270019 8006270022 8006270362	NUREG 71-6387 NUREG NUREG NUREG			8004230707# 8006260344# 8006260363# 8006260395# 8006260401#	50-344 50-331 50-331 50-331 50-331	P G G
Bayly, Marfin & Fay Inc Bear Creek Uranium Co Bechtol Corp	8004120272 8004120101 8005300441	MISC 40-8452 50-482	S	Bechtel Power Corp (subs of Bechtel Corp)	8006300343* 8006060170*	CONTRACT 50-424	S
Becites, edit	8006110022* 8006110027*	50-348 50-348	P P	COTY /	8006060204* 8006110035* 8006110199*	50-424 50-361 50-416	8 Q A
	8006170333 8006230526* 8006230531* 8006230554* 8006230558*	REGGD 50-361 50-361 50-361 50-361	A A A		8004110202* 8004110203* 8004110208* 8004110211* 8004110215*	50-416 50-416 50-416 50-416 50-416	A A A A
	8004230405* 8004230404* 8004230407* 8004230408* 8004230409*	50-344 50-344 50-344 50-344 50-344	P P P P		8006110220* 8006110227* 8006110230* 8006130261* 8006130262*	50-416 50-416 50-416 50-237 50-237	A A A P P
	8006230610* 8006230611* 8006230612* 8006230613* 8006230614*	50-344 50-344 50-344 50-344	P P P	Beckman Instruments, Inc Binder, Elster, Mendelson & Wheeler, Inc	6006130263* 6006190360 6006200179* 6006120217 6006240649*	50-237 50-414 50-387 PR CONTRACT	P A B
	8004230415* #8004230414* #814023408	50-344 50-344 50-344	P P P	Bio-Dynamics, Inc (subs of Boehringer Manheim Corp)	8005220706	PR	
	8006230620* 8006230621*	50-344 50-344 50-344	ъ Б	Black Hills Alliance Booke B L Borg-Warner Corp Borg-Warner Corp , Nuclear Valve Div	8006120186 8006240459* 8006180356 8006200614	FOIA 40-1162 PT21 XPORTLIC	:
	8006230623* 8006230624* 8006230625 8006230626*	50-344 50-344 50-344 50-344	Р Р Р Р	Bostan Edison Co	8005200517* 8005030035 8005030310 8005030345 8005030346	XPORTLIC 50-293 50-293 50-293 50-293	
	8006230628* 8006230639* 8006230631* 8006230633*	50-344 50-344 50-344 50-344	P P P		8006030407 8006090385 8006090391# 8006120342	50-293 50-293 50-293 50-293	P 8 8
	8006230635* 8006230635* 8006230636* 8006230637*	50-344 50-344 50-344 50-344	P P P		8006130280 8006130303 8006160001 8006160069 8006180444	50-293 50-293 50-293 50-471 50-293	P F H R
	8006230639* 8006230640*	50-344 50-344	P P		8006180446* 8006170640	50-293 50-293	R R
	8004230441* 8004230443* 8004230444*	50-344 50-344 50-344	P P		8006170643* 8006240471 8006240477* 8006250242	50-293 50-293 50-293 50-293	2 2 2 3 3
	8006230645* 8006230646* 8006230648* 8006230649*	50-344 50-344 50-344 50-344	P P		8006250243* 8006250244 8006250246* 8006260179	50-273 50-273 50-273 50-273	8 8 8
	8004230450* 8004230451* 8004230452* 8004230453* 8004230455*	50-344 50-344 50-344 50-344 50-344	р Р Р Р	Breman,Univ of. Bristol Steel & Iron Works,Inc Brookhaven National Laboratory	8006270195 80062300585* 8006230214* 8006030308 8006030365 8006040118*	50-293 PRM GA999 TOPREP 50-331 50-320	GI F P
	8006230659* 8006230661* 8006230662* 8006230662*	50-344 50-344 50-344 50-344	р Р Р		8006040119* 8006050276 8006180261 8006180267 8006190070	50-320 50-237 RES RES RES	P F
	8006230664* 8006230665* 8006230666* 8006230667*	50-344 50-344 50-344 50-344	# P P		E006190079 E006200014 E006200022 E006200025 E006200026	RES RES RES RES RES	
	8004230467* 8004230470* 8004230472* 8004230475*	50-344 50-344 50-344 50-344	P P P		8006200027 8006200031 8006200583 8006230374 8006250201	RES RES NUREG 50-243 RES	F
	8006230679* 8006230682* 8006230684* 8006230685*	50-344 50-344 50-344 50-344	Р Р		8006260025 8006300171 8006300215	RES RES RES	

AUTHOR Affil1åtion	ACCESSION NUMBER	SUBJECT CATEGOR	\$Y	AUTHOR AFFILIATION	ACCESSION PREMUM	SUBJECT CATEGOR	
Brownsville.TX Bruce Norton Brush-Wellman, Inc Budd Co	B006300234 B006230157 B006110417 B006040080 B006040075*	RES 50-445 50-275 40-8722 71-9051	м Ф		8005160058 8006160070 8005160070 8005160070 8006160070	50-261 50-400 50-400 50-400 50-400	P & & & & & & & & & & & & & & & & & & &
Buffalo.NY C-E Power Systems	8006030153 8006090103* 8006170753 8006200151 8006300415	40-8502 0A999 70-1100 70-1100 TOPREP			800616075* 8006160145 8006160145 8006160145 8006160145	50-400 50-400 50-400 50-400 50-400	8 A A A
California, State of	8006020546* 8006050447 8006050453* 8006110056 8006120332	50-206 PR PR PROJ 50-275	P 0		8006160147* 8006160147* 8006160147* 8006160147* 8006160147*	50-400 50-400 50-400 50-400 50-324	A A A Q
California, Univ of, Berkeley California, Univ of, Los Angeles	8006160049 8006170277 8006160117 7910310452 8006240138	50-312 PR 50-142 PR PR	0		8006180228 8006180228 8006180361 8006180365 8006180425	50-324 50-324 50-261 50-324 50-324	0 9 9 9
California, Univ of, Santa Barbare Capital X-Ray Service Carolina Environmental Study Group Carolina Power & Light Co	8004030425 8004230518 8004040041 8004110244 8004020230	50-433 50-433 71-9039 70-2623 50-325	F F		8006180425 8006180447 8006180449* 8006180452 8006180454*	50-324 50-325 50-325 50-325 50-325	5 5 5 5
	8004020237* 8004030331 8004030331 8004030332* 8004030332*	50-325 50-324 50-324 50-324 50-324	P 8 8 8		8006180495 8006180469* 8006180481 8006180491 8006180493	50-324 50-324 50-325 50-261 50-261	8 9 P F
	8006030352 8006030374 8006030374 8006030376* 8006030376*	50-324 50-324 50-324 50-324 50-324	8 G G G		8006180496 8006180505* 8006190638 8006190664 8006190664	50-324 50-324 50-325 50-400 50-400	5 9 9 9
	8004030395 8004030397* 8004030470 8004030475* 8004040307	50-324 50-324 50-324 50-324 50-324	8 9 9 6		8006190664 8006190664 8006190672 8006230389 8006230389	50-400 50-400 50-261 50-324 50-324	G G P P
	8006040310* 8006040335 8006040337* 8006050009 8006050018*	50-324 50-325 50-325 50-325 50-325	6 9 8		8006230390* 8006230390* 8006230396 8006230398* 8006230572	50-324 50-324 50-261 50-261 50-261	8 6 6
	8004050251 8006050328 8006050332* 8006050370 8006050374	50-324 50-261 50-261 50-324 50-261	8 8 8		8006230584* 8006240285 8006240285 8006240285 8006240285	50-261 50-400 50-400 50-400 50-400	8 9 9
	8004040334 8004040342 8004090304 8004090304 8004090306	50-325 50-261 50-400 50-400 50-400	9 9 8 8		8006240312 8006240315 8006240315 8006240383 8006240438	50-261 50-324 50-324 50-400 50-261	F F 8 0
•	8004090304 8004090304 8004090310 8004090314 8004090325	50-400 50-400 50-261 50-325 50-325	8 8 8 8		8006240475 8006240497 8006240502* 8006250267 8006250267	50-324 50-219 50-219 50-324 50-324	8 8 8
	8004070327* 8004070347 8004070355* 8004070372 9004070378*	50-325 50-324 50-324 50-325 50-325	P 8 8 8	Carpenter Technology Carp	8004290301 8004300317* 8004020572 8004120111 8004120115*	50-261 50-255 XPORTLI XPORTLI XPORTLI	I Ç
	8006110092 8006110095* 8006110095* 8006110127 8006110133	50-324 50-324 50-324 50-325 50-255	R R R P R	Center for Development Policy Center for Lew & Social Policy	8004190439 8006230107 8006240204 800626020B 8006200369	XPORTLI FOIA XPORTLI XPORTLI 50-574	ic ic
	8006110136* 8006110184 8006110178* 8006110234 8006110234	50-255 50-325 50-325 50-400 50-400	# 8 8 8 8	Center for Law in the Public Interest Central & South West Corp Central & South West Services, Inc	8004040199 8006300643 8004110282* 8004170242 8004110375	50-275 50-275 50-445 50-445 50-445	₩
	8006110234 8006110234 8006110244 8006110244 8006110244	50-400 50-400 50-400 50-400 50-400	8 8 8 8	Chem-Nuclear Systems, Inc	8006240250 8005130121 8005270516 8005270925* 8005270926*	50-445 71-9096 71-9096 71-9096	6 4 4
	8006110244 8006110347 8006110358* 8006160025 8006160026*	50 -400 50-261 50-261 50-261 50-261	\$ 8 8 R R		8006030152 8006030161* 8006030164* 8006040076 8006190146	71-909/ 71-909/ 71-909/ 71-627/ 71-637/	4 4 5

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
Chemtron Corp , Tube Turns D)v Chicago Bridge & Iron Co Chictering & Gregory	8006300462 8006300470* 8006200024 8006130032 8006110014	27-47 27-47 50-204 71-15 50-361	s G	Commerce Dept of, National Bureau of Standards Commerce Dept of National Oceanographic &	8006060457* 8006170094 8006170106* 8006230047	70-398 71-390 71-390 70-398 NUREO	
	8006110014 8006110019* 8006110019* 8006110024* 8006110024*	50-361 50-361 50-361 50-361 50-361	Q Q Q Q	Atmospheric Adminstration Commonwealth Edison Co	8006200593 7903160172 8006020008 8006020091	NUREQ 50-237 50-237 PR	P Q
	8004110028* 8004110028* 8004110031* 8004110031* 8004110078	50-361 50-361 50-361 50-361 50-361	G G G		8004020248 8004020347 8004020347 8004020349* 8004020349*	TOPREP 50-295 50-295 50-295 50-295	P P P
, Christa-Maria	8006110098 8006110107* 8006110107* 8006170336 8006240358	50-341 50-341 50-341 PR 50-155	0		8004030042 8004030042 8004030042	50-10 50-10 50-10 50-10	թ թ
Cincinnati Gas & Electric Co	8004040138 8004120481 8004140154 8004170482 8004170501	PR 50-358 50-358 50-358 50-358	Q Q A Q		8006030072* 8006030072* 8006030072* 8006030072*	50-10 50-10 50-10 50-10 50-10	P P P P
CINICARA Assirat Nacional Succession	8906240064* 8906250340 8906260293* 8906300242	50-358 70-2838 50-358 50-358	a a		80060303072# 8006030309 8006030340 8006030349*	50-10 50-454 50-237 50-237	P H S
Citizens Against Nuclear Dangers Citizens Against Nuclear Power	8004040487 8004040487 8004170540 8004170540	50-387 50-387 50-599 50-599	0 0 0		8006030364 8006030379* 8006030394	50-237 50-237 50-237 50-237	8 8 8
Citizens Association for Sound Energy	8006170570# 8006170570# 8006060255	50-599 50-599 50-445	9		8006030478 8006030497 8006030506* 8006040203	50-237 50-295 50-295 50-249	9 8 8
	8004040255 8004040257* 8004040257* 8004040241*	50-445 50-445 50-445 50-445	0		8006040208* 8006060242* 8006060243* 8006060246*	50-249 50-295 50-295 50-295 50-295	80000
Citizens Concerned About Nuclear Power, Inc Citizens for Equitable Utilities	8004040261* 8004040344 8004190595 8004190595	50-445 50-445 50-498 50-498	0		8006090047* 8006090047* 8006090048 8006090256	50-454 REQQD 50-295	Q P
Citizens for Fair Utility Regulation Citizens for Safe Environment	8006090001 8006060245	50-445 50-320	9 9		8006070274 8006070274	50-295 50-295 50-295	F F P
Citizens for the Conservation of Natural Resources: Inc Clark Dietz Engineers Clermont County, OH Cleveland Electric Illuminating Co	8006170132 8006200117* 8006170355 8006240378	50-376 70-36 50-358 50-440	0		8006070305 8006070356 8006070363* 8006110034 8006110040	50-254 50-254 50-254 50-454	P P R
	8006270278 8006270278 8006270280* 8006270280* 8006270285*	50-440 50-440 50-440 50-440 50-440	C C C C		8006110078 8006110078 8006110084* 8006110084* 8006110100	50-254 50-254 50-254 50-254 50-10	R R R R
	8006270285* 8006270295 8006270295 8006270298* 8006270298*	50~440 50~440 50~440 50~440 50~440	C I I I		8006110102* 8006110111 8006110115* 8006110120 8006110125*	50-10 50-304 50-304 50-304 50-304	8 8 8
Cleveland, CH Cleveland-Cliffs Iron Co Coalition for a Non-Nuclear World Cohn, D B	8006060314 8006020458 8006120253 8006300576* 8006300376	50-346 40-8714 40-8714 FOIA 50-367	н		8006110141 8006110151* 8006110304 8006110312* 8006110320	50-254 50-254 50-254 50-254 50-265	8 8 8 8
Colorado State Univ, Colorado, State of Colt Industries, Inc., Fairbanks Morse	8006040173 8006090551 8006120154 8006120372 8006200012	WASTE MO WASTE MO WASTE MO PRM 50-375	Ŧ		8006110330* 8006110363 8006110369* 8006120125 8006130138*	50-265 50-265 50-265 PR 50-10	9 9 9
Engine Div Columbia Univ Combustion Engineering, Inc	8006070352 8006060315* 8006060317* 8006060321*	50-208 50-335 50-335 50-335	F P P		8006130142* 8006130165 8006130165 8006130260 8006160071	50-10 50-295 50-295 50-237 50-295	Q P
	8006060326* 8006060327* 8006190417 8006200426* 8006200428*	50-335 50-335 70-34 50-307 50-307	P P P		8006160071 8006160097 8006160102* 8006160121 8006160125*	50-295 50-237 50-237 50-249 50-249	P 8 8
Commerce:Dept of	8006230543* 8006230547* 8006250034*	50-361 50-361 CONTRACT	A		8006170160 8006170218 8006170218	50-454 50-295 50-295	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFF1LIATION	ACCESS LON NUMBER	SUBJECT CATEGOR	
	8006170448 8006170448 8006170452* 8006170457* 8006170459*	50-10 50-10 50-10 50-10 50-247	R R R P		8005240318* 8005240490 8005240490 8005240490 8005240490	50-10 50-10 50-10 50-10 50-10	F F F F
	8006170459* 8006170459* 8006170459* 8006170461* 8006170470	50-247 50-247 50-247 50-10 50-295	ዞ የ የ		8006250266# 8006250277 8006250277 8006250277 8006250277	50-373 50-237 50-237 50-237 50-237	0 P P
	8006170475* 8006170498 8006170505* 8006170510 8006170519*	50-295 50-295 50-295 50-237 50-237	5 6 5 5 5		8004240312# 8004270248 8004270251 8004270252# 8004270254	50~454 50~295 50~295 50~295 50~295	9 9 9 9
	8004170559 8004170481 8004170814 8004180278 8004180278	50-254 50-10 PR 50-373 50-373	F H A A		8006270256* 8006270259* 8006270266 8006270272* 8006270273	50-295 50-295 50-265 50-265 50-265	5 9 9 8 P
	8006180281* 6006180285* 6006180285* 6006180273 6006180315*	50-373 50-295 50-295 50-10 50-10	A B B F F		8006270277* 8006270306 8006270306 8006270306 8006270306	50-265 50-10 50-10 50-10 50-10	P P P P
	8004180317# 8004180324# 8004180324# 8004180331# 8004180331#	50-10 50-10 50-10 50-10 50-10	F F F		8004270304 8004270304 8004270304 8004270329 8004270329	50-10 50-10 50-10 50-295 50-295	6 6 6
	8006180331* 8006180340* 8006180340* 8006180347* 8006180347*	50-10 50-10 50-10 50-10 50-10	# F F		8006300403 8006300407* 8006300412* 8006300453 8006300358	50-295 50-295 50-295 50-373 50-10	5 8 4 0
	8006180347* 8006180347* 8006180347* 8006180347*	50-10 50-10 50-10 50-10 50-10	F F F F	Comsip.Inc , Delphi Systems Di∨	8006300558 8006300558 8006300558 8006110166* 8006300397*	50-10 50-10 50-10 50-416 50-390	0 0 8 A
	8006180347* 8006180347* 8006180364 8006180364 8006180369*	50-10 50-10 50-373 50-373 50-373	F K K K	Conference of Radiation Control Program Directors, Inc Connecticut Yankee Atomic Power Co	8006130003* 8006020203 8006020203 8006030510 8006030518*	COMMISSI 50-213 50-213 50-213 50-213	ION P P S S
	8006180369* 8006180550* 8006180552* 8006190305 8006190305	50-373 50-373 50-373 50-10 50-10	K G P P		80040303187 8004110237 8004120270 8004120375 8004130270	50-213 50-213 50-213 50-213 50-213	F 8 6 8
	8006190307 8006190307 8006190307 8006190307 8006190307	50-10 50-10 50-10 50-10 50-10	P P P P		8006130316 8006130329 8006170526 8006170528* 8006190457	50-213 50-213 50-213 50-213 50-213	P R R
	8006190307 8006190419 8006190419 8006190419 8006190419	50-10 50-237 50-237 50-237 50-237	P P P P	ø	8006190457 8006200456 8006200571 8006240017 8006240297	50-213 50-213 50-213 50-213 50-213	P P G S
	8006190456 8006190456 8006190456 8006200104 8006200168*	50-10 50-10 50-10 REGGD 50-265	P P		8006240301* 8006270198 8006300383 8006300383 8006300420	50-213 50-213 50-213 50-213 50-213	ងមាន
	8004200384 8004200555 8004200555 8004230194 8004230318*	50-10 70-2609 70-2609 50-249 50-454	р Ф	Conner, Moore & Corber	8006060262 8006060547 8006060547 8006090069	50-320 50-320 50-320 50-272 50-272	00000
	8006230340 8006230381 8006230387* 8006230391 8006230392*	50-295 50-249 50-249 50-254 50-254	8 8 8 8		8006130024 8006160156 8006180509 8006180513* 8006190501	50-272 50-358 50-272 50-272 50-358	TOGOG
	8006230559 8006230565* 8006230570 8006230577* 8006240274	50-249 50-249 50-249 50-249 70-2609	\$ 8 8 8	Conover & Associates, Inc. Insurance Consolidated Edison Co. of New York	8004200547* 8004200547* 8004140020 8004040280 8004040521	50-272 50-272 70-1621 50-247 50-247	0 0 F 0
	8005240274 8005240315 8005240315 8005240315 8005240318*	70-2607 50-10 50-10 50-10 50-10	F F F		8004110051 8006110471 8006130294 8006160063	50-247 PR 50-247 50-247	P P 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGORY
	8006160068* 8006160108 8006160108 8006170431 8006170431	50-247 50-247 50-247 50-3 50-3	\$ P P R	•	8006160051 8006160139 8006170515 8006170527* 8006170529*	50-255 F 50-155 0 50-155 S 50-155 S 50-155 S
	8006170431 8006170434* 8006170434* 8006170434* 8006170451	50-3 50-3 50-3 50-3 50-247	ត ត ត ក P		8006170534* 8006170593 8006170670 8006170706 8006170870	50-155 S 50-265 G 30-155 P 50-155 S PR
	8006170454* 8006170454* 8006180426 8006180426 8006180426	50-247 50-247 50-3 50-3 50-3	P R R		8006180166* 8006180242 8006180266 8006180266 8006180362	50-255 Q 50-330 A 50-329 S 50-329 S
	8006180427* 8006180427* 8006180427* 8006180434 8006180526	50-3 50-3 50-3 50-247 50-247	Я Я Р Р		8006180362 8006180469 8006190414 8006190422* 8006190426*	50-329 K 50-329 B 50-255 B 50-255 B 50-255 B
	8006180527 8006170535 8006170541* 8006170626 8006170630*	50-3 50-247 50-247 50-247 50-247	R S S R R		8006190428* 8006190431* 8006190524 8006200352 8006200356	50-255 \$ 50-255 \$ 50-255 0 50-255 0 50-155 0
	8006240349 8006240350* 8006240352* 8006240354* 8006240361	50-247 50-247 50-247 50-247 50-247	Р Р Р Р		8006200361 8006200361 8006200365* 8006200365* 8006200445	50-329 A 50-329 A 50-329 A 50-329 A 50-255 Ø
Construction Technology Laboratories	8006240364* 8006240367* 8006250257 8006260212 8006200147*	50-247 50-247 50-247 50-247 50-482	P P G P		8006200448* 8006200499 8006200537* 8006200537* 8006230213	50-255
(div of Portland Gement Assoc) Consumers Power Co	8006020272 8006030077 8006040300 8006040303*	50-255 PR 50-155 50-155	P S S		8006240128 8006240253 8006240379 8006240379 8006240409	50-155 0 50-255 P 50-327 K 50-327 K 50-327 A
	8006040311 8006040313* 8006040315* 8006040316*	50-255 50-255 50-255 50-255 50-255	Ե Ե Ե	•	8006240409 8006240508 8006240513* 8006240585 8006240585	50-327 A 50-255 B 50-255 B 50-327 Q 50-327 Q
	8006040320* 8006040323* 8006040325* 8006040330* 8006050044	50-255 50-255 50-255 50-255 50-329	P P P O		8006250268 8006260342* 8006270209 8006270307 8006300277	50-155 P 50-329 Q 50-255 Q 50-155 S 50-329 S
	8006050044 8006050533* 8006060017 8006060465	50-329 50-255 50-329 50-329 50-255	0 0 0		8004300377 8006300439 8006300439 8006300513 8004300517*	50-255 P 50-329 R 50-329 R 50-255 P 50-255 P
	8004090291 000000000 80000000 80000000 800000000	50-255 50-255 50-329 50-329 50-329	ም K K K	Container Research Corp Cook County Hosp Chicago, IL Cornell Univ	8006300530* 8005120005* 8006030127 8006040167 8006230164*	50-255 0 71-5450 PR 50-157 P CONTRACT
	8004090309* 8004090312* 8004090312* 8004090557 8004110048	50-329 50-329 50-329 PR 50-155	K K	Coulee Region Energy Coalition Council on Environmental Guality Critical Mass Energy Project Cumberland County, PA Cutler-Hammer,Inc	8006170125 8005280885 8006300396 8006120324* 8006030270	50-409 0 PR 50-367 0 50-269 F 50-440 8
	8006110072* 8006110073 8006110130 8006110132* 8006110153	50-155 50-329 50-255 50-255 50-255	я н в е	Cyprus Mines Corp D'Appolania Consulting Engineers, Inc DNA - People's Legal Services,Inc	800602059Q 8006040179 8006170366 8006030243* 8006200064	WABTE MOT WABTE MOT WABTE MOT 40-1162 FOIA
	8006110157* 8006110165 8006110487 8006120045 8006120045	50-255 50-255 PR 50-327 50-329	Р С С	DRG International Inc Daedalean Associates Inc Dairyland Power Cooperative	8006250336 8006200017 8006020545 8006040031* 8006050363	XPORTLIC RES 50-409 G 50-409 G
	8006120144 8006120263 8006120308 8006120384 8006130124*	REGOD 50-255 50-155 50-255 50-255	0 0 P 0		8006090316 8006110343 8006130273 8006130276* 8006170468	50-409 P 50-409 F 50-409 R 50-409 R 50-409 J
	8006130136* 8006130247 8006130285 8006160005 8006160005	50~255 50~255 50~255 50~329 50~329	Q Q S S	Dallas Power & Light Co Dames & Hoore	8006180523 8006200420 8006110282* 8006130250* 8006270033*	50-409 P 50-409 P 50-445 M CONTRACT PR

AUTHOR AFF!LIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Dartmouth College Data Consultants, Inc Dattilo, T (8006260421 8006250210* 8005210208* 8005210208* 8006130187*	50-544	- т т н		8006050344* 8006050345* 8006050345* 8006050361 8006060281*	50~269 S 50~413 S 50~413 S 50~270 P 50~269 0
Dauphin County, PA DeKalb Area Alliance for Responsible Energy	8006130187* 8006120327* 8006060232	50-289 50-454	Н F O		8004040281* 8004040281* 8004040281* 8004040281*	50-269 0 50-269 0 50-269 0 50-269 0
DaMent Laboratories Debevoise & Liberman	8004020414* 8005230577	MIBC 50-249	G		8006060281* *8006060286	50-269 0 50-269 0
	8004050458 8006050555 8006050555 8006060267 8006060267	50-445 50-269	អ ម g g		#86204098 #862040368 #862040368	50-249 0 50-249 0 50-249 0
	8006060267 8006060267 8006060281* 8006060281*	50-269 50-269 50-269 50-269	G G G		8006060286* 8006060345 8006060364 8006090142 8006090266	50-269 0 50-369 A 50-269 P 50-491 Q 50-369 A
	8004060284* 8004060286* 8004040286* 8004060347	50-269 50-269 50-269 50-445	0 0 0		8006090343 8006090343 8006090347* 8006090360 8006090560	50-413 8 50-413 8 50-413 8 50-413 5 50-369 0
	8004040541 8004040541 8004040541 8004090175 8004090175	50-445 50-445 50-445 50-445	н н н и		8006110071 8006110076* 8006110101 8006110105* 8006110144	50-287 8 50-287 8 50-269 8 50-269 8
	8006090175 8006110205 8006110297 8006110302 8006110302 8006110454	50-369 50-468 50-445	н е е н н		8006110144 8006110144 8006110158* 8006110158*	50-269 P 50-269 P 50-269 P 50-269 P 50-269 P
	8006120024 8006120052 8006120398 8006170133 8006170141*	50-488 50-445	O M T		8004110205 8004110277 8004110277 8004110277 8004110297	50-367 Q 50-408 Q 50-409 Q 50-488 Q 50-270 S
	8006170157* 8006170423 8006170847 8006180517 8006240143	PRM 70-2623 PR	ç o		8004110326# 8006110327 8004110327 8004110351 8004110351	50-270 B 50-369 A 50-369 A 50-269 P 50-269 P
Dafense, Dept of Delaware, State of	8006250253 8006060167 8006060028 8006110164	50-369 PR	0 T		80061 10351 80061 10354 80061 10354 80061 20024 80061 201 34*	50-267 P 50-367 A 50-367 A 50-488 G 50-370 G
Denver.Univ of. 8006030055*	CONTRACT				8006120139* 8006120367	50-370 G 50-369 A
Detroit Edison Co	8006230040* 8006030613* 8006040253 8006170408* 8006230681	CONTRACT NUREG 50-341 50-341	G I G		8006120367 8006120370* 8006130D53* 8006130283	50-367 A 50-369 A 50-413 G 50-269 S
	8006230881 8006240481 8006270230 8006270282 8006270286*	50-341 50-341 50-341 50-341 50-341	9 6 8		6004130284* 6004130322 6004130322 6004130322	50-269 8 50-269 P 50-269 P 50-269 P
Døggett, S A	8004270330 8004270334* 8004300544 8004190549	50-341 50-341 50-341 50-341 50-466	5 G		8004140032 8004140033* 8004140074 8004160074 8004140074	50-270 P 50-270 P 50-269 F 50-269 F 50-269 F
Doherty, J F Dow Chemical Go Dow Chemical Go , Dow Chemical U S A	8006190101 8006300454 8006190582	50-466 TOPREP 50-264	o F		8006170141* 8006170157* 8006170229 8006170229	PRM PRM 50-267 P 50-267 P
Div Duke Power Co	8006020341 8006020343+ 8006020548 8006030130	50-267 50-267 NUREO PR	S		8006170229 8006170234* 8006170234* 8006170234*	50-269 P 50-269 P 50-269 P 50-269 P
	8004040217 8004040217	50-249 50-249	P P		8006170423 8006170458	70-2623 50-269 P
	8006040217 8006040221* 8006040221*	50-269 50-269 50-269 50-269	P P		8006170459 8006170459 8006170523 8006170530* 8006170637	50-269 P 50-269 P 50-269 S 50-269 B 50-369 S
	8006040278 8006040302* 8006050108	50-269 50-269 50-269	8 8 F		8006170637	50-369 B
	8006050241	50-270 50-413	8		9006170969 9006180237 9006190254	PR 50-367 0 50-269 0
	8006050337 8006050343	50-413 50-269	8 8		8006180254	50-267 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8006180254 8006180478 8006180478 8006180478 8006180517	50-269 Q 50-269 P 50-269 P 50-269 P 50-269 Q		8006170532 8006170558 8006170563* 8006170571* 8006170576*	50-334 P 50-334 S 50-334 S 50-334 S
	8006180517 8006180517 8006180517 8006180517 8006200065	50-269 0 50-269 0 50-269 0 50-269 0 70-2623		6006170315 8006170321* 8006200310 8006200450 8006230557	50-412 B 50-412 B 50-334 P 50-334 H 50-334 B
	B006200562 B006230360 B006230360 B006240117# B006240143	50-269 P 50-369 G 50-369 G 50-269 G 50-488 G		8006230562* 8006240291 8006240379 8006240429 8006250260	50-334 8 50-334 F 50-334 8 50-334 0 50-334 8
	8006240207 8006240207 8006240228 8006240228 8006240228	50-249 F 50-249 F 50-488 Q 50-488 Q	E 1 du Pont de Nemaurs & Ca , Inc EG&G Idaha,Inc	8006300552 8006060446* 8006020184 8006020481 8006020503	50-334 Q 71-5607 RES RES RES
	8006240248 8006240248 8006240282 8006240282 8006240411	50-269 Q 50-269 Q 50-413 Q 50-413 Q 50-413 S		8006120503 8006180026 8006180038 8006180097 8006180306	50-324 P REG REG RES RES
	8006240465 8006240485 8006240506 8006240512* 8006250251	50-269 P 50-369 A 50-270 S 50-270 S 50-488 Q		8006190685 8006200542 8006200572 8006270045 8006300301	RES NUREO NUREO RES
	8006250253 8006250255 8006260169 8006260174 8006260175*	50-367 Q 50-287 S 50-287 S 50-267 S 50-267 S	EO&O, Inc	8006300455 8006300506 8006300514* 8006300520* 8006020138	NUREO NUREO NUREO REB
	8004240233 8004240233 8006270219 8006270219 8006270248	50-269 P 50-269 P 50-413 Q 50-413 Q NUREO		8006020141 8006020144 8006020537 8006020546 8006020552	res Res Res Res
	\$100023008 \$100023008 \$0410023008 \$150023008 \$150023008	50-369 Q 50-369 Q 50-269 Q 50-269 Q 50-269 Q		8006020561 8006020568 8006130040# 8006130373 8006200041	res res 50-266 p res res
	2120023008 2006300342 2320063008 2320063008 44320063008	50-269 0 50-269 P 50-269 P 50-269 P 50-269 P		8006200047 8006260004 8006260009 8006260015 8006260020	50-250 P 50-287 P 50-295 P REB REB
Dequesne Light Co	8004300344* 8004300344* 8004300404 8004020021* 8004020358	50-267 P 50-267 P 50-267 P 50-334 Q 50-334 S		8004240031 8004240035 8004240037 8004240039 8004240042	reo Reo Reo Reo Reo
	6006020362* 6006030262* 8006030406 8006030415* 8006060365	50-334 8 50-334 Q 50-334 8 50-334 8 50-334 8		8006240046 8006300506 8006300514* 8006300520* 8006300574	RES NUREO NUREO NUREO 50-269 P
	8006060374* 8006060379 8006060381* 8006060385* 8006060390	50-334 S 50-334 R 50-334 R 50-334 S 50-334 R	Ebasco Services, Inc (subs of Ensurch Corp) Eberline Instrument Corp Ed L. Roed & Associates, Inc	8006180247 8006180253* 8006120445 8006200268 8006060147*	50-281 P 50-281 P XPORTLIC XPORTLIC WASTE MOT
	8006060391* 8006090137 8006090373 8006090382* 8006090389*	50-334 R 50-334 Q 50-334 8 50-334 8 50-334 B	Edison Electric Institute Ediaw International Co	8006040003 8006050494 8006120361# 8006130041 8006170862	PR PR SECY XPORTLIC XPORTLIC
	8006110061 8006110108 8006110112* 8006110121	50-334 G 50-334 S 50-334 S 50-334 S 50-334 S	Electric Power Research Institute Energy Daily, Inc	8006200249* 8006300019 8006020209* 8006040322 8006180087*	40-8576 70-1252 GEN TEC IS NUREO CONTRACT
		50-412	Energy Fuels Nuclear, Inc Energy, Dept of	8006120459 8006180156 8006200634 8006240531 8006020344	40-8691 40-8691 40-8691 40-8681 HISC
		50-334 8 10-334 8 10-334 R 10-334 R 10-334 B		8004020415 8004040088 8004050445 8004040008*	71-6400 71-9853 PR 71-4986

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	8004040010* 8004040014* 8004040020* 8004040022* 8004040022*	71-4786 71-4786 71-4786 71-4786 71-4786		6006060341 6006060342 6006060342 6006070092	50-250 50-250 50-250 PR 50-231	P P P
	8005050025* 8006060438 8005060442* 8005090098 8005090125	71-4986 71-5607 71-5607 50-561 A REGOD		6006090342* 6006090390 6006090393* 6006090393*	50-251 50-250 50-250 50-250 50-250	G P P P P
	B006120453 B006160214 B006160218* B006160221* B006160222*	71-5939 ORO ORO ORO ORO		8006090397* 8006090397* 8006110025 8006110033* 8006110037	50-250 50-250 50-250 50-250 50-335	P P 9 8 8
	8006160226* 8006160228* 8006160230* 8006180313 8006190645*	ORO ORO ORO FOIA 50-344 I		8006110042# 8006110099# 8006110099# 8006110217	50-335 50-250 50-250 50-250 50-250	90000
	8006200276 8006200380 8006240094 8006260073 8006270027*	XPORTLIC 50-201 H 50-201 H 50-201 H 50-317 P		8006130254 8006170171 * 8006170267 8006170273 * 8006170467	50-250 50-250 50-389 50-389 50-250	F G M M
y.Dept of, Clinch River Breeder tor Plant	8006300483 8006110301	71-6697 50-537 B		0006170467 0006170467 0006170471#	50-250 50-250 50-250	R R R
onmental Coelition on Nuclear Power	8006270205 8006270223* 8006040264	50-537 B 50-537 B 50-387 0		8006170474* 800617047 7 *	50-250 50-250	R
onmental Policy Institute onmental Protection Agency	8004040377 8004090002 8004140047* 8004170778 8004030343	50-387 Q 50-387 Q 50-289 Q PR 50-387 D	•	8006170479* 8006170542 8006170551* 8006170647 8006170652*	50-389 50-335 50-335 50-335 50-335	M 88 88 88
	8004040145 8004110103 8004110264 8004130031* 8004200543	PR 50-320 R 50-409 D COMMISSION NUREO		8004170475 8004170494* 8004180021* 8004180024* 8004180090	50-335 50-335 50-250 50-250 98	8 0
onmentalists, Inc , E P , om Supply Agency (Belgium) ,ean Communities, Commission of	8006240246* 8006060435 8006120293 8006240129 8006030230	CONTRACT 70-1729 ACRB XPORTLIC XPORTLIC		80061 80471 80061 90258 80061 90285# 80061 90301 80061 90301	50-335 50-251 50-251 50-335 50-335	4 4 8 8 4 4
presn Legal Services Corp /Warner Associates, Inc 1 Minerals Co . USA	8004030238 8004190047 8004090143 8004200093* 8004030124	XPORTLIC XPORTLIC 50-522 A CDNTRACT 40-8064		8006190646 8006200216* 8006200216* 8006200479 8006200479	50-250 50-250 50-250 50-250 50-250	99000
1 Nuclear Co., Inc. (subs. of Exxon	8004230427 8006170535	40-8102 TOPREP		6006230166# 6006230184	50-335 50-250 50-250	0 0 8
1 }	8006200081 8006200083* 8006240424	70-1257 70-1257 TOPREP		8006230464 8006230464 8006230476#	50-335 50-335 50-335	8
	8006250100 8006250105* 8006250146 8006300621	TOPREP TOPREP 70-1257 71-6581		8006230483 8006230475* 8006230555 8006230564*	50-335 50-335 50-250 50-250	8 8
al Emergency Management Agency	8004300623* 8004300627* 8004300628* 8004050502*	71-6581 71-6581 71-6581 State Prog		8006230567 8006230571* 8006230576 8006230579 8006230581	50-251 50-251 50-387 50-250 50-250	8 8 8
ral Energy Regulatory Commission ral-State Reports Inc	8006170808* 8006180407 8006200227 8006130308 8006270344	50-171 H PR PR 50-387 D NUREO	•	8006230586* 8006230588* 8006240187 8006240192 8006240196	50-250 50-250 50-335 50-250 50-250	8 8 F F
and schaker, D B	8009090031 8009150505	XFORTLIC 50-275 0		8006240261 8006230203	50-250 50-335	P
ida Power & Light Co	8004180517 8004030053 8004030053 8004030443	50-275 Q 50-250 P 50-250 P 50-335 B		8006250294 8006250304 8006250307	50-335 50-250 50-335	G G
	8006030449* 8006030454 8006030456* 8006040021*	50-335 8 50-251 8 50-251 8 50-250 0		8004240129 8006260129 8006270311 8006270314* 8006270317*	50-250 50-250 50-335 50-335 50-335	G G P P
	8006040025* 8006050235	50-250 Q 50-335 P 50-335 8		8006300021 8006300021	50-250 50-250 50-250	a 0
	8006050325 8006060310 8006060341	50-335 8 50-335 P 50-250 P	Florida Power Corp	8006300579 8006020159 8006020403	20-305 20-305 20-320	Fa

AUTHOR AFFILIATION	ACCESSION NUMBER	GUBJEC CATEGO		AUTHOR AFFIL IATION	ACCESSION NUMBER	SUBJE CATEO	ORY
	8006030303 6006030304* 8006030323 8006030493 8006030500*	50-302 50-302 50-302 50-302 50-302	5 8 9 6		8005270351* 8005270066 8005270070* 8005270075* 8005270083*	71-904 71-904 71-904 71-904	4 4 4
	8004030505 8004030508> 8004040354 8004040355* 8004040541	50-302 50-302 50-302 50-302 50-302	8 8 8 9		8005290087* 8005290091* 8005290095* 8005290100* 8005290105*	71-904 71-904 71-904 71-904 71-904	4 4 4
	8004110123 8004110123 8004110128 8004110134* 8004110140*	50-302 50-302 50-302 50-302 50-302	P & & & & & &		8005270111* 8005270115* 8005270120* 8005270123* 8006020243*	71-904 71-904 71-904 71-904 50-325	4 4 4
	8006110185 8006110290 8006110475 8006170436 8006170484	50-302 50-302 PR 50-302 50-302	G G G		8004020247 8004020270 8004030019 8004030022* 8004030025*	TOPREP TOPREP 71-905 71-905 71-905	0 0
	8006170488 8006170740 8006180511 8006180531 8006170 5 76	50-302 50-302 50-302 50-302 50-302	P G K F S		8006030031* 8006030034 8006030037* 8006030041* 8006030044*	71-9050 71-904 71-904 71-904 71-904	5 5 5
	8006190603* 8006190617 8006190621* 8006190683* 8006200357	50-302 50-302 50-302 50-302	8 R R G		8006030048# 8006030489 8006040032# 8006040067# 8006040070#	71-9045 REGOD 71-9005 71-9051 71-9051	i i
	8006230403 8006230403 8006230485 8006240326 8006240419	50-302 50-302 50-302 50-302 50-302	5 9 9 8		8006040072* 8006060067 8006060074* 8006060078* 8006060390*	71-9051 71-9001 71-9001 71-9001 50-333	i I
	8006240446 8006240446 8006240450* 8006240475 8006240573*	50-302 50-302 50-302 50-302 50-302	8 6 1 0		8006070016* 8006070038 8006070504 8006110278* 8006110317	50-245 XPORTL1 XPORTL1 70-1305 TOPREP	l C
	8004270283 8004270347* 8004270353* 8004300374 8004300378	50-302 50-302 50-302 50-302 50-302	P P G S		8006120247 8006120365* 8006120464 8006120510 8006130013*	REB BECY 71-9044 50-392 70-1007	P
Florida, Univ of, Gainasville	8004300401* 8004300550 8004020345 8004090485* 8004230133*	50-302 50-302 50-83 50-83 CONTRACT	8 9 9 0		8006130015* 8006170721 8006170424 8006200608 8006240114*	70-1007 RES 70-754 Nureo Gaggg	
Forelaws on Board Foxboro Corp Franklin Institute/Franklin Research Genter	8006270073 8006110235 8006120472* 8006030040*	NUREG 50-514 GA999 50-293 50-293	O F		8006240149 8006240202 8006250347 8006260084* 8006260088*	70-1308 70-1308 PR TOPREP TOPREP	
Friends of the Earth	8006030047# 8006120296 8006120299 8006170732 8006200569	50-293 ACRB ACRB CONTRACT	F		8005260425 8005250431# 8005250499* 8005270035 8005300335	REB 50-331 50-331 NUREQ 71-5926	q q
Gary, IN	B005300395	50-574 50-367	o o	General Electric Co , Nuclear Energy Products Div	8006090489	70-1113	
General Atomic Co (subs of Gulf Oil Co)	8006040252# 8006040254* 8006040258* 8006040262#	70-2523 SECY SECY 70-2523			8006120480# 8006130006 8006160220 8006160223	71-9044 70-1007 70-1308 70-1113	
General Dynamics Corp , Electric Boat Div	8006040264* 8006060154 8006120273 8006200565 8006120142	SECY PR XPORTLIC 70-734 71-9039			8006180357 8006180363 8006170184 8006200125 8006200127	PT21 70-1113 70-754 70-754 70-754	
General Electric Co	8005210456 8005210460* 8005210461* 8005210465* 8005210469*	71-5942 71-5942 71-5942 71-5942 71-5942			8004200431 8004200544 8004230045 8004230287 8004270345	70-1113 70-1113 70-1113 70-77B 70-1113	
	8005210472* 8005210475*	71-5942 71-5942		General Public Utilities - GPU Service	6004270369 8004020354	70-1113 50-320	P
	8005210479* 8005210481* 8005270339	71-5942 71-5942 71-5942 71-9046		Gorp	8004030411 8004040213 8004170495	50-320 50-287 50-320	J 9 P
	8005270342* 8005270345* "13270348*	71-9046 71-9046 71-9046			8006170495 8006170711 8006170711	50-320 50-320 50-320	P I I

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
Ceneral Services Life Insurance Co Georgia Institute of Technology	8006240498 8006300441 8006170813 8006020421 8006110118	50-219 50-219 FOIA 50-160 50-160	J F 8		8006200481* 8006200483* 8006230218* 8006230218* 8006230522	50-366 8 50-366 8 50-321 0 50-321 5
Georgia Power Co	8006250248 8006020483 8006020499 8006020518 8006020565	50-160 71-6601 71-6144 71-6275 71-5026	F		8006230548 8006230574 8006230580 8006240277 8006240276	50-321 8 50-321 8 50-321 9 50-424 0 50-321 0
	8006020569 8006030241 8006030413 8006030432* 8006030435	71-9044 50-321 50-321 50-321 50-366	8 8 8		8004240274 8004240325 8004240431 8004240436* 8004240442	50-321 0 50-321 0 50-366 8 50-366 8
	8004030445* 8004030458 8004030442* 8004050334 8004050335*	50-366 50-321 50-321 50-366 50-366	9 9 8 8		8006240454 8006240455* 8006240458* 8006240507 8006240514*	50-366 B 50-366 6 50-366 B 50-366 B 50-366 B
	8004050338 8004050340* 8004050347 8004050348 8004050349*	50-346 50-346 50-321 50-346 50-321	8 8 8	Georgia, State of	8006250072 8006250249* 8006250249* 8006270337 8006240262*	50-321 0 50-321 0 50-321 0 50-424 8 State Prog
	8004050355# 8004050340 8004050345 8004050346# 8004050347	50-344 50-344 50-344 50-346 50-321	8 8 8 8	Georgia, Univ of, Oibson, Dunn & Crutcher Oilbert/Commonwealth Cos	8006270020* 8006050454 8006200150 8006030326* 8006060222*	50-317 P 71-389 PROJ 50-302 P GA979
	8004050372* 8004050373* 8004050541 8004050541 8004050541	50-366 50-321 71-5026 71-5026 71-5026	8 6	Goldberg, Fieldman & Letham, P C Golder Associates	8006060229* 8006170365 8006170641 8006060314 8005130516*	GA999 50-395 A 50-395 A 50-346 M WASTE MOT
	8004050541 8004050541 8004060374	71-5026 71-5026 50-321 50-321	P P	Gould-Brown Boyeri Gulf Gil Corp , Gulf Mineral Resources	8006130007* 8006090478 8006120284	CONTRACT 50-358 S Wabte Mot
	8004040374 8004090327	50-321	8	Co Oulf States Utilities Co	8004120289* 8004040345	WASTE MOT 50-458 S
	8004070333* 8004070415* 8004070535* 8004110053 8004110239	50-321 50-321 50-321 50-366 50-321	8 9 9 P	Outman, Peter	8006070015* 8006110268 8006180327* 8006230100 8006230083*	50-458 Q 50-458 8 50-458 A 50-458 Q CONTRACT
	8006110239 8006110288 8006110291* 8006170310 8006170310	50-321 50-346 50-346 50-321 50-321	р Р І І	HEW.Dept of, US Public Health Service Hanford Engineering Development Laboratory	8006020380 8006050656* 8006240104 8006270044	50-987 D 70-442 PR NUREO
	8006170310 8006170318*	50-321 50-321	I I	Harper-Grace Hosps Detroit.MI	8009180183	PR
	8006170337 8006170640 8006170640	50-321 50-321 50-321	G P P	Harsco Corp ,Capitol Manufacturing Co Div Hawaii, State of	8006200084 8006050487	PT21 PR
	8006170673 8006170674	50-321 50-321	6	Health, Education & Welfare, Dept of Helix Technology Corp , Process Systems Div	8006020382* 8006190160	50-367 D XPORTLIC
	8006170679* 8006170680*	50-321 50-321	8	High Rock Lake Association	8009500099	50-488 Q
	8006170683* 8006180323* 8006180323* 8006180323*	50-366 50-366 50-321 50-321 50-424	9 Q Q A	High Steel Structures, Inc Hill Christopher & Phillips	8004200071* 8004240111 8004120332 8004120332 8004120334*	50-488 Q 71-7037 50-275 Q 50-275 Q 50-275 Q
	B006180438	50-321	R	Hittman Nuclear & Development Corp	8005070261	50-275 0 71-9079
	8006180439* 8006180494 8006180497* 8006190135 8006190566	50-321 50-366 50-366 50-424 50-321	R R G B	(subs Hittman Corp)	8005070268* 8005070274* 8005070284*	71-9079 71-9079 71-9079
	8006190574* 8006190578 9006190508* 8006190607 8006190619*	50-321 50-321 50-321 50-321 50-321	8 8		8005070294* 8005070303* 8005070316* 8005070319* 8005070560	71-9079 71-9079 71-9079 71-9079 71-9089
	8006200437 8006200441 8006200444* 8006200447* 8006200452	50-366 50-321 50-366 50-321 50-321	8 8 8		8005070544* 8005120181 8005120182* 8004050041* 8004050433	71-9089 71-9086 71-9086 50-320 P 71-9079
	8006200461 * 8006200468 8006200474* 8006200474 8006200476	50-321 50-366 50-366 50-366 50-366	8 8		8004050437* 8004050437* 8004050441* 8004120377* 8004180115*	71-9079 71-9079 71-9079 80-320 P FOIA

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
	8006180119* 8006180129* 8006180135* 8006180152* 8006180192*	FOIA FOIA FOIA FOIA			8006170609 8006180196 8006180200* 8006180205* 8006180246	50-466 50-466 50-466 50-466 50-466	0000
Hoke, Inc Holland & Hart Homestake Mining Co	8006180195* 8006180198* 8006170823 8006110088 8005270286	FDIA FOIA XPORTLI 40-1162 40-8434			8004180370 8004180373# 8004180504 8004180504 8004180438	50-478 50-478 50-478 50-478 50-478	K 0 0
House of Rep	8005270296* 8005270304* 8005270310* 8006060516* 8006120086*	40-8434 40-8434 40-8434 50-275 50-254			8006180638 8006240292 8006240292 8006240341 8006240457	50-498 50-498 50-498 50-466 50-466	8 8 9 0
	8006120122* 8006120508 8006130387* 8006170465 8006200071*	MISC 50-219 COMMISS: 50-275 50-320	, H ION H U		8006240464 8006270237 8006270327 8006300307 8006300317	50-466 50-287 50-466 50-466 50-466	9999
	8006230456 8006230459* 8006230463 8006270129* 8006300389	50-70 50-70 50-275 50-341 50-367	9 H H U		8006300323 8006300334 8006300340 8006300435 8006300578	50-466 50-466 50-466 50-498 50-498	00080
	8006300481* 8006300484* 8006300505* 8006300510* 8006300515*	50-320 50-320 50-320 50-320 50-320	អ អ អ អ អ	Human Performance Technologies, Inc Hunton & Williams	8006300644* 8006300644* 8006270349 8006240347 8006300425	50-498 50-498 NUREQ 50-338 50-322	9 9 9
	B006300518* B006300525* B006300557* B006300571* B006300693*	50-320 50-320 50-320 50-320 50-219	H H H H	INTERA Environmental Consultants, Inc IRT Corp Idaho National Engineering Laboratory	8006270002 8006200157 8006200598 8006300400* 8006270015	NUREQ 70-1359 NUREQ 50-390 NUREQ	A
House of Rep , Appropriations House of Rep , Armed Services House of Rep , Interst & Foreign Commerce	8006270150* 8006120221 8005200512*	50-171 PR COMMISSI		Idaho, Univ af Illinois Power Co	6004120281 1700204008 1820204008 8004250375*	PRM PR 50-315 50-461	g 0
House of Rep , Science & Technology	8006130191# 8006120107#	COMMISSI			8006300438	50-461	F
Housing & Urban Development, Dept of	8006120114* 8006120117* 8006130173* 8006130176* 8006240332	50-320 50-320 90-320 50-320 50-10	0 0 0 0	Illinois, State of	8006300616* 8008130810 8006020009* 8006080088	50-461 PR State Pr PR PR	G rog
Housing & Urban Development, Dept of, Federal Disaster Assistance Admin	8005230283*	50-327	þ		8006120019* 8006180333	PR 70-1308	
Houston Lighting & Power Co	800402004B 8004030018 8004030018	PR 50-498 50-498	g Q		8006170335 8006170352 8006200006	27-39 50-367 PRM	o
	8004030023 8004030023 8004030172 8004030172 8004050085	50-498 50-498 50-498 50-498 50-466	Q Q Q Q		8006240281 8006240521 8006240597* 8006240592* 8006270417	PRM 70-1309 70-1309 70-1309 FOIA	
	8006050368 8006060036* 8006060478 8006070021*	50-498 50-445 50-498 50-498 50-498	F M Q Q	îndiana & Michigan Electric Co	8004300410 8005210255 8004030284 8004030284 8004030300	50-10 50-315 50-315 50-315 50-315	4 4 4
	8006070204 8006070215 8006070571 8006110282* 8006110282*	50-446 50-446 50-446 50-445 50-445	С 8 М М		8006030300 8006030301* 8006030301* 8006050037 8006050306	50-315 50-315 50-315 50-315 50-316	P P P
	8006110282* 8006110282* 8006110314 8006110314 8006110322*	50-445 50-445 50-498 50-498 50-498	M S S S		8004050312* 8004050315* 8004040019 8004110477 8004120300	50-316 50-316 50-315 PR 50-316	\$ 0 8
	8006110322* 8006110337 8006110337 8006110364 8006110364	50-478 50-478 50-478 50-445 50-445	5 8 8 M M		8006120303* 8006120426 8006170521 8006170550* 8006170669	50-314 PRM 50-315 50-315 50-316	e R R S
	8006110364 8006110364 8006120030 8006120061 8006120064	50-445 50-445 50-466 50-466 50-466	м о о		8006170677* 8006170698 8006170704* 8006230407 8006230487	50-316 50-316 50-316 50-315 50-315	S R R P
	8006120068 8006120097 8006160166 8006160170#	50-466 50-466 50-466 50-466	00		8006230487 8006230491* 8006230491* 8006240072 8006240462	50-315 50-315 50-315 50-315 50-316	P P Q S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		***	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	ORY
	8006240476* 8006240482 8006240491 8006260177 8006300495	50-316 50-315 50-315 50-315 50-315	S P P P	J & P Co Japan		8004030510 8004120249 8004120505 8004200533* 8004240120	40-8684 XPORTL1 XPORTL1 50-320 XPORTL1	IC IC P
Indiana & Michigan Power Co	8004300498* 8004300502 8004300508* 8004130111* 8004130113*	50-315 50-315 50-315 50-315 50-315	8 8 9 0	Jarsey Co	entral Power & Light Co	8006240275 8006240277 8006240654 8006020447 8006030007	XPORTLI XPORTLI XPORTLI 50-219 50-219	EC
Indiana Univ Indiana, State of	8006130115* 8006180600* 8006170386* 8006230124* 8006130342	50-315 50-315 50-315 CONTRACT State Pr				8006030012* 8006030014* 8006030444 8006030450* 8006060156	50-219 50-219 50-219 50-219 50-219	P 8 8
Interior,Dept of Interior,Dept of, Fish & Wildlife Service Interior,Dept of, Geological Survey	8004030307 8004190328 8004250228 8004020322 8004040457*	50-387 70-2909 50-275 MISC 50-70	D A P			#606000163* #606060419 #606060424* #606070249 #606070335	50-219 50-219 50-219 50-219 50-219	9 8 F P
	8006050462* 8006060471* 8006060473* 8006060476* 8006120305	50-70 50-70 50-70 50-70 50-70	P P P P			8006120294 8006120297* 8006160018 8006160021* 8006160050	50-219 50-219 50-219 50-219 50-219	8 6 8 8
International Brotherhood of Electrical Workers International Verbatim Reporters, Inc Interpace Corp Iowa Electric Light & Power Co	8006190407 8006110255 8006230178* 8006030157 8006020064*	70-2909 NUREO CONTRACT XPORTLIC 50-331				80061600\$5* E006160080 8006160086* E006170496 8006180423	50-219 50-219 50-219 50-219 50-219	8 8 8
	8006030297 8006030298* 8006030299 8006030441* 8006030467	50-331 50-331 50-331 50-331 50-331	8 8 8			8006190453 8006190604 8006200455 8006200458* 8006260171	50-219 50-219 50-219 50-219 50-219	8 P R R
	8006030449 8006030473* 8006030483 8006090339 8006090346*	50-331 50-331 50-331 50-331 50-331	0 8 0 8			8006260172* 8006260185 8006260187* 8006270299 8006270303*	50-219 50-219 50-219 50-219 50-219	8 8 8
	8006090371 8006090380* 8006110335 8006160133 8006170539	50-331 50-331 50-331 50-331 50-331	8 8 F			8006300356 8006300472 8006300474 8006300477* 8006300482*	50-219 50-219 50-219 50-219 50-219	F 8 8 8 8
	8004170458 8004170445*	50-331 50-331	8 8	(subs t	llume & Associates, Engineers JRS Corp) aughlin Steel Corp (subs of	8006170612* 8006030076	50-219 PR	P
	8006190400 8006190461 8006190464*	50-331 50-331 50-331	F R R	LTV Co)	own & Clifford	8006190437 8006190439*	50-133 50-133	0
	8004230207* 8004230342 8004230370 8004230432 8004230501	50-331 50-331 50-331 50-331 50-331	ь Б Б	Justice. B	ept of	8006240313 8006030350 8006030350 8006060492 8006060492	50-275 50-416 50-416 50-445 50-445 50-445	0
	8006230504# 8006240183 8006260255 8006270256 8006270261#	50-331 50-331 50-331 50-331	F G 8 8			8006060492 8006110357 8006120056 8006120056 8006120137*	50-445 50-445 50-445 50-445 50-458	M M M M
Isham, Lincoln & Beale	8006270264 8006270267* 8006270271 8006270274* 8006050044	50-331 50-331 50-331 50-331 50-327	8 8 9			8006160163 8006160163 8006160163 8006160163 8006170004	30-445 50-445 50-445 50-445	H H H
	8006060236 8006060236 8006060357 8006060366 8006060428	50-295 50-295 50-295 50-155 50-445	9 9 9 M			8006170007* 8006170007* 8006170007* 8006170007* 8006170555	50-445 50-445 50-445 50-445 50-346	M M M
	8006060465 8006110375 8006120045 8006120263 • 8006160123	50-255 50-445 50-327 50-255 50-255	9 M			8006180187 8006180187 8006180187 8006180187 8006180215*	50-445 50-445 50-445 50-445 50-458	м м м
	8006160139 8006170218 8006170218 8006170814 8006190524	50~155 50~275 50~275 PR 50~255	0	KMC: Inc.	•	8006170240* 8006170240* 8006200142 8006230254 8006070108	50-416 50-416 50-445 50-445 PR	M M M N
Isomedix, Inc. (subs. of Maesfield Enterprises, Inc.)	8006240128 8006240250 8006300513 8006300429*	50~155 50~445 50~255 50~370	9 H Q A		s & Electric Co	8006070108 8006070188* 8006120356	FDIA 50-482 50-482	g G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8006160015 8006180525 8006200144 8006230384 8006240200	NUREG 50-482 50-482 50-482 50-482	9 P F S	Lowenstein, Newman, Reis, Axelrad & 7oll	8004050085 8006050474 8006060033 8006060033 8006060033	50-466 PR 50-445 50-445 50-445	м М
Kentucky, State of	8006240204 8006250012 8006030215 8006200061* 8006260155*	50-482 50-482 State P State P COMMISS	rog		800606033 8006060348 8006060478 8006060497 8006090060	50-445 50-344 50-498 90-344 PR	М 9 0
Kentucky, Univ of Kenyon College Kepford, C Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8006120298 8006130290 8006090199 8006120436	ACRS 70-623 50-320 PRM	G		8006070204 8006110233 8006110233 8006110233 8006110233	50-466 50-445 50-445 50-445 50-445	9 M M M
Kerr-McGee Corp Kerr-McGee Nuclear Corp	8006120441* 8006190121 8006160192 8006250333 8005090057 8005090045*	PRM 40-2051 71-9091 70-1193 40-8027 40-8027			8006110266 8006110338 8006110364 8006120030 8006120061	50-445 50-344 50-445 50-466 50-466	H 0 H 0 0
	8006090524 8006090553 8006300026 8006300645 8006300649*	40-2061 40-8027 40-8027 40-8027 40-8027			8006120064 8006120068 8006120153 8006120417 8006170493	50-466 50-466 50-344 50-466 50-389	3000
Keves Corp Analytica) Instrument Div Kite.M S Kodner, J L Lake Michigan Federation	8004040175 8004110088 8004170540 8004170570* 8004090251	71-9070 40-1162 50-599 50-599 50-367			8006170607 8006180158 8006180346 8006180506 8006230433	50-446 50-376 50-466 50-498 50-466	0000
Lancaster County, PA Lane County, OR Laudig, S Laurence Livermore Laboratory	8006300373* 8006120326* 8006030572* 8006110427 8006020189	50-367 50-287 50-344 50-367 RES	U F G G		8006240341 8006260202 8006270327 8006300307 8006300317	50-466 50-250 50-466 50-466 50-466	0000
,	8004040098 8004040481* 8004170164 8004190059 8004250052*	NUREO 50-70 NUREO 71-6400 50-282	p p	Maine Yankse Atomic Power Co	8006300323 8006300334 8006300340 8006020221 8006020229*	50-466 50-466 50-466 50-309 50-309	Q Q R R
LeBoeuf, Lamb, Leiby & MacRae	8006260053 8006270378 8006300054 8006300178 8006050482	NUREO NUREO NUREO NUREO PRM			800000178 *801020008 *802020208 *02020208 *02020208	50-309 50-309 50-309 50-309 50-309	G R R Q
	8004040454 8004040552 80040405134 8004110084 8004110424	50-548 50-320 50-546 50-285 50-546	о н н		8004040447 8004090271 8004090280 8004090353 8004090357*	50-309 50-309 50-309 50-309 50-309	8 6 6
	8006120174 8006120412 8006170404 8006180006 8006230094	FOIA FOIA 50-341 50-244 FOIA	1 0		8006070482 8006110003 8006110008* 8006110189 8006110200*	50-307 50-307 50-307 50-307 50-307	9 9 8
League of Women Voters of Rockford,IL Leckenby Co Leed,R M	8006300224 8006170874 8006250110* 8006060279 8006190447	50-320 PR GA999 50-522 50-522	H Q G		8006110334 8006160110 8006170241 8006170689 8006170696*	50-309 50-309 50-309 50-309 50-309	8 9 8 8 8
Lehigh-Pocono Committee of Cancern Liberty Equipment & Supply Co Limitorque Corp Long Island Lighting Co	8006170231 8006070438* 8006040004* 8006120228 8006130162*	PR 50-416 GA999 PR 50-322	a o		8006170739* 8006180274 8006180326 8006200424 8006230379*	50-307 50-309 50-309 50-309 50-309	G G P G
Looney, Nichols, Johnson → Haues	8006170261 8006170601 8006240600 8006300267 8006120495	50-322 50-322 50-51 <i>6</i> 50-322 PR	A Q Q Q		8006230386 8006230440* 8006300358 8006300360* 8006300418	50-309 50-309 50-309 50-309 50-309	F & P P
Los Alamos Scientific Laboratory Louisiana Power & Light Co	8006170705 8006040169* 8006050297 8006110309 8006170283	RES 50-382 50-382 50-382 50-382	g g A K	Maine, State of Mapleton Intervenors	8006030355 8006130233* 8006110258 8006170569 8006300423	50-309 50-309 50-329 50-329 50-329	F H H G
	8006170290* 8006170293* 8006180384	50-382 50-382 50-382	K K S	Marrack,D Marsh & McLennan:Inc , M & M Nuclear Gonsultants,Inc Div	B006060392 B006030421 B006110097	50-444 50-335 50-272	٠, د
	8006180387 8006180391* 8006190313	50-382 50-382 50-382	8 8		7010414008 7010414008 E110414008	50-335 50-335	î Û
Louisiana, State of	8006230107 8006050487 8006120208	50-382 PR PR	q	Maryland, State of	8006240381 8006270016*	50-70 50-448 50-317	O P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Haryland, Univ of	8006020543 8006110159 8006110169 8006110174 8006110180	NUREQ 50-166 P 50-166 K 50-166 K 50-166 K	MAA	8005050574 8005070263 8005070313 8005070319 8005070364	50-287 Q 50-287 F 50-287 Q 50-287 Q 50-320 P
	8006110186 8006110170 8006110195 8006110197 8006110201	50-166 K 50-166 K 50-166 V 50-166 K 50-166 K		8006090364 8006090374 8006090419 9006110066 8006110070	50-320 P 50-320 Q 50-287 Q 50-289 Q 50-320 P
	8006110207 8006110212 8006110213 8006110216 8006110218	50-166 K 50-166 K 50-166 K 50-166 K 50-166 K		8006110071 8006110071 8006110106 8006110114 8006110117*	50-320 F 50-320 F 50-320 P 50-320 P 50-287 0
Massachusetts Institute of Technology	8006110232 8006110339 8006300130 8006020405 8006030384	50-166 F 50-166 C NUREQ 50-20 S 50-20 S		8006110145 8006110148* 8006110167 8006110179* 8006110182	50-320 P 50-320 P 50-320 P 50-320 P 50-320 F
	8006160073* 8006230051 8006230062* 8006270420 8006300290	50-443 0 50-20 8 50-20 8 NUREO 50-20 P		8006110182 8006110204 8006110300 8006110317 8006120036	50-320 F 50-320 P 50-320 P 50-320 P 50-289 0
Massachusetts Materials Research, Inc Massachusetts, State of Matheson Gas Products Matthews, Nowlin, Macfarlane & Barrett	8006130034 8006130036# 8006090168 8006120366 8006110076	71-387 71-387 50-471 0 XPORTL1C 50-498 M		8006120040 8006120084 8006120259 8006120317 8006120318+	50-287 0 50-287 0 50-320 0 50-287 F 50-287 F
Mayer, Drown & Platt McCullough, E R McDermott, Will & Emery	8006120292 8006110293 8006240148 8006300687* 8006130243	50-498 M 70-1308 70-1308 50-10 H 50-445 M		8006120374 8006120400 8006120414 8006130239 8006130256	50-320 P 50-289 G 50-289 G 50-289 G
McCinnis, Lochridge & Kilgore McCrath, E. J McCraw-Hill Publications Co McNail, J. E.	8006200167 8006200167 8006120077 8006250225* 8006260204	50-445 M 50-445 M WABTE MOT CONTRACT XPORTLIC		8006130312 8006130315 8006140024 8006140027* 8006140046*	50-289 P 50-320 D 50-320 S 50-320 S 50-289 G
Macklemburg County, NC Media Communications, Inc Medinaelectric Gooperative, Inc Metcalf & Eddy	8006260208 8006270203 8006230117* 8006200167 8006060262	XPORTLIC 50-269 H COMMIBBION 50-445 M 50-320 Q		8006140052 8006140078 8006140144 8006170583 8006170785	50-267 0 50-320 0 50-320 8 50-320 0 50-287 0
Metropolítan Edison Co	7812270093 8006020106 8006020106 8006020195 8006020201*	50-320 \$ 50-320 F 50-320 F 50-289 P 50-289 F		8004180154 8004180157 8004180315 8004180534 8004170105	50-287 0 50-287 0 50-287 0 50-320 0 50-287 0
	8004020205* 8004020210* 8004030302 8004030325 8004030327*	50-289 P 50-289 P 50-289 P 50-320 P 50-320 P		8006190435 8006200371 8006200371 8006200495 8006200496*	50-289 0 50-320 I 50-320 I 50-289 R 50-289 R
	8006030335 8006030359 8006030362 8006030459 8006030465	50-289 P 50-320 Q 50-320 P 50-320 S 50-320 S		8006230326 8006230335* 8006230344 8006230366 8006240303	50-320 8 50-320 8 50-320 P 50-287 Q 50-320 I
	8006030472* 8006040112* 8006050038 8006050280 8006050327	50-320 S 50-320 G 50-320 P 50-289 P 50-320 P		8006240303 8006240304* 8006240304* 8006240504 8006240510*	50-320 I 50-320 I 50-320 I 50-320 S 50-320 S
	8006050346 8006050386 8006050380 8006080380	50-320 J 50-320 J 50-320 P 50-320 P 50-287 Q		8005240275 8005270216 8005270290 8005270296* 8005270297*	50-287 0 50-320 0 50-320 P 50-320 P 50-320 P
	8006060253 8006060262 8006060262 8006060271*	50-287		8006270332 8006300390 8006300447 8006300451 8006300471	50-289 P 50-289 Q 50-320 P 50-289 Q 50-289 B
	8006060304 8006060368 8006060404 8006060409* 8006060423	50-320 P 50-320 P 50-289 S 50-289 S 50-289 Q	Michigan State Univ Michigan, Univ of	8006300478* 8006300689 8006090515* 8006180256 8006180264*	50-287 8 50-320 0 50-274 0 50-2 F 50-2 F
	8006060475 8006060527 8006060547 8006060547 8006060552	50-287 0 50-287 0 50-320 0 50-320 0 50-320 0	Mid-America Legal Foundation Middle South Services, Inc Middle South Utilities,Inc Minerals Exploration Co (subs of Unic Dil Co of California)	8006260210 800630227* 8006302027* 8006060012*	27-39 50-416 C PR 50-416 C 40-8348

AUTHDR AFFILIATION		ACCESSION NUMBER	SUBJECT	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Ministry of Concern for Public Minnesata, State of Mississippi Power & Light Co		8004250350 8004300548 8004170715 8004030003 8004030003	PR PRM PR 50-416 50-416	К К	Monsanto Co Monsanto Research Corp Morgan, Lewis & Bockius	8006300584* 8006200524 8006190213 8006190219* 8006040029*	XPORTLIC NUREQ 70-572 70-572 50-409 G
		8006030005* 8006030007* 8006030007* 8006030223	50-416 50-416 50-416 50-416	К К С	Mutual Atomic Energy Liability Underwrit ers N M Neumark Consulting Engineoring Borvices	8004200046	50-320 J 70-754
		8004030223 8004030229* 8004030229*	50-416 50-416 50-416	c c	NL Industries, Inc	8006200050* 8004220262* 8004220270*	70-754 71-9010 71-9010
		8004030375 8004050246 8004080246 8004050314	50-416 50-416 50-416 50-416	R 8 8	NL Industries, NL Nuclear Div NUS Corp	8004220277* 8004220225 8004200130 8005130517* 8005130522*	71-9010 71-9010 XPORTLIC WASTE MOT WASTE MOT
		8004050357 8004040247 8004040247 8004110109	50-416 50-416 50-416 50-416	5 5 5 5	NHT Corp National Academy of Sciences National Aeronautics & Space Admin National Image.Inc National Valve & Mfg Co	8006250143* 8006170154* 8006110087 8006130212 8006070148*	50-33B P 50-376 Q 70-1314 FOIA GAP99
		8006110150 8006110150 8006110178* 8006110178*	50-416 50-416 50-416 50-416	9 8 8 8 8 A	National Wildlife Federation Natural Resources Defense Council	8006040328 8006200587 8006110465 8006170247 8006170336	40~4472 70~2709 PR PR PR
		8004110303 8004110303 8004140088 8004140088	50-416 50-416 50-416 50-416	8 8 C C	Navy, Dept. of	8006170340 8006200569 8006020574 8006020579* 8006200606	PR 50-574 Q 71-388 71-388 71-9138
		6004160103 6006160106# 6006160106# 6006160128	50-416 50-416 50-416 50-416	8 8 8 K	Navy,Dept of, Bureau of Medicine &	8004300422* 8004300424* 8004300408*	71-165 71-165 71-371
		8004140128	50-416	Ķ	Burgery Navy Dept of Naval Facilities Engineeri	#006300600#	71-391
		8006180237 8006180237 8006180251*	50-416 50-416 50-416	8 8 6	ng Command Navy,Dept of, Naval Nuclear Power Unit	8006300594	71-391
		8005180251* 8005180287 8005180287 8005180291*	50-416 50-416 50-416 50-416	8 8 8	Nebraska Public Power District	8006300620 8006030461 8006040046 800609031B 8006090322	71-145 50-298 P 50-298 G 50-298 F 50-298 R
		8006180291# 8006180462 8006180468* 8006180468*	50-416 50-416 50-416 50-416	8 A A		8006070323* 8006110075 8006110251 8006230542 8006230546*	50-298 R 50-298 P 50-298 F 50-298 P 50-298 P
		8004190577 8004200345 8004200345 8004200381 8004240384	50-416 50-416 50-416 50-416 50-416 50-416	8 M H H 8	Nebraska, Univ of Nekton, Inc	8006240500 8006190276* 8006250216* 8006250216* 8006250218*	50-298 P CONTRACT 50-361 A 50-361 A
		8006240384 8006240487 8006240487 8006260343	50-416 50-416 50-416 50-416	5 Q Q	Neutron Products, Inc New England Coalition on Nuclear Pollution	8006250218* 8006120183 8006120175 8006110049	50-361 A 71-5364 71-6144 50-443 0
		8006270284 8006270284	50-416 50-416	8 8		8006110224	PR
		8006300375 8006300375 8006300382* 8006300382* 8006300384*	50-416 50-416 50-416 50-416 50-416	F F F F	New England Conference of Public Utility Commissioners	8006120379 8006170247 8006170336 8006170340 8006170267*	50-289 Q PR PR PR CONTRACT
Mississippi, State of		8006300384* 8006300469 8006300469 8006120232* 8006120246*	50-416 50-416 50-416 PR PR	A A	New England Nuclear Corp New Hampshire, State of New Jersey Utilities Association	8006230257 8006230260* 8006170183* 8006170246 8006300300	71-384 71-384 80-443 H PR 50-287 H
Mississippi, Univ of. Missouri, State of Missouri, Univ of. Columbia Missouri, Univ of, Rolla		8004200078* 8004030487 8004110137 8004300275* 8004110044	CONTRACT PR 50-186 50-186 50-186	\$ Q 8	New Mexico, State of New York, State Univ of: Buffalo New York, State of	8006040185 8006190677 8006190679* 8006110214 8006110225	WASTE MOT 70-267 70-267 50-596 Q 50-244 Q
Mitre Corp Mitsubishi International Corp Mitsubishi Corp)	(subs of	8006120075* 8006250058	50-320 XPORTLIC	P	New York, State Univ of, (Albany)	8006180236* 8006190252*	FOIA CONTRACT
		8006260012 8006260013* 8006260014	XPORTLIC XPORTLIC XPORTLIC		Newberry Township, York Haven,PÅ Niagara Mohawk Power Corp	8006240343 8006020462 8006030058	50-320 Q 50-220 Q 50-220 Q
Mitsui & Go , Ltd		8006260018* 8006120179 8006190026 8006300581	XPORTLIC 40-9052 XPORTLIC XPORTLIC			8006030471 8006030390 8006090360 8006090362* 8006090370	50-220 P 50-220 P 50-220 S 50-220 S 50-220 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	PΥ
	8006090376* 8006110171 8006110176* 8006110241 8006110253	50-220 S 50-220 R 50-220 R 50-220 J 50-220 J	Northern Michigan Electric Cooperative, Inc	8006110331 8006200370 8006260195 8006170405*	50-367 50-367 50-367 50-367 50-341	A R R
	8006120358 8006160090 8006170323 8006190475 8006230550	50-220 G 50-410 A 50-410 A 50-220 F 50-410 A	Northern States Power Co	8004020259 8004020334 8004030203 8004030479 8004050477	50-282 50-263 50-282 50-282	f e e e
	8006240012 8006240406 8006270289 8006300265 8006300271	50-410 G 50-410 S 50-220 P 50-220 G 50-220 G		8004050247 8004050375 8004050378# 8004040398# 8004070289	50-263 50-263 50-263 50-263 50-263 50-282	P 88 R R 8
Nissho-Iwai American Corp North Carolina State Univ	8006300305 8006300378 8006020165 8006110367 8006170479	50-220 P 50-220 P 70-2805 50-277 F 50-111 W		8004070278 8004070400 8004070400 8004130245 8004130247*	50-263 50-282 50-282 50-263 50-263	P P R
North Carolina, State of Northampton County, PA Northcutt Ely	8006170482* 8006240594 8006190381 8006190454 8006250193	50-111 W 50-269 0 50-289 H 50-445 M 50-445 M		8006170377 8006170429 8006170486 8006180448 8006100448	50-282 50-283 50-282 50-282 50-282	P P R
Northeast Nuclear Energy Co (subs of Northeast Utilities)	8005300283 8006020203 8006020211* 8006020394 8006020392*	PR 50-213 P 50-213 P 50-336 8 50-336 8		8006180451* 8006180453* 8006180453* 8006200373 8006200466	50-282 50-282 50-283 50-263	R R P S
	8006030064 8006030474 8006030476* 8006040011 8006050369	50-245 Q 50-336 P 50-336 P 50-336 Q 50-245 P		8005200472* 8005200548 8005230253 8005230337 8005230437	50-263 PR 50-282 50-263 50-263	S G F P
	8004040304 8004040347 8004090284 8004090474* 8004110081	50-336 P 50-213 F 50-245 P 50-423 8 50-245 P	Northwestern Univ	8004240246 8004240558 8004300473 8004300477* 8004040073	50-263 50-262 50-262 50-262 ORG	F 9 8
	8006110163 8006110248 8006110256* 8006160045 8006160047	50-245 P 50-336 S 50-336 S 50-245 P 50-336 P	Nuclear Assurance Corp	8003120430 8006160137 8006160161* 8006160172* 8006160176*	70-1510 71-6698 71-6698 71-6698 71-6698	
	8006160048* 8006170657 8006170661* 8006170408 8006170457	50-336 P 50-336 S 50-336 S 50-336 P 50-213 P	Nuclear Energy Bervice, Inc	8006160179* 8006160184* 8006160187* 8006110032 8006170606*	71-6698 71-6698 71-6698 71-6717 50-322	a
	8006190602 8006190610* 8006240387 8006240393* 8006240466	50-336 P 50-336 P 50-245 S 50-245 S 50-336 P	Nuclear Engineering Co , Inc , (subs of Teledyne, Inc)		50-282 50-282 50-282 71-6400	P P
	8006240517* 8006270293 8006300379 8006300383 8006300460	50-293 G 50-245 P 50-245 P 50-213 P 50-245 P		8006060173* 8006060179* 8006060181* 8006060183* 8006060187*	71-6400 71-6400 71-6400 71-6400 71-6400 71-6400	
Northeast Utilities	8006020436 8006060275 8006060285* 8006110226 8006110272	NUREQ 50-334 8 50-336 8 50-245 P TOPREP	Nuclear Fuel Services, Inc. (subs. of	800A0A0170# 800A0A0171# 800A120177 800A300AA4 800A12030A	71-6400 71-6400 71-6400 27-39 70-143	
	8006110261* 8006110276* 8006110307 8006170361 8006170438	TOPREP TOPREP 50-336 P REGGD 50-245 R	Qetty Oil Co)	8006120392 8006120371 8006120376 8006180387	70-143 70-143 70-143 70-143	
	8006170440* 8006170464 8006170464 8006170464 8006170408	50-245 R 50-245 H 50-245 H 50-245 H 50-236 P		8006180428 8006190197* 8006190203 8006190334 8006190330	70-143 50-201 70-143 70-143 70-143	Q
	8004190402 8004190410# 8004200491 8004230504 8004230515#	50-334 P 50-336 P 50-245 Q 50-336 R 50-336 R		8004190481 8004190579 8004200558 8004200573 8004200579	70-143 70-143 70-143 50-201 50-201	R
Northern Indiana Public Service Co	8004030371 8004040314 8004110119 8004110144	50-367 R 50-367 R 50-367 R 50-367 R		8006230141 8006230144* 8006230297	50-201 50-201 50-201	R R F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO:	
Nuclear Fuel Services, Inc , West Valley Reprocessing Plant	8006240391 8006240403 8006250235 8006300003 8006230244	70-143 70-143 70-143 70-143 50-201 R		8006020345 8006030330 8006060582 8006110417 8006160022	50-275 50-275 50-317 50-275 50-133	A A B Q
Nuclear Metals, Inc	8006230247* 8006120397 8006130030 8006130033* 8006170821	50-201 R XPORTLIC XPORTLIC XPORTLIC XPORTLIC		8006160023* 8006160039 8006160040 8006160040	50-133 50-275 50-275 50-275 50-275	R F A
Nuclear Packaging, Inc	80061/0826* 8006120149 8006250315 8006250319* 8006250322*	XPORTLIC 71-9073 71-9113 71-9113 71-9113		8006160044# 8006160044# 8006180299 8006180424 8006180424	50-275 50-275 50-275 50-275 50-275	A Q H H
Nuclear Pharmacy, Inc Nucleonits Weeks, pub of McGraw Hill,	8004120518 0006230090	FOIA FOIA		8006180522* 8006190488 8006190573	50-275 50-275 PROJ	Q A
Inc Dak Ridge National Laboratory	8006120469 8006130383	NUREG RES		800624041& 800630048&	50-275 50-344	8
	8004130390 8004160174 8004190045 8004190040 8004200021	RES RES RES RES RES	Parker,R A Pathfinder Mines Corp	8005300492* 8005200586 6005170254 8005180474 8005170585	50-344 71-102 40-2259 40-2259 40-2259	8
	8006200023 8006200518 8006200531 8006200588	RES NUREG NUREG NUREG	Peabody Testing/X-Ray Engineering Co Pennsylvania Power & Light Co	8006300029 8006060055* 8006060064* 8006060369 8006060490	71-4717 50-387 50-387 50-387 50-387	A A A D
	8004230094 8004250345 8004240041 8004270031 8004270045	RES RES NUREO NUREO NUREO RES		8006060490 8006090311 8006090311 8006110222 8006110229*	50-387 50-387 50-387 50-387 50-387	D S S A A
	8004270078 8004300049 8004300071 8004300085 8004300298 8004300500	NUREG NUREG NUREG REB REB		8006120106* 8006170328 8006170733 8006180151 8006190484	50-387 50-387 50-387 50-289 50-387	8 0 0
Dak Ridge Univs Ogle Petroleum, Inc	8006300578 8006120266* 8006040063 8006120047 8006120053*	RES COMMISSION 40-8693 40-8745 40-8745		8006190484 8006200163 8006200171 8006200171 8006200366	50-387 50-387 50-387 50-387 50-387	9 9 9
Ohio State Univ Ohio, State of Ohmart Corp Omaha Public Power District	8004020344 8006110404 8004090087 8006040024 8006040071	MISC PR PR 50-265 G 71-7113	Pennsylvania State Univ	8004200344 8004240575* 8004270321 8004270342 8004130278	50-387 50-387 50-387 50-387 50-5	8 9 8 F
	B006040277 B006110012 B006110015* B006110026 B006110030*	50-285 F 50-285 8 50-285 8 50-285 8 50-285 8	Pennsylvania. State of	8004050070 80040405* 80040406* 8004040542* 8004070075*	50-320 50-289 50-289 50-320 50-320	0 0 0 P
	8006130090* 8006130092* 8006170442 8006170443* 8006230356	50-285 Q 50-285 Q 50-285 R 50-285 R 50-285 J		8006070102* 8006120320* 8006120321* 8006120327* 8006120351	50-320 50-269 50-269 50-269 50-367	P F F D
	8006230414 8006230422 8006240324 8006300372 8006300468	50-285 B 50-285 P 50-285 P 50-285 P 50-285 S		8006120387 8006180040 8006180043* 8006180190 8006180194*	50-387 50-289 50-289 50-289 50-269	A0000
Oregon State Univ	8006300475* 8006300543 8006110193 8006240389 8006300286	50-285 8 50-285 9 50-243 9 50-243 P 50-243 F	People Against Nuclear Energy Perkins, Cois, Stone, Olsen & Williams	8006170547 8006240343 8006060328 8006060328 8006180181	50-320 50-320 50-522 50-522 50-522	00000
Oregon, State of	8006040160* 8006040533 8006040537* 8006060544* 8006120216	State Prog 50-344 0 50-344 0 FR	Pfefferkorn & Cooley, P A Philadelphia Electric Co	8006180181 8006070014 8006110342 8006180341 8005170521	50-522 50-488 50-488 50-488 50-171	0 0 0
	8006170499* 8006170273* 8006170499* 8006240137	50-387 M 50-387 M 50-387 M 50-250 M		8006020001 8006020330 8006020330 8006020379 8006020385*	50-277 50-352 50-352 50-171 50-171	2240
Pacific Gas & Electric Co	8006020171* 8006020171*	50-409 Q 50-275 A 50-275 A 50-275 A 50-275 A		8004030121 8004050379 8004050379 8004050383* 8004050383*	50-277 50-277 50-277 50-277 50-277	9 P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESS ION NUMBER	CATEGO	
	80040\$0386* 80040\$0386* 8004040039* 8004040242 8004040547	50-277 50-277 50-277 50-320 50-320	P Q Q Q		6006240327 6006240331* 6006240333* 6006240365 6006240362	50-344 50-344 50-344 50-344 50-344	P P P P
	8006060557 8006090062* 8006110082 8006110094 8006110329	50-277 50-352 50-277 50-277 50-352	0 8 8 8 8	Potomac Electric Power Co Potomac Resparch, Inc Power Authority of the State of New York	8006240401 8006300504 8006060509 8006250295# 8006020076#	50-344 PR 50-448 CONTRAC 50-333	F G T a
	8006110327 8006110332* 8006110332* 8006120348 8006120348	50-352 50-352 50-352 50-352 50-352	5 5 9 9		8006020081* 8006020308 8006020318* 8006020355	50-333 50-333 50-333 50-333 50-333	0 8 8 8
	8006130279 8006130279 8006130324 8006130324 8006170445	50-277 50-277 50-277 50-277 50-277	P P F R		8004020347 8004020370* 8004020372 8004020377* 8004020383	50-333 50-333 50-333 50-333	9999
	8006170445 8006170446* 8006170446* 8006170627 8006170339	50-277 50-277 50-277 NUREQ 50-277	R R R		8004020387* 8004020391 8004020394* 8004020412 8004020417*	50-333 50-333 50-333 50-333 50-333	9999
	8006190339 8006190345# 8006190345# 8006200487 8006200487	50-277 50-277 50-277 50-277 50-277	R R P P		8006030246 8006030315 8006030384 8006040294 8006050493	50-333 50-284 50-284 50-284 50-333	Q P P Q
	8006230566 8006230240 8006230241* 8006260176 8006260176	50-278 50-277 50-277 50-277 50-277	6 8 9 P		8006050505* 8006060280 8006060373 8006060553 8006110006	50-333 50-247 50-286 50-286 50-333	9 9 9
	8006260181 8006260181 8006270217 8006270217 8006270224*	50-277 50-277 50-352 50-352 50-352	P. P. S.		8006110010* 8006110016 8006110021* 8006110069 8006110077*	50-333 50-333 50-333 50-333 50-333	8 8 9 9
Philadelphia, PA Philibrick, S.S Philippine Hovement for Environmental Protection	8006270224* 8006200605* 8006230467 8006120302 8006200569	50-352 50-320 50-352 50-70 50-574	8 P H O		8006110183 8006110181 8006110183 800612013	50-284 50-333 50-333 50-284 50-286	0 R 0 0
Picker Corp Pittsburgh, Univ of Plateau Resources, Ltd Pollution & Environmental Problems, Inc Porter-Gentz Consultants, Inc	8006040189 8006300116* 8006250332 8006170786 8006020295	71-5796 ACRB 40-7869 PR 50-320	R		8006160108 8006160137 8006170451 8006170454* 8006180499	50-247 50-333 50-247 50-247 50-333	₽ P P
Portland General Electric Co	8006020275 8006020303* 8006020303* 8005280231 8006030371	50-320 50-320 50-320 PR 50-344	R R R		9004190500 9004180503* 9004190551 9004190561* 9004200380	50-333 50-333 50-286 50-286 50-286	8 R R 9
	6004050321 6006050324* 8006050326* 8006040350* 6006040363	50-344 50-344 50-344 50-344 50-344	ድ P B P		8006230435 8006240013 8006240801 8006260168 8006260178	50-286 50-333 50-333 50-286 50-286	Р 0 Р Н
	8004040411 8004040415* 8004040477 8004070377 8004070384*	50-344 50-344 50-344 50-344 50-344	8 8 8 8		8004240180 8004240212 8004240212 8004270175 8004300309	50-333 50-247 50-247 50-286 50-286	Н О Р О
	8004110221 8004110273 8004110277* 8004110313 8004130043	50-344 50-344 50-344 50-344 71-5450	9 R R 8	President of UB & Executive Offices	8004300440 8004300464 8004300467* 8004130027* 8004270418*	50-333 50-286 50-286 COMMISSI FOIA	F 8 8
	8006160124 8006170139 8006170516 8006180472 8006190625	50-344 50-344 50-344 50-344 50-344	P Ø F G 1	Princeton Univ Public Citizen Litigation Group	1004300251* 8004300347* 8004120207* 8004110356 8004110376*	50-443 50-320 COMMISSI 50-367 50-367	H H VDI O O
	8004200498 8004230409 8004230423 8004230590 8004230593*	50-344 50-344 50-344 50-344 50-344	8 P Q P	Public Service Co of Colorado	8006110378# 8006110382# 8006030253 8006030455 8006040040	50-367 50-367 50-267 50-267 50-267	0 0 0 F 0
	8006230397* 8006230604 8006240319 8006240321*	50-344 50-344 50-344 50-344	P 8 8		8006040041 8006040043 8006050301 8006060057* 8006060266	50-267 50-267 50-267 50-267 50-267	0 0 0 0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8006060273 800609037\$ 8006090381* 8006160017 8006160030	50-267 50-267 50-267 50-267 50-267	P R R R R	RTE-Delta Corp Rad Services. Inc	8004180185# 8004180185# 8004240058# 8004180227# 8004180224#	50-522 Q 50-522 Q GA999 FOIA FOIA
	8006160031* 8006160034 8006160035* 8006160036* 8006160115	50-267 50-267 50-267 50-267 50-267	9 P R 9	Radiation & Environmental Monstoring, Inc	8004180241* 8004180252* 8004180243* 8004130170	FOIA FOIA FOIA 40-8752
	8006160118* 8006170692 8006180419 8006240335	50-267 50-267 50-267 50-267	8 P P 8 P	Radiation Management Corp	7903140178 8004180248* 8004180272* 8004180284* 8004180292*	FOIA FOIA FOIA FOIA FOIA
Public Service Co of Indiana, Inc	8005240400 8005270197 8005110424 8005170531 8005200059 8005230162	50-267 50-267 50-546 50-546 50-546	Р О Н В О		8006180307* 8006180335* 8006180335* 8006180342* 8006180348*	FOIA FOIA FOIA FOIA
Public Service Co of New Hampshire Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8004260356# 8004300276 8004300348 8004020163	50-546 50-443 50-556 50-272 50-354	Q Q A P	Radiation Research Associates Radiological Controls Radium Chemical Co , Inc Reed College	8004080587* 8004060445 8004300559 8004070035 8004020216 8004020374	FOIA FOIA YPORTLIC 50-288 F 50-288 P
	8004020475 8004030340 8004050364 8004050371* 8004040212	50-354 50-311 50-272 50-272 50-272	G P S S	Rehab Group, Inc Reilly & Like Reuter-Stokes, Inc	8006200003* 8005220614 8006090566 8006120155 8006120448	CONTRACT PR XPORTLIC XPORTLIC XPORTLIC
	8004040242 8004040547 8004040547 8004090049 8004090072#	50-320 50-320 50-320 50-272 50-272	0000	Ridihalgh, Eggers & Associates Rio Algom, Ltd Riverside, CA Rochester Oas & Electric Corp	8006120489 8006020529 8006040187 8006190538* 8006020374	XPORTLIC 71-6639 40-8084 50-361 I 50-244 F
	8006110231 8006110231 8006120203 8006120210# 8006120214#	50-272 50-272 50-311 50-311 50-311	о Р Р		8004030294 8004030318 8004030324 8004030328* 8004030338	50-244 P 50-244 P 50-244 P 50-244 P 50-244 F
	8006120369 8006130024 8006160009 8006160012* 8006160107	50-272 50-272 50-272 50-272 50-272	G T R R R		8004030347* 8004030587 8004040237 8004040338 8004050030	50-244 P 50-244 B 50-244 P 50-244 P 50-244 B
	8006160136* 8006170450 8006170450 8006170573 8006170578*	50-272 50-272 50-272 50-272 50-272	R P B S		8006050427* 8006090317 8006090326 8006090331 8006110238	50-244 Q 50-244 B 50-244 P 50-244 P 50-244 V
	8004170420 8004170451 8004170444 8004170471* 8004180307	50-272 50-272 50-272 50-272 50-272	P B S J		800&110355 800&1&0002 800&1&0037 800&1&0038* 800&18000&	50-244 F 50-244 P 50-244 R 50-244 R 50-244 Q
	8006180513* 8006190649 8006230454 8006230527 8006230535*	50-272 50-272 50-272 50-272 50-272	0 8 8		8004180514 8004180537 8004190473 8004190478* 8004230401	50~244 P 50~244 P 50~244 E 50~244 E 50~244 S
	8006240371 8006240375 8006240443 8006240449* 8006240486	50-272 50-272 50-311 50-311 50-272	9 8 8 8		8004240405 8004250242 8004250245* 8004300344 8004300433	50-244 Q 50-244 P 50-244 P 50-244 Q 50-244 P
	8006240492# 8006250226# 8006300233 8006300282 8006300282	50-272 50-354 50-272 50-272 50-272	8 Q Q Q	Rockwell International Corp Rockwell International Corp , Energy Systems Div	8004300494 8004030070 8004170297* 8004250054	50-244 Q XPORTLIC 70-25 70-25
	8004300370 8004300373* 8006300421 8006300424* 8006300459	50-272 50-272 50-272 50-272 50-272	8 8 8 8	Racky Mountain Energy Go ,	8006060089 8006060093# 8006190344 8006190670 8006240269 8006240271	40-8697 40-8380 40-8380 40-8380 40-8697 40-8380
	9006300465* 8006300477 8006300487* 8006300470 8006300470	50-272 50-311 50-311 50-272 50-272	8 8 9 0	Rogovin, Stern & Huge Ropes & Oray	8004240079 8004130313 8004170107 8004230034* 8004040447	40-8380 M180 50-443 H CONTRACT 50-309 G
Puerto Rico Electric Power Authority Puget Bound Power & Light Co	8006180158 8006110247 8006180181 8006180181	50-376 NUREQ 50-522 50-522	o o	TOPPE & STAY	8006180274 8006180326 8006230261	50-307 Q 50-307 Q 50-443 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Rosemount, Inc Rose Construction Co S M Stoller Corp (subs of Arthur D Little, Inc.)	0006120383 0006200632 0006090028 0006110059#	PT21 PT21 40-8502 50-361 G	Science Applications, Inc	8006020348 8006190104* 8006230041* 8006250330 8006270391*	50-320 P CONTRACT CONTRACT CONTRACT CONTRACT
Sacramento Municipal Utility District	8006030342 8006030361 8006030367* 8006110069 8006110131	90-312 I 50-312 P 50-312 S 50-312 P 50-312 P	Genate	6005210113 6006120280 6006170873 6006270095* 6006270106*	50-546 H 50-271 U PR 50-302 H 50-287 H
	8006130337 8006130337 8006130341* 8006160010 8006180632	50-312 1 50-312 0 50-312 0 50-312 8 50-312 9		8006270146+ 8006270155+ 8006300347 8006300522+ 8006300529+	50-171 U 50-171 H 50-275 H 50-320 H 50-320 H
	8006170636 8006170641* 8006240488 8006250954* 8006250237	50-312 R 50-312 R 50-312 P 50-312 Q 50-312 S		8006300534* 8006300538* 8006300541* 8006300551* 8006300562*	50-320 H 50-320 H 50-320 H 90-320 H 50-320 H
	8006250238* 8006300374 8006300405* 8006300528 8006300533*	50-312 8 50-312 8 50-312 8 50-312 8 50-312 8	Senate, Commerce, Science & Transportatio Senate, Energy & Natural Resources Senate, Finance Senate, Governmental Affairs	8004170134 8004300392 8004040289	50-320 H 50-546 H PRM 50-329 H 50-346 H
Safe Energy for New Haven San Antonio: TX San Diego Cas & Clectric Co	8006060232 8006120272 8006110017* 8006110017* 8006110024*	50-454	Bhannon & Wilson, Inc Bhaw, Pittman, Potts & Trowbridge	8006120079* 8006120129* 8006120820 8006030042* 8006040012	50-311 U 50-358 H 50-483 U CONTRACT PR
	*#\$200116008 *#8200116008 *#1200116008 *1200116008	50-361		8006060250 8006060253 8006060423 8006060475 8006060809	50-287 Q 50-287 Q 50-289 Q 50-289 Q 50-448 Q
	8006110098 8006110098 8006110107* 8006110107* 8006120291	50-361		8006060527 8006060547 8006110110 8006110116 8006110117#	50-289 Q 50-320 Q 50-289 Q 50-289 Q
Ban Luis Obispo Mothers for Peace Sandia Laboratories	8006040194 8006040196* 8006040199 8006020225* 8006040086	50-275		8004110334 8004110341# 8004110350# 8004120020 8004120022	50-312 T 50-312 T 50-312 T 50-289 Q 50-289 Q
	8005060168 8005090514 8006110046* 8006130360 8006160141	71-6400 NUREO 50-361 O REB NUREO		8006120036 8006120040 8006120084 8006120414 8006130237	50-287 0 50-287 0 50-287 0 50-289 0 50-289 0
	8006170330 8006200535 8006200546 8006200578 8006230011	RES NUREO NUREO NUREO NUREO		8006160004 8006160043 8006160046* 8006160052 8006160078	50-289 0 50-289 0 50-289 0 50-289 0 50-320 0
	8006250338 8006260286 8006270349 8006300204 8006300211	RES NUREO NUREO RES RES		8006170399 8006170733 8006170785 8006180154 8006180199	50-266 0 50-387 0 50-289 0 50-289 0
Sargent & Lundy, Inc	8006300218 8006090073* 8006170564* 8006170564* 8006170386*	RES 50-546 A 50-254 F 50-254 F 50-254 F		8006180315 8006180934 8006190435 8006190484 8006260276	50-287 0 50-320 0 50-267 0 50-307 0 50-289 0
	8006170591* 8006170591* 8006170597* 8006170602* 8006170607*	50-254 F 50-254 F 50-254 F 50-254 F 50-254 F	Sheldon, Harmon & Weiss	8006270216 8006270237 8006110049 8006110224 8006110370	50-320 0 50-287 0 50-443 0 PR 50-287 0
	8006170613* 8006170616* 8006170622* 8006170628* 8006170632*	50-254 F 50-254 F 50-254 F 50-254 F 50-254 F		8006110380* 8006110465 8006120371 8006120381 8006160089	50-289 0 PR 50-289 0 50-289 0 50-443 0
Sassafras Audubon Society Savannah River Ecology Laboratory Save the Valley - Save Marble Hill	8006200137* 8005210187* 8005210202* 8006300127 8005210217*	GA999 30-544 T 50-546 T NUREQ 50-546 T		8006170247 8006170340 8006230206 8006240358 8006240483	PR PR COMMISSION 50-155 Q 50-247 Q
	8005210217# 8006090585 8006170342# 8006170342#	50-546 T 50-546 H 50-546 H 50-546 H		8006240537 8006260186 8006260186 8006260188* 8006260188*	COMMISSION 50-247 0 50-247 0 50-247 0 50-247 0

ADHTUA VIGITALIARA	ACCESSION NUMBER	CATEGO!	ł Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Shoreham Opponents Coalition Sierra Club	8006300670 8006160087* 8006020113 8006180216 8006190439*	FOIA 50-322 FOIA FOIA 50-133	0		8006190440 8006190444* 8006190444* 8006190497 8006190522	50-361 50-361 50-206	8 8 9 1
Sigma Chemical Co (subs of Sigma-Aldri ch Corp)		50-574 FOIA XPORTLIC			8006190584 8006200150 8006200464 8006200186	PROJ 50-206 50-395	P F K K
Skagitonians Concerned About Nuclear Power	8006060299 8006190447	50-522 50-522	o G		8004230190* 8004230313		8
Slemmons, D B Small Business Administration Smell & Nilmer Bouth Carolina Electric & Gas Co	8006200137* 8006160227* 8006110417 8006030477 8006040241	CONTRACT CONTRACT 50-275 50-395 50-395	ī		B004230323* B004230517 B004240440 B004250214	50-204 50-341 50-341 50-341	8 A A A Q
	8004040304 8004050042 8004050047* 8004040116 8004040343	50-395 50-395 50-395 PR 50-395	8 8 8 8	Southwest Texas Electric Cooperative Spiegel & McDiarmid	8006130243 8006060026 8006060361 8006110371	50-445 50-498 50-498 50-445	MMMM
	8006060344* 8006180401 8006190654	30-395 50-395 50-395	F S G	Square D Co , Electromagnetic Industries St Joseph Hosp Stamford.CT Standardised Nuclear Unit Power Plant System	8006170240 8006270025* 8006120269	70-2260 NUREG	
	8004230424 8004230455	50-375 50-375	9 8		8006120311		8
South Carolina, State of South Dakota, State of	8006240276 8006300320 8006120159 8006190064* 8006190375*	50-395 50-395 NUREQ 40-1341 40-1341	g Q		8006120311 8006120311 8006120311 8006120312 8006120312	50-482 50-482 50-482	8 8 0 0
Southern California Edison Co	8006020340 8006020340 8006030295 8006030358 8006030373	50-206 50-204 50-206 50-395 50-206	F F P A P		8006120312 8006120312 8006170492 8006170492 8006170492	50-482 50-482 50-482	0 0 8 8
	8004030420 8004030430 8004030434* 8004030438* 8004030439	50-206 50-206 50-206 50-206 50-206	8 8 8	Stanford Research Institute	8006170612 8006170612 8006170612 8006250018 8006230048*	50-492 50-482	8 8
	8004030513 8004030517* 8004050019 8004050023* 8004040297	50-204 50-204 50-395 50-395 50-204	, 8 8 6 6 8	Stanford Univ State.Dept of	8006110122 8006050532 80060606079 80060606083 8006060087	50-141 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	H
	8006060307* 6006060337 8006060337 8006060340* 8006060340*	50-206 50-361 50-361 50-361 50-361	8 8 8 8	State,Dept of, Bureau of Doeans & Internati Environ & Scientific Affairs	8004120509 8004130185 8004230084 8004030054	XPORTLIC XPORTLIC FOIA XPORTLIC XPORTLIC	
	B004040357 B004040357 B004040360* B004040340* B004040375	50-361 50-361 50-361 50-361 50-361	5 5 6 6		8004030114 8004050480 8004040201 8004040203 8004040203	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8004040393 8004110009 8004110011 8004110013*	50-361 50-206 50-361 50-206 50-361	A P P P Q		8004090424 8004120078 8004120430* 8004120473* 8004120477*	XPORTLIC XPORTLIC SECY BECY SECY	
	8006110019* 8006110024* 8006110024* 8006110028* 8006110028*	50-361 50-361 50-361 50-361 50-361	0000		8006120482* 8006170095 8006170110 8006170120 8006170382	SECY XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	H004110031* B004110031* B004110055* B004110098 8004110098	146-08 146-08 146-08 146-08 146-08	0 0 0 0		8006230116 8006250287 8006260032 8006260034 8006260036	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	8006110107* 8006110107* 8006110254 8006120286 8006120290*	50-361 50-361 50-375 50-206 50-206	G G B B S	Steel, Hector & Davis Stone & Webster Engineering Corp	8004240050 8004240050 8004240052 8004110093 8004250300*		ь Ь
	8006130210 800613021B* 8006130301 8006130301 8006160011	50-206 50-206 50-361 50-361 50-206	5 9 A A R		8006250302* 8006250309* 8006250312* 8006250314* 8006250316*	50-339 50-339 50-339	<u></u>
	8006160013* 8006180301* 8006190440	50-206 50-206 50-361	R G S	Stone & Webster, Inc Suffolk County, NY	8004250318* 8004140241 8004130020	50-337	P 8 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATI	ON	ACCESSION NUMBER	SUBJEC CATEGO	RY
Susquehanna Alliance Susquehanna Environmental Advocates Swedish Hosp Medical Center Seattle, WA Switzerland	8006130162* 8006170503 8006120027 8006120217* 8006130236	50-322 50-387 50-387 COMMISSI XPORTLIC	0 D 0			8006040370 8006040383 8006060383 8006040387* 8006040387*	50-553 50-438 50-438 50-438 50-438	A S S S
TERA Corp TRW, Inc., TRW Mission Mfg. Co. Div Teknekron, Inc.	8006050529* 8006060483* 8006250042* 8006300149* 8006030049*	CONTRACT 50~70 CONTRACT GA999 CONTRACT	P			8004040374 8004040401 8004040401 8004040401 8004040401	50-327 50-519 50-519 50-518 50-519	សេខ១១១
'eledyne Energy Systems /eledyne Engineering Services Teledyne Isotopes	8006170662 8006300555* 8006300630 8006160008* 8006300014	CONTRACT CONTRACT 71-5862 50-329 70-124	s			8006060401 8006060401 8006060403* 8006060412 8006060413*	50-518 50-518 50-327 50-327 50-518	0 0 0 0 0 0
Teledyne Precision - Cincinnati Tennessee Valley Authority	8006190107 8005230276 8006020178 8006020183* 8006020338	XPORTLIC 50-327 50-327 50-327 50-438	P P P A			8006060413* 8006060413* 8006060413* 8006060413*	50-518 50-519 50-518 50-518 50-518	9 8 8 8 8
	8004030080 8004030344 8004030344 8004030392 8004030392	50-327 50-438 50-438 50-328 50-328	R A A S S			8005050415* 8005050484 8005050484 8005050487* 8005050487*	50-327 50-390 50-390 50-390 50-390	ម ម ម ម ម
	8006030372 8006030397 8006030378* 8006030378*	50-328 50-327 50-328 50-328 50-328	5 9 8 8			8006090330 8006090330 8006090336* 8006090336*	50-327 50-327 50-438 50-327 50-327	9 9 9 9
	8006030408* 8006030417 8006030417 8006030427 8006030442	50-327 50-327 50-327 50-327 50-259	ន p p ន			8004090337* 8004090454 8004090471 8004090471	50-43B 50-51B 50-43B 50-43B 50-43B	9 9 9 8
	8006030447* 8006030452* 8006030453 8006030457 8006030460*	50-327 50-259 50-327 50-327 50-327	5 5 5 6			8005090476* 8006110036 8006110036 8006110043* 8006110043*	50-438 50-390 50-390 50-390 50-390	8666
	8006030463* 8006030480 8006030490* 8006030604* 8006030604*	50-327 50-327 50-327 50-553 50-553	9 9 9 9			8006110048 8006110048 8006110048 8006110048	50-518 50-518 50-518 50-518 50-518	8 8 8
	6006030608* 8006040007 8006040230 8006040233* 8006040245*	50-553 PR 50-518 50-518 50-566	G S S G			8006110048 8006110058* 8006110058* 8006110058*	50-519 50-519 50-519 50-518 50-518	8 8 8
	8006040256# 8006040306 8006040308# 8006050002	50-544 50-328 50-328 50-544 50-544	0 8 8 8			8006110059* 8006110058* 8006110074 8006110074	50-518 50-518 50-438 50-438 50-438	9 9 9
	8006050004* 8006050004* 8006050026 8006050026 8006050031*	50-544 50-544 50-327 50-327 50-327	9 9 9			8004110079# 8004110097 8004110104 8004110124# 8004110138	50-43B PR 50-276 50-276 50-438	9 8 8
	1006050031 \$006050608 \$110406008 \$2060608	50-327 50-391 PR 50-518 50-518	9 F 9 8			8006110138 8006110156 8006110156* 8006110173	50-438 50-240 50-260 50-327 50-327	5 5 5
	8004040230 8004040235 8004040235 8004040235 8004040270	50-518 50-257 50-257 50-257 50-257	8 F F 8			8006110219 8006110223* 8006110250 8006110259 8006110259	50-327 50-327 50-327 50-327 50-327	8 8 8
	8005050270 8005050274 8005050274 8005050274 8005060274	50-390 50-327 50-327 50-327 50-327	9 F F F			8006110262* 8006110262* 8006110263 8006110269	50-327 50-327 50-438 50-438 50-259	# # # #
	8006060298* 9006060305* 9006060309 9006060313	50-370 50-370 50-370 50-276 50-257	9 9 9 F			8006110270 8006110274 8006110274 8006110276* 8006110280*	50-327 50-544 50-564 50-327 50-259	8 8 8
	8004060313 8004060313 8006060323* 8006060356 8006060356	50-259 50-259 50-296 50-518 50-518	F F 8 9 9			8006110283 8006110284* 8006110284* 8006110285* 8006110285*	50-327 50-566 50-566 50-438 50-438	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8006110286 8006110287 8006110292* 8006110294* 8006110315	50-259 50-259 50-259 50-259 50-327 50-438	6 8 8 8		8006170746* 8006180064* 8006180072* 8006180232 8006180484	50-566 50-518 50-518 70-1966 50-327	G G G
	000110115 8160114008 8260114008 8260114008 8660114008	50-438 50-327 50-438 50-438 50-438	A 11 13 16 16		8006180487* 8006180502 8006180520* 8006180521 8006180524*	50-327 50-294 50-296 50-327 50-327	000000
	8006120037* 8006120037* 800612013 8006120113	50-438 50-438 50-438 PR 40-1341	5 0 0		8004180527 8004180533* 8004180535* 8004190385	50-327 50-327 50-327 50-327 50-390	000000
	8006120207 9006120309 9006120309 9006120309	50-438 50-518 50-518 50-518 50-518	A \$ \$ \$ \$ \$		8006190391 8006190391 8006190466 8006190468 8006190470*	50-327 50-327 50-553 50-259 50-259	天大 6 5 6
	9006120309 9006120313* *E1E0516008 *E1E0516008	50-518 50-518 50-518 50-518 50-518	8 6 8		8004190584 8004190415 8004190415 8004200321 8004200324*	50-327 50-327 50-327 50-327 50-327	0 P P P
	8004120313* 8004120313* 8004120313* 8004130004 8004130244	50~518 50~518 50~518 40~1341 50~370	8 8 8		8006200375 8006200378* 8006200432 8006200432 8006200432	50-566 50-566 50-518 50-518 50-518	8 8 8
	8004130246 8004130295 800413029&* 8004130307 8004130307	50-390 50-327 50-327 50-327 50-327	0 R R F F		8004200432 8004200432 8004200432 8004200451 8004200454*	50-518 50-518 50-518 50-327 50-518	9999
	8006160054 8006160069 8006160069 8006170211* 8006170331	50-390 50-327 50-327 50-327 FR	9 8 9		8006200454* 8006200454* 8006200454* 8006200454*	50-518 50-518 50-518 50-518 50-518	80808
	B006170485 B006170485 B006170489* B006170489* B006170497	50-438 50-438 50-438 50-438 50-259	8888		8006200457* 8006200475 8006200484* 8006200488 8006200497*	50~327 50~327 50~327 50~327 50~327	8 8 8
	8006170501 8006170501 8006170502* 8006170506 8006170507*	50-259 50-259 50-259 50-296 50-259	R R 8 R		8006230033* 8006230267* 8006230327* 8006230327* 8006230438	50~370 50~327 50~438 50~438 50~257	9
	8006170512* 8006170525 8006170525 8006170536 8006170540	50-296 50-390 50-390 50-327 50-566	8 8 8		8006230488 8006230488 8006230514 8006230514 8006230514	50-439 50-439 50-259 50-259 50-259	9 9 P P
	8006170541* 8006170543 8006170545 8006170547* 8006170552*	50-327 50-327 50-328 50-327 50-328	8 8 8		8006230520* 8006230520* 8006230520* 8006240164* 8006240164*	50-259 50-259 50-259 50-259 50-259	р Р О
	8006170554 8006170561* 8006170566 8006170575* 8006170591	50-327 50-327 50-259 50-259 50-276	8 8 8		8006240164* 8006240254 8006240258* 8006240258*	50-259 50-327 50-259 50-259 50-259	0 0 0
	8004170582 8004170582 8004170592* 8004170594 9004170597	50-327 50-327 50-294 50-390 \$0-327	G G S S		8004240240 8004240240 8004240240 8004240240 8004240323	50-327 50-327 50-327 50-327 50-327	G G G P
	8004170599 8004170403 8004170403* 8004170414* 8004170435	50-327 50-294 50-390 50-294 50-259	8 9 8 8		8004240323 8004240328 8004240328 8004240330* 8004240330*	50-327 50-327 50-327 50-327 50-327	P 8 8 8 8
	8006170639* 8006170689 8006170659 8006170659 8006170672*	50-257 50-328 50-328 50-328 50-328	8 8 9 8		8006240363 8006240369* 8006240372 8006240372 8006240374	50-327 50-327 50-327 50-327 50-327	88888
	8006170672* 8006170672* 8006170685 8006170691* 8006170746*	50-328 50-328 50-327 50-327 50-566	3 C C C		8006240377 8006240377 8006240380* 8006240388 8006240390	50-390 50-390 50-327 50-327 50-390	8888

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	·
, 	8006240390 8006240396# 8006240397# 8006240397# 8006240405	50-390 50-327 50-390 50-390 50-438	S S S S S	Texas Utilities Co Texas Utilities Generating Co	8006180013 8006050561* 8006060541 8006050113* 8006050113*	50-445 50-445 50-445	G M M G G
	6006240410 6006240412 6006240420* 6006240423* 8006240425	50-327 50-327 50-327 50-327 50-327	8 8 6 8 8		8006060347 8006060570 8006090140 8006090175 8006090584#	50-445 50-445 50-445	0 8 0 M 0
	8006240433* 8006240453 8006240472 8006240499 8006240509*	50-327 50-390 50-327 50-296 50-296	\$ \$ p \$		8006070584* 8006110302 8006110454 8006120052 8006120245*	50-445 PR	G M M Q
	6006250053 6006250062 6006250062 6006250065* 6006250065*	70-2910 50-391 50-391 50-391 50-391	A A A		8006120398 8006170141# 8006170157# 8006180118 8006190063	50-445 PRM PRM 50-445 50-445	T G
	8006250144* 8006250198 8006250198 8006250227 8006250227	50-257 50-370 50-370 50-438 50-438	0 8 8 8		6006190458 6006190740 6006230115 6006230156 6006240242	50-445 50-445 50-445 50-445 50-445	A Q B S
	8006250230* 8006250230* 8006250234 8006250234 8006250252	50-439 50-438 50-370 50-370 50-553	8 8 8 6	Texas, State of Texas-Louisiana Electric Cooperative, Inc. The Gouthern Co.	8006060353 8006090083* 8006110371 8006250193 8006170314*	PR 50-466 50-445 50-445 50-321	0 M M
	8006250252 8006250256 8006250257 8006250257 8006250261*	50-593 50-518 50-553 50-553 50-553	0 8 8 8	Three Mile Island Alert	8006060388 8006120085 8006120330 8006120335 8006160131	50-289 50-289 50-289 50-289 50-289	00000
	8006250261* 8006250275 8006250275 8006250275 8006250281*	50-553 50-518 50-518 50-518 50-518	8 8 8 8	Taledo Edison Co	8006170628 8006020117 8006020475 8006030210 8006030311	50-289 50-346 71-9081 50-346 50-346	O P O R
	8006250281* 8006250281* 8006250281* 8006250237 8006260160	50-518 50-518 50-518 REGCD 50-327	9 8 8		8006030313* 8006030372 8006030377* 8006050522 8006050527	50-346 50-346 50-346 50-346 50-346	R S Q Q
	8006260160 8006260162* 8006260162* 8006260164 8006260165*	50-327 50-327 50-327 50-327 50-327	8 8 F F		8005050303 8005090554 8005120192 8005120343 8005120344*	50-346 71-6144 71-9094 50-346 50-346	F 6
	8004260165* 8004270197* 8004270204 8004270249 8004200228	50-327 50-438 50-390 50-259 50-259	F 0 0 P 0		8006120345 8006120347* 8006120350 8006120352*	50-346 50-346 50-346 50-346 50-346	8 8 8 8
	8004300228 8004300248 8004300257* 8004300387 8004300391	50-259 50-327 50-327 50-327 50-390	Q Р Р Р		8006120357* 8006130274 8006130275* 8006160082 8006160085*	50-346 50-346 50-346 50-346 50-346	8 R 8 8
	8006300391 8006300430 8006300457* 8006300516 8006300523*	50-390 50-328 State Pr 50-327 50-327	A P Og S S		8006170351 8006170354* 8006170456 8006170463* 8006170472*	50-346 50-346 50-346 50-346 50-346	\$ 8 P P
': State of 'loration Drilling Co , Inc	8006260166* 8006020034 8006020037* 8006050520 8006070004	50-327 40-8693 40-8693 40-8720 40-8693	F		8006200379 8006230110 8006230201 8006230460 8006240494	50-346 50-275 50-346 50-346 50-346	О А О Р
* M Univ	8006110348 8006110357 8006020534* 8006230152* 8006230420	40-8728 40-8728 50-126 50-128 50-128	a a s	Franscomm. Inc Transcordear, inc	8004250059* 8005080533 8005080537* 8004030059 8004030043*	CONTRACT 71-9015 71-9015 XPORTLIC XPORTLIC	3
Etric Bervice Co Eruments. Inc	8004110282* 8004050078* 8004110152* 8004200149 8004300011	50-445 70-33 50-367 70-33 70-33	M R		8006120420 8006120424* 8006120497 8006120500* 8006120502*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	C C C
to the light Co lic Interest Research Group	8006110282* 8006110346 8006120167 8006160028 8006160029*	50-445 50-466 FOIA 50-466 50-466	M. G.	Transportation.Dept of Tubeco. Inc	8006260019 8006260022* 8006160169 8006190356* 8006190370*	XPORTLIC XPDRTLIC NUREQ GA999 GA999	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Tuomey, Latham / Schmitt US Radium Corp Union 76 Minerals Exploration Co Union Carbide Corp	8006190570 8006300296 8006270263 8006040095* 8006040099*	50-322 0 XPORTLIC 40-8584 71-9853 71-9853		8004050341* 8004050351 8004060407 8004040410* 8004070252	50-337 P 50-337 B 50-338 B 50-338 R
	8006040102* 8006040105* 8006040107* 8006040109* 8006160203	71-9853 71-9893 71-9853 71-9853 ACRS		8006070253* 8006070341 8006070357 8006070361* 8006070388	50-338 R 50-337 P 50-338 S 50-338 S 50-280 Q
Union Electric Ca	8006180218 8006200262 8006230021 8006230709 8006090531	XPORTLIC 50-54 S 70-687 XPORTLIC PR		8006110005 8006110005 8006110007# 8006110003	50-338 F 50-338 F 50-338 F 50-338 F 50-280 P
Union Kinerals	6006110240 6006170260 6006230069* 6006240441 6006020533	50-483 H 50-483 A 50-483 G 50-483 S 40-8584		8004110063 8004110043 8004110043 8004110204 8004110252	50-280 P 50-280 P 50-280 P 50-281 S 50-339 S
Union of Concerned Scientists	8006040183 8006060009* 8006160208 8006040047 8006110370	40-8584 40-8348 40-8584 50-320 P 50-289 0		8006119257* 8006110265* 8006110324 8006110324 8006110324	50-339 8 50-281 8 50-280 8 50-280 8 50-280 8
	8004110380* 8004110445 8004120371 8004120381 8004240483	50-289		8006110324 8006120301 8006120301 8006120304# 8006120317	50-280 S 50-338 R 50-338 R 50-338 R 50-280 S
United Engineers & Constructors, Inc (subs of Raytheon Co)	8006260188* 8006020019 8006020052	50-247 G 50-449 B 50-440 S		6006120323* 8006120326* 8006120331 8006120333*	50-280 8 50-280 8 50-338 8
United Nuclear Corp	8006180372 8006190735*	50-443 6 70-820		8006120337*	50-281 S
United Nuclear Corp , UNC Recovery Systems Div	8006030102 8006180374 8006240231 8006250016	PR 70-820 70-820 70-820		8006120341* 6006120359 8006120362* 8006120378	50-281 8 50-338 8 50-338 9 50-337 P
United Nuclear Corp , Naval Products Div	8004250130 8004250153 8004040158 8004040140* 8006110444	40-8728 70-820 70-371 70-371 PR		8006120386 8006120386 8006120388 8006120392 8006120395	50-338 G 50-338 G 50-339 P 50-339 P 50-339 P
Utah, State of Valentine B Deale Vermont Yankee Nuclear Power Corp	8006200589 8006180429 8006080274 8006030314	40-8681 50-338 0 50-271 P 50-271 P 50-271 S		8006130174 8006130174 8006130297 8006130297 8006130299*	50-338 8 50-338 8 50-280 P 50-280 P
	8006030329 8006030333# 8006030469 8006060511 8006110019 8006170548	50-271		8006130299* 8006130334 8006130334 8006130334 8006130334	50-280 P 50-280 P 50-280 P 50-280 P
	8006170589 8006170595* 8006170645 8006170649* 8006200492	50-271 9 50-271 9 50-271 R 50-271 R 50-271 J		8004160053 8006160056* 8006160074 8006160079* 8006170513	50-337 8 50-337 8 50-337 8 50-337 8 50-280 R
Vermont, State of Vinginia Electric & Power Co	8006200501 8006260370* 8006270192 8006170345 8006020173	50-271 Q 50-271 Q 50-271 P PR 50-280 P		8006170513 8006170517* 8006170518 8006170580 8006170587*	50-280 R 50-280 R 50-337 E 50-337 B 50-339 B
•	8004020173 8004020277 8004030014 8004030014 8004030334	50-280 P 50-404 G 50-338 F 50-338 F 50-280 S		8006170611 8006170615* 8006170621* 8006170626* 8006170633*	50-339 P 50-339 P 50-339 P 50-339 P 50-337 P
	8006030338 8006030338* 8006030336* 8006040174 8006050223 8006050227*	50-280 8 50-280 8 50-280 F 50-338 P		8006170643 8006170653 8006170653 8006170662* 8006170694	50-338 8 50-338 8 50-280 9 50-280 8 50-337 6
	8006050304 8006050308* 8006050323 8006050323	50-938 \$ 50-938 8 50-280 F 50-280 F		8006170699 8006170699 8006170701* 8006180470 8006180476*	50-280 P 50-280 P 50-339 8 50-280 8 50-280 8
	8006050327 8006050330* 8006050333* 8006050336* 8006050337*	50-337 P 50-337 P 50-337 P 50-337 P		8006180532 8006190463 8006190543 8006190545 8006190562	50-337 P 50-337 P 50-280 P 50-280 P 50-280 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATIGN	ACCESSION NUMBER	SUBJECT CATEGORY
	8004190542 8004200480 8004200604 8004200604 8006200604	50-280 P 50-339 P 50-280 Q 50-280 Q	Virginia Tech	8006300507* 8006300512* 8006300673 8006300673 8006270038	50-339 P 50-339 P 50-280 Q 50-280 Q NUREO
	8006230189* 8006230417 8006230418* 8006230442 8006230444	50~280 0 50~339 8 50~339 8 50~339 8 50~338 8	Virginia, State of Virginia, Univ of W A Wahler 3 Associates, Inc	8006110060 8006170828 8006300102 8006160225 8006160229*	PR PRM NUREG WASTE MGT WASTE MGT
	8006230444 8006230447* 8006230494 8006230499 8006230499	50-338	Walter Kidde & Co , Inc , Fenwal, Inc Washington Public Power Supply System	8006170781 8006030464 8006050358 8006050540 8006060480	PR 50-460 A 50-460 A 50-397 A 50-397 Q
	8006230499 8006230499 8006230500* 8006230503 8006230507	50-280 S 50-280 S 50-339 S 50-338 S 50-280 P		8006090404* 8006090414* 8006110135 8006110139* 8006110278	50-460 Q 50-460 Q 50-397 K 50-397 K 50-397 A
	8004230507# 8004230514 8004230524* 8004230534 8004230537#	50~338 8 50~338 8 50~338 8 50~339 8 50~339 8		8006130305 8006170141* 8006170157* 8006170509 8006240404	50-397 A PRM PRM 50-397 K 50-397 F
	8006230544 8006230551* 8006240238 8006240238 8006240238	50-339 8 50-339 8 50-280 0 50-280 0 50-280 0		BCO4240408 * BCO4240413* BCO4240413* BCO4240418* BCO4240418*	50-397 F 50-397 F 50-397 F 50-397 F 50-397 F
	8006240283 8006240386 8006240386 8006240427 8006240434*	50-281 0 50-280 0 50-280 0 50-280 S 50-280 B	Washington State Univ Washington Univ	8006270324 8006270326* 8006300381 8006060311 8006250090*	50-460 F 50-460 F 50-397 A 50-27 P CONTRACT
	8006240469 8006240469 8006240478* 8006240478* 8006240484	50-338 F 50-338 F 50-338 F 50-338 F 50-280 Q	Weschester County,NY West Texas Legal Bervices	8004120403 8004070005 8004070005 8004070007 8004070007	FOIA 50-445 0 50-445 0 50-445 0 50-445 0
	8006240484 8006250099* 8006250120 8006250128 8006250129*	50-280 Q 50-280 Q 50-339 P 50-339 P 50-339 P	West Virginia Univ Western Nuclear, Inc (subs of Phelps Dodge Corp)	8006030341 8006030240 8006110088 8006240305	50-129 W 40-1162 40-1162 40-1162
	8006250132 8006250137 8006250289 8006250278# 8006260183	50-339 Q 50-33B P 50-339 P 50-339 P 50-338 F	Westinghouse Electric Corp	8006240306* 8003280527 9005120001 8005120018* 8006040223 8006060150	40-1162 50-282 P 71-5450 71-5450 TOPREP PR
	8006260183 8006260184* 8006260184* 8006270236 8006270241*	50-338 F 50-338 F 50-339 F 50-339 B		8006060372 8006090179 8006120252 8006120258* 8006120349	TOPREP XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-445 A
	8006270262 8006270265* 8006270270 8006270275* 8006270277	50-338 8 50-339 8 50-337 9 50-337 8 50-280 8		8006120404 8006120439 8006120442 8006120446* 8006120447	50-3 P XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8006270292 8006270294* 8006270302* 8006270310	50-281 8 50-280 8 50-281 8 50-338 8		9004120450* 8004120452 8004120532 8004130320 8004140217	XPORTLIC 70-2542 XPORTLIC TOPREP 70-698
	8006270315* 8006300235 8006300235 8006300235	50-338 8 50-280 0 50-280 0 50-280 0	•	8004170358 8004170340* 8004170446* 8004180002* 8004180404*	TOPREP TOPREP 50-247 P 70-1151 50-375 S
	8004300253 8004300253 8004300253 8004300349 8004300349	50-280 Q 50-280 Q 50-280 Q 50-280 Q		8006180540 8006190139 8006200007* 8006200101 8006200107*	RE8 70-1143 70-1151 70-698 70-698
	8006300349 8006300389 8006300388 8006300388	50-280 P 50-280 P 50-280 P 50-280 P		8006200120 8006200576 8006200591 8006200592 8006230304	70-1143 70-1143 70-2909 70-1143 70-1143
	8006300456 8006300456 8006300456 8006300501 8006300507*	50-280 P 50-280 P 50-280 P 50-339 P 50-339 P		8004230308* 8004240101* 8004250021 8004250050	70-1143 GA999 70-1151 70-1151

ACHTUA ACTALLATAN	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	
Westinghouse Electric Corp , Nuclear	8006250117* 8006260010 8006260044 8005120006*	GA999 XPORTLI XPORTLI 71-5450	C	Wisconsin's Environmental Decade Wisconsin, State of	8006250185 8006030287 8006160074	50-305 50-266 50-409	G G D
Energy Systems	B005120009#	71-5450			8006250045* 8006260193	GONTRAC 50-409	D
	800\$120014# 8006050032# 8006090396#	71-5450 50-244 50-280	S Q	Wise, W C Wolverine Electric Cooperative Woodward-Clyde Consultants, Inc	8006240137 8006170407* 8006110039*	50-250 50-341 50-361	H I O
Westinghouse Electric Corp . PWR Systems Div	8004040087	XPORTLI			8006110041* 8006180536*	50~361 50~3	Q R
	8006160127 8006170666	TOPREP		Worsham, Forsythe & Sampels Wyoming Mineral Corp	8006050561# 8006110302 8006050164	50~445 50~445 40~8502	M
Westinghouse Operating Plants Owners	8006230162 8006300017 8006300292 8006030596	70-2909 70-1151 70-1151 NUREG		mydallig illieta. 667,p	8004050148* 8004050172* 8004050444	40~8502 40~8502 40~8502	
Grava					8006050448* 8006060431	40~8502 40~8502	
Widoff, Reager, Selkowitz & Adler	8006060388 8006120085 8006120330 8006160151	50-289 50-289 50-289 50-289 50-289	0000		800609000B 8006090075 8006120163 8006120173* 8006120191	40-8502 PR 40-8502 40-8502 PR	
William Powell Co Wisconsin Electric Power Co	8006190628 8006060213* 8006030344	50-267 GA999 50-266	0 P	Wyoming Outdoor Council	8006180282 8006240451	40-8502 40-1162	
	8006030344 8006040060	50-266 50-266	P P	Wyoming, State of	8006240459* 8006040076 8006040257	40-1142 40-1142 40-1142	
	8006050034 8006050034	50-266 50-266	0 Q P		8006060155 8006120504	40-8745 40-8502	
	8006110129 8006110129 8006110149	50-266 50-266 50-266	F 8		8006170793 8006190051 8006230111 8006300118	40-1162 40-8348 40-8502 40-8502	
	8004110271 8004110271	50-266 50-266	Ÿ		004000400	40-1162	
	8006110279 8006160092	50-266 50-301	g G	Yale Univ Yankee Atomic Electric Co	8006030028 8006030028 8006030367	PR 50-27 50-29	FP
	8006170399 8006170473 8006170477*	50-246 50-246	Q R R		8004050283 8850504008	50-29 50-29	G G
	8006170477* 8006180558*	50-246 50-266	P P		8004050283 8004060469	50-29 50-29	G G
	8006190650 8006190650	50-266 50-266	Q Q		8004040449 8004040449 8004040803	50-27 50-27 50-27	Q Q
	8006200460 8006200547* 8006200547*	50-266 50-266	P G G		8004040504* 8004070240 8004070450	50-29 50-29 50-271	g P G
	8006239110 8006300262 8006300262	50-275 50-266 50-266	A Q Q		8006110029* 8006110177	50-271 50-29	G P
Wisconsin Public Service Corp	8006300452 8006160095	50-266 50-305	F R		8006110187* 8006170236	50-29 50-29	P
	8006160079* 8006170426	50-305 50-305	R P		8006170636 8006170639# 8006230576	50-29 50-29 50-29	R R F
	8006200465 8006200469* 8006200473*	50-305 50-305 50-305	9 9 8	York, PA	8006240590 8006120322*	50-29 50-289	G F
	8006240297 8006240493	50-305 50-305	G P	Zimmer Area Citizens - Zimmer Area Citizens of KY	8006060371 8006130021	50-358 50-358	e e

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCEBBION NUMBER	BUBJECT CATECORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCERSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
8006260007 8006260015	8005250007 8005250015	50-275 P RES	EQQ-CAAP-5136 EQQ-TFBP-5049	8004020138 8004020141	8004020138 8004020141	RES RES	LTR 1111-62 LTR LO-97-90-13
8006260020	8009590050	RES	E00-8EM1-5121	8006020144	8004020144	RES	LTR 1111-65
8006260025	8006260025	RES	BNL-NUREQ-27817	8006020184	6006020184	RES	LO-87-80-130
8004240031	B004240031	RES	EQQ-CAAP-5114	8004020189	8004020189	RES	MC B0-05-05-LR
8006260035	8006260035 8006260037	RES RES	EGG-CAAP-5162 EGG-LOFT-5165	6004020491	8004020481 8004020503	RES RES	LTR 20-69 L0-87-79-129
8004240037 8004240039	8006260037	RES	EQQ-8EMI-5047	8004020503 8004020539	8004020539	RES	EQQ-EA-5150
8006260042	8006260042	RES	EGO-8EMI-5090	8004020544	8006020544	RES	YBR-59-80
8004240044	8006260046	RES	E00-8EM1-5055	9004020552	8004020552	RES	E00-CAAP-5140
8006260425	8006260425	RES		8006020561	8004020541	RES	LO-00-8114
8006270078	8004270078	RES	ORNL/HABRD-78	8006020568	8004020548	RES	LTR-141-118
8004300171	9006300171	RES		8006120193	8006120193	RE9	
8004300183	8006300183	RES		8004120247	8006120247 8006120503	RES	
8006300189	8004300189	RES		9004120503			P E00-EA-5109
8006300204 8006300211	8006300204 8006300211	RE9 RE8		9006130360 9006130393	8006130360 8806130363	RES RES	ORNL/ED/E19-128
8006300215	8004300215	RES		8004130390	8006130390	RES	GRNL/MCD/NEEB-B
8006300218	8006300218	RES		8004130393	8004130373	REB	
8006300234	8006300234	REB		8006160174	8006160174	REB	ORNL/CSD/INF-80
8006300298	8006300298	RES	UC-70	8006170330	8006170330	RES	
B006300301	8006300301	REB	L0-00-79-108	8004170705	8004170705	RES	
8004300455	8006300455	REB	EEQ-GAAP-5134	8006170708	8006170708	REB	
8006300500	8004300500	REB 50-269 P	ORNL/HABRD-78 EQQ-EA-5164	9006170716 9006170721	8006170716 8006170721	RES RES	
8006300574	8006300574						
8006300598	8006300598	RES	ORNL/FTR-843	6006180026	8006180024	RES	EGG-CAAP-5152
81A0622 R1	8004180108*	50-282 P 50-282 P		8004180038 8004180097	8004180038 8004180097	REB REB	E0G-TFBP-5144 E0G-SEMI-5137
81A0623 R1	8006180101 8006270033*	50-262 P		8004180047	8006180261	RES	BNL-NUREQ-26297
AIF/NESP-019 ANL/RAS/LWR BO∺2	8004040093	ORO		8006180267	8006180267	REB	DIC-HOREW-ROLFT
BAW-1067	8006110085*	50-302 P		8006180306	8006180306	RES	E00-SEMI-5139
BAN-381	8006180165*	70-824		8006180540	8006190540	REB	
BAH-381	8006180169*	70-924		8004190045	9006190045	RES	ORNL/ED/EIS-129
BAW-381 R10	8004200169#	70-824		8004170060	8004190040	RES	ORNL/ED/EAS-80/ BNL-NUREQ-27581
BAW-381 R11	8006250211*	70-824		8006190070	8006190070	REB	
BAW-301 R12	8006270071*	70-824	16514	8006190079	8004190079	REB	BNL-NUREQ-275BO
BAW-381 R6	8006200172*	70-824		B006140885	8006190685	RES	EQG-CDAP-5149
CEN-122(F)	*915090908	50-335 P		8004200014	8004200014 8004200017	RES RES	BNL-NURE0-27541
CEN-123(F)-NP PT1	*12E0404008 ********************************	50-335 P 50-335 P		8006200017 8006200021	8004200017	RES	ORNL/HASRD-79
CEN-123(F)-NP PT2							
CEN-123(F)-NP PT3	6006060327*	50-335 P		B006200022	8004500055	RES RES	GRNL/HASRD-80
CEN-126(F)-NP	8006060315*	50~335 P		8008200023 8008200025	8009500052	RES	OKNE/HASKU-SU
CEN-129(H)-NP	8006200426* 8006200428*	50-309 P		B006200025	8006200026	RES	
CEN-131(M)-NP DOE/NE-0003/1	8005150214	50-307 P		B006200027	8006200027	RES	
DOE/NE-0003/2	8009190518*	ORO		8006200031	8004200031 8004200041	REB REB	EQQ/TFBP-5026
DDE/NE-0003/3	8006160221*	ORG		8006200041 8006200047	8004200041		P EQQ-EA-5154
DOE/NE-0003/4	8006160222*	ORQ ORQ		8006230096	8004230096	RES	
DOE/NE-0003/5	8006160226*	ORO		8006230078	8006250338	RES	
DOE/NE-0003/6					*		
DOE/NE-0003/7	*0ES0919008	ORO		8006250342	8004250342 8004250345	RES RES	ORNL/HASRD-77
E901183-4139	8006130040*	50-266 P	UCRL-15104	8006250345	8006250345 8006250347	RES	PURPLY MARKUTY
F-C5157-1	6004030040*	50-273 F		8006250347 8006250352	8006250352	RES	
F-C5189-2	#C4000043#	50-293 F 50-293 F		8006260004	8006260004		EQQ-EA-5167
F-C3137-3	8006030047*	20~%AG L		SOUGEDOOUT			

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSIUN NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
0EK-72281 NAC-E-801 NEDO-10084-2 V1 NEDD-10084-2 V2	800606160187* 8006160187* 8006060074* 8006060078*	50-333 (71-6698 71-9001 71-9001	1 16397 16333	NUREG/CR-1231 NUREG/CR-1237 NUREG/CR-1239 NUREG/CR-1242	8006270002 8006200578 8006200518 8006300085	NUREO NUREO NUREO NUREO	EALTS-PTGMAR C-MT\QBRUN\NNRG E-MT\QBRUN\NNRG
NEDO-11277 NEDO-24239	8006020243*	70-1007	74NED7 9 80NED258	NUREO/CR-1243 NUREO/CR-1243	8006300069 8006270344	NUREQ NUREG	GRNL/NUREG/TM-3
NEDD-24259 NFS-1001 NUREG-0254	8004240088* 8004040221* 8004300579	TOPREP 50-267 F 50-368 E	•	NUREO/CR-1264 NUREO/CR-1276 NUREO/CR-1283	8006260048 8006200588 8006260045	NUREO NUREO NUREO	BMI-2041 ORNL/NUREO/TOMC PNL-3265
NURE0-0254 NURE0-0282	8006270060 8006300102	NUREO NUREO	NRC-13	NVREO/CR-1287 NVREO/CR-1305	8006160141 8006200531	NUREO	9AND78-2411 GRNL/NUREG/TM-3
NUREG-0285 NUREG-0286 NUREG-0303 NUREG-0307	8006270040 8006300130 8006300122 8006270097	50-322 E NUREO NUREO NUREO	NRC-5	NUREO/CR-1315 NUREO/CR-1321 NUREO/CR-1331	8006300198 8006040086 8006270045	NUREO NUREO NUREO	UCRL-52740 SAND 80-0384 EQQ-EA-5079
NURE0-0320 NURE0-0322 NURE0-0347 81	8006300071 8006270026 8006300575	NUREO NUREO 50-546 E		NUREG/CR-1343 NUREG/CR-1354 NUREG/CR-1363 VI NUREG/CR-1363 V2	8006230011 8006270073 8006300506 8006300514*	NUREO NUREO NUREO NUREO	SAND80-0276 UFL/COEL/TR/038 EGG-EA-5125 EGG-EA-5125
NUREG-0380 V4 ND5 NUREG-0422 83	8006160149 8006180049	NUREQ 50-369 E		NUREG/CR-1363 V2 O-Y NUREG/CR-1368	8006300520# 8006200546	NUREO NUREO	EGG-EA-5125 BANDBO-7053
NUREG-0435 VI NO4 NUREG-0442 NUREG-0472 NUREG-0484 R1	8006260424 8006300027 8006020557* 8006090522	NUREG SO-204 P NUREG	r	NUREO/CR-1369 NUREO/CR-1369 NUREO/CR-1390 NUREO/CR-1392	8006270349 8006200563 8006200593 8006040081	NUREO NUREO NUREO NUREO	9AND80-7054 BMI-2049
NUREG-0494 NUREG-0660 VI	8006270073 8006040101	40~8681 NUREG		NUREG/CR-1397 NUREG/CR-1412	8006200535 8006260043	NUREO NUREO	ANL/EB-08
NUREG-046B NUREG-046B NUREG-046B NUREG-0474	8004300247 8004300256 8004270003 8004200597	NUREO NUREO NUREO NUREO		NUREO/CR-1422 NUREG/CR-1429 NUREG/CR-1430	8006120476 8006200583 8006200542	NUREO NUREO NUREO	ANL-CT-80-19 EQQ-2033
NUREQ-0480 NUREQ-0481	8004250060* 8004300187	50-287 P 50-320 P		NUREG/CR-1446 NUREG/CR-1452 NUREG/CR-1455	8006270401 8006090446 8006020543	NUREO NUREO NUREO	PNL-3364
NUREG-0686 NUREG-0694 NUREG-0695	8006160198* 8006200054 8006260423	50-10 D NUREG 70-1308	•	NUREO/CR-1462 ORNL/DEPA-4	8006300278 8006300278	NUREQ PR	PNL-3384 UC-70
NUREG-75/097 03 9 6 NUREG/CP-0011 NUREG/CR-0588	8006070117 8006240077 8006260038	NUREO PR NUREO	PBRP-3 4 6 R2	RTL-090 BECY-77-283A BECY-78-142 BECY-78-365	8006230365 8006030118 8006020523 8006070436#	RES SECY SECY CONTRACT	
NUREO/CR-0641 NUREO/CR-0672 V1	8004090514 8004250171	NUREO NUREO	8AND78~8034	BECY-79-038A SECY-80-132C	B006020351 B006020232	50-320 P	
NUREO/CR-0808 NUREO/CR-0827 NUREO/CR-0849 VI NUREO/CR-0849 VA NUREO/CR-0930 V2	8004020537 8004270342 8004240053 8004040098 8004270398	NUREO NUREO NUREO NUREO NUREO	PNL-2795 PNL-3021 UCRL-52715-79-1 UCRL-52715-79-4 UCRL-52638	8ECY-80-132D BECY-80-169 BECY-80-182E SECY-80-202	8006240034 8006170127 8006180132* 8006200348*	50-320 P BECY 50-247 T 190FR	
NUREO/CR-1017 NUREO/CR-1021	8006200524 8006200532	NUREO NUREO	MLM-2691 PNL-3108	8ECY-80-214 8ECY-80-217 8ECY-80-235	8006300575 8006180117 8006120425	SECY SECY SECY	
NUREQ/CR-1077 NUREQ/CR-1078 NUREQ/CR-1080	8006270022 8006260421 8006270015	NUREO NUREO NUREO	PNL-3156 EGO-2003	8ECY-80-238 8ECY-80-2388	8006120360 8006120468	BECY BECY	
NUREQ/CR-1091 NUREQ/CR-1092 NUREQ/CR-1111 NUREQ/CR-1114	8006270031 8006300071 8006270045 8006260286	NUREO NUREO NUREO NUREO	ORNL/NUREO/TM-3 ORNL/NUREO/TM-3 ORNL/NUREO/TM-3 SAND79-2060	8ECY-80-247 8ECY-80-263 8ECY-80-271A 8ECY-80-275 TR-3887-1 ADD1	8006040250 8006160207 8006250030# 8006300379# 8006160008#	70-2523 BECY 10CFR 50-367 0 50-329 8	
NUREQ/CR-1120 NUREQ/CR-1120 V2 NUREQ/CR-1133 APP NUREQ/CR-1135	8004300034 8004170164 8004300032 8004120467	NUREO NUREO 40-665 NUREO	ANL/E8-81 DRNL-NUREO/TM-3	FSC-1 FTC-0123 KCID-18464 NCAP-7638	8006230260* 8006020225* 8006250052* 8006070376*	71-384 State Prog 50-282 P 50-280 G	16516
NUREG/CR-1138 NUREG/CR-1143	8006270019 8006270420	NUREO NUREO	PNL-3207	ACAP-9663	8004050032*	50-244 8	
NUREG/CR-1154 V1 NO2 NUREG/CR-1154 V1 NO2 NUREG/CR-1158 NUREG/CR-1206 NUREG/CR-1217	8006200608 8006270035 8006270044 8006300127 8006270038	NUREO NUREO NUREO NUREO NUREO	GEAP-21304-14 GEAP-21304-14 HEDL-TME 79-51	HCAP-9726 XN-301, 9C1 XN-52-01 XN-601, 825 O/M (N-NF-79-6(NP)	8006170360# 8006300627# 8006300623# 8006300628# 8006250105#	TOPREP 71-6581 71-6581 71-6581 TOPREP	NS-TMA-2261 16576 16576 16576
NUREG/CR-1229	8004240041	NUREC	NRNL/NUREO/NBIC	/AEC-1216 /AEC-1217	8004110029# 8004110008#	50-271 G 50-309 G	IEB-79-01B

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCERSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

71-5942

71-5942 71-5942 71-5942 71-5942

71-5942 ACRB ACRB ACRB

ACRE

ACRE

ACRS ACRS 40-8434 40-8434 40-8434

71-9046 71-9046 71-9046 71-9094

71-9094 71-9094 10CFR

50-437 ACRS

COMMISSION 71-9044 71-9044 71-9044 71-9044

71-9044 71-9044 71-9044 71-9044 71-9044

71-9044

71-9044 71-9044 State Prog 50-454 G

50-334

50-546 40-8693 50-460 50-546

Q

50-327 50-10 ACRB ACRB ACRB

0

ACCESSION NUMBER

7000000				ACCEBBIO	ROTIBER	
	PRINCIPAL	DATE	SUDJECT		501110101	
ENCLOSURE	DOCUMENT	188VED				ATE
ENCLUSIVE	MACONENI	199041	CATEGORY	ENCLOSURE		BUED
7902140223	8006180016	80/05/23	FOIA		********	
7911190247				8005210469		03/18
	7911190149	79/10/30	50-3 P	8005210472		03/18
8003100181	8003100176	80/03/05	10CFR	8005210475		03/10
8004010006	8004010004	90/02/29	50-295 P	B005210479		03/18
B004160190	8004160186	80/03/15	COMMISSION	8003210481	8005210456 80/	03/18
00011/0100						
B004160193	8004160186	80/03/12	COMMISSION	8005230082		04/21
B004160196	8004160186	80/03/12	COMMISSION	8005230116		04/22
8004160200	8004160186	80/03/12	COMMISSION	8005230253		04/25
8004140202	80041601B6	80/03/12	COMMISSION	8005230280		04/15
8004160203	#004160186	80/03/12	COMMISSION	8005230283	8005230276 80/	05/20
8004440004	8000110181	00 (00 (10	*****			
8004160206	8004160186	90/03/12	COMMISSION	8005230341		04/07
8004160209	8004160186	80/03/12	COMMISSION	8005230389		04/16
8004140212	8004160186	80/03/12	COMMISSION	8005230398		04/22
8004160215	8004160186	80/03/12	COMMISSION	8005230566		04/29
8004140220	8004160186	80/03/12	COMMISSION	8005270050	8005270043 80/	04/03
5501000010	500 405000N		*** ***			
8004220262	8004220225	80/02/21	71- 9 010	8005270059		04/10
6004220270	B004220225	80/02/21	71-9010	9005270236		04/24
B004220277	8004220225	60/02/21	71 -90 10	8005270296		01/17
8005070015	8005070013	80/03/24	71 -90 07	8005270304	8005270286 80/	01/17
8005070023	8005070 013	80/03/24	71-9007	8005270310	8005270286 80/	01/17
6005070029	8005070013	80/03/24	71~9007	8005270342		04/22
8005070032	8005070013	80/03/24	71-9007	8005270345		04/22
8005070268	8005070261	80/03/17	71 9 079	9005270348		04/22
8005070274	8005070261	80/03/17	71- 9 079	8005270351		04/22
8005070284	8005070261	80/03/17	71 9 07 9	8003270522	8005270516 80/	03/31

8005070294	0000070261	60/03/17	71~9079	8005270525		03/31
8005070303	0005070261	00/03/17	71-9079	8003270328		03/31
8005070316	0005070261	80/03/17	71 -9079	8005270581		04/23
8005070317	0005070261	80/03/17	71-9079	8005280079		04/17
8005070544	8005070560	80/03/17	71-9009	8005280090	8005280086 807	04/02
******		*****		200000000000000000000000000000000000000		
8005080537	0005000533	80/04/09	71-9015	B005280473		05/14
8005090045	0005090057	80/04/15	40-8027	8005290070		04/09
8005120005	8005120001	80/04/02	71-5450	8005290075		04/09
8005120006	8005120001	80/04/02	71-5450	8005290083		04/09
8005120009	6005120001	80/04/02	71-5450	8005290087	8005290066 80/	04/09
8005120014	8005120001	80/04/02	71-5450	8005290091	8005270066 60/	04/09
8005120019	8005120001	80/04/02	71-5450	8003290095		04/09
8005120182	9005120181	80/03/17	71-9086	8005290100		04/09
9005130514	8005130512	80/04/29	WARTE HOT	9005290105		04/09
8005130517	8005130512	80/04/28	HASTE HOT	7005290111	8005290066 80/	04/09
8005130522	#AA#14A#+*	00/04/00	LIASTE MAT	gaasana (t	BANESBANAL DA	na /no
	8005130512	90/04/29	HASTE MOT	9003290115		04/09
8005200512	8005200503	80/04/20	COMMISSION	8005290120		04/09
8005210177	6005210137	80/05/05	50-546 Y	8005290123		04/07
8000210187	8005210137	80/05/05	50-546 T	9006020009		05/14
8005210202	8005210137	90/05/05	50-546 T	8006020016	B006020013 B0/	04/26
500E910955	000501010	00 (00 (55	EA 842 -	607100000	BAAAAAAAAA	05/08
8005210208	8005210137	80/05/05	50-546 T	8006020021		05/05
8005210217	8008210137	80/05/05	50-546 T	9006020024		04/25
8005210460	8005210456	80/03/18	71-5942	8006020037		04/09
8005210461	8005210456	80/03/18	71-5942	8006020055		05/13
8005210465	8005210454	80/03/18	71-5942	8006020063	B006020059 B0/	04/26

ACCERSION					ACCESSION NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 16SUED	SUBJECT CATEODR	٧	PRINCIPAL DATE ENCLOSURE DOCUMENT 1884ÆD	BUBJECT CATEGOR	
8006020064 8006020073 8006020076 8006020077 8006020081	8006020062 8006020069 8006020072 8006020070	80/03/21 80/04/26 80/05/03 80/04/26 80/05/03	50-331 50-546 50-333 50-249 50-333	0	8006030090 8006030086 80/04/16 8006030101 8006030093 80/04/17 8006030109 8006030106 80/04/22 8006030110 8006030103 90/05/01 8006030120 800603011B 77/06/17	50-311 50-322 50-309 50-29 8ECY	9
8006020084 8006020085 8006020088 8006020089 8006020092	8004020080 8004020072 8004020072 8004020082	80/04/26 80/03/03 80/05/03 80/04/26 80/05/03	50-330 50-333 50-333 50-265 50-333	0 0 0 0	8006030146 8006030141 80/05/07 8006030161 8006030152 80/05/07 9006030162 8006030155 80/05/17 8006030163 8006030155 90/05/17 8006030164 8006030152 80/05/07	70-25 71-9094 GA999 GA999 71-9094	
8006020116 8006020135 8006020171 8006020180 8006020183	8006020110 8006020130 8006020169 8006020176 8006020178	80/05/29 80/04/30 80/05/27 80/05/28	50-358 50-298 50-275 50-219 50-327	0 0 A 0 P	## ## ## ## ## ## ## ## ## ## ## ## ##	9A999 9A999 50-309 50-271 50-312	0 H T
8009050510 8009050508 8009050502 8009050501 8009050145	8006020195 8006020195 8006020195 8006020195	80/04/23 80/05/23 80/05/23 80/05/07 80/05/23	50-254 50-287 50-287 GEN TEC 50-287	Q P P IS P	8006030224 8006030219 80/05/30 8006030225 8006030218 80/04/16 8006030229 8006030223 80/05/27 8006030232 8006030219 80/05/30 8006030243 8006030240 80/05/08	50-320 50-458 50-416 50-320 40-1162	0
8006020211 8006020225 8006020227 8006020237 8006020243	8006020203 8006020224 8006020221 8006020230 8006020230	80/05/21 80/05/21 80/05/27 80/05/23 80/05/23	50-213 State Pr 50-309 50-325 50-325	P R R P	BO06030262 BO060302856 BO060302856	90-334 50-334 50-334 50-334 90-331	0 0 0
8006020259 8006020266 8006020303 8006020318 8006020343	8006020253 8006020264 8006020295 8006020308 8006020341	80/04/11 80/04/11 80/05/27 80/05/27 80/05/28	50-397 50-220 50-320 50-333 50-297	G R S S	8006030301 8006030300 80/08/28 8006030304 8006030303 80/08/29 8006030313 8006030311 80/08/27 8006030322 8006030323 80/06/01 8006030327 8006030325 80/05/27	50-315 50-302 50-346 50-302 50-320	P 8 8 P
8006020349 8006020361 8006020362 8006020370 8006020377	8006020347 8006020355 8006020358 8006020367 8006020372	80/05/30 80/05/27 80/05/21 80/05/27 80/05/27	50-295 50-333 50-334 50-333 50-333	P 8 8	8004030328 8004030324 80/05/28 8004030332 8004030331 80/05/27 8004030333 8004030327 80/05/30 8004030347 8004030324 80/05/28 8004030348 8004030334 80/05/30	50-244 50-324 50-271 50-244 50-280	# 8 8 P 9
8006020382 8006020385 8006020387 8006020392 8006020396	8006020380 8006020379 8006020383 8006020386 8006020391	80/05/20 80/05/23 80/05/27 80/05/22 80/05/27	50-387 50-171 50-333 50-336 50-333	0 8 8	9006030349 8006030340 80/05/27 8006030356 8006030336 80/05/30 8006030349 8006030338 80/05/28 8006030374 8006030374 80/05/27 8006030377 8006030372 90/05/23	\$0-237 \$0-280 \$0-309 \$0-324 \$0-346	8 8 8 9
8006020417 8006020440 8006020443 8006020445 8006020526	8004020412 8006020435 8006020435 8006020435 8004020517	80/05/27 80/05/16 80/05/16 80/05/16 78/01/25	50-333 50-281 50-281 50-281 CONTRACT	8 P P	8006030379 8006030364 80705/27 8006030387 8006030361 80705/20 8006030399 8006030392 80703/27 8006030399 8006030395 80705/30 8006030400 8006030374 80705/20	50-237 50-31 <i>2</i> 50-328 50-324 50-237	8 8 8
8006020530 8006020534 8006020554 8006020557 8006020559	8004020523 8004020527 8004020547 8004020551 8004020547	78/03/09 80/05/15 80/05/23 80/05/20 80/05/23	SECY 50-128 50-206 70-27 50-206	Q P P	8004030408 8004030397 80705/27 8004030415 8004030406 80705/28 8004030432 8004030413 80705/22 8004030434 8004030430 80705/29 8004030436 8004030430 80705/28	50-327 50-334 50-321 50-206 50-206	9 8 8 8
8006020556 8006020575 8006020579 8006020585 8006020614	8004020547 8006020573 8006020574 8006020582 8006020594	80/05/23 80/04/14 80/05/05 80/05/20 80/05/14	50-206 50-324 71-388 71-9096 MISC	P G	8006030441 8006030299 80/05/27 8006030445 8006030435 80/05/23 8006030447 8006030427 90/05/28 8006030449 8006030443 80/05/21 8006030450 8006030444 80/05/23	50-331 50-366 80-327 50-335 50-219	8 8 8
8006030005 8006030007 8006030012 8006030014 8006030022	E000603009 6000603009 6000603009 6100603009	80/05/30 80/05/30 80/05/22 80/05/22 80/04/18	50-416 50-416 50-219 50-219 71-9050	K P P	8004030452 8004030442 80/05/29 8004030456 8004030451 80/05/21 8004030460 8004030453 80/05/28 8004030462 8004030458 80/05/22 8004030443 8004030457 80/05/29	50-257 50-251 50-327 50-321 50-327	8 8 9 8
8004030025 8004030029 8004030031 8004030035 8004030037	8006030019 8006030026 8006030019 8006030033	80/04/18 80/04/16 80/04/18 80/05/20 80/04/21	71-9050 70-371 71-9050 71-9094 71-9045		8004030472 8004030445 80/05/28 8004030473 8004030447 80/05/27 8004030475 8004030470 80/05/27 8004030474 8004030474 80/05/30 8004030490 8004030480 80/05/27	50-320 50-331 50-324 50-336 50-327	명 명 P 명
8006030040 8006030041 8006030042 8006030043 8006030044	8006030036 8006030037 8006030036 8006030034	80/05/29 80/04/21 79/11/01 80/05/29 80/04/21	50-293 71-9045 CONTRACT 50-293 71-9045	F	8006030500 8006030493 80/05/29 8006030506 8006030497 80/05/29 8006030508 8006030505 90/05/29 8006030511 8006030513 80/04/22 8006030517 8006030513 80/05/29	50-302 50-295 50-302 50-518 50-206	8 8 9 0
8006030047 8006030048 8006030049 8006030053 8006030063	8006030036 8006030034 8006030046 8006030052 8006030059	80/05/29 80/04/21 80/05/12 80/05/16 80/05/14	50-293 71-9045 CONTRACT CONTRACT XPORTLIC	F	8006030518 8006030510 80705/30 8006030534 8006030519 80704/18 8006030559 8006030552 80705/09 8006030572 8006030552 80705/09 8006030585 8006030581 80704/21	50-213 50-298 50-344 50-344 50-424	8000
8004030048 8004030079 8004030073 8004030083 8004030085	8006030066 8006030062 8006030066 8006030081 8006030078	80/05/14 80/05/30 80/05/14 80/05/21 80/04/21	50~364 50~10 50~364 50~346 50~302	0 0 0	8004030593 8004030592 90/04/21 8004030404 8004030402 80/05/21 8004030404 8004030402 80/05/21 8004030408 8004030402 80/05/21 8004030412 8004030410 80/04/22	50-390 50-553 50-553 50-553 50-277	@ @ @ @

ACCESSION	NUMBER			ACCEBSION NUMBER	
ENCLOSURE	PRINCIPAL	DATE	NUBJECT	PRINCIPAL DATE	SUBJECT
	DOCUMENT	1980ED	CATEGORY	ENCLOSURE DOCUMENT ISSUED	CATEGORY
8004040004	8006030596	80/04/07	NUREQ		50-445 Q
8004040005	8006040001	80/05/14	QA797		50-445 Q
8004040005	8006040001	80/05/14	QA797		50-273 Q
8004040008	8006040001	80/05/14	QA797		40-8502
8004040010	8006040001	80/05/14	QA797		40-8502
8006040021 8006040025 8006040027 8006040031 8006040032	8006040013 8006040013 8006040026 8006040026 B006040030	80/05/19 80/05/19 80/05/16 80/05/16 80/05/13	50-250 G 50-250 G 50-409 G 50-409 G 71-9001	8006050308 8006050304 80705727 8006050312 8006050306 80706702 8006050315 8006050306 80706702	50-338 P 50-338 8 50-314 8 50-316 8 50-344 P
9006040033 9006040035 9006040037 9006040039 9006040056	800&040026 800&040030 800&040030 800&040030 800&040034	80/05/16 80/05/13 80/05/13 80/05/13	50-409 0 71-9001 71-9001 71-9001 71-135	8006050339 8006050327 80705730 8006050332 8006050328 80705730 8006050333 8006050329 80705730	50-344 P 50-337 P 50-261 9 50-339 P 50-366 8
800&040059	B006040055	90/04/19	90-245 G		50-337 P
800&0400&7	B006040064	90/04/22	71-9051		50-339 P
800&040070	B006040064	90/04/22	71-9051		50-346 B
800&040072	B006040064	90/04/22	71-9051		50-339 P
800&040075	B006040064	90/04/22	71-9051		50-269 B
8006040082	800&040077	80/04/14	27-47	8004050345 8004050337 80/04/01	50-413 8
8006040092	800&040089	80/05/09	70-824	8004050349 8004050347 80/05/29	50-321 8
8006040095	800&040088	80/05/05	71-9853	8004050353 8004050350 80/05/30	50-348 P
8006040099	800&040088	80/05/05	71-9853	8004050355 8004050348 90/05/28	50-366 8
8006040102	800&040088	80/05/05	71-9853	8004050346 8004050340 80/05/27	50-366 8
8006040105 8006040107 8006040109 8006040112 8006040117	800&040088 800&040088 800&040088 800&040111 800&040113	80/05/05 80/05/05 80/05/05 80/06/02 80/05/15	71-9853 71-9853 71-9853 50-320 Q	8006050371 8006050364 80705/30 8006050372 8006050365 80705/29 8006050373 8006050367 80705/20 8006050378 8006050375 80706/02 8006050383 8006050377 80706/03	50-272 B 50-366 B 50-321 B 50-263 B 50-277 P
800&040118	8006040113	80/03/15	50-320 P	B006050386 B006050377 B006050377 B006050403 B006050410 B0060503979 B006050407 B006050407 B006050407 B006050407 B006050407 B006050415 B006050415 B006050423 B006050423 B006050423 B006050423 B006050423 B006050425 B006050423 B006050425 B006050423 B006050425 B006050425	50-277 P
800&040117	8006040113	80/05/18	50-320 P		70-27
800&040125	8006040122	80/06/02	50-289 9		50-351 Q
800&040160	8006040138	80/03/16	8tate Prog		50-353 G
800&040167	8006040166	80/03/06	50-382 0		50-387 G
8004040191	8004040182	80/05/17	50-443 G	BO0A030429 B00A030426 B0/05/14 B00A030432 B00A030426 B0/05/14 B00A030434 B00A030431 B0/04/25 B00A030436 B00A030426 B0/05/14 B00A030437 B00A030426 B0/05/14 B00A030437 B00A030433 B0/05/20	50-244 Q
8004040196	8004040174	80/04/23	50-275 G		50-244 Q
8004040208	8004040203	80/05/27	50-249 8		50-364 Q
8004040221	8004040217	80/05/20	50-269 F		50-244 Q
8004040233	8004040230	80/05/29	50-518 8		71-9079
8006040249	8004040232	80/05/19	50-566 0	8004050439 8004050433 80/05/20	71-9079
8006040282	8004040250	80/05/13	70-2523	8004050444 8004050432 80/05/14	50-244 Q
8006040284	8006040250	80/05/13	86CY	8004050441 8004050433 80/05/20	71-9079
8006040236	9006040232	80/05/19	50-566 0	8004050448 8004050444 80/05/16	40-8502
8006040298	8004040250	80/05/13	86CY	8004050449 8004030443 80/05/15	50-546 Q
8006040262	8004040250	80/08/13	70-2523		PR
8006040264	8004040250	80/05/13	8ECY		50-206 O
8006040270	8004040045	80/04/08	70-135		50-333 O
8006040302	8004040276	80/05/29	50-269		Btate Prog
8006040303	8004040300	80/05/30	80-155		50-333 O
8006040308 8006040310 8006040313 8006040315 8006040316	8006040306 8006040307 8006040311 8006040311	80/03/29 80/03/13 80/03/29 80/03/29 80/03/29	50-328 6 50-324 6 50-255 F 50-255 F 50-255 F		50-483 Q 70-1143 70-1143 50-245 Q 50-482 Q
8004040318 8004040320 8004040323 8004040325 8004040330	0004040311 8004040311 8004040311 8004040311	80/05/29 80/05/29 80/05/29 80/05/29 80/05/29	50-255 F 50-255 F 50-255 F 50-255 F	8004050528 8004050523 80/04/11 8004050529 8004050524 80/05/22 8004050533 8004050535 80/05/14 8004050541 8004050555 80/05/09 8004050454 8004050455 80/05/08	50-482 Q CONTRACT 50-255 Q 50-445 H 70-442
8006040339 8006040352 8006030004 8006030013 8006030023	8004040335 8004040347 8004050002 8004050009 8004050019	80/05/28 80/04/02 80/05/27 80/05/28 80/05/27	50-325 6 50-318 8 50-566 8 50-325 8 50-395 6	9004090645 800608065055 80708708 90040400005 80040409002 80708701 8004040008 8004040002 80708701	70-442 70-442 71-4986 71-4986 40-8348
9004080031 8004080032 8004080035 8004080036 8004080041	8006050026 8006050028 8006050023 8006050036	80/05/29 80/05/28 80/05/30 80/05/28 80/05/28	50-327 8 50-244 50-317 8 50-348 8 50-320 8	8004040012 8004040004 80/01/31 80040400014 8004040002 80/05/01 8004040020 8004040002 80/05/01 8004040022 8004040002 80/05/01	71-4986 40-8348 71-4986 71-4986 71-4986
9006050043 8006050045 8006050047 8006050078 8006050082	8006050033 8006050039 8006050042 8006050053 8006050053	90/05/28 90/06/02 90/05/28 90/04/30 90/04/30	50-348 50-318 50-375 70-33 70-33	8004040025 80040400002 80/05/01 8004040030 80040400027 80/05/09 8004040032 8004040027 80/05/09 8004040034 8004040027 80/05/09	71-4986 71-4986 50-309 Q 50-309 Q
8004050084	8006050053	90/04/30	70-33	8004040041 8004040039 80/04/18	50-309 Q
8004050088	8006050053	90/04/30	70-33		50-445 M
8004050103	8006050075	90/04/11	50-566		50-277 Q
8004050113	8006050110	90/05/21	50-445		70-687
8004050115	8006050110	90/05/21	50-445		50-277 Q

ACCEBBIO						ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUBJEC*		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1880ED	SUBJECT CATEGOR	
8006060044	8006060037	90/05/12	50-277	G.	9006060405	8006060400	80/05/20	50-287	
8006060047 8006060055	8006060037 8006060049	80/05/12 80/05/06	50-277 50-387	Q A	8006060408 8006060407 8006060410	9006060400 9006060404	80/05/20 80/05/30 80/05/30	50-287 50-287 50-338	9 8 8
8004040057 8004040044	8004040053 8004040049	80/05/22 80/05/06	50-267 50-387	Q A	B0040413	9006060407 9006060401	80/06/02	50-518	8
8004040074 8004040077	8006060067 8006060060	80/05/12 80/05/20	71-9001 CONTRACT	г	8006060415 8006060416	11404040411	80/05/30 90/06/02	50-344 50-327	8
8006060078 8006060084	8005050067 8005050082	80/05/12 80/05/07	71-9001 50-275	Œ	8006060424 8006060425	8006060419 8006060421	80/05/30 80/05/22	50-219 71-9853	8
8006060093	8004040089	80/04/23	40-8697		EE+0404008	8006060429	80/05/21	71-9132	
8006060094 8006060101	8004040088 8004040097	90/05/21 90/04/19	40-4337 50-293	Q.	9005050437 9005060442 9005060445	8006060429 8006060438 8006060438	80/05/21 80/05/07 80/05/07	71-9132 71-5607 71-5607	
8004040102 8004040107 8004040109	8700404008 8700404008 6010404008	90/05/09 90/05/09 90/04/17	50-327 50-327 50-272	P G	9006060452 9006060457	8006060449 8006060449	80/05/23 80/05/23	50-70 50-70	P
8004040112	8006060098	80/05/08	50-327	P	800&0&0489	B004060455	80/05/07	70-398	
8006060121	8004040118 8004040125	80/04/25 80/04/25	50-192 50-285	œ œ	B006060462 B006060464	0006060449 0006060455	80/05/23 80/05/07	50-70 70-3 98	P
9004040131 9004060140	8210404008 4E10404008	80/04/16 80/04/28	50-492 WASTE MO	G T	80060448 8006040471	8006060455 8006060449	90/05/07 90/05/23	70~398 50~70	ρ
8006060141 8006060147	B006060134 B006060136	80/04/28 80/04/28	50-460 WASTE MG	, G	BÓ06060472 BO06060473	8006060455 8006060449	80/03/07 80/03/23	70-3 70 50-70	P
8004040152 8004040140	8006060146 8006060158	80/04/23 80/02/01	50-269 70-371	œ	B006060476 B006060481	B006060449 B006060449	80/05/23 80/05/23	50-70 50-70	P
8006060163	9006060156	80/05/16	50-219	8	B0060604B3	8006060449	80/05/23	50-70	P
8004040170 8004060172	8006060164 8006060168	80/05/12 80/05/08	30-424 71-6400	8	8006060497 8006060498	B006060484 B006060491	80/05/30 80/05/21	50-390 CONTRACT	8
8006060173 8006060178	8006060168 8006060169	80/05/08 80/04/02	71-6400 50-445	G	8006060476 8006060499	8006060474 8006060474	80/04/08 80/04/08	40-8727 40-8727	
8006060179	BA10A0A0QB BA10A0A0QB	80/05/0B 80/05/0B	71-6400		B006060501 B006060506	8006060494	80/04/09 80/05/08	40-8727 50-29	a
8006060183 8006060186	841040400B 841040400B	90/05/08 90/05/08	71-6400 71-6400		8004040307 8004040313	8006060504 8006060504	80/03/15 80/05/15	50-275 50-275	H
8006060187 8006060190	841040400B	90/05/08 90/05/08	71-6400 71-6400		9006060516 9006060519	8004040504 8004040504	80/05/15 80/05/15	50-275 50-275	H
8006060191 8006060194	8&10&0&00B	80/05/09	71-6400	a	8006060522 8006060528	8006060504 8006060504	80/05/15	50-275	H
8006060200 8006060204	8006060184 8006060184 8006060164	80/05/14 80/05/14 80/05/12	50-412 50-412 50-424	9 8	8006060830 8006060831	8006060504 8006060525	80/05/18 80/05/15 80/05/08	50-275 50-275 50-348	H
8006060213	8006060208	80/05/12	9A777		8006060334	8004040525	80/05/0B	50-346	ā
8006060222 8006060226	8006060216 8006060223	80/05/13 80/05/12	94999 50-329	a	9006060537 9006060539	8006060504 8006060533	B0/05/15 B0/05/19	50-275 50-344	H
8004040227 8004040229	8006060216 8006060216	80/05/13 80/05/13	0A999 0A999		8006060542 8006060544	8004040525 8004040533	80/05/08 80/05/19	50-349 50-344	Q Q
8006060234	8006060216	80/05/13	94999		9004040550 9004040542	8004040525	80/03/09	50-348	a
8006060237 8006060240 8006060242	9006060216 9006060216 9006060236	BO/05/13 BO/05/13 BO/05/05	QA999 QA99 9 50~295		B004040364 B004040364 B004040364	8004040552 8004040541 80040405341	80/05/27 80/04/17 80/04/17	50-320 50-302	ā.
8006060243 8006060246	9006060236 B006060236	80/05/05 80/05/05	50-275 50-295	0	B006060568 8006060571	8006060561 8006060559	80/04/17 80/03/07	50-302 50-302 50-142	0
8004040257	8009090822	90/04/21	50-445	٥	8006060573	9004040847	90/05/16	50-206	P
8006060261 8006060271	BO04040255	80/04/21 80/05/30	50-445 50-320	8	8006060576 8006060578	8006060567 8006060559	80/05/16 80/03/07	50-206 50-142	P
8006060281 8006060282	9006060269 9006060276	90/05/19 90/05/23	50-269 71-9079	0	80303000 0760303000	9006060561 9006060589	80/05/01 80/05/16	50-280 50-333	g g
8006060 28 5	8004040275 8004040269	80/05/29 80/05/19	50-336 50-269	9	8004040574 8004040401	8006060592 8006060374	80/05/23 79/11/20	50-546 CONTRACT	A
8006060298	B006060290 B006060290	80/05/30 80/05/30	50-390 50-390	8	20000000000000000000000000000000000000	8006060600 8006060605	79/12/13 80/05/23	50-312 71-9007	œ
8004040307	8006060297	80/05/22	20-204	s	9006060616	8004060412	80/05/22	71-5939	
8004040315	8004040310 8004040310	80/05/29 80/05/29	50-335 50-335	P P	80060 9 0006 80060 9 0018	80040 7 0003 80040 7 0012	80/05/28 80/05/22	50-486 50-488	0
8004040321 8004040323	8006060310 8006060309	80/05/27	50-335 50-296	P 8	8006090016 8006090021	8006090011 8006090017	80/05/12 80/05/14	50-245 50-498	ā ā
8009090359	8006060310	80/05/27	50-335	P	8006090024	8004070022	80/05/27	71~300	
8006060329 8006060333 8006060340	8006060310 8006060325 8006060337	80/05/29 80/04/24	50-335 50-373	9	8006090046 8006090047	8006090041 8006090044	80/05/05 80/05/21	70-25 50-456	a
8006060340 8006060350	9006060337 9006060343 9006060349	80/05/21 80/06/04 80/05/20	50-361 50-375 50-344	8 F 8	9006090054 9006090055 8006090056	8006090050 8006090049 8006090052	80/04/30 80/05/30 80/04/35	70-754 50-599 50-546	٥
100000000000000000000000000000000000000	8006060349	80/05/16	50-320	P	8006090062	8006070052	80/04/25 80/05/14	50-352	8
8004040355 04£0404008	9005050354 9005050357	60/06/02 80/05/29	50-302 50-361	P	8004090072 8004090073	8006090069 8006090071	80/05/13 80/05/23	50-272 50-546	ě
8006060374 8006060381	9006060365 9006060379	80/05/30 80/05/30	50-334 50-334	Ë R	80040 9 0074 90040 9 0074	8004090066 8004090065	90/05/02 90/05/30	50-280 50-466	G O
8006060385	8006060365	80/06/02	50-334	8	8006090081	8006090078	80/05/01	50-201	Q.
8006060391 8006060398	8006060383 8006060390	80/05/30 80/06/02	50-438 50-334	8 R	280090308 380090308 380090308	8004090045 8004090078	80/05/30 80/05/01	50~466 50-201	9
8006060403	8006060396 8006060394	80/05/02 80/05/29	50-263 50-327	R	8006090088 8006090095	8004090082 8004090091	80/05/02 80/05/05	50-336 50-320	P

ACCESSION					ACCEBS10N			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8006090097	9004090090	00/04/23		- 0	B006090441	8005090406	80/05/30	50-460 Q
8006090102 8006090103	8006070100 8006070074	80/05/07 80/05/07	50-320 GA999	P	8006090444 8006090445	8005090406 8005090430	80/05/30 80/05/13	50-460 G State Prog
8006090104 8006090109	8004070098 8004070094	80/05/21 80/05/07		A	9006090447 9006090459	8005090405 8005090452	80/05/30 77/05/01	50-460 G CONTRACT
E110904008	8004090110	80/04/29	CO##18810	N .	9006090461	8006090453	80/05/05	50-263 Q
8006070115 8006070118	8006070074 8006070078	90/05/07 90/05/21	QA999	· · · · · · · · · · · · · · · · · · ·	8004090446	8006090462 8006090470	80/05/23 80/05/01	50-206 0 50-250 Q
8006090122	8006090094	B0/05/07 B0/05/08	GA799	0	8006090473 8006090474	8006090469	80/05/04	50-423 S 50-438 S
8006090144	9006090142 9006090142	80/05/08 80/05/08		0 0	8006090476	8004090471 8004090479	80/05/21	50-83 G
8004090147 8004090148	8006070138	80/05/07	QA999	•	8006090485 8006090491	8006090479	80/05/21	50-83 Q
8006090153 8006090156	8006070138 8006070142	80/05/07 80/05/08		q	8004070474 8004070503	8006090479 8006090495	80/05/21 80/04/24	50-83 G 50-312 G
9004090157	8006090155	80/04/29		Q	8006090505	8005070479	80/05/21	50-83 Q
9004090160 9004090163	8004070155 8004070138	B0/04/29 B0/05/07	QA999	a	8006090513 8006090515	800A07050B 800A070507	80/05/05 80/05/22	50-73 Q 50-294 Q
8006090167 8006090170	8006070138 8006070135	80/05/07 80/04/29	9A999 50-320	Q.	8004090519 8004090521	8004090514 8004090514	80/04/28 80/04/28	50~327 0 50~327 0
9006090173	8004070138	80/05/07	GA999		8004070527	8006090525	80/05/19	50-338 P
8006090177 8006090189	8006090174 8006090183	80/05/27 80/05/22	71-135 50-462	a	8004090534 8004090535	8006090525 8006090528	80/05/17 80/05/21	50-33B P 50-321 G
8006090196	8006090191	80/04/18	50-213	ā G	8004090537	8006090525	80/05/19	50~33B P
8006090202 8006090213	8006090182 8006090210	80/05/21 80/06/06	50-400 50-407	•	8006070540 8006070542	8004070528 8004070528	80/05/21 80/05/21	50-321 G 50-321 G
8006090219	8004090210	80/06/06	50-409	0	8004090544	8006090541	80/05/27	50-361 T 50-321 G
8004040558 8004040553	8004090210 8004090210	80/06/06 80/06/06	50-409 50-409	•	8006090547 8006090561	8006090528 8006090560	80/05/21 80/05/21	50~369 G
8006090229 8006090234	8004090225 8004090225	80/04/30 80/04/30	50-498 50-498	a a	9006090565 9006090584	8004090540 8004090580	80/05/21 80/05/14	50-367 G 50-445 G
8004090235	8004040510	80/06/06	50~409	•	9004090834	8004070832	80/05/23	90-301 8
8004090244 8004090253	B004090244 B004090252	80/04/05 80/04/05	70-41308 50-338	R	8006110002 8006110007	8006110001 8006110005	80/05/29 80/06/06	50-313 R 50-338 F
8006090297 800609030 7	B004090263 B004090306	80/05/09 80/05/30	50-367 50-327	G K	8004110009 8004110010	6004110003 8004110004	80/06/05	50-307 G 50-333 S
8006090312	B00409030B	80/05/30	50-329	K	8006110013	8004110009	79/10/17	50-204 P
8006090323 8006090329	8004090322 8004090325	80/06/02 80/05/30	50-278 50-325	R P	8006110015 8006110019	8004110012 8004110014	80/05/31 80/06/06	50-285 8 50-361 9
8006090333 8006090336	8004070327 8004070330	80/06/02	50-321 50-327	8 8	6006110021 6006110022	8006110016 8006110017	80/06/06 80/06/05	50-333 8 50-348 P
8006090337	B004090334	80/06/02	50-438	6	8006110024	8004110014	80/06/06	50-361 Q
8004070342 8004070346	8006090340	80/06/05 80/06/02	50-251 50-331	Q 8	8006110027 8006110028	8004110017 8004110014	80/06/05 80/06/06	50-348 P 50-361 0
6006090347	B006090343	80/06/02	50-413	9	8006110029	8006110016	80/06/02	50-271 0
8006090348	0004070344	80/06/03	30-317	9	8006110030	9006110026	60/05/05	50-285 B
8006090355 8006090357	8006090349 8006090353	80/06/03 80/06/03	50-324 50-30 7	8 6	8006110031 8006110033	9004110014 9004110025	60/05/26 60/05/26	50-250 B
8006090361 8006090362	8006090359 8006090360	90/04/04 80/04/03	50~336 50~220	8	8006110035 8006110039	8004110014 8004110014	80/06/0 <u>6</u> 80/06/06	50-361 0 50-361 0
8004090343	8006090356	80/06/06	50-254	P	8006110041	8006110014	80/06/06	50-361 Q
8006090368 8006090376	8004090345 8004090370	80/06/03 80/06/03	50-317 50-220	6 9	8005110042 8005110043	8004110037 8004110034	80/05/26 80/06/03	50-335 B 50-390 B
080000000 180000000	8006090371 8006090375	80/06/02 80/05/27	50-331 50-267	ä R	8006110046 8006110047	8006110014	90/06/04 80/06/06	50-361 Q 50-361 Q
8006070382	8004090373	60/06/05	50-334	8	8006110052	8006110014	80/06/06	50-361 0
8004090384 8004090389	8006090379 8006090373	80/05/30 80/06/02	50-344 50-334	8 8	8006110055 8006110058	8006110014 8006110048	80/06/06 80/06/04	50-341 0 50-518 B
8006090391	8004070385	80/04/02	50-293	8	6004110059	8006110014	80/06/06	50-341 O
8006090393 8006090394	8604090390 8604090386	80/04/02	50~250 50~368	B	8006110072 8006110077	8006110069 8006110069	90/06/06 90/06/06	50~155 R 50~333 B
8004090394	8006090388	80/06/03	50-280	<u>q</u>	8006110079	8006110074	80/04/03	50-438 B
8006090397 8006090398	8004090390 8006090392	80/06/05 80/06/03	50-250 50-325	P 8	8006110084 8006110085	8004110078 8004110080	80/05/30 80/06/06	50-254 R 50-302 P
8006090404 8006090409	B006090402 B006090402	80/05/30 80/05/30	50-460 50-460	Q Q	8006110095 8006110096	8004110092 8004110091	80/06/06 80/06/08	50-324 R 50-287 B
8004070410	8004090407	80/05/20	71-9141		8006110099	8006110093	80/06/05	50-250 P
8006090412 8006090413	8006090402 8006090407	90/05/30 90/05/20	50-460 71-9141	Q	8005110102 8005110105	8006110100 8006110101	80/05/12 80/06/05	50-10 R 50-269 B
8006090414 8006090415	8006090406 8006090408	80/05/30 80/05/23	50-460 50-321	q q	8006110107 8006110112	800611007B	80/06/06	50-361 Q 50-334 8
8006090418	B006090402	60/05/30	50-460	- 0	8006110115	1110116008	80/05/27	50-304 8
8006070421 8006070422	B006090416 B006090408	80/05/23 80/05/23	71-5364 50-321	- Q	9006110117 9006110124	8004110110 8004110104	80/06/04 80/06/06	50-289 0 50-296 B
6006090427	8006090408	80/05/23	50-321	0	8006110125	8004110120	80/06/03	50-304 B
8006090432	8006090429	80/05/28	CONTRACT	Δ	8004110124	8006110121	80/06/04	50-334 B 50-255 B
8006090435 8006090436	8006090408 8006090429	90/05/23 90/05/29	50-321 CONTRACT	Q	8006110132 8006110134	8006110130 8006110123	80/05/04 80/05/30	50-302 B
8006090437 8006090438	8006090429 8006090428	80/05/28 80/05/23	CONTRACT 50-416	Q	8006110136 8006110137	B006110133 B006110135	80/06/03 80/05/27	50~255 R 50~397 K
8006090439	8005090434	80/05/23	TOPREP		8005110140	8004110128	80/05/06	50-302 8

ACCESSIO	N NUMBER				ACCESSIO			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEOD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUBJECT CATEGORY
B006110148	6006110145	80/06/04	30-320		8006120114	B006120110	80/05/14	50-320 U
8006110151 8006110152	8006110141 8006110146	80/05/23 80/06/04	50-254 50-367	R	8006120115 8006120117 8006120122	8006120111	80/05/12 80/05/14	XPORTLIC 50-320 U
8006110154 8006110156	8006110142 8006110143	80/05/12 80/06/04	50-313 50-260	R	ES102120122	8006120120	80/05/21 80/05/09	90-286 g
8006110157 8006110158	8006110153 8006110144	80/06/04 80/06/04	50-255 50-269	P P	8006120127 8006120132	8006120126 8006120119	90/05/21 90/05/29	50-358 H 50-286 G
8006110161 8006110166	8006110147 8006110150	80/05/02 80/05/30	50-266 50-416	8 6	8006120134 8006120137	8006120128	80/05/08 80/05/21	50-370 G 50-450 H
8004110176	8006110171	80/05/06	20-550	R	8006120138	8006120119	80/05/09	50-286 Q
8006110178 8006110179	8006110150 8006110167	80/05/30 80/04/05	50~416 50~320	8 P	8006120139 8006120140	8006120128 8006120119	80/05/08 80/05/09	50-370 G 50-286 G
8006110187 8006110188	8006110177 8006110181	80/04/05 80/04/03	50-29 50-333	P	8006120145 8006120146	8006120129 8006120141	80/03/08 80/03/28	50-370 Q 50-546 H
8006110193	8004110173	80/04/05	50-327	8	B006120147	8006120119	80/05/09	50-286 G
8006110174 8006110178	8004110191 8004110184	80/06/03 80/06/05	50-334 50-325	g	9006120148 9006120150	8006120128 8006120141	80/05/08 80/05/28	50-370 Q 50-546 Н
8005110199 8005110200	8006110192 8006110189	80/04/02 80/04/04	50-416 50-309	8	8006120181 8006120188	8006120128 8006120157	80/05/08 80/05/27	50-370 Q MISC
8004110202	8006110192	80/04/05	50-416	A	8006120160	8006120136	80/05/22	NURED
6006110203 6006110208	8006110192 8006110192	80/04/02	50-416 50-416	A	8006120161 8006120173	8004120157 8004120143	80/05/27 80/05/12	MISC 40-8502
8006110211 8006110215	8006110192 8006110192	80/04/02	50-416 50-416	A	8006120190 8006120207	8006120181 8006120201	80/03/14 80/03/02	50-272 G COMMISSION
8006110220	8006110192	80/06/02	50-416	٨	8006120210	8004120203	90/06/06	50-311 P
8006110223 8006110227	8006110219 8006110192	80/06/04	50-327 50-416	8 A	8006120214 8006120219 8006120227	8006120203 8006120213	80/06/06 80/08/02	50-311 P COMMISSION
8006110229 8006110229	8006110210 8006110222	80/06/06 80/06/09	50-275 50-387	Ą	8006120227 8006120231 8006120232	8006120223 8006120223	90/04/19 90/04/19	50-445 G 50-445 G FR
8006110230	8004110192	80/06/02	50-416	A	8006120234	9006120221 9006120226	80/04/08 80/05/27	71-230
8006110256 8006110257	8006110248 8006110252	80/06/04 80/06/05	50-336 50-339	8	8006120245 8006120246	8006120240 8006120221	80/03/22 80/04/08	50-445 G
80051 10262 80051 10265	8006110259 8006110206	80/06/06 80/06/04	50-327 50-261	K B	8004120258 8004120256	9006120252 5006120264	80/04/23 80/05/02	PR XPDRTLIC COMMISSION
8006110276 8006110277	8005110270 8005110273	80/06/04	50-327 50-344	B	8006120274	9006120267	80/04/25	40-3453
8005110280 8005110281	8006110273 8006110269 8006110272	B0/06/05 B0/06/06	50-259 TOPREP	8	8006120283 9006120289	8006120277 8006120284	80/06/05 80/04/11	50-313 B
9006110282 8006110284	8006110266 8006110274	60/04/10 60/05/27	50-445 50-566	H B	8006120290 9006120297	8006120286 8006120294	80/04/04 80/04/04	50-206 8 90-219 8
8005110285	8004110243	80/05/15	50-438	8	9006120303	8006120300	80/06/04	50-316 8
8006110291	8006110289 8006110287	B0/06/02 B0/06/04	50-364 50-259	P	8006120304 8006120313	8004120301 8004120309	80/06/09 80/06/04	50-338 R 50-518 B
8006110294 8006110296	8006110283 8006110272	80/06/06 80/06/06	50-327 TOPREP	8	9006120316 81006120318	8006120315 8006120317	80/04/09 80/04/10	50-368 P 50-289 F
8006110298	8006110293	80/05/22	70-1300		9006120320	8004120317	80/05/10	50-299 F
8006110312 8006110316	B006110304 B006110309	90/05/27 90/06/02	50-254 50-392	S	9006120321 9006120322	8006120317 #006120317	80/06/10 80/06/10	50-299 F 50-299 F
8004110322 8004110325	8006110314 8006110309	B0/05/30 B0/05/02	50-499 50-382	8	8006120323 8006120324	8006120319 8006120317	80/06/05 80/06/10	50-260 8 50-267 F
8006110326	8004110321	80/06/05	50-270	8	8004120324	9006120317	80/06/10	50-209 F
8006110330 8006110332	8006110320 8006110329	80/05/27 80/06/06	50-352 50-255	6 8	8006120327 8006120328	8006120317 8006120319	B0/06/10 B0/06/05	50-289 F 50-280 B
8004110333 8004110341	8006110328 8006110336	80/06/03	50-436 50-312	B T	9006120327 8006120333	8006120317 8006120331	90/06/10 90/06/09	50-297 F 50-338 B
9006110350	8006110336	80/06/09	50-312	Ţ	6004120334	8006120332	90/06/11	50-275 G 50-281 B
8006110358 8006110369	9006110347 9006110363	80/05/03 80/05/27	50-261 50-265	8	8006120337 8006120341	8006120336 8006120336	80/06/06 80/06/06	50-281 6
8006110376 8006110378	8006110356 8006110356	80/06/05 80/06/05	50-367 50-367	9	8006120344 8006120347	8006120343 8006120345	80/04/04 80/04/04	50-346 8 50-346 8
8006110380 8006110382	8006110370 8006110356	80/06/04 80/06/05	50-289 50-367	0	8006120352 8006120357	9006120350 8006120354	80/04/07 80/04/03	50-346 B 50-346 B
8006110444 8006110458	8006110436 8006110455	80/05/22 80/05/28	50-262 50-361	g T	8004120361 8004120342	8006120360 8006120359	80/05/07 80/06/09	SECY 50-336 S
8006120019	8000120008	80/03/22	PR	•	8006120365	9006120360	80/05/07	BECY
8006120023 8006120026	8006120017 8006120017	80/05/27 80/05/27	50-285 50-285	P P	9006120370 9006120377	B006120367 B006120374	80/06/06 80/06/05	50-369 A 50-320 P
8006120028 8006120037	8006120017 8006120033	80/05/27 80/05/22	50-265 50-438	ė a	800±120393 800±120394	8006120389 8006120390	90/06/10 90/05/09	50-409 © TOPREP
8006120037	8006120033	80/05/22	50-438	ā	8006120415	8004120413	80/03/31	CONTRACT
8006120041 8006120043	8004120033 8004120033	80/05/22 80/05/22	50-438 50-438	g g	8006120424 8006120430	8006120420 8006120425	80/05/14 80/05/07	XPORTLIC BECY
8004120053 8004120071	9006120047 9006120065	80/05/17 80/05/14	40-8745 COMMISSI	אכ	8006120431 8006120441	8006120427 8006120436	80/05/15 80/02/14	10CFR PRH
8006120075	8006120072	80/05/27	50-320	P	8006120446	8006120442	80/05/13	XPDRTLIC
8006120079 8006120086	8006120074 8006120082	80/05/22 80/05/28		H	8006120447 8006120450	8006120443 8006120449	80/05/16 80/05/14	SO-416 M XPDRTLIC
8006120078 8006120106	8006120090 8006120102	80/04/18 80/05/14	50-54 50-387	9 8	8006120472 8006120473	8006120467 8006120468	80/05/22 80/05/15	GA999 SECY
8006120107	8006120100	00/05/14	COMMISSIO	N	8006120475	8006120467	80/05/22	QA 99 9

ACCESSION	NUMBER				AC	CE8810N 1	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGORY		ENCLO	ISURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEGORY	_
9006120477 9006120478	8006120468 8006120467	90/05/15 90/05/22	BECY GA999		60061	30199	3006130195 3006130197	80/05/28 80/05/28	50-280 COMMISSIO	G
9005120480 8005120482	8006120464 8006120468	80/05/07 80/05/15	71-9044 BECY		80061	30201 6	9004130192 9004130194	80/05/23 80/04/04	50-315	P
8006120483	8008120467	60/05/22	QA999				3004130175	80/05/28		a
8006120489 8006120499	8006120468 8006120496	80/05/15 80/05/29	BECY 50-10	P			9004130197 3004130192	80/05/28 80/05/23	COMMISSION 50-315	
8006120500 8006120502	800&120497 800&120497	80/05/29 80/05/29	XPORTLIC XPORTLIC		80061	30207 6	9006130197 9006130197	80/05/28 80/05/28	COMMISSIO	
8006130003	8004130002	90/04/30	COMMISSI	DN			000130177 0004130208	80/05/23	50-247	P
8006130007 8006130008	8006130005 8006130006	80/06/09 80/05/15	CONTRACT				0006130197	80/05/28	COMMISSIO	N B
8006130012	8006130006	80/05/15	70-1007 70-1007		80061	30220 8	9006130210 9006130208	90/06/10 90/05/23	50-247	P
8006130013 8006130015	8006130006 8006130006	80/05/15 80/05/15	70-1007 70-1007				300613020B 3006130227	80/05/23 80/05/27		H
8006130019	8006130016	80/05/05	50-255	P			0006130244	80/05/23	CONTRACT	_
8006130027 8006130028	8004130023 8004130026	BO/05/12 BO/05/28	XPORTLIC	DN			8004130255 8004130255	B0/04/26 B0/04/26		0
8006130031 8006130033	B004130023 B004130030	80/03/12 80/05/21	COMMISSION XPORTLIC	DN			9004130260 9004130260	80/06/10 80/06/10		P
9006130036	8006130034	80/05/28	71-397				8006130260	80/06/10		Þ
8000120038	8006130035	80/04/30	50-335	0	80061	130267 (9006130265	80/06/09	50-263	R
8006130039 8006130040	8004130037 8004130037	80/05/22 80/05/22	50-266 50-266	P P			9006130274 9006130273	80/06/09 80/06/03		R R
8006130045	8006130044	80/05/16	71-9071	•			9006130283	80/06/06		В
8004130051 8004130083	8004130047 8004130050	B0/05/06 B0/05/29	PR 50-413	a			9004130295 9004130297	80/06/06 80/05/16		R
8006130054	8006130042	80/05/01	50-424	Q	80061	130341 1	9006130339	90/06/04	50-312	a
8004130084 8004130040	8004130050 8004130050	80/05/29 80/05/29	50-413 50-413	a a			8006130385 8006130389	80/03/19 80/04/29	COMMISSIO 50-261	a
8004130041	8004130057	80/05/09	NUREO				8006160005	90/06/12		8
8006130044 8006130065	8004130062 8004130050	80/05/14 80/05/29	71-9009 50-413	Q.		60013 1	800616000 7 8006160011	80/06/10 80/06/09	50~206	R
8006130067 8006130068	8006130059 8006130066	80/05/02 80/05/04	50-275 PR	a			8006160014 8006160018	80/06/10 80/06/05		R B
8006130071	9004130070	80/05/15	NUREO				8006160022	80/06/04		R
8004130074 8004130075	8004130049 8004130073	80/04/25 80/05/15	50-498 DRO	Q			B006160025 B006160024	80/06/10 80/06/10		R 8
8004130077 8004130080	8004130072 8004130074	80/05/08 80/05/23	PR 50-285	a	80061	140029	B006160028 B006160030	80/04/04 80/04/04		8
8004130082	8004130074	80/05/23	50-255	0			8006160032	80/06/09		P
E000613000B	2004130076	80/05/23	50-344	ā	90061	160035	8006160034 8006160017	90/06/05 90/06/06		P R
9004130084 9004130084	8006130079 8006130076	80/05/01 80/05/23	10CFR 50-255	a	80061	160038	9006160037	80/06/09	50-244	R
8006130088	8004130074	80/05/23	50-255	G.			8004160040	80/06/06		A
8004130090 8004130091	9004130074 9004130097	90/05/23 90/05/04	50-285 100FR	a			8006160043 8006160047	B0/06/10 B0/06/03	50-336	Q P
8004130072	6004130074	80/05/23	50-265	Q .	B0061	160055	0000160050 E006160053	80/06/05 80/06/10		8 9
8004130074 8004130077	8006130076 8006130076	80/05/23 80/05/23	50-333 50-307	Q	80041		8004140057	80/05/27		P
8006130098	8004130094	80/05/06	PRH	_			14004140041	90/06/12 80/06/11		0 8
8004130099 8004130102	8004130074 8004130074	80/05/23 80/05/23	50~255 50~295	a a			8006160063 8006160070	80/06/09	50-400	Ø
8006130103 8006130104	8006130100 8006130076	80/05/04 80/05/23	100FR 50-295	G.			B006160073 B006160076	E1\40\08 01\40\08		8 8
8005130104	8004130076	80/05/23	50-275	g.			8006160082	80/06/09		8
8006130111	0004130074	80/05/23	50-315	Gr C	90061	480084	9006160090	80/06/05	50-217	8
9006130113 9006130115	8004130074 8004130074	80/05/23 80/05/23	50-315 50-315	Q Q			E800414008 P800414008	80/06/12 80/06/11	50-443	0
8006130120	8004130074	80/05/23	50-292	ā	8006	160099	8006160075	80/06/09	50-305	R
8006130124 8006130136	8004130074 8004130074	90/05/23 80/05/23	50-255 50-255	Q Q			8006160097 8006160103	80/06/03 80/06/07		8 8
8004130136	8006130076	80/05/23	50-10	a	90061	1601 IB	8006160115	80/66/06	50-267	ä
8005130141 8005130142	8006130076 8006130076	80/05/23 80/05/23	50-10 50-10	0 G			8006160116 8006160121	80/05/29 80/06/03	0A999 50-249	B
8006130144	8004130074	00/05/23	FOIA				8110616008	80/05/29	QA997	
8006130145	8004130074 8004130074	80/05/23 80/05/23	FOIA FOIA		:4008 :4008		B004160114 B004160107	80/05/27 80/06/03	9A999 50-272	R
8006130148 8006130151	8004130076	80/05/23	FOIA		8004	160138	B006160116 B006160140	80/05/29 80/06/10	QA999	0
8006130152	8004130074	80/05/23	FOIA							
8006130154 8006130162	8004130074 8004130189	80/05/23 80/06/11	FOIA 50-322	۰	8006	160150	9006160145 9006160146	90/06/10 90/04/03	70-2909	A
8006130173	8004130170	90/05/29 90/05/29	50-320 50-320	Ŭ U			8006160152 8006160157	90/05/2 9 90/05/21	PR 71-6698	
8006130176 8006130178	8004130170 8004130171	80/03/29	50-482	a			8006160166	80/05/27		¢
8006130187	8006130184	80/05/23	50-546	н			9006160157	80/05/21	71-6498	
8006130191 80106130193	8006130180	90/05/2 7 90/05/02	COMMIBS1 50-315	ON G		160179	8006160157 8006160157	80/05/21	71-6698 71-6698	
8006130196	8006130192	80/05/23	50-315	P Q	B004	160184	8006160157 8006160181	80/05/21 80/04/29	71-4478 50-338	a
90 061301 7 8	8006130189	80/05/02	50-315	•	3000	-30.00				

ACCE9810N	NUMBER				AC CESS	ION NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJEC*	
8006160187 8006160194 8006160196 8006160198 8006160206	8006160157 8006160189 8006160190 8006160188 8006160200	80/05/21 80/05/30 80/04/30 80/05/30 80/04/30	71-6698 50-10 50-280 50-10 50-390	 D D D	890617045 800617045 800617045 800617046 800617046	7 8006170449 9 8006170451 1 8006170449	80/05/05 80/05/07 80/05/05 80/05/07 80/05/13	50-247 50-10 50-247 50-10 90-344	P R P R
8005150215 8005160216 8005160217 8005160221 8005160222	8006160210 8006160214 8006160216 8006160214 8006160214	80/05/05 80/01/31 90/05/02 80/01/31 80/01/31	50-186 ORC 50-395 ORC DRO	Q Q	800417044 800417047 800417047 800417047 800417047	1 8006170467 2 8006170456 4 8006170467	80/06/05 80/06/07 80/06/13 80/06/07 80/06/06	50-247 50-250 50-346 50-250 50-275	P R P R
8006160226 8006160227 8006160228 8006160229 8006160230	8006160214 8006160224 8006160214 8006160225 8006160214	80/01/31 80/08/31 80/01/31 80/05/29	DRO CONTRACT DRO WASTE MG DRO		800617047 800617047 800617048 800617048 800617049	7 8006170467 2 8006170478 7 8006170485	80/06/10 80/06/07 80/06/05 80/06/06 80/06/12	50-266 50-250 50-111 50-439 50-389	R N S M
0006160234 8006160235 8006160236 8006160242 8006160248	8006160232 8006160233 8006160233 8006160239 8006160245	80/03/30 80/05/29 90/05/29 80/05/27 80/05/08	50-387 ORQ ORQ 70-143 50-263	A Q	800417050 800417050 800417050 800417051 600417051	5 8006170498 7 8006170501 2 8006170506	90/06/10 . 90/06/06 80/06/10 90/06/11 80/06/12	50-259 50-295 50-259 50-296 50-280	8 R 8
8006160257 8006170007 8006170052 8006170064 8006170083	8006170004 8006170004 8006170044 8006170057 8006170073	80/05/08 80/05/23 80/04/28 80/05/02 80/06/05	50-263 50-445 50-315 70-1308 50-409	0 H D	800417051 800417052 800417052 800417052 800617053	7 9006170515 8006170526 9 8006170515	80/06/05 80/06/11 80/06/12 80/06/11 80/06/12	50-237 50-155 50-213 50-155 50-269	8 R 8
8006170088 8006170106 8006170141 8006170149 8006170137	8006170073 8006170074 8006170133 8006170136 8006170133	90/06/05 90/05/30 90/03/12 90/02/07 90/03/12	50–407 71–390 PRM PRM PRM	a	800417053 800417054 800417054 800417055 800417059	1 8006170536 9 8006170543 0 8006170521	80/06/11 80/06/11 80/06/12 80/06/11 80/06/06	50-155 50-327 50-327 50-315 50-335	8 9 R 8
8006170159 8006170171 8006170176 8006170180 8006170183	8006170154 8006170165 8006170165 8006170165 8006170107	80/04/23 80/05/29 80/05/29 80/05/29 80/05/12	50-382 50-250 50-250 50-250 50-443	а о о	800417035 800417034 800417036 800417036 800417037	1 8006170554 3 8006170558 4 8006170559	90/06/11 90/06/10 90/06/09 90/06/06	50-328 50-327 50-334 50-254 50-599	8 8 F 0
8006170195 8006170195 8006170197 8006170201 8006170211	8006170165 8006170187 8006170196 8006170196 8006170193	80/05/29 80/05/02 80/04/26 80/04/26 80/05/23	50-250 50-483 50-483 50-483 50-327	0 0 0	800417057 800417057 800417057 800417057 800417058	5 8006170566 6 8006170558 8 8006170573	80/06/09 80/06/09 80/06/09 80/06/12 80/06/06	50-334 50-259 50-334 50-272 50-254	8 8 8 F
9004170213 8006170215 8004170219 8006170222 8006170228	8006170208 6006170193 8006170208 8006170193 8006170193	80/04/25 80/05/23 80/04/25 80/05/23 80/05/23	50-454 50-327 50-454 50-327 50-327	G G G	800417038 800417039 800417039 800417039 800417039	1 80051/0559 2 8005170581 5 8005170589	80/04/11 80/04/06 80/04/10 80/04/12 80/06/06	50-339 50-254 50-296 50-271 50-254	8 F 8 F
8006170234 8006170249 8006170253 8006170256 8006170273	8005170229 8005170244 8005170244 8005170244 8005170267	80/04/11 80/05/20 80/05/20 80/05/20 80/06/13	50~269 50~266 50~266 50~266 50~269	Р Р Р М	800417040 800417040 800417040 800417040 800417040	4 9006170598 5 9006170596 6 9006170601	90/06/06 90/06/10 90/06/06 90/06/09 80/06/06	50-254 50-348 50-390 50-322 50-254	F 8 0 F
8006170274 8006170276 8006170279 8006170290 8006170292	8006170269 8006170268 8006170269 9006170283 8006170269	80/06/03 80/05/01 80/06/03 80/06/10 80/06/03	70-25 50-254 70-25 50-382 70-25	G K	800617061 800617061 800617061 800617061 800617062	4 B006170603 5 B006170611 6 B006170559	80/06/06 80/06/11 80/06/13 80/06/06 80/06/13	50-254 50-296 50-339 50-254 50-339	F 8 F P
8006170293 8006170295 8006170297 8006170302 8006170312	8006170283 8006170291 8006170269 8006170269 8006170308	80/06/10 80/04/30 80/06/03 80/06/03 80/04/24	50-362 50-295 70-25 70-25 50-10	G G	800617062 800617062 800617063 800617063 800617063	6 9006170611 8 9006170559 0 9006170623	90/06/06 90/06/13 90/06/06 90/06/13 90/06/06	50~254 50~337 50~254 50~313 50~254	F 8 8
8006170314 8006170318 8006170320 8006170321 8006170342	8006170310 8006170310 8006170308 8006170316 8006170335	80/06/11 80/06/11 80/04/24 80/04/24 80/05/23	50-321 50-321 50-10 50-282 50-546	I I Q Q H	900617043 900617043 900617043 900617043 900617044	4 8006170625 8 8006170636 9 8006170635	80/06/13 80/06/12 80/06/09 80/06/12	50-339 50-348 50-29 50-239 50-271	р 8 8 8
8006170354 8006170360 8006170375 8006170391 8006170398	8006170351 8006170358 8006170371 8006170387 8006170395	B0/06/10 B0/06/13 B0/06/02 B0/04/30 B0/04/24	50-346 TOPREP 50-458 50-247 50-277	8 Q Q	800417045 800617045 800617046 800617046 800617046	2 8006170647 1 8006170657 2 8006170653	90/06/11 90/06/06 90/06/06 90/06/12 90/06/09	50-338 50-335 50-336 50-280 50-331	8 8
8006170405 8006170407 8006170408 8006170417 8006170434	8006170404 8006170404 8006170404 8006170413 8006170431	80/06/13 60/06/13 80/06/13 80/06/16 00/06/10	50-341 50-341 50-341 50-409 50-3	1 1 0 R	800617067 800617067 800617067 800617067 800617069	2 9006170659 7 8006170669 9 8006170673	80/04/12 80/04/11 80/04/10 80/04/06 80/04/03	50-272 50-328 50-316 50-321 50-321	8 8
8006170440 8006170441 8006170443 8006170446 8006170452	8006170438 8006170439 8006170442 8006170445 8006170448	90/06/09 90/06/10 90/06/09 90/06/10 90/06/09	50-245 50-317 50-285 50-277 50-10	R F R R	900617048 900617048 900617045 900617049 900617070	7 8006170483 1 8006170485 6 8006170489	80/03/31 80/04/03 80/04/11 80/04/12 80/04/11	50-335 50-366 50-327 50-309 50-339	8 8 8

ACCES910					ACCEB810	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUS JECT CATEGOR	γ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8006170704 8006170729	8006170698 8006170724	90/06/11 90/04/10	50-316 70-1201	R	8006180138 8006180141	8006180125 8006180016	80/05/30 80/05/23	50-247 FQIA	Ť
8006170730 8006170736 8006170738	8006170727 8006170726 8006170727	90/04/26 90/05/05 90/04/26	50-295 50-373 50-295	0 0 0	9005180142 9005180145 9005180149	8004180117 8004180016 8004180123	80/04/29 80/05/23 80/05/30	8ECY FOIA 50-247	т
B006170739 B006170744	8006170735 8006170735	60/05/21 80/05/21	50~309 50 ~3 09	G G	8006180152 8006180165	8006180016	80/05/23 80/04/08	FOIA 70-824	
8006170746 8006170749 8006170750	8006170740 8006170742 8006170735	80/05/02 80/05/06 80/05/21	50~566 50~358 50~309	Q G	8004180164 8004180169 8004180178	8006180161 8006180162 8006180171	B0/06/04 B0/04/08	50-255 70-824	G
8006170751 8006170757	8006170740 8006170740	80/06/02 80/06/02	50-566 50-566	a	9004180182 8004180185	8006180016 8006180181	80/05/30 80/05/23	50-271 FOIA	н
8006170788 8006170762	8006170755 8006170760	80/04/26 80/04/18	50-327 50-302	a a	8006180172	8006180016	80/05/23 80/05/23	50-522 FOIA	0
8006170763	6006170755	80/04/26	50-329	Q	8006180194 8006180195	8006180190 8006180016	80/05/07 80/05/23	50-289 FDIA	Q
9006170764 8006170765	8004170784 8004170740	80/04/26 80/04/18	50-373 50-302	Q Q	8006180198 8006180200	8006180016 8006180176	80/05/23 80/05/20	FDIA 50-466	٥
8006170766 8006170768	0006170761 0006170740	80/05/05 80/06/02	50-331 50-566	g G	8006180203	8006180016	80/05/23	FOIA	
9006170769	8004170740	80/04/18	50-302	ā	8006180205 8006180206	8006180196 8006180016	80/05/20 80/05/23	50~466 FDIA	•
8006170772 8006170774	8006170747 8006170756	80/04/22 80/04/26	50-321 50-373	a a	8006180215 8006180219	8004180197 8004180210	80/05/19 80/05/09	50-458 FOIA	И
8006170775 8006170776	B006170767 B006170771	80/04/22 80/05/06	50-321 50-456	q q	8006180223	8006180210	80/05/09	71-9103	
9006170784	8006170779	80/04/30	50-321	Ğ	8006180227 8006180234	8006180016 8006180016	80/05/23 80/05/23	FOIA FOIA	
8006170788 8006170794	8004170782 8004170789	80/04/24 80/04/30	50-277 50-3 87	a a	9004190234	8004180210	80/05/09	FOIA	_
8006170796 80061707 9 9	8004170790 8004170795	90/04/24 90/05/01	50-247 50-346	a a	8006180240 8006180241	8006180237 8006180016	80/03/28 80/03/23	50-349 F01A	Œ
2006170905	0006170004	80/04/30	50-293	ā	8006180245 8006180246	8006180016 8006180237	80/05/23 80/05/28	FDIA 50-349	œ
8004170807 8004170808	9004170901 9004170902	80/05/01 80/05/30	REGOD 50-171	н	8006180251	8006180239 8006180016	11/30/08	50-416	8
8006170816 8006170817	8004170810 8004170815	80/04/25 80/05/29	50-317	ā	8006180252 8006180253	8006180247	80/05/23 80/06/12	FOIA 50-281	P
8004170918	2004170812	80/05/20	71~9094 PRM		8006180263 8006180264	8006180016 8006180256	80/05/23 80/06/12	F01A 50-2	F
8004170826 8004170829	9004170821 9004170822	90/05/22 80/04/24	XPORTLIC 50-293	œ.	B0041B026B	81006180016	80/05/23	FOIA	
6004170933 6004170843	#006170830 #004170839	79/11/01	TOPREP		8006180272 8006180276	8006180016 8006180016	80/05/23 80/05/23	FOIA FOIA	
8006170857	8006170971	79/07/17 80/05/13	TOPREP 50-324	G .	8006180279 8006180281	8006180016 8006180278	80/05/23 80/06/05	FOIA 50-373	A
8006180002 8006180003	9004190001 9004190001	80/05/29 80/05/29	70-1151 70-1151		8004180283	8006180016	80/05/23	FOIA	
8006180004 8006180005	9004180001 8004180001	80/05/29	70-1151		8006180286 8006180286	8004180014 8004180014	80/05/23 80/05/23	FOIA FOIA	
8004180010	8006180006	90/05/29 90/06/02	70-1151 50-244	•	80061 8028 9 80061 8 0291	8006180285 8006180287	80/05/19 80/06/13	50-295 50-416	8
8006180012 8006180021	8004180009 8004180017	80/05/01 80/05/30	50-324 50-250	Q Q	8006180292	8006180016	80/05/23	FOIA	
8006180024	8004180017	80/05/30	50~250	Q.	8006180294 8006180300	8006180016 8100818008	80/05/23 80/05/23	FOIA FOIA	
8004180028 8004180032	8004180017 8004180017	80/05/30 80/05/30	50-250 50-250	a a	8006180301 8006180303	9006190295 8006190298	80/06/02 80/05/12	50-206 0A999	Q.
8006180033 80008180096	9004190017 9004190017	80/05/30 80/05/30	50-250 50-250	Q Q	9006190305	8006180295	80/06/02	50-204	Œ
8006180043	8004180040	80/05/30	50-289	0	80041 8 0307 8004180310	8006180016 8006180275	80/05/23 80/06/02	FDIA 50-204	a
9006190046 9006190049	8004180041 8004180045	90/04/25 90/04/14	50-255 50-416	G G	8006180314 8006180319	8006180295 8006180293	80/06/02 80/06/04	50-204 50-10	G F
8006180051 8006180056	0006180045 0006180053	80/04/14 80/04/29	50-416 50-272	Q Q	8006180323	8004180317	80/06/02	50-321	q
8006190057	8004180054	80/04/29	50-29	Q.	8006180324 8006180327	8006180293 8006180317	80/06/04 80/06/02	50-10 50-321	F 9
8004180044 8006180048	8006180061 8006180061	80/05/21 80/05/21	50-518 50-518	G G	8006180329 8006180331	8006180321 8006180273	80/05/29 80/06/04	50~458 50-10	A F
8006180072	8004180041 8004180070	80/05/21 80/04/29	50-518	Q	9006190332	8006180317	80/06/02	50-321	q
8006180075 8006180077	10008100081	80/05/21	50~263 50~518	Q Q	8006180335 60018008	8006180016 8006180016	80/05/23 80/05/23	FOIA FOIA	
5800819008 5800819008	8006180059 8006180061	80/04/24 80/05/21	50-320 50-518	Q Q	8006180338 8006180340	8006180317 8006180293	80/06/02 80/06/04	50-321 50-10	g F
9006180097	18006190081	80/05/30	CONTRACT	_	8006180342	8004180016	80/05/23	FOIA	
17008180091 5700818008	8006180061 8006180092	BO/05/21 BO/04/24	50~518 50-293	Q Q	8004180347 8004180348	8006180293 8006180016	80/05/04 80/05/23	50-10 FOIA	F
8006180108 8006180110	B0061B0101 B0061B0016	79/09/28 80/05/23	50-282 FOIA	P	8006180349 8006180350	8004180343 8004180344	80/06/09 80/03/20	CONTRACT 70~135	Г
9006190114	8004180111	80/04/29 80/05/23	70-371		8006190353	8004180344	80/03/20	70-135	
8006180115 8006180119	8004180014 8004180014	00/05/23	FOIA FOIA		8006180369 8006180373	8006180364 8006180370	80/06/05 80/06/18	50~373 50~498	K
8006180123 8006180126	8004180117 8004180121	80/04/29 80/04/29	BECY 50-272	a	8006180390 8006180391	8004180384 8004180384	80/05/08 80/06/13	50-414 50-392	Ğ 8
8006180127 8006180131	8006180016 8006180117	80/05/23 80/04/29	FOIA BECY		9006180394 8006180397	8006180346 8006180373	80/06/12 80/05/08	50-466 50-328	9
8006180132 8006180135	8006180125 8006180016	80/05/30 80/05/23	50-247 FOIA	Ŧ	8960814008	8006180395	80/06/12	50-466	G
8006180137	8006180016	80/08/53	FOIA		8006180404 8006180414	8006180401 8006180410	80/06/13 80/04/29	50-395 50-483	S

ACCESSIO	N NUMBER				ACCESSIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT	
8006180417 8006180418 8006180427 8006180436 8006180439	8006180416 8006180416 8006180426 8006180435 8006180438	80/05/29 80/05/29 80/05/15 80/06/12 80/06/10	50-336 50-336 50-3 50-318 50-321	P R P R	8006190323 8006190345 8006190356 8006190362 8006190362	8006190319 8006190339 8006190349 8006190349	80/04/29 80/06/13 80/03/20 80/03/20 80/05/09	50-546 50-277 GA999 GA999 50-373	Q R
8006180442 8006180443 8006180446 8006180447 8006180451	8006180440 8006180433 8006180444 8006180447 8006180448	90/06/09 90/06/01 90/06/11 90/06/13	50-348 50-317 50-293 50-325 50-282	R B R B	8006170347 8006170370 8006170371 8006170374 8006170375	8006170365 8006170347 8006170361 8006170347 8006170365	80/05/22 80/03/20 80/04/24 80/03/20 80/05/22	40-1341 94779 50-277 94779 40-1341	a
9006180453 8006180454 8006180459 8006180460 8006180465	8006180448 8006180452 8006180456 8006180458 8006180455	80/06/13 80/06/12 80/06/11 80/06/13	50-282 50-325 50-368 50-368 50-324	R 8 8	8006190376 8006190379 8006190386 8006190386 8006190398	8006170347 8006170378 8006170347 8006170383 8006170389	90/03/20 80/05/09 80/03/20 80/06/05 80/06/04	QA999 50-295 QA999 50-315 50-116	Q Q
8006180467 8006180468 8006180476 8006180480 8006180487	B006180463 B006180462 B006180470 B006180473 B006180484	80/06/12 80/06/12 80/06/13 80/06/12	50-368 50-416 50-280 50-318 50-327	8 8 9 8	8006190422 8006190426 8006190431 9006190431 8006190439	8006170414 8006170414 8006170414 8006170414 8006170437	00/06/13 00/06/13 00/06/13 00/06/06	50-255 50-255 50-255 50-255 50-133	8880
8006180490 8006180497 8006180503 8006180505 8006180513	8006180493 8006180494 8006180500 8006180496 8006180509	80/06/13 80/06/10 80/06/13 80/06/11 80/06/13	50-318 50-366 50-333 50-324 50-272	8 8 8 9	8006190444 8006190446 8006190470 8006190478 8006190925	8006170440 8006170461 8006170468 8006170473 8006170522	00/06/11 00/06/13 00/06/13 00/06/16 01/60/08	50-361 50-331 50-259 50-244 50-361	8 8 8
8006180518 8006180520 8006180522 8006180524 8006180533	8004180515 8004180502 8004180519 8004180521 8004180527	80/06/13 80/06/12 80/06/10 80/06/11 80/06/11	50-318 50-296 50-275 50-327 50-327	8 9 8 8	8006190332 8006190339 8006190339 8006190341 8006190357	8006170522 8006170522 8006170537 8006170535 8006170553	B0/06/16 B0/06/16 B0/06/12 B0/06/17 B0/06/03	50-361 50-361 50-320 50-247 50-466	I O S O
8006180535 8006180536 8006180550 8006180552 8006180556	8006180539 8006180529 8006180547 8006180547 8006180544	80/06/12 80/06/13 80/06/04 80/06/04	50-327 50-3 50-373 50-373 50-437	8 R Q Q	8006170361 800619034 8006190374 8006190388 8006190389	8006170551 8006170553 8006170566 8006170578 8006170583	80/06/13 80/06/03 80/06/10 80/06/09 80/06/13	50-286 50-466 50-321 50-321 50-368	R 0 8 8
8004180558 8004180581 8004180587 8004180400 8004180411	8006180555 8006180574 8006180582 8006180594 8006180607	80/06/05 80/05/02 80/06/04 80/06/03 80/04/24	50-266 50-266 CONTRACT 50-315 EEE-06	Р О О	8006190603 8006190606 8006190610 8006190612 8006190617	8006170576 8006170573 8006170602 8006170604 8006170607	80/06/12 80/06/17 80/06/11 80/06/03 80/06/11	50-302 50-249 50-336 50-219 50-321	8 9 9
8005180624 8005190025 8005190064 8005190075 8005190080	8006180617 8006190021 8006190089 8006190069 8006190072	80/04/24 80/05/28 80/05/22 80/04/24 80/06/13	70-687 XPORTLIC 40-1341 50-184 FOIA	e G	8006190621 8006190630 8006190641 8006190643 800619064	8006190617 8006190626 8006190636 8006190640 8006190634	80/06/10 80/06/13 80/06/03 80/06/01 80/06/04	50-302 50-247 50-312 50-293 50-320	R R R H
8005190088 8005190095 8005190104 8005190118 8005190125	8006190083 8006190089 8006190100 8006190115 8006190115	80/04/29 80/06/05 80/05/23 80/06/13 80/06/13	70-820 50-373 CONTRACT FOIA FOIA	. ^	8006190645 8006190668 8006190675 8006190679 8006190683	8006190625 8006190667 8006190673 8006190677 8006190681	90/06/12 79/12/10 90/05/09 90/05/02 90/05/29	50-344 ACR8 50-255 70-267 50-302	I G G
800&170127 800&170130 800&170133 800&170153 800&170154	8004170115 8004170127 8004170127 8004170148 8004170132	80/06/13 80/03/31 80/03/31 80/05/23 80/04/30	FOIA BECY BECY 50-219 50-376	Q Q	8006190687 8006190689 8006190691 8006190692 8006190700	8006190686 8006190681 8006190681 8006190696	80/05/29 80/06/13 80/05/29 80/05/29 80/05/29	50~302 50~313 50~302 50~302 50~546	0 R 0 0
8006 90168 8006 90182 8006 90197 8006 9020 8006 9020	8006170137 8006170177 8006170172 8006170172 8006170172	80/04/24 80/03/07 80/05/21 80/05/21 80/05/21	50-320 50-373 50-201 50-201 50-201	0 0 0 0	8006190703 8006190703 8006190713 8006190717 8006190735	8006190696 8006190696 8006190696 8006190696 8006190732	80/05/29 80/05/29 80/05/29 80/05/29 80/04/01	50~546 50~546 50~546 50~546 70~820	9
8006190208 8006190219 8006190226 8006190227 8006190230	8006170172 8006170213 8006170218 8006170213	80/05/21 80/03/12 80/04/30 80/03/12 80/04/24	50-201 70-572 50-445 70-572 50-220	G G	8006190745 9006200003 8006200005 8006200007 8006200010	8006190744 8006200002 8006200002 8006200004 8006200004	80/04/08 80/05/20 80/05/20 80/05/29 80/05/29	70-2909 CONTRACT CONTRACT 70-1151 70-1151	
8006190231 8006190240 8006190249 8006190252 8006190255	8006170224 8006170232 8006170243 8006170244 8006170237	80/06/11 80/05/30 80/04/24 80/05/29 80/06/12	XPORTLIC 50-416 50-277 CONTRACT FOIA	M Q	8006200011 8006200013 8006200015 8006200050 9006200061	9006200007 9006200009 9006200004 8006200046 9006200051	80/05/30 80/05/30 80/05/29 80/04/14 80/05/28	WARTE HO WARTE HO 70-1151 70-754 State Pr	T
8006190287 8006190267 8006190268 8006190276 8006190278	9006170246 8006170261 9006170262 8006170272 9006170274	80/05/07 80/04/30 90/05/05 90/05/28 90/05/01	50-370 CONTRACT 50-302 CONTRACT 50-334	a	8006200071 8006200074 8006200078 8006200083 8006200091	8005200055 8005200058 8005200073 8005200081 8005200087	80/05/23 80/04/03 80/06/02 80/04/29 80/03/19	50-498 50-312 CONTRACT 70-1257 50-320	e P U
800&170285 800&170287 800&170300 800&170308 800&170321	9006170258 9006170284 9006170276 8006170303 8006170315	80/05/30 80/05/07 80/06/06 80/04/25 80/06/16	50-251 50-298 50-544 50-271 50-412	8 Q Q Q B	8006200093 8006200094 8006200197 8006200100 8006200107	8004200084 8004200088 8004200088 8004200094 8004200101	90/06/04 90/05/06 90/05/12 80/04/22 90/04/01	CONTRACT 50-348 50-305 71-185 70-498	g g

ACCEBBIO	NUMBER				ACCEBBIO	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEODR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEGORY
8006200111	8006200107	80/04/23	50-358	a	8006230020	8006230016	80/05/16	50-10 G
8006200113 8006200114	8006200107 8006200105	80/04/23 80/05/08	50~358 50~339	Q Q	8006230022	8006230019	80/03/27	70-984
B006200117	8006200112 8006200118	80/04/18 80/04/25	70-36		8006230024 8006230025	8006230016 8006230019	80/03/14 80/03/27	50-10 0 70-984
	8005200118		50-461	a	8006230026	8006230019	B0/03/27	70-984
B006200124 B006200128	8006200126	80/04/25 80/05/08	50-441 50-339	a 6	8006230033 8006230036	B006230030 B006230034	80/06/05 80/ 0 6/04	50-390 G CONTRACT
8006200135 8006200136	8004200133 8004200131	80/04/11 80/05/09	0A999 50-373	G.	8004230037 8004230040	B006230032 B006230035	B0/05/05 B0/05/29	71-5939 CONTRACT
8006200137	8006200134	80/06/04	CONTRACT		8006230041	8006230039	B0/06/04	CONTRACT
B006200139 B006200141	6004200138 6004200131	80/05/29 80/05/09	9A999 50~373	a	8006230043	8006230038	80/06/10	50-246 G
6006200143	8006200138 8006200140	B0/05/29	94777	u	8006230048 8006230054	8006230044 8006230049	80/05/23 80/05/14	CONTRACT 50-461 Q
B006200145 B006200146	8006200130	80/06/05 80/05/29	70-1308 GA979		9006230060 9006230061	8006230055 8006230049	80/05/13 80/05/14	50-373 Q 50-461 Q
B006200147	8006200144	79/10/26	50-462	P	8004230042	8006230051	80/05/27	50~20 8
B006200148 B006200168	8004200138 8004200142	80/05/29 80/05/30	0A 97 7 50-265	P	8006230069 8006230071	8006230063 8006230065	80/05/10 80/05/19	50-483 G
B006200169 B006200172	8006200165 8006200165	80/03/25 80/03/25	70-824 70-824		E006230077	8004230070	80/05/13	50-295 Q
				_	8006230078	8006230075	80/05/14	50-254 G
8006200179 8006200199	8006200171 8006200176	80/06/16 80/05/13	50-397 50-315	8 0	8006230083 8006230087	8006230004 8006230082	80/03/30 80/05/13	CONTRACT 50-358 G
8006200216 8006200219	8006200212 8006200212	80/06/04 80/06/04	50~250 50~250	Q.	8006230071 8006230072	8006230085 8006230082	B0/05/14 B0/05/13	50-409 Q 50-358 Q
8009500555	8004200212	80/06/04	50-250	ā	8004230113	8006230102	BQ/05/0B	50-150 G
8006200227	8004200212	60/06/04	50-250	Q	8006230114	B006230098	80/06/04	50-280 Q
B006200248 B006200257	8006200237 8006200237	80/05/20 80/04/25	40-8576 70-33		8006230117 8006230118	8006230112 8006230098	80/06/02 80/06/04	20-580 0 COHRIBSION
B004200244 B004200280	8008200256 8008200272	80/05/14 80/05/16	50-341 50-266	G G	8005230123 8005230124	8006230119 8006230120	B0/05/22 B0/06/04	COMMIBBION CONTRACT
B006200292	8006200288	80/05/16	71-173		8006230125	8006230121	80/03/27	70-27
8004200324 8004200338	8004200321 8004200327	80/06/13 80/05/12	50-327 70-143	P	8006230126	8006230098	80/06/04	50-280 G
B00420034B	8006200343	80/05/23	LOCER	_	9006230131 9006230133	8006230128 8006230129	80/05/21 80/06/11	COMMIBBION TOARTMOD
B006200363	8006200359	80/06/16	50-349	8	8006230136	8006230108	40/40/08	DR 0
B006200345 B006200378	8006200361 8006200375	B0/06/11 B0/06/13	50-329 50-566	A B	8005230144 8005230148	8006230141 8006230145	80/04/21 80/03/09	50~201 R 50~461 0
B006200426 B006200428	8006200424 8006200424	80/06/11 80/06/11	50-309 50-309	P P	8006230151	8006230145	80/05/09	50-461 0
B006200434	B006200430	80/06/16	50-368	8	8006230152 8006230153	8006230143 8006230147	80/03/28 80/05/30	50-128 Q 70-820
B005200444	8004200437	80/06/10	50~366	6	8006230164	8004230150	80/05/10	CONTRACT
B006200447 B006200449	8006200441 8006200445	80/06/11 80/06/16	50-321 50-255	8	8006230166 8006230171	8004230159 8004230159	80/06/02 80/06/02	50-335 G 50-335 G
B006200454 B006200457	8006200432 8006200451	80/06/13 80/06/13	50-518 50-327	8	8006230173 8006230178	8006230159 8006230170	80/06/02 80/06/11	50-335 Q CONTRACT
B006200458	8006200455	80/06/13	50-219	R				
B006200461	8006200452	80/06/13	50-321	8	8006230179 8006230180	8006230159 8006230176	80/05/23 80/05/23	50-335 Q 50-272 Q
B006200469 B006200472	8006200465 8006200466	80/06/16 80/06/12	50-305 50-263	8 9	8006230189 8006230190	8006230183 8006230186	80/06/08	50-280 G 50-375 K
8006200473	8006200465	80/06/16	50-305	8	8009530142	8006230183	80/06/05	50-280 0
B006200474 B006200481	800620046B 8006200476	80/06/11 80/06/11	50~366 50~366	8	8004230198 8004230200	8006230183 8006230194	80/06/05	50~290 Q
8006200483	900420047日	80/06/12	30-364	8	8006230202	8006230183	80/06/04 80/06/05	CONTRACT 50-280 G
8006200484 8006200493	8006200475 8006200485	80/06/16 80/06/17	50-327 50-368	8 8	8006230209 8006230214	8004530515 8004530502	80/05/30 80/05/20	50-331 G 999AD
8006200496	8006200495	80/06/16	50-287	R	8006230216	8006230212	80/05/20	QA999
8006200497 8006200516	8006200488 8006200514	90/05/13 90/05/09	50~327 50~280	e G	8006230218 8006230219	8006230210 8006230212	80/06/02 80/05/20	50-321 G GA999
8006200517	8006200510	80/05/09	50-392	ā	8006230222	8004230210	80/06/02	50-321 0
8006200525	8006200519	90/05/07	90-302		8006230223	8006230212	80/05/20	9 4777
8004200533 8004200534	B006200529 B006200530	80/05/06 80/05/30	50-320 50-471	P	8006230226 8006230226	8006230210 8006230210	80/06/02 80/06/02	50-321 0 50-321 0
8006200537 8006200538	8004200527 8004200520	80/06/10 80/04/29	50-329 70-33	ū	8006230230 8006230232	B006230224 B006230210	80/04/29 80/06/02	70-1319 50-321 G
B006200547	8006200541	80/06/10	50-266	Q	8006230237	8006230210	80/06/05	50-321 G
8006200564 8006200567	8006200557 8006200559	80/04/24 80/06/06	40-672 50-272	٥	8006230238	8004230233	80/04/11	QA999
8004200566	8006200566	80/05/23	40-8502	•	8006230247 8006230260	8006230244 8006230257	80/04/28 80/04/05	50-201 R 71-384
8006200570 8006200599	8006200566 8006200576	80/05/23 80/06/03	40-8502 50-320	н	8006230267 8006230273	8006230249 8006230249	B0/06/03	50-327 0 50-327 0
8006200605	8006200601	80/05/30	50-320	P	9004230281	8006230278	B0/06/04	10CFR
8006200611 8006200617	8006200610 8006200614	80/05/30 80/05/27	50~514 XPORTLIC	b	8006230308	8006230304	80/05/12	70-1143
8006200629	8006200626	80/04/30	50-267	E	81E0624008 82E0624008	8006230313	80/06/10 80/06/18	50-454 G 50-206 B
B006200633	8006200631	80/04/03	50-269	P	8008230327	B006230321	80/06/09	50-438 Q
8006200636 8006200639	8004200631 8004200431	80/06/03 80/06/03	90-267 50-269	P P	8006230331 8006230332	8006230321	80/06/09 80/06/09	50-438 Q 50-438 Q
8006200643 8006200645	8006200631 8006200642	80/06/03 80/06/02	50-289 REGOD	P	8006230335 8006230336	8006230326 8006230321	80/06/17 80/06/09	50-320 B 50-43B Q
8006230012	8006230008	80/04/02	50-261	P	8006230341	8006230249	80/04/03	50-327 G

ACCESSION NUMBER				ACCESS IC	N NUMBER			
PRINCIPAL ENGLOSURE DOCUMENT	ISSUED	SUBJECT CATEODS		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
9006230350 800623024 8006230363 800623034 8006230367 800623036 8006230371 800623036 8006230376 800623034	8 80/06/13 0 80/06/05 0 80/06/05	50-327 50-348 50-349 50-349 50-348	0 0 0 8	8004230439 8006230440 8006230541 8006230643 8006230644	8004230404 8004230404 8004230404 8004230404 8004230404	80/06/16 80/06/16 80/06/16 80/06/16	50~344 50~344 50~344 50~344 50~344	P P P
8006230377 800623037 8006230382 800623037 6006230387 800623038 8006230390 800623038 8006230392 800623039	3 80/05/28 1 80/06/10 9 80/06/18	30-309 50-309 50-249 50-324 50-254	0 8 P 8	8004230445 8006230448 8006230449 8004230649 8004230650	8006230604 8006230604 8006230604 8006230604 8006230604	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344 50-344 50-344	P P P
8006230398 800623039 9006230418 800623041 8006230439 800623037 8006230440 800623037	7 80/06/18 4 80/05/22 3 80/05/28 3 80/05/28	50-241 50-339 50-313 50-309 50-309	P 8 0 0	8006230651 8006230632 8006230653 8006230655 8006230657	8006230604 8006230604 8006230604 8006230604 8006230604	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344 50-344 50-344	P P P P
8006230447 800623044 8006230451 800623037 8006230452 800623037 8006230457 800623045 8006230459 800623045	3 80/05/28 3 80/05/28 0 80/06/04	50-339 50-309 50-309 50-348 50-70	6006	8006230639 8006230639 8006230661 8006230662 8006230663	8006230604 8006230604 8006230604 8006230604 8006230604	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344 50-344 50-344	P P P
8006230474 B00623046 8006230491 B00623048 8006230495 B006230495 8006230500 B006230495 B006230504 B00623050	7 80/04/14 80/04/10 80/04/19	50-335 50-315 50-335 50-339 50-331	8 8 8 8	8006230664 8006230665 8006230666 8006230667 8006230668	8004230404 8004230404 8004230404 8004230404 8004230404	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344 50-344 50-344	4 4 4
8006230507 8006230503 8006230515 8006230504 8006230520 8006230514 8006230524 8006230514 8006230524 8006230515	6 80/06/16 1 80/06/13 6 80/06/19	50-336 50-334 50-257 50-336 50-361	8 R P B A	8006230669 8006230670 8006230672 8006230675 8006230678	8006230604 8006230604 8006230604 8006230604 8006230604	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344 50-344 50-344	P P P P
8006230531 8006230513 8006230535 8006230532 8006230539 8006230534 8006230539 8006230534	80/06/17 80/06/18 80/06/19	50-361 50-272 50-361 50-337 50-361	8 A B A	8004230477 8004230480 8004230482 8004230484 8004230485	8004230404 8004230474 8004230404 8004230404 8004230404	80/06/16 80/06/19 80/06/16 80/06/16 80/06/16	50-344 50-528 50-344 50-344 50-344	P A P P
8006230546 8006230542 8006230547 800623054 8006230554 8006230554 8006230554 8006230515	80/06/18 80/06/18 80/06/18	50-248 50-341 50-339 50-361 50-361	Р А В А	8004230487 8004230489 8004230490 8004230492 8004230696	8006230604 8006230604 8006230604 8006230686 8006230691	80/06/16 80/06/16 80/06/16 80/06/19 80/06/19	50-344 50-344 50-344 50-528 50-528	P P C F
8004230562 8004230557 8004230564 8004230558 8004230565 8004230557 8004230571 8004230570	80/06/10 80/06/13 80/06/09	50-251	8888	8004230697 8008230698 8008230699 8008230702 8004230704	8006230686 8006230694 8006230604 8006230686 8006230604	80/06/19 80/06/19 80/06/16 80/06/19 80/06/16	50-528 50-528 50-344 50-528 50-344	С K Р С Р
#004230584 #004230572 #004230586 #004230581 #004230593 #004230581 #004230593 #004230590 #004230590	80/06/13 80/06/10 80/06/19	50-250 50-250 50-344	8 8 P P	8006230705 8005230707 8005240007 8006240008 8006240008	8006230686 8006230604 8006240005 8006240005 8006240032	80/06/19 80/06/16 80/05/23 80/05/16	50-528 50-344 50-247 50-267 50-373	С 9 9
B004230405 B004230404 B004230404 B004230404 B004230407 B004230404 B004230409 B004230404 B004230404	80/06/16 80/06/16 80/06/16 80/06/16	50~344 50~344 50~344	Р Р Р	8006240042 8006240043 8006240046 8006240051 8006240052	8006240035 8006240035 8006240036 8006240047 8006240045	80/05/05 80/05/29 80/05/05 80/06/11 80/05/12	50-313 50-416 50-313 50-324 50-395	G M Q Q
9005230510 8005230504 8005230511 8005230504 8005230512 8005230504 8005230513 8005230504 8005230514 8005230504	80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344	P P P P	8006240053 8006240053 8006240057 9006240058 8006240064	8004240050 8004240050 8004240047 8004240054 8004240060	80/05/06 80/05/06 80/06/11 80/05/27 80/06/06	50-267 50-267 50-324 QA999 50-359	G G
8004230615 8004230404 8004230416 8004230404 8004230418 8004230404 8004230421 8004230404 8004230421 8004230404	80/06/16 80/06/16 80/06/16 80/06/16	50-344 50-344 50-344	P P P P	8006240045 8006240070 8006240071 8006240073 8006240080	8006240054 8006240054 8006240066 8006240054 8006240054	80/05/27 80/05/27 80/05/12 80/05/27 80/05/27	GA999 GA999 50-321 GA999 GA999	a
8004230422 8004230404 8004230423 8004230404 8004230424 8004230404 8004230424 8004230404 8004230404 8004230404	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 1 50-344 1 50-344 1	P P P P	8006240084 8006240090 8006240093 8006240098 8006240101	8004240083 8004240083 8004240083 8004240091 8004240097	80/06/17 80/06/17 80/06/17 80/05/29 80/05/29	50-397 50-397 50-397 50-352 GA999	G G G
B004230428 B004230404 B004230430 B004230404 B004230431 B004230404 B004230431 B004230404 B004230404	B0/06/16 B0/06/16 B0/06/16 B0/06/16 B0/06/16	50-344	P P	8006240103 8006240103 8006240107 8006240114 8006240117	8006240097 8006240097 8006240097 8006240110 8006240109	80/05/29 80/05/29 80/05/29 80/06/04 80/05/30	QA999 QA999 QA999 QA999 50-249	Q
8006230634 8006230604 8006230635 8006230604 8006230637 8006230604 8006230638 8006230604	80/06/16 80/06/16 80/06/16 80/06/16 80/06/16	50-344 F 50-344 F 50-344 F 50-344 F))	8006240119 8006240122 8006240125 8006240146 8006240149	8006240110 8006240110 8006240110 8006240141 8006240121	80/06/04 80/06/04 80/06/04 90/06/03	QA979 QA999 QA999 QA999 50-366	P

ACCE8810	NUMBER				ACCEBBION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	_
8006240153 8006240155 8006240164 8006240167 8006240169	8006240141 8006240141 8006240160 8006240160 8006240160	80/06/05 80/06/05 80/06/02 80/06/02 80/06/02	GA999 GA999 50-259 50-259 50-259	a a a	8006240581 8006240584 8006240587 8006240592 8006240604	8006240569 8006240569 8006240521 8006240521 8006240598	80/05/29 80/05/29 80/06/20 80/06/20 80/06/03		Q Q
8006240172 8006240174 8006240175 8006240177 8006240179	8006240141 8006240160 8006240171 8006240171 8006240171	80/06/05 80/06/06 80/06/06 80/06/06	GA999 50-259 50-344 50-344 50-344	а Р Р	8006240607 8006240617 8006240626 8006240636 8006240649	8006240598 8006240611 8006240623 8006240630 8006240645	80/06/03 80/05/22 80/06/04 80/05/23 80/06/02		P 0
8006240182 8006240186 8006240188 8006240199 8006240203	8006240178 8006240184 8006240180 8006240194 8006240193	80/04/30 80/06/06 80/05/07 80/06/02 80/06/10	50-247 50-313 70-820 REGOD 50-321	Q Q	8006240653 8006250009 8006250013 8006250017 8006250024	8004240450 8004250008 8004250007 8004250007 8004250022	80/06/20 80/06/03 80/05/27 80/05/27 80/06/06	FOIA State Pros 50~219 C 50~219 C XPDATLIC	
8006240206 8006240208 8006240212 8006240213 8006240225	8006240201 8006240193 8006240193 8006240211 8006240223	80/05/19 80/06/10 80/06/10 80/06/02 80/05/22	100FR 50-321 50-321 100FR 100FR	PP	B004250030 B006250034 B006250035 B00625003B B006250042	8006250025 8006250027 8006250032 8006250033 8006250040	80/06/12 80/01/21 80/06/04 80/06/03 80/06/12	10CFR CONTRACT 70-143 CONTRACT CONTRACT	
8006240236 8006240246 8006240258 8006240262 8006240264	8006240232 8006240241 8006240251 8006240256 8006240251	80/06/02 80/06/02 80/06/03 80/06/03	50-528 CONTRACT 50-259 State Pr 50-259	Q	8006250045 8006250047 8006250048 8006250052 8006250054	8006250041 8006250043 8006250044 8006250044 8006250051	80/01/01 80/05/14 80/05/22 80/05/22 80/06/12		
9006240267 9006240273 9006240301 9006240304 9006240306	8004240251 8004240251 8004240297 8004240303 8004240305	80/06/02 80/06/02 80/05/28 80/06/16 80/05/15	50-259 50-259 50-213 50-320 40-1162	Q Q S I	8006250057 8006250059 8006250060 8006250064 8006250065	8006250051 8006250049 8006250051 8006250061 8006250062	80/06/12 80/05/27 80/06/12 79/11/01 80/05/13	CONTRACT 50-312 CONTRACT	3 3 4
8006240310 8006240317 8006240318 8006240321 8006240330	8006240308 8006240314 8006240316 8006240319 8006240328	80/05/11 80/05/20 80/05/18 80/05/10 80/05/18	50-311 REGOD 50-10 50-344 50-327	P F 8 8	8006250066 8006250076 8006250081 8006250082 8006250083	8004250051 8004250073 8004250078 8004250078 8004250080	80/06/12 80/05/16 80/06/05 80/06/05 80/05/15	50-302 (50-285 (50-285 (3
8006240331 8006240333 8006240350 8006240352 8006240354	8006240329 8006240329 8006240349 8006240349 8006240349	80/06/19 80/06/19 80/06/23 80/06/23 80/06/23	50-344 50-344 50-247 50-247 50-247	P P P P	8004270084 8004270087 8004270090 8004270093 8004270099	8004250078 8004250078 8004250084 8004250089 8004250094	80/06/05 80/06/05 80/04/29 80/05/15 80/06/06	50-285 (CONTRACT 50-344 (0 0 0
B006240364 B006240367 B006240369 B006240375 B006240376	8006240361 8006240361 8006240363 8006240369 8006240369	80/06/23 80/06/23 80/06/17 80/06/17 80/06/17	50-247 50-247 50-327 50-348 50-348	P P 8 9 9	8006250103 8006250104 8006250105 8006250106 8006250107	8004250074 8006250074 8006250100 8006250102 8006250074	80/06/06 80/06/06 80/04/15 80/08/16 80/06/06	50-280 (TOPREP 50-395 (3
B006240380 B006240393 B006240396 B006240397 B006240408	8006240374 8006240387 8006240388 8006240370 8006240404	80/06/19 80/06/13 80/06/17 80/06/19 80/06/16	50-327 50-245 50-327 50-370 50-377	8 8 8 9	8006250110 8006250112 8006250114 8006250117 8006250119	8006250097 8006250108 8006250097 8006250113 8006250097	80/06/05 80/05/16 80/06/05 80/06/05 80/06/05	QA799 50-275 (QA799 QA799 QA999	Or
8006240413 8006240418 8006240420 8006240423 8006240426	B006240404 B006240404 B006240410 B006240412 B006240419	80/04/14 80/06/14 80/06/19 80/06/19	50-397 50-397 50-327 50-327 50-302	F 6 8 8	8006250121 8006250123 8006250124 8006250126 8006250127	9004250113 9004250113 9004250116 9004250097 9004250113	80/04/05 80/06/05 80/05/19 80/06/05 80/06/05	GA999 GA999 50-312 GA999 GA999	3
3006240433 3006240434 3006240436 3006240444 3006240448	8006240425 8006240427 8006240431 8006240308 8006240308	90/06/16 80/06/20 80/06/17 80/06/11 80/06/11	50-327 50-280 50-366 50-311 50-311	8 8 8 P P	8006250129 8006250143 8006250144 8006250150 8006250155	8006250128 8006250137 8006250135 8006250135 8006250135	80/06/20 80/06/03 80/06/03 80/06/03	50~259 (50~259 (9
9006240449 9006240450 3006240455 8006240458 8006240459	8006240443 8006240446 8006240442 8006240454 8006240451	80/06/18 80/06/20 80/06/19 80/06/17 80/03/21	50-311 50-302 50-366 50-366 40-1162	9 9 9	8004250157 8004250140 8004250144 8004250145 8004250170	8006250152 8006250156 8006250161 8006250135 8006250166	80/05/02 80/05/20 80/05/04 80/06/03 80/05/21	70-824 50-29 50-259	3 3 3
8006240473 8006240476 8006240478 8006240479 8006240472	8006240468 8006240462 8006240469 8006240471 8006240486	80/06/20 80/06/19 80/06/20 80/06/18 80/06/18	50-387 50-316 50-338 50-273 50-272	M 8 8 9	8006250172 8006250176 8006250179 8006250182 8006250184	8006250169 8006250173 8006250174 8006250178 8006250181	80/05/12 80/05/14 80/05/12 80/05/15 80/05/20	50~423 (50~312 (50~289 (0 0: 0: 0:
8006240502 8006240509 8006240510 8006240512 8006240513	8006240497 8006240499 8006240504 8006240506 8006240508	80/06/16 80/06/17 80/06/17 80/06/17 80/06/19	50-219 50-296 50-320 50-270 50-255	\$ \$ \$	8006250186 8006250170 8006250172 8006250204 8006250205	8006250183 8006250188 8006250187 8006250199 8006250202	80/05/09 80/05/07 80/05/02 80/05/15 80/05/14	50-333 (50-528 (10CFR	0 0 0
8006240514 8006240518 8006240573 8006240575 8006240579	8006240507 8006240515 8006240566 8006240569 8006240569	80/06/19 80/05/06 80/06/09 80/05/29 80/05/29	50-366 70-1201 50-302 50-397 50-387	8 Q Q	8006250209 8006250210 8006250211 8006250215 8006250216	8004250207 8004250204 8004250206 8004250212 8004250214	80/05/14 80/06/02 80/03/24 80/05/14 80/06/20	CONTRACT 70-824 50-370	g G A

ACCESSIO	N NUMBER			ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENGLOSURE	PRINCIPAL DOCUMENT	DATE Daved	SUBJECT CATEGORY	Ý
8006250218 8006250219 8006250221 8006250225	8006250214 8006250217 8006250217 8006250222	80/05/20 80/05/21 80/05/21 80/05/06	50-361 A 50-445 Q 50-445 Q CONTRACT	8006260187 8006260188 8006260190 8006260192	8006260185 8006260186 8006260186 8006260186	80/06/17 80/06/23 80/06/23 80/06/23	50-247 50-247 50-247	8000
8006250226 8006250229 8006250230 8006250231 8006250233	8004250223 8004250223 8004250227 8004250223	80/05/22 80/05/22 80/06/20 80/05/22	50-354 G 50-354 G 50-438 8 50-354 G	8006260198 8006260200 8006260201 8006260293 8006260312	8006260196 8006260196 8006260196 8006260288 8006260305	80/06/24 80/06/24 80/06/24 80/06/12 80/06/12	50-498 50-498 50-358	0 0000
8006250238 8006250238	8004250223 8004250237 8004250240	80/05/22 80/06/16 80/06/17	50-354 G 50-312 S 50-277 S	8004260342 8004260344	8004240325 8004240255	80/06/11 80/06/17	50-329	ā Q
8006250243 8006250246 8006250249 8006250250	8004250242 8004250244 8004250245 8004250245	80/06/12 80/06/16 80/06/11 80/06/11	50-293 8 50-293 8 50-321 9 50-321 9	8006260353 8006260356 8006260357 8006260363	8006260343 8006260352 8006260343 8006260255	80/06/05 80/06/11 80/06/05 80/06/17	50-546 50-416 50-331	0 0 0
8006250254 8006250258 8006250261 8006250264 8006250265	8004250245 8004250245 8004250287 8004250245 8004250242	80/06/11 80/06/11 80/06/17 80/06/11 80/06/18	50-321 G 50-321 G 50-553 S 50-321 G 50-244 P	8006260364 8006260370 8006260375 8006260401 8006260431	8006260329 8006260255 8006260255 8006260255	80/05/23 80/05/29 80/06/17 80/06/17 80/06/17	50-331 50-331	0 0 0
8006250266 8006250271 8006250274 8006250281 8006250282	8004250263 8004250269 8004250269 8004250275 8004250279	80/06/11 80/06/10 80/06/10 80/06/19 80/06/11	50-373 G 50-321 P 50-321 P 50-518 S 50-331 P	8006260479 8006270014 8006270016 8006270017 8006270018	8006260253 8006270010 8006270011 8006270010 8006270011	80/06/17 80/06/20 80/06/13 80/06/20 80/06/13	FOIA 50-317 FOIA	G P P
8006250270 8006250275 8006250275 8006250276	8004250288 8004250288 8004250288	80/06/12 80/06/12 80/06/10 80/06/12 80/06/23	50-313 P 50-313 P CONTRACT 50-313 P 50-337 P	8006270020 8006270025 8006270027 8006270029 8006270032	8006270011 8006270021 8006270011 8006270021 8006270021	80/06/13 80/06/06 80/06/13 80/06/06	70-2260	P P
8006250300 8006250305 8006250309 8006250310	8006250289 8006250289 8006250303 8006250289 8006250306	80/06/23 80/06/23 80/05/27 80/06/23 80/05/16	50-337 P 50-337 P COMMISSION 50-337 P 50-327 Q	8006270033 8006270037 8006270039 8006270042 8006270052	8006270030 8006270034 8006270034 8006270034 8006270046	80/06/11 80/06/11 80/06/11 80/06/11 80/06/04	50-324 50-324	P P P H
8006250312 8006250314 8006250316 8006250318 8006250319	8004250289 8004250289 8004250289 8004250289 8004250315	80/06/23 80/06/23 80/06/23 80/06/23 80/05/09	50-339 P 50-339 P 50-339 P 50-339 P 71-9113	8006270071 8006270070 8006270075 8006270106 8006270127	8006270067 8006270084 8006270088 8006270102 8006270126	80/05/30 80/06/05 80/06/10 80/06/16 80/06/02	50-302 50-289	Q Н Н
8006250320 8006250322 8006250323 8006250348 8006250358	8006250313 8006250315 8006250317 8006250344 8006250354	80/05/02 80/05/09 80/05/27 80/05/08 80/05/06	10CFR 71-9113 PR PR 10CFR	8006270146 8006270150 8006270155 8006270177 8006270180	8006270141 8006270147 8006270152 8006270172 8006270172	80/06/02 80/06/03 80/05/22 80/05/22	50-171	U U H
8006250373 8006250375 8006250377 8006250382 8006250390	8006250369 8006250372 8006250376 8006250360 8006250365	80/05/22 80/06/11 80/05/30 80/06/16 80/06/02	RE00D 50-461 G 10CFR 50-313 P 50-155 P	8006270184 8006270188 8006270197 8006270207 8006270211	8006270172 8006270172 8006270191 8006270191 8006270191	80/05/22 80/05/22 80/06/10 80/06/10 80/06/10	50-438	G G
8006250608 8006260007 8006260009 8006260013 8006260016	8006250605 8006260003 8006260006 8006260012	80/06/02 80/06/10 80/06/16 80/06/06 80/05/08	70-2619 50-344 G XPORTLIC XPORTLIC 10CFR	8006270214 8006270220 8006270222 8006270223 8006270224	8006270191 8006270216 8006270219 8006270205 8006270217	80/06/10 80/06/24 80/06/07 80/06/27 80/06/20	50-320 50-413 50-537	Q Q B B
8006260018 8006260022 8006260023 8006260028 8006260040	8006260014 8006260019 8006260017 8006260021 8006260026	80/06/06 80/06/09 80/05/15 80/05/09 80/06/12	XPORTLIC XPORTLIC 50-302 Q 10CFR 50-344 Q	8006270228 8006270231 8006270233 8006270240 8006270241	8006270219 8006270219 8006270227 8006270007 8006270236	80/06/09 80/06/25 80/06/25 80/06/16 80/06/20	50-413 50-272 XPORTLIC	9 9 8
8006260059 8006260060 8006260049 8006260072 8006260077	8004260055 8004260055 8004260066 8004260061 8004260066	80/04/14 80/04/14 80/05/20 80/05/19 80/05/20	50-287 P 50-287 P 50-305 Q 10CFR 50-305 Q	8006270245 8006270252 8006270256 8006270259 8006270261	8006270239 8006270248 8006270251 8006270254 8006270258	80/05/05 80/06/09 80/06/13 80/06/20	50-295 50-295 50-295	0 8 8 8 8
8006240084 8006240088 8006240139 8006240146	8004260081 8004260081 8004260134 8004260141 8004260152	80/06/10 80/06/10 80/05/21 80/06/13 80/06/09	TOPREP TOPREP PRM 50-304 9 COMMISSION	8006270265 8006270267 8006270272 8006270274 8006270275	8006270262 8006270264 8006270266 8006270271 8006270270	80/06/20 80/06/20 80/06/10 80/06/20 80/06/23	50-331 50-245 50-331	888
8006240157 8006240161 8006240162 8006240163 8006240165	8006260158 8006260158 8006260160 8006260158 8006260164	80/06/19 80/06/19 80/06/18 80/06/19 80/06/19	50-275 9 50-275 9 50-327 8 50-275 9 50-327 F	8006270277 8006270280 8006270285 8006270286 8006270287	8006270279 8006270278 8006270278 8006270282 8006270277	80/06/17 80/06/20 80/06/20 80/06/10 80/06/23	50-440 50-440 50-341	P C B B
8006260166 8006260172 8006260173 8006260175 8006260184	8006260164 8006260171 8006260170 8006260174 8006260183	80/06/19 80/06/18 80/05/22 80/06/19 80/06/25	50-327 F 50-219 B PR 50-269 B 50-336 F	8006270274 8006270276 8006270297 8006270298 8006270302	8006270279 8006270290 8006270290 8006270295 8006270292	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-320 50-440	8 P P I S

ACCESS ION	NUMBER					N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEGORY
8006270303	8006270299	80\09\50	50-219	 6	9005300424	8006300421	80/06/23	50-272 B
8006270314 8006270315	8006270311	80/06/20	50-335	P	8006300428	8009300550	60/06/20	50-320 H
8006270317	8004270310 8004270311	80/06/20 80/06/20	50-338 50-335	8 P	8005300427	8006300391	60/06/53	
8006270326	8006270324	80/06/11	50-460	F	8005300431 8006300437	8007300550 8007300550	60/06/20 60/06/20	50-320 H 50-320 H
8006270334 8006270347	8004270330 8004270283	80/06/13 80/04/23	50-341 50-302	₽ P	9006300445 8006300457	8006300220 8006300447	60/06/03	50-320 H State Prog
8006270353 8006270361	8006270283 8006270357	80/04/23 80/04/13	50-302 50-277	P	8006300465	8006300459	60/06/23	50-272 6
8006270364	8004270357	80/06/13	50-277	P	8006300467 8006300470	8006300464 8006300462	80/06/26 80/06/06	50~286 B 27-47
8006270368 8006270391	8006270357 8006270386	80/06/13 80/05/28	50-277 CONTRACT	P	8006300475 8006300477	800630046B 8006300474	80/06/23 80/06/20	50-285 B 50-217 S
8006270406 8006270418	8006270403 8006270416	80/05/12 80/06/20	50-219 FOIA	Q	B00630047B	8004300471	80/06/25	50-289 8
8006270419	8006270416	80/09/50	FOIA		8006300481	8006300473	80/06/16	50-320 H
8006300031	8004300029	80/05/08	71-6717	_	8006300482 8006300484	8006300472 8006300473	80/06/23 80/06/16	50-217 8 50-320 H
8006300033	8004300030 8004300037	80/05/20 80/05/09	50-341 50-334	G G	8005300487 8005300488	8006300479 8006300473	80/06/25 80/06/16	50-311 8 50-320 н
8006300060 8006300070	8006300055 8006300067	80/05/19 80/05/14	50-322 50-483	G G	9005300492	8005300495	80/06/20	50-344 8
8004300073	B006300067	80/05/14	50-483	Q	8005300498 8005300499	8005300495 8005300493	80/06/23 80/06/27	50-315 B 50-282 S
8006300116 8006300131	8006300097 8006300120	80/05/23 80/05/12	ACR9 70-1143		COE00F2008 E0E00E2008	8006300488 8006300488	80/06/16 80/06/16	50-320 H 50-320 H
8006300149 8006300152	B006300143 B006300139	80/06/05 80/05/22	94999 925-08	G	8006300507	8004300501	80/06/24	50-339 P
8006300153	B006300143	90/06/05	QA999	-	00000000 90000000 90000000	8004300502	80/06/25 80/06/24	50-315 S 50-337 P
8006300156 8006300157	B00630014B	80/05/21 80/06/05	50-341	q	8006300510	8006300488	80/06/16	50-320 H
8006300166	8004300143 8004300159	80/06/12	QA999 50-364	G	8006300512	100000000	80/06/24	
8006300172	B004300143	80/06/05	9A999	_	8006300514 8006300515	8006300506 8006300488	80/06/30 80/06/16	20-350 H
8006300176 8006300182	9004300159 9004300175	80/06/12 80/05/21	50-364 50-546	Q	8006300517 9006300518	8004300513 8004300488	80/06/23 80/06/16	50-255 0 50-320 H
8006300199 8006300201	8006300190 8006300188	80/06/12 78/06/08	50-269 REGOD	a	8006300520	8006300306	80/06/30	NUREO
8006300209	B006300190	80/06/12	50-249	Q	9006300522 9006300523	8006300488 8006300516	80/06/16 80/06/24	50-320 H 50-327 S
1520054008 4520054008	8004300224	80/06/20 80/05/23	50~320 50~245	H	9006300524 9006300525	8006300519 8006300488	80/06/12 80/06/16	70-27 50-320 H
8006300239 8006300243	8006300220 8006300237	80/05/20 80/05/20	50-320 50-280	H	8006300329	8006300488	00/06/16	50-320 H
8006300245	8004300220	80/06/20	50-320	Ĥ	9005300530 \$\$\$005300	8004300513 8004300519	80/06/23 80/06/12	50-255 Q 70-27
9006300251 9006300254	8006300240 8006300220	80/06/11 80/06/20	50-443 50-320	H	8006300 5 33	8004300528 8004300488	80/06/19 80/06/16	50-312 B
9004300257 8004300240	8006300248 8006300255	80/06/24	50-327 50-271	P	8006300539	8004300488	80/06/16	20-350 H
8006300263	8009300550	80/06/13 80/06/20	50-320	Н	8006300539	8004300535	80/06/17	FOIA
8006300266	8006300261	80/03/20	50-324	Q	8006300541 8006300546	8004300488 8004300535	80/06/16 80/06/17	50-320 H FDIA
8004300270 8004300273	B006300264 B006300269	80/03/08 80/03/16	50-320 50-335	H	8006300547 8006300549	8006300488 8006300340	80/06/16 80/06/03	50-320 H State Prog
8004300275 8004300278	8006300268 8006300272	80/06/16 80/05/19	50-186 50-364	Q Q	8006300551	8006300488	80/06/16	50-320 H
8006300285	9006300281	80/05/28	40-8681		8006300555 8006300557	8006300345 8006300488	80/06/13 80/06/16	CONTRACT 50-320 H
\$0000000B	B006300304 B006300304	61/40/08 61/40/08	50-320 50-320	0	\$280000008 5250000000	8004300498 8004300498	80/06/16	50-320 H 50-320 H
8006300315 8006300321	8004300220	80/06/20	50-320 50-320	H	8006300571	8004300488	80/06/16	50-320 H
8006300322	8004300320	80/06/12	50-395	e.	9006300 57 3 8006300 57 7	8004300544 8004300488	80/06/11 80/06/16	50-407 D 50-320 H
8006300325 8006300326	B004300320 B004300220	80/04/12 80/06/20	50-395 50-320	Ğ H	80004300884 8880023098	8004300581 8004300548	80/06/03	XPORTLIC
8006300337	8006300220 8006300338	80/06/20	50-320	Н			79/12/14	PRM
8006300343		90/06/10	CONTRACT		17500E300E9 \$7500E300E	9004300597 9004300599	80/06/17 80/06/18	50-397 A FOIA
8004300345 8004300352	8009300550	80/06/20 80/06/20	50-320 50-320	H	8006300574 000630060	8004300588 8004300594	80/06/18 80/06/10	FOIA 71-391
8006300354 8006300359	B004300220	80/06/20	50-320 50-320	H	8906300602	8004300597	80/05/16	50-54 G
006300360	8006300359	80/06/20	50-309	P	2040063008 8040064008	8006300583 8006300594	80/06/16 80/06/10	FOIA 71-391
B006300364 B006300367	8009300350 8009300395	80/06/24 80/06/20	50-269 50-320	P H	8006300610 8006300612	8006300606 8006300583	80/05/14 80/06/16	50-225 Q FOIA
8006300373 8006300382	B004300370 B004300375	80/06/23 80/06/27	50-272 50-416	S	8006300616	8006300613	00/06/17	50-461 Q
8006300384	8006300375	80/06/27	50-416	F	8006300417 8006300418	8004300414 8004300411	80/05/21 80/06/12	COMMISSION 71-390
8006300393 8980063008	B004300392	80/06/03 80/06/18	50-347 50-329	U	E2900E3008	8004300420 8004300420	80/02/28 80/06/13	71-165 71-6581
8006300397 8006300397 8006300399	8006300374 8006300391	80/06/23 80/06/24	50-327 50-390 50-367	Ä	800630082	9004300620	80/02/28	71-165
8006300400	8006300376	80/06/23	50-340	Ă	8006300627	8004300421	80/06/13	71-6581
8006300401	8006300398	80/06/24	50-302	B	8004300428 8004300427	8004300421	80/06/13 80/06/16	71-6581 FOIA
8004300403 8004300407	B004300394 B004300403	80/06/19 80/06/18	50-312 50-275	B	8006300635 8006300644	8006300583 4006300583	80/06/16 90/06/09	FDIA 30-498 Q
8005300409 8005300412	8006300391 8006300403	80/06/23 80/06/18	50-390 50-295	B	8006300649 8006300655	8004300445 8004300450	80/06/06 80/06/13	40-8027 50-329 A
8006300414 8006300422	0006300391 0006300391	80/06/23 80/06/23	50-390 50-390	A	784006408 EP40064008	8006300685 1740064008	80/06/23	50-10 H 50-219 H

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
 proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating
 to technical specifications, the operating license or technical issues arising after the issuance
 of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. i&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

l. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

- 1. Application submitted by the utility.
- 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
- 3. Applicant's Quality Assurance Manual.
- 4. Early site review information.
- 5. Backup technical documents submitted in support of the application.
- 6. Early site visits.

B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- 2. Amendments and changes to the PSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include.

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG — State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.

- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

			,

C FORM 335 U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available 1, 20, 1000	1 REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol 2, No66 2 (Leave blank) 3 RECIPIENT'S ACCESSION NO
June 1-30, 1980 .uthor(s)	5. DATE REPORT COMPLETED MONTH July 1980
PERFORMING ORGANIZATION NAME AND MAILING ADDRESS linclude Division of Technical Information and Document (U.S. Nuclear Regulatory Commission Washington, D.C. 20555	MONTH
sponsoring organization name and mailing address (Include Division of Technical Information and Document (U.S. Nuclear Regulatory Commission Washington, D.C. 20555	10 PROJECT/TASK/WORK UNIT NO
TYPE OF REPORT Monthly	PERIOD COVERED (Inclusive dates)
SUPPLEMENTARY NOTES	14 (Leave plank)
ABSTRACT (200 words or less)	

This document is a monthly publication containing descriptions of information received and generated by the US NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through the U.S. Department of Energy's Technical Information Center under the title Power Reactor Docket Information (PRDI). This document replaces PRDI, which will no longer be prepared. This document contains the following indexes: Personal Author Index, Corporate Source Index, and Report Number Index.

KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

1.17a DESCRIPTORS

AVAILABILITY STATEMENT

19. SECURITY CLASS (This report)
Unclassified

20. SÉCURITY CLASS (This page)
Unclassified

22. PRICE
S

FORM 335 (7.77)